



SERVICE BULLETIN

Classification: EL15-028	Reference: NTB15-112	Date: December 22, 2015
-----------------------------	-------------------------	----------------------------

2013-2015 PATHFINDER; LOW POWER / STOP LAMPS STAY ON

APPLIED VEHICLE: 2013-2015 Pathfinder (R52) 2WD with V6 engines only

IF YOU CONFIRM

The following, or the customer reports the following:

- Intermittently there is low power when accelerating,

And/or
- The stop lamps (brake lights) stay ON after releasing the brake pedal, with the ignition ON or OFF.

ACTION

- Delete the stop lamp relay and bypass the stop lamp relay circuit.
- Replace the stop lamp switch with the one listed in **PARTS INFORMATION**.

IMPORTANT: The purpose of “ACTION” (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire Service Procedure as it contains information that is essential to successfully completing the repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Remove the stop lamp fuse (#10) from the “junction box” fuse block in the Instrument panel.
2. Remove “fuse and relay box” (fuse box) cover and locate stop lamp relay (Figure 1).
 - Fuse box located on bulkhead above engine.




Figure 1

3. Remove the stop lamp relay (Figure 2).
NOTE: This relay will not be reinstalled.




Figure 2

4. Release the fuse box from its mounting bracket.




Figure 3

5. Remove the back cover of the fuse box.
NOTE: Do not remove the back cover from the harness.




Figure 4

6. Release the stop lamp relay connector from the fuse block.

7. Locate the red and the white wires on the bottom of the stop lamp relay connector (Figure 5).




Figure 5

8. Cut the red and white wires of the stop lamp relay connector (Figure 6).




Figure 6

9. Strip approximately 1/4" of insulation from the ends of both the red and the white wires (Figure 7).




Figure 7

10. Twist the red and white wires together (Figure 8).




Figure 8

11. Slide a solder sleeve connector (#J-47003-2) over the twisted pair (Figure 9).
- Confirm that the bare wires are aligned with the solder in the center of the connector.




Figure 9

12. Apply heat (Figure 10) with a Flameless Heat Gun (#J-46538) until:
- The solder completely melts
- And
- Both ends of the shrink tube have been sealed.




Figure 10

- Figure 11 shows completed solder connection.




Figure 11

13. Cut the remaining two wires (yellow and black; Figure 12) to the stop lamp relay connector, and discard the connector.
- Tape the ends of the yellow and black wires.
 - Tuck all wires from stop lamp relay out of the way and reinstall the back cover of the fuse box.
 - Reattach the fuse box to its bracket.
 - Reinstall fuse box cover.




Figure 12

14. Replace the stop lamp switch with the part listed in **PARTS INFORMATION**.
- Refer to the Electronic Service Manual (ESM), section **BR – Brake System / Brake Pedal** for replacement information and adjustment.
15. Reinstall the stop lamp fuse #10 into the instrument panel junction box.

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
Stop Lamp Switch	25320-AX10A	1
Solder Sleeve Connector	J-47003-2	1

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

OPERATION	PFP	OP CODE	SYM	DIAG	FRT
Delete stop lamp relay	25320-AX10A	PX82AA	ZE	32	0.4