

# APS/NRC Meeting

## July 20, 2004

Discussion of A600 Repair/Inspection  
issues and associated relief requests

Mike Winsor

Director, Nuclear Engineering  
Arizona Public Service Co



# Purpose

- Discuss CE plant alliance efforts to develop a methodology for replacement of pressurizer heater sleeves and provide information to the NRC on needed relief requests.
- Provide additional information on Palo Verde RR #25 “Palo Verde CEDM inspection”
- Provide additional information on Palo Verde RR #24 “Removal of RV head vent orifice”



# Agenda

## **Background and Alliance Efforts – Mike Winsor**

- Overview of A600 Replacement Program
- Pressurizer heater sleeve repair/replacement history
- Cooperative efforts between APS, Entergy, and SCE to develop a mid-wall heater sleeve replacement option

## **Pressurizer Modification using the Mid Wall technique**

**Rex Meeden**

## **Palo Verde CEDM Nozzle Inspection RR #25**

**Mike Melton**

## **Palo Verde Reactor Head Vent Orifice Relocation**

**Mark Radspinner**



# Palo Verde A600 Replacement Program

- **Aggressive and Systematic Replacement Program based on relative susceptibility (temperature and yield strength)**
- **Initiated Replacement Program in Fall 1991 with Unit 2 Hot Leg Instrument Nozzles (75 ksi Yield Strength)**



# A600 Nozzle Replacements

## A600 Nozzle Replacements

Nozzle Location	# of Nozzles/Unit	Completion Date
Pressurizer Instrument Nozzles	7	Unit 1 Spring 1992
	7	Unit 3 Fall 1992
	7	Unit 2 Spring 1993
Hot Leg Instrument/Sampling Nozzles	8	Unit 2 Fall 1991
	1	Unit 2 Fall 2000
	9	Unit 3 Fall 2001
Hot Leg Spare RTD Nozzles	9	Unit 1 Spring 2001
	8	Unit 2 Fall 2000
	8	Unit 1 Spring 2001
Hot Leg Inservice RTD Nozzles	8	Unit 3 Fall 2001
	10	Unit 1 Fall 2002
	10	Unit 3 Spring 2003
Pressurizer Heater Sleeves	10	Unit 2 Scheduled for Completion Spring 2005
	36	Unit 2 Fall 2003
	36	Unit 3 Scheduled for Completion Fall 2004
	36	Unit 1 Scheduled for Completion Fall 2005

Red indicates Half-nozzle Repairs. Black indicates Full Nozzle (no remnant) Repairs



# A600 Nozzle Replacements

- Replacement of Unit 1 Pressurizer Heater Sleeves scheduled for Fall 2005 will complete nozzle replacement plan for all A600 nozzles/penetrations at Hot Leg Temperature or above
- Strategically plan for upper head replacement and dissimilar butt weld examinations and mitigation techniques



# Palo Verde Pzr Heater Sleeve Repair/Replacement Program

- Pressurizer heater sleeve status
  - Unit 2 completed replacement in Fall 2003 using pad repair
    - 36 day installation duration
    - 32 REM installation dose
- Original schedule for Palo Verde heater sleeve replacement
  - Unit 1 scheduled for Fall 2005
  - Unit 3 scheduled for Fall 2007



# Alliance Efforts to Address PZR Heater Sleeves

- **Arizona Public Service Co., Entergy Nuclear Inc., and Southern California Edison Co., agreement to support development of a mid-wall heater sleeve replacement technique**
- **Develop a common replacement technique to leverage licensing, developmental, training, and tooling costs**
- **Welding Services Inc and Structural Integrity to provide technical and field services**
- **Began in spring of 2004 following Palo Verde U3 February SNO outage**





# Pressurizer Heater Sleeve Replacement Schedule

- **Palo Verde will be the lead plant with its 3R11 Fall 2004 outage and U1R12 Fall 2005 outage**
- **Waterford 3 Spring 2005**
- **SONGS 2 Fall 2005, SONGS 3 Spring 2006**



# **Palo Verde Unit 1 and 3 Pressurizer Heater Sleeve Repair And Remnant Sleeve Flaw Evaluation**



**NRC Presentation**

**Rex Meeden**

**July 20, 2004**

# Pressurizer Heater Sleeve Repair

## Agenda

- Pro-Active Strategy
- Pad Repair
- Midwall Repair
  - Concept (Rex Meeden)
  - Relief Requests #28 & #29 (Rex Meeden)
  - Design and Analysis (Dick Mattson)
  - Tooling (Pedro Amador)
  - Welding Development Program (Pedro Amador)
  - NDE (Michael Lashley)
  - Triple Point Flaw Evaluation (Pete Riccardella)
- Conclusions



# Pressurizer Heater Sleeve Original Strategy

- February 2004: Implement pad repair during replacement steam generator outages
  - Unit 2 – pad repair complete fall 2003
  - Unit 1 – fall 2005
  - Unit 3 – fall 2007
- MNSA contingency
  - 2 Mechanical Nozzle Seal Assemblies (MNSAs) installed, U3R10 (Spring 2003)
  - Relief Request #17 granted 2 cycles of operation
- Plan supported by failure rate analysis
  - Yield strength of material
  - Industry experience




# Pressurizer Heater Sleeve Revised Strategy

- March 2004 – Unit 3 forced outage
  - BMV identified 1 leaking heater sleeve
- Installed MNSA - third MNSA in unit 3
  - Radiological exposure of 3 REM
- Management decision to accelerate unit 3 repair from fall 2007 to fall 2004
  - Planned repair of 36 heater sleeves
  - Remove 3 MNSAs
  - No need to exercise 2<sup>nd</sup> cycle of operation granted in RR #17




# Pressurizer Heater Sleeve Repair

## Pad Repair



# Pressurizer Heater Sleeve Repair

## Pad Repair



# Pressurizer Heater Sleeve Repair

## Pad Repair


- Unique concentric ring configuration favors rectangular pad
- Installation dose - 32 REM
- Installation duration - approximately 36 days
- Other utilities likely to incur more dose due to different sleeve configuration






# Pressurizer Heater Sleeve Repair

## Midwall Repair



# Pressurizer Heater Sleeve Repair Midwall Repair



# Midwall Sleeve Repair

- Relatively small weld volume, increased effective throat
- Extensive welding development program conducted
- Qualified NDE procedure to support repair
- Future ISI per Section XI and NRC Bulletin 2004-01
- Projected installation dose – 23.5 vs. 32 REM
- Projected installation duration – 20 vs. 36 days
- 8.5 REM savings/PV Unit (2 Units to do)
- Potential savings for 5 CE alliance Units approximately 50 REM



# Pressurizer Heater Sleeve Repair

## Relief Request #28

- Ambient temperature temper bead versus preheat/post weld soak temper bead welding
- GTAW versus SMAW
- Code Case N-638-0 used as a guide (included in Regulatory Guide 1.147) – minimal changes
- Ultrasonic examination in place of radiography required by section XI ('92 Edition '92 Addenda)
- Liquid penetrant examination of midwall weld area prior to welding and final weld surface/heat affected zone after welding
- Relief Request #28 is similar to Relief Request #23 (previously approved for Unit 2 pad repair)



# Pressurizer Heater Sleeve Repair

## Relief Request #29

- Leave postulated flaws in remnant sleeve and J-Weld w/o full characterization or successive examinations
- Section XI flaw evaluation complete; worst case flaw modeled
  - Linear elastic fracture mechanics (LEFM) and elastic plastic fracture mechanics (EPFM) utilized
  - EPFM precedence established by Entergy for reactor head
- Corrosion analysis
  - WCAP-15973-P Rev.1 demonstrates that the limiting CE plant lifetime following half sleeve repair is 194 years




# ASME Code Evaluations

- ASME Code, Section III evaluations
- ASME Code, Section XI evaluations
- Elastic-Plastic Fracture Mechanics evaluations



# Pressurizer Heater Sleeve Mid-wall Repair Concept




# Section III Evaluations

- Load Definition
  - Original design basis (pressure/thermal transients)
- Stress Analysis
  - Three-dimensional finite element analysis
  - 90° model with appropriate boundary conditions
- Section III Evaluations
  - Stress criteria
  - Fatigue evaluation (60 years of extrapolated 40 year cycles)
  - Attachment mid-wall weld is the controlling location





# Finite Element Model




# Section XI Evaluations

- Postulated axial flaw in sleeve, overlay, and J-groove weld
- Stresses extracted from Section III analyses
- Linear elastic fracture mechanics (LEFM) techniques utilized
- Residual stress analyses for similar plant
- Fatigue crack growth analyses
- Limited life based upon LEFM analyses
- Acceptability to end-of-life (including 20 year license renewal period) demonstrated utilizing elastic-plastic fracture mechanics (EPFM) techniques



# Fracture Mechanics Finite Element Model



# Basis for EPFM Approach

- Controlling transients occur at operating temperature
  - Well above upper shelf on Charpy impact energy curve
  - Pressurizer material possesses considerable ductility in this regime
- EPFM is the more appropriate technology for ductile materials (such as the Palo Verde pressurizer at upper shelf)
- Ample precedent exists in ASME Code, Section XI for the use of EPFM and appropriate treatment of safety factors
  - Appendix C for Flaws in Austenitic Piping
  - Appendix H for Flaws in Ferritic Piping
  - Appendix K for Assessment of RPVs with Low Upper Shelf Toughness
- These code appendices all specify reduced safety factors (SFs) for secondary (strain controlled) loading conditions, and permit EPFM instability analysis




# ASME Code Evaluation Conclusions

- Proposed mid-wall repair concept is acceptable because:
  - Design meets ASME Code, Section III criteria
  - Remaining postulated defect in Alloy 600 material is acceptable for life of plant plus life extension




# Sequential Repair Procedure

- ID Sleeve Sever
  - WSI Nozzle  
Severing Tool
  - Depth of cut  
selected to  
maximize weld  
area work  
envelope




# ID Sever Tool with Articulating Arm




# Sequential Repair Procedure

- SSAT Tool Installation
  - Positioning Collar Locates Axially
  - Self Centering Feature Locates Radially
  - Tool Extends through the first Heater Tray






# Sequential Repair Procedure




# Sequential Repair Procedure

- SSAT with Replacement Sleeve and Alignment Shaft
  - Piloted in SSAT




# Internal Alignment Tool




# Sequential Repair Procedure

- Sleeve External Alignment Tool
  - Shims installed
  - Clamping Device Installed
- Tool is Mandrel or OD Mounted to two or three adjacent penetrations




# Zero Force Clamp Installation




# Sequential Repair Procedure

- Mid-Wall Weld  
Head Front-End
  - Video
  - Wire Feed
  - Inert Gas Delivery
  - Water Cooled




# Sequential Repair Procedure




# Sequential Repair Procedure

- Mid-Wall Weld
  - Water Cooled Copper Front End Piece after Machining
  - Core component of torch assembly






# Sequential Repair Procedure




# Sequential Repair Procedure

- As Welded Configuration
  - Minimum three layers and 1/8" weld deposit
  - Minimal build-up beyond sleeve wall thickness




# Sequential Repair Procedure


- Post Weld Clean-Up
  - Grind/abrade surface of weld to:
    - Remove any build-up beyond bore ID
    - Prepare weld surface for final NDE




# Sequential Repair Procedure




# Sequential Repair Procedure



# PZR “Bazooka” Mockup



# PZR "Bazooka" Mockup




# Welding Development Program

- Extensive welding development program conducted to address potential triple point / welding solidification anomaly
  - Over 13 weld samples produced to date
  - Triple point cross sections examined at high magnification
  - Welding parameters refined & improved
- Demonstrated ability to repeatedly produce defect-free welds with no solidification anomalies at the weld root






# Early Sample with Cracking at Weld Root (50x)



# Recent Weld Sample (50x) (Typical of 6 production welds produced)



# Weld Process Conclusions

- OE and initial shop trials produced cracks at weld root
- Further process variable changes were able to reliably resolve the “triple point” issue
- Process has been refined to produce reliable and repeatable high quality welds



# Mid-Wall Repair NDE

- PVNGS is committed to the '92 Edition/'92 Addenda of ASME Code, Section XI
- IWA-4170(b) requires repairs and replacements to be performed in accordance with the Construction Code, or all or part of later editions and addenda thereof, and code cases
- Weld to be examined per Section III NB-5000, guidance to be taken from N-638-0
  - PT of pressurizer bore before welding
  - Final PT of weld surface and adjacent base metal
  - Volumetric examination with straight beam and angle beam transducers



# Midwall Repair NDE

- Surface Examination
  - PT examination prior to welding to ensure surface is free of defects
  - Final PT examination of weld surface and adjacent base metal
- Volumetric Examination
  - Straight beam examination to a depth of 0.25”
    - Surface of weld and adjacent heater sleeve to ensure no lack of bond or lack of fusion and to detect any reflectors that could interfere with the angle beam examination
  - Angle beam examination to a depth of 0.25”
    - Scanning looking in both direction for axial reflectors
    - Scanning looking in both direction for circumferential reflectors




# Mid-Wall Repair NDE


- Demonstration of Midwall Repair NDE
  - Volumetric Examination
    - Straight beam examination
      - Welded mockup with flat bottom holes
    - Angle beam examination
      - Welded mockup with OD/ID circumferential and axial EDM notches and end drilled holes



# NDE of OD Axial EDM Notched Sleeve





# NDE of OD Circumferential EDM Notched Sleeve






# NDE of ID Circumferential EDM Notched Sleeve



# Pressurizer Mid-Wall Repair UT Inspection Coverage



04066r0



# Pressurizer Heater Sleeve Repair

## Midwall Repair NDE Timeline

### Completed Items

- Review applicable codes and standards to define inspection requirements
- Design and fabricate calibration standard and preliminary test samples
- Design/build/test development scanner
- Design, procure, and machine prototype probes/heads/wedges
- Perform preliminary examination on test samples

### Scheduled Items

- Design and fabricate final demonstration blocks – 7/30
- Perform technique demonstration – 8/5 and 8/6
- Finalize NDE procedure – 8/17
- Compile demonstration package and procedure qualification – 8/20
- NDE personnel training – 8/23



# Mid-Wall Repair NDE

- NDE meets applicable ASME Code requirements (Section XI, III, and V)
- Technique will be Demonstrated on a Mid-wall Welded Mockup



# Triple Point Flaw Evaluation

- Although triple point flaws not expected, ASME Section XI applied to establish NDE detection and acceptance criteria, considering:
  - Flaw Acceptance Standards (IWB-3500)
  - Fracture Mechanics Flaw Evaluation Criteria (IWB-3600)




# ASME Section XI

## Allowable Flaw Standards

- Allowable flaw sizes in accordance with Section XI Pre-service Inspection Standards
  - IWB-3514.3, Austenitic Piping
  - IWB-3514.4, Dissimilar Metal Welds
- Established for Paths 1 and 2 (see Figure)
- Applicable to austenitic piping, including wrought stainless and Ni-Cr-Fe piping material and associated weldments
- If no indications are detected that exceed these limits:
  - welds are considered clean in accordance with ASME Section XI, IWB-3112, and
  - no successive examinations, in accordance with ASME Section XI, IWB-2420 are required



# Triple Point Flaw Evaluation Paths



# ASME Section XI


## Fracture Mechanics Flaw Evaluation

- Employ Fracture Mechanics principles to determine crack growth rates and end of life allowable flaw sizes
  - Strictly applicable only to Inservice (not Pre-service) Inspections
  - When employed, introduce requirement for successive examinations per IWB-2420
- Applied to mid-wall triple point evaluation to demonstrate conservatism of Section XI Standards






# Evaluation Results for Postulated Path 1 Flaw



# Evaluation Results for Postulated Path 2 Flaw



# Summary of Triple Point Flaw Evaluation Results

Postulated Flaw Location	Allowable Flaw Sizes per Section XI Standards	Allowable Flaw Sizes per Fracture Mechanics Evaluation	
		Initial Flaw Size*	End-of-Evaluation Period
Path 1	0.0166"	0.095"	0.112"
Path 2	0.0522	0.26"	0.36"

\*Approximate flaw size that would grow to End-of-Evaluation Period Allowable in sixty years.



# Pressurizer Heater Sleeve Repair

## Conclusions

- Midwall repair requires less machining and significantly less welding than pad repair
- Palo Verde would save 8.5 REM per unit by implementing the midwall repair in lieu of the pad repair
- Other utilities would likely incur more dose than Palo Verde by implementing pad repair due to sleeve configuration



# Pressurizer Heater Sleeve Repair

## Conclusions Cont'd

- Requesting relief to utilize GTAW ambient temperature temper bead process for midwall repair (RR28)
- Requesting relief to leave the postulated flaw in place w/o full characterization and successive exams (RR29)
- Requesting relief to utilize EPFM for flaw evaluation



# Pressurizer Heater Sleeve Repair

## Conclusions Cont'd

- Successive volumetric examinations in addition to Section XI/NRCB 2004-01 exams are not required
  - Qualified welds
  - ASME flaw margin demonstrated
- Successive volumetric examinations would eliminate CE alliance dose reduction benefit
- NRC concurrence needed to support Unit 3 fall 2004 outage



# Relaxation Request No. 25 on Inspection Coverage for Palo Verde Unit 1



NRC Presentation

Mike Melton

July 20, 2004

# Background

- Arizona Public Service Company (APS) requested relaxation from the requirements of first revised order EA-03-009, section IV.C.(5)(b).
- The NRC requested analysis be performed to substantiate inspection coverage below the weld for Unit 1 CEDM Nozzles 84, 87 and 93 were acceptable.
- APS has completed an additional finite element analysis (FEA) of CEDM Nozzles 84, 87 and 93 using the as-built J-weld configuration for these nozzles.
- APS recently submitted revised analysis






# Actual Inspection Coverage

Penetration No.	Nozzle Angle (°)	Proposed Inspection Coverage in Relaxation Request	ID Distance Covered by UT Below Weld	OD Distance Covered by PT Below Weld
84	35.7	0.40"	0.28"	1.0 "
87	51.5	0.35"	0.20"	0.8 "
93	35.7	0.40"	0.36"	0.7 "



# As Built J-Weld Configuration (penetration No. 84, 87 and 93)




L = As-Built J-Weld Heights

Nozzle 84 = 2.24"

Nozzle 87 = 2.62"

Nozzle 93 = 1.76"



DETAIL "G"

TYPICAL PENETRATION NO'S 1 THRU 97

# Revised Stress Analysis

- Hoop stress distribution for as-built J-weld configuration
- Methodology same as discussed in relaxation request (letter 102-05075-CDM/SAB/RJR, dated March 19, 2004.)
- Accounted for instrumentation measurement uncertainty



# Crack Growth Calculation

- For the three penetrations with incomplete coverage, a through-wall axial flaw was postulated
- The upper end of the flaw was located at the location where inspection coverage stopped
- The lower end of the flaw was located where the stresses dropped to zero
- Maximum stresses anywhere along the crack were used to calculate the stress Intensity factor
- Crack growth model of MRP-55 used



# Conclusions

- No crack growth below the weld for any undetected flaws in penetration No. 84,87 and 93
- Undetected flaws will not reach weld bottom before next inspection
- Provides an acceptable level of quality and safety for a full operation cycle



# Follow-up Requested

- APS has submitted the analysis and revised table for Unit 1 to support a full cycle of operation
  - Currently under 7.7 month limited operation
- The relaxation for Unit 3 CEDM inspection coverage was previously submitted and needs NRC approval for the 2004 fall outage
  - Outage start October, 2004



# Reactor Vessel Head Vent Line Orifice Relocation



**NRC Presentation  
Mark Radspinner  
July 20, 2004**


# Relief Request 24

- ◆ APS requested relief from Order requirement IV.C.(1)(b) for the head vent line nozzle with integral orifice
- ◆ Either
  - UT of each nozzle ID and an assessment to determine if leakage has occurred into the interference fit zone OR
  - ET or PT of wetted surface






# Vent Line and Orifice



CLOSURE HEAD  
SCALE NONE

VENT PIPE




# Vent Line Orifice

- ◆ NUREG 0737 Item II.B.1 Requirement
  - Remotely operated RCS vent system
  - Stipulated must not lead to an unacceptable increase in the probability of a LOCA
    - Meet 10CFR50.46 acceptance criteria and General Design Criteria
  - Palo Verde construction status allowed optimal orifice location



# Vent Line and Orifice



# Relief Request 24

- ◆ Proposed alternative of surface exam of vent nozzle J-groove weld and orifice attachment weld
- ◆ Combined with IV.C.(1)(a)-required bare metal visual exam, felt to provide acceptable level of quality and safety



# NRC SER

- ◆ Relief granted for one cycle, Unit 1 only, in recognition of magnitude of radiation exposure (hardship) that would be incurred considering lack of developed tooling and methods to remove orifice




# Unit 3 Preparation Status

- ◆ Developing remote tooling for orifice removal
- ◆ Developing orifice relocation package
  - ASME Code Class Break reconciliation
    - Will require PT of one existing butt weld to meet Class 1 requirements
  - Design and licensing basis reconciliation
    - NUREG 0737 and GDC requirements met



# Orifice Relocation



# 10CFR50.59

- ◆ Meets NUREG 0737 Requirements
- ◆ Will meet ASME Class 1 Requirements
- ◆ Meets GDC Requirements
- ◆ No/minimal increase in frequency of occurrence or consequences of accident or malfunction



# Expectation

- ◆ Full compliance with Order requirements
- ◆ Developed methods and tooling to minimize radiation exposure (basis for granting of Relief Request)

