


---

---

Brent M. Wilson  
Amsted Rail  
February 12, 2010

# What does Amsted Rail do??

---




CLASS AND SIZE	CAR CAPACITY (TONS)	CONE BORE (in)	CUP O.D. (in)
B (4 1/4 X 8)	30	4.0000	6.5000
C (5 X 9)	40	4.6875	7.6875
D (5 1/2 X 10)	50	5.1870	8.1875
E (6 X 11)	70	5.6870	8.6875
L (6 X 8)	70	5.6870	8.6564
F (6 1/2 X 12)	100	6.1870	9.9375
K (6 1/2 X 9)	100	6.1870	9.8375
G (7 X 12)	125	6.9996	10.8750
M (7 X 9)	125	6.4995	10.3750
EE	Passenger Car	5.4995 5.9995	10.8780
GG	Locomotive	6.4995 6.8745	11.8780




- A primary reason for bearings to be pulled is due to overheating
  - Bearing overheating is detected by a hot box scanner
  - Hot Box Trigger is @  
 $T > 190^{\circ}\text{F}$  above ambient



# WMC 50 removals











a)



b)



c)



d)

a) Wheel flat b) Shell / Spall  
c) Shattered rim d) Built-up-tread

---

---

## 1. Control of Retained Austenite

- a) Transformation of retained austenite causes a 3-4% volume change at the surface of the bearing race.
- b) Transformation leads to cone bore growth, and can cause an “axle burn-off failure”

## 2. Microscopic Cleanliness

- a) Subsurface discontinuities act as stress risers and are the primary sites of fatigue initiation.
- b) Subsurface fatigue initiation leads to “spalling” type failures which generate heat and can cause derailments.


## 3. Wheel / Rail Interactions


- a) Impact damage from “wheel flats” can lead to structural damage.
- b) Early detection and energy absorbent structures are necessary.

---

---


# Retained Austenite and Residual Stress





**Austenite**


Carbon  
Atoms





**Martensite**

Outline of  
BCT Cell

### Volume Change as Austenite (A) Transforms to Martensite (M)









During service the cone will grow on the order of 0.001 to 0.002 inches.




Samples fractured at 200 °C  
Viewed at 500x



18% RA  
37 in-lbs




13% RA  
15.5 in-lbs




5% RA  
16 in-lbs


Samples fractured at 200 °C  
Viewed at 900x



18% RA




13% RA




5% RA


## 25% Retained Austenite



## 3% Retained Austenite



## Residual stress and retained austenite reflect the service history



## Service Load Factor (SLF) :

Absolute residual stress (martensite) / %RA  
Normalized to new cones ( $42.5/22.5 = 1.88$ )



	Serviced Load Factor
New Product 0 lbs 0 miles	1.00
Typical Bench Test 34,500 lbs 250,000 miles	2.38
Typical Field Test 34,500 lbs 300,000 - 600,000	2.56
Failure Criterion 140ksi / 10% RA	7.50
Severe Overload	15.10

## 1 million miles

	Serviced Load Factor
1 million mile 66 OB *	6.56
1 million mile 66 IB	3.23
1 million mile 67 OB	3.40
1 million mile 67 IB	5.93
Failure Criterion 140ksi / 10% RA	7.50

## 1.2 million miles

	Serviced Load Factor
1 million mile 66 OB	10.67
1 million mile 66 IB	3.45
Failure Criterion 140ksi / 10% RA	7.50

\* One measurement = 7.89

---

---

1 million




1.2 million






## Retained Austenite of bearing cones, July 2004 – June 2005





---

---

# Steel Cleanliness and Ultrasonic Testing








# Objectives

---


- Phase 1 – Develop an automatic inclusion detection system for the purpose of quality inspections. System is able to scan a cup/cone and rank the cleanliness based on total number of indications per inspected volume.
- Phase 2 – Goal is to qualify premium components for certain heavy haul markets.
- Phase 3 – Ultrasonic testing integrated into the manufacturing process.

# Ultrasonic Scanning System







1. Pixel above 0% = 691200




2. Pixel above 30% = 8195




3. Pixel above 60% = 2059



4. Pixel above 80% = 1067



## C-scan (top) and TOF (bottom) for Chinese Steel






---

---


## C-scan (top) and TOF (bottom) for North European steel



## C-scan (top) and TOF (bottom) for USA steel




## C-scan (top) and TOF (bottom) for South European steel



---

---


## C-scan (top) and TOF (bottom) for Russian steel




---

---


## C-scan (top) and TOF (bottom) for Indian steel




# C-scan (top) and TOF (bottom) for ABD setouts



Sept 98



Aug 02




Mar 99


---

---

## C-scan (top) and TOF (bottom) for Korean steel




## Advanced Analysis



*In this example there are 6 inclusions*


- Any C-Scan image consists of pixels in a matrix format
- The pixels in grey indicate inclusions
- We need to form cluster of pixels which belongs to the same inclusion
- For every pixel, we look at its 8 neighboring pixels to decide which inclusion any particular grey pixel belongs to





- Fig. (a) - C-Scan
- Fig (b) - Post processing data from Fig. (a). Here each inclusion is denoted by individual color
- Fig (c) is the area of each inclusion
- Fig. (d) is the histogram of inclusion area distribution


# Korean vs. USA









Total Scan Area –  $7.1 \times 10^4 \text{ mm}^2$ ,  
Total Inclusion Area = 4,047  $\text{mm}^2$

Total Scan Area =  $7.1 \times 10^4 \text{ mm}^2$ ,  
Total Inclusion Area = 44.5  $\text{mm}^2$









---

---


# The Effects of Impacting Wheels




CO317H OB





X61H OB










# Dynamic Testing Results









### Bearing Acceleration at 6 Hz




Worst Case Hourglass Damage Area for Cumulative Impact Cycles





Steel Cage


Bearing Impact  
 Rotational  
 (plastic strain)  
 Polyamide Cage



# Bearing Trending

---

- Laboratory bearing testing has determined that the root cause of trending is due to roller misalignment caused by vibration
- Excessive tolerances and deformation of the cage can allow misalignment to occur ... multiple solutions under test:
- A collaborative field test with the UP validated the laboratory findings and future studies are underway.



---

---

Brent M. Wilson  
Amsted Rail  
February 12, 2010