

# **5R55W SHIFT KIT®**

Fits: S/W/N 1999-10

# This kit is about: Won't Move- Pump Noise No Lockup Hot- Code- Slip- Shudder Lockup Problems: Usually valve body caused, not the converter.

Trouble Codes: P1740, P0732, 733, 735

"Hello Shop: You are going to love this trans.

When it is right it's very efficient and smooth." Gil

Port Holes

This is not a "do it yourself" kit. It's for experienced, professional Transmission mechanics only.

#### 1. Flow Control Assembly

Install **solid** end of piston into bushing. Insert **YELLOW** spring into **hollow** end of the **Piston**.

Install **Retainer** into **Bushing** opposite port holes and under the spring.

**Original Flow Control Assembly** 

Sticks, causing won't move, wears out causing burned friction and noise. It is included in a new pump, and not sold separately. We believe the upgraded design will outlast the original part.



O-ring
Port holes
Big open passage.

Page 1

O-ring

Flow Control

**Assembly** 

Pump Body

**2.** Install with Port Holes

facing Big Open Passage.


#### 1. Assemble & Align Pump

Align pump **BEFORE** installing front seal. Start bolts, leave pump halves loose. Slide Pump Tool over stator spline. Push tool, while wiggling pump body making sure tool enters and snugs into the pump bushing. Tighten the pump bolts to 18 ft lbs.




#### **High Temp Low Shrink Direct Clutch Rings**

2. Install Rings on support. Don't squeeze ends together firmly, that could cause ring to be stuck in the groove.



With sealing rings removed look for cracks on the edge of the metal sleeve that continues under the bearing. Replace support if found. Over-heating of the trans increases this possibility.


**Delay forward** or burned direct



## 55W or S Valve Body

**5R55-N Valve Body: See Page 5** 


**IMPORTANT:** The retainer makes small burr on the inside edge of bushing groove. Using sharp end of a drill bit or sharpened screwdriver, carefully scrape off burr. Then remove bushing by **GENTLY** prying thru opening in bottom of VB.



New Lockup Valve No lockup, Shudder, Slip, and/or Code 1740.

LISTEN UP: If the trans has no lockup when hot, but the fluid and filter look OK: Then this page will fix it from the bottom.

Have Fun. Gil



1. Remove and discard original spring, lockup valve, bushing & inner valve.

2. Install new Lockup Valve. Make sure valve freely strokes to bottom of bore.

3. Remove new Lockup Valve and reassemble in the following order: Install **New White spring** and **Lockup Valve**. Install New Bushing and Inner Valve. Install Retainer. Lock-up will have **smoother engagement** & **more** capacity.

New Lockup Valve, Bushing & Inner Valve




**Spring** 

Remove & Discard Original Parts



New Lockup Valve increases lockup capacity to reduce-prevent slip, shudder and Codes while retaining a smooth engagement. Works on ALL MODEL CONVERTERS.

#### This page is for 5R55N Valve Body Only - Has Bottom Plate.




### Additional information for reducing comebacks.

Wrong Fluid Level is BIG Problem:

Check/Fill with Vehicle level, Engine running, Selector in Park. **TEMPERATURE: NOT HOT or Cold.** Must be 80° to 120°, warm to touch and yet be able to keep your hand on the pan.

Remove Allen plug in center of pan drain plug. Install Mercon 5 fluid thru Fill Hole, until fluid flows with steady stream out Allen plug hole. Reinstall Allen plug with sealer.



Overfull: Fluid will burp into bell housing.

Check Level:

Must run full stream out this hole. If just burping out--it is not full.

> Codes PO732 & PO735, 1-2 Slide Bump, 2-3 Flare, 4-5 Slide Bump or Trans has Burned OD Band.

**Drain Plug** 

**LOOK HERE:** Worn OD Band Servo Pin Bore Inspect bore in case for wear. If pin



Repair kit available www.servobore.com Or call 715-458-2617--FAX 715-458-2611

Intermediate and Overdrive band servo struts install with short side towards VB.



SK 5R55W 04Apr2013

**OD & Intermediate Band Adjust** Tighten adjusting screws snug with short wrench. Back off two turns and tighten the locknuts.



Page 6 © TransGo 2013