

**JSS MAHAVIDYAPEETHA**  
**JSS SCIENCE & TECHNOLOGY UNIVERSITY**  
**(JSS&TU)**  
FORMERLY SRI JAYACHAMARAJENDRA COLLEGE OF ENGINEERING  
**MYSURU-570006**

**DEPARTMENT OF MECHANICAL ENGINEERING**

**Foundry and Forging Laboratory Manual**  
**III Semester B.E. Mechanical Engineering**



USN : \_\_\_\_\_  
Name: \_\_\_\_\_  
Roll No: \_\_\_\_\_ Sem \_\_\_\_\_ Sec \_\_\_\_\_  
Course Name \_\_\_\_\_  
Course Code \_\_\_\_\_

## **DEPARTMENT OF MECHANICAL ENGINEERING**

### **VISION OF THE DEPARTMENT**

Department of mechanical engineering is committed to prepare graduates, post graduates and research scholars by providing them the best outcome based teaching-learning experience and scholarship enriched with professional ethics.

### **MISSION OF THE DEPARTMENT**

- M-1:** Prepare globally acceptable graduates, post graduates and research scholars for their lifelong learning in Mechanical Engineering, Maintenance Engineering and Engineering Management.
- M-2:** Develop futuristic perspective in Research towards Science, Mechanical Engineering Maintenance Engineering and Engineering Management.
- M-3:** Establish collaborations with Industrial and Research organizations to form strategic and meaningful partnerships.

### **PROGRAM SPECIFIC OUTCOMES (PSOs)**

- PSO1** Apply modern tools and skills in design and manufacturing to solve real world problems.
- PSO2** Apply managerial concepts and principles of management and drive global economic growth.
- PSO3** Apply thermal, fluid and materials fundamental knowledge and solve problem concerning environmental issues.

### **PROGRAM EDUCATIONAL OBJECTIVES (PEOS)**

- PEO1:** To apply industrial manufacturing design system tools and necessary skills in the field of mechanical engineering in solving problems of the society.
- PEO2:** To apply principles of management and managerial concepts to enhance global economic growth.
- PEO3:** To apply thermal, fluid and materials engineering concepts in solving problems concerning environmental pollution and fossil fuel depletion and work towards alternatives.

## PROGRAM OUTCOMES (POS)

- PO1 Engineering knowledge:** Apply the knowledge of mathematics, science, engineering fundamentals, and an engineering specialization to the solution of complex engineering problems.
- PO2 Problem analysis:** Identify, formulate, review research literature, and analyze complex engineering problems reaching substantiated conclusions using first principles of mathematics, natural sciences, and engineering sciences.
- PO3 Design/development of solutions:** Design solutions for complex engineering problems and design system components or processes that meet the specified needs with appropriate consideration for the public health and safety, and the cultural, societal, and environmental considerations.
- PO4 Conduct investigations of complex problems:** Use research-based knowledge and research methods including design of experiments, analysis and interpretation of data, and synthesis of the information to provide valid conclusions.
- PO5 Modern tool usage:** Create, select, and apply appropriate techniques, resources, and modern engineering and IT tools including prediction and modeling to complex engineering activities with an understanding of the limitations.
- PO6 The engineer and society:** Apply reasoning informed by the contextual knowledge to assess societal, health, safety, legal and cultural issues and the consequent responsibilities relevant to the professional engineering practice.
- PO7 Environment and sustainability:** Understand the impact of the professional engineering solutions in societal and environmental contexts, and demonstrate the knowledge of, and need for sustainable development.
- PO8 Ethics:** Apply ethical principles and commit to professional ethics and responsibilities and norms of the engineering practice.
- PO9 Individual and team work:** Function effectively as an individual, and as a member or leader in diverse teams, and in multidisciplinary settings.
- PO10 Communication:** Communicate effectively on complex engineering activities with the engineering community and with society at large, such as, being able to comprehend and write effective reports and design documentation, make effective presentations, and give and receive clear instructions.
- PO11 Project management and finance:** Demonstrate knowledge and understanding of the engineering and management principles and apply these to one's own work, as a member and leader in a team, to manage projects and in multidisciplinary environments.
- PO12 Life-long learning:** Recognize the need for, and have the preparation and ability to engage in independent and life-long learning in the broadest context of technological change.

## FOUNDRY AND FORGING LABORATORY

<b>Subject Code</b>	<b>:ME37L</b>	<b>No. of Credits</b>	<b>: 0 – 0-1.5</b>
<b>No. of Practical Hours / Week</b>	<b>: 03</b>	<b>Exam Hours</b>	<b>:03</b>
<b>Total No. of Lecture/Practical Hours</b>	<b>: 48</b>	<b>Exam Marks</b>	<b>:50</b>

### **COURSE OBJECTIVE:**

- 1. To provide students with the knowledge and necessary skills to perform sand testing and preparation of moulds.**
- 2. To provide students with the knowledge and necessary skills to perform metal forging operations and sheet metalwork.**

### **COURSE CONTENT**

#### **UNIT-1**

##### **Testing of Moulding sand and Core sand**

Preparation of sand specimen's and conduction of the following tests:

1. Compression, Shear and Tensile tests on Universal Sand Testing Machine.
2. Permeability test
3. Core hardness & Mould hardness tests.
4. Sieve Analysis to find Grain Fineness number of Base Sand
5. Clay content determinations in Base Sand

##### **Foundry Practice**

Use of foundry tools and equipment. Preparation of moulds using two moulding boxes using patterns or without patterns. (Split pattern, Match plate pattern and Core boxes). Preparation of one casting (Aluminum or cast iron-Demonstration only)

**24 Hours**

#### **UNIT-2**

##### **Forging Operations:**

1. Calculation of length of the raw material required to do the model.
2. Preparing minimum three forged models involving upsetting, drawing and bending operations.
3. Out of these three models, at least one model is to be prepared by using Power Hammer.

##### **Sheet Metal Work:**

Preparation of four models involving development of surfaces of regular solids, transition pieces and trays

**24 Hours**

## **COURSE OUTCOMES**

Upon completion of this course, students should be able to:

- CO1 Demonstrate the knowledge and necessary skills to perform sand testing and preparation of moulds.**
- CO2 Demonstrate the knowledge and necessary skills to perform metal forging operation and sheet metal work.**



**JSS MAHAVIDYAPEETHA**  
**JSS SCIENCE & TECHNOLOGY UNIVERSITY, MYSURU**

**SRI JAYACHAMARAJENDRA COLLEGE OF ENGINEERING, MYSURU**

*Department of Mechanical Engineering*

**LABORATORY SAFETY PRECAUTIONS**

1. Laboratory uniform, shoes & safety glasses are compulsory in the lab.
2. Do not touch anything with which you are not completely familiar. Carelessness may not only break the valuable equipment in the lab but may also cause serious injury to you and others in the lab.
3. Please follow instructions precisely as instructed by your supervisor. Do not start the experiment unless your setup is verified & approved by your supervisor.
4. Do not leave the experiments unattended while in progress.
5. Do not crowd around the equipment's & run inside the laboratory.
6. During experiments material may fail and disperse, please wear safety glasses and maintain a safe distance from the experiment.
7. If any part of the equipment fails while being used, report it immediately to your supervisor. Never try to fix the problem yourself because you could further damage the equipment and harm yourself and others in the lab.
8. Keep the work area clear of all materials except those needed for your work and cleanup after your work.

**'Instructions to the Candidates'**

1. Students should come with thorough preparation for the experiment to be conducted.
2. Students will not be permitted to attend the laboratory unless they bring the practical record fully completed in all respects pertaining to the experiment conducted in the previous class.
3. Experiment should be started only after the staff-in-charge has checked the experimental setup.
4. All the calculations should be made in the observation book. Specimen calculations for one set of readings have to be shown in the practical record.
5. Wherever graphs are to be drawn, A-4 size graphs only should be used and the same should be firmly attached to the practical record.
6. Practical record should be neatly maintained.
7. They should obtain the signature of the staff-in-charge in the observation book after completing each experiment.
8. Theory regarding each experiment should be written in the practical record before procedure in your own words.



**JSS MAHAVIDYAPEETHA  
JSS SCIENCE & TECHNOLOGY UNIVERSITY, MYSURU**

**SRI JAYACHAMARAJENDRA COLLEGE OF ENGINEERING, MYSURU**

*Department of Mechanical Engineering*

**CONTENTS**

<b>Exp. No.</b>	<b>Title of the Experiment</b>	<b>Page No.</b>
<b>UNIT - 1</b>		
<b>TESTING OF MOULD AND CORE SAND</b>		
01	Properties of Moulding Sand	7-7
02	Sand Testing Experiments	8-8
03	Compression strength test for moulding sand	9-11
04	Shear strength test for moulding sand	13-15
05	Tensile strength test of core sand	16-20
06	Permeability test	21-25
07	Core hardness and mould hardness test	26-27
08	Sieve analysis to find grain fineness number of base sand	28-31
09	Clay content test	32-35
<b>FOUNDRY</b>		
01	Foundry -Introduction	37-39
02	Core and Core Making	40-50
03	Solid Pattern	50-51
04	Hand Cutting	52-54
05	Self-Cored Pattern	55-56
06	Stepped Cone Pulley with Core Print	57-57
07	Split Pattern with Two Halves	58-58
08	Split Pattern with Two Halves	59-64

<b>UNIT - 2</b>		
<b>FORGING</b>		
01	Forging Introduction	66-79
02	Square Section Prism	80-81
03	Square Section Nail	82-83
04	T-bolt (hexagonal)	84-84
<b>SHEET METAL WORK</b>		
01	Sheet Metal -Introduction	85-92
02	Development of Hexagonal Prism	93-94
03	Development of Pentagon Prism	95-96
04	Development of Truncated Square Pyramid	97-98
05	Development of Frustum of Cone	99-101
06	Development of Rectangular Tray	102-103
07	Viva Questions with answers	104-109



## **UNIT - 1**

### **TESTING OF MOULD SAND AND CORE SAND**

**Date:**

## **PROPERTIES OF MOULDING SAND**

Good moulding sand must possess the following properties. The properties are determined by the amount of clay, moisture content and by the shape and size of the silica grain in the sand.

### **PERMEABILITY:**

It is the ability of sand to allow the gasses to escape from the mould.

### **COHESIVENESS OR STRENGTH:**

This is the ability of sand particles to stick together. Insufficient strength may lead to a collapse in the mould or its partial destruction during conveying turning over or closing.

### **ADHESIVENESS:**

The sand particles must be capable of adhering to another body, i.e, they should cling to the sides of the moulding boxes.

### **PLASTICITY:**

It is the property to retain its shape when the pressure of the pattern is removed.

### **REFRACTORINESS:**

The sand must be capable of withstanding the high temperature of the molten metal without fusing.

### **BINDING:**

Binder allows sand to flow to take up pattern shape.

### **CHEMICAL RESISTIVITY:**

Moulding sand should not chemically react or combine with molten metal so that it can be used again and again.

### **FLOWBILITY:**

It is the ability of sand to take up the desired shape.

Date:

## **SAND TESTING EXPERIMENTS**

Periodic test is necessary to determine the essential qualities of foundry sand.

The most important tests to be conducted for any foundry sand are as follows.

### **1. Compression, shear and tensile strength test on universal sand testing machine.**

#### **Purpose:**

- i) Moulding sand must have good strength otherwise it may lead to collapse of mould.
- ii) It must be retained when the molten metal enters the mould (bond strength)
- iii) To retain its shape when the pattern is removed and movement of the mould.

### **2. Permeability test.**

It is the property of moulding sand which allows gases to pass through easily in the mould.

### **3. Core and mould hardness test.**

The hardness test is useful to find out the mould's surface uniformly.

### **4. Sieve analysis to find the grain fineness number of base sand.**

To find the average grain fineness number for the selection of fine, medium, and coarse sand.

### **5. Clay content determination in base sand.**

It is to find the % of the clay content in the base sand.

## **COMPRESSION STRENGTH TEST FOR MOULDING SAND**

**AIM:** To find the green compression strength of the given specimen at different percentage of clay and moisture

**Materials used:** Base sand, clay, water,

**Apparatus used:** Sand Ramming machine (Rammer) with specimen tube with base, stripper, universal sand testing machine with Compression shackles, weighing pan, measuring jar, steel scale, Electronic weighing scale.

### **Theory:**

1. Periodic tests are necessary to check the quality of foundry sand and compression strength test is one among them.
2. The constituents of moulding sand are silica sand, clay, water and other special additives.
3. Clay imparts the necessary bonding strength to the moulding sand when it is mixed with water etc. bentonite.
4. Compression test determines the bonding or adhesiveness power of various bonding materials in greensand.
5. The green compressive strength of foundry sand is the maximum compression strength a mixture is capable of developing when it is in most condition.

### **Procedure:**

1. Conduct the experiment in two parts:
  - a) Vary the clay content keeping the water content constant
  - b) Vary the water content keeping the clay content constant
2. Take weighed proportions of sand and clay and dry mix them together in a Muller for 3 minutes.
3. Adjust the weight of the sand to get standard specimen
4. Remove the standard specimen by the stripper and place it between shackles which are fixed in the sand testing machine.
5. Rotate the handle of the testing machine to actuate the ram. Thus, hydraulic pressure is applied continuously till the specimen ruptures.
6. Read the compression strength from the gauge and record the same.
7. Conduct the experiment for the above said two cases and tabulate the result.

## Result and discussion

Plot the graphs with compression strength on y-axis & percentage clay on x-axis and the other with compression strength on y-axis v/s percentage water on x-axis.

Discuss the result with respect to the variation of percentage of clay on compression strength and percentage of water on compression strength.

### TABULAR COLUMN

#### VARYING THE % OF CLAY

Sl. No.	Percentage of sand	Percentage of clay	Percentage of water	Compression Strength gm/cm <sup>2</sup>
1				
2				
3				

#### VARYING THE % OF WATER

Sl. No.	Percentage of sand	Percentage of clay	Percentage of water	Compression Strength gm/cm <sup>2</sup>
1				
2				
3				




Fig 1.1 Universal Strength Machine




Fig 1.2 Sand Rammer

Date.....

Signature of the Faculty

## SHEAR STRENGTH TEST FOR MOULDING SAND

**AIM:** To determine the green shear strength of the given specimen for different percentages of clay and moisture.

**Materials used:** Base sand, clay, water.

**Apparatus used:** Sand ramming machine (rammer), universal sand testing machine with attachments, weighing pan.

### **Theory:**

1. Shear strength is the ability of sand particles to resist the shear stress and to stick together.
2. Insufficient Shear strength may lead to the collapsing of sand in the mould or its partial destruction during handling. The mould and core may also be damaged during flow of molten metal in the mouldcavity.
3. The moulding sand must possess sufficient strength to permit the mould to be formed to the desired shape and to retain the shape even after the hot metal is poured into the mould cavity.
4. In shearing, the rupture occurs parallel to the axis of thespecimen.

### **Procedure:**

1. Conduct the experiment in twoparts:
  - a) Vary the clay content keeping the water contentconstant
  - b) Vary the water content keeping the clay contentconstant
2. Take weighed amount of foundry sand (mixture of sand, clay & water asspecified).
3. Transfer the sand mixture into the tube and ram it with the help of a sand rammerthrice.
4. Fix the shackles to the universal sand testingmachine.
5. Remove the specimen from the tube with the help of a stripper and load it into the universal sand testingmachine.
6. Apply the hydraulic pressure by rotating the handle of the universal sand testing machine continuously until the specimenruptures.
7. Read the shear strength directly from the scale and tabulate thereadings.

## TABULAR COLUMN

### VARYING THE % OF CLAY

Sl. No.	Percentage of sand	Percentage of clay	Percentage of water	Compression Strength gm/cm <sup>2</sup>
1				
2				
3				

### VARYING THE % OF WATER

Sl. No.	Percentage of sand	Percentage of clay	Percentage of water	Compression Strength gm/cm <sup>2</sup>
1				
2				
3				

### Graphs:

- a) Shear strength (Y-axis) V/s Percentage of clay(X-axis).
- b) Shear strength (Y-axis) V/s Percentage of water(X-axis).




**Results and Discussions:**

The Graphs above reveal:

- a) With the increase in the percentage of water the shear strength of the specimen.....
  
- b) With the increase in the percentage of clay the shear strength of the specimen.....

**Shear Strength Attachment**



**Fig. 2.1 Shear Strength Attachment**

Date.....

Signature of the Faculty

## TENSILE STRENGTH TEST OF CORE SAND

**AIM:** To determine the tensile strength of sand using two types of binders Viz. core oil binder and sodium silicate binder.

**Materials used:** Base sand, core oil, sodium silicate.

**Apparatus used:** universal sand testing machine, Split core box, Sand rammer, oven, tension shackles.

### **Theory:**

1. A core is compacted sand mass of a known shape.
2. When a hollow casting (to have a hole – through or blind) is required, a core is used in the mould or when a complex contour is required a mould is created out of cores. This core has to be properly seated in the mould on formed impressions in the sand. To form these impressions extra projections called core points are added on the pattern surface at proper places.
3. Core boxes are used for making cores. They are either made single or in two parts. Their classification is generally according to the shape of the core or the method of making the core.
4. Split core box is very widely used and is made in two parts, which can be joined together by means of dowels to form the complete cavity for making the core.
5. The purpose of adding binder to the moulding sand is to impart strength and cohesiveness to the sand to enable it to retain its shape after the core has been rammed.
6. Binders used can be
  - a) Organic: ex. Dextrin, Core oil
  - b) Inorganic: ex. Sodium silicate, Bentonite
7. Classification of binders:
  - a. Baking type: Binding action is realized in the sand after baking the sand mixture in an oven.

- b. Gassing type: Binding action is obtained in the sand after passing a known gas through the sand mixture.

Ex.  $\text{CO}_2$  gas passed through a mixture of sand and sodium silicate.

8. Core oil is used as binder that hardens with the addition of heat. The sand and binder are mixed and baked at a temperature of  $250^\circ - 300^\circ \text{C}$  and binding action takes place within few hours.
9. Sodium silicate is a self-setting binder and no external heat is required for the binding action which takes place at room temperature when  $\text{CO}_2$  gas is passed.
10. During casting the core is placed inside the mould and the molten metal is poured into the cavity. As the molten metal begins to cool, it begins to contract on the inner radius as well as the outer radius. Due to the contraction of the inner radius the core sand will be pulled outwards causing a tensile load around the core. Hence knowledge of tensile strength of core sand is important.

#### **Procedure:**

1. Conduct the experiment in two parts.
  - a. Using core oil as binder and
  - b. Using sodium silicate as binder.
2. Take proper proportions of base sand and binder then mix them together thoroughly.
3. Assemble the core box and fill the mixture into it.
4. Place the core box under sand rammer and ram the sand thrice.
5. Using a wooden piece tap the core box gently from sides. Remove the core box leaving the rammed core on a flat metal plate.
6. Bake the specimen (which is on a plate) for about 30 minutes at a temperature of  $150^\circ - 200^\circ \text{C}$  in an oven. (When the binder is core oil)
7. If the binder is sodium silicate, pass  $\text{CO}_2$  gas for 5 secs. The core hardens instantly and the core can be directly used.
8. Fix the tension shackles on to the sand testing machine, and place the hardened specimen

in the shackles.

9. Apply the load gradually by turning the hand wheel of the testing machine. Note down the readings when the specimen breaks.

10. Repeat the procedure for the different percentage of binder and tabulate the readings.

**TABULAR COLUMN**


Sl. No.	Percentage of sand	Percentage of Sodium Silicate or core oil	Tensile strength N/m <sup>2</sup>	
1				
2				
3				
4				
5				
6				

Result and discussion:


Plot the graph of tensile strength on y-axis and binder on x-axis. Discuss the effect of variation of binder content on tensile strength.

**Figures to be drawn:**


- 1) Split core box for tensile specimen(Fig. 3.1)
- 2) Tensile stress on core(Fig. 3.2 a and Fig.3.2 b)
- 3) Dimensions of standard tensile specimen(Fig.3.3)
- 4) Tensile test shackles(Fig. 3.4)




**Fig. 3.1 Split core box (Tension)**




**Fig. 3.3 Dimensions of standard tensile**



**Fig. 3.4 Tensile test shackles**



**Fig. 3.2 a: Tensile Core Box**



**Fig. 3.2 b: Tensile strength attachment**

Date.....

Signature of the Faculty

## **PERMEABILITY TEST**

**AIM:** To find the effect of water content, clay content on green permeability of foundry sand.

**Materials used:** Base sand, clay and water.

**Apparatus used:** Sand rammer, Permeability meter, Electronic weighing scale, stripper, stop watch, measuring jar, specimen tube, specimen tube cup.

### **Theory:**

1. Molten metals always contain certain amount of dissolved gases, which are evolved when the metal starts freezing.
2. When molten metal comes in contact with moist sand, generates steam or water vapour.
3. Gases and water vapour are released in the mould cavity by the molten metal and sand. If they do not find opportunity to escape completely through the mould, they will get entrapped and form gas holes or pores in the casting. The sand must therefore be sufficiently porous to allow the gases and water vapour to escape out. This property of sand is referred to as permeability.
4. Permeability is one of the most important properties affecting the characteristic of moulds which depends upon the grain size, grain shape, grain distribution, binder content, moisture level and degree of compactness.
5. Permeability is a physical property of the physical sand mixture, which allows gases to pass through it easily.
6. The AFS (American Foundry Men Society) definition of permeability is “the number obtained by passing 2000cc of air through a standard specimen under a pressure of 10 gm/cm<sup>2</sup> for a given time in minutes”.
7. The permeability number  $P_N$  can be found out by the equation

$$P_N = \frac{(VH)}{(PAT)}$$

Where

V = Volume of air passing through the specimen, 2000cc

H = Height of the specimen = 50.8 mm (standard value)

P = Pressure as read from the manometer in gm/cm<sup>2</sup>

A = Area of the specimen =  $\pi d^2/4$

Where d = 50.8 mm (standard value)

T = time in minutes for 2000 cc of air passed through the sand specimen.

### **Experimental setup details:**

Permeability meter has a cylindrical water tank in which an air tank is floating. By properly opening the valve, air from the air tank can be made to flow through the sand specimen and a back pressure is setup. The pressure of this air is obtained with the water manometer. The meter also contains the chart, which directly gives the  $P_N$  depending on pressure.

### **Procedure:**

1. Conduct the experiment in two parts. In the first case vary water percent keeping clay percent constant. In the second case vary clay percent and keep water percent constant.
2. Take weighed proportions of sand dry mix them together for 3 minutes. Then add required proportions of water and wet mix for another 2 minutes, to get a homogeneous and mixture. Take the total weight of the mixture between 150-200 grams. The correct weight has to be determined by trial and error method.
3. Fill the sand mixture into the specimen tube and ram thrice using sand rammer. Use the tolerance limit provided at the top end of the rammer for checking the specimen size. If the top end of the rammer is within the tolerance limit, the correct specimen is obtained. If it lies below the limit, increase the weight of sand mixture and prepare a new specimen. The specimen conforming to within limits represent the standard specimen required.
4. Now the prepared standard specimen is having a dia.50.8mm and height 50.8mm.



5. Place the standard specimen along with the tube in the inverted position on the rubber seal or on the mercury cup (specimen in the top position in the manometer reading).
6. Operate the valve and start the stop watch simultaneously. When the zero mark on the inverted jar just touches the top of water tank, note down the manometer reading.
7. Note down the time required to pass 2000cc of air through the specimen. Calculate the permeability number by using the formula given.

**Direct scale reading:**

The permeability can also be determined by making use of the graduated marker provided near the manometer.

**Procedure to be followed:**

- Coincide the graduations on the transparent scale with the meniscus of the manometer liquid.
- Note the reading of the scale.
- This reading represents the permeability number of the sand.

**TABULAR COLUMN**

Varying the percentage of Clay and keeping percentage of Water constant. Indicate percentage of Clay (No. of arms = 3)

Sl. No.	Percentage of Clay	Pressure gm/cm <sup>2</sup>	Time in min.	P <sub>N</sub>	
				Indicated	Calculated
1					
2					
3					

Varying the percentage of water and keeping percentage of Clay constant. Indicate percentage of Water (No. of arms = 3)


Sl. No.	Percentage of water	Pressure gm/cm <sup>2</sup>	Time in min.	P <sub>N</sub>	
				Indicated	Calculated
1					
2					
3					

**Draw graph:**

Permeability number v/s % Clay

Permeability number v/s % water

Discuss the effect of water and clay on Permeability



**Fig. 4.1 Permeability Meter**

Date.....

Signature of the Faculty

**CORE HARDNESS AND MOULD HARDNESS TEST**

Mould and core hardness can be found out by the hardness – tester which is based on the same principle as Brinell hardness tester. A steel ball of 50 mm diameter weighing 237 gm is pressed on the mould surface. The depth of penetration of steel ball will give the hardness of mould surface on the direct reading dial. This hardness test is useful in finding out the mould uniformity




Fig. 5.1 Mould Hardness Tester

The following are the moulding hardness numbers for

Moulding sand (1 number = 1/100 mm)

Soft rammed moulds = 100

Medium rammed moulds =125

Hard rammed mould = 175

**Tabular column for Core Hardness Test**

Sl. No.	% of Sand	% of sodium silicate	Core Hardness Number
1			
2			
3			

**Tabular column for Mould Hardness Test**

Sl. No.	% of Sand	% of Water	Mould hardness Number
1			
2			
3			

**Date.....**

**Signature of the Faculty**

**SIEVE ANALYSIS TO FIND GRAIN FINENESS NUMBER OF BASE SAND**

**AIM:** To find the distribution of sand grains using a set of sieves and to find the average grain fineness number.

**Materials used:** Base sand- Silica sand.

**Apparatus used:** Electronic weighing scale, stop watch, sieve shaker.

**Theory:**

1. The base sand is a mixture of grains having a variety of shapes such as
  - a) Round
  - b) sub-angular
  - c) angular
  - d) compounded grains.Base sand is relatively free from any binder or additives.
2. Depending on the average size of the grains, the sand can be grouped into:
  - a) Fine
  - b) Medium
  - c) Coarse grains.
3. The shape and size of grains has a large influence on the permeability of sand mix as well as on the bonding action.
4. The shape and size of grains determine the possibility of its application in various types of foundry practice.

Ex: Fine grain sand results in good surface, on the casting but gases cannot escape out of the mould made from it. Coarse grain sand allows gases to escape out easily but the casting surface will be very rough. Hence grain size should select appropriately.

5. The given size of sand grains is designated by a number called grain fineness number that indicates the average size of grains in the mixture.

6. The size is determined by passing the sand through sieves having specified apparatus which are measured in microns.
7. The sieve number designates the pore size through which the sand grains, may pass through it or retained in it.
8. Average grains fineness number can be found out by the equation

$$GFN = Q/P$$

Where Q = sum of product of percentage sand retained in sieves and Corresponding multiplier.

P = sum of percentage of sand retained in sieves.

**Procedure:**

1. Take 50 gm or 100 gm of dry sand and place in the top sieve of a series and close the lid.
2. Place the whole assembly of sieves on the vibratory sieve shaker and clamp it.
3. Switch on the motor and allow the sieve assembly to vibrate for 5 minutes. Then switch off the motor.
4. Collect the sand particles retained in each of the sieve separately and weigh in Electronic weighing scale and enter into the tabular column. Calculate the percentage weight retained by each of the sieves. Multiply this value with the multiplier for each sieve.

(Calculate the average GFN using the formula as shown below.)

**Tabular Column:**

Total weight of sand taken = 100g.

Sl. No.	(a) Sieve No. in microns	(b) Weight in grams		(c) % Retained	(d) Multiplying factor	(e) Product $\Sigma e = c \times d$
		Empty Sieve $W_1$	Sieve with sand $W_2$			
1	1700				5	
2	850				10	
3	600				20	
4	425				30	
5	300				40	
6	212				50	
7	150				70	
8	106				100	
9	75				140	
10	53				200	
11	Sieve pan				300	

$$P = \Sigma c$$

$$Q = \Sigma e$$


$$\% \text{ Retained } C = \frac{\text{Weight of sand in each sieve}}{\text{Total weight of sand}} \times 100$$

Calculation: AFS grain number =  $Q$  (sum) /  $P$  (total)

Results; The average grain fineness number is =

Graph: Percentage of sand retained v/s sieve number





**Fig. 6.1 Sieve Shaker**

**Date.....**

**Signature of the Faculty**

## CLAY CONTENT TEST

**AIM:** To determine the percentage of clay present in base sand.

**Materials used:** Base sand, 5 % NaoH solution and water.

**Apparatus used:** Wash bottle, measuring jar, mechanical stirrer and siphon tube.

### **Theory:**

1. Clay can be those particles having less than 20 microns size. Moulding sand contains 2 to 50 percent of clay. When mixed with water it imparts, binding strength and plasticity.
2. Clay consists of two ingredients a) Fine silt and b) True clay. Fine silt has no binding power whereas true clay imparts the necessary boundary strength to the moulding sand; thereby the mould does not lose its shape after ramming.
3. Clay also can be defined as those particles which when mixed with water, agitated and then made to settle, fails to settle down at the rate of 1"/mm.
4. The particles of clay are plate like in form and have a very large surface area compared to its thickness and therefore have a very high affinity to absorb moisture.
5. Clay is the main constituent in a moulding sand mixture other than sand grains. Clay imparts binding action to the sand and hence the strength.
6. Clay is of mineral origin available in plenty on earth. It is made of alumina silicate. The types of clay are a) montmorillonite b) Kaolinite and c) Illite the first type is generally referred to as Bentonite.

Clay is the main constituent in a moulding sand mixture other than sand grain. Clay helps impart binding action to the sand and hence strength to the sand.

### **Procedure:**

1. Take 100g of base sand in a wash bottle and add 475ml of distilled water and 25ml of NaOH solution to it.

2. Using the mechanical stirrer, stir the mixture for about 5 minutes add distilled water to make up the level to 6" height. Stir the mixture again for 2 minutes. Now allow the content of the bottle to settle down.
3. Siphon out 5" level of unclean water using a standard siphon.
4. Add distilled water again up to 6" height and stir the content again. Allow the mixture to settle down for 5 minutes.
5. Siphon out 5" level of water from the bottom of the bottle

Repeat the above procedure for 3-4 times till the water becomes clear in the wash bottle.

6. Transfer the wet sand from the bottle in to a tray and dry in it in an oven at 110 ° C to remove moisture. Note down the dry sand weight accurately. Using the calculations find percentage of clay.

### Calculations

Weight of sand W1= 100 gm


Weight of dried sand W2 = ----- gm

$$\% \text{ of clay} = \frac{(W1 - W2) \times 100}{100}$$

### Results and discussion:

The % of clay is -----%

Discuss whether the % of Water is present is high or low and whether this % is enough to act as binder in the sand.



**Fig 7.1 Clay Washer**

**Date.....**

**Signature of the Faculty**

**UNIT - 1**  
**FOUNDRY**

# FOUNDRY

## **Introduction:**

Foundry is a process of shaping the metal components in their molten stage. It is also called as metal casting. The shape and size of the metal casting is obtained depends on the shape and size of the cavity produced in sand mould by using wooden/ metal pattern.

## **Practical application**

1. Casting is the cheapest and most direct way of producing the shape of the component
2. Casting is best suited to work where components required is in low quantity.
3. Complicated shapes having internal openings and complex section variation can be produced quickly and cheaply by casting since liquid metal can flow into any form/ shape.  
Example: 1. Outer casing of all automobile engines.

2. Electric motor housing

3. Bench vice, Irrigation pump etc.

4. Heavy equipment such as machine beds of lathe, milling machine, shaping, drilling planing machine etc. can be cast/easily
5. Casting is best suited for composite components

Example.1: steel screw threads in zinc die casting

All conductors into slot in iron armature for electric motor.

## **Steps in foundry process**

The Foundry process involves three steps.

- (a) Making the required pattern
- (b) Moulding process to produce the cavity in sand using pattern.
- (c) Pouring the molten metal into the cavity to get casting.

## Classification of foundries;

- Steel foundry
- C.I foundry
- Light alloy foundry
- Brass foundry
- Shell moulding foundry
- Die casting foundry (using permanent metal or dies for high volume of low and pressure die)

## Pattern:

A pattern is normally a wooden/ metal model or thermosetting plastic which is facsimile of the cast product to be made, there are many types of pattern and are either one piece, two piece or three piece, split pattern, loose piece pattern, Gated and match plate pattern etc.

Pattern size: Actual casting size + shrinkage allowance + shake allowance + finish allowance

1. Shrinkage allowance: The liquid metal shrinks during solidification and its contraction to its room temperature, so that the pattern must be made larger than the casting to provide for total contraction.
2. Finishing allowance: The casting is to be machined at some points then the casting should be provided with excess metal for machining.

## Types of foundry sand

1. **Natural sand:** Sand containing the silica grains and clay bond as found. It varies in grain size and clay content. Collected from natural sources.
2. **Synthetic sand:** It is an artificial sand obtained by mixing relatively clay free sand, binder (water and bentonite). It is better moulding sand as its properties can be easily controlled.
3. **Facing sand:** It is the fine grade sand used against the face of the pattern and finally governs the surface finish of the casting.
4. **Parting sand:** It is fine dry sand + brick dust used to preserve the joint face between the cope and the drag.

**Natural Greensand**= sand+ clay+ moisture

(10to15%) (7 to9%)

**Synthetic Greensand**= sand+ clay+ moisture

(5to7%) (4 to8%)

5. **Green sand:** moulding is the most common moulding process
6. **Dry sand mould:** Dry sand mould refer to a mould which is artificially dried before the molten metal is poured into it.  
Dry sand moulds are costly, stronger, used for complicated castings, i.e. avoid casting defects, casting gets smoother surface.

#### **Moulding methods:**

- **Bench moulding:** In this method the moulding is carried out on convenient bench and moulds are relatively small.
- **Floor moulding:** In this method the moulding is carried out in medium and large moulds are carried out on the floor.
- **Plate moulding:** For large quantity production and for very heavy casting two plates may be used with pattern.
- **Pit moulding:** In this method the moulding is carried out in the pits and generally very large moulds are made.
- **Machine moulding:** A machine is used to prepare moulds of small and medium. This method is faster and gives uniform moulding.



## CORE AND CORE MAKING

**CORES:** Cores are sand blocks they are used to make hollow portion in a casting. It is placed in a mould so that when molten metal is poured into the mould. This apart of mould will remain vacant i.e. the molten metal will not fill this part of the mould. So, when the mould is broken and the castings removed a hollow portion will result in the casting.

Core sand= Moulding sand+ binders (ABC core oil) or sodium silicate

**Core making:** Cores are made separately in a core box made of wood or metal.




Fig. 8.1 Core making

### **Core binders**

1. Water soluble binders (2 to 4% byweight)
2. Oil binders (1-3% byweight)
3. Pitch and resin binders (1-35 byweight)

The sand is treated with binder to achieve cohesion

### **Core Baking**

The core is baked (hardened) by heating at 150C depends on core size in oven.

This hardening of the core helps to handle and to place the core in the mould.

The core is supported in the mould by projection known as core prints.











Fig. 8.2 Nomenclature of a Mould

MOULDING TOOLS & EQUIPMENTS





Flange bed



Boss tool



scoth cleaner




straight bead




English cleaner



girdar tool



fluted bead





Gate knife



Spoon tool



Safe edge heart and upset




Smoothers




Bellows

Selected  
centre line



finished component


Locating dowels



Two halves of pattern

Lower half of moulding box (drag)


green sand




turnover board

facing sand











(a) Coke fired



(b) Oil/Gas fired



(c) Resistance type

### Pin Type Furnaces

**Trowels:** These are used for working up into a square corner.

**Taper trowel:** It is more useful for working along the curved edges of a pattern. trowels are measured by the length and width of the blade.

**Slicks:** Used for repairing and slicking small surfaces. They are named according to the shape of the blade and measured at the widest part of the blade.

**Lifters and Cleaners:** They are used to clean & finish the bottom and sides of deep narrow openings.

**Gate Knife:** is for cutting the channel from the mould to the bottom of the runner or riser.

**Spoon tool:** is convenient for cutting the pouring basin.

**Corner Slicks:** are, as the shape implies, for finishing off fillets and corners of moulds.

**Draw Spike:** is a spike for knocking into the wooden pattern in order to withdraw it.

**Draw Screw:** is for the same purpose as the draw spike; the end is threaded to screw into the rapping plate.

**Swap:** is a soft – pointed brush for moistening the edges of the mould before lifting the pattern. The angle at which it is held will decide the area to be covered. Care must be taken not to get the sand too damp.




**Bellows:** are used for blowing out loose sand from the completed mould; they must be used gently; too vigorous use will damage the mould.

## **Working steps in making the sand casting:**

- Place the pattern on the turn overboard.
- Place the drag around the pattern with upside and sprinkle the parting sand at the bottom.
- Fill the Moulding sand over the pattern pack, Ram, Jolt & squeeze.
- Level the bottom drag surface by leveler & turn over the drag.
- Sprinkle the parting sand, place the cope on the drag to suit the drag slot.
- Select the in and out gate in the drag, Place the sprue pins.
- Fill the moulding sand around the sprue pins pack, Ram, Jolt and Squeeze & level the surface.
- Make vent holes on both the boxes with the help of vent wire.
- Remove the sprue pin & Separate cope from drag.
- Remove the pattern carefully with the help of draw pin, Cut gate ways to flow the molten metal.
- Form the funnel shape on runner & riser, Hole to pour the molten metal on the top of the cope box.
- Join the two boxes with clamps, Now the mould is ready to pour the molten metal.

# Solid Pattern

## Calculation for solid Pattern



M= Mass of the Product

M<sub>1</sub>=Mass of the Hexagonal prism

M<sub>2</sub>= Mass of the Square

M<sub>1</sub>=Volume x Density  
a=30mm=3cm

$$=2.6 \times a^2 \times h \times \rho \quad h=25\text{mm}=2.5\text{cm}$$

$$=2.6 \times 3^2 \times 2.5 \times 2.70 \quad \rho = 2.70 \text{ gm/cm}^3$$

$$=157.95\text{gms}$$

M<sub>2</sub>=Volume x Density  
l=100mm=10cm

$$=l \times b \times h \quad b=100\text{mm}=10\text{cm}$$

$$=10 \times 10 \times 2.5 \times 2.70 \quad \rho = 2.70\text{gm/cm}^3$$

$$=675\text{gms}$$

M=m<sub>1</sub>+m<sub>2</sub>

$$=832.95\text{gms}$$

Add 30% Extra=249.89




$$=832.95+249.89$$

$$=1082.83\text{gms}$$

**Date.....**

**Signature of the Faculty**

Hand Cutting



## Calculation for Hand Cutting

M= Mass of the Product

m1=Mass of the Cylinder

m2= Mass of the Square

$$\begin{aligned}m1 &= \text{Volume} \times \text{Density} & d &= 100\text{mm} = 10\text{cm} \\m1 &= A \times L \times \rho & L &= 30\text{mm} = 3\text{cm} \\&= \pi d^2/4 \times L \times \rho & \rho &= 2.70 \text{ gm/cm}^3 \\&= 636.17\text{gms}\end{aligned}$$

$$\begin{aligned}m2 &= \text{Volume} \times \text{Density} & l &= 20\text{mm} = 2\text{cm} \\&= l \times b \times h & b &= 50\text{mm} = 5\text{cm} \\&= 2 \times 5 \times 5 \times 2.70 & \rho &= 2.70\text{gm/cm}^3 \\&= 135\text{gms} & h &= 50\text{mm} = 5\text{cm}\end{aligned}$$



$$\begin{aligned}M &= m1 + m2 \\&= 771.17\text{gms}\end{aligned}$$

$$\begin{aligned}\text{Add 30\% Extra} &= 231.35 \\&= 771.17 + 231.35 \\&= 1002.52\text{gms}\end{aligned}$$

Date.....

Signature of the Faculty

Self-Cored Pattern





## Calculation for Self-Cored Pattern

M= Mass of the Product

m1=Mass of the Cylinder (a)

m2= Mass of the Cylinder (b)

m3= Mass of the Cylinder (c)

m1=Volume x Density                      d=90mm=9cm

$$m1=A \times L \times \rho$$

$$L=25\text{mm}=2.5\text{cm}$$

$$= \pi d^2/4 \times L \times \rho \quad \rho = 2.70 \text{ gm/cm}^3$$

$$=432.59\text{gms}$$

m2=Volume x Density                      d=65mm=6.5cm

$$m2=A \times L \times \rho \quad L=5\text{mm}=2.5\text{cm}$$

$$= \pi d^2/4 \times L \times \rho \quad \rho = 2.70 \text{ gm/cm}^3$$

$$=225.64\text{gms}$$

m3 =Volume x Density                      d=40mm=4cm

$$m3 =A \times L \times \rho \quad L=50\text{mm}=5\text{cm}$$

$$= \pi d^2/4 \times L \times \rho \quad \rho = 2.70 \text{ gm/cm}^3$$

$$=170.90\text{gms}$$

M=m1+m2-m3

$$=487.29\text{gms}$$

Add 30% Extra=146.18



$$=487.29+146.18$$

$$=633.47\text{gms}$$

Date.....

Signature of the Faculty


**Stepped Cone Pulley with Core Print**



Date.....

Signature of the Faculty

Split Pattern with Two Halves



Date.....

Signature of theFaculty

## Estimation of Material Costs

In this chapter the material cost means the direct material cost. The frequently used materials are: Aluminum, Copper, Gunmetal, Brass, Iron, Tin, Magnesium, Mild steel, Alloy steel & Lead etc.

### **The generalized procedure to calculate the Material Cost:**

1. Observe the component drawings, break up the drawing into simple parts as per convenience.
2. Using formulae calculate area & Volume of each part. Scrap should be taken into account while calculating the volume.
3. Add the Volume of all the parts.
4. Multiply the component volume & density of material. It will be weight of the component.  $\text{Density} \times \text{Volume} = \text{Weight}$ .
5. Multiply the weight of the component with the cost of material per unit weight.

The following table gives the densities of various materials:


No.	Material	Density G m/cc	No.	Material	Density G m/cc
1	Aluminum Cast	2.70	2.	Al-wrought	2.681
3.	Cast Iron	7.209	4.	Wrought- Iron	7.707
5.	Steel	7.868	6.	Mild Steel	7.2
7.	Brass-Cast	8.109	8.	Brass-Wire	8.382
9.	Bronze	8.7	10.	Gun Metal	8.735

11.	Zinc-Cast	6.872	12.	Zinc Sheet	7.209
13.	Copper	8.622	14.	Gold	19.316
15.	Lead	11.368	16.	Tin	7.418

### Solved Examples: Stepped Pulley:

**Q. No 1.** A Cast-Iron Step cone pulley is shown in the following Figure. The Density of the C.I. is 7.209 gm/cc, Material Cost is Rs.20/ kg. Calculate the mass and material cost.

**Solutions:**



Let L, M, N, P are the different parts of the fig shown.

Total Length of the Fig. =  $80 + 80 + 80 = 240$  mm

Now calculate the volume of Each Part:

a) Volume of hole i.e., Part "L"

$$V_L = \pi/4 \times d^2 \times l = \pi/4 \times 60^2 \times 240 = 678584 \text{ mm}^3 = 678.584 \text{ cm}^3$$

b) Volume of part "M"

$$V_M = \pi/4 \times d^2 \times l = \pi/4 \times 250^2 \times 80 = 3926990 \text{ mm}^3 = 3926.99 \text{ cm}^3$$

c) Volume of part "N"

$$V_N = \pi/4 \times d^2 \times l = \pi/4 \times (180)^2 \times 80 = 2035752 \text{ mm}^3 = 2035.72 \text{ cm}^3$$

d) Volume of part "P"

$$V = \pi/4 \times d^2 \times l = \pi/4 \times 120^2 \times 80 = 904778.68 \text{ mm}^3 = 904.778 \text{ cm}^3$$

The volume of the part = (b + c + d) – a

$$= (3926.99 + 2035.72 + 904.778) - 678.584 = 6188.904 \text{ cm}^3$$

Total mass of the part = Volume of the part X Density of the CI Material

$$= 6188.904 \times 7.209 = 44615.809 \text{ gm.} = 44.615 \text{ kg}$$






Assume the cost of CI = Rs. 75/-

Cost of the Material Required = Weight X Cost

$$= 44.615 \times \text{Rs. } 75 = \text{Rs. } 3346.125$$

## ESTIMATION

Some of the important formulae regarding Planes and Solids are given below

1 Rectangle		<p>l = length of rectangle                      b = breadth of rectangle  <math>\therefore</math> Area = <math>l \times b</math>, Perimeter = <math>2 \times (l + b)</math></p>
2 Square		<p>S = length of each side of square                      d = length of diagonal  <math>\therefore</math> Area = <math>s^2</math> or <math>\frac{d^2}{2}</math>, Perimeter = <math>4S</math></p>
3 Parallelogram		<p>l = length of one side of parallelogram                      b = length of another side                      h = height of parallelogram  <math>\therefore</math> Area = <math>l \times h</math>, Perimeter = <math>2(l + b)</math></p>
4 Triangle		<p>h = height of A from BC                      Area = <math>\frac{1}{2} \times a \times h = \frac{1}{2} \times \text{base} \times \perp^r \text{ height}</math>                      Perimeter = <math>a + b + c = 2s</math></p>
5 Hexagon		<p>a = length of each side; h = height                      Area = <math>\frac{3\sqrt{3}}{2} a^2</math>                      Perimeter = <math>6a</math>, <math>h = \sqrt{3}a</math></p>




6 Any Regular Polygon

Let n = no of sides; a = length of each side

Perimeter = n x a

Area =  $\frac{1}{2}$  x perimeter x inner radius

7 Trapezium




a, b, c, d are the lengths,  
h = distance between parallel sides

$$\text{Area} = \left(\frac{a+b}{2}\right)h$$

perimeter = a + b + c + d

8 Circle




r = radius, d = dia

$$\text{Area} = \frac{\pi d^2}{4} = \pi r^2$$

Perimeter =  $\pi d = 2\pi r$


9 Sector



r = radius,  $\theta$  = angle in radius,  
l = length of arc,  $l = r \times \theta$ ,


$$\text{Area} = \frac{\theta}{2\pi} \times \pi r^2 = \frac{\theta r^2}{2}$$

10 Fillet



$$\text{Area of fillet} = r^2 - \frac{\pi}{4}r^2 = r^2 \left(1 - \frac{\pi}{4}\right) = 0.215r^2$$

11 Ellipse



a = Semi major axis

b = Semi minor axis

area =  $\pi \times a \times b$

Perimeter =  $\pi (a + b)$

**UNIT - 2**  
**FORGING**

# FORGING

## Introduction:

Forging is a process of shaping the metal components in cold or hot condition by the application of impact or pressure but the primary difference between various forging methods is the rate which the energy is applied to the work piece.

## Practical Application:

Forging is generally used for those components which require high strength and resistance to shock or vibration sudden impact of load and uniform properties

Example:     Automobiles

- (1) Chassis of all vehicles
- (2) Front and Rear axle
- (3) Wheel drums
- (4) Spring blades
- (5) Rocker arm
- (6) Gear shifter
- (7) Connecting rod etc.

- Railways
- (1) Railway wheels
  - (2) Railway tracks

- General
- (1) D. E. Spanners
  - (2) Ring Spanner
  - (3) Wrenches
  - (4) Cutting Pliers
  - (5) Hammers etc.

## **FORGING METHODS**

- (1) Handforging
- (2) Dropforging
- (3) Pressforging
- (4) Rollforging

**Hand forging:** Hand forging is made by heating the metal until it is plastic state in an open hearth furnace and there by hammering is done on anvil by smith/sledge hammer with use of open face dies to get the desired shape and size by judgment of an individual.

**Drop forging:** In this process of forming the desired shape by placing a heated bar or billet on the lower half of the forging die and hammering the top half of the die into the metal by means of a power hammer by repeated blows the impact of which compel the plastic metal to conform the shape of the die. This method is used to produce large number of small and medium sized forging of similar parts.

**Press forging:** In this process the heated billet is squeezed between die. The pressure is applied by the forging press which completes the operation in a single stroke. Large forging are generally shaped by thin method.


**Roll forging:** Rolling involves the passing of a heated bar between revolving rolls that contains an impression of the required shape. It is used to reduce short thick section to long slender pieces.

### **FORGING operations;**


- (1) Drawingdown
- (2) Upsetting
- (3) Punching
- (4) Bending
- (5) Welding
- (6) Cutting

### Drawing down:


The operation of spreading or thinning action and is accomplished by striking the work piece with flat dies. Due to impact of die on metal its thickness is reduced and length is increased



**Fullers:** are blunt hosed chisel and are used to reduce the thickness of hot metal. They may be held with hand fitted with a rod handle. Bottom fullers may be inserted in the square hole of the anvil.



**Flatters:** this is used to flatten and smoothen metal flatters are used under a sledge hammer to flatten the metal particularly after its thickness has been reduced using fullers.



**Upsetting:** This is just opposite to drawing and involves increasing of the cross-sectional area usually by pressing or hammering in the direction parallel to the original ingot axis. Only the part to be upset is heated to forging temper and the bar or work is then struck at the end, usually between the hammer and the axis as shown in figure.


**Punching:** It is the process of producing hole generally cylindrical by using a hot punch over a cylindrical die.

**Drifting:** It is the opening out of holes previously punched.

**Bending:** It is one of the most important processes of forging and is very frequently used.

Bends may be classified as sharp cornered bends or more gradual bends.

The operation is performed by hammering the metal over the edge of the anvil or over a block of metal held in vice.




When the metal is bending by hammering, the outer and inner surface does not remain same. The inside surface is shortened while the outer surface is stretched which causes bulging of the side at the inner surface and a radius on the outer surface of a sharp corner is required an additional metal is required at the place where the bend occur in order to permit stretching of metal at outer surface.

**Welding:** Metal like wrought iron and steel are welded by pressing or hammering together surface after they have been raised to the correct welding temperature at 1350°C when the metal is white hot. The operation of such a type of welding is performed in forge shop. And hence is also called forge welding.


**Cutting:** In order to perform a rapid cutting operation by chiseling, the metal is heated in black smith fire to a temperature of 850-900°C and then hammer blows are directed on the chiselhead. If the thickness of metal to be cut is more than two notched or grooves are made 180° apart.

**Swaging:** it is a process of finishing a round or hexagonal section of bar between a pair of swages of the appropriate size. These may be separate tools for top and bottom or these may be held together by a long spring handle as shown in figure.




**Swages**




**TOOLS & EQUIPMENTS REQUIRED FOR FORGING.**




A SMITH'S ANVIL












Use of chisels in forging







cold set



hot set




Hot set with wooden handle




cold set with steel rod handle



hardie



Cutting a steel bar  
using a hardie



taper rod punch



top and bottom swages



Flat mouth




Open mouth



Chisel or bolt




close mouth




hollowbit




Double hollow bit



Square mouth



side mouth



Band saw

**Anvil:** It is used as a mount for pairs of tools between which the work is forged by hammer blows. The main body of the anvil is made of mild steel with a hardened top face welded on. The beak is soft and with an increasing diameter of cross section. Beak is useful for producing bends of different radii. The ledge between the beak and the anvil face is soft and can be used as a base for cutting operation with hot chisels.

**Sledge hammer:** It is a very heavy hammer with a long handle. It may weigh from 4 to 16 kg. These are used for heavy work. The length of the handle increases with the weight.

**Chisel:** It is fitted with a long handle. The chisel is held on the work and struck with a hammer.

**Cold chisel:** It is used for cutting cold metal.

**Hot chisel:** It is used for cutting hot metal.

**Hardie:** This is a chisel fitted in to a hole in the anvil with its cutting edge at the top. There is usually one for hot and another for cold use.

**Swages:** These are used in pairs to shape hot metal. They are supplied in pairs, top and bottom.

**Fullers:** These are blunt nosed chisels and are used to reduce the thickness of hot metal. They may be held with hand or fitted with a rod handle. Bottom fullers may be inserted in the square hole of the anvil. For occasional use, fullers can be improvised from round mild steelbar.

**Flatter:** This is used to flatten and smooth the metal. It is used under a sledge hammer to flatten and smoothen the metal, particularly after its thickness has been reduced using fullers.

**Tongs:** These are used to hold hot metal pieces. Various shapes of blacksmith's tongs are available.

## **Types of Tongs:**

**Single pick up tong:** It is used to pick up either flat work or round work.

**Curved lip tong:** This is also called as chisel or bolt tong. It is used to hold round work.

**Straight lip tong:** It is also called as flat-jawed or flat mouth tong. It is used to hold flat work.

**Double hollow bit:** It is used to pick up either flat work or round work.

## **WORKING STEPS IN MAKING THE FORGING JOB**


- 1) Calculate the final length of the model to be forged of the given round rod of 12mmdiameter.
- 2) Place the given round rod in the Hearth furnace in suitable place.
- 3) Switch on the blower and set the temperature range up to 900-1000<sup>0</sup>C in control panel.
- 4) The job is heated to red hot temperature.
- 5) Place the heated job in between open-faced Bottom & Top Die, which is set on Anvil.
- 6) Draw down the heated work piece to calculated length with the help of hammer, tong & flatter.
- 7) The process is carried approximately until the circular rod is transformed into desired shape and with desired dimensions.
- 8) The work piece is re-heated to carry out bending operation.
- 9) Bending is carried out on Leg vice as per dimensions.
- 10) With the help of flatter, open faced dies finish the work piece to the final dimension and surface finish, cool the specimen by dipping in water.

**Date.....**

**Signature of the Faculty**



**SQUARE SECTION PRISM**



**Calculation of length of the raw material required to do the component**

$M_f$  = Mass of the finished product

$M_f$  of Square Prism = Volume x Density

$$M_f = a^2 \times L \times \rho$$

$$a = 40 \text{ mm} = 4.0 \text{ cm}$$

$$\rho = 7.85 \text{ gm/cm}^3$$

$$L = 60 \text{ mm} = 6.0 \text{ cm}$$

$M_r$  = Mass of the raw material MS round

$M_r$  = Volume x Density

$$M_r = A \times L \times \rho$$

$$L = ?$$

$$d = 16 \text{ mm} = 1.6 \text{ cm}$$

$$753.6 = \pi d^2 / 4 \times L \times \rho$$

$$\rho = 7.85 \text{ gm/cm}^3$$

$L =$


Add extra 10 % forging allowance =

Total=

**Date.....**

**Signature of theFaculty**

## SQUARE SECTIONNAIL



### Calculation of length of the raw material required to do the component

M= Mass of the finished product

$M_1$  = square prism = volumex density

$$= L \times B \times H \times \rho$$

$$L = 15\text{mm} = 1.5\text{cm}$$

$$B = 15\text{mm} = 1.5\text{cm}$$

$$H = 20\text{mm} = 2.0\text{cm}$$

$$\rho = 7.85\text{gm/cm}^3$$

$M_2$  = square prism = volumex density

$$= L \times B \times H \times \rho$$

=

=

$$L = 50\text{mm} = 5.0\text{cm}$$

$$B = 15\text{mm} = 1.5\text{cm}$$

$$H = 15\text{mm} = 1.5\text{cm}$$

$$\rho = 7.85\text{gm/cm}^3$$

$M_3$  = Square Pyramid =  $\frac{1}{3} \times A^2 \times H$

=

$$\rho = 7.85\text{gm/cm}^3$$

$$A = 15\text{mm} = 1.5\text{cm}$$

$$H = 30\text{mm} = 3\text{cm}$$

$$M = M_1 + M_2 + M_3 =$$

=

M = Mass of the raw material MS round

L=?

Mass = Volumex Density

d=16mm=1.6cm

$$= \pi d^2/4 \times L \times \rho =$$

$$\rho = 7.85 \text{gm/cm}^3$$

L=

Add extra 10 % forging allowance =


=

Total =

**Date.....**

**Signature of the Faculty**

HEXAGONAL BOLT



Calculation of length of the raw material required to do the component

M= Mass of the finished product

$$m1 = \text{Hexagon prism} = A\rho = 6ah + 3\sqrt{3}a^2 \cdot \rho$$

a=12mm=1.2cm  
h=8mm=0.8cm

=

$\rho = 7.85 \text{ gm/cm}^3$

$$m2 = \text{Round} = \pi d^2/4 \times L \times \rho$$

d=12mm=1.2cm

=

L=50mm=5cm

$$= \rho = 7.2 \text{ gm/cm}^3$$

$$M = m1 + m2 =$$

=

M = Mass of the raw material MS Round d=16 mm=1.6 cm

$$= \pi d^2/4 \times L \times \rho = L = ?$$

$$L = 4.30 \text{ cm} \rho = 7.85 \text{ gm/cm}^3$$

Add extra 10 % forging allowance =

=

Total=

Date.....

Signature of the Faculty

# SHEET METAL

Metal in the form of sheet is called 'sheet metal'. Sheet metal work involves, working with metallic sheets using various tools to make components/articles such as office trays, funnel, box, cans, chimney air ducts and to fabricate boiler shells, pipe joints, storage tanks etc. Sheets up to 3mm thickness are called 'sheet metal' and above 3 mm thickness, they are called 'plate'.

## Practical Applications:

Many industries like automobile, aircraft, ship building, packing, air conditioning, ventilating system, fabrication of funnels, hoppers, bins, paint tins, trays, oil tins, buckets, storage tank, chimney boilers, involves sheet metal fabrication.

## Methods of Developments:

1. **Parallel line method of development:** The surfaces of right prisms, cylinders, cubes, Rectangular Trays & Similar objects.
2. **Radial line method of development:** The lateral surfaces of right pyramids and cones may be developed by this method.
3. **Triangulation method of development:** The surfaces are made of a No of Triangular strips laid out in their true size. Ex. Square to round Rectangular to square etc.
4. **Approximate Method of development:** This method is used to draw the development of a sphere etc.

## Common metal sheets used in sheet metal Work are:

1. B.P or H R Sheet (Black Plain sheet or Hot Rolled sheet)
2. C R plain sheet (Cold Rolled sheet) – 0.1-0.3 % of Carbon
3. Galvanized plain sheet (Galvanizing Zinc)
4. Aluminum sheet
5. Copper sheet
6. Tin Sheet
7. Stainless steel sheet – (Alloy steel it contains 18% Chromium, 8%, Nickel, less than 1% carbon rest is iron)

Gauge number corresponding to the thickness of sheet or wire diameter.

I. No	Gauge No	Thickness of sheet or diameter of wire in mm
1	10 G	3.25
2	12 G	2.64
3	14 G	2.03
4	16 G	1.63
5	18 G	1.22
6	20 G	0.91
7	22 G	0.71
8	24 G	0.56
9	26 G	0.46
10	28 G	0.38
11	30 G	0.30




Fig. Standard wire gauge (SWG)

## FABRICATING SHEET METAL PARTS

To make a sheet metal object, first the sheet has to be cut to the desired shape. The technique employed to know the shape of the given object, is to unfold all the outer surfaces of the object so as to lie on a plane.

When the complete surface of an object is opened out and laid on a plane, the object is said to be 'developed'. The figure so obtained on the plane is called 'development of the object'. For ex., consider a cylinder with both of its end being open. To fabricate the object, first the surface should be developed. Figure shows the process of laying out the surface of the object on a plane. The figure

so obtained is called the ‘development of surface of a cylinder’.

The surface to be developed is first drawn on a paper (or can be drawn directly on the sheet metal itself). Suitable allowance should be provided for joining the end surfaces. The paper is then pasted on the sheet metal. All other processes, namely cutting, bending, folding and joining are done manually with the help of tools. The end surface can be joined either by soldering, riveting, brazing etc.




Fig: Development of cylinder

### TOOLS USED IN SHEET METAL WORK

The different types of tools used in sheet metal work are explained in below.

#### Snip

Snips are used to shear or cut the sheet metal to the required shape and size. Different types of snip such as straight snip, bent snip (pipe snip), universal combination snip, heavy snip etc., are used to depend on the requirements.

Figure shows a straight snip used for cutting sheet metal along a straight line. A bent snip can be used for cutting the metal along a curvature.




Fig. Different types of snips



## Stakes

Stakes are anvils of different shapes on which the sheet metal is placed and formed (bended) to the required shape. Different types of stakes like bick iron stake, round head stake, half-moon stake, horse head stake etc., are used in sheet metal work.

Material: Stakes are made from wrought iron and faced with steel.

## Hammer / Mallet:

Hammers used in sheet metal work are made to have round or square heads to suit hammering of the round and corner surfaces respectively. Soft faced (nylon faced) hammers are frequently used in sheet metal work to avoid damage to the metal sheet. A wooden mallet is also used for the same purpose, particularly when light blows are needed. A soft face hammer and a mallet are shown in Figure a and b.




Fig.a : Nylon faced hammer.







Fig.b Mallet




Round bottom




Tea kettle




Half moon



Funnel



Beak or pick iron



Horse

Fig. Different types of stakes

## Sheet Metal Operations:

1. **Measuring:** - It is process of measuring length, width and thickness of sheet by using steel scale, standard wire gauge, micrometer etc.
2. **Marking:** - It is a Process of marking the desired shape on a given sheet ( G P Sheet 28G) thin punch on line of bending with use of center punch & Ball peen hammer.
3. **Cutting & Shearing:** - It is a Process of Cutting block. The term shearing stands for cutting of sheet metal is by parallel cutting edges moving in opposite direction. This can be done either by hand snip or by means of shearing machine.
4. **Notching:** - It is a Process of removal of excess material from the edge of strip to avoid wrinkling or bulging to obtain correct shape. Straight Notch, Square Notch, V Notch
5. **Bending:** - It is a Process of bent the sheet in one plane.
6. **Piercing and Punching:** - It is a Process in which a pointed bullet shape punch is forced enough to produce a hole on sheet.
7. **Nibbling:** - It is a Process of continuous cutting along a contour which may be a straight line or on irregular profile is known as Nibbling by potable shearing machine.
8. **Hemming:** - It is a Process of folding the edge of sheet to provide stiffness and safety on hand for sheet metal products.
9. **Seaming:** - It is a Process of interlocking of sheet metal products such as drums, can, bucket, funnel etc.
10. **Forming:** - It is a Process of shaping sheet metal objects to give it desire shape and size of the final product by using different shapes of stakes.
11. **Planishing:** - It is a Process of giving good surface finish by rubber, Nylon & wooden mallets.
12. **Swaging:** - It is a Process of marking the sheet into a ridge surface or corrugated. Ex: Rolling shutters, Roof Sheets etc.
13. **Coining:** - Coin, medal and other similar part are produced by using hand press with coining die and punch.
14. **Stamping:** - It is a Process of printing letters and other figures on metal using stamping dies and punch. A, B and 1,2
15. **Riveting:** - It is a Process joining permanent in which the end of the metal pin is pressed over or spread out by hammering operation.

## SKETCHES OF SHEET METAL TOOLS




Fig. Sheet Metal Tools

## SOLDERING

Soldering is a method of joining similar or dissimilar metals by means of a filler metal whose melting temperature is below  $450^{\circ}\text{C}$ . The filler metal usually called 'solder' is an alloy of tin and lead in various proportions.

The surface of the parts to be joined are first cleaned in order to remove dirt, grease and other oxides. After cleaning, 'flux' is applied at the edge of the parts to be joined. Zinc chloride, Hydrochloric acid and Alcohol-rosin are some of the fluxes used in soldering.

The function of the flux is to wet the surface of the work piece and to permit the molten solder to flow easily into the joint. It also prevents oxides from separating the solder from the surface. The solder is heated by an electric source, usually a soldering iron and molten solder is deposited at the joint. The solder is allowed to cool for some time and then the soldered joint is cleaned to remove any flux residues in order to avoid corrosion.

## FLUX

The principal function of the flux is

- To wet the surface of the metal and to permit the molten solder to flow easily into the joint.
- To clean any impurities, present on the surface of the sheet metal to be joined.
- To prevent the formation of oxides during soldering.

The different types of flux used are

- Borax it is the most commonly used flux. It is supplied as a powder mixed with water. It should always be applied as a paste.
- Zinc chloride or Killed spirits although it is commonly used, it causes corrosion.
- Resin type flux or rosin It is non-corrosive but does not have the cleaning properties of zinc chloride
- A mixture of equal amounts of HCl solution and zinc chloride solution.

## SOLDERING IRON

Figure shows the soldering iron used for soldering sheet metal joints. The working end of this tool is made of copper, which is a good conductor of heat.

Material for soldering bit Copper (copper bit wets readily and the molten solder clings to the bit easily).




Fig. Soldering iron

## SOLDER

A solder is an alloy metal which melts at low temperatures. There are two types of solder.

(i) Soft solder

- These are alloys of tin and lead. (Lead = 37 % and Tin = 63 %).
- The melting range of soft solder is between 150 - 190°C.
- Soft solders are used where the soldered joints are not subjected to heavy loads and high

temperatures.

(ii) Hard solder

- Silver alloyed with lead (lead = 97.5 % and silver = 2.5 %) or silver alloyed with copper and zinc are called hard solder. (Silver = 50 %, copper = 34 % and zinc = 16 %). A soft solder in the form of wire is shown in Figure.





Fig. Solder

Date.....

Signature of the Faculty

## Development of Hexagonal Prism



### Sequence of operations or procedure for preparing Hexagonal Prism


- Draw the top and front view of the prism of the given dimensions.
- Equal to six sides of the prism  $40 \times 6 = 240$  mm.
- Draw a stretch out line  $A1A1$  and mark off the sides of the base along this line i.e.  $A1B1, B1C1, C1D1$  &  $D1E1, E1F1$  and  $F1A1$ .
- Erect perpendiculars through these points and mark the edges  $AA1, B B1, CC1, DD1, EE1, FF1$  and  $AA1$  and height of the prism 60mm.
- Add 5mm extra adjacent to  $AA1$  for seam joint.

- Cut the development to shape on lines by using paper cutting scissor.
- Place and fix the development on gives G.P sheet by using sticker.
- Punch two points on each bending line.
- Mark the boundary line by using marking pen.
- Remove the paper development join the two points by scriber or marking pen.
- Shear the boundary lines by hand snip.
- Flatten the sheet by using mallet on flatter.
- Always bend the seaming line first and then the remaining lines to get desired shape.
- Finish the surface keeping on stake to shape.
- Solder the joint.
- Finish the surface finishing and complete the job.

**Date.....**

**Signature of theFaculty**

## Development of Pentagon Prism



All dimensions are in mm




## Sequence of operations or procedure for preparing Pentagonal Prism

- Draw the Top & Front view of the prism to the given dimensions.
- Draw a stretch out line A1A1 and mark off the sides of the base along this line i.e. A1B1, B1C1, C1D1 & D1E1 and E1A1.
- Erect perpendiculars through these points and mark the edges AA1, B B1, CC1, DD1, EE1 and AA1 and height of the prism is 60mm.
- Add 5mm extra adjacent to AA1 on each side.
- Cut the development to the shape of the line by using paper cutting scissor
- Place & fix the development to the given GP sheet by using sticker.
- Punch the two points on each bending line
- Mark the boundary line by using marking pen.
- Remove the paper development; join the two points by scribe or marking pen.
- Shear the boundary line by hand snip.
- Flatten the sheet by using mallet on flatter.
- Always bend the seaming line first and then the remaining lines to get desired shape.
- Finish the surface keeping the stake to correct shape
- Solder the joints
- Finish the surface finishing and complete the job

**Date.....**

**Signature of the Faculty**

### Development of Truncated Square Pyramid



#### Sequence of operation to prepare truncated square pyramid.


- Draw the front view of the Truncated Pyramid as per dimensions.
- Extend the outer slant edges to mark apex 'O'.
- Project and get the top view of the pyramid and O'C is the true length of the slant edge.
- With O' as center and radius O'C' describe an arc.
- Transfer the true length of top face edges 40mm each on the arc AB, BC, CD and DA. Join them with straight line and to Apex 'O'.
- Section points are marked on the development by measuring their true distances from O on the true length of slant edge in front view.
- Join the sections and draw dark lines to set the development of the surface of the remaining portion of the pyramid.
- Set 5mm extra for seam joint.

- Continue the same procedure of marking, bending, forming

**Date.....**

**Signature of the Faculty**

### Development of Frustum of Cone



**Procedure:**

Draw the top view and front view of the right circular cone of base dia. 60mm. A section plane cuts perpendicular to the axis of the cone at 40mm height above the base.



With 'O' as center and radius equal to slant generator length (O'C' or O'A'), draw an arc.

Find  $\theta = (r/R) \times 360^\circ$  where r= Radius of the base circle of the cone, R=Length of slant generator of the cone and  $360^\circ =$  Angle subtended to cut the arc.


Date.....

Signature of the Faculty

### Development of Funnel



All dimensions are in mm



### Procedure for preparing a funnel

Draw the top view and front view of the right circular cone of base dia. 60mm. A section plane cuts perpendicular to the axis of the cone at 40mm height above the base.

With 'O' as center and radius equal to slant generator length (O'C' or O'A'), draw an arc.


Find  $\theta = (r/R) \times 360^\circ$  where  $r$  = Radius of the base circle of the cone,  $R$  = Length of slant generator of the cone and  $360^\circ$  = Angle subtended to cut the arc.

- Draw the top view and front view of the cylinder of base dia. 30mm and bottom of funnel is beveled off completely to  $40^\circ$ .
- Develop the cylinder of base diameter 30 mm and height 65mm.
- Circumference  $= 2\pi r$ , where  $r$  = Radius of cylinder
- Cut the sheet along the line according to shape of the development.
- Fold 5 mm extra allowance in clockwise and anti-clockwise directions by keeping hacksaw blade thickness and pressed.
- Remove the hacksaw blade, Bend the main body using the stake and lock the end joint.
- Solder the two parts with electric soldering.


Date.....

Signature of the Faculty


### Development of Rectangular Tray



2D Drawing



3D Drawing (Isometric)



Development of Rectangular Tray

#### Sequence of operation or Procedure to prepare Trays in Sheet metal.

- Draw 2D/ 3D sketches as per scale.
- Draw the development considering all lines must be a “True Length”
- Construct the base of the Tray.
- Construct the two sides of the tray.
- Construct the two ends of the tray.

- Set 5mm extra, allowance on side face for joining the corners by seaming.
- Notch the points to prevent bulging on seaming
- Cut the development shape on lines by using paper cutting scissor
- Place and fix the development on given G.P sheet by using Sticker.
- Punch two points on each bending line.
- Mark the boundary line by using Marking Pen.
- Remove the paper development join the two punch points by a scribe or marking pen.
- Shear the boundary lines by hand snip.
- Flattening the sheet by using mallet on flatter.
- Always bend the seaming line first and remaining lines to get the desired shape by forming.
- Finish the surface keeping on stake to shape.
- Solder the joint.
- Finish surface finishing and complete the Tray.

**Date.....**

**Signature of theFaculty**



## Viva Questions with answers

1. What is coresand?

Sand that prepared by mixing a special binder such as core oil with sand, that develop high strength.

2. What are the properties of good mouldingsand?

- Permeability
- Cohesiveness or Strength
- Adhesiveness
- Plasticity
- Refractoriness
- Binding
- Chemical resistivity
- Flowability.

3. What is moldingsand?

Its prepared by using a mixture of base sand, binder, additives and with or without water. The mixture of sand is referred to as moulding sand.

4. What is abinder?

It is a material, which imparts the necessary binding action to the sand, a binder holdsthe sand grains together and induces strength and other properties to themoulds

5. What is greensand?

Containing 5-7% water and 6-10% clay it's the cheapest of sand mix.

6. What is permeability?

The ability of sand to allow the gasses to escape from the mould

7. What is clay?

Its most common binder system used in foundries, it's a product of siliceous rocks, containing hydro silicates of alumina ( $Al_2O_3$ ).

8. What is the importance of GFN? Explain how GFN affects the properties of sand and casting.

Grains fineness number Fine grain sand result in good surface, on the casting but gases cannot escape out of the mould made from it. Coarse grain sand allows gases to escape out easily but the casting surface will be very rough. Hence grain size should select appropriately.

9. What are the different types of patterns used in foundry?

- Solid pattern
- Split pattern
- Cope and Drag pattern
- Loose piece pattern
- Gated Pattern
- Match plate pattern
- Follow board pattern
- Skeleton pattern
- Sweep pattern.

10. What are the different methods of preparing moulds?

- Open mould
- Pit mould
- Loma mould
- Sweep mould
- Core sand mould
- Cement bonded mould
- Plaster mould
- CO<sub>2</sub> Sand mould
- Shell mould.

11. What is a dry sand mould? Why binder is used.

It refers to sand mould in the dried condition when there is no moisture in the mould, Dextrin is used up to 2% with clay as Binder.

12. What are the different types of furnaces used for melting?

- Crucible Furnace
- Coke Fired Furnace
- Gas or oil-Fired Furnace
- Resistance Furnace
- Electric Arc Furnace
- Induction Furnace
- Cupola Furnace.

13. What are the different tools used for making moulds in the foundry?

- Round Rammer
- English Trowels
- English cleaner
- Spoon tool
- Smoothers
- Bellows.

14. What is pattern allowance? Why it is required.

Pattern has the same shape as that of the casting but the dimensions will be generally larger than that of the casting. These extra dimensions or deviations from the required value, given on the pattern are referred to as pattern allowance.

15. Name different allowances given for the pattern.

- ❖ Shrinkage allowances

- ❖ Draft allowances
- ❖ Machining allowances
- ❖ Scale & grinding allowances
- ❖ Distortion allowances

16. What are the different patterns materials used in foundry?

- Wood
- Metal
- Plastic
- Wax
- Plaster of Paris.

17. What is cope and Drag?

The upper part of mould is cope and lower part of mould is drag.

18. What is foundry?

Shaping the metal components in their molten stage is known as Foundry.

19. Name different additives used in foundry practice.

- Cereal husks
- Sea Coal
- pitch
- wood flour
- Silica flour
- Iron oxide
- Dextrin
- Molasses.

20. What is casting?

Casting is a manufacturing process by which a liquid material is usually poured into a mold, which contains a hollow cavity of the desired shape, and then allowed to solidify. The solidified part is also known as a casting, which is ejected or broken out of the mold to complete the process.

21. Name the different casting processes.

- ❖ Sand Casting
- ❖ Permanent Mold Casting
- ❖ Low Pressure Casting
- ❖ Die Casting (high pressure)
- ❖ Direct Squeeze Casting
- ❖ Continuous Casting
- ❖ Investment Casting
- ❖ Shell mould casting
- ❖ Vacuum Casting
- ❖ Investment (top) and Conventional Castings
- ❖ Lost Foam Casting
- ❖ Centrifugal Casting

22. What is a Core?

Core is sand blocks they are used to make hollow portion in a casting.

23. How a core is made?

Core is made separately in a core box made of wood or metal.

24. What is Sprue?

It is taper shaped vertical component in the system. It will help transfer of molten metal

from the pouring cup into the runner.

25. What is Runner and Riser?

It is a long horizontal channel which carries molten metal and distributes it to the ingates or gates. It will ensure proper supply of molten metal to the cavity so that proper filling of the cavity takes place.

Riser is to supply the molten metal to the solidifying casting and eliminate shrinkage cavity and should permit easy escape of air and gases.

26. Name some of the Common casting defects.

- Porosity/Holes
- Shrinkage cavity
- Inclusions
- Hot Tears
- Scab, Rat tails
- Sand burn-on/sand fusion
- Cold shut
- Core shift/Mould shift
- Fins.

27. What is gating?

Molten metal is conveyed into the mould cavity and the mould gets completely filled up. After solidification, the solid metal represents casting, for conveying the molten metal into the mould cavity components referred to as Gating system.

28. What is forging?

The process of shaping the metal components in cold or hot condition by the application of impact or pressure but the primary difference b/w various forging method is the rate which the energy is applied to the work piece.