

# Material Strengthening Mechanisms

Academic Resource Center

# Agenda

- Definition of strengthening
- Strengthening mechanisms
- Grain size reduction
- Solid solution alloying
- Cold Working (strain hardening)
- Three steps of Annealing: Recovery, Recrystallization & Grain Growth


# Strengthening

- The ability of a metal to deform plastically depends on the ability of dislocations to move.
- Hardness and strength are related to how easily a metal plastically deforms, so, by reducing dislocation movement, the mechanical strength can be improved.
- To the contrary, if dislocation movement is easy (unhindered), the metal will be soft, easy to deform.

# Strengthening Mechanisms

1. Grain Size Reduction
2. Solid Solution Alloying
3. Strain Hardening (Cold Working)
4. Annealing

# 1. Grain Size Reduction



- Grain boundaries are barriers to slip.
- Barrier "strength" increases with misorientation.
- Smaller grain size: more barriers to slip.

# Hall Petch Relation


- This equation indicates that the yield strength has an inverse square root relation with grain size (d).

- Theoretically, as grain size decreases, yield strength increases. The equation is  $S_{yield} = S_o + k_y d^{-1/2}$  where  $S_o$  is the yield strength of a single crystal and  $k_y$  is a constant. Long if the grains are made

## 2. Solid Solutions


- Impurity atoms distort the lattice & generate stress.
- Stress can produce a barrier to dislocation motion.

Small substitutional impurity



Impurity generates local shear at A and B that opposes dislocation motion to the right.

Large substitutional impurity




Impurity generates local shear at C and D that opposes dislocation motion to the right.


# 3. Strain Hardening (Cold Work)

- Room temperature deformation.
- Common forming techniques used to change the cross sectional area:


-Forging




-Rolling



-Drawing




-Extrusion






# Dislocations during Cold Work



- Dislocations entangle one another during cold work.
- Dislocation motion becomes more difficult, which makes the material stronger overall.

# Result of Cold Work


- Dislocation density increases, which leads to an increase in yield strength: Materials become harder.
- Ductility and tensile strength also increase.



# Percentage Cold Work - Definition

$$\%CW = \frac{A_o - A_d}{A_o} \times 100$$

$$\%CW = \frac{\pi r_o^2 - \pi r_d^2}{\pi r_o^2} \times 100 = 35.6\%$$



# Cold Rolling Illustration



Isotropic  
grains are approx. spherical,  
equiaxed & randomly oriented.



Anisotropic (directional)  
since rolling affects grain  
orientation and shape




# Annealing

- Process where material is heated to above the recrystallization temperature of the sample and then cooled down.
- Main purpose is to improve Cold work properties by increasing ductility and retaining most of the hardness.
- There are 3 steps involved with annealing: **recovery**, **recrystallization** and **grain growth**.

# Recovery

- During recovery, some of the stored internal strain energy is relieved through dislocation motion due to enhanced atomic diffusion at the elevated temperatures.
- Leads to reduction in the number of dislocations.



# Recrystallization

- After recovery is complete, the grains are still in a relatively high strain energy state.
- Recrystallization is the formation of a new set of strain-free and uniaxial grains that have low dislocation densities.
- The driving force to produce the new grain structure is the internal energy difference between strained and unstrained material.
- The new grains form as very small nuclei and grow until they consume the parent material.



# Recrystallization Illustration




Cold Worked grains.  
Not annealed.



Initial recrystallization  
after 3 seconds @  
580°C




Partial replacement  
of grains, after 4  
seconds



Complete recryst.  
after 8 seconds



# Grain Growth



- After recrystallization, the strain-free grains will continue to grow if the metal specimen is left at elevated temperatures.
- As grains increase in size, the total boundary area decreases, as does the total energy.
- Large grains grow at the expense of smaller grains.

# References

- Abbaschian, Reed-Hill. *“Physical Metallurgy Principles”*. 4<sup>th</sup> edition. 2009
- Beer & Johnston (2006). *Mechanics of Materials* (5<sup>th</sup> edition). McGraw Hill.