



Transformer Design

(© Dr. R. C. Goel & Nafees Ahmed)



By



Nafees Ahmed

Asstt. Prof. Department of Electrical Engineering
DIT, University, Dehradun, Uttarakhand



References:

1. Notes by Dr. R. C. Goel
2. Electrical Machine Design by A.K. Sawhney
3. Principles of Electrical Machine Design by R.K Agarwal
4. VTU e-Learning
5. www.goole.com
6. www.wikipedia.org

OUTPUT EQUATION: - It gives the relationship between electrical rating and physical dimensions of the machines.

Let

- V_1 = Primary voltage say LV
- V_2 = Secondary voltage say HV
- I_1 = Primary current
- I_2 = Secondary current
- N_1 = Primary no of turns
- N_2 = Secondary no of turns
- a_1 = Sectional area of LV conductors (m^2)
 $= \frac{I_1}{u}$
- a_2 = Sectional area of HV conductors (m^2)
 $= \frac{I_2}{u}$
- u = Permissible current density (A/m^2)
- Q = Rating in KVA

We place first half of LV on one limb and rest half of LV on other limb to reduce leakage flux. So arrangement is LV insulation then half LV turns then HV insulation and then half HV turns.

(1) For 1-phase core type transformer

Rating is given by

$$\begin{aligned}
 Q &= V_1 I_1 \times 10^{-3} \quad \text{KVA} \\
 &= (4.44 f w_m N_1) I_1 \times 10^{-3} \quad \text{KVA} \quad (\because V_1 = 4.44 f w_m N_1) \\
 &= 4.44 f (A_i B_m) N_1 I_1 \times 10^{-3} \quad \text{KVA} \quad \text{-----(1)} \quad (\because w_m = A_i B_m)
 \end{aligned}$$


Where

- f = frequency
- w_m = Maximum flux in the core
- A_i = Sectional area of core
- B_m = Maximum flux density in the core

Window Space Factor

$$\begin{aligned}
 K_w &= \frac{\text{Actual Cu Section Area of Windings in Window}}{\text{Window Area } (A_w)} \\
 &= \frac{a_1 N_1 + a_2 N_2}{A_w} \\
 &= \frac{(I_1/u)N_1 + (I_2/u)N_2}{A_w} \quad (\because a_1 = I_1/u \text{ \& } a_2 = I_2/u) \\
 &= \frac{I_1 N_1 + I_2 N_2}{u A_w} \\
 &= \frac{2I_1 N_1}{u A_w} \quad (\text{For Ideal Transformer } I_1 N_1 = I_2 N_2)
 \end{aligned}$$

So



1-phase core type transformer with concentric windings

$$\left[N_1 I_1 = \frac{u K_w A_w}{2} \right] \text{----- (2)}$$

Put the value of $N_1 I_1$ form equation (2) to equation (1)

$$Q = 4.44 f A_i B_m \frac{u K_w A_w}{2} \times 10^{-3} \quad \text{KVA}$$

$$\boxed{Q = 2.22 f A_i B_m u K_w A_w \times 10^{-3} \quad \text{KVA}} \text{----- (3)}$$

(2) For 1-phase shell type transformer

Window Space Factor

$$K_w = \frac{a_1 N_1 + a_2 N_2}{A_w}$$

$$= \frac{(I_1/u)N_1 + (I_2/u)N_2}{A_w} \quad (\because a_1 = I_1/u \text{ \& } a_2 = I_2/u)$$

$$= \frac{I_1 N_1 + I_2 N_2}{u A_w}$$

$$= \frac{2 I_1 N_1}{u A_w} \quad (\text{For Ideal Transformer } I_1 N_1 = I_2 N_2)$$

So

$$N_1 I_1 = \frac{u K_w A_w}{2} \text{----- (4)}$$


Put the value of $N_1 I_1$ form equation (4) to equation (1)

$$Q = 4.44 f A_i B_m \frac{u K_w A_w}{2} \times 10^{-3} \quad \text{KVA}$$


$$\boxed{Q = 2.22 f A_i B_m u K_w A_w \times 10^{-3} \quad \text{KVA}} \text{----- (5)}$$

Note it is same as for 1-phase core type transformer i.e. equ (3)

(3) For 3-phase core type transformer



1-phase shell type transformer with sandwich windings



3-phase core type transformer with concentric windings

Rating is given by

$$Q = 3 \times V_1 I_1 \times 10^{-3} \quad \text{KVA}$$

$$= 3 \times (4.44 f w_m N_1) I_1 \times 10^{-3} \quad \text{KVA} \quad (\because V_1 = 4.44 f w_m N_1)$$

$$= 3 \times (4.44 f A_i B_m N_1) I_1 \times 10^{-3} \quad \text{KVA} \quad \text{----- (6)} \quad (\because w_m = A_i B_m)$$

Window Space Factor

$$K_w = \frac{\text{Actual Cu Section Area of Windings in Window}}{\text{Window Area } (A_w)}$$

$$= \frac{2(a_1 N_1 + a_2 N_2)}{A_w}$$

$$= \frac{2 \times [(I_1 / \mu) N_1 + (I_2 / \mu) N_2]}{A_w} \quad (\because a_1 = I_1 / \mu \text{ \& } a_2 = I_2 / \mu)$$

$$= \frac{2(I_1 N_1 + I_2 N_2)}{\mu A_w}$$

$$= \frac{2 \times 2 I_1 N_1}{\mu A_w} \quad (\text{For Ideal Transformer } I_1 N_1 = I_2 N_2)$$

So

$$N_1 I_1 = \frac{\mu K_w A_w}{4} \quad \text{----- (7)}$$

Put the value of $N_1 I_1$ form equation (7) to equation (6)

$$Q = 3 \times 4.44 f A_i B_m \frac{\mu K_w A_w}{4} \times 10^{-3} \quad \text{KVA}$$

$$Q = 3.33 f A_i B_m \mu K_w A_w \times 10^{-3} \quad \text{KVA} \quad \text{----- (8)}$$

(3) For 3- phase shell type transformer

Window Space Factor

$$K_w = \frac{a_1 N_1 + a_2 N_2}{A_w}$$

$$= \frac{(I_1 / \mu) N_1 + (I_2 / \mu) N_2}{A_w} \quad (\because a_1 = I_1 / \mu \text{ \& } a_2 = I_2 / \mu)$$

$$= \frac{I_1 N_1 + I_2 N_2}{\mu A_w}$$

$$= \frac{2 I_1 N_1}{\mu A_w} \quad (\text{For Ideal Transformer } I_1 N_1 = I_2 N_2)$$


So

$$N_1 I_1 = \frac{\mu K_w A_w}{2} \quad \text{----- (9)}$$

Put the value of $N_1 I_1$ form equation (9) to equation (6)

$$Q = 3 \times 4.44 f A_i B_m \frac{\mu K_w A_w}{2} \times 10^{-3} \quad \text{KVA}$$

$$Q = 6.66 f A_i B_m \mu K_w A_w \times 10^{-3} \quad \text{KVA} \quad \text{----- (10)}$$



3-phase shell type transformer with sandwich windings

CHOICE OF MAGNETIC LOADING (B_m)


- | | |
|---|--------------|
| (1) Normal Si-Steel
(0.35 mm thickness, 1.5%—3.5% Si) | 0.9 to 1.1 T |
| (2) HRGO
(Hot Rolled Grain Oriented Si Steel) | 1.2 to 1.4 T |
| (3) CRGO
(Cold Rolled Grain Oriented Si Steel)
(0.14---0.28 mm thickness) | 1.4 to 1.7 T |

CHOICE OF ELECTRIC LOADING (μ)


This depends upon cooling method employed

- | | |
|----------------------|--|
| (1) Natural Cooling: | 1.5---2.3 A/mm ² |
| AN | Air Natural cooling |
| ON | Oil Natural cooling |
| OFN | Oil Forced circulated with Natural air cooling |
| (2) Forced Cooling : | 2.2---4.0 A/mm ² |
| AB | Air Blast cooling |
| OB | Oil Blast cooling |
| OFB | Oil Forced circulated with air Blast cooling |
| (3) Water Cooling: | 5.0 ---6.0 A/mm ² |
| OW | Oil immersed with circulated Water cooling |
| OFW | Oil Forced with circulated Water cooling |


CORE CONSTRUCTION:




(a) U-I type




(b) E-I type



(c) U-T type



(d) L-L type



(e) Mitred Core Construction (Latest)

EMF PER TURN:

We know

$$V_1 = 4.44 f W_m N_1 \text{ ----- (1)}$$

So EMF / Turn $E_t = \frac{V_1}{N_1} = 4.44 f W_m \text{ ----- (2)}$

and

$$\begin{aligned} Q &= V_1 I_1 \times 10^{-3} && \text{KVA} && \text{(Note: Take Q as per phase rating in KVA)} \\ &= (4.44 f W_m N_1) I_1 \times 10^{-3} && \text{KVA} \\ &= E_t N_1 I_1 \times 10^{-3} && \text{KVA} \text{ ----- (3)} \end{aligned}$$

In the design, the ration of total magnetic loading and electric loading may be kept constant

Magnetic loading = W_m

Electric loading = $N_1 I_1$

So $\frac{W_m}{N_1 I_1} = \text{constant (say "r")} \Rightarrow N_1 I_1 = \frac{W_m}{r} \text{ put in equation (3)}$

$$Q = E_t \frac{W_m}{r} \times 10^{-3} \text{ KVA}$$

Or $Q = E_t \frac{E_t}{4.44 f r} \times 10^{-3} \text{ KVA}$ using equation (2)

$$E_t^2 = (4.44 f r \times 10^{-3}) \times Q$$

Or $E_t = K_t \sqrt{Q} \text{ Volts / Turn}$

Where $K_t = \sqrt{4.44 f r \times 10^{-3}}$ is a constant and values are

- $K_t = 0.6 \text{ to } 0.7$ for 3-phase core type power transformer
- $K_t = 0.45$ for 3-phase core type distribution transformer
- $K_t = 1.3$ for 3-phase shell type transformer

- $K_t = 0.75 \text{ to } 0.85$ for 1-phase core type transformer
- $K_t = 1.0 \text{ to } 1.2$ for 1-phase shell type transformer

ESTIMATION OF CORE X-SECTIONAL AREA A_i

We know


$$E_t = K_i \sqrt{Q} \quad \text{-----(1)}$$

$$E_t = 4.44 f W_m$$

Or $E_t = 4.44 f A_i B_m \quad \text{-----(2)}$

So $A_i = \frac{E_t}{4.44 f B_m} \quad \text{-----(3)}$

Now the core may be following types



1-Step Or Square- Core 2-Step Or Cruciform- Core 3-Step Core 4-Step Core

K=	0.45	0.56	0.60	0.625
----	------	------	------	-------

d = Diameter of circumscribe circle

For Square core

$$\text{Gross Area} = \frac{d}{\sqrt{2}} \times \frac{d}{\sqrt{2}} = 0.5 d^2$$

Let stacking factor

$$K_i = 0.9$$

Actual Iron Area

$$A_i = 0.9 \times 0.5 d^2$$

$$= 0.45 d^2$$

(0.45 for square core and take 'K' as a general case)

$$= K d^2$$

So $A_i = K d^2$

Or $d = \sqrt{\frac{A_i}{K}}$

Graphical method to calculate dimensions of the core


Consider 2 step core

$$n = \frac{90^\circ}{n+1}, \quad n = \text{No of Steps}$$

i.e n = 2

$$\text{So } a = d \cos n$$

$$n = \frac{90^\circ}{2+1} = 30^\circ \quad b = d \sin n$$



2-Step Or Cruciform- Core

Percentage fill

$$= \frac{\text{Gross Area of Stepped core}}{\text{Area of circumcircle}} = \frac{K d^2 / K_i}{f d^2 / 4}$$


$$= \frac{0.625d^2 / 0.9}{\frac{\pi}{4}(d^2)} \quad \text{for 4 Step core}$$

$$= 0.885 \text{ or } 88.5\%$$

No of steps	1	2	3	4	5	6	7	9	11
% Fill	63.7%	79.2%	84.9%	88.5%	90.8%	92.3%	93.4%	94.8%	95.8%

ESTIMATION OF MAIN DIMENSIONS:

Consider a 3-phase core type transformer



We know output equation

$$Q = 3.33 f A_i B_m u K_w A_w \times 10^{-3} \quad \text{KVA}$$

So, Window area

$$A_w = \frac{Q}{3.33 f A_i B_m u K_w \times 10^{-3}} \quad m^2$$

where

K_w = Window space factor

$$K_w = \frac{8}{30 + \text{HigherKV}} \quad \text{for upto 10 KVA}$$

$$K_w = \frac{10}{30 + \text{HigherKV}} \quad \text{for upto 200 KVA}$$

$$K_w = \frac{12}{30 + \text{HigherKV}} \quad \text{for upto 1000 KVA}$$

For higher rating $K_w = 0.15$ to 0.20

Assume some suitable range for

$$D = (1.7 \text{ to } 2) d$$

Width of the window $W_w = D - 0.9d$

Height of the window

$$L = \frac{A_w}{\text{width of window}(W_w)} \quad (\because L \times W_w = A_w)$$

Generally $\frac{L}{W_w} = 2 \text{ to } 4$

The yoke can have same area as that of the core and can be of same stepped size as core (in this case $D_y=a$, $h_y=a$). Alternatively it could be of rectangular section. In that case yoke area A_y is generally taken 10% to 15% higher than core section area (A_i), it is to reduce the iron loss in the yoke section. But if we increase the core section area (A_i) more copper will be needed in the windings and so more cost through we are reducing the iron loss in the core. Further length of the winding will increase, resulting higher resistance so more cu loss.


Depth of yoke $A_y = (1.10 \text{ to } 1.15) A_i$
 $D_y = a$
 Height of the yoke $h_y = A_y/D_y$

Width of the core

Or $W = 2*D + 0.9 d$
 $W = 2W_w + 3 \times 0.9d$ (As $W_w = D - 0.9d$)

Height of the core

$H = L + 2*h_y$



2-Step
Or Cruciform- Core

Flux density in yoke

$$B_y = \frac{A_i}{A_y} B_m$$

ESTIMATION OF CORE LOSS AND CORE LOSS COMPONENT OF NO LOAD CURRENT I_c :

Volume of iron in core $= 3*L*A_i$ m^3
 Weight of iron in core $= \text{density} * \text{volume}$
 $= \dots_i * 3*L*A_i$ Kg
 $\dots_i = \text{density of iron (kg/m}^3)$
 $= 7600 \text{ Kg/m}^3$ for normal Iron/steel
 $= 6500 \text{ Kg/m}^3$ for M-4 steel

From the graph we can find out specific iron loss, p_{core} (Watt/Kg) corresponding to flux density B_m in core.

So

Iron loss in core $= p_{\text{core}} * \dots_i * 3*L*A_i$ Watt

Similarly

Iron loss in yoke $= p_{\text{yoke}} * \dots_i * 2*W*A_y$ Watt

Where $p_{\text{yoke}} = \text{specific iron loss corresponding to flux density } B_y \text{ in yoke}$

Total Iron loss $P_i = \text{Iron loss in core} + \text{Iron loss in yoke}$

Core loss component of no load current

$I_c = \text{Core loss per phase/ Primary Voltage}$

$$I_c = \frac{P_i}{3V_1}$$

ESTIMATION OF MAGNETIZING CURRENT OF NO LOAD CURRENT I_m :

Find out magnetizing force H (at_{core} , at/m) corresponding to flux density B_m in the core and at_{yoke} corresponding to flux density in the yoke from B-H curve

$$(B_m \Rightarrow at_{core} / m, \quad B_c \Rightarrow at_{yoke} / m)$$

So

$$\begin{aligned} \text{MMF required for the core} &= 3 * L * at_{core} \\ \text{MMF required for the yoke} &= 2 * W * at_{yoke} \end{aligned}$$

We account 5% AT for joints etc

$$\text{So total MMF required} = 1.05[\text{MMF for core} + \text{MMF for yoke}]$$

Peak value of the magnetizing current

$$I_{m, peak} = \frac{\text{Total MMF required}}{3N_1}$$

RMS value of the magnetizing current

$$\begin{aligned} I_{m, RMS} &= \frac{I_{m, peak}}{\sqrt{2}} \\ I_{m, RMS} &= \frac{\text{Total MMF required}}{3\sqrt{2}N_1} \end{aligned}$$

ESTITMATION OF NO LOAD CURRENT AND PHASOR DIAGRAM:


No load current I_o

$$I_o = \sqrt{I_c^2 + I_m^2}$$

No load power factor

$$\text{Cos}w_o = \frac{I_c}{I_o}$$

The no load current should not exceed 5% of the full load current.



No load phasor diagram

ESTIMATION OF NO OF TURNS ON LV AND HV WINDING

$$\text{Primary no of turns} \quad N_1 = \frac{V_1}{E_t}$$

$$\text{Secondary no of turns} \quad N_2 = \frac{V_2}{E_t}$$

ESTIMATION OF SECTIONAL AREA OF PRIMARY AND SECONDARY CONDUCTORS

Primary current $I_1 = \frac{Q \times 10^{-3}}{3V_1}$

Secondary current $I_2 = \frac{Q \times 10^{-3}}{3V_2} \quad \text{OR} \quad \frac{N_1}{N_2} I_1$

Sectional area of primary conductor $a_1 = \frac{I_1}{u}$

Sectional area of secondary conductor $a_2 = \frac{I_2}{u}$

Where u is current the density.

Now we can use round conductors or strip conductors for this see the IS codes and ICC (Indian Cable Company) table.

DETERMINATION OF R_1 & R_2 AND CU LOSSES:

Let L_{mt} = Length of mean turn

Resistance of primary winding

$$R_{1, dc, 75^\circ} = 0.021 \times 10^{-6} \frac{L_{mt} N_1 (m)}{a_1 (m^2)}$$

$$R_{1, ac, 75^\circ} = (1.15 \text{ to } 1.20) R_{1, dc, 75^\circ}$$

Resistance of secondary winding

$$R_{2, dc, 75^\circ} = 0.021 \times 10^{-6} \frac{L_{mt} N_2 (m)}{a_2 (m^2)}$$

$$R_{2, ac, 75^\circ} = (1.15 \text{ to } 1.20) R_{2, dc, 75^\circ}$$

Copper loss in primary winding = $3I_1^2 R_1$ Watt

Copper loss in secondary winding = $3I_2^2 R_2$ Watt

Total copper loss = $3I_1^2 R_1 + 3I_2^2 R_2$

$$= 3I_1^2 (R_1 + R_2')$$

$$= 3I_1^2 R_p$$

Where $R_{01} = R_p = R_1 + R_2'$

= Total resistance referred to primary side

Note: Even at no load, there is magnetic field around connecting leads, tanks etc which causes additional stray losses in the transformer tanks and other metallic parts. These losses may be taken as 7% to 10% of total cu losses.

DETERMINATION OF EFFICIENCY:

Efficiency $y = \frac{\text{Output Power}}{\text{Input Power}}$

$$y = \frac{\text{Output Power}}{\text{Output Power} + \text{Losses}}$$

$$y = \frac{\text{Output Power}}{\text{Output Power} + \text{Iron Loss} + \text{Cu loss}} \times 100 \%$$

ESTIMATION OF LEAKAGE REACTANCES (X_1 & X_2):

Assumptions

1. Consider permeability of iron as infinity that is MMF is needed only for leakage flux path in the window.
2. The leakage flux lines are parallel to the axis of the core.

Consider an elementary cylinder of leakage flux lines of thickness 'dx' at a distance x as shown in following figure.

MMF at distance x

$$M_x = \frac{N_1 I_1}{b_1} x$$

Permeance of this elementary cylinder

$$\begin{aligned} &= \sim_o \frac{A}{L} \\ &= \sim_o \frac{L_{mt} dx}{L_c} \quad (L_c = \text{Length of winding } 0.8L) \end{aligned}$$

$$\left(\because S = \frac{1}{\sim_o} \frac{L}{A} \quad \& \quad \text{Permeance} = \frac{1}{S} \right)$$

Leakage flux lines associated with elementary cylinder

$$\begin{aligned} dW_x &= M_x \times \text{Permeance} \\ &= \frac{N_1 I_1}{b_1} x \times \sim_o \frac{L_{mt} dx}{L_c} \end{aligned}$$

Flux linkage due to this leakage flux

$$\begin{aligned} d\mathcal{E}_x &= \text{No of turns with which it is associated} \times dW_x \\ &= \frac{N_1 I_1}{b_1} \times \frac{N_1 I_1}{b_1} x \times \sim_o \frac{L_{mt} dx}{L_c} \end{aligned}$$

$$= \sim_o N_1^2 \frac{L_{mt}}{L_c} I_1 \left(\frac{x}{b_1} \right)^2 dx$$

Flux linkages (or associated) with primary winding

$$\mathcal{E}'_1 = \sim_o N_1^2 \frac{L_{mt}}{L_c} I_1 \int_0^{b_1} \left(\frac{x}{b_1} \right)^2 dx = \sim_o N_1^2 \frac{L_{mt}}{L_c} I_1 \left(\frac{b_1}{3} \right)$$

Flux linkages (or associated) with the space 'a' between primary and secondary windings


$$\mathcal{E}_o = \sim_o N_1^2 \frac{L_{mt}}{L_c} I_1 a$$

We consider half of this flux linkage with primary and rest half with the secondary winding. So total flux linkages with primary winding

$$\mathcal{E}_1 = \mathcal{E}'_1 + \frac{\mathcal{E}_o}{2}$$

$$\mathcal{E}_1 = \sim_o N_1^2 \frac{L_{mt}}{L_c} I_1 \left(\frac{b_1}{3} + \frac{a}{2} \right)$$

Similarly total flux linkages with secondary winding



MMF Distribution

$$\mathcal{E}_2 = \mathcal{E}_2' + \frac{\mathcal{E}_o}{2}$$

$$\mathcal{E}_2 = \sim_o N_2^2 \frac{L_{mt}}{L_c} I_2 \left(\frac{b_2}{3} + \frac{a}{2} \right)$$

Primary & Secondary leakage inductance

$$L_1 = \frac{\mathcal{E}_1}{I_1} = \sim_o N_1^2 \frac{L_{mt}}{L_c} \left(\frac{b_1}{3} + \frac{a}{2} \right)$$

$$L_2 = \frac{\mathcal{E}_2}{I_2} = \sim_o N_2^2 \frac{L_{mt}}{L_c} \left(\frac{b_2}{3} + \frac{a}{2} \right)$$

Primary & Secondary leakage reactance

$$X_1 = 2\pi f L_1 = 2\pi f \sim_o N_1^2 \frac{L_{mt}}{L_c} \left(\frac{b_1}{3} + \frac{a}{2} \right)$$

$$X_2 = 2\pi f L_2 = 2\pi f \sim_o N_2^2 \frac{L_{mt}}{L_c} \left(\frac{b_2}{3} + \frac{a}{2} \right)$$

Total Leakage reactance referred to primary side

$$X_{01} = X_p = X_1 + X_2' = 2\pi f \sim_o N_1^2 \frac{L_{mt}}{L_c} \left(\frac{b_1 + b_2}{3} + a \right)$$

Total Leakage reactance referred to secondary side

$$X_{02} = X_s = X_1' + X_2 = 2\pi f \sim_o N_2^2 \frac{L_{mt}}{L_c} \left(\frac{b_1 + b_2}{3} + a \right)$$

It must be 5% to 8% or maximum 10%

Note:- How to control X_p ?

If increasing the window height (L), L_c will increase and following will decrease b_1 , b_2 & L_{mt} and so we can reduce the value of X_p .

CALCULATION OF VOLTAGE REGULATION OF TRANSFORMER:

$$\begin{aligned} V.R. &= \frac{I_2 R_{o2} \cos W_2 \pm I_2 X_{o2} \sin W_2}{E_2} \times 100 \\ &= \frac{R_{o2} \cos W_2}{E_2 / I_2} \times 100 \pm \frac{X_{o2} \sin W_2}{E_2 / I_2} \times 100 \\ &= \% R_{o2} \cos W_2 \pm \% X_{o2} \sin W_2 \end{aligned}$$

TRANSFORMER TANK DESIGN:

Width of the transformer (Tank)

$$W_t = 2D + D_e + 2b$$

Where

D_e = External diameter of HV winding

b = Clearance width wise between HV and tank

Depth of transformer (Tank)

$$D_t = D_e + 2a$$

Where



a = Clearance depth wise between HV and tank

Height of transformer (Tank)

$$H_t = H + h$$

Where

$h = h_1 + h_2$ = Clearance height wise of top and bottom



Tank of a 3-Phase transformer

CALCULATION OF TEMPERATURE RISE:

Surface area of 4 vertical side of the tank (Heat is considered to be dissipated from 4 vertical sides of the tank)

$$S_t = 2(W_t + D_t) H_t \quad \text{m}^2 \quad \text{(Excluding area of top and bottom of tank)}$$

Let

$$\begin{aligned} \theta &= \text{Temp rise of oil (35}^\circ\text{C to 50}^\circ\text{C)} \\ 12.5S_t\theta &= \text{Total full load losses (Iron loss + Cu loss)} \end{aligned}$$

So temp rise in $^\circ\text{C}$ $\theta = \frac{\text{Total full load losses}}{12.5 S_t}$

If the temp rise so calculated exceeds the limiting value, a suitable no of cooling tubes or radiators must be provided

CALCULATION OF NO OF COOLING TUBES:

Specific Heat dissipation
 6 Watt/m²-⁰C by Radiation
 6.5 Watt/m²-⁰C by Convection

Let $xS_t =$ Surface area of all cooling tubes
 Then

Losses to be dissipated by the transformer walls and cooling tube
 = Total losses

$$(12.5S_t + 8.5xS_t) = \text{Total losses}$$

6 W-Radition+6.5 W-Convection=12.5

6.5*1.35 W \approx 8.5 (\approx 35% more) Convection only


So from above equation we can find out total surface area of cooling tubes (xS_t)

Normally we use 5 cm diameter tubes and keep them 7.5 cm apart

$$\begin{aligned} A_t &= \text{Surface area of one cooling tube} \\ &= \pi d_{tube} l_{tube, mean} \end{aligned}$$

Hence

$$\text{No of cooling tubes} = \frac{xS_t}{A_t}$$



Tank and Arrangement of Cooling tubes

WEIGHT OF TRANFORMER:

Let

W_i = Weight of Iron in core and yoke (core volume* density + yoke volume* density) Kg

W_c = Weight of copper in winding (volume* density) Kg
 (density of cu = 8900 Kg/m³)

Weight of Oil
 = Volume of oil * 880 Kg

Add 20% of (W_i+W_c) for fittings, tank etc.

Total weight is equal to weight of above all parts.

Example 1: Estimate the main core dimensions for a 50 Hz, 3-phase, 200 KVA, 6600/500 V, Star/mesh connected core type transformer. Use the following data:

Core limb section to be 4-stepped for which the area factor =0.62

Window space factor =0.27

$$\frac{\text{Height of window}}{\text{Width of window}} = 2$$

Current density = 2.8 MA/m²

Volts per turn =8.5

Maximum flux density =1.25 Wb/m².

Solution:

We know emf per turn

$$E_t = 4.44 f A_i B_m \Rightarrow 8.5 = 4.44 \times 50 \times A_i \times 1.25 \Rightarrow A_i = 0.03063 \text{ m}^2$$

For 4 stepped core

$$A_i = K d^2 \Rightarrow 0.03063 = 0.625 d^2 \Rightarrow d = 0.2214 \text{ m}$$

We also know

$$Q = 3.33 f A_i B_m u K_w A_w \times 10^{-3}$$

$$\Rightarrow 200 = 3.33 \times 50 \times 0.03063 \times 1.25 \times 2.8 \times 10^6 \times 0.27 A_w \times 10^{-3}$$

$$\Rightarrow A_w = 0.0415 \text{ m}^2 = L \times W_w \text{ ----- (1)}$$

$$\frac{L}{W_w} = 2 \text{ ----- (2)}$$

Solving (1) & (2)

$$W_w = 0.144 \text{ m}$$

$$L = 0.288 \text{ m}$$

$$A_y = 1.15 A_i \quad (\text{Let yoke area } A_y \text{ is 15\% more than area } A_i)$$

$$D_y = a \quad (\text{Width of largest stamping})$$

$$= d \cos \theta$$

$$D_y = 0.92 d \quad (\text{To give maximum area } A_i)$$

$$\text{Or } = 0.95 d \quad (\text{By Graphical Method})$$

Selecting $D_y = 0.92 d \Rightarrow D_y = 0.204 \text{ m}$

Also assuming rectangular section for yoke

$$h_y = A_y / D_y = 1.15 A_i / D_y \quad (\text{Assuming } A_y = 15\% \text{ more than } A_i)$$

$$= 1.15 \times 0.03063 / 0.204 \Rightarrow h_y = 0.173 \text{ m}$$

Overall height $H = L + h_y = 0.288 + 0.173 \Rightarrow H = 0.461 \text{ m}$

Overall width $W = 2D + 0.9d = 2W_w + 3 \times 0.9d = 2 \times 0.144 + 3 \times 0.9 \times 0.2214$

$$\Rightarrow W = 0.88578 \text{ m}$$

Example 2: Calculate no load current of a 400 V, 50 Hz, 1-Phase, core type transformer, the particulars of which are as follows:

- Length of means magnetic path = 200 Cm,
- Gross core section = 100 Cm²,
- Joints equivalent to 0.1 mm air gap,
- Maximum flux density = 0.7 T,
- Specific core loss at 50 Hz & 0.7 T = 0.5 W/Kg,
- Ampere turns = 2.2 per cm for 0.7 T,
- Stacking factor = 0.9,
- Density of core material = $7.5 \times 10^3 \text{ Kg/m}^3$.

Solution:

Find I_C :

$$\text{Core loss component of no load current } I_C = \frac{\text{Total core loss}}{V_1} = \frac{\text{Specific core loss} \times \text{Weight of core}}{V_1}$$

$$I_C = \frac{\text{Specific core loss} \times (K_i \times A_{gi} \times \text{length} \times \text{density})}{V_1} = \frac{0.5 \times 0.9 \times 100 \times 10^{-4} \times 200 \times 10^{-2} \times 7.5 \times 10^3}{400}$$

$$\Rightarrow I_C = 0.168 \text{ A}$$

Find I_m :

We know $V_1 = 4.44 f A_i B_m N_1$

$$400 = 4.44 \times 50 \times 0.9 \times 100 \times 10^{-4} \times 0.7 \times N_1 \Rightarrow N_1 = 286$$

$$\text{Magnetizing component } I_m = \frac{\text{Total MMF}}{\sqrt{2} N_1} = \frac{\text{MMF for core} + \text{MMF for airgap of length of 0.1mm}}{\sqrt{2} N_1}$$

$$I_m = \frac{\text{MMF for core} + B_m \times \frac{1}{\mu_0} l_g}{\sqrt{2} N_1} = \frac{2.2 \times 200 + 0.7 \times \frac{1}{4\pi \times 10^{-7}} \times 0.1 \times 10^{-3}}{\sqrt{2} \times 286} \quad \left(\because \text{MMF} = w \times S = B_m \times \frac{1}{\mu_0} l_g \right)$$

$$\Rightarrow I_m = 1.226 \text{ A}$$

So No load current

$$I_0 = \sqrt{I_C^2 + I_m^2} = \sqrt{0.168^2 + 1.226^2}$$

$$\Rightarrow I_0 = 1.237 \text{ A}$$

Example 3: Design an adequate cooling arrangement for a 250 KVA, 6600/400 V, 50 Hz, 3-phase, delta/star core type oil immersed natural cooled transformer with the following particulars:

- Winding temperature rise not to exceed 50⁰ C,
- Total losses at 90⁰ C are 5 Kw,
- Tank Dimensions height x length x width = 125 x 100 x 50 (all in cm)
- Oil level = 115 cm length
- Sketch diagram to show the arrangement of cooling tubes.

Solution:

Dissipating surface area of plain tank after neglecting the top and bottom

$$S_t = 2(W_t + D_t)H_t = 2(50 + 100)125 = 3.75 \times 10^4 \text{ cm}^2 = 3.75 \text{ m}^2$$

$$n = \frac{\text{Total full load losses}}{12.5 S_t} = \frac{5000}{12.5 \times 3.75} = 106.66^\circ C$$

But it is required that the temp rise is not to exceed $50^\circ C$. So cooling tubes are required.

Let xS_t = Surface area of all cooling tubes

$$(12.5 S_t + 8.5 xS_t)_n = \text{Total losses}$$

$$\Rightarrow xS_t = 6.25 \text{ m}^2$$


Surface area of one cooling tube (Assuming Tube dia = 5 cm, average height of tube = 105 cm)

$$A_t = f d_{\text{tube}} l_{\text{tube, mean}} = 3.14 \times 0.05 \times 1.05 = 0.1649 \text{ m}^2$$

$$\text{No of cooling tubes} = \frac{xS_t}{A_t} = \frac{6.25}{0.1649} \approx 38$$

Let the tubes to space 7 cm apart centre to centre, we will be able to accommodate 13 tubes on 100 cm side and 6 tubes on 50 cm side.

$$\text{Total tubes} = 2 \times 13 + 2 \times 6 = 38$$



Tank and Arrangement of Cooling tubes