

UNIVERSITY OF MASSACHUSETTS LOWELL

Asbestos Materials**SAFETY AWARENESS ANNOUNCEMENT
Standard Operation Procedure**

The consulting firms of Kaselaan & D'Angelo, Barnes & Jarnis and UMass Lowell's Office of Environmental & Emergency Management (EEM) have surveyed the University buildings and identified asbestos containing materials (ACM) in various locations. This collaborative approach of information has been consolidated into a source document providing generalized information regarding the location of samples collected in each UMass building and if the sample contained asbestos materials that the university community should be made aware. This document can be accessed on the UML-EEM homepage at <http://www.uml.edu/eem> or by contacting the EEM office at extension 42618 (978-934-2618). In conjunction to this source document, additional sampling data and abatement information are continually occurring and recorded at the EEM Office for reference and awareness.

Care must be taken to insure that asbestos containing material is not disturbed and protective coverings are not damaged. University faculty, staff, contractors and students (all persons) are directed not to disturb materials containing asbestos, such as drilling into ceilings, floors, fire rated doors, hanging items from ACM materials, cutting, and or removing protective coverings. All persons shall contact the EEM office to request an asbestos determination prior to impacting any suspect materials such as but not limited to insulation, window caulking and glazing, transite paneling, fire rated doors, flooring, mastic, and ceiling materials, wall joint compound, and HVAC duct sealants that have not been identified by EEM.

The University conducts periodic inspections of the asbestos containing materials and makes repairs as necessary to insure that the material remains intact or is contained in protective coverings or abated by licensed individuals. Contact the EEM Office, extension 42618, regarding asbestos material information or to report damage to asbestos containing materials.

Note: Asbestos building information can be accessed at <http://www.uml.edu/eem>

UMass Lowell North

Alumni Library

Location	Description	Asbestos: (Yes/No)
Acoustic Plaster	Walls /Ceilings, All floors.	Yes
Basement	Pipe Insulation	No
	Bottom of wall	No
B4	Ceiling Plaster	Yes
	Wall Plaster	No
B-101	Corridor Wall	No
	Upper Wall	No
B-101A	Pyrobar Look-alike	No
Ceiling #1	Right side	No
	Left Side	No
Ceiling Tile in Basement	Bulk	No
Corridor	Wall Plaster	No
First Floor	Putty from Window	Yes
	Putty from Window #2	Yes
Floor Tile in Basement Foyer	Bulk	No
	Mastic from #3	No
	Ceiling Material	No
Second Floor	Putty and Debris from Window #3	Yes
	Wall	No
Stairs	Black Tar under Fieldstone	No
	Building Fare to Fieldstone Patio	No
	Ceiling Material in Foyer	No
	Granite Steps Grey Caulking Material	No
	Fieldstone Caulking Material	No
Vinyl Floor Tile	9" X 9" brown.	Yes
Wall in Basement	Bulk	No

Ball

Location	Description	Asbestos: (Yes/No)
106	Black felt paper	No
	Grey material	No
	Outer board	No
107	Popcorn ceiling (Abated) August 2005	No
109	Floor tile and mastic, popcorn ceiling (Abated) August 2005	No
118	Pipe Insulation	No
	Elbow Insulation	Yes
	PCM	Yes
	Bulk Floor Sample	Yes
118-A	Floor tile	No
121	200 sqft. floor tile and mastic, popcorn ceiling and 10 ft of pipe insulation (Abated) August 2010	No
201	Lab bench top	Yes
210	Ceiling, floor tile and glue dobs (brown) abated June 2013	No
213	180 sqft. floor tile and mastic, popcorn ceiling and 12 glue dobs (Abated) March 2011	No
220	180 sqft. floor tile and mastic, popcorn ceiling (Abated) March 2011	No
214	Spray-on ceiling	Yes
	Elbow of pipe in heat ventilation units	Yes
	Elbow of pipe	Yes
	Pipe insulation	No
317	Expansion joint debris	No
401	Ceiling	No
416	Mastic	No
C-3	Floor tile	Yes
Catwalk to	Tile	Yes
Olney	Mastic	Yes
Window Caulk	Exterior 1 st floor across from Cumnock	No
	Interior 1 st floor across from Cumnock in Mech Rm (behind glass)	Yes
Ceiling in lab (Dana)	Ceiling	No
Ceilings	Acoustical Ceilings, All floors.	Yes
Elbow Insulation		Yes
Exterior	Expansion caulking	Yes
First floor	VFT, Blue	No
	VFT, white speckled	No
	Mastic	No
	TSI on waterline from 101	No
	TSI on waterline from ceiling	No
	TSI on waterline from 102	No
	Cove base	Yes

	Cove base mastic	Yes
	Bulk	No
Glazing window	Parking lot side	Yes
	Parking lot side	Yes
	Riverside side	Yes
NCPP Coal Room 2	Bulk	No
Pipe insulation	Various types & diameters, All floors.	Yes
Vinyl Flooring	9" X 9" floor tiles.	Yes
WJUL	Floor tile	Yes
	Ceiling Material	No
	Mastic	No

Costello

Location	Description	Asbestos: (Yes/No)
305	Bulk	No
Below football room	Elbow insulation	Yes
	Elbow insulation	Yes
First floor	Drain pipe insulation	No
Floor tile		Yes
General	Ceiling material shower room #1	No
	Pipe elbow above ceiling	No
	Ceiling material restroom #2	No
Gym	Cork beneath wooden floor	No
	Mastic with cork	Yes
	Black felt paper	Yes
Machine room	Pipe fitting insulation	Yes
Pipe insulation	Emergency generator exhaust.	Yes
	Pipe joints, All floors.	Yes
Tank insulation	Mechanical room basement.	Yes
Underlay Floor Material	Material	Yes
Weight room ceiling	Ceiling material	No
Women's shower room	Ceiling	No

Cumnock

Location	Description	Asbestos: (Yes/No)
Affirmative action room	Walk, bulk	No
	Storage area, floor tile	Yes
Annie's floor	Tan tile	Yes
	Black mastic	No
Brown floor tile		Yes
C-3	Floor tile	Yes
	Mastic	No
	Pipe insulation	Yes
C-7	PLM wipe	No
	Floor tile	Yes
C-11	Mastic to floor tile	No
	Ceiling, bulk	No
Ceilings	Acoustical and plaster on all floors	Yes
Dr. Levine's office, 1 st floor	Wipe	No
Employee lounge	Ceiling material	Yes
	Wall material	No
	Floor tile	Yes
First floor	Tile	No
First floor lobby	Wall	Yes
	Ceiling	Yes
Lower stairwell	Riser	No
	Skirt	No
Mechanical room	Basement ceiling insulation	No
Mechanical room under C-1	Elbow	Yes
	Off-white vertical run	Yes
	Off-white horizontal run	Yes
PCM	Cumnock hall tunnel	Yes
		Yes
Pipe insulation	Various diameters, All floors.	Yes
Projection screen		No
Second floor stairwell	Skirt	No
	Tread	No
	Lt. mastic, landing tile	No
	Landing tile	No
	Mastic from first	No
Third floor	Brown tile on left	No
Vinyl Flooring	Brown vinyl sheet flooring, basement.	Yes

Eames

Location	Description	Asbestos: (Yes/No)
Basement	Pipe insulation	Yes
Ceiling	Basement plaster ceiling.	Yes
Hot water distribution room	Pipe insulation	Yes
	Pipe fitting insulation	No
Mechanical room	Green wall lower section	No
	Wall plaster	No
	Soil sample	Yes
New boiler room	Textured ceiling plaster	No
	Interior wall-plaster skim and base	No
	Block pipe insulation	Yes
	Aircell pipe insulation	Yes
	12x12 tan floor tile	No
	Black mastic associated with 05A,05B,05C	No
	2'x4' white ceiling tiles	No
	Pyro block fire stop	No
	Layered paper pipe insulation	Yes
	Pipe fitting insulation	Yes
Room 103	Wall plaster	No
Room 104	Wall plaster	No
Room 106	Wall plaster	No
Room 209	Wall plaster	No
Vinyl Flooring	Tan "sheet" vinyl flooring.	Yes

Perry

Location	Description	Asbestos: (Yes/No)
114	PCM	Yes
	Ceiling	No
	Tile	Yes
	Mastic	Yes
	Swept from floor/doorway (bulk)	No
118	Bulk	No
211	Window glazing	No
225	Window glazing	No
307	Window glazing	Yes
414	Window glazing	No
Ceilings	Corridor (only) acoustical ceilings.	Yes
Exterior	Window glazing east side	No
	Window glazing west side	Yes
	Window perimeter expansion glazing east side	Yes
	Window perimeter expansion glazing west side	Yes
Pipe insulation	Various types & diameters, All floors.	Yes
Tank insulation	Mechanical room.	Yes
Vinyl Flooring	9" X 9" brown & 12" X 12" gray.	Yes

Fallmouth

Location	Description	Asbestos: (Yes/No)
201	Elbow insulation	Yes
	Pipe joint insulation	Yes
206	Mastic	Yes
	Air sample	No
Pipe insulation	Various types & diameters, All floors.	Yes
Stairwell, bookstore	Floor tile	No
	Mastic	Yes
Tank insulation	Sub Basement.	Yes

IPI

Location	Description	Asbestos: (Yes/No)
9x9 floor tile	Red Tile	Yes
Above custodial room	Elbow insulation	No
Back foyer area	Mastic	No
	Floor tile	No
Conference room	Mastic	Yes
A	Floor tile	Yes
12x12 floor tile	Red Tile	Yes
Floor tile	Red floor tile	Yes
Main storage room	Mastic	Yes
	Mastic from the back of room	Yes
	Floor tile	Yes
	Floor tile from the back of room	Yes
Machine shop	Mastic	Yes
	Floor tile	Yes
Linoleum floor sample		No

Kitson

Location	Description	Asbestos: (Yes/No)
Duplicating room	Bulk sample – wipe	No
Drain pipe	Joint insulation	No
Pipe insulation	Basement floor.	Yes
Tank insulation	Basement condensate tank.	Yes
Tunnel to	Tan tile	No
Cumnock	Mastic off 1	No

Location	Description	Asbestos: (Yes/No)
Basement	Chiller Mechanical Room	Yes
	Muffler Mechanical	Yes
Janitor's closet – 4th floor	Elbow insulation	No
	Valve insulation	No
Mechanical room	Elbow	Yes
Lydon Innovation Center Basement	6" Wall base molding	No
	4'x8' Acoustical Board	No
	Residual brown and gold carpet adhesive	No
	Skim coat on concrete wall/column	No
	Gypsum wallboard	No
	Joint compound associated with gypsum wallboard and plaster wall	No
	Plaster wall skim and base	No
	Plaster ceiling skim and base	No
	Black coating over window w/squares	No
	Cement floor white crack sealant	Yes
	Canvas tape duct seam sealant – Boiler room AC-3	No
	Duct hanger seam sealant	No
	Interior window with metal squares glazing	No
	Interior window glazing corridor	Yes
	Exterior door caulk	No
	Exterior metal window frame caulk East entrance	Yes
	Exterior wall to ceiling caulk symposium center wall	Yes
	12x12 slate floor tile grout	No
	12x12 slate floor tile bedding mortar corridor	No
	Interior window caulk	Yes
	Skim coat on concrete ceiling	No
	Light weight concrete at duct penetration through wall	No
Mechanical room	Canvas duct vibration cloth RF3 and AC3	Yes
	Abandoned reserve tank flange gasket South East corner	Yes
	Air handler rib seam sealant AC3	Yes
	Small holding tank head cover insulation South East corner	Yes
	Large holding tank head cover insulation North East side	No
Pipe insulation	Various types & diameters, basement.	Yes
2nd Floor Men's Bathroom	Ceiling plaster	No
Sides	Left side	Yes
	Right side	Yes
	Right side of Chiller	Yes

Location	Description	Asbestos: (Yes/No)
Between concrete walls	Caulking	No
Stairwells All Floors	Floor Tile and mastic (Abated) August 2004	No
Basement	Mixing station lower elbow	Yes
Fire Rated Doors	Georgia Pacific Corp. Curtis Door Division (wooden door cores)	Yes
Mech Rm	Mixing station upper, right elbow	No
	Mixing station upper, left elbow	No
	Hot/Cold mixing station	Yes
	LHS chiller	No
	RHS chiller	No
All Hallways	Floor tile and mastic (Abated)	No
Rooms 203, 212, 218, 219, 222, 223, 305, 311, 312, 403B, 410, 414, 507, 508, 510, 513, 515	Floor tile and mastic (Abated)	No
	Note Old 12x12 tile and black mastic may remain under counter and bench tops	Yes
Olney 150	Floor tile and mastic (Abated) June 2006	No
Boiler room	Header pipe Glue Dots	No
	Pipe fitting insulation	No
All Labs	Glue dots behind chalk boards	Yes
Olney 313	Chalkboard removal Glue Dots (Abated) February 2006	No
Emergency Generator	Exhaust pipe	Yes
Mechanical room	Exhaust Generator Pipe Insulator	Yes
	Heat exchange gasket	Yes
	Red duct seam sealant	Yes
Penthouse	Valve CHS 65	No
	Bulk	No
Pipe insulation	Basement mechanical room.	Yes
	Pipe joints all floors.	Yes
Roof	Chiller baffle material	Yes
	Chiller gasket material	Yes
	Pipe elbow insulation	No
Ground Floor, Rm. #23	Elbow insulation	No
Room 416	Blackboard mastic	No
Room 428	Brown mastic	No
	Bulk	No
	Cove base	No
Room 430	Blackboard mastic	No
Room 519	Bulk	No
Room 520	Paneling glue	No
	Chalkboard mastic	Yes
	Brown glue on chalkboard	Yes
	Mastic	Yes

	White VFT	Yes
Tank insulation	Basement mechanical room	Yes
Vinyl Floor Tile	12" X 12" White tile, All floors.	Yes

Olsen

Location	Description	Asbestos: (Yes/No)
Tank insulation	Mechanical room.	Yes
Basement	Elbow insulation from hot water line	No
Ceiling tile	Bulk asbestos Glue dots	No
All Rooms	Glue dots behind white boards	Yes
Floor tile	Bulk asbestos	Yes
1 st floor computer room	Floor tile	Yes
5 th floor	Wall	No
	Pipe insulation sprayed acoustic	No
Machine room	Pipe fitting insulation	No
Room 222	Floor tile and mastic	Yes
Room 102, 103, 107, 108, 112, 511, 612	Floor tile and mastic (Abated)	No
Room 310	Insulation	No
Room 602	Pipe insulation	Yes
Room 606	Floor tile	Yes
	Ceiling tile	Yes
Penthouse	Elbow insulation on chill supply pipes	No
Roof	Chiller baffle material	Yes
	Chiller gasket material	Yes
Pipe insulation	Emergency generator exhaust.	Yes

Pasteur

Location	Description	Asbestos: (Yes/No)
Pipe insulation	Various types & diameters, All floors.	Yes
BB	Bulk	No
Hallway	Pipe insulation	Yes
Mastic		Yes
Room 211	Wall	No
3 rd floor corridor	Brown, top floor tile	No
	Red, bottom flooring	No
	Mastic	Yes

Pinasaki

Location	Description	Asbestos: (Yes/No)
AC-2	Valve #1, Bulk	Yes
	Valve #2, Bulk	No
	Elbow #1	No
	Elbow #2	No
	Elbow #3	No
	Elbow #4	No
Basement	12x12 floor tile	Yes
	Water tank pipe bulk	Yes
	Pipe insulation	Yes
	Pump elbow	No
	Pipe elbow	No
	Chiller #2, Elbow #1	No
	Chiller #2, Elbow #2	No
	Chiller #1, Elbow #1	No
	Chiller #1, Elbow #2	No
	Elbow on backflow preventer	No
	Face piece on valve	No
	Shingle material	Yes
	Blackboard mastic	Yes
Mechanical room	Pipe insulation	Yes
Pipe insulation	Emergency generator exhaust. Pipe joints, All floors.	Yes
Roof ventilation	Pipe lagging	Yes
	Elbow lagging	No
Room 205	Floor tile and mastic (Abated)	No
	Elbow pipe insulation in ceiling	Yes
Room 207	Floor tile and mastic (Abated)	No
Room 209	Floor tile and mastic (Abated)	No
Room 211	Floor tile and mastic (Abated)	No
Room 213	Floor tile and mastic (Abated)	No
Room 213	Elbow pipe insulation in ceiling	Yes
Room 303	Bulk samples	No
3 rd floor mechanical room	Pipe elbow insulation	No
Tank insulation	Mechanical room 2.	Yes
Room 101	Elbow Insulation under sink (exterior wall) abated June 2013	No

Pinasaki Reactor

Location	Description	Asbestos: (Yes/No)
Fire proofing	Exterior walls of reactor cylinder.	Yes
Cooling pipe	Insulation	No

Power Plant (NCPP)

Location	Description	Asbestos: (Yes/No)
Carpenter shop	Elbow from heater	Yes
Ceiling	Ceiling	No
Floor Tile 1 st floor	12 x 12 floor tile and mastic	No
1 st Floor Bathroom	9x9 Floor tile (mastic is clean)	Yes
Pipe insulation	Inside Boiler #3 (all other insulation abated July 2012)	Yes
Tank insulation	Receiver Tank Abated July 2012	No
	Boiler #3 Header Gasket	Yes
Underground steam line and soil	White pipe insulation steam line	Yes
	Loose debris from pile	Yes
	Outer insulation from pipe	Yes

Steam Tunnel (Southwick to Eames)

Location	Description	Asbestos: (Yes/No)
Pipe insulation	All pipes.	Yes

Smith

Location	Description	Asbestos: (Yes/No)
Basement	Office pipe insulation	Yes
	Closet pipe insulation	Yes
Cafeteria	Dishwasher wall plaster	No
	Ceiling pipe insulation	Yes
	Ceiling	No
Mechanical room	Pipe insulation	Yes
	Pipe fitting insulation	Yes
	Textured ceiling plaster	Yes
	Hot water tank insulation	Yes
	Aircell pipe insulation	Yes
	Block pipe insulation	Yes
Pipe insulation	Located in basement.	Yes
Room 104	Wall plaster	No
Room 106	Wall plaster	No
Vinyl Flooring	Tan "Sheet" vinyl flooring, All floors.	Yes

Southwick

Location	Description	Asbestos: (Yes/No)
Pipe insulation	Various types & diameters, All floors.	Yes
Email area	9x9 floor tile	No
Fax/ ATM area	9x9 gray floor tile	No
Game room	9x9 gray floor tile	Yes
Kitchen	Black pipe insulation	Yes
	Wall air duct bulk	Yes
Room 303	Brown tile	Yes
	Black tile	Yes
	Yellow mastic from black tile	No
Room 305	Black mastic from brown tile	No
	Yellow mastic from brown tile	No
Room 307	Tan tile	Yes
	Black mastic from tan tile	Yes
	Yellow mastic from tan tile	No
Student mail room	9x9 floor tile	No
Tunnel to Smith	Joint filler	No
TV area	9x9 floor tile	No

UMass Lowell South

Allen House

Location	Description	Asbestos: Yes/No
Basement	Boiler room's aircell pipe insulation	Yes
	Brown paper pipe insulation	Yes
Living room	Ceiling plaster	No
Kitchen	Ceiling plaster	No
1st floor	9x9 green vinyl tile	Yes
2nd floor	Vinyl tile	No
	9x9 gray tile	Yes
	Black vinyl tile	No
Pipe insulation	Various types & diameters, All floors	Yes
Vinyl Floor Tile	9" X 9" green tile.	Yes

Coburn

Location	Description	Asbestos: Yes/No
Pipe insulation	Various types & diameters, All floors.	Yes
Brick moldings	Caulking	No
Boiler room	Ceiling	No
	Breaching insulation	No
Ground floor	Window trim	No
	Exit door paint	No
	Exit door trim	No
	Outside door	Yes
	Outside paneling	No
1st floor	Fire escape door	No
	Door of fire escape	No
	Door trim of fire escape	No
2nd floor	Fire escape door	No
	Paint of fire escape door #1	No
	Trim of fire escape door #1	No
	Black trim of fire escape door #2	No
Room 112	Ceiling Plaster	No
Room 205	Wall Ceiling	No
Room 209	Hallway bulk	No
Room 306	Hallway bulk	No
Window	Black paint on window sill	No
	Black window pane	No
	Window pane glazing	No
	Wood putty	No

Concordia

Location	Description	Asbestos: Yes/No
Vinyl Floor Tile	9" X 9" tile.	Yes
1 st floor	Men's room ceiling	No
Pipe insulation	Various sizes in Penthouse. 6th floor elevator lobby.	Yes

Dugan

Location	Description	Asbestos: Yes/No
Vinyl Floor Tile	9" X 9" tan, gray & blue tile, All floors.	Yes
Chalkboard	Adhesive	No
Computer lab	Tile	No
1 st floor	Closet, PCM	No
	Janitor's closet	Yes
	Ceiling material	No
2 nd floor	Pipe insulation	Yes
	Closet, PCM	No
	Janitor's closet, bulk	Yes
	Room #1 tile	Yes
	Room #2 tile	Yes
	Room #3 tile	Yes
	Mastic	No
	Hallway ceiling material	No
Storage room	Left pipe sample	Yes
	Right pipe sample	Yes
1 st Floor Registrar's Office March 2013	2'x2' Ceiling tile main entrance	No
	Gray duct seam sealant	No
	Sprinkler pipe thread sealant	No
	White Block Pipe insulation corridor and Room 101	Yes
	Gypsum wall panel Room 101G	No
	Basecoat wall plaster	No
	Skim coat wall plaster	No
	Yellow and black carpet adhesive Room 101, 101A, 101H, and next to stairwell	Yes
	Black cove base and cove base adhesive	No
	Joint compound Room 101, 101E, and 101F	No
	Gypsum wallboard Room 101, 101E	No
	Drain Line Insulation next to Room 101D	Yes
	Floor leveler Room 101	No
	Sink basin undercoating	No
	Ceramic tile grout/mortar Room 101D	No
	2'x4' ceiling tile Room 101	No
	Red fire stop Room 101	No
	Glue behind gypsum wall panel	No
	Gray Window caulking	Yes
Pipe Insulation	Various types & diameter, All floors.	Yes

Durgin

Location	Description	Asbestos: Yes/No
114	Purple textured floor tile	Yes
	Red textured floor tile	No
	Floor tile mastic	Yes
	Blue textured floor tile	No
	White floor tile	No
	Cove base	No
	Cove base mastic	No
	Generator Exhaust pipe	No
Janitor's closet	Hot water pipe insulation	No
Room 419	Abated 120 sqft. of purple floor tile and black mastic (6/17/2012)	No
Mechanical Room	Generator Pipe Insulation	No
Custodial Room 310	Elbow Insulation	No
Roof Membrane	Black Heterogeneous, Fibrous, Roofing Felt	Yes

Mahoney

Location	Description	Asbestos: Yes/No
Ceilings	Acoustical ceilings, All floors unless otherwise noted.	Yes
Ductwork dust	Sampled November 2001	No
Window	Window caulking	Yes
	Floor tile and mastic all floors unless otherwise noted	Yes
1 st Floor Hallway	Floor tile and mastic (Abated) July 2006	No
Rooms 200/201	Floor tile and mastic and acoustical ceiling (Abated) July 2006	No
Room 212 A,B,C	Floor tile and mastic and acoustical ceiling (Abated) June 2007	No
Gym	Double door insulation	No
	Partition core	No
Men's locker room	Shower ceiling	No
Steam Pit	Pipe insulation	Yes
Auditorium	Wall	No
Rooms B7,B8,101, 103, 108	Over laid 12x12 non acm tile over 9x9 tile and mastic containing asbestos	Yes
Office B4	80 sqft floor tile and mastic (Abated)	No
Gym	Double Door Insulation	No
	Brown patrician core	No
Women's locker room	Room	No
Offices	#1 PCM (Air Sample) 3/28/2005	No
	#2 PCM (Air Sample) 3/28/2005	No
	#3 PCM (Air Sample) 3/28/2005	No

	#4 PCM (Air Sample) 3/28/2005	No
	#5 PCM (Air Sample) 3/28/2005	No
	#6 PCM (Air Sample) 3/28/2005	No
	#7 PCM (Air Sample) 3/28/2005	No
	#8 PCM (Air Sample) 3/28/2005	No
	#9 PCM (Air Sample) 3/28/2005	No
Pipe insulation	Various types & diameters. All floors.	Yes
North Stairwell Ground Floor	Floor tile and mastic ground floor landing (Abated) March 2009	No
Square wall panels	Acoustical tile material and brown glue dobs on wall	Yes
Room 9	PCM	No
	Air sample	No
Room 110-A	Room	No
Room 202	PCM (Air Sample) 6/15/2005	No
Room 203	PCM (Air Sample) 6/21/2005	No
Room 209	Room	No
Room 211	PCM (Air Sample) 4/20/2005	No
Room 214	PCM (Air Sample) 8/10/2000	No
	Swipe	No
Tank insulation	Mechanical room.	Yes
Weight room	Ceiling	No

McGauvran

Location	Description	Asbestos: Yes/No
2 nd floor	16x16 Tan/Red floor tile over 12x12 dark brown floor tiles and mastic (Tile Over)	Yes
	Tile from the TV area	Yes
	Mastic from around the Exit door	Yes
	Mastic from around the TV area	Yes
1 st floor	12x12 dark brown floor tile/mastic All Floors	Yes
2 nd Floor Cat Walk Area	Tile and mastic at elevator lobby, and entire Catwalk Area (Abated 8/20/2010)	No
3 rd Floor Cat Walk Area	Tile and mastic at elevator lobby, and entire Catwalk Area (Abated 8/20/2010)	No

Location	Description	Asbestos: Yes/No
Room 500	Roof drain	No
All Floors	12x12 Dark brown floor tile and mastic unless otherwise noted	Yes
Interior Emergency Generator	Tank insulation, exhaust insulation (Abated June 2013)	No
Basement Hallway and Electric Room	Floor tile and mastic 780 sqft. (Abated) June 2012	No
Mailroom	Floor tile and mastic 700 sqft. (Abated) November 2011	No
First Floor and Mezzanine	Floor tile and mastic 14,000 sqft. (Abated) June 2011	No
	1000 Linear feet of acm adhesive paper (Abated) June 2011	No
	500 sqft. duct seam sealant and 60 linear feet of gray caulking at brick and concrete junctions (Abated) June 2011	No
1 st and 4 th Floors Sept and Nov 2010 testing results	Red/gray duct seam sealant various locations above ceilings	Yes
	Adhesive associated with foil paper above ceiling, between angle iron cleat and ceiling deck throughout floor	Yes
	Window frame caulk and glazing	Yes
	Gray caulk at brick concrete junctions	Yes
	Black cementitious wall panels, rooms 412, 413, and 414	Yes
	Compressed wood fiber/paper (tectum-style) ceiling panels	No
	Wall base molding and adhesive	No
	2'x4' ceiling tile front entrance	No
	Mudded pipe fitting insulation on heating lines 1 st and 4 th floors	No
	Pipe thread sealant on heating lines 1 st and 4 th floors	No
	Pre-fabricated gypsum wall panels 1 st and 4 th floors	No
	Carpet adhesive on quarry tile, front entry, Room 110, 114, and open library area, Room 437	No
	Bedding mortar and grout associated with quarry tile	No
	Ceramic wall and floor tile grout, all areas both floors	No
	Plaster ceiling finish and base coat, restrooms both floors	No
	Floor leveling compound, Room 114	No
	2'x2 ceiling tile 4 th floor offices	No
Room 222	Dark blue carpet with golden brown adhesive	No
4 th Floor	Floor tile and mastic 7,000 sqft. and duct seam sealant 400 linear feet (Abated) June 2011	No
	Floor tile and mastic 15,000 sqft, ACM cement board, window glazing and ductwork seam sealant associated with English Department project renovation. (Abated) December 2010 through January 2011	No

South Campus Cafeteria

Location	Description	Asbestos: Yes/No
Tank insulation	Basement mechanical room.	Yes
Catering dry store and Cafeteria	Floor tile	Yes
	Personnel room	Yes
	Mastic	Yes
	Mastic from personnel room	Yes
	Tan 12x12 floor tile and mastic	Yes
Elbows	#1	No
	#2	No
	#3	No
	#4	No
	#5	No
	Pipe elbow #1	No
	Pipe elbow #2	No
Mechanical room	Hot water pipe insulation	No
	Chill pipe elbow insulation	No
	Elbow Insulation	No

South Campus Power Plant

Location	Description	Asbestos: Yes/No
Pipe insulation	Various types & diameters, All floors.	Yes
Boiler #2	Bulk	No
	Drum material	No
Hazard waste room	Elbow #1	No
	Elbow #2	No
1 st floor	Condensate tank face bulk	No
	Condensate tank side bulk	No
Tank insulation	Boiler room.	Yes
Valves	#1	Yes
	#2	Yes
	#3	Yes

Weed

Location	Description	Asbestos: Yes/No
Between window and brick and concrete and brick	Caulking	No
1 st floor	Mechanical room pipe insulation	No
	Joint elbow	No
	Insulation from valve joint Floor tile	No
	Floor tile Red	Yes
	Mastic Black	Yes
Classrooms 201, 204, and 206	Floor tile and mastic (Abated 12/27/2007)	No
Janice Stecchi's office, 1 st floor	Wipe	No
Lecture Room #3	Pipe elbow from sink	No
Mechanical Room #001	Valve insulation pipe to condensate tank from the hot water condensate tank	No
	Elbow insulation, joint to condensate pipe from the elbow pipe	No
	Valve insulation from hot water	No
	Elbow #1	No
	Elbow #2	No
	Elbow #3	No
Mechanical Rooms	Hard pack elbow and fittings at various locations near strainer; AC2, AC3, AC4, AC5, AC6, AC7, AC8, AC10	No
Mechanical Room	Hard pack mudded fitting on fiberglass pipe run (12" Line) Chill Water Supply North Side	Yes
Mechanical Room	Hard pack mudded fitting on fiberglass pipe run (1" Line) Condensate North side	No
Mechanical Room	Cement coating over fiberglass insulated fitting chill water supply and return North and South Side. Also on Chill Water UT Tank	No
Room 303	Bulk from bench top	No
	Bulk from bench top, Saff hallway	No
Room 305	Wall mount glassware holder	Yes
Room 307	Bulk from pipe elbow on table	No
Window	Caulking	Yes
Vinyl Floor Tile	12" X 12" tan tile, All floors.	Yes

UMass Lowell East

Bourgeois

Location	Description	Asbestos: Yes/No
Boiler room basement	Ceiling	No
Ceilings	Sprayed acoustical ceilings, All floors.	Yes
Duct insulation	Boiler room exhaust pipe.	Yes
1 st floor	Lobby air sample	No
	East wing air sample	No
	West wing air sample	No
2 nd floor	Lobby air sample	No
	East wing air sample	No
	West wing air sample	No
3 rd floor	Lobby air sample	No
	East wing air sample	No
	West wing air sample	No
4 th floor	Lobby air sample	No
	East wing air sample	No
	West wing air sample	No
Mechanical room, basement	Elbow 1	No
	Elbow 2	No
	Debris	No
	Bulk, top	No
	Bulk, middle	No
	Bulk, bottom	No
	Valve insulation	Yes
	Boiler Refractory Material	No
	Rope Gasket Boiler Doors	Yes
	Boiler Rib Rope Gasket	No
	Pipe Gasket	No
	Gypsum wallboard and joint comp.	No
	Note Boiler removed and abated July 2011	
Pipe insulation	Generator room exhaust pipe.	Yes
Room 109	Textured ceiling abated 180 sqft. July 13, 2012	No
Vinyl Floor Tile	White 9" X 9" in building, All floors.	Yes

Fox

Location	Description	Asbestos: Yes/No
Basement	Pump #3	No
	Elbow from pipe	No
	Hot water pipe elbow	No
	Pipe #2 elbow	No
Pipe insulation	The emergency generator exhaust pipe.	Yes
Telecommunication room	Elbow	No
Vinyl Floor Tile	12" X 12" gray vinyl floors 1 through 6	Yes

Leitch

Location	Description	Asbestos: Yes/No
Ceilings	Sprayed acoustical ceilings, All floors.	Yes
1 st floor	Lobby air sample	No
	East wing air sample	No
	West wing air sample	No
2 nd floor	Lobby air sample	No
	East wing air sample	No
	West wing air sample	No
3 rd floor	Lobby air sample	No
	East wing air sample	No
	West wing air sample	No
4 th floor	Lobby air sample	No
	East wing air sample	No
	West wing air sample	No
Room 115	Textured ceiling 260 sqft abated July 11, 2011	No
Pipe insulation	Hot water tank room.	Yes
102	PCM	No
	Air sample	No
312	Ceiling material	Yes
	Air sample	No
316	Air sample by PLM	No
Room 209	Textured ceiling 150 sqft abated July 13, 2011	No

University Crossing

Location	Description	Asbestos: Yes/No
Common Wall between Sisters and Gagnon Bldg.	Transite Panel	Yes
Sisters Bldg. 3 rd floor nurses area and basement electrical room	Spray on Fireproofing	No
Sisters Bldg. 3 rd Floor Stairwell	Perimeter Waterproofing	No
Gagnon Building Roof	Brown Insulation	No
	Built up tar and gravel	No
	Insulation under tar and gravel	No
	Tar on concrete deck	No
	Felt/tar between insulation	No

UMass Lowell West

Bigelow

Location	Description	Asbestos: Yes/No
Kitchen	Wipe	No
	PCM	Yes
Attic	Wipe	No
	PCM	No
Basement	Wipe	No
	PCM	No

Gould

Location	Description	Asbestos: Yes/No
Pipe insulation	Various types & diameters, All floors.	
Porch	Porch paint (Lead 37.3)	Yes

Richardson

Location	Description	Asbestos: Yes/No
Fire Proofing	Structural beams.	
Pipe insulation	Various types & diameters, All floors.	
Tank insulation	Basement.	
Boiler breeching	Basement.	

Read

Location	Description	Asbestos: Yes/No
Tank insulation	Basement.	

Upham

Location	Description	Asbestos: Yes/No
Walls	Textured paint 2nd floor new addition.	
Pipe insulation	Various types & diameters, All floors.	

Web Office G.N

Location	Description	Asbestos: Yes/No
Kitchen	Wipe	No
	PCM	Yes
Attic	Wipe	No
	PCM	No
Basement	Wipe	No
	PCM	No

