Field campaign

Topic	Rear suspension refinement update (SC 20/26)
Market area	Russische Föderation (5RU),Australia E04 Bentley rest Asia and Australia (6E04),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2060745/1
Campaign number	EB68
Note	
Type	
US code	

Vehicle data

New Flying Spur

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
ZG2*	2020	E		*	*	*

Chas is numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SCB	*	*	*	L	C	082629	083900		

Documents

Document name
master.xml
sc2026vinlist.pdf

Notes

Technical background

Software update available for the Chassis control unit - Diagnostic address 0074

Remedy

Latest level software is now available for all VIN's prior to SCBBE53S2LC082629

The update refines the operation of the rear air springs

Customer notification

Please ensure that all affected vehicles are checked and repaired after the PDI process is conducted/prior to customer handover

▪

The PDI MUST be completed prior to running the following software updates

Warranty accounting instructions

Warranty type   790

Damage service number EB68

Damage code   0066

Labour

Labour operation code   01 51 00 00

Time   As per ODIs log (Must not exceed 30 time units)

Criteria   01

Genuine parts

Not applicable

Parts supply

Not applicable

Parts despatch control

Not applicable

Repair instructions

Technical background

Software update available for the Chassis control unit - Diagnostic address 0074

Check

If the vehicle is not already listed as repaired in the "Repair history" (in Elsa Pro) refer to the Identification section and check the presence of a silver paint mark next to the OBD port

Should neither be evident ("Repair history" or applicable paint mark) carry out the required work in accordance with these instructions

Genuine parts

Not applicable

Work

Software updates

Pre-requisites

▪

The PDI MUST be completed prior to running the following software update

- The closed-circuit voltage of the vehicle must be at least 12.5 V during the update. Connect a suitable battery charger to the vehicle. For further information refer to the Repair manual

- During the update switch off all unnecessary consumers (ventilation, seat heater, interior illumination etc)

- Because of the highest transmission stability you MUST use the diagnosis interface VAS 6154 (WiFi diagnostic tool) ONLY in USB operation or the cable-connected VAS 5055 for the reprogramming (updating) of control units. If these units are not available, the diagnosis interface VAS 5054 (A) can also be used in USB mode

- Do Not under any circumstances use a Bluetooth connection to conduct the reprogramming (updating) of any control units

1) Select and run Guided fault finding *NOTE: Ensure all DTC's are erased prior to starting the update*

- Referring to Figure 1 - Within the Special functions tab - Select SVM – Code Input (Point A)

- Select Perform test (Point B)

Figure 1

2) Referring to Figure 2 - Enter SVM code 37174GWT01

- Select - Adopt

Figure 2

3) Referring to Figure 3 - Check and confirm the code is correct - Select – Yes

Figure 3

4) Follow all on screen prompts and allow the update to continue as shown in Figures 4 and 5

Figure 4

Figure 5

5) Once at Figure 6 - Select – Done/Continue - Follow all on screen prompts

Figure 6

6) Once at Figure 7 - Select - Done/Continue - Follow all on screen prompts


Figure 7

7) Referring to Figure 8 - Select the Read identification data test (Point A)

• Select – Execute (Point B)

Figure 8

8) Referring to Figure 9 – Ensure the Record number is V03935337GD this confirms the update has successfully completed

• Select Yes and follow any remaining prompts

Figure 9

9) After the update programming, gear selection may not be possible. To wake up the system a bus silence is required, carry out the following steps in the order stated below:

- Switch off the ignition

- Remove the diagnostic interface from the OBD port

- Switch off and remove the battery charger from the vehicle

- Close the bonnet and all doors then lock the vehicle

- Wait 5 minutes to allow the vehicle to into bus silence

- When 5 minutes gas elapsed, unlock the vehicle and open the drivers door

- Switch on the ignition

- Confirm that gear selection is possible

10) On completion apply a silver campaign identification mark next to the OBD port (see Identification section)

Identification

Repair instructions   Notes

SCBBE53S2LC082629	SCBBS53S9LC082734	SCBBB6ZG8LC082846	SCBBB6ZG3LC082947
SCBBB6ZG7LC082630	SCBBS53S0LC082735	SCBBS53S2LC082848	SCBBA53S4LC082949
SCBBS53S1LC082632	SCBBA53S0LC082737	SCBBB63S3LC082850	SCBBB6ZG3LC082950
SCBBA5ZG6LC082633	SCBBB6ZG7LC082739	SCBBB6ZG5LC082853	SCBBB6ZG7LC082952
SCBBA53S3LC082635	SCBBE53S7LC082741	SCBBB6ZG9LC082855	SCBBS53SXLC082953
SCBBB6ZG8LC082636	SCBBA5ZG2LC082743	SCBBS53S3LC082857	SCBBB6ZG2LC082955
SCBBA53S9LC082638	SCBBE53S4LC082745	SCBBA5ZGXLC082859	SCBBS53S5LC082956
SCBBE53S1LC082640	SCBBA5ZGXLC082747	SCBBB6ZG2LC082860	SCBBS53S9LC082958
SCBBB6ZG3LC082642	SCBBB6ZG8LC082748	SCBBE53S8LC082862	SCBBB6ZGXLC082959
SCBBB6ZG5LC082643	SCBBB6ZG6LC082750	SCBBA53S7LC082864	SCBBS53S9LC082961
SCBBE53S0LC082645	SCBBS53S0LC082752	SCBBA5ZG7LC082866	SCBBB6ZGXLC082962
SCBBA5ZG4LC082646	SCBBB6ZG3LC082754	SCBBA5ZG0LC082868	SCBBA5ZG7LC082964
SCBBB6ZG4LC082648	SCBBE53S9LC082756	SCBBA53S2LC082870	SCBBS53SXLC082967
SCBBE53S8LC082649	SCBBA5ZG4LC082758	SCBBB6ZG9LC082872	SCBBA5ZG6LC082969
SCBBB6ZG4LC082651	SCBBE53S0LC082760	SCBBB6ZG4LC082875	SCBBE53S2LC082971
SCBBA5ZG1LC082653	SCBBA5ZG6LC082762	SCBBA53S5LC082877	SCBBA5ZG8LC082973
SCBBE53S3LC082655	SCBBS53S7LC082764	SCBBE53S3LC082879	SCBBA5ZG1LC082975
SCBBS53S6LC082657	SCBBA5ZG3LC082766	SCBBA5ZG3LC082881	SCBBB6ZG1LC082977
SCBBA5ZG2LC082659	SCBBA53S0LC082768	SCBBA5ZG7LC082883	SCBBS53S6LC082979
SCBBE53S9LC082661	SCBBA5ZG7LC082771	SCBBE53S9LC082885	SCBBA5ZG7LC082981
SCBBB6ZG0LC082663	SCBBA5ZG0LC082773	SCBBA53S8LC082887	SCBBS53S8LC082983
SCBBB63S8LC082665	SCBBE53S2LC082775	SCBBS53S5LC082889	SCBBB6ZG0LC082985
SCBBS53S9LC082667	SCBBS53S5LC082777	SCBBB6ZG2LC082891	SCBBE53S6LC082987
SCBBA53S9LC082669	SCBBE53SXLC082779	SCBBB6ZG6LC082893	SCBBE53S8LC082988
SCBBB6ZGXLC082671	SCBBS53S9LC082782	SCBBA53S7LC082895	SCBBE53S6LC082990
SCBBE53S5LC082673	SCBBE53S3LC082784	SCBBA5ZG7LC082897	SCBBA5ZG1LC082992
SCBBB6ZG7LC082675	SCBBE53S9LC082787	SCBBB6ZG7LC082899	SCBBS53S2LC082994
SCBBE53S2LC082677	SCBBB6ZG0LC082789	SCBBB6ZGXLC082900	SCBBB6ZG5LC082996
SCBBS53S5LC082679	SCBBB6ZG0LC082792	SCBBS53S4LC082902	SCBBA53S6LC082998
SCBBS53S3LC082681	SCBBS53S5LC082794	SCBBB6ZG7LC082904	SCBBE53S3LC083000
SCBBE53S8LC082683	SCBBE53SXLC082796	SCBBB6ZG0LC082906	SCBBS53S4LC083001
SCBBB6ZG1LC082686	SCBBA53S9LC082798	SCBBE53S4LC082907	SCBBB6ZG7LC083003
SCBBB6ZG5LC082688	SCBBS53S7LC082800	SCBBB6ZG6LC082909	SCBBS53S1LC083005
SCBBE53S7LC082691	SCBBA53S7LC082802	SCBBB6ZG4LC082911	SCBBS53S5LC083007
SCBBS53S1LC082694	SCBBE53S5LC082804	SCBBB6ZG6LC082912	SCBBA5ZG1LC083009
SCBBB6ZG6LC082697	SCBBS53S8LC082806	SCBBE53S1LC082914	SCBBS53S7LC083011
SCBBE53S4LC082700	SCBBS53S1LC082808	SCBBS53S4LC082916	SCBBA53S5LC083012
SCBBA53S3LC082702	SCBBA5ZG2LC082810	SCBBA5ZG0LC082918	SCBBA5ZG5LC083014
SCBBA5ZG3LC082704	SCBBE53S4LC082812	SCBBS53S6LC082920	SCBBA5ZG7LC083015
SCBBB6ZG3LC082706	SCBBB6ZGXLC082816	SCBBA53S6LC082922	SCBBB6ZG7LC083017
SCBBA5ZG9LC082707	SCBBE53S7LC082819	SCBBA53SXLC082924	SCBBA5ZG2LC083018
SCBBA53S6LC082709	SCBBS53S4LC082821	SCBBS53S5LC082925	SCBBS53S8LC083020
SCBBB6ZG7LC082711	SCBBS53S8LC082823	SCBBE53SXLC082927	SCBBE53S4LC083023
SCBBA53S8LC082713	SCBBB6ZG2LC082826	SCBBB6ZG1LC082929	SCBBS53S7LC083025
SCBBS53S3LC082714	SCBBS53S5LC082827	SCBBA5ZG3LC082931	SCBBE53S3LC083028
SCBBA5ZGXLC082716	SCBBB6ZG8LC082829	SCBBB6ZG3LC082933	SCBBA5ZG3LC083030
SCBBB6ZGXLC082718	SCBBB6ZG6LC082831	SCBBB6ZG7LC082935	SCBBA5ZG7LC083032
SCBBE53SXLC082720	SCBBE53S1LC082833	SCBBA5ZG4LC082937	SCBBS53S8LC083034
SCBBE53S3LC082722	SCBBA5ZG7LC082835	SCBBA5ZG8LC082939	SCBBA5ZG4LC083036
SCBBA53S2LC082724	SCBBE53S9LC082837	SCBBA5ZG6LC082941	SCBBB6ZG4LC083038
SCBBS53SXLC082726	SCBBE53S2LC082839	SCBBB6ZG4LC082942	SCBBB6ZG2LC083040
SCBBA53SXLC082728	SCBBB6ZG7LC082840	SCBBB6ZG6LC082943	SCBBE53S8LC083042
SCBBS53S1LC082730	SCBBS53S1LC082842	SCBBB6ZG8LC082944	SCBBA5ZG3LC083044
SCBBE53S6LC082732	SCBBB6ZG4LC082844	SCBBA5ZG5LC082946	SCBBS53S2LC083045

SCBBE53S7LC083047	SCBBE53SXLC083141	SCBBE53S9LC083227	SCBBS53S1LC083327
SCBBB6ZG7LC083048	SCBBB6ZG1LC083143	SCBBE53S0LC083228	SCBBB6ZG4LC083329
SCBBA5ZG9LC083050	SCBBS53S8LC083146	SCBBE53S9LC083230	SCBBS53S1LC083330
SCBBS53S8LC083051	SCBBB6ZG0LC083148	SCBBE53S0LC083231	SCBBA53S1LC083332
SCBBE53S2LC083053	SCBBA53S6LC083150	SCBBE53S4LC083233	SCBBE53S8LC083333
SCBBB6ZG2LC083054	SCBBB6ZG2LC083152	SCBBE53S6LC083234	SCBBE53S1LC083335
SCBBA53S3LC083056	SCBBE53S8LC083154	SCBBS53S9LC083236	SCBBA53S9LC083336
SCBBB6ZG8LC083057	SCBBB6ZGXLC083156	SCBBE53S1LC083237	SCBBA53S2LC083338
SCBBB6ZG1LC083059	SCBBS53S4LC083158	SCBBB6ZG3LC083239	SCBBS53S8LC083339
SCBBS53S9LC083060	SCBBS53S6LC083159	SCBBE53S1LC083240	SCBBA53S2LC083341
SCBBS53S2LC083062	SCBBE53S5LC083161	SCBBE53S3LC083241	SCBBE53S9LC083342
SCBBS53S4LC083063	SCBBB6ZG5LC083162	SCBBE53S5LC083242	SCBBE53S2LC083344
SCBBA5ZG0LC083065	SCBBB6ZG9LC083164	SCBBS53S8LC083244	SCBBA53SXLC083345
SCBBE53S2LC083067	SCBBA53S8LC083165	SCBBE53S0LC083245	SCBBA53S1LC083346
SCBBE53S4LC083068	SCBBS53S5LC083167	SCBBE53S4LC083247	SCBBS53S7LC083347
SCBBB6ZG2LC083071	SCBBS53S7LC083168	SCBBS53S5LC083248	SCBBE53S1LC083349
SCBBE53S8LC083073	SCBBS53S5LC083170	SCBBB6ZG2LC083250	SCBBA53S3LC083350
SCBBE53SXLC083074	SCBBS53S7LC083171	SCBBS53S5LC083251	SCBBE53S1LC083352
SCBBA5ZG5LC083076	SCBBB6ZGXLC083173	SCBBE53SXLC083253	SCBBE53S3LC083353
SCBBS53S4LC083077	SCBBS53S2LC083174	SCBBE53S1LC083254	SCBBA53S2LC083355
SCBBE53S9LC083079	SCBBB6ZG5LC083176	SCBBE53S1LC083271	SCBBA53S6LC083357
SCBBC53SXLC083081	SCBBE53S9LC083177	SCBBB6ZG1LC083272	SCBBS53S3LC083359
SCBBS53S8LC083082	SCBBB6ZG0LC083179	SCBBE53S7LC083274	SCBBE53S2LC083361
SCBBA5ZG6LC083085	SCBBS53S8LC083180	SCBBE53S0LC083276	SCBBA53S3LC083364
SCBBS53S5LC083086	SCBBB6ZG0LC083182	SCBBE53S4LC083278	SCBBE53S1LC083366
SCBBB6ZG8LC083088	SCBBE53S4LC083183	SCBBE53S6LC083279	SCBBE53S5LC083368
SCBBA5ZG3LC083089	SCBBA53S3LC083185	SCBBA53SXLC083281	SCBBA53S9LC083370
SCBBS53S9LC083091	SCBBE53SXLC083186	SCBBE53S6LC083282	SCBBE53S7LC083372
SCBBS53S2LC083093	SCBBE53S3LC083188	SCBBA5ZG1LC083284	SCBBB6ZG9LC083374
SCBBA5ZG9LC083095	SCBBE53S5LC083189	SCBBA53S9LC083286	SCBBA53SXLC083376
SCBBS53SXLC083097	SCBBE53S3LC083191	SCBBE53S5LC083287	SCBBE53S8LC083378
SCBBE53S4LC083099	SCBBB6ZG3LC083192	SCBBA5ZG0LC083289	SCBBA53S1LC083380
SCBBA53S4LC083101	SCBBE53S9LC083194	SCBBE53S7LC083291	SCBBA53S3LC083381
SCBBB6ZG0LC083103	SCBBE53S0LC083195	SCBBA5ZG0LC083292	SCBBA53S7LC083383
SCBBE53S6LC083105	SCBBA5ZG6LC083197	SCBBS53S1LC083294	SCBBB6ZG5LC083386
SCBBB6ZG6LC083106	SCBBE53S6LC083198	SCBBA5ZG6LC083295	SCBBB6ZG7LC083387
SCBBB6ZGXLC083108	SCBBA53S6LC083200	SCBBE53S8LC083297	SCBBA5ZG4LC083389
SCBBA5ZG1LC083110	SCBBA5ZG4LC083201	SCBBE53S1LC083299	SCBBS53S8LC083390
SCBBE53S3LC083112	SCBBE53S6LC083203	SCBBE53S4LC083300	SCBBA53S8LC083392
SCBBE53S7LC083114	SCBBS53S7LC083204	SCBBB6ZG6LC083302	SCBBE53S4LC083393
SCBBA5ZG2LC083116	SCBBE53S1LC083206	SCBBA5ZG1LC083303	SCBBB6ZG6LC083395
SCBBB6ZG2LC083118	SCBBB6ZG1LC083207	SCBBS53S2LC083305	SCBBE53SXLC083396
SCBBE53S6LC083119	SCBBE53S7LC083209	SCBBE53S5LC083306	SCBBA53S9LC083398
SCBBB6ZG2LC083121	SCBBE53S3LC083210	SCBBS53S8LC083308	SCBBS53S4LC083399
SCBBA53S1LC083122	SCBBE53S7LC083212	SCBBS53SXLC083309	SCBBS53S9LC083401
SCBBS53S9LC083124	SCBBB6ZG7LC083213	SCBBE53S9LC083311	SCBBE53S1LC083402
SCBBA5ZG3LC083125	SCBBA5ZG4LC083215	SCBBS53SXLC083312	SCBBA5ZG2LC083407
SCBBE53S5LC083127	SCBBE53S4LC083216	SCBBE53S4LC083314	SCBBS53SXLC083410
SCBBS53S4LC083130	SCBBA5ZGXLC083218	SCBBE53S6LC083315	SCBBE53SXLC083415
SCBBE53S9LC083132	SCBBE53SXLC083219	SCBBS53S9LC083317	SCBBA53S0LC083418
SCBBE53S2LC083134	SCBBA5ZGXLC083221	SCBBE53S1LC083318	SCBBE53S5LC083421
SCBBB6ZG2LC083135	SCBBE53SXLC083222	SCBBE53S1LC083321	SCBBA53S6LC083424
SCBBE53SXLC083138	SCBBE53S3LC083224	SCBBB6ZG3LC083323	SCBBE53S6LC083427
SCBBB6ZG6LC083140	SCBBS53S4LC083225	SCBBS53SXLC083326	SCBBS53S9LC083429

SCBBA53S3LC083431	SCBBS53S6LC083548	SCBBS53S0LC083626	SCBBS53S8LC083700
SCBBS53S0LC083433	SCBBB6ZG3LC083550	SCBBS53S2LC083627	SCBBE53S0LC083701
SCBBS53S3LC083443	SCBBB6ZG7LC083552	SCBBS53S6LC083629	SCBBE53S4LC083703
SCBBA53S1LC083444	SCBBA53S8LC083554	SCBBE53S3LC083630	SCBBA53S1LC083704
SCBBS53S9LC083446	SCBBS53S5LC083556	SCBBE53S5LC083631	SCBBS53S9LC083706
SCBBS53S0LC083447	SCBBE53SXLC083558	SCBBE53S8LC083633	SCBBE53S1LC083707
SCBBE53S5LC083449	SCBBE53S8LC083560	SCBBE53S0LC083634	SCBBE53S5LC083709
SCBBA53S7LC083450	SCBBS53S0LC083562	SCBBE53S2LC083635	SCBBA53S9LC083711
SCBBE53S5LC083452	SCBBE53S5LC083564	SCBBE53S6LC083637	SCBBS53S6LC083713
SCBBE53S7LC083453	SCBBB6ZG7LC083566	SCBBB6ZG6LC083638	SCBBE53S9LC083714
SCBBB6ZG9LC083455	SCBBE53S0LC083567	SCBBS53S9LC083639	SCBBE53S2LC083716
SCBBA53S8LC083456	SCBBE53S2LC083568	SCBBE53S8LC083641	SCBBE53S4LC083717
SCBBA53S1LC083458	SCBBA53S6LC083570	SCBBE53SXLC083642	SCBBE53S8LC083719
SCBBA53S3LC083459	SCBBS53S1LC083571	SCBBE53S1LC083643	SCBBE53S6LC083721
SCBBE53S3LC083465	SCBBE53S4LC083572	SCBBE53S5LC083645	SCBBE53SXLC083723
SCBBE53S5LC083466	SCBBB6ZG6LC083574	SCBBE53S7LC083646	SCBBE53S1LC083724
SCBBB6ZG7LC083468	SCBBS53S9LC083575	SCBBS53S8LC083647	SCBBA53S0LC083726
SCBBE53S0LC083469	SCBBS53S0LC083576	SCBBS53S1LC083649	SCBBB6ZG5LC083727
SCBBE53S9LC083471	SCBBB6ZG3LC083578	SCBBS53S8LC083650	SCBBB6ZG9LC083729
SCBBE53S0LC083472	SCBBA53S2LC083579	SCBBA53S6LC083651	SCBBE53S9LC083731
SCBBA53SXLC083474	SCBBE53S3LC083580	SCBBE53S4LC083653	SCBBE53S0LC083732
SCBBE53S6LC083475	SCBBS53S6LC083582	SCBBA53S1LC083654	SCBBS53S3LC083734
SCBBE53SXLC083477	SCBBE53S9LC083583	SCBBB6ZG6LC083655	SCBBS53S5LC083735
SCBBS53S0LC083478	SCBBA53S6LC083584	SCBBS53S0LC083657	SCBBE53SXLC083737
SCBBS53S9LC083480	SCBBE53S4LC083586	SCBBS53S2LC083658	SCBBS53S0LC083738
SCBBE53S1LC083481	SCBBE53S6LC083587	SCBBB6ZG3LC083659	SCBBE53SXLC083740
SCBBA53S0LC083483	SCBBE53S8LC083588	SCBBE53S3LC083661	SCBBE53S1LC083741
SCBBE53S7LC083484	SCBBE53S6LC083590	SCBBS53S4LC083662	SCBBE53S5LC083743
SCBBE53S0LC083486	SCBBB6ZG6LC083591	SCBBS53S6LC083663	SCBBS53S6LC083744
SCBBS53S1LC083487	SCBBS53S9LC083592	SCBBS53SXLC083665	SCBBE53S0LC083746
SCBBE53S8LC083493	SCBBE53S3LC083594	SCBBA53S8LC083666	SCBBS53S1LC083747
SCBBE53S1LC083495	SCBBA53S0LC083595	SCBBE53S4LC083667	SCBBE53S6LC083749
SCBBA53S9LC083496	SCBBA53S2LC083596	SCBBS53S7LC083669	SCBBS53S3LC083751
SCBBS53S6LC083498	SCBBS53SXLC083598	SCBBE53S4LC083670	SCBBA53S3LC083753
SCBBS53S8LC083499	SCBBS53S1LC083599	SCBBE53S6LC083671	SCBBS53S0LC083755
SCBBE53S3LC083501	SCBBE53S5LC083600	SCBBE53SXLC083673	SCBBE53S3LC083756
SCBBE53S5LC083502	SCBBA53S4LC083602	SCBBS53S0LC083674	SCBBA53S2LC083758
SCBBB6ZG7LC083504	SCBBB6ZG9LC083603	SCBBA53S9LC083675	SCBBE53S9LC083759
SCBBB6ZG9LC083505	SCBBB6ZG0LC083604	SCBBS53S6LC083677	SCBBS53S6LC083761
SCBBE53S4LC083507	SCBBE53S6LC083606	SCBBS53S8LC083678	SCBBE53S9LC083762
SCBBB6ZG9LC083519	SCBBE53S8LC083607	SCBBA5ZG2LC083679	SCBBA53S8LC083764
SCBBS53SXLC083522	SCBBS53S9LC083608	SCBBA53S4LC083681	SCBBS53S3LC083765
SCBBB6ZG4LC083525	SCBBA53S3LC083610	SCBBE53S0LC083682	SCBBE53S8LC083767
SCBBS53S7LC083526	SCBBA53S5LC083611	SCBBA53S8LC083683	SCBBS53S9LC083768
SCBBA53S7LC083528	SCBBE53S3LC083613	SCBBS53S5LC083685	SCBBA53S3LC083770
SCBBS53S9LC083530	SCBBS53S4LC083614	SCBBA53S3LC083686	SCBBS53S9LC083771
SCBBE53S3LC083532	SCBBA53S2LC083615	SCBBS53S0LC083688	SCBBS53S2LC083773
SCBBE53S7LC083534	SCBBB6ZG9LC083617	SCBBS53S2LC083689	SCBBS53S4LC083774
SCBBB6ZG9LC083536	SCBBB6ZG0LC083618	SCBBA53S7LC083691	SCBBE53S7LC083775
SCBBA53SXLC083538	SCBBS53S3LC083619	SCBBE53S3LC083692	SCBBS53SXLC083777
SCBBS53S1LC083540	SCBBE53S2LC083621	SCBBA53S2LC083694	SCBBA5ZG4LC083778
SCBBA53S1LC083542	SCBBB6ZG2LC083622	SCBBS53S8LC083695	SCBBA53SXLC083779
SCBBE53SXLC083544	SCBBB6ZG4LC083623	SCBBS53S1LC083697	SCBBA53S8LC083781
SCBBS53S2LC083546	SCBBE53SXLC083625	SCBBS53S3LC083698	SCBBS53S3LC083782

SCBBE53S6LC083783
SCBBE53SXLC083785
SCBBE53S1LC083786
SCBBS53S2LC083787
SCBBA53S2LC083789
SCBBA5ZG5LC083790
SCBBA53S0LC083791
SCBBE53S9LC083793
SCBBA53S6LC083794
SCBBA53S8LC083795
SCBBE53S6LC083797
SCBBA53S3LC083798
SCBBA53S8LC083800
SCBBA53SXLC083801
SCBBA53S3LC083803
SCBBE53SXLC083804
SCBBS53S0LC083805
SCBBA5ZG7LC083807
SCBBE53S7LC083808
SCBBS53S4LC083810
SCBBE53S7LC083811
SCBBA53S6LC083813
SCBBE53S2LC083814
SCBBS53S5LC083816
SCBBE53S8LC083817
SCBBE53S1LC083819
SCBBE53S8LC083820
SCBBE53S1LC083822
SCBBA53S9LC083823
SCBBA53S2LC083825
SCBBE53S9LC083826
SCBBE53S0LC083830
SCBBE53S2LC083831
SCBBE53S6LC083833
SCBBE53S8LC083834
SCBBE53S1LC083836
SCBBA53S0LC083838
SCBBE53S7LC083839
SCBBE53S5LC083841
SCBBE53S9LC083843
SCBBS53SXLC083844
SCBBS53S3LC083846
SCBBS53S5LC083847
SCBBA5ZG1LC083849
SCBBS53S5LC083850
SCBBE53SXLC083852
SCBBE53S1LC083853
SCBBE53S5LC083855
SCBBA5ZG9LC083856
SCBBA53S6LC083858
SCBBE53S2LC083859
SCBBE53S9LC083860
SCBBE53S2LC083862
SCBBE53S4LC083863

SCBBA53S1LC083864
SCBBE53SXLC083866
SCBBS53S0LC083867
SCBBA53S9LC083868
SCBBE53S1LC083870
SCBBS53S2LC083871
SCBBE53S5LC083872
SCBBE53S9LC083874
SCBBC53S3LC083875
SCBBS53S1LC083876
SCBBE53S6LC083878
SCBBE53S8LC083879
SCBBE53S4LC083880
SCBBE53S8LC083882
SCBBE53SXLC083883
SCBBE53S1LC083884
SCBBE53S5LC083886
SCBBE53S7LC083887
SCBBS53S8LC083888
SCBBE53S7LC083890
SCBBE53S9LC083891
SCBBE53S0LC083892
SCBBS53S3LC083894
SCBBE53S6LC083895
SCBBE53S8LC083896
SCBBA53S7LC083898
SCBBS53S2LC083899
SCBBE53S6LC083900