



ENGINE SYSTEMS, INC.

175 Freight Road
Rocky Mount, NC 27804

Telephone: 252/977-2720
Fax: 252/446-1134

January 23, 2006

U.S. Nuclear Regulator Commission
Document Control Desk
Mail Stop 0P1-17
Washington, DC 20555

Subject: 10CFR21 Reporting of Defects and Non-Compliance -
Engine Systems, Inc. Report No. 10CFR21-0091, Rev. 0

Woodward DRU Controls (Manufactured between November 2000
& November 2005) P/N: 9903-364, 9903-365, 9903-439 and 9903-470

Dear Sir:

The enclosed report addresses a reportable notification about Woodward digital
reference units (DRU's).

A copy of the report has also been sent to the NRC.

Please sign below, acknowledging receipt of this report, and return a copy to the
attention of Document Control at the address above (or, fax to number 252/446-1134)
within 10 working days after receipt.

Yours very truly,

ENGINE SYSTEMS, INC.

Susan Woolard
Document Control

Please let us know if ANY of your mailing information changes - name of recipient, name
of company/facility, address, etc. Mark the changes on this acknowledgment form and
send to us by mail or FAX to the number above.

(93)

RECEIVED: _____

DATE: _____

IE19



ENGINE SYSTEMS, INC.

175 Freight Road, Rocky Mount, NC 27804

Telephone: 252/977-2720

Fax: 252/446-1134

Report No. 10CFR21-0091

Rev. 0: 01/23/06

**10CFR21 REPORTING OF DEFECTS
AND NON-COMPLIANCE**

COMPONENT: Woodward DRU Controls (manufactured between Nov. 2000 & Nov. 2005)
P/N: 9903-364, 9903-365, 9903-439 and 9903-470

SYSTEM: Governor Control

CONCLUSION: Reportable in accordance with 10CFR21.

Prepared By: *[Signature]*
Engineering Manager

Date: 1/23/06

Reviewed By: *[Signature]*
Quality Assurance Manager

Date: 1/23/2006

REV	DATE	PAGE	DESCRIPTION
0	01/23/06		Initial issue.

COMPONENT:

Woodward DRU Controls (manufactured between Nov. 2000 & Nov. 2005)
P/N: 9903-364, 9903-365, 9903-439 and 9903-470

DISCUSSION:

Engine Systems Inc. (ESI) has concluded an investigation of a condition reported by Woodward about their Digital Reference Units (DRU's). DRU's provide a speed reference signal (via a proportional DC output voltage) to the electronic governor and are used to enable remote speed adjustment via raise/lower control switches.

A slight increase in the failure rate of a CMOS PDIP integrated circuit (IC) from a specific manufacturer has been noted by customer returned DRU's. The IC manufacturer has not identified a specific cause of the failure; however, a failure analysis completed by Woodward on some failed components identified the cause as internal aluminum conductor corrosion resulting from delaminating of the outer plastic package from the device lead frame. Woodward reports that alternative manufacturer's components have been used in these applications with no reported problems. Failure of the IC could result in the DRU not allowing speed raise/lower adjustment in the governor control system or it could result in a control shutdown (DRU output voltage to electronic governor goes to zero volts). DRU's shipped from Woodward between November 1, 2000 and November 22, 2005 containing the suspect IC's may be more susceptible to failure and have been identified by Woodward (see attached Woodward Service Bulletin 01363A). The bulletin identifies DRU's supplied by Woodward for commercial (8272 prefix), military (9900 prefix) and nuclear (9903 prefix) applications. Suspect DRU's that have been supplied by ESI for nuclear applications are identified on the next 2 pages.

This condition was originally reported by ESI in April 2004 (report 10CFR21-0088) following a DRU failure reported by Fairbanks Morse. At that time, the Fairbanks unit was the only reported failure in nuclear applications. The cause was attributed to a random contamination problem of an integrated circuit (IC) in DRU's manufactured by Woodward between November 2000 and January 2002. Three (3) additional IC failures within DRU's in nuclear service have now been reported. Three of the units failed during initial installation testing and one unit failed after approximately one year in service. All four (4) DRU failures occurred when the DRU was given a raise or lower signal.

AFFECTED CUSTOMERS:

Part No.	Serial #	Latest ESI Ship Date	Original ESI SO#	Repair & Return ESI SO#	DOMESTIC CUSTOMER	Customer PO
9903-365	13576301	1/16/2004	111394		AMERICAN ELECTRIC POWER – D.C. COOK	190-0000031268
9903-365	13576302	10/11/2005	111394	8000473	AMERICAN ELECTRIC POWER – D.C. COOK	190-0000031268
9903-365	13577159	1/16/2004	111394		AMERICAN ELECTRIC POWER – D.C. COOK	190-0000031268
9903-365	13577160	10/9/2003	111394		AMERICAN ELECTRIC POWER – D.C. COOK	190-0000031268
9903-365	13577892	1/16/2004	111394	8000278	AMERICAN ELECTRIC POWER – D.C. COOK	190-0000031268
9903-365	13577893	1/16/2004	111394		AMERICAN ELECTRIC POWER – D.C. COOK	190-0000031268
9903-470	13149513	12/31/2001	94806		DOMINION NUCLEAR – MILLSTONE	03003390, REV.2
9903-470	13149514	12/31/2001	94806		DOMINION NUCLEAR – MILLSTONE	03003390, REV.2
9903-439	13186111	6/27/2002	92470	97802	DUKE ENERGY CORPORATION – MCGUIRE	NM6840 003
9903-439	13516650	6/17/2003	107763		DUKE ENERGY CORPORATION – MCGUIRE	NM12719
9903-470	13347822	11/30/2002	102165		ENTERGY OPERATIONS – FITZPATRICK	4500515542
9903-470	13347823	11/30/2002	102165		ENTERGY OPERATIONS – FITZPATRICK	4500515542
9903-470	13348461	11/30/2002	102165		ENTERGY OPERATIONS – FITZPATRICK	4500515542
9903-470	13348462	11/30/2002	102165		ENTERGY OPERATIONS – FITZPATRICK	4500515542
9903-470	13349177	11/30/2002	102165		ENTERGY OPERATIONS – FITZPATRICK	4500515542
9903-470	14212574	8/10/2005	3001597		ENTERGY OPERATIONS – RIVER BEND	10103424
9903-470	12382055	9/16/2004	80843	8000230	ENTERGY OPERATIONS – RIVER BEND	10069952 - AFW#2497
9903-470	12382056	9/16/2004	80843	8000230	ENTERGY OPERATIONS – RIVER BEND	10069952 - AFW#2497
9903-470	12382057	9/16/2004	80843	8000230	ENTERGY OPERATIONS – RIVER BEND	10069952 - AFW#2497
9903-365	13262045	9/16/2004	96239	8000237	EXELON – BRAIDWOOD	703 REL#11136
9903-365	14374699	8/22/2005	3001382		EXELON – BRAIDWOOD	703; Rel. 11202
9903-365	14374700	8/22/2005	3001382		EXELON – BRAIDWOOD	703; Rel. 11202
9903-365	14374701	8/22/2005	3001382		EXELON – BRAIDWOOD	703; Rel. 11202
9903-365	13175373	5/3/2002	93244		EXELON – BYRON	703; REL. 10704
9903-365	13319008	8/21/2002	101317		EXELON – BYRON	703; REL. 10809
9903-470	14071860	6/27/2005	3001371		EXELON / AMERGEN - OYSTER CREEK	80 015737
9903-439	13344808	10/28/2002	102350		FIRST ENERGY – DAVIS BESSE	7102012
9903-470	13490742	6/27/2003	111071		FIRST ENERGY – DAVIS BESSE	45101243
9903-470	13564432	7/23/2003	111071		FIRST ENERGY – DAVIS BESSE	45101243
9903-470	13443890	3/10/2003	105364		FLORIDA POWER & LIGHT – ST. LUCIE	00062193/ REV. 1
9903-470	13443891	3/10/2003	105364		FLORIDA POWER & LIGHT – ST. LUCIE	00062193/ REV. 1
9903-470	13443892	3/10/2003	105364		FLORIDA POWER & LIGHT – ST. LUCIE	00062193/ REV. 1
9903-470	13720683	5/27/2004	3000368		FLORIDA POWER & LIGHT – ST. LUCIE	00072539
9903-470	14209071	4/27/2005	3001086		FLORIDA POWER & LIGHT – TURKEY POINT	80356
9903-470	14209072	4/27/2005	3001086		FLORIDA POWER & LIGHT – TURKEY POINT	80356
9903-470	11514197	7/14/2003	92917	108898	NEBRASKA PUBLIC POWER DIST – COOPER STATION	4500028301-AFW 2353
9903-470	13149515	3/26/2003	106919		NEBRASKA PUBLIC POWER DIST – COOPER STATION	4500028501
9903-470	14081384	12/27/2004	3000733		NEBRASKA PUBLIC POWER DIST – COOPER STATION	4500042762
9903-470	14081385	12/27/2004	3000733		NEBRASKA PUBLIC POWER DIST – COOPER STATION	4500042762
9903-365	14177285	6/10/2005	8000316		PENNSYLVANIA POWER & LIGHT – SUSQUEHANNA	296924
9903-365	14177286	6/10/2005	8000316		PENNSYLVANIA POWER & LIGHT – SUSQUEHANNA	296924
9903-365	14177470	6/10/2005	8000316		PENNSYLVANIA POWER & LIGHT – SUSQUEHANNA	296924
9903-365	14177471	12/13/2005	8000316		PENNSYLVANIA POWER & LIGHT – SUSQUEHANNA	296924
9903-365	14177472	12/13/2005	8000316		PENNSYLVANIA POWER & LIGHT – SUSQUEHANNA	296924
9903-365	14177473	12/13/2005	8000316		PENNSYLVANIA POWER & LIGHT – SUSQUEHANNA	296924
9903-365	14177474	12/13/2005	8000316		PENNSYLVANIA POWER & LIGHT – SUSQUEHANNA	296924

<u>Part No.</u>	<u>Serial #</u>	<u>Latest ESI Ship Date</u>	<u>Original ESI SO#</u>	<u>Repair & Return ESI SO#</u>	<u>DOMESTIC CUSTOMER</u>	<u>Customer PO</u>
9903-470	13709567	8/20/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13713930	6/16/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13713931	6/16/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13715637	6/16/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13715638	6/16/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13716888	6/16/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13716889	6/16/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13717949	8/20/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13717950	8/20/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13719247	8/20/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13719248	8/20/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13720684	8/20/2004	8000005		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13861533	3/7/2005	3000571		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	14146651	4/28/2005	3000957		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	14146660	4/28/2005	3000957		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	14151877	4/28/2005	3000957		SOUTHERN CALIFORNIA EDISON CO – SAN ONOFRE	6H2N3025
9903-470	13564433	8/12/2003	112425		TENNESSEE VALLEY AUTHORITY – WATTS BAR	00001690/00251
					FOREIGN CUSTOMER	
9903-470	13149512	7/9/2002	96580		KOREA HYDRO & NUCLEAR POWER CO – KORI 2	NKR2-01M0142-010
9903-470	13253050	7/9/2002	96580		KOREA HYDRO & NUCLEAR POWER CO – KORI 2	NKR2-01M0142-010
9903-470	13263718	7/9/2002	96580		KOREA HYDRO & NUCLEAR POWER CO – KORI 2	NKR2-01M0142-010
9903-470	13789808	7/23/2004	8000124		KOREA HYDRO & NUCLEAR POWER CO – KORI 3 & 4	K040102011
9903-470	13789815	7/23/2004	8000124		KOREA HYDRO & NUCLEAR POWER CO – KORI 3 & 4	K040102011
9903-470	13789818	7/23/2004	8000124		KOREA HYDRO & NUCLEAR POWER CO – KORI 3 & 4	K040102011
9903-470	13789819	1/28/2005	8000128		KOREA HYDRO & NUCLEAR POWER CO – KORI 3 & 4	K040102011
9903-470	14425565	10/12/2005		8000457	KOREA HYDRO & NUCLEAR POWER CO – KORI 3 & 4	K040102011 AFW 2601
9903-470	14071858	12/15/2004	3000714		KOREA HYDRO & NUCLEAR POWER CO – ULCHIN	U040353011
9903-470	14071859	12/15/2004	3000714		KOREA HYDRO & NUCLEAR POWER CO – ULCHIN	U040353011
9903-470	14073051	12/15/2004	3000714		KOREA HYDRO & NUCLEAR POWER CO – ULCHIN	U040353011
9903-470	14073052	12/15/2004	3000714		KOREA HYDRO & NUCLEAR POWER CO – ULCHIN	U040353011
9903-470	14073053	12/15/2004	3000714		KOREA HYDRO & NUCLEAR POWER CO – ULCHIN	U040353011
9903-470	14081386	12/15/2004	3000714		KOREA HYDRO & NUCLEAR POWER CO – ULCHIN	U040353011
9903-365	13383317	3/6/2003	104392		KOREA HYDRO & NUCLEAR POWER – WOLSONG	NWS1-02M0041-810
9903-365	13383318	3/6/2003	104392		KOREA HYDRO & NUCLEAR POWER – WOLSONG	NWS1-02M0041-810
9903-365	13384198	3/6/2003	104392		KOREA HYDRO & NUCLEAR POWER – WOLSONG	NWS1-02M0041-810
9903-365	13384199	3/6/2003	104392		KOREA HYDRO & NUCLEAR POWER – WOLSONG	NWS1-02M0041-810
9903-365	13467372	4/30/2003	108337		KOREA HYDRO & NUCLEAR POWER – WOLSONG	W030013011
9903-365	13467373	4/30/2003	108337		KOREA HYDRO & NUCLEAR POWER – WOLSONG	W030013011
9903-365	13468141	4/30/2003	108337		KOREA HYDRO & NUCLEAR POWER – WOLSONG	W030013011
9903-365	13468142	4/30/2003	108337		KOREA HYDRO & NUCLEAR POWER – WOLSONG	W030013011
9903-470	12382054	6/17/2004	102141	8000173	KOREA HYDRO & NUCLEAR POWER CO – YONGGWANG	NYG1-02M0086-010
9903-470	13351538	12/6/2002	102141		KOREA HYDRO & NUCLEAR POWER CO – YONGGWANG	NYG1-02M0086-010
9903-470	13351539	12/6/2002	102141		KOREA HYDRO & NUCLEAR POWER CO – YONGGWANG	NYG1-02M0086-010
9903-470	13352957	12/6/2002	102141		KOREA HYDRO & NUCLEAR POWER CO – YONGGWANG	NYG1-02M0086-010
9903-470	13352958	12/6/2002	102141		KOREA HYDRO & NUCLEAR POWER CO – YONGGWANG	NYG1-02M0086-010
9903-470	13603450	12/29/2003	115518		NUCLEAR POWER PLANT KRSCO+	8035 / 309 REV 1
9903-470	13684563	3/3/2004	115518		NUCLEAR POWER PLANT KRSCO+	8035 / 309 REV 1
9903-470	13684564	3/3/2004	115518		NUCLEAR POWER PLANT KRSCO+	8035 / 309 REV 1

CONCLUSION:

The suspect DRU's listed under Affected Customers could experience an increase in IC failures. These reported IC failures occurred when the DRU was issued a raise or lower signal. Therefore, in-service, suspect DRU's that have successfully completed surveillance testing are not susceptible to this failure mode while energized in standby, since raise and/or lower signals are normally not issued during emergency mode operation. DRU failure can be detected by observing a sudden load shift and/or loss of load adjustability when synchronized with the utility or by a sudden frequency shift and/or loss of speed adjustability when running isolated from the utility.

CORRECTIVE ACTION:

1. Suspect DRU's that are currently not in service should have the IC's replaced as soon as possible. Contact ESI's Customer Service department with the part number and serial number of the DRU(s).
2. Suspect DRU's that are currently in service should be replaced at the earliest convenience with a non-suspect DRU or with a corrected DRU (item 1 above). The removed DRU can then have its IC's replaced and retained as a spare.

SERVICE BULLETIN
**Digital Reference Unit
CMOS PDIP Integrated Circuit—Corrosion Issue**

January 2006

01363A

Issue

Corrosion has been detected in some CMOS PDIP integrated circuits (IC) used in Digital Reference Unit (DRU) products. The corrosion of certain ICs on the circuit board can cause the DRU to function incorrectly.

Description

Woodward has identified DRUs that have been returned for repair due to internal corrosion of a CMOS PDIP integrated circuit from a specific manufacturer. Failure analysis recently completed on defective components confirmed that the cause of failure was due to internal aluminum conductor corrosion resulting from delamination of the outer plastic package from the device lead frame. Although the IC manufacturer has not identified a specific failure cause, customer returns indicate a slight increase in the failure rate that began with units shipped in November, 2000. Alternative manufacturer's components have been used in these applications with no reported problems.

The potential failure modes of affected units could result in the DRU not allowing speed control raise/ lower adjustment in the governor control system, or could result in a control shutdown.

Affected Units

Specific DRU controls with the following item numbers that shipped between 1 November 2000 and 22 November 2005, containing the suspect manufacturers/type components may be more susceptible to delamination.

9903-364	9900-486	5422-047	8272-682
9903-365	9900-517	5422-059	8272-683
9903-439	9900-519		8272-684
9903-470	9900-524		8272-685

Refer to tables below for specific serial numbers. Units that are currently within the standard warranty period (as of 1 January 2006) are identified with an asterisk (*) The affected date range was determined from actual field return and inventory transaction data.

Corrective Action

Woodward has removed the specific manufacturer as an approved vendor for the affected IC grade on all eight component part numbers that are used on the DRU.

Customer Action

If it is determined that a unit needs to be returned to Woodward, please select one of the following options:

- Contact your Woodward customer service representative for a return authorization number (RAN) and return the unit(s) to Woodward.
- If a return is not feasible, contact your Woodward customer service representative to discuss the availability of replacement/exchange unit(s).

Please refer to this service bulletin number when scheduling your return. Service bulletin actions will be performed at no charge for all controls that fall within the product warranty period at the time they are returned. Units outside of the standard warranty period can be quoted for replacement of the affected ICs.

Parent Item	Serial Number
5422-047	13248424
5422-059	13049814
8272-682	12376944
8272-682	12376945
8272-682	12376946
8272-682	12387999
8272-682	12388000
8272-682	12388001
8272-682	12388002
8272-682	12404127
8272-682	12404128
8272-682	12404129
8272-682	12404130
8272-682	12404386
8272-682	12404387
8272-682	12405817
8272-682	12405818
8272-682	13016075
8272-682	13017714
8272-682	13017715
8272-682	13022073
8272-682	13022074
8272-682	13022075
8272-682	13022076
8272-682	13022077
8272-682	13023706
8272-682	13025071
8272-682	13025072
8272-682	13046435
8272-682	13046436
8272-682	13046437
8272-682	13046438
8272-682	13061950
8272-682	13063072
8272-682	13067610
8272-682	13073421
8272-682	13074204
8272-682	13081916
8272-682	13081917
8272-682	13092871
8272-682	13092872
8272-682	13102898
8272-682	13102899
8272-682	13104150
8272-682	13104151
8272-682	13106729
8272-682	13107148
8272-682	13107149
8272-682	13108663
8272-682	13110231
8272-682	13112097
8272-682	13113952
8272-682	13115070
8272-682	13115071
8272-682	13146972

8272-682	13146974
8272-682	13147940
8272-682	13147941
8272-682	13149674
8272-682	13150078
8272-682	13150079
8272-682	13152934
8272-682	13179256
8272-682	13179257
8272-682	13179258
8272-682	13190573
8272-682	13192039
8272-682	13192940
8272-682	13193629
8272-682	13193630
8272-682	13195491
8272-682	13196796
8272-682	13197975
8272-682	13200352
8272-682	13207221
8272-682	13207741
8272-682	13227661
8272-682	13228868
8272-682	13234756
8272-682	13236766
8272-682	13236767
8272-682	13237755
8272-682	13246607
8272-682	13259342
8272-682	13268966
8272-682	13270962
8272-682	13272212
8272-682	13306023
8272-682	13309056
8272-682	13310998
8272-682	13312469
8272-682	13315405
8272-682	13322143
8272-682	13324398
8272-682	13333103
8272-682	13333104
8272-682	13333807
8272-682	13334306
8272-682	13334307
8272-682	13344260
8272-682	13348445
8272-682	13357514
8272-682	13358275
8272-682	13370076
8272-682	13391521
8272-682	13393136
8272-682	13394666
8272-682	13395538
8272-682	13396420
8272-682	13396421
8272-682	13399323
8272-682	13399324

8272-682	13409633
8272-682	13460535
8272-682	13462311
8272-682	13465497
8272-682	13472131
8272-682	13477583
8272-682	13482423
8272-682	13482424
8272-682	13485000
8272-682	13485002
8272-682	13486659
8272-682	13488277
8272-682	13490722
8272-682	13492120
8272-682	13493455
8272-682	13494997
8272-682	13495948
8272-682	13496746
8272-682	13513994
8272-682	13514974
8272-682	13523515
8272-682	13532991
8272-682	13534050
8272-682	13534792
8272-682	13552620
8272-682	13560027
8272-682	13563676
8272-682	13563678
8272-682	13563679
8272-682	13569088
8272-682	13569089
8272-682	13570137
8272-682	13570138
8272-682	13578510
8272-682	13578511
8272-682	13592746
8272-682	13594624
8272-682	13594625
8272-682	13603922
8272-682	13617947
8272-682	13617948
8272-682	13619809
8272-682	13619810
8272-682	13653381
8272-682	13660810
8272-682	13660811
8272-682	13666891
8272-682	13666892
8272-682	13667601
8272-682	13691730
8272-682	13691731
8272-682	13710472
8272-682	13710473
8272-682	13740427 *
8272-682	13749950 *
8272-682	13749951
8272-682	13752839

8272-682	13752840 *
8272-682	13752841
8272-682	13752842 *
8272-682	13753388
8272-682	13753389
8272-682	13754550
8272-682	13754551
8272-682	13856137 *
8272-682	13856138 *
8272-682	13861547 *
8272-682	13892906 *
8272-682	13892907 *
8272-682	13903010 *
8272-682	13905060 *
8272-682	13905061 *
8272-682	13906563 *
8272-682	13906564 *
8272-682	13908825 *
8272-682	13908826 *
8272-682	13911053 *
8272-682	13911054 *
8272-682	13911055 *
8272-682	13913706 *
8272-682	13913707 *
8272-682	13917923 *
8272-682	13917924 *
8272-682	13920044 *
8272-682	13920045 *
8272-682	13920046 *
8272-682	13920047 *
8272-682	13929243 *
8272-682	13929244 *
8272-682	13977413 *
8272-682	13977414 *
8272-682	14093964 *
8272-682	14122517 *
8272-682	14136274 *
8272-682	14136275 *
8272-682	14141274 *
8272-682	14141275 *
8272-682	14145960 *
8272-682	14146064 *
8272-682	14178659 *
8272-682	14186820 *
8272-682	14186821 *
8272-682	14253990 *
8272-682	14326934 *
8272-682	14340711 *
8272-682	14343378 *
8272-682	14343379 *
8272-682	14344980 *
8272-682	14354558 *
8272-682	14354559 *
8272-682	14362063 *
8272-682	14362064 *
8272-682	14362065 *
8272-682	14362066 *

8272-682	14368822 *	8272-683	14373255 *	9900-517	13014781	9900-517	13472184
8272-682	14368823 *	8272-683	14373256 *	9900-517	13014782	9900-517	13474162
8272-682	14369958 *	8272-683	14406656 *	9900-517	13029282	9900-517	13474724
8272-682	14391451 *	8272-684	12372929	9900-517	13032320	9900-517	13476735
8272-682	14398961 *	8272-684	13001460	9900-517	13032321	9900-517	13478523
8272-682	14462586 *	8272-684	13041926	9900-517	13034056	9900-517	13479101
8272-682	14462587 *	8272-684	13041927	9900-517	13034057	9900-517	13479817
8272-682	14462588 *	8272-684	13067718	9900-517	13035950	9900-517	13479818
8272-682	14471962 *	8272-684	13080884	9900-517	13035951	9900-517	13480758
8272-682	14471963 *	8272-684	13080885	9900-517	13037773	9900-517	13483172
8272-682	14519058 *	8272-684	13182972	9900-517	13037774	9900-517	13485033
8272-682	14519059 *	8272-684	13188987	9900-517	13039523	9900-517	13485034
8272-683	12374531	8272-684	13305136	9900-517	13039524	9900-517	13505140
8272-683	12375576	8272-684	13307431	9900-517	13126265	9900-517	13505141
8272-683	12375577	8272-684	13315407	9900-517	13126266	9900-517	13511804
8272-683	12385202	8272-684	13316132	9900-517	13127367	9900-517	13511805
8272-683	12385203	8272-684	13372903	9900-517	13127368	9900-517	13513439
8272-683	12388003	8272-684	13550483	9900-517	13155519	9900-517	13513440
8272-683	12388004	8272-684	13668487	9900-517	13155520	9900-517	13513441
8272-683	13046564	8272-684	13773978	9900-517	13173268	9900-517	13513442
8272-683	13051247	8272-684	13773979	9900-517	13173269	9900-517	13513443
8272-683	13064803	8272-684	13773994	9900-517	13232471	9900-517	13514060
8272-683	13080284	8272-684	13901799 *	9900-517	13232472	9900-517	13514061
8272-683	13080881	8272-684	13901800 *	9900-517	13233560	9900-517	13515039
8272-683	13141533	8272-684	13929241 *	9900-517	13233561	9900-517	13515040
8272-683	13141534	8272-684	13929242 *	9900-517	13234372	9900-517	13515999
8272-683	13143931	8272-684	14054104 *	9900-517	13234373	9900-517	13516000
8272-683	13152440	8272-684	14054105 *	9900-517	13235074	9900-517	13516001
8272-683	13152441	8272-684	14252872 *	9900-517	13235075	9900-517	13516002
8272-683	13160181	8272-684	14253989 *	9900-517	13251756	9900-517	13516003
8272-683	13183754	8272-684	14388707 *	9900-517	13251757	9900-517	13516004
8272-683	13184515	8272-684	14430623 *	9900-517	13259801	9900-517	13522186
8272-683	13185920	8272-684	14430624 *	9900-517	13263903	9900-517	13522187
8272-683	13188925	8272-685	12376631	9900-517	13269127	9900-517	13522188
8272-683	13272234	8272-685	12376632	9900-517	13275087	9900-517	13522189
8272-683	13278187	8272-685	12385265	9900-517	13367767	9900-517	13523557
8272-683	13284783	8272-685	13046638	9900-517	13367768	9900-517	13523558
8272-683	13287177	8272-685	13046639	9900-517	13368593	9900-517	13524124
8272-683	13315406	8272-685	13046643	9900-517	13368594	9900-517	13524125
8272-683	13364519	8272-685	13047315	9900-517	13370749	9900-517	13613325
8272-683	13386354	8272-685	13047316	9900-517	13370750	9900-517	13613326
8272-683	13436549	8272-685	13047317	9900-517	13372197	9900-517	13615453
8272-683	13448861	8272-685	13048772	9900-517	13391576	9900-517	13615454
8272-683	13514975	8272-685	13210549	9900-517	13391577	9900-517	13617163
8272-683	13525997	8272-685	13210550	9900-517	13392176	9900-517	13617164
8272-683	13673185	8272-685	13242534	9900-517	13392177	9900-517	13617165
8272-683	13742765	8272-685	13628945	9900-517	13393077	9900-517	13617166
8272-683	13742766	8272-685	13901801 *	9900-517	13393078	9900-517	13617167
8272-683	13900415 *	8272-685	14479401 *	9900-517	13456706	9900-517	13617168
8272-683	13915398 *	9900-486	13091988	9900-517	13456707	9900-517	13638877
8272-683	13942393 *	9900-486	13665271	9900-517	13457658	9900-517	13638878
8272-683	14136276 *	9900-486	13761403 *	9900-517	13457659	9900-517	13639802
8272-683	14136277 *	9900-486	13812358 *	9900-517	13458668	9900-517	13639803
8272-683	14289446 *	9900-486	14423465 *	9900-517	13458669	9900-517	13654274
8272-683	14289451 *	9900-517	12393072	9900-517	13469225	9900-517	13654275
8272-683	14369956 *	9900-517	13014779	9900-517	13470453	9900-517	13658560
8272-683	14369957 *	9900-517	13014780	9900-517	13471122	9900-517	13658561

9900-517 13667707
9900-517 13667708
9900-517 13668550
9900-517 13668551
9900-517 13670118
9900-517 13670119
9900-517 13673199
9900-517 13675946
9900-517 13686505
9900-517 13991200 *
9900-517 14035012 *
9900-517 14036408 *
9900-517 14036409 *
9900-517 14037963 *
9900-517 14037964 *
9900-517 14039704 *
9900-517 14039705 *
9900-517 14043933 *
9900-517 14043934 *
9900-517 14043935 *
9900-517 14045202 *
9900-517 14045203 *
9900-517 14081382 *
9900-517 14081383 *
9900-517 14082820 *
9900-517 14085314 *
9900-517 14086748 *
9900-517 14086749 *
9900-517 14089130 *
9900-517 14089131 *
9900-517 14090346 *
9900-517 14090347 *
9900-517 14091761 *
9900-517 14091762 *
9900-517 14093969 *
9900-517 14093970 *
9900-517 14096259 *
9900-517 14096260 *
9900-517 14119910 *
9900-517 14119911 *
9900-517 14120965 *
9900-517 14120966 *
9900-517 14220887 *
9900-517 14220888 *
9900-517 14220889 *
9900-517 14234705 *
9900-517 14270727 *
9900-517 14270728 *
9900-517 14290601 *
9900-517 14290602 *
9900-517 14292225 *
9900-517 14292226 *
9900-517 14304130 *
9900-517 14304131 *
9900-517 14318895 *
9900-517 14318896 *
9900-517 14322884 *

9900-517 14322885 *
9900-517 14330595 *
9900-517 14330597 *
9900-517 14333886 *
9900-517 14333887 *
9900-517 14338769 *
9900-524 13000971
9900-524 13051903
9900-524 13051904
9900-524 13072526
9900-524 13072527
9900-524 13105939
9900-524 13105940
9900-524 13108690
9900-524 13108691
9900-524 13256344
9900-524 13266616
9900-524 13266617
9900-524 13268082
9900-524 13268083
9900-524 13268986
9900-524 13268987
9900-524 13271636
9900-524 13272235
9900-524 13616210
9900-524 13616211
9900-524 13617949
9900-524 13617950
9900-524 13620364
9900-524 13620365
9900-524 13625325
9900-524 13630415
9900-524 13639730
9900-524 13967396 *
9900-524 13967397 *
9900-524 13967398 *
9900-524 13967399 *
9900-524 13967400 *
9900-524 13967401 *
9900-524 14113073 *
9900-524 14113074 *
9900-524 14292224 *
9903-364 13154469
9903-364 13155639
9903-364 13158005
9903-364 13161043
9903-364 13161044
9903-364 13280329
9903-364 13280330
9903-365 13073449
9903-365 13175373
9903-365 13175374
9903-365 13262045
9903-365 13319008
9903-365 13383317
9903-365 13383318
9903-365 13384198

9903-365 13384199
9903-365 13467372
9903-365 13467373
9903-365 13468141
9903-365 13468142
9903-365 13576301
9903-365 13576302
9903-365 13577159
9903-365 13577160
9903-365 13577892
9903-365 13577893
9903-365 13649235
9903-365 14177284 *
9903-365 14177285 *
9903-365 14177286 *
9903-365 14177469 *
9903-365 14177470 *
9903-365 14177471 *
9903-365 14177472 *
9903-365 14177473 *
9903-365 14177474 *
9903-365 14374699 *
9903-365 14374700 *
9903-365 14374701 *
9903-365 14484581 *
9903-439 13115209
9903-439 13115786
9903-439 13149152
9903-439 13149153
9903-439 13154486
9903-439 13170657
9903-439 13170658
9903-439 13186111
9903-439 13186112
9903-439 13192223
9903-439 13193853
9903-439 13206689
9903-439 13284579
9903-439 13284580
9903-439 13344808
9903-439 13445722
9903-439 13516650
9903-439 13541781
9903-439 13541782
9903-439 13542472
9903-439 13542473
9903-439 13576266
9903-439 13629594
9903-439 13647136
9903-439 13650148
9903-439 13650149
9903-439 13650150
9903-439 13651337
9903-439 13651338
9903-439 13651339
9903-439 13982105 *
9903-439 14001239 *

9903-439 14205663 *
9903-470 13149512
9903-470 13476736
9903-470 12382054
9903-470 12382055
9903-470 12382056
9903-470 12382057
9903-470 13149513
9903-470 13149514
9903-470 13149515
9903-470 13253050
9903-470 13263718
9903-470 13347822
9903-470 13347823
9903-470 13348461
9903-470 13348462
9903-470 13349177
9903-470 13351538
9903-470 13351539
9903-470 13352957
9903-470 13352958
9903-470 13443890
9903-470 13443891
9903-470 13443892
9903-470 13490742
9903-470 13564431
9903-470 13564432
9903-470 13564433
9903-470 13603450
9903-470 13671900
9903-470 13684563
9903-470 13684564
9903-470 13709567
9903-470 13713930
9903-470 13713931
9903-470 13715637
9903-470 13715638
9903-470 13716888
9903-470 13716889
9903-470 13717949
9903-470 13717950
9903-470 13719247
9903-470 13719248
9903-470 13720683
9903-470 13720684
9903-470 13789808
9903-470 13789809
9903-470 13789815
9903-470 13789818
9903-470 13789819
9903-470 13861533 *
9903-470 14071858 *
9903-470 14071859 *
9903-470 14071860 *
9903-470 14073051 *
9903-470 14073052 *
9903-470 14073053 *

9903-470	14081384 *
9903-470	14081385 *
9903-470	14081386 *
9903-470	14146651 *
9903-470	14146660 *
9903-470	14151877 *
9903-470	14209071 *
9903-470	14209072 *
9903-470	14212574 *
9903-470	14331530 *
9903-470	14366376 *
9903-470	14425565 *
9903-470	14501580 *
9903-470	14501581 *
9903-470	14503911 *
9903-470	14503912 *
9903-470	14517524 *
9903-470	14517525 *
9903-470	14517526 *



PO Box 1519, Fort Collins CO 80522-1519, USA
1000 East Drake Road, Fort Collins CO 80525, USA
Phone +1 (970) 482-5811 • Fax +1 (970) 498-3058

Email and Website—www.woodward.com

**Woodward has company-owned plants, subsidiaries, and branches,
as well as authorized distributors and other authorized service and sales facilities throughout the world.**

Complete address / phone / fax / email information for all locations is available on our website.

06/1/F