

2016 SERVICE DEALER GUIDE **VOLUME 1**

DORMAN[®]
NEW SINCE 1918

Engine
Intake
Manifolds

Turbochargers

Auto Transmission
Kickdown Solenoids

Leaf Spring Hangers

HID Headlight
Control Modules

Formerly "Dealer Only" Parts,
Now Available in the Aftermarket



WWW.DORMANPRODUCTS.COM



DORMAN ENGINEERED SOLUTIONS
DESIGNED TO CORRECT OE FAILURES

WIN WITH DORMAN'S
Outdoor Adventure
Window Regulator Sweepstakes

See inside for details >



AFTERMARKET LEADING COVERAGE & QUALITY

Over 2,300 SKUs Available



OE PROBLEM:

Original units fail when cable pulls free from broken plastic window slide.



Improved design includes metal cable grips and over molded window slide for added strength.



Power Window Motor and Regulator Assemblies

Mechanical component attached to window glass enabling the ability to raise and lower vehicle window

748-568: Jeep Liberty 2007-02

- Dorman Window Regulators include all components needed for a complete repair
- Direct-replacement plug-and-play design — no wire splicing required

ALSO AVAILABLE



741-306 [FL], 741-307 [FR]:
Honda Accord 2007-03



748-524 [FL], 748-525 [FR]:
Infiniti QX56 2010-04;
Nissan Armada 2013-05,
Pathfinder 2004, Titan 2010-04



748-576 [FR], 748-577 [FL]:
Jeep Liberty 2012-08

#Techstrust



WIN WITH DORMAN'S

Outdoor Adventure Window Regulator Sweepstakes

Between May and September, every qualifying purchase of a Dorman Window Regulator earns you a chance to win a fabulous outdoor experience and prizes!

For more information, visit DormanSweepstakes.com



...and more!

NO PURCHASE NECESSARY. A PURCHASE WILL NOT INCREASE YOUR CHANCES OF WINNING. This is a closed promotion and not opened to the general public. Must be legal resident of the 50 United States (D.C.) or Canada (except Quebec), 18 years or older (or age of majority in his/her state) as of the start date. For official rules with details on entry without purchase, complete eligibility requirements, prize descriptions, odds disclosure and other details, visit www.dormansweepstakes.com. Sweepstakes ends 9/30/16. Sponsored by Dorman Products, Inc. Void where prohibited.



Over 65 SKUs Available



Air Bag Clocksprings

Relays power to steering wheel functions and air bag

525-028: Chevrolet Malibu 2012-08, Malibu 2005-04, Pontiac G6 2010-05, Saturn Aura 2009-07

- Restores the airbag system to its original performance
- Secure direct-fit connectors are pre-attached; no wire splicing necessary

Failure Mode:

- Failure results in wheel controls not functioning properly or illumination of the airbag light

ALSO AVAILABLE



525-019:

GM Astro, Safari, Silverado, Sierra, Tahoe, Suburban, Express, Savana 2002-93



525-027:

GM Bravada, Trailblazer, Envoy, Rainier, SSR 2004-02



525-140:

Chrysler, Dodge, Plymouth Minivans 2000-98



525-401:

Pontiac 2010-09; Toyota 2013-05



525-403:

Toyota Camry 2006-02, Sienna 2010-04

6 SKUs Available



ALSO AVAILABLE:
BMW, Chrysler, Ford & Toyota applications

Antenna Masts

Secures antenna in proper position

76840: Honda 2014-00; Subaru 2010-08



Cabin Air Filter Cover

Retains cabin air filter in place

45000: Pontiac Vibe 2008-03



OE PROBLEM:

The Dealer's only repair for a failed original hinge is the complete replacement of an entire console assembly.

Dorman's kit allows for replacement of just the failed original hinge, saving an average of 85% on repair costs.

Center Console Hinge Repair Kit

Repair kit for a broken or damaged center dash console

924-451: Toyota Corolla 2008-03, Matrix 2008-03

Over 5 SKUs Available



Center Console Latches

Secures console lid in closed position

924-822: Volkswagen Beetle 2010-98, Jetta 2005-99, Passat 2001-99

- Replace just the failed latch, instead of the entire center console assembly
- Made to match the overall aesthetic design of the original latch

Over 15 SKUs Available



Console Lids

Replacement lid for a center console assembly

924-829: Volkswagen Beetle 2005-98

- Complete Kit - Includes all necessary hardware for a complete repair (where applicable)
- Reduce Repair Costs - Replace just the broken lid, instead of the entire console assembly

5 SKUs Available



Dashboard Air Vents

Allows vehicle occupants to control air flow and direction

74337: Jeep Liberty 2007-02

- Necessary replacement item ensures interior ride comfort

Over 5 SKUs Available



Door Arm Rests

Replacement for frequently worn driver's side door

924-838: Toyota Prius 2009-04

- Reduce Repair Costs - Replace just the failed arm rest, instead of the entire door panel

HIGH GROWTH POTENTIAL

As Integrated Door Lock Actuators become increasingly common in today's new vehicles, Dorman helps keep you ahead of replacement demand through the continuous introduction of new applications.



Over 590 SKUs Available



Door Lock Actuator Motors

Electric motor located inside door housing used to control lock and unlock functions

931-318: GM Suburban, Tahoe, Yukon, Silverado, Sierra, Escalade 2007-00

- Aftermarket leading application coverage for Integrated Door Lock Actuators
- Engineered with high quality electric motor

Failure Mode:

- Failure results in lock becoming inoperable

OVER 590 SKUS AVAILABLE INCLUDING:



931-080:

Chrysler 2015-08, 2009, Ram Pickup 2015-09, Compass/Patriot/Caliber 2015-11, Minivans 2010-08



931-310:

Saturn Aura 2009-07; Chevrolet Malibu 2012-08

FOR ADDITIONAL INFORMATION PLEASE VISIT US AT:

WWW.DORMANPRODUCTS.COM/IDLASOLUTIONS



OE PROBLEM:

The Dealer's only repair for a failed clip is the complete replacement of a headrest assembly.



Dorman makes it possible to replace only the failed original clip, saving an average of 90% on repair costs.

Headrest Mechanism

Repair kit restores ability to adjust vehicles headrest to the desired level of comfort and safety

924-264: BMW 2004-94, 7-Series 1999-94, 5-Series 2004-98

- Includes necessary components for complete installation
- Easy to install



Fuel Filler Door Switch

Remotely operates fuel door lock mechanism

901-350: Lincoln Mark VIII 1998-93

- Restores the ability to release the fuel door with ease
- Designed to match size, function and appearance of the original



Interior Door Lights

Interior reflector lamp that illuminates when vehicle door is open

923-103: GM C/K Series Trucks, Silverado, Sierra 2006-95

- Replacement door lights available for the right and left side vehicle doors
- Easy to install



Over 75 SKUs Available



OE PROBLEM:

The Dealer offers no repair for worn or cracked key fobs, instead requiring expensive replacement and programming.



Dorman's case repair allows customers to easily replace just the case, saving cost and eliminating the need to program.

Keyless Remote Cases

Replacement for broken keyless remote cases

13666: Subaru Baja 2006, Forester 2007-05, Impreza 2006-05

- Each replacement case includes new outer shell and keypad
- No special tools required



3 SKUs Available

Parking Brake Release Cables

924-087: Various Ford 2004-99

- Repair solution for broken release cable



Sunroof Switch Bezel

Interior part that retains sunroof switch

924-821: Chevrolet Cobalt 2010-05, Pontiac G5 2010-07, Pursuit 2006-05

- Direct fit replacement matches original design

4 SKUs Available



ALSO AVAILABLE:
Chevy & GMC applications

Tailgate Moldings

Protects top edge of vehicle tailgate

924-572: Ford F-250/350/450/550 Super Duty 2014-08

- Replaces original cracked moldings
- Easy to install, requires no special tools

Over 25 SKUs Available



Undercar Shields

Protects vehicle engine from road debris and severe weather conditions

924-048: Chrysler 300 2010-07, Dodge Charger 2010-07, Magnum 2008-07

- Includes all hardware needed for a complete repair (where applicable)

Over 90 SKUs Available



Import & Domestic applications available

Wheel Caps

Replacement covers for steel wheels

910-104: Chevrolet Malibu 2008-04

- Designed to match original look and accept original center caps

Over 35 SKUs Available



Windshield Washer Nozzles

Controls and directs flow of washer fluid

47237: Universal

- Universal and direct replacement washer nozzles available (where applicable)

Over 200 SKUs Available



Windshield Wiper Arms

Maintains pressure and wiper blade contact with windshield

42713: Toyota Prius 2009-03

- Long-lasting enamel prevents flaking, peeling and fading

Over 200 SKUs Available



Windshield Wiper Linkages

Provides mechanical connection between the wiper motor and wiper arm

602-322: Ford Explorer 2003-97, Explorer Sport Trac 2005-01, Ranger 2011-97

- Includes everything needed for a complete repair



30 SKUs Available



Upgraded Diodes



Dorman design features upgraded diodes, and complete reflowing of solder joints.



OE PROBLEM:

Original design relies on transistors that easily corrode, leading to electronic failure.

ABS Control Modules


ABS system component that regulates brake pressure, to prevent sliding or skidding as a result of hard braking

599-775: GM Avalanche 1500, Silverado 1500, Suburban 1500, Tahoe, Sierra 1500, Yukon 1500 2013-09

- Completely remanufactured and vehicle simulator tested
- Plug and play - no programming required
- Available for both import and domestic vehicle applications (where applicable)



Brake
Dust
Shield





Over 25 SKUs Available

Brake Dust Shields

Prevents debris from entering the braking system

924-371: Ford Explorer 2003-01, Explorer Sport Trac 2005-01

- Includes two plates in just one SKU, saving time and money (where applicable)
 - Powder coated finish prevents rust and corrosion
- Failure Mode:**
- Rust and corrosion
 - Failure results in rattling sound from brake area



Over 65 SKUs Available

Brake Hydraulic Lines – Stainless Steel Brake Lines

Direct fit pre-bent stainless steel brake lines carry pressurized fluid from the master cylinder to the brake caliper or cylinder at the wheel

919-102: Chevrolet Silverado 1500 2002-99, GMC Sierra 1500 2002-99

- Each kit includes multiple lines for a complete truck application repair

Over 30 SKUs Available



Body Mount Sets

Secures frame or subframe to vehicle body, isolating road noise and vibration

924-354: Jeep Wrangler 2006-05, 1997, 1995-87

- All necessary bushings and hardware are included for a complete repair (where applicable)

Over 20 SKUs Available



Import & Domestic applications available

Leaf Springs

Spring used to support vehicle suspension

929-302: Dodge Ram 1500 1997-94, Ram 2500 1997

- Replacement restores an even suspension load, resulting in a smoother ride
- Coated for added resistance to rust and corrosion

Over 30 SKUs Available



Leaf Spring Hangers

Attaches leaf spring to the frame of the vehicle

722-093: Ford Explorer 2002-01, Explorer Sport Trac 2002-01

- Includes bracket and mounting hardware for a complete repair (where applicable)

4 SKUs Available



Leaf Spring Bumpers

Prevents damage to vehicle suspension during heavy impact, while driving over bumps or potholes

523-065: Chevrolet Express 1500 2014-96, GMC Savana 1500 2014-96

- Replacement eliminates knocking noise from leaf spring

Over 30 SKUs Available



Leaf Spring Shackles

Mounts leaf spring to frame

722-059: Dodge Durango 2003-98

- Includes all necessary hardware for a complete repair (where applicable)



Complete Knuckle Assembly

Over 10 SKUs Available



OE PROBLEM:

Dealer does not offer bushing separately, forcing replacement of entire assembly.



Dorman's Bushing only replacement saves shop time and money.

Suspension Knuckle Bushings

Bushing used as the mounting point between the knuckle and suspension arms or links

523-077: Lexus GS400 2000-98, GS300 2005-98, GS430 2005-01, IS300 2005-01, SC430 2010-02

- Replacement restores smooth ride, directional stability, and agile handling

Over 15 SKUs Available



Suspension Control Arm Bumpers

Prevents control arm from contacting vehicle frame

905-208: GM 2014-99; Silverado, Sierra, Tahoe, Suburban 2006-99; Express & Savana 2014-03

- Constructed of upgraded material for greater durability
- Weather and crack resistant design ensures longer service life

5 SKUs Available



Suspension Subframe Bushings

Secures frame or subframe to vehicle body and isolates road noise and vibration

523-096: Chevrolet Equinox 2014-10, GMC Terrain 2014-10

- Complete Kit - Includes all necessary components for a complete repair

Over 90 SKUs Available



Suspension Trailing Arms

Attaches wheel to vehicle frame while allowing vertical and horizontal movement

523-094: GM Cutlass, Malibu, Alero, Grand Am, Classic 2003-97

- Bushings included for a complete installation, saving time and labor (where applicable)

Over 10 SKUs Available



Suspension Trailing Arm Bushings

Connects trailing arm to vehicle frame

523-069: Ford Escape 2012-01, Mercury Mariner 2011-05

- Complete Kit - Includes necessary components for a complete repair (where applicable)



Diesel Emissions Fluid (DEF) Heater

Heats diesel exhaust fluid

904-373: Ford F-350 Super Duty 2015-11, F-450 Super Duty 2015-11, F-550 Super Duty 2015-11

- Complete Kit - Includes all necessary components for a complete DEF heater repair
- Quality tested to ensure trouble-free installation, performance and durability

Failure Mode:

- Original DEF heating element fails
- Failure results in drivability issues



Diesel Emissions Fluid (DEF) Pump

Supplies fluid to the SCR module

904-369: Ford F-250/350/450/550 Super Duty, Transit-150/250/350 2015-11

- Mounting hardware and syringe included for ease of installation
- Plug and play design, for easy installation




3 SKUs Available

Diesel Glow Plug Wiring Harnesses

Provides power to vehicle glow plugs

904-453: Ford 2010-05; F-250/350/450/550 Super Duty 2007-05; E-350/450 Super Duty 2010-05

- Direct replacement ensures a proper fit every time
- No special tools required during installation



FUEL COOLER IS LOCATED BETWEEN THE ENGINE AND FUEL TANK

Fuel Cooler

Cools and regulates diesel fuel temperatures

904-180: GM Silverado, Sierra 2500, 3500 2010-01

- Constructed of high quality aluminum for added reliability
- Easy to install direct replacement

Failure Mode:

- Fails due to corrosion and road debris

7 SKUs Available



Turbochargers

Restores vehicle power and engine efficiency

917-152: Mazda 3 2013-07

- Complete Kit - Includes O-rings for a complete repair
- Individually balance tested, with results provided in product packaging

Over 10 SKUs Available



Turbocharger Oil Lines

Feeds oil to turbocharger unit

904-116: GM Silverado, Sierra 2500 HD, 3500 2004-01

- Extensive quality testing performed to ensure this part conforms to product standards for durability and a long service life

6 SKUs Available



Turbocharger Oil Return Tubes

Carries oil away from turbocharger unit

904-125: GM Silverado, Sierra, Express, Savana 2010-04

- Includes all necessary components for a complete repair (where applicable)
- Constructed of durable materials for corrosion-resistance



Turbocharger Unison Ring

Controls vanes in turbo exhaust housing

904-267: Ford F-Series Super Duty, E-Van Super Duty 2010-05

- Replacement prevents damage to the turbocharger vanes and compressor wheel
- Constructed of quality steel material for greater performance and increased durability

FREE NEW PRODUCT ALERTS!

BE THE FIRST TO KNOW! 

ABOUT FORMERLY "DEALER ONLY" PARTS

HUNDREDS OF EXCLUSIVE NEW PARTS
DELIVERED TO YOUR EMAIL EVERY MONTH!

SIGN UP TODAY!

VISIT DORMANPRODUCTS.COM/SIGNUP





4 SKUs Available



Upgraded
Filter Plate



OE PROBLEM:

Original solenoid easily wears, corrodes and becomes contaminated.



Dorman's Solenoids are remanufactured using higher quality components designed to withstand harsh transmission environments.

Auto Trans Kickdown Solenoids (ALSO KNOWN AS: Transmission Shift Solenoid)

Receives signal from vehicle's TCM to shift transmission through the gears

609-040: Grand Cherokee, Dakota, Liberty, Durango, Commander, Aspen, Wrangler, Ram Pickup 2011-99

- Fully remanufactured and tested for durability and quality assurance
- Ready-to-Install - plug and play design requires no programming

Failure Mode:

- Inability to shift in and out of gear
- Failure results in contamination and deterioration of solenoids and pressure switches



Auto Trans Shift Tube Lever Pin

Attaches shift lever to the column

924-440: Ford, Lincoln, Mercury Vehicles 2015-90

- Replacement prevents a loose or inoperable shift lever
- Constructed of steel material for durability and performance



Auto Trans Shifter Repair Kit

Helps vehicle shift into gear smoothly

76848: Honda Accord 2005-03

- Complete Kit - Includes necessary components for a complete repair



3 SKUs Available

Auto Trans Valve Body Sealing Sleeves

Connects vehicle wiring harness to internal transmission electrical components

917-029: BMW 1, 3, 5 Series w/xDrive 2011-04



Over 120 SKUs Available

Differential Ring and Pinions

Transmits power from prop shaft to axle shafts

697-130: Dodge & GM Trucks w/11.5 In. Ring Gear Silverado, Sierra, Express, Savana, Ram Pickup 2013-01

Over 40 SKUs Available



Air Bag Impact Sensors

Alerts vehicle's onboard computer system in the event of a sudden or extreme deceleration

590-231: GM Express & Savana Van 2014-08

- Plug and play design for easy installation without the need to program

Over 10 SKUs Available



Body Control Modules

Monitors and controls various electronic accessories in a vehicle

502-017: Chevrolet Malibu 2010-08, Pontiac G6 2010-08, Saturn Aura 2009-08

- Fully remanufactured and tested for durability and quality assurance

Over 10 SKUs Available



High Intensity Discharge (HID) Headlight Control Modules

Regulates voltage to xenon headlamps, restoring proper operation of vehicle headlights

601-061: Escalade 2006-03, Challenger, Charger 2013-08; Flex, Taurus, Explorer, Edge, Mustang, MKS, MKT, F-150 2013-10

- Re-engineered design consolidates several parts into just one SKU to save inventory space



DVD Player Remote Controls

Replaces lost or broken remote for vehicle DVD player

57002: Lexus GX470 2006-03, Toyota Sequoia 2006-03, Tundra 2006-04

- This replacement brings back the convenience of watching movies in your vehicle, and restores peace and quiet on long road trips



Information Display Module

Overhead display module, providing fuel level, temperature and compass readings

599-951: Ford F-250/350/450/550 Super Duty 2007-03

- Completely remanufactured and tested
- Upgraded resistor prevents failure mode found in the original design from reoccurring
- Plug and play design and requires no additional programming during installation



Complete Original Assembly

**OE PROBLEM:**

Original Instrument Clusters often fail due to burned out motors and bulbs, leading to complete replacement.



Dorman's kit provides everything needed to repair original unit, including upgraded stepper motors, housings and bulbs.

Instrument Cluster Repair Kit

Restores proper function to instrument cluster gauges and instrument lighting for optimal performance

10-0200F: GM Impala, Monte Carlo, Aztec, Trailblazer, Envoy, Silverado, Sierra, Tahoe, Yukon, Escalade, Avalanche 2006-00

- Kit includes six upgraded stepper motors and ten replacement bulbs for a complete repair
- Replacement bulbs feature longer and thicker filaments for an extended and more reliable service life



Upgraded Gaskets

5 SKUs Available

**OE PROBLEM:**

Internal filters clog, allowing debris contamination to cause solenoid and sensor to fail.



Dorman's units include upgraded gaskets, preventing contamination.

Transmission Control Modules (ALSO KNOWN AS: TEHCM)

Combines the valve body solenoids, pressure and temperature switches into one complete unit

609-000: GM Vehicles Acadia, Aura, Enclave, Equinox, G6, Malibu, Outlook, Torrent, Traverse, Vue 2009-07

- Completely remanufactured and vehicle simulator tested for durability assurance
 - 100% replacement of gaskets, grommets and seals
 - Free priority shipping included with each order received before 5:00PM EST
- Failure Mode:**
- Debris contaminates unit, deteriorating switches and solenoids
 - Failure results in delayed shifting and/or the inability to shift gears

ALSO AVAILABLE TRANSMISSION CONTROL MODULE

609-030: Ford Fiesta 2014-11, Focus 2014-12



TEHCM TRAINING MODULE AVAILABLE AT:
WWW.DORMANUNIVERSITY.COM

Over 50 SKUs Available



Engine Intake Manifolds

Directs airflow into the cylinder head and intake passages

615-376: Ford E-150 2013-10, E-250 2013-10, F-150 2010-09

- Re-engineered with heat-resistant molding to reduce the warping and coolant leaks associated with original design
- Consolidated design combines multiple OE manifolds into just one Dorman SKU to save inventory space

Over 25 SKUs Available



Engine Oil Filter Covers

Retains Oil Filter

917-069: Volkswagen Corrado 1994-92, Passat 1996-93, Jetta 1996-94, Golf 1996-95

- Constructed of quality material for a longer service life
- Torque values listed on parts (where applicable)

5 SKUs Available



Engine Oil Filler Tubes

Provides pathway for oil to flow into the engine block

917-414: GM Various FWD Cars 2009-95

- Prevents oil leaks and debris from entering engine

Over 95 SKUs Available



Engine Oil Dipsticks

Measures vehicle oil level

917-442: Mercedes-Benz E430, CLK320, SL500, CLK430, E320, ML320, CL500, S500, S430 2005-98

- Application specific direct replacement for a proper fit every time

Over 40 SKUs Available



Engine Valve Covers

Protects cylinder head components and seals oil flow

264-988: Ford Explorer, Ranger, Explorer Sport Trac, Mountaineer 2008-04

- Direct replacement
- Provides a tight, lasting seal against oil leaks
- High quality plastic, steel and aluminum construction resists warping and cracking (where applicable)

Over 20 SKUs Available



Exhaust Manifold Hardware Kits

Direct replacement hardware vital in servicing Exhaust Manifolds

03218: Dakota, Durango, Ram 1500, Grand Cherokee, Commander, Aspen 2007-05

- Save time by having the right hardware on hand when you need it



VVT SOLUTIONS PROGRAM

HIGH GROWTH POTENTIAL

A majority of today's vehicles use VVT systems, and high failure rates among original VVT components results in growing aftermarket demand for direct replacements.



Over 75 SKUs Available



Engine Variable Timing Solenoids

Actuates variable valve timing by controlling oil flow and pressure

917-291: Chrysler, Dodge, Jeep Cirrus, Sebring, Compass, Patriot, Avenger, Journey, 200 2014-07

- 100% Tested - All Engine Variable Timing Solenoids have undergone vehicle simulator testing and laboratory testing for quality assurance
- Complete Kit - Includes all gaskets needed for a complete repair (where applicable)
- Plug and Play - Easily plugs into the electrical harness
- Extensive coverage for both domestic and import applications

Failure Mode:

- Oil sludge builds up on screens and electrical failure
- Failure results in rough idle, loss of power or illumination of the check engine light

ALSO AVAILABLE



917-281:

Acura CL 1999-98;
Honda Accord 2002-98, Odyssey 1998



917-290:

Chrysler, Dodge, Jeep Cirrus, Sebring,
Compass, Patriot, Avenger, Journey,
200 2014-07



917-293:

Toyota 4Runner, Land Cruiser,
Sequoia, Tundra 2009-98; Lexus
GS430, GX470, LX470, SC430 2009-98



917-298:

GM Terraza, Monte Carlo, Relay, Uplander, Malibu, G6,
Impala, Montana, Aura, Vue, Lucerne 2011-06



918-005:

Buick Encore 2013, Chevrolet Cruze 2013-11,
Sonic 2013-12, Volt 2013-11

FOR ADDITIONAL INFORMATION PLEASE VISIT US AT:

WWW.DORMANPRODUCTS.COM/VVTSOLUTIONS

7 SKUs Available



Fuel Filter Caps

Covers the secondary fuel filter

904-244: Ford F-250/350/450/550 Super Duty 2012-11

- Redesigned with a hex for easier removal and installation

3 SKUs Available



Fuel Injection Harnesses

Provides power to vehicle injector

904-138: GM Silverado, Sierra 2500 HD, 3500 2005-04; Workhorse LF72 2005

- Repairs worn harness

9 SKUs Available



Fuel Management Wiring Harness

(ALSO KNOWN AS: Fuel Injector Harness)

Sends power to the fuel injectors

911-089: Chrysler & Dodge Minivans 2003-01

- Design includes a wire loom and heat wrap to protect harness wires



Secondary Air Injection Check Valves

Emissions control device that directs air into the exhaust manifold to burn off exhaust gases

911-643: Toyota Tundra 2015-07, Land Cruiser 2015-08, Sequoia 2015-08; Lexus LX570 2015-08

- Re-engineered with stainless steel internal plunger to help reduce corrosion (where applicable)



Vapor Canisters

Stores excess fuel vapor from the gas tank until ready to be released into the combustion chamber

911-641: Toyota RAV4 2000-96

- Redesigned with an extra hose to consolidate two OE numbers into just one Dorman part (where applicable)
- Extensive durability, functionality and emissions tested

40 SKUs Available



Failure Mode:

- Physical damage, valve failure and over filling of fuel tank
- Failure results in illumination of the check engine light



A/C Service Valve Cap

Seals service port in A/C system, preventing leaks

902-025: GM Cars & Trucks 2015-93

- New repair solution for a leaking A/C port, now available in the Aftermarket for a wide range of GM and Saab applications
- Reduce repair costs by sealing the leaking A/C port, instead of evacuating A/C system, saving time, money and labor



MARKET LEADING COVERAGE FOR OVER 180 MILLION VEHICLES

Coolant Water Outlet

Transfers coolant

902-964: Volkswagen Beetle 2010-98, Beetle Cabrio 2010

- Redesigned to withstand extreme changes in temperature that frequently cause original housing to become brittle, crack and leak



Engine Coolant Recovery Tanks

Provides coolant to the engine

603-033: Buick Century 2005-01, Regal 2004-01, Chevrolet Impala 2003-00, Monte Carlo 2003-00


- Redesigned with a more durable plastic construction for a longer service life (where applicable)
- Includes caps, drain tube and sensor (where applicable)

Over 60 SKUs Available



SAVE INVENTORY SPACE!

Exclusive design consolidates 6 OE SKUs into **ONE** Dorman module!



HVAC Control Modules

Controls a variety of cabin temperature options

599-210: GM Silverado, Sierra, Tahoe, Yukon, Trailblazer and Envoy 2009-02

- 100% new, not remanufactured
- Ready to install - Plug and play design requires no programming
- Includes backlight replacement LED bulbs and O-rings, (where applicable)

Failure Mode:

- Bulbs burn out or fan and temperature control failure
- Failure results in dark display and inability to change modes, temperature and fan speeds

ALSO AVAILABLE



599-193:

Chevrolet 2002-99, GMC 2002-99



599-260:

Chevrolet Tahoe 2002-00, GMC Yukon 2002-00

Over 200 SKUs Available



HVAC Heater Blend Door Actuators

Electronic motor controlling the blend door used in interior temperature modes

604-917: Lexus GS300, RX300, GS430, IS300, SC430 2010-98

- Re-engineered with upgraded motor and internal materials for improved durability and performance (where applicable)

Over 15 SKUs Available



HVAC Heater Control Knobs

Adjusts heating temperature options inside the vehicle

76835: Jeep Grand Cherokee 1995-93

- Direct replacement for commonly broken, lost, or worn control knob
- Available in a variety of assortments that contain a range of styles and sizes
- Easy to install

Over 60 SKUs Available

**OE PROBLEM:**

Original connectors are constructed of plastic, and frequently leak due to cracking.



Dorman units are upgraded to aluminum construction for added strength and durability.

HVAC Heater Hose Assemblies

Preserves proper coolant circulation

626-314HP: Chrysler Town & Country 2010, Dodge Grand Caravan 2010

- Include clamps and/or fittings for a complete installation (where applicable)
- Replace just the failed hoses, not the entire heater hose assembly, saving time and money
- Durable construction resists corrosion and coolant leaks
- Direct replacements available for both import and domestic applications

Failure Mode:

- Original metal tube corrodes and plastic Y-connector cracks and leaks
- Failure results in coolant leaks

ALSO AVAILABLE

626-307HP: Chrysler Town & Country 2009-08, Dodge Grand Caravan 2009-08, Volkswagen Routan 2010-09

LIVE CUSTOMER SERVICE & TECH SUPPORT AVAILABLE!

Online
www.DormanProducts.com



Email
techlinemarketing@dormanproducts.com



Phone
1-866-933-2911

HOURS: MON-THU 8AM-7PM EST; FRI 8AM-5PM EST

14 SKUs Available



OE PROBLEM:
The original bus bars quickly corrode, leading to electrical failure.



Dorman's design uses nickel plated bus bars to reduce corrosion.



Hybrid Drive Batteries

587-007: Toyota Prius 2013-09, Prius V 2013-12; Lexus CT200H 2013-11

- Ready-to-install direct replacements
- Includes modules (such as ECU) – no need to reuse from the old battery
- No programming required
- Completely remanufactured and tested
- Each unit and individual cell is tested to confirm optimal battery pack performance

ALSO AVAILABLE



587-015:
Toyota Prius C Hatchback 2013-12



587-004:
Honda Civic 2011-06

SUSPENSION ASSORTMENTS



Wheel Hub Bolt

Direct replacement tech tray containing wheel hub bolts of various styles and sizes

030-008: Universal

- Save time by having the right hardware on hand when needed



Wheel Hub Seal Kit

Seals 4WD hub components

600-207: Ford F-250/350/450/550 Super Duty 2004-99, Excursion 2005-00

- New 4WD front hub seal kit, now available in the Aftermarket for a variety of Ford applications
- This kit includes all wheel hub seals, O-rings and wheel hub retainers needed for a complete front hub repair

ELECTRONIC THROTTLE BODY



OE PROBLEM:

Original unit often requires replacement due to sensor failure and excessive wear and tear.



Completely redesigned circuit board eliminates carbon track wear associated with original unit.

Electronic Throttle Body

Maintains the correct volume of air flow into the vehicle engine

977-025: Chrysler 2013-11, Dodge 2013-07, Jeep 2013-07

- Aluminum casting construction for an exact fit, performance match and corrosion-resistance
- Direct replacement for bolt-on and plug-in installation

Failure Mode:

- Internal electrical failure, motor burnout and wear

SUSPENSION COMPRESSORS



Over 25 SKUs Available



Suspension Air Compressors

Inflates and regulates active air suspension shock absorbers


949-002: GM Bravada, Trailblazer, Envoy, Rainier, 9-7X 2009-02

- 100% new, not remanufactured
- Includes additional components that are often not available separately, such as mounting bracket, motor, dryer, heat shield and air tubing (where applicable)
- Direct-fit plug for an easier and more secure connection

Failure Mode:

- Environmental contamination, water intrusion and motor burnout
- Failure results in sagging suspension and dash trouble codes displayed

ADDITIONAL COMPRESSORS AVAILABLE – EACH INCLUDING VALUE-ADDED COMPONENTS



Vent Tube

Direct-Fit Connector

949-200:

Crown Victoria, Town Car, Grand Marquis 2011-03



Direct-Fit Connector

949-202:

Ford Expedition 2013-07, Lincoln Navigator 2013-07




Direct-Fit Connector

New Bracket

949-902:

Volkswagen Touareg 2010-04



Direct-Fit Connector

949-911:

Mercedes-Benz ML500, ML350, GL320, ML320, ML63 AMG, GL450, ML550, GL550, ML450, GL350 2012-06

MARKET LEADING COVERAGE FOR OVER 35 MILLION VEHICLES

Over 175 SKUs Available



AVAILABLE FOR STOCKING OR NEXT DAY DELIVERY

Drive Shafts

Couples the transmission to the differential

936-803: Ford F-150 2008-04

- Dorman Drive Shafts are 100% new, not remanufactured
- Dorman Engineered with serviceable U-joints (where applicable)
- Direct Fit Replacement - No special tools or welding required

Failure Mode:

- U-joint failure or center support degrades
- Failure results in clunking or vibration

**NEXT DAY
DROP
SHIPMENT**



ALSO AVAILABLE



936-200:
Kia Sorento 2006-03



936-875:
Volvo XC90 2005-03



938-320:
Infiniti 2012-03



Over 25 SKUs Available



Drive Shaft Center Support Bearings

Supports mounting point for drive shaft

934-610: Cadillac CTS 2007-03, Cadillac STS 2011-05

- Complete Kit - Includes mounting bracket for a complete repair

DORMAN
NEW SINCE 1918

2016000

Dorman Products, Inc. | 3400 East Walnut Street | Colmar, PA 18915
Corporate Office and Customer Service: 1-800-523-2492
New Product Idea Hotline: 1-800-336-3575

©2016 No reproduction in whole or in part without prior written approval.



www.DormanProducts.com