

 BALDWIN
 FUEL/WATER SEPARATOR

 FILTERS
 FUEL/WATER SEPARATOR

with Open Port for Bowl

BF791-C	
Contains: Fits: Replaces: Thread: O.D.: Length: O-Ring:	Port Thread: 3 1/4-10 Quicksilver Outboard Applications Racor S3213 11/16-16 3 25/32 (96.0) 4 1/32 (102.4) [3] Included

BF1223-O	
	BF1223-0
Contains: Fits: Replaces: Thread: O.D.: Length: F. Gskt.: I. Gskt.: Related To:	Ford Trucks Ford F1HZ-9365-A; Motorcraft FD3368 1-14 4 1/4 (108.0) 5 7/32 (132.6) [1] Included



Contains: Port Thread: 1 1/4-10 Fits: Racor 225R Assembly Replaces: Racor R26S Thread: 1-14 O.D.: 3 3/4 (95.3) Length: 4 11/16 (119.1) F. Gskt.: [1] Included I. Gskt.: [1] Included	Contains Fits: Replaces O.D.: Length: F. Gskt.: Related

BF1249-0	0
	BF1249-0
Contains: Fits:	Port Thread: 1 1/4-10, Integral Post Seal Blue Bird, Ford, Freightliner, International Buses, Trucks; Hamm Rollers; Hyundai, Liebherr Equipment; Optional on Cummins Engines
Replaces:	Nissan FL6442N
	1-14
O.D.:	3 21/32 (92.9)
Length: F. Gskt.:	6 5/8 (168.3) [1] Included
I. Gskt.:	[1] Included
O-Ring:	[1] Included
Related To:	BF1249 (Standard Version) BF1249-SP (Sensor Port Version)

BF1282-O	
	0 100000 BF-1282-0
Contains: Fits:	Port Thread: 1 1/4-2B Agco, Komatsu Equipment; Case Dump
	Trucks; Cummins Engines
Replaces:	Fleetguard FS1241
Thread: O.D.:	1-14
Length:	3 21/32 (92.9) 4 19/32 (116.7)
I. Gskt.:	[1] Included
O. Ring:	
	BF1282 (Standard Version)




BF1222-SP (Sensor Port Version)

BF1278-O



BF1283-O	
	BF1283-0
Contains: Fits:	Port Thread: M95 x 2.5, Integral Post Seal Caterpillar Equipment, Industrial, Marine, Truck Engines; Racor 4120 Series
Replaces:	Racor R120S; Donaldson P550175; Fleetguard FS1071
Thread:	1-14
O.D.:	4 13/32 (111.9)
Length:	8 19/32 (218.3)
F. Gskt.:	[1] Included
I. Gskt.: Belated Tex	[2] Included
Related 10:	BF1283 (Standard Version) BF1283-SP (Sensor Port Version)

BF1287-0



BF1292-O Figure 2015 Contains: Port Thread: M95 x 2.5, Integral Post Seal Fits: Deutz Engines; Deutz-Fahr, Fendt Tractors Iveco Trucks Replaces: Deutz 4291642; Fendt F339202060120; Iveco 42549295, Mercedes-Benz 4771602, A0004771602; Racor R90T-DMAX Thread: 1-14 O.D.: 4 5/32 (105.6)

6 5/16 (160.3)

[1] Included

[1] Included

BF1296-O

Length:

I. Gskt.: O-Ring:



BF1299-0



BF1288-0

DF 1200-	0
	Рания В-1288-0
Contains:	Port Thread: M95 x 2.5 Integral Post Seal
Fits:	Komatsu Dump Trucks, Equipment
Replaces:	Komatsu 600-311-4510, 600-319-4500
Thread:	1 1/4-12
O.D.:	4 7/8 (123.8)
Length:	9 29/32 (251.6)
F. Gskt.:	[1] Included
I. Gskt.:	[1] Included

BF1294-O

 Interact:
 1-14

 O.D.:
 4 1/4 (108.0)

 Length:
 7 5/32 (181.8)

 I. Gskt.:
 [1] Included

 O-Ring:
 [1] Included





BF1290-O



Contains: Replaces:	Port Thread: B80 x 3.0 8A Metric Buttress CLARCOR Filtration (China) WBF219B; Foton Lovol 1307211500005
Thread:	1-14
O.D.:	4 11/32 (110.3)
Length:	6 13/32 (162.7)
I. Gskt.:	[1] Included
O-Ring:	[1] Included

BF1295-O





BF1345-0



BF1346-0

	BF1346-0
Contains:	Port Thread: M95 x 2.5
Fits:	Ford, Freightliner, International, Sterling, Western Star Trucks; Racor Housings; Mercedes-Benz Engines
Replaces:	Racor S3226P; Donaldson P550554; Fleetguard FS19593
Thread:	1-14
O.D.:	4 1/4 (108.0)
Length:	6 5/16 (160.3)
I. Gskt.:	[1] Included
O-Ring:	[1] Included
Related To:	BF1346 (Fuel/Water Separator Version)
	BF1346-SP (Sensor Port Version)

BF1358-0

	BF135E-0
Contains:	Port Thread: 3 3/4-10 Integral Post Seal
Fits:	Volvo Dump Trucks, Equipment
Replaces:	Volvo 11110474, 11110668
Thread:	1-14
O.D.:	4 13/32 (111.9)
Length:	8 19/32 (218.3)
F. Gskt.:	[1] Included
I. Gskt.:	[1] Included
Related To:	BF1358-SP (Sensor Port Version)


BF1386-O	
	BF13B6-0
Contains:	Port Thread: M80 x 2.5 Integral Post Seal
Fits:	Mack, Volvo Engines, Trucks
Replaces:	Mack 21017305; Volvo 20879806
Thread:	1-14
0.D.:	4 1/4 (108.0)
Length:	5 3/16 (131.8)
I. Gskt.: O-Ring:	[1] Included [1] Included
U-King:	



BF1348-O	
	Patries BF1348-2
Contains: Fits: Replaces: Thread: O.D.: Length: A. Gskt.: I. Gskt.: O-Ring:	Port Thread: M95 x 2.5 Blue Bird Buses; Freightliner, Hino, Peterbilt Trucks; Racor 325 Series Racor S3225P 1-14 4 1/4 (108.0) 5 3/16 (131.8) [1] Attached [1] Included [1] Included

BF1366-	0
	Instant BF1366-0
Contains:	Port Thread: M80 x 2.5 Integral Post Seal
Fits:	R.V.I., Volvo Trucks
Replaces:	Volvo 20998367; Donaldson P559628; Fleetguard FS19735
Thread:	1-14
0.D.:	3 21/32 (92.9)
Length:	5 5/8 (142.9)
I. Gskt.:	[1] Included
O-Ring:	[1] Included





BF1355-O



BF1383-0

BF1383-0	0
	ИСТОТИТИТИ И ЛИТИТИТИТИТИТИТИТИТИТИТИТИТИТИТИТИТИТИ
Contains: Fits:	Port Thread: B80 x 3.0 8A Metric Buttress DAF Engines, Trucks; Doosan, Terex Equipment
Replaces:	M.A.N. 51.12501.7288, 51.12503.0052; Daewoo K1006529; CLARCOR Filtration (China) WBF219
Thread:	1-14
0.D.:	4 9/32 (108.7)
Length:	9 3/32 (231.0)
I. Gskt.:	[1] Included
O-Ring:	[1] Included

BF1388-0
Contains: Port Thread: M95 x 2.5
Integral Post Seal
Fits: R.V.I., Volvo Trucks
Replaces: R.V.I. 7420851191; Volvo 20853583;
Racor R60T-D-MAX; Fleetguard FS19895 Thread: 1-14
Thread: 1-14 O.D.: 4 1/4 (108.0)
Length: 5 1/8 (130.2)
I. Gskt.: [1] Included
O-Ring: [2] Included

BF1391-(D Manual Br1391-0 COMMANNA Manual Common Manual Common Manual Common Manual Common Manual Common Manual Common Manual Common Manual Common Manual Common
Contains: Fits: Replaces: Thread: O.D.: Length: I. Gskt.: O-Ring: Related To:	

BF1395-O




BF9866-O ALOWI Contains: Port Thread: M95 x 2.5 Fits: John Deere Equipment Replaces: John Deere RE532952, RE539465 Thread: 7/8-14 4 3/8 (111.1) 0.D.: Length: 8 11/16 (220.7) F. Gskt.: [1] Included I. Gskt.: [1] Included



BF9912-0

	BF9812-0
Contains:	Port Thread: 3 3/4-10 Buttress
Replaces:	Atlas Copco 2914809200; Fleetguard FS19775
Thread:	1-14
O.D.:	4 1/4 (108.0)
Length:	3 15/32 (88.1)
F. Gskt.:	[1] Included
I. Gskt.:	[1] Included

BF1398-0 Inside-Out Flow Direction Notes: Port Thread: M80 x 2.5 Contains: Integral Post Seal Fits: Volvo Trucks with D6B Engine Volvo 20386080; Racor R25P; Fleetguard FS19704 Replaces: Thread: 1-14 3 21/32 (92.9) O.D.: Length: 5 5/8 (142.9) [1] Included O-Ring:







BF7968-O




BF9871-0



BF9898-O

I. Gskt.:

O. Ring:



BF9922-O Notes: Inside-Out Flow Direction Contains: Port Thread: M80 x 2.5 Fits: Mercedes-Benz Latin America Buses, Trucks Replaces: Mercedes-Benz A3820927005; Racor R20P Thread: 1-14 0.D.: 3 21/32 (92.9) Length: 4 1/8 (104.8)

Related To: BF46021-O, BF46022-O (Micron Difference)

[1] Included

[1] Included

BF9923-O









BF9925-	
Contains: Replaces: Thread: O.D.: Length: F. Gskt.:	Port Thread: M95 x 2.5 Racor S6464, Donaldson P551034; Fleetguard FS19538 1-14 4 1/4 (108.0) 6 5/16 (160.3) [2] Included







BF9926-O



Contains:	Port Thread: M80 x 2.5
Fits:	Yanmar Engines
Replaces:	Yanmar 12065066020
Thread:	1-14
O.D.:	3 11/16 (93.7)
Length:	4 1/8 (104.8)
I. Gskt.:	 Included
O. Ring:	[1] Included
-	

BF46018-O









BF46026-O

BF46029-O



BF46027-O





 Contains:
 Port Thread: 3 1/4-10

 Fits:
 Racor Marine Applications

 Replaces:
 Racor S3228UL

 Thread:
 1-14

 O.D.:
 3 25/32 (96.0)


 Length:
 4 1/32 (102.4)

 F. Gskt.:
 [1] Included

 O-Ring:
 [1] Included

BF46030	9-0
	0
Contains: Fits:	Port Thread: 3 3/4-10 UN-1B Racor 660R-RAC, 3120R-RAC Series Assemblies
Replaces: Thread: O.D.: Length: F. Gskt.: O-Ring:	Racor \$3232 1-14 3 25/32 (96.0) 5 1/2 (139.7) [2] Included [1] Included

BF46028-O



QUICK CROSS-REFERENCE

BALDWIN	DONALDSON	FLEETGUARD	HENGST	LUBER-FINER	MANN & Hummel	RACOR
BF791-0	-	-	-	-	-	\$3213
BF1204-0	-	FS1234	-	LFF8061	-	R26S
BF1222-0	P550829	FS1278	-	LFF5824	-	-
BF1223-0	P550730	-	_	LFF8063	-	R60T
BF1249-0	-	FS1242	-		-	-
BF1249-0 BF1278-0	-	-	-	- LFF9012	-	-
		– FS19754	– H7120WK30	LFF9012 -	– PFF5605-MH	
BF1281-0	P551077					R120P
BF1282-0	-	FS1241	-	LFF8065	-	-
BF1283-0	P550175	FS1071	-	LFF8707	-	-
BF1287-0	-	FS20036	-	-	-	-
BF1288-0	P550937	-	-	LFF5357	-	-
BF1290-0	-	-	-	-	-	-
BF1292-0	-	FS19950	H7091WK10	-	WK1070X	R120T-MH
BF1294-0	-	-	-	-	-	-
BF1295-0	-	-	-	-	-	-
BF1296-O	-	FS19907	H304WK	-	PL270X	-
BF1297-0	-	-	-	-	PL4202X	-
BF1298-0	-	-	-	-	-	-
BF1299-0	-	-	-	-	-	-
BF1329-0	P550747	FS19532	H7090WK30	LFF5766	R160T-MH	R90P
BF1345-0	P550729	FS19547	-	LFF3579	-	R43
BF1346-0	P550554	FS19593	_	LFF5850U	_	S3226P
BF1348-0	P550436	FS19521	-	LFF5849	-	S3220P
BF1355-0	F 550450	FS19799	-	LFF9982		S3238P
						33230F
BF1358-0	P505957	FS19753	H7121WK10	LFF9753	WK1176X	-
BF1366-O	P559628	FS19735	H700WK	LFF3293	R90T-MH	R260P
BF1383-0	P550778	FS19769	H710WK	LFF9769	PL420	-
BF1386-0	P550913	FS19918	-	LFF3358	WK10006Z	-
BF1387-0	-	FS19920	H7091WK30D199	-	-	R90HDP
BF1388-0	-	FS19895	H7063WK30	-	WK1040/1X	R60T-D-MAX
BF1389-0	P550746	FS19734	-	-	WK1020	R45T
BF1390-O	-	FS19551	H7090WK10	-	WK1060/5X	R90T
BF1391-0	-	FS19914	H701WK	LFF9737	WK10807	R160T
BF1395-0	P551075	2040TM-FLTG	H7120WK10	-	PFF5603-MH	R120T
BF1398-0	-	FS19704	H7025WK30	-	WK94032	R25P
BF7968-0	-	-	-	-	-	S3214
BF9866-O	-	FS1096	-	LFF6964	-	PFF56203
BF9867-0	P551033	FS19949	-	-	-	R160T-D-MAX
BF9871-O	P551066	_	-	LFF8957	-	_
BF9880	_	-	_	_	-	_
BF9882	-	FS20002	-	LFF6012	-	MF1102
BF9898-0	-	FS19593	_	LFF5849	-	-
BF9990-0 BF9912-0	-	FS19595	– H7045WK30	LFF3049 -	-	– R45P
						K40P
BF9921-0	-	-	-	-	-	
BF9922-0	- DE00500	FS19996	-	-	WK923/2X	R20P
BF9923-0	P502566	FS19805	-	-	-	-
BF9925-0	P551034	FS19538	-	-	-	S6464
BF9926-O	-	-	-	-	-	-
BF46016-O	-	-	-	-	-	-
BF46017-O	-	-	-	-		-
BF46018-O	-	FS20040	-	LFF7660	-	-
BF46019-O	-	-	-	-	-	R15S
BF46020-O	-	-	-	-	-	R15T
BF46021-0	-	-	-	-	-	R20S
BF46022-0	-	-	-	-	-	R20T
BF46023-O	_	-	-	-	-	R24P
BF46024-0	P551744	-	-	-	-	R24T
TVVET V						11471

QUICK CROSS-REFERENCE

					MANN &	
BALDWIN	DONALDSON	FLEETGUARD	HENGST	LUBER-FINER	HUMMEL	RACOR
BF46026-O	P550088	FS1234	-	-	-	R26T
BF46027-O	P551055	FS1084	-	-	-	R45S
BF46028-O	-	-	-	-	-	S3227
BF46029-O	-	-	-	-	-	S3228UL
BF46030-O	-	-	-	-	-	S3232