
VW PROFI Program

Product Support - VWoA

ProFI Program Updates				
	Contents			
1.	Inbound Requests - Overview	Pg. 2		
2.	Outbound Requests – New/Open	Pg. 3		
3.	Outbound Requests - Closed	Pg. 4		



	2. Outbound Requests – New/Open				
Topic ID	New/Open outbound requests	Opened	Weeks Open		
	There are no outbound requests currently open.				

	3. Outbound Requests – Closed				
Topic ID	Outbound requests closed within the last month	Closed	Weeks Open		
2015-047	Golf SportWagen Sunroof Drain Tube (VIN-4-A-PIN)	4/12/2016	22		
	Model Year: 2015-2016 Carline(s): Golf SportWagen See outbound request form attached for details.				
	This topic is now closed as an outbound request and we are no longer requesting any further actions.				
	We have collected all of the information we need for this concern.				
	We greatly appreciate your support with this topic.				

3. Outbound Requests – Closed				
Topic ID	Outbound requests closed within the last month	Closed	Weeks Open	
2015-049	Golf Front Window Regulator (VIN-4-A-PIN)	4/12/2016	20	
	Model Year: 2015-2016 Carline(s): Golf, Golf GTI, Golf SportWagen See outbound request form attached for details.			
	This topic is now closed as an outbound request and we are no longer requesting any further actions.			
	We have collected all of the information we need for this concern.			
	We greatly appreciate your support with this topic.			

	PROFI Dealer Outbound	Information Requ	est Form	
MY(s) Affected:	2015-2016	Issue ID #		2015-047
Vehicle Model(s):	Golf SportWagen	Photos (if applicable):		
VIN Range (if applicable):	All			
Engine Code(s):	All			
Gearbox (Manual / Automatic):	All			
Issue Description / Symptom: Water leak from sunroof / water stains on	headliner	_		
Workshop Problem Validation Procedure:				
Required Actions:	found to be the cause of the complaint			
If a loose or pinched sunroof drain tube is found to be the cause of the complaint, please obtain pictures showing the condition of the sunroof drain tube and the location of the pinched/disconnected drain on the vehicle. Please send pictures and vehicle		VWoA Contact Informati	on:	
information in to the Profi inbox with the tit Drain Tube."	le "2015-047 Golf SportWagen Sunroof	Requestor:	The second secon	nmerman
		E-mail:		erman@vw.com
Please repair the vehicle as needed.		Phone Number:		54-4340
		Alternative Contact:		Lentzer
		E-mail:	kevin.lentz	
			Novint. Joint	

	PROFI Dealer Outbound	Information Reque	est Form	
MY(s) Affected:	2015-2016	Issue ID #		2015-049
Vehicle Model(s):	Golf, GTI, Golf SportWagen	Photos (if applicable):		
VIN Range (if applicable):	All			
Engine Code(s):	All			
Gearbox (Manual / Automatic):	All			
Issue Description / Symptom: Rattle noise when closing front door.				
Workshop Problem Validation Procedu Inspect front window regulator assembly for cables are properly secured and window re			N/A	
Required Actions: Please obtain pictures showing the locatio and vehicle information into the Profi Mailk Window Regulator."	n of any loose components. Send pictures box with the title "2015-049 Golf Front	VWoA Contact Information	on:	
		Requestor:	Jeff Zir	nmerman
		E-mail:	jeffrey.zimme	rman@vw.com
		Phone Number:	248-7	54-4340
		Alternative Contact:	Kevin	Lentzer
		E-mail:	kevin.lentz	er@vw.com
		Phone Number:	248-7	54-5901