


# Navigation Update User Guide

HYUNDAI **MnSOFT**

for a better driving experience...  
every **move**, every **mo'ment**

| Business 1 Team  
| Hyundai Mnsoft  
| Dec, 2016



- ① Dealership must have the pc tool and USB.
- ② MMI will verify the input information and pass it to HMNS server in order to obtain the activation code.
- ③ Dealers can get the activation code through [india.map-care.com](http://india.map-care.com).
- ④ Dealership MUST **back-up the POI(point of interest) from the SD card for i20 only.**
- ⑤ Once you receive the map update USB, please back-up the data into your personal computer.

# Memory type by vehicles

for a better driving experience...  
every move, every moment



Santa Fe(DM)



Creta(GS)



Verna(RB)



i20(IB)

SD Card/Nand Flash

Motrex

Nand Flash



Tucson(TL)



Elantra(AD)

Mobis

SD Card

※ In case of SD card(i20), Dealer must **back-up the customer's POI(point of interest)** in your computer before formatting the SD card.

## Map Update Service Tool Kit (STK)



### Includes:

- Map update
- PC Tool
- Install Manual

PC Tool



+ Map

Copy to PC



※ In case of malfunctioning of the USB, please copy all files from USB to your computer(once)

This Software requires the following technical requirements:

- ✓ Guarantee for **Windows XP 32Bit, Windows 7 32Bit only**
- ✓ Free Hard Disk space of **12GB**
- ✓ HMNS Service Tool Kit (**STK**)
- ✓ **SD-Card reader** (either already installed at computer or a separate device)
- ✓ **Internet** Connection

# Getting an activation code

HYUNDAI **MnSOFT**


for a better driving experience...  
every **move**, every **moment**

## ① When consumer visits dealer



② Dealer turns on the customer's AVN

## ② Find the Device ID from AVN




1) Dealer turns on the customer's AVN

2) For example DMi navigation unit


Push Navi Button → Select Settings Icon → Select  
Reset/Info Icon → Select Version Information Icon  
\* Find Device ID

# How to find the DeviceID from AVN


for a better driving experience...  
every move, every moment




① Go to “Menu”



③ Go to “Reset/info” and Version Information



② Go to “Settings”



④ Find the “DeviceID”



## Santa Fe | Creta | i20 | Verna

Hyundai Motor India Limited (HMIL) being the second largest car manufacturer of India, introduced Navigation arrangements in it's multiple product offering: - Santa Fe, CRETA, i20 etc. Purpose of this web page information is to offer better navigation experiences to all Hyundai End user as per mutually agreed terms & condition

### Get the Authentication Key

Name:

Mobile:

E-mail:

Model:


Car Plate No:

\*Purchase Y/M:

\*VIN:   
(Vehicle Identification Number)

\*Device ID:  ?


\*Mandatory Fields



Helpline



Map Coverage



Map Feedback



Download the latest Map

- ① Access the Website([india.map-care.com](http://india.map-care.com))
- ② Input customer's information, VIN, Purchasing Date and DeviceID

※ Hyundai Provides one free yearly update within three years of vehicle purchase date.



HYUNDAI  
MnSOFT



Santa Fe | Creta | i20 | Verna

Hyundai Motor India Limited (HMIL) being the second largest car manufacturer of India, introduced Navigation arrangements in it's multiple product offering: - Santa Fe, CRETA, i20 etc. Purpose of this web page information is to offer better navigation experiences to all Hyundai End user as per mutually agreed terms & condition



Helpline



Map Coverage



Map Feedback



Download the latest Map

## Get the Authentication Key

Device Id: 2883560001

Activation Code: 2246-6NJR-ZL6Y-XLQV

**Free Map Updates: Remaining 1 times**

Please input the deviceID, UUID and Activation code to Authentication program.

If you don't have the authentication program, please download it.

You can also update the map in Hyundai 3S dealership.

For more information, please call helpline No. 011-43953000

Download

③ Once you input all information and click the submit button, you will see the DeviceID and Activation code.

# Update GS/GS+/RB/RB+/IB+ GS(Creta), RB(Verna), IB(i20)

HYUNDAI **MnSOFT**

for a better driving experience...  
every **move**, every **mo'ment**

## ● Compatibility table GS/GS+/RB/RB+/IB+

Company	Vehicle	Year	Map version		Software version	
			Old	New	Old	New
Motrex	GS	2016	IN.08.47.52.550	IN.09.47.51.510	PIO.IND.HMC.151208.83591	MOT.IND.HMC.161215.100905
Motrex	GS+	2016	-	IN.09.47.51.510	-	MOT.IND.HMC.161215.100905
Motrex	RB	2016	IN.08.47.52.550	IN.09.47.51.510	PIO.IND.HMC.151208.83591	MOT.IND.HMC.161215.100905
Motrex	RB+	2016	-	IN.09.47.51.510	-	MOT.IND.HMC.161215.100905
Motrex	IB+	2016	-	IN.09.47.51.510	-	MOT.IND.HMC.161215.100905


- Have your USB Master kit handy that includes new software versions for different vehicle models and a new map update
- Getting ready
  - ① Get the device ID from car navigation system
  - ② Go to website(<http://india.map-care.com>) and get the activation code
  - ③ Prepare “**update USB stick**” (minimum 8GB)

## STEP 1: Check the update file in USB Stick

- Insert “update USB stick” in computer (8GB)
- Make sure that all the files are in the USB as right side




In USB Stick



## STEP 2: Run application software from your PC

- Run “SerialNumber\_ENG.exe” from PC

- (1) Select the USB Drive
- (2) Input Device ID 10 digits (from customer’s vehicle)
- (3) Enter the Activation Code (retrieved from website)
- (4) Click on Activation button



## # Result (Example)

Authentication Program for SerialNu...

(1) Select Drive  
Select the Drive : F: Drive ( 7.5 GBytes)

(2) Device ID  
Input Device ID (10 Digits)  
3726614232

(3) Activation Code  
Input Activation Code  
224C - 5NQ2 - KWHT - H3ZW

HYUNDAI MnSOFT

Activation Cancel

STD.4.X/PRE2.X/EUAVN2.0



Authentication Program for SerialNu...

(1) Select Drive  
Select the Drive : F: Drive ( 7.5 GBytes)

(2) Device ID  
Input Device ID (10 Digits)  
3726614232

(3) Activation Code  
Input Activation Code  
224C - 5NQ2 - KWHT - H3ZW

HYUNDAI MnSOFT

Activation Cancel

STD.4.X/PRE2.X/EUAVN2.0



Information

Make hmnsdat complete.


OK

## # Result 2(Example)

- Check inside Bin folder in USB




Plug the USB memory stick in the USB slot.  
Navigation system and navigation data will be upgraded automatically





Check the MAP version information (Refer to the Slide No.7)



Check the System version information

(Press and hold the set-up button  on the AVN control panel. You can see the Version information)



GS



IB+



RB

# Recovery Mode

for a better driving experience...  
every move. every moment

1. Turn off the AVN, insert USB and power on
2. When you see the booting logo, long press the below button(20 sec)



GS/GS+




RB/RB+




IB+

3. You can enter system recovery mode as below



## 4. Press the Force Update



## 5. Perform the upgrade SW automatically



**Caution : Do not power off(engine off) during S/W update**

# Update IB(i20) (SD Card)

HYUNDAI **MnSOFT**

for a better driving experience...  
every **move**, every **mo'ment**

## ● Compatibility table IB

Company	Vehicle	Year	Map version		Software version	
			Old	New	Old	New
Motrex	IB	2016	IN.08.47.52.550	<b>IN.09.47.51.510</b>	PIO.IND.HMC.151208.83591	<b>MOT.IND.HMC.161215.100905</b>


- Have your USB Master kit handy that includes new software versions for different vehicle models and a new map update
- Getting ready
  - ① Get the device ID from car navigation system
  - ② Go to website(<http://india.map-care.com>) and get the activation code
  - ③ Bring “update USB stick” (minimum 8GB)
- Before Map Update, System Update is required.(Please use SD Card kit)

## ● Applicable Vehicle

Model : Elite i20, i20 Active (IB/IB Cross)

Applicable vehicle production date range : 01 Jun 2015 ~ 31 Jul 2016.

## ● Part Information

PART NAME	FIGURE	REMARK
SD Card		Dispatched from Map My India. If not received the SD Card, Please contact Map My India.

### Caution

- Size of the file will be approximately 2.79 GB.
- Do not modify, delete and write other contents to the SD Card.
- Ensure that during the Update the battery power supply is in a stable operational mode.
- Never switch off the car during the update process. Do not remove the SD Card while upgrade.
- Upgrade Time : 10~15min

# Update IB – System SOFTWARE UPDATE – i20 (SD Car d)







for a better driving experience...  
every move. every moment

## ● Service Procedure

1. Verify that the vehicle is an affected one by check S/W Version.
2. It is recommended to start the engine and turn on AVN system.

### Caution

Make sure the AVN system is not switched off during upgrade procedure.

Procedure	Photo
<p>Press and hold the <b>set-up</b> button "  "  on the AVN control panel. Check the current version information.</p> <p>If the System / Navigation version are lower than new software, Please update according service procedure below.</p> <p><b>New Version information</b> Software Version : <b>610281</b></p>	 <p>Firmware Version : IB.IN.PRO.10.826 Software Version : IB.IN.PRO.10.610281</p>
<p><b>Caution</b> Make sure the AVN system is not switched off during upgrade procedure.</p> <p>Plug the supplied SD Card in the SD slot and Waiting.</p> <p>System will restarting.</p>	  



# Update IB - System SOFTWARE UPDATE – i20 (SD Car d)

for a better driving experience...  
every move. every moment

## Procedure

Hyundai logo and Version Information table will be shown.  
Verify the current version and Press the “Upgrade” Button.




Caution Message will be shown, Press the “Agree” Button.  
Update will start Automatically.

### Caution

Updating process will last approximately 10~15 minutes.

**Do NOT unplug the SD Card in this step.**

Make sure the AVN system is not switched off during upgrade procedure.



After the upgrade is successfully done, system will reboot automatically.

Hyundai logo and Version Information table will be shown.

Verify the current version and Press “Cancel” button.

Unplug SD Card.





# Update IB – System SOFTWARE UPDATE – i20 (SD Car d)

for a better driving experience...  
every move, every moment


## Procedure

Factory settings required after upgrade.

Press the "Set-up" button "   .


Press the "System" button on the screen.


## Photo



In System settings screen

Press "Factory settings" – Select "All" check box.

Press the  button → Pop up → Press "Yes"





Turn off the Engine and reboot the AVN System.  
Check the functions  
Check the upgrade version and make sure once again.

and  
Finish.

Firmware Version : IB.IN.PRO.10.826  
Software Version :  
IB.IN.PRO.10.610281

# Back up Customer's POI(Point of Interest)

for a better driving experience...  
every move, every moment



Dealer **must back up customer's POI(point of interest) to dealer's computer before formatting.**

After map update, dealer must copy the customer's POI to updated SD Card.

Path : **SDMemory/Navi/Data/UserData**


# Erase SD Card Content

for a better driving experience...  
every move, every moment


- Take the memory card out of the navigation device
- Check that the Map SD is unlocked
- **Insert** the card in the SD slot of your computer




- Select SD card drive and click the right mouse button and click **[Format]**



- Use the following settings:  
Files System: FAT32 (Default)  
Allocation unit size: 32KB
- Click **[Start]** button



- Start format by clicking **[OK]**
- When format is done click **[OK]**
- Duration: < 5 sec




SD card reader is needed.  
(computer SD slot or external reader)



# Copy Map Update Data on SD Card

for a better driving experience...  
every move. every moment



- Go to USB




- Select Navi folder only
- Click right mouse button and click [COPY]



- Select SD Card drive
- Click the right mouse button and click [PASTE]
- Duration: < 20 min



- Check copy completion
- Select ALL files
- Click right mouse button and click [PROPERTIES]
- Check number of data/folder and size. (size: 3.73GB, 133 files)



## STEP 1: Check the update file in SD CARD


- Insert “update USB stick” in computer (8GB)
- Make sure that all the files are in the SD CARD as right side



## STEP 2: Run application software from your PC

- Run “SerialNumber\_ENG.exe” from PC

- (1) Select the SD Card drive
- (2) Input Device ID 10 digits
- (3) Enter the Activation Code (retrieved from website)
- (4) Click on Activation button



## # Result (Example)

Authentication Program for SerialNu...

(1) Select Drive  
Select the Drive : F: Drive ( 7.5 GBytes)

(2) Device ID  
Input Device ID (10 Digits)  
3726614232

(3) Activation Code  
Input Activation Code  
224C - 5NQ2 - KWHT - H3ZW

HYUNDAI MnSOFT

Activation Cancel

STD.4.X/PRE2.X/EUAVN2.0



Authentication Program for SerialNu...

(1) Select Drive  
Select the Drive : F: Drive ( 7.5 GBytes)

(2) Device ID  
Input Device ID (10 Digits)  
3726614232

(3) Activation Code  
Input Activation Code  
224C - 5NQ2 - KWHT - H3ZW

HYUNDAI MnSOFT

Activation Cancel

STD.4.X/PRE2.X/EUAVN2.0

Information


Make hmnsdat complete.

OK

## # Result 2(Example)


- Check inside Bin folder in SD CARD

이름	유형	크기
AUTH_TOOL	파일 폴더	
Navi	파일 폴더	



- Previous BIN folder

ATL90.DLL  
HafAuth3.dll  
iEngine2U.dll  
MFC90U.DLL  
MGDIQType.dll  
Motrex\_AVN.exe  
MSVCR90.DLL  
redEngine3U.dll  
redRelay\_2.dll




After, Created **hmnsdat** file in BIN folder

501170BF.hmnsdat  
ATL90.DLL  
HafAuth3.dll  
iEngine2U.dll  
iEngine2U.exp  
iEngine2U.lib  
MFC90U.DLL  
MGDIQType.dll  
Motrex\_AVN  
MSVCR90.DLL  
redEngine3U.dll  
redRelay\_1.dll  
redRelay\_2.dll




## STEP 3: Check the new Navi version

- 1) Insert SD Card into customer 's navigation device and acc on
- 2) Push Navi Button
- 3) Select "Settings"




- 4) Select "Reset/Info"




## STEP 4: Check the new Navi version

### 5) Select “Version Information”



### 6) Check the new version



# Update AD(Elantra)/TL(Tucson) (SD Card)

HYUNDAI **MnSOFT**

for a better driving experience...  
every **move**, every **mo'ment**

## ● Compatibility table AD/TL

Company	Vehicle	Year	Map version		Software version	
			Old	New	Old	New
Mobis	AD	2016	IN.08.47.52.550	<b>IN.09.47.51.510</b>	DAP.IND.ADi.160725.95282	<b>DAP.IND.HMC.161222.101132</b>
Mobis	TL	2016	IN.08.47.52.550	<b>IN.09.47.51.510</b>	DAP.IND.TLi.161103.99132	<b>DAP.IND.HMC.161222.101132</b>

- Have your USB Master kit handy that includes new software versions for different vehicle models and a new map update
  
- Getting ready
  - ① Get the device ID from car navigation system
  - ② Go to website(<http://india.map-care.com>) and get the activation code
  - ③ Bring “**update USB stick**” (minimum 8GB)


# Erase SD Card Content

for a better driving experience...  
every move, every moment


- Take the memory card out of the navigation device
- Check that the Map SD is unlocked
- **Insert** the card in the SD slot of your computer




- Select SD card drive and click the right mouse button and click **[Format]**



- Use the following settings:  
Files System: FAT32 (Default)  
Allocation unit size: 32KB
- Click **[Start]** button



- Start format by clicking **[OK]**
- When format is done click **[OK]**
- Duration: < 5 sec




SD card reader is needed.  
(computer SD slot or external reader)



# Copy Map Update Data on SD Card

for a better driving experience...  
every move. every moment



- Go to USB




- Select all files
- Click right mouse button and click [COPY]



- Select SD Card drive
- Click the right mouse button and click [PASTE]
- Duration: < 20 min



- Check copy completion
- Select ALL files
- Click right mouse button and click [PROPERTIES]
- Check number of data/folder and size. (size: 4.39GB, 112 files)




## STEP 1: Check the update file in SD CARD

- Insert “update USB stick” in computer (8GB)
- Make sure that all the files are in the SD CARD as right side




In SD CARD



## STEP 2: Run application software from your PC

- Run “SerialNumber\_ENG.exe” from PC

- (1) Select the SD Card drive
- (2) Input Device ID 10 digits
- (3) Enter the Activation Code (retrieved from website)
- (4) Click on Activation button





## # Result (Example)

Authentication Program for SerialNu...

(1) Select Drive  
Select the Drive : F: Drive ( 7.5 GBytes)

(2) Device ID  
Input Device ID (10 Digits)  
3726614232

(3) Activation Code  
Input Activation Code  
224C - 5NQ2 - KWHT - H3ZW

HYUNDAI MnSOFT

Activation Cancel

STD.4.X/PRE2.X/EUAVN2.0



Authentication Program for SerialNu...

(1) Select Drive  
Select the Drive : F: Drive ( 7.5 GBytes)

(2) Device ID  
Input Device ID (10 Digits)  
3726614232

(3) Activation Code  
Input Activation Code  
224C - 5NQ2 - KWHT - H3ZW

Information

Make hmnsdat complete.

OK

HYUNDAI MnSOFT

Activation Cancel

STD.4.X/PRE2.X/EUAVN2.0

## # Result 2(Example)

- Check inside of folder in SD CARD as below.  
→ SDHC ▶ Data ▶ Nation ▶ IND ▶ Map

- Previous Map folder

이름	수정한 날짜
MAPMODULE	2016-06-08 오전...
VIT_IND.hafp	2015-10-06 오후...
VIT_IND.hafp01	2015-10-06 오후...
VIT_IND.hafr	2015-11-12 오후...
VIT_IND	2015-10-06 오후...
VIT_IND_3D_LANDMARK.hafmma	2015-08-21 오후...
VIT_IND_3D_MODEL_SYM.hafmma	2013-05-15 오후...
VIT_IND_LandMarkPoi.hafImp	2015-11-26 오전...



After, Created **hmnsdat** file in Map folder

MAPMODULE.bin
VIT_IND.hafp
VIT_IND.hafp01
VIT_IND.hafr
VIT_IND
VIT_IND_3D_LANDMARK.hafmma
VIT_IND_3D_MODEL_SYM.hafmma
VIT_IND_LandMarkPoi.hafImp
3726614232.hmnsdat

# Update DM(Santa Fe)

HYUNDAI **MnSOFT**

for a better driving experience...  
every **move**, every **moment**

## ● Compatibility table DM

Company	Vehicle	Year	Map version		Software version	
			Old	New	Old	New
Motrex	DM	2016	IN.08.47.52.550	<b>IN.09.47.51.510</b>	PIO.IND.HMC.151208.83591	<b>MOT.IND.HMC.161215.100905</b>

- Have your USB Master kit handy that includes new software versions for different vehicle models and a new map update
- Getting ready
  - ① Get the device ID from car navigation system
  - ② Go to website(<http://india.map-care.com>) and get the activation code
  - ③ Bring “update USB stick” (minimum 8GB)
- Before Map Update, System Update is required.(Please use System USB kit)

## Notice

- This Update is System improvement for Santa Fe
  - During Update, please follow the caution as below.
  - If you have any question, please contact MOTREX Service Centre.
- Please Discard Old Pen drive(USB)!! Do not use anymore.**
- MOTREX is not in charge of any problem caused by inappropriate use.**

## Caution


- Do not modify, delete or write any other contents.
- Ensure during the Update, the power of the battery should be supplied consistently.
- Do not switch off the car during the upgrade procedure.
- Do not remove USB & SD Card during upgrade procedure.
- It is recommended to start the engine and turn on AVN system.
- Upgrade Time : 5~30 min
- USB & SD Card will be dispatched from Motrex. If you did not receive, please contact Motrex.
- After the Update, please check completed Software version

## ● Applicable Vehicle

Model : Santa Fe (DM)

Applicable vehicle production date range : 01 Jan 2015 ~ 31 Dec 2016.

## ● Part Information

PART NAME	FIGURE	REMARK
USB MEMORY STICK		Dispatched from Map My India. If not received the USB memory stick, Please contact Map My India.

### Caution




- Size of the file will be approximately 42.4 MB.
- Do not modify, delete and write other contents to the USB.
- Ensure that during the Update the battery power supply is in a stable operational mode.
- Never switch off the car during the update process. Do not remove the USB while upgrade.
- Upgrade Time : 10~15 min

## ● Service Procedure

1. Verify that the vehicle is an affected one by check S/W Version.
2. It is recommended to start the engine and turn on AVN system.

### Caution

Make sure the AVN system is not switched off during upgrade procedure.


Procedure	Photo
<p>Press <b>Setup</b> button on the AVN control panel. Click <b>System</b> → <b>Device Information</b> Check the current version information.</p> <p><b>New Version information</b> Software Version : <b>DM-N3000D-AP-028</b> Micom : <b>DM-N3000D-MC-027</b> OS : <b>DM-N3000D-OS-010</b></p>	 
<p>Plug the supplied USB memory stick in the USB slot.</p> <p><b>Caution</b> Make sure the AVN system is not switched off during upgrade procedure.</p>	




## Procedure

## Photo


Press the **SETUP** Button.  
Click the **System**.




Click the **Device Information** → **Software Update**



Caution Message will be shown, Press the **"YES"** Button.  
Update will start Automatically.




Procedure	Photo
<p>Hyundai logo will be shown and will start upgrade automatically.</p> <p><i>Caution</i> Updating process will last approximately 10~15 minutes. Do NOT unplug the USB stick in this step.</p>	
<p>After the upgrade is successfully done, system will reboot automatically.</p> <p>Unplug the USB stick from the slot.</p> <p>And verify the current S/W version</p>	<p>New Version information</p> <p>Software Version : DM-N3000D-<b>AP-028</b> Micom : DM-N3000D-MC-027 OS : DM-N3000D-OS-010</p>

## Procedure


## Photo

System Default required after upgrade.

Press the **SETUP** Button.  
Click the **System** button on the screen.



Click the **Device Information** → **System Default**



Turn off the Engine and reboot the AVN System.  
Check the functions  
Check the upgrade version and make sure once again.

and  
Finish.

### New Version information


Software Version : DM-N3000D-**AP-028**

Micom : DM-N3000D-MC-027


OS : DM-N3000D-OS-010

## STEP 3: Method of entering update screen

- 1) Insert update USB into customer 's navigation device
- 2) Push Navi Button
- 3) Select "Settings"




- 4) Select "Reset/Info"




## STEP 3: Method of entering update screen


### 5) Select "Version Information"



### 6) Long Press(10sec) "BACK" hardkey to move "Device Info" page





- Update Screen





## STEP 3: Method of entering update screen

- 7) If below message is displayed, the wrong(input wrong code) authentication key is generated in USB.  
Please run application software and generate the correct authentication key again.

If authentication key is wrong




If authentication key is correct





## STEP 4: Update navigation system with update USB stick

### 1) Select "USB Check"




### 2) If there is no issue with the map in USB, "the update Navi" button will be activated.




## STEP 4: Update navigation system with update USB stick

### 3) Select "Update Navi"




### 4) It takes about 15~20 minutes to update. If update is done, automatically reboot the AVN.





## STEP 5: If you already updated the map with wrong authentication key.

- 1) Run application software and generate the correct authentication key again.
- 2) Go to Navi or Map Screen.
- 3) Press "OK" button.(then, automatically copy the correct authentication key from USB to Navigation.)



- 4) Go to Navi or Map Screen after re-booting(Turn off the ignition)
- 5) If the correct authentication key is copied, you can use the navigation. if not, try No.1 ~ 4 again.

## STEP 5: Check the new Navi version

- Check if the update has been successful
- Push Navi Button → Select “Settings” → Select “Reset/Info” → Select “Version Information”

