

### Taper Bushing Installation

**IMPORTANT NOTE:** Please follow the instructions on this sheet in order for the Martin bushing to perform satisfactorily.









1008 to 3030

3535 to 6050

#### INSTALLATION

- 1. Clean all oil, dirt, and paint from shaft, bushing bore, outside of bushing and component (sprocket, sheave...etc.) bore.
- 2. Insert bushing into component. Match the hole pattern, not the threaded holes (each hole will be threaded on one side only.)
- 3. Thread set or cap screws into those half threaded holes indicated by O on above diagram. Mount assembly on shaft.
- 4. Alternately torque set or cap screws\* to recommended torque setting in chart below.
- 5. On 3535 and larger bushings use a block, sleeve or drift and hammer large end of bushing (do not hammer bushing directly).
- 6. Repeat steps 4 and 5 until torque wrench reading, after hammering, is the same as before hammering.
- 7. Fill all unoccupied holes with grease.

#### **REMOVAL**

- 1. Remove all set or cap screws.
- 2. Insert set or cap screws in holes indicated by on drawing. Loosen bushing by alternately tightening set or cap screws.
- 3. To reinstall, complete all seven (7) installation instructions.

RECOMMENDED TORQUE									
Bushing No.	Set Screw	Wrench Torque in/lb							
	1/4 – 20 Socket Set Screw	55							
1008, 1108 1210, 1215, 1310	5/16 – 18 Socket Set Screw	165							
1610, 1615	3/8 - 16 Socket Set Screw	175							
	3/8 – 16 Socket Set Screw	175							
2012	7/16 – 14 Socket Set Screw	280							
2317, 2525	1/2 – 13 Socket Set Screw	430							
3020, 3030	5/8 - 11 Socket Set Screw	800							
3535	1/2 – 13 Socket Set Screw	1000							
4040	5/8 - 11 Socket Set Screw	1700							
4545	3/4 - 10 Socket Set Screw	2450							
5050	7/8 – 9 Socket Set Screw	3100							
6050, 7060, 8065	1-1/4 – 7 Socket Set Screw	7820							
10085, 120100	1-1/2 – 6 Socket Set Screw	13700							

CAUTION

WARNING: USE OF
ANTI-SEIZE LUBRICANT ON
TAPERED CONE SURFACE OR
ON BOLT THREADS WHEN
MOUNTING MAY RESULT IN
DAMAGE TO SHEAVE AND
SPROCKETS. THIS VOIDS
ALL MANUFACTURER'S
WARRANTIES

If two bushings are used on same component and shaft, fully tighten one bushing before working on the other

**WARNING:** Because of the possible danger to person(s) or property from accidents which may result from the improper use of products, it is important that correct procedures be followed: Products must be used in accordance with the engineering information specified in the catalog. Proper installation, maintenance and operation procedures must be observed. The instructions given above must be followed. Inspections should be made as necessary to assure safe operation under prevailing conditions. All rotating power transmission products when used in a drive are potentially dangerous and must be guarded by the user as required by applicable laws, regulations, standards, and good safety practice. (Refer to ANSI Standard B15.1.)


## Taper Bushings Dimensions



### No. 1008 to 3030 Taper Bushings

			шро. Ба	
Bushing Number	Bore	Wt. Ibs (appr)	Bushing Keyseat	Shaft Keyseat
	.5 to .563	.27	.125 × .063	.125 × .063
1008	.625 to .875	.21	.188 × .094	.188 × .094
1000	.938 to 1	.16	.25 × .063 ▼	.25 × .125
	.5 to .563	.33	.125 × .063	.125 × .063
	.625 to .875	.27	.188 × .094	.188 × .094
1108	.938 to 1	.22	.25 × .125	.25 × .125
	1.063 to 1.125	.17	.25 × .063 ▼	.25 × .125
	.5 to .563	.61	.125 × .063	.125 × .063
	.625 to .875	.55	.188 × .094	.188 × .094
1210	.938 to 1.25	.49	.25 × .125	.25 × .125
	.5 to .563	.8	.125 × .063	.125 × .063
1215	.625 to .875	.7	.188 × .094	.188 × .094
1210	.938 to 1.25	.6	.25 × .125	.25 × .125
	.5 to .563	.7	.125 × .063	.125 × .063
	.625 to .875	.7	.123 × .003	.123 × .003
1310	.938 to 1.25	.6	.25 × .125	.25 × .125
	1.313 to 1.375		.23 × .125	.25 × .125
	.5 to .563	.6 .9	.125 × .063	.125 × .063
				.123 × .063
	.625 to .875	.8	.188 .094	
1610	.938 to 1.25	.7	.25 × .125	.25 × .125
	1.313 to 1.375	.7	.313 × .156	.313 × .156
	1.438 to 1.5	.6	.375 × .188	.375 × .188
	1.563 to 1.625	.5	.375 × .125 ▼	.375 × .188
	.5 to .563	1.2	.125 × .063	.125 × .063
	.625 to .875	1.1	.188 × .094	.188 × .094
1615	.938 to 1.25	1.0	.25 × .125	.25 × .125
1010	1.313 to 1.375	.8	.313 × .156	.313 × .156
	1.438 to 1.5	.7	.375 × .188	.375 × .188
	1.563 to 1.625	.6	.375 × .125 ▼	
	.5 to .563	1.7	.125 × .063	.125 × .063
	.625 to .875	1.6	.188 × .094	.188 × .094
	.938 to 1.25	1.5	.25 × .125 ▼	.25 × .125
2012	1.313 to 1.375	1.4	.313 × .156	.313 × .156
	1.438 to 1.75	1.2	.375 × .188	.375 × .188
	1.813 to 1.875	1.0	.5 × .25	.5 × .25
	1.938 to 2	1.0	.5 × .188 ▼	.5 × .25
	.5 to .563	3.5	.125 × .063	.125 × .063
	.625 to .875	3.4	.188 × .094	.188 × .094
	.938 to 1.25	3.3	.25 × .125	.25 × .125
2517	1.313 to 1.375	3.2	.313 × .156	.313 × .156
	1.438 to 1.75	3.0	.375 × .188	.375 × .188
	1.813 to 2.25	2.4	.5 × .25	.5 × .25
	2.313 to 2.5	1.9	.625 × .188 ▼	.625 × .313
	.75 to .875	4.9	.188 × .094	.188 × .094
	.938 to 1.25	4.7	.25 × .125	.25 × .125
	.938 to 1.375	4.5	.313 × .156	.313 × .156
2525	1.438 to 1.75	4.2	.375 × .188	.375 × .188
	1.813 to 2.25	3.3	.5 × .25	.5 × .25
	2.313 to 2.5	2.5	.625 × .188 ▼	.625 × .313
	.938 to 1.25	6.5	.25 × .125	.25 × .125
	1.313 to 1.375	6.3	.313 × .156	.313 × .156
	1.438 to 1.75	6.0	.375 × .130	.375 × .130
3020	1.813 to 2.25	5.3	.5 × .25	.5 × .25
	2.313 to 2.75	4.5	.5 × .25	.5 × .25
	2.813 to 3	3.9	.025 × .313	.75 × .375
	.938 to 1.25	9.2	.25 × .125	.25 × .125
	1.313 to 1.375	8.9	.313 × .156	.313 × .156
3030	1.438 to 1.75	8.6	.375 × .188	.375 × .188
	1.813 to 2.25	7.6	.5 × .25	.5 × .25
	2.313 to 2.75	6.2	.625 × .313	.625 × .313
I	2.813 to 3	5.0	.75 × .25 ▼	.75 × .375





#### **Dimensions**

				СØ				Ly	<del>k</del>	M ★	*
Bushing Number	- Δ	В	Class 20 Gray Iron	Class 30 Gray Iron	Steel	D	D F†			Std. Hex. Key	Short Key ‡
1008	1.386	.875	2.375	2.188	1.938	1.328	.25 × .5	1.125	.625	1.25	.75
1108	1.511	.875	2.5	2.313	2.063	1.453	.25 × .5	1.125	.625	1.25	.75
1210	1.875	1	3.625	3.25	2.875	1.75	.375 × .625	1.375	.813	1.625	1.063
1215	1.875	1.5	3.125	2.875	2.625	1.75	.375 × .625	1.375	.813	1.625	1.063
1310	2	1	3.75	3.375	3	1.875	.375 × .625	1.375	.813	1.625	1.063
1610	2.25	1	4	3.625	3.25	2.125	.375 × .625	1.375	.813	1.625	1.063
1615	2.25	1.5	3.5	3.25	3	2.125	.375 × .625	1.375	.813	1.625	1.063
2012	2.75	1.25	4.75	4.375	3.875	2.625	.438 × .875	1.563	.938	2	1.375
2517	3.375	1.75	5.5	4.875	4.375	3.25	.5 × 1	1.625	1	2.25	1.625
2525	3.375	2.5	4.75	4.5	4.25	3.25	.5 × 1	1.625	1	2.25	1.625
3020	4.25	2	7	6.25	5.625	4	.625 × 1.25	1.813	1.188	2.688	2.063
3030	4.25	3	6.25	5.75	5.375	4	.625 × 1.25	1.813	1.188	2.688	2.063

Bushings cannot be bored larger than largest bore listed.

For detail dimensions required for machining hubs, consult factory.

- Key furnished for these sizes only.
- Ø For general reference. Severe conditions may require larger hub. Heavy well-located web may permit smaller hub. Hub diameter required depends on the particular application. Consult Martin giving full information on the proposed design. Hub diameters shown are based on 20,000, 30,000, and 50,000 P.S.I. minimum ultimate tensile strength respectively for Class 20 gray iron, Class 30 gray iron, and steel hubs.
- 2 screws required. Use in positions shown for tightening bushing on shaft. In removing bushing from shaft, remove screws and use one of them in the other hole. Bushing price includes screws.
- ♦ Space required to tighten bushing. Also space required to loosen screws to permit removal of hub by puller.
- ★★ Space required to loosen bushing using one screw as jackscrew no puller required.
- ‡ Standard hex key cut to minimum usable length.



# Taper Bushings Dimensions

### No. 3535 to 5050 Bushings

Duching			Duching	Chaff				CØ					
Bushing Number	Bore	Weight	Bushing Keyseat	Shaft Keyseat	A	В		Class 30 Gray Iron	Steel	D	F†	G	R
	1.188 to 1.25	14	.25 × .125	.25 × .125									
	1.313 to 1.375	14	.313 × .156	.313 × .156									
	1.438 to 1.75	13	.375 × .188	$.375 \times .188$									
3535	1.813 to 2.25	12	.5 × .25	.5 × .25	5	3.5	7.75	7	6.5	4.83	.5 × 1.5	39°	<b>A</b>
	2.313 to 2.75	11	.625 × .313	$.625 \times .313$									
	2.813 to 3.25	9	.75 × .375	.75 × .375									
	3.313 to 3.5	8	▼ .875 × .25	.875 × .438									
	1.438 to 1.75	22	.375 × .188	.375 × .188									
	1.813 to 2.25	21	.5 × .25	.5 × .25									
	2.313 to 2.75	19	.625 × .313	$.625 \times .313$	5.75	4	9.5		7.75		.625 × 1.75	40°	•
4040	2.813 to 3.25	17	.75 × .375	.75 × .375				8.5		5.54			
	3.313 to 3.625	15	.875 × .438	.875 × .438									
	3.688 to 3.75	14	.875 × .438	.875 × .438									
	3.813 to 4	13	▼ 1 × .25	1 × .5									
	1.938 to 2.25	30	.5 × .25	.5 × .25									
	2.313 to 2.75	28	.625 × .313	$.625 \times .313$									
4545	2.813 to 3.25	26	.75 × .375	.75 × .375	6.375	4.5	10.5	9.5	8.75	6.13	.75 × 2	40°	
7070	3.313 to 3.75	23	.875 × .438	.875 × .438	0.070	7.0	10.0	0.0	0.70	0.10	.70 ^ 2	70	_
	3.813 to 4.25	20	1 × .5	1 × .5									
	4.313 to 4.5	18	▼ 1 × .25	1 × .5									
	2.313 to 2.75	38	.625 × .313	.625 × .313									
	2.813 to 3.25	35	.75 × .375	.75 × .375	_								
5050	3.313 to 3.75	32	.875 × .438	.875 × .438	7	5	11.5	10.5	9.5	6.72	.875 × 2.25	37°	<b>A</b>
3030	3.813 to 4.5	27	1 × .5	1 × .5									
	4.563 to 5	24	▼ 1.25 × .438	1.25 × .625									

### No. 4030 to 5040 Short Taper Bushings

								CØ					
Bushing Number	Bore	Weight	Bushing Keyseat	Shaft Keyseat	Α	В		Class 30 Gray Iron	Steel	D	F†	G	R
	1.438 to 1.75	24	.375 × .188	.375 × .188									
	1.813 to 2.25	21	.5 × .25	.5 × .25									
	2.313 to 2.75	20	$.625 \times .313$	$.625 \times .313$									
	2.813 to 3.25	18	.75 × .375	.75 × .375	5.75	3	9.5	8.5	7.75	5.54	.625 × 1.75	39°	
4030	3.313 to 3.688	15	$.875 \times .438$	.875 × .25	3.73	٦	9.5	0.5	1.13	3.54	.023 × 1.73	39	_
	3.75	13	▼ .875 × .25	.875 × .438									
	3.813	13	1 × .5	1 × .5									
	3.875 to 4.438	13	1 × .25	1 × .5									
	1.938 to 2.25	31	.5 × .25	.5 × .25									
	2.313 to 2.75	29	.625 × .313	.625 × .313									
	2.813 to 3.25	25	.75 × .375	.75 × .375									
4535	3.313 to 3.688	23	.875 × .438	.875 × .438	6.375	3.5	10.5	9.5	8.75	6.13	.75 × 2	40°	<b>A</b>
4555	3.813 to 4.25	20	1 × .5	1 × .5									
	4.375 to 4.5	17	▼ 1 × .25	1 × .5									
	4.75 to 4.938	15	<b>▼</b> 1.25 × .25	$1.25 \times .625$									
	2.438 to 2.75	40	.625 × .313	.625 × .313									
	2.813 to 3.25	37	.75 × .375	.75 × .375	7								
5040	3.313 to 3.75	33	.875 × .438	.875 × .438		4	11.5	10.5	9.5	6.72	.875 × 2.25	37°	<b>A</b>
5040	3.813 to 4.5	29	1 × .5	1 × .5		'							_
	4.75 to 5	23	▼ 1.25 × .25	1.25 × .625									

Bushings cannot be bored larger than largest bore listed.

For detail dimensions required for machining hubs, consult factory.

- ▼ Key furnished for these sizes only.
- For general reference. Severe conditions may require larger hub. Heavy well located web may permit smaller hub. Hub diameter required depends on the particular application. Consult factory giving full information on the proposed design. Hub diameters shown are based on 20,000, 30,000, and 50,000 P.S.I. minimum ultimate tensile strength respectively for Class 20 gray iron, Class 30 gray iron, and steel hubs.
- † 3 screws required. Use in positions shown for tightening bushing on shaft. In


removing bushing from shaft, remove screws and use two of them in the other two holes. Bushing price includes screws. See following footnote.


 Provide sufficient space to tighten and loosen bushing. Width across flats of screw head is same as screw diameter which is shown in column F.

## Taper Bushings Dimensions









### No 6050 to 120100 Taper Bushings

			-					СØ						
Bushing Number	Bore	Weight	Bushing Keyseat	Shaft Keyseat	A	В	Class 20 Gray Iron	Class 30 Gray Iron	Steel	D	E	F†	L*	M★★
6050	3.813 to 4.5 49/16 to 5.5 5.563 to 6	60 55 50	1 × .5 1.25 × .625 1.5 × .75	1 × .5 1.25 × .625 1.5 × .75	9.25	5	17	15.5	13.5	9	6.75	1.25 × 3.5	1.625	4.375
7060	4.563 to 5.5 5.563 to 6.5 6.563 to 7	85 75 65	1.25 × .625 1.5 × .75 1.75 × .75	1.25 × .625 1.5 × .75 1.75 × .75	10.25	6	18.5	17	14.75	10	7.75	1.25 × 3.5	1.625	4.375
◊ 8065	5.063 to 5.5 5.563 to 6.5 6.563 to 7.5 7.563 to 8	120 105 90 75	1.25 × .625 1.5 × .75 1.75 × .75 2 × .75	1.25 × .625 1.5 × .75 1.75 × .75 2 × .75	11.25	6.5	19	17.5	15.5	11	8.75	1.25 × 3.5	1.625	4.375
◊ 10085	6.563 to 7.5 7.563 to 9 9.063 to 10	260 230 190	1.75 × .75 2 × .75 2.5 × .875	1.75 × .75 2 × .75 2.5 × .875	14.75	8.5	23.5	22	19.5	14.5	11.75	1.5 × 4.25	2	5.375
◊ 120100	7.563 to 9 9.063 to 11 11.063 to 12	410 360 290	2 × .75 2.5 × .875 3 × 1	2 × .75 2.5 × .875 3 × 1	17.25	10	28	26	23	17	14.25	1.5 × 4.25	2	5.375

Bushings cannot be bored larger than largest bore listed.

For detail dimensions required for machining hubs, consult Martin.

- Ø For general reference. Severe conditions may require larger hub. Heavy well located web may permit smaller hub. Hub diameter required depends on the particular application. Consult Martin giving full information on the proposed design. Hub diameters shown are based on 20,000, 30,000, and 50,000 P.S.I. minimum ultimate tensile strength respectively for Class 20 gray iron, Class 30 gray iron, and steel hubs.
- 3 screws for 6050; four for 7060 to 10085; six for 120100. Use in positions shown for tightening bushing on shaft. In loosening bushing, remove screws and use all except one in the other holes. Bushing price includes screws.
- Space required to tighten bushing. Also space required to loosen screws to permit removal of hub by puller.
- \*\* Space required to loosen bushing using screws as jackscrews— no puller required.
- ♦ Not currently stocked Available on order.



### **Taper Bushed Type S-Type W Weld-On Hubs Dimensions**


#### Type S

Martin taper bushed type S weld-on hubs are suitable for use in many applications such as for welding to plate steel sprockets. The outside diameters of these hubs have been reduced to a minimum. This is permissible because of the reinforcing strength of the items to which they are to be welded. Cases where the attached item is of small dimensions should be referred to Martin.

Type S weld-on hubs are made of steel, drilled, tapped, and taper bored for tapered bushings. Their small size and the convenience and advantages of taper bushed construction make them of great value on many devices for use on shafts.

Bushing Number	For Use with Bushing Number	Max. Bore of Bushing	Weight	Α	<b>B</b> ◊	C **	D▼	G	J
S16-4	1610	1.625	.9	3	1	.275	.725	2.875 †	2.25
S16-6	1610	1.625	.9	3	1	.450	.550	2.875 †	2.25
S20-6	2012	2	1.8	3.563	1.25	.450	.800	3.438 †	2.75
S20-8	2012	2	1.4	3.563	1.25	.570	.680	3.438 †	2.75
S25-6	2517	2.5	2.6	4.25	1.75	.450	1.300	4.125 †	3.375
S25-8	2517	2.5	2.6	4.25	1.75	.565	1.185	4.125 †	3.375
S25-10	2517	2.5	2.5	4.25	1.75	.685	1.065	4.125 †	3.375
S25-16	2517	2.5	2.4	4.25	1.75	1.090	.660	4.125 †	3.375
S30-10	3020	3	4.3	5.25	2	.675	1.325	5.125 †	4.25
S30-16	3020	3	4.2	5.25	2	1.090	.910	5.125 †	4.25
S35	3535	3.5	12.8	6.5	3.5	1.160	2.340	6.375 Ø	5





See dimension tables on preceding page for bushing data and wrench space required.


.000 - .002 .005 - .010 .001 - .003 .000 - .005

.010 - .010

### Ty

pe WA						
pe WA weld-on hubs are ma ceive tapered bushings. They lleys, plate sprockets, impell ust be firmly fastened to the	are very useful fores, agitators, and	or welding into	fan rotoi	rs,		

Bushing Number	Bushing Number	Max. Bore of Bushing	Weight	A	В	С	D	F	G	Н	J	K
WA12	1215	1.25	1.3	2.875	1.5	.375	.625	.375	2.5 †	2.375	1.875	2.625
WA16	1615	1.625	1.5	3.25	1.5	.375	.625	.375	2.875 †	2.75	2.25	3
WA25	2517	2.5	4.0	4.875	1.75	.5	.75	.375	4.375 †	4.25	3.375	4.625
WA30	3030	3	8.6	5.5	3	.75	.75	.25	5.125 †	4.813	4.125	5
WA35	3535	3.5	15	6.75	3.5	1.25	1	.375	6.25 †	5.938	5	6
WA40	4040	4	29	7.75	4	1.5	1	.375	7.25 †	6.875	5.75	7
WA45	4545	4.5	42	8.75	4.5	1.75	1	.375	8 †	7.625	6.375	8
WA50	5050	5	57	9.5	5	1.75	1	.375	8.75 •	8.375	7	8.75
WA60	6050	6	115	13.25	5	1.75	1.25	_	12.25 ★	11.875	9.25	_
WA70	7060	7	155	14.5	6	2.25	1.25	_	13.5 ★	13.25	10.25	_
WA80	8065	8	180	15.25	6.5	2.25	1.25	-	14.25 ★	14	11.25	_
WA100	10085	10	340	19.75	8.5	3.5	1.5	-	18.75 ★	18.25	14.75	-



See dimension tables on preceeding page for bushing data and wrench space required.

- .000 .002
- .000 .003
- .000 .004

# Taper Bushings Metric and Reborable



### **Stock Taper Bushings With Metric Bores and Keyways**

★ Metric Bores	★ Metric Keyway	Taper Bushing Number								
14.16	5 × 2.3	1008	1108	1210						
14, 16	3 × 2.3	1215	1610	1615						
18, 19	6 × 2.8	1008	1108	1210	1215					
20, 22	0 × 2.0	1610	1615	2012	2517					
24	8 × 3.3	1108	1210	1215						
24	0 × 3.3	1610	1615	2012	2517					
25	8 × 3.3	1210	1215	1610						
20	0 × 3.3	1615	2012	2517						
28, 30	8 × 3.3	1210	1215	1610						
20, 30	0 × 3.3	1615	2012	2517	3020					
32	10 × 3.3	1610	1615							
32	10 × 3.3	2012	2517	3020						
35	10 × 3.3	1610	1615							
33	10 × 3.3	2012	2517	3020						
38	10 × 3.3	1610	1615							
30	10 × 3.3	2012	2517	3020						
40, 42	12 × 3.3	2012								
40, 42	12 × 3.3	2517	3020							
45, 48	14 × 3.8	2012	·							
45, 40	14 × 3.0	2517	3020							
50	14 × 3.8	2517	3020							
55	16 × 4.3	2517	3020							

<sup>★</sup> Millimeter Bores and Keyways from ISO Std. R773. 1" = 25.4 millimeters

NOTE: For other metric bore sizes consult factory.

### **Stock Reborable Taper Bushings With No Keyways**

Sinter	red Steel		Gray Iron	Ste	el	Stainles	s Steel
1008	.563			1008	.5	1008	.5
1108	.5			1108	.5	1108	
1210	.563			1210	.5	1210	.5
1215	.5			1215	.5	1215	
1310	.5			1310		1310	
1610	.5 1.313			1610	.5	1610	.5
1615	.5 1.313			1615	.5	1615	
2012	.5			2012	.5	2012	.5
2517	.5 1.563			2517	.5	2517	.5
		2525	2.125	2525		2525	
3020	.938 1.688	3020	.938 1.438 2.938	3020	.938	3020	.938
		3030	.938 2.438 2.938	3030		3030	
		3535	1.188 2.438 2.938	3535		3535	
		4040	1.438 3.438 3.938	4040		4040	
		4545	3.938 4.438	4545		4545	
		5050	2.438 3.938				
		6050	3.438 5.438				
		7060	3.938				
		8065	4.438				
		10085	7				
		H120100	8				

 $<sup>\</sup>bigstar$  Not currently stocked. Consult factory for availability and pricing.