



TPMS TIRE PRESSURE
MONITORING SYSTEMS
CATALOG

2012

YOUR ONE SOURCE FOR QUALITY
BRAND NAME EQUIPMENT, TOOLS
AND SUPPLIES FOR THE TIRE INDUSTRY

Ascot Supply Corporation



Are you ready for TPMS?

TPMS RELEARN TYPES:

Use an activation tool with the car in "re-learn" mode. New ID's can be programmed without driving the vehicle.

25%
STATIONARY

An activation tool in conjunction with a scan tool is required to program new sensor ID's into the vehicle. New ID's can be programmed without driving the vehicle.

36%
OBD


Vehicle can learn a single new ID and in some cases multiple new ID's without the use of a tool. Requires driving the car in order to turn off the light.

39%
AUTO LEARN

TPMS SENSOR POPULATION:

MY	Units Sold	Market Coverage	Vehicles with Sensors Installed
2011*	10,700,000	100%	10,700,000
2010	11,024,374	100%	11,024,374
2009	10,431,504	100%	10,431,504
2008	13,245,687	100%	13,245,687
2007	16,154,010	70%	10,607,807
2006	16,561,482	20%	3,399,437
2005	16,997,182	20%	3,398,931
2004	16,913,361	10%	1,691,336
Estimated No. of Vehicles with TPMS			64,499,076
Estimated No. of Vehicles with TPMS			257,996,304

TPMS SENSORS OUT OF WARRANTY:



* Based on Industry Average Bumper to Bumper 3 year/36,000 mile Warranty and 15,000 miles per year average

TPMS Sensors to be Serviced or Replaced

- Nearly 260 million TPMS sensors now on the road!
- Over half of those are now at least three years old.
- Average battery life is five to seven years.

Market Studies Estimated Replacements Due to Battery Failure:

- **2012:** Approx. 1.71 million sensor units replaced
- **2013:** Approx. 2.68 million sensor units replaced
- **2014:** Approx. 3.79 million sensor units replaced

TPMS CHALLENGE:

There is a growing number of vehicles that require a corporate scan tool to complete a vehicle repair. The market needs a tool that can function as BOTH a scan tool AND sensor activation tool.



TPMS Made Easy

2 Sensors 90%* Coverage



Part No. 33000
315 MHz



Part No. 33100
433 MHz



*Software is being updated to enable 2 EZ-sensors to cover 90% of the market.

Schrader® is committed to supporting the aftermarket with OE-quality products, dedicated training and industry-leading technical support. From EZ-sensor™ to OEM replacement sensors, service kits and replacement parts, we've got you covered. When it comes to supporting our customers, the sky's the limit.



What's New at Bartec!




TECH400SD

Bartec announces the latest in Combination TPMS Tool Technology.

Improving on the widely used TPMS Diagnostic and Programming tool, the Tech400+, Bartec has added features and functionality to help Tire Shops and Repair Facilities build their success in TPMS! The Tech400SD has market leading coverage for the diagnosis and repair of the TPMS of Domestic and Import vehicles. Through its uniquely robust OBD cable, the Tech400SD can diagnose problems and reset the TPMS control module of Asian makes such as Acura, Honda, Hyundai, Kia, Infiniti, Lexus, Mazda, Mitsubishi, Nissan, Subaru and Toyota. Also, because the Tech400SD is an activation tool, it can quickly activate the TPMS Sensors during a domestic car relearn on such makes as GM, Ford and Chrysler.



SD Card Updates



Re-learn procedure
on the tool



Raised button keypad

TECH300SD

Bartec announces the latest in compact TPMS Tools.

The Tech300SD has many of the same Bartec TPMS features in a compact and ergonomic form factor. The Tech300SD can be purchased as a complete combination tool, or separately as an Activation Tool only. Based on the time tested and proven Bartec tool platform, the Tech300SD is a lower cost way to get started in TPMS.



TPMS PAD

Bartec announces the new TPMS PROGRAMMING ACCESSORY DEVICE also known as the TPMS PAD.

This Programming tool will help make your tire shop more efficient because it programs the market leading EZ-sensor™. Simply load the software, connect the PAD to a PC or LAPTOP and program sensors! The PAD makes programming EZ-sensors™ even easier and faster - and that will make you more successful in TPMS! Just two EZ-sensors™ (one for 315 MHz and one for 433 MHz) will cover 90% of the TPMS replacement market.



TABLE OF CONTENTS

● TPMS RELEARN CHART	
TPMS Relearn Chart _____	4
● TPMS SENSOR ACTIVATION TOOLS	
Sensor Activation Tools _____	5
● UNIVERSAL TPMS TRANSMITTERS	
EZ-Sensors _____	10
REDI-Sensors _____	11
REDI-Sensor Accessories _____	12
● OE TPMS TRANSMITTERS	
Schrader TPMS Transmitters _____	13
Dill TPMS Transmitters _____	14
● TPMS TOOLS, ACCESSORIES & KITS	
Accessories & Kits _____	15
Tools & Tool Kits _____	18
● BANDED TPMS SYSTEMS	
Banded TPMS Systems & Accessories _____	22
● TPMS CABINETS	
TPMS Cabinets _____	23
● TPMS RETROFIT KITS	
TPMS Retrofit Kits _____	24
● TRAINING & PROMOTIONAL MATERIALS	
Training & Promotional Materials _____	25
● UNIVERSAL TPMS TRANSMITTERS APPLICATION GUIDES	
EZ-Sensor Application Guide _____	26
REDI-Sensor Application Guide _____	31
● SCHRADER APPLICATION GUIDE	
Schrader 2011 TPMS Application Guide _____	32
Manufacturer's Part Numbers _____	97
Numerical Listing: Sensors/Transmitters _____	98
Numerical Listing: Service Packs _____	106
● DILL APPLICATION GUIDE	
Dill 2011 TPMS Application Guide _____	116

Ascot Supply Corporation is not responsible for inadvertent typographical errors or omissions.



**THE BEST
TPMS
RELEARN
CHART ON
THE MARKET**



469-12011
2011 TIA TPMS
Relearn Chart

TPMS RELEARN CHART

2011 TIA TPMS Relearn Chart

The TIA Tire Pressure Monitoring System (TPMS) Relearn Chart serves as a valuable, comprehensive, and quick reference guide that technicians can easily navigate through to service any vehicle - foreign AND domestic - equipped with TPMS.

Your organization won't want to be without one! It will save you time and money the first time you use it.

- Information on vehicles equipped with TPMS through Model Year 2009
- Laminated Flip Chart designed to provide accurate information on all aspects of TPMS applications, including relearn procedures
- Chart is divided into Domestic & Import vehicle sections

CHART PROVIDES THE FOLLOWING INFORMATION:

- The type of TPMS, whether direct or indirect.
- Three columns of data that indicate when a system relearn is necessary, i.e. after a change in air pressure, tire rotation, or tire/sensor replacement.
- A relearn summary: this includes a reference number that corresponds to the vehicle's procedure for initiating sensor relearn mode. The vehicle relearns are located in the back of the corresponding section, either domestic or import.
- The sensor manufacturer.
- OEM sensor part number, Schrader replacement sensor part and service pack numbers, Dill replacement sensor part and kit and band numbers, Continental replacement sensor part and kit and band numbers, and NAPA replacement sensor part and service pack numbers.
- The torque specifications for the sensor nut, torx bolt, worm gear and lug nuts are listed.

Ascot No.	Description
469-12011	2011 TIA TPMS Relearn Chart

Snapshots of what is included in the 2011 TIA TPMS Relearn Chart:

Make	Model	Year	Subtract Indirect TPMS	Requires Disarm After Change Air Pres.	Requires Tire Rotation	Requires Tire/Sensor Replacement	Release Summary	Sensor Brand	OEM Sensor Part#	Schrader Sensor Part#	Schrader Service Pack#	Dill Sensor Part#	Dill Kit or Band #	NAPA Sensor Part#	NAPA Service Pack#	Continental Part # (Sensor Service Pack)	Continental Part # (Kit or Band)	Sensor Nut	Torque Spec. (lb-ft)	Worm Gear	Worm Gear Torque Spec. (lb-ft)	Lug Nut PT. Size (Metric)
Buick	Aliant	2008	I	✓	✓	✓	SM-2	Schrader		20158	20004		1070K	821011	820125				62(7)			100(1.40)
	Aliant	2007	D	✓	✓	✓	SM-6	Siemens	10921013		20030	1047	1000K		820130	8203007	8204308	80(9)			100(1.40)	
	Aliant	2008	D	✓	✓	✓	SM-11	Schrader		20158	20004		1070K	821011	820125				62(7)			100(1.40)
	Aliant	2009	D	✓	✓	✓	SM-11	Schrader	20020613	20153	20008	8153	83830	821021	820145				11.5			100(1.40)
Century	1999-05	I	✓	✓	✓	SM-1																100(1.40)

IMPORT RELEARN

IC-1

Ensure all tires are inflated to the pressure listed on the tire placard. Drive vehicle at speeds above 15 mph for a minimum of 40 seconds. Sensor IDs will be learned automatically.

IC-2

- Inflate all tires to pressure listed on tire placard.
- Hold down RESET button (on end of valve stem) until DISPLAY TPMS is displayed.
- Press button on end of valve stem to select TIRE PRESSURE.
- Press RESET button.
- Press button on end of valve stem to select WHEELS. CHANGED current STORE PRESSURE if mounting all sensors.
- Press RESET button. Relearn can take 20 minutes to complete.

IC-3

Inflate all tires to pressure indicated on tire placard.

IF equipped with drive:

- Turn ignition to ON position (engine off).
- Select SET/TREK from drive menu.
- Select VEHICLE.
- Select TPMS.
- Select RESET.

IF not equipped with drive:

- Turn ignition to the position (engine off).
- Hold down TIRE PRESSURE (wheel) or RDC button (located on instrument panel) until TPMS vehicle is illuminated.
- Vehicle must be driven to complete relearn.

IC-4

A properly formulated scan tool is required to learn new sensor IDs when replacing sensors.

IC-5

Initialization following rotation and tire replacement:

- Inflate all tires to pressure indicated on tire placard.
- Apply parking brake and leave ignition in ON position (engine off).
- Hold down low pressure warning reset switch until TPMS vehicle beeps 2 times.
- It will take several minutes for the IC3 to receive signals from the sensors and complete initialization.
- Properly formulated scan tool is required to learn new sensor IDs when replacing sensors.

IC-6

Initialization following rotation and tire replacement:

SENSOR ACTIVATION TOOLS

A. Bartec Wheelrite Tech 400SD

- Large, easy to read display
- Make - Model - Year Vehicle Look up
- Downloads TPM data directly to the vehicle
- Rechargeable Battery
- Decodes and displays sensor data including: Sensor ID, PSI, Battery State, Temperature
- Displays the replacement part number
- Compact and ergonomic
- Most complete sensor coverage
- Audit Mode - easily download TPMS Sensor Data to a PC or Laptop for printing
- Upgradable via USB port
- Removable SD card for easy update [no PC]
- New "rubberized" key pad
- Increased Memory –means better functions (like on-board re-learn procedures)



469-40111
Bartec Wheelrite
Tech 400SD

ALL IN THE PALM OF YOUR HAND:

- Update without a computer or the internet
- Re-Learn Procedures right on the tool, at your finger tips!
- Raised key touch pad for easier operation!
- Still programs EZ sensor



Compliant with Asian Vehicle Manufacturers such as: Toyota, Lexus, Nissan, Infiniti, Honda, Acura, Hyundai, Kia and more

SOFTWARE UPDATES:

- 1 year WRT400SUL1
- 2 year WRT400SUL2
- 3 year WRT400SUL3

CERTIFICATE INCLUDES:

- Update Certificate (w/Activation Code) 4 1/2" X 4 1/2" certificate, packaged in a CD jacket
- Instruction Sheet included in the package



Still programs EZ-Sensor



469-40011
One Year
Software
Update

469-40022
Two Year
Software
Update

469-40033
Two Year
Software
Update

Ascot No.	Mfg. No.	Description
469-40111	Tech400SD	Bartec Wheelrite Tech 400SD
469-40011	WRT400SUL1	One Year Software Update
469-40022	WRT400SUL2	Two Year Software Update
469-40033	WRT400SUL3	Three Year Software Update

B. Bartec Programming Fixture

- Designed for use with the Bartec Tech 400 TPMS reprogramming tool in conjunction with the EZ Sensor
- The use of the fixture allows for the EZ Sensor to rest securely in the correct position for relearning
- Is also included in the 469-40010 Bartec EZ Sensor starter kit as standard procedure



469-40035
Bartec
Programming
Fixture

Ascot No.	Mfg. No.	Description
469-40035	WRTEZS-STK35	Bartec Programming Fixture

SENSOR ACTIVATION TOOLS (CONT'D.)

C



469-40012
Bartec Wheelrite
Tech ESC

COMING SOON!

C. Bartec Wheelrite Tech ESC

- Niche Scan Tool –underbody systems
- Service Electronic Braking systems
- Recalibrate steering wheel position
- Re-set stability control –2012 mandate
- Oil re-set function

Ascot No.	Mfg. No.	Description
469-40012	Tech ESC	Bartec Wheelrite Tech ESC

D



469-30002
Bartec Wheelrite
Tech 300SD


D. Bartec Wheelrite Tech 300SD

- Replacing the Tech 300+
- More Compact than the Tech400+
- Rechargeable battery
- SD Card updates –no computer needed
- Optional OBD Connector –either in kit or sold separate
- Functions similar to Tech400+
- Can program EZ-Sensor

TOOL KIT INCLUDES:

- Standard USB Cable
- Magnet
- Protective rubber boot

Screenshots:



469-30005
Tech 300SD
Upgrade Kit

Ascot No.	Mfg. No.	Description
469-30002	TECH300SD	Bartec Wheelrite Tech 300SD
469-30003	WRT300PSD	Bartec Wheelrite Tech 300SD Kit ▪ Includes carrying case, relearn magnet, USB cable & user guide
469-30004	WRT300PSDC	Bartec Wheelrite Tech 300SD Combo Kit ▪ Includes all of the above plus the OBD connector
469-30005	WRT300POBD	Tech300SD Upgrade Kit ▪ OBD connector for Tech 300SD
469-33001	WRT300PSDSUL1	1 Year Software Update License Certificate (Tech300PSDC)
469-33002	WRT300PSDSUL2	2 Year Software Update License Certificate (Tech300PSDC)
469-33003	WRT300PSDSUL3	3 Year Software Update License Certificate (Tech300PSDC)

BARTEC WHEELRITE TECH 300SD KITS



469-30003
Bartec Wheelrite
Tech 300SD Kit



469-30004
Bartec Wheelrite
Tech 300SD Combo Kit

SENSOR ACTIVATION TOOLS (CONT'D.)

E. Toyota Loop Reset Tool

- Resets TPMS warning light when stuck in loop
- Plugs into OBD II connection and hold button
- No pin jumping required with the WRTRST50
- Accurate and fast

Ascot No.	Mfg. No.	Description
469-00450	WRTRST50	Toyota Loop Reset Tool



469-00450
Toyota Loop Reset Tool

E

F. TPMS Pad

- Programs EZ-Sensor
- No internet required
- Make Model Year look up
- Connects with a standard USB cable
- No battery required
- Activates and decodes sensors –like a tool
- Ideal for busy repair facilities



NEW ITEM!



469-50001
TPMS Pad

F

Ascot No.	Mfg. No.	Description
469-50001	TPMS Pad	TPMS Pad

G. TPMS Hub

- Application driven
- Centralized point for all things TPMS
- Runs the Programming Pad
- Runs the new updater application
- Optional web connectivity for added function

Ascot No.	Mfg. No.	Description
469-50002	TPMS Hub	TPMS Hub



NEW ITEM!

469-50002
TPMS Hub

G

SENSOR ACTIVATION TOOLS (CONT'D.)




469-05500
ATEQ VT55
OBDII TPMS Tool



469-71991
KTI P.S.T.



469-03200
TPMS
Transmitter
Check Box



469-71985
Nissan
Reset Tool

H. ATEQ VT55 OBDII TPMS Tool

- The only tool which needs updates by software instead of purchasing other tools to comply with future TPM Systems.
- RF range adjustable from 300 to 900 Mhz by software to accommodate future sensors
- Duplicate sensor warning to prevent displaying or writing incorrect information to vehicle ECU
- Visual, audible and physical feedback when VT55 receives sensor information
- Rewrite sensor information directly to TPMS ECU
- USB port to print decoded sensor information and update VT55 with PC
- Large, fluid resistant tool reference guide
- Useful remote keyless entry option to test battery/signal strength
- Test and diagnose all tpm sensors
- Kit includes VT55, protective pouch, USB cable, cd manual and software, power supply, magnet, OBDII connector, reference guide

Ascot No.	Mfg. No.	Description
469-05500	VT550BD	ATEQ VT55 OBDII TPMS Tool

I. KTI P.S.T.

- The KTI P.S.T. allows you to manually select the desired electronic triggering protocol or you may simply activate the tool and allow the "hunting" feature to automatically choose the correct solution.
- These tools are digital and can be upgraded with new pulse modulated protocols as they become available in the future.
- Quick Reference Guide and Application Quick Start Flip Chart included with the KTI 71990A

Ascot No.	Mfg. No.	Description
469-71991	71990A	KTI P.S.T.

J. TPMS Transmitter Check Box

- Identify a difference between gauge and your vehicle dash reading
- Helps eliminate possible transmitter defects or failures before mounting and inflating transmitter on wheel
- An ideal device to ensure quality service
- Designed for use with all styles of direct TPMS transmitters
- Portable and easy to use
- Equipped with a regulator and gauge to ensure proper functionality

Ascot No.	Mfg. No.	Description
469-03200	OCB	TPMS Transmitter Check Box

K. Nissan Reset Tool

- Designed to extinguish the Tire Pressure Warning Light on 2003 & newer Nissan vehicles with TPM Reset Connector

Ascot No.	Mfg. No.	Description
469-71985	71985	Nissan Reset Tool

SENSOR ACTIVATION TOOLS (CONT'D.)

L. Genisys™ Heavy-Duty Standard Deluxe Kit

INCLUDES THE FOLLOWING:

- Genisys™ scan tool
- OBD II Smart Cable
- Automated System Test™
- Heavy-Duty Standard software: USA 2007 Domestic with Pathfinder, Repair-Trac™, Fast Fixes™, USA 2007 Asian, InfoTech 2006, USA 2004 ABS/Air Bag software
- Manuals, adapters, and domestic OBD I vehicle cables (for GM, Ford, Chrysler, Jeep, Saturn)
- Carrying case

Ascot No.	Mfg. No.	Description
351-03860	3860HD	Genisys™ Heavy-Duty Standard Deluxe Kit



351-03860
Slotted Screwdriver
Genisys™ Heavy-Duty Standard Deluxe Kit

M. OTC Tire Pressure Monitor Kit

- Displays sensor data, such as ID and pressure. Sensor activation and data display are dependent upon system type
- Updatable via serial cable to PC to keep up with changing vehicle requirements
- Maintains “last vehicle” use history
- Three “C” batteries provide hours of continuous use (Auto shutdown is after three minutes of inactivity)

Ascot No.	Mfg. No.	Description
496-03833	3833	OTC Tire Pressure Monitor Kit



496-03833
OTC Tire Pressure Monitor Kit

N. OTC TPR

- Works on all known TPMS sensors
- Bright graphic display and simple navigation buttons enable vehicle selection for fast activation
- Automatically adjusts activation output power to eliminate cross activation of near sensors
- Easily updated with a wireless connection to the Genisys™ scan tool when new software is installed on the Genisys™
- Compatible with the entire Genisys™ family of scan tools
- Register new sensor ID's on Asian vehicles
- Use the TPR to activate and decode sensor ID's and transmit them to the Genisys™ wirelessly
- Bluetooth wireless communication adapter included
- Quick reference reset procedures can be quickly accessed on the Genisys™

Ascot No.	Mfg. No.	Description
469-03866	3866-TPR	OTC TPR



469-03866
OTC TPR



461-33000
EZ-Sensor 315 MHz
Programmable
TPMS Sensor



A

461-33100
EZ-Sensor 433 MHz
Programmable TPMS Sensor



B

469-34000
Replacement
Aluminum
Valve Stem



C

469-20008
Replacement
Snap-In Valve for
Schrader 20153
Transmitter



D

Bartec
EZ-Sensor
Starter Kits



UNIVERSAL TPMS TRANSMITTERS: EZ-SENSORS

A. EZ-Sensor Programmable TPMS Sensors

- Designed to eliminate multiple sensors required for TPMS work
- Covers most GM, Chrysler, Honda, Nissan, Toyota, Lexus, Scion, Ford, Lincoln, & Mercury vehicles and some Mitsubishi, Subaru & Suzuki vehicles
- Fully programmable
- Compatible with Bartec, Schrader and SPX/OTC programming tools
- Replacement aluminum valve stem available separately—469-34000

Ascot No.	Mfg. No.	Description
461-33000	33000	EZ-Sensor 315 MHz Programmable TPMS Sensor
461-33100	33100	EZ-Sensor 433 MHz Programmable TPMS Sensor

B. Replacement Aluminum Valve Stem

Ascot No.	Mfg. No.	Description
469-34000	34000	Replacement Aluminum Valve Stem

C. Replacement Snap-In Valve for Schrader Snap-In Transmitters

- Rubber stem & attaching screw for Schrader 20153 snap-in transmitter
- Cap & core included
- Requires T-10 Torx Tool for assembly/disassembly

Ascot No.	Mfg. No.	Description	Qty./Box
469-20008	20008	Replacement Snap-In Valve for Schrader 20153 Transmitter	50

D. Bartec EZ-Sensor Starter Kits

- Designed to provide all of the necessary startup information for EZ-Sensor users

Ascot No.	Mfg. No.	Description
469-40010	WRTEZS-STK10	Bartec EZ-Sensor Starter Kit The starter kit comes complete with the following tools: <ul style="list-style-type: none"> ▪ Training DVD ▪ Application Chart ▪ User Guide ▪ Quick Start Guide ▪ Programming Fixture
469-40015	WRTEZS-STK15	Bartec EZ-Sensor Starter Kit - 2 EZ-Sensors and 2 Aluminum Stems The starter kit comes complete with the following tools: <ul style="list-style-type: none"> ▪ Training DVD ▪ Application Chart ▪ User Guide ▪ Quick Start Guide ▪ Programming Fixture ▪ EZ-Sensor Activation Certificate ▪ 2 EZ-Sensors and 2 Aluminum Replacement Stems Included
469-40020	WRTEZS-STK20	Bartec EZ-Sensor Starter Kit - 4 EZ-Sensors and 4 Aluminum Stems The starter kit comes complete with the following tools: <ul style="list-style-type: none"> ▪ Training DVD ▪ Application Chart ▪ User Guide ▪ Quick Start Guide ▪ Programming Fixture ▪ EZ-Sensor Activation Certificate ▪ 4 EZ-Sensors and 4 Aluminum Replacement Stems Included

UNIVERSAL TPMS TRANSMITTERS: REDI-SENSORS

REDI-Sensor™

A. REDI-Sensor Universal Transmitter

- Installs right out of the box
- No programming required
- Reduces replacement sensor inventory
- Adjustable valve stem design
- Fits most Ford, GM, Chrysler, Mazda, Suzuki, and Mitsubishi vehicles
- No additional training necessary

WORKS WITH EXISTING MAJOR TPMS SCAN TOOLS:

If a shop has the tools to handle OE sensors, it's ready for REDI-Sensor. Unlike other sensors that require the purchase of specialized tools and software upgrades, no additional purchases, training or investments are needed with REDI-Sensor.

It works with all major TPMS scan tools, including ATEQ, Bartec, OTC and T.I.P.S. With REDI-Sensor, technicians can use the OE scan tool procedures for TPMS service - no new service routines are required.



A small sampling of existing major TPMS scan tools that are compatible with the REDI-Sensor Universal Transmitter.

FASTER HUNT MODE:

REDI-Sensor saves valuable time during the vehicle relearn process, when using trigger tools that incorporate a hunt mode.

REDI-Sensor uses an "intelligent design" to wake faster and deliver positive results sooner. This prevents the relearn process from timing out, which eliminates the need to redo the procedure.

BUILT TO DELIVER LONG-LIFE RELIABILITY:



469-07011
REDI-Sensor Universal
Transmitter, Snap-In Style




469-07001; 469-07004
REDI-Sensor Universal
Transmitter, Clamp-In Style

Ascot No.	Mfg. No.	Description
469-07001	7001	315MHz REDI-Sensor Universal Transmitter - Clamp-In Style
469-07004	7004	433MHz REDI-Sensor Universal Transmitter - Clamp-In Style
469-07011	7001-R	315MHz REDI-Sensor Universal Transmitter - Snap-In Style

REDI-Sensor™

469-00772
REDI-Sensor
Replacement
Valve Stem w/
all Components



REDI-SENSOR VALVE STEMS

469-00771
REDI-Sensor
Valve with Black
Anodized Nut &
Black Cap



469-00770
REDI-Sensor
Valve Stem with
Cap and Core
Assembled



469-00925
Dill Aluminum
Replacement
TPMS Stem



469-07000
TPMS Kit for
REDI-Sensor



RUBBER SNAP-IN REPLACEMENT VALVES

469-00950
Rubber Snap-In
Repl. Valve for GM
& Ford Transmitters



469-09305
TPMS Snap-In
Valve Chrome
Sleeve & Cap Kit



UNIVERSAL TPMS TRANSMITTERS: REDI-SENSOR ACCESSORIES

B. REDI-Sensor Valve Stems

Ascot No.	Mfg. No.	Description
469-00770	VS-70	REDI-Sensor Replacement Valve Stem w/ All Components
469-00771	VS-70B	REDI-Sensor Valve with Black Anodized Nut and Black Cap
469-00772	VS-70S	REDI-Sensor Valve Stem with Cap and Core Assembled

C. Dill Aluminum Replacement TPMS Stem

- Metal Replacement Clamp-In Valve for GM, Ford, Dodge Ram, Subaru & Suzuki
- Made from anodized aluminum
- T-10 screw included
- Packaged 20 per box

Ascot No.	Mfg. No.	Description
469-00925	VS-925A	Dill Aluminum Replacement TPMS Stem

D. TPMS Kit for REDI-Sensor

Ascot No.	Mfg. No.	Description	Qty./Box
469-07000	7000K	TPMS Kit for REDI-Sensor	25

E. Rubber TPMS Snap-In Replacement Valves

- Rubber stem & attaching screw for Schrader 20153 snap-in transmitter
- Cap & core included
- Requires T-10 Torx Tool for assembly/disassembly

Ascot No.	Mfg. No.	Description	Qty./Box
469-09305	950SC-4	TPMS Snap-In Valve Chrome Sleeve & Cap Kit – 4-Pack	4
469-00950	VS-950	Rubber Snap-In Replacement Valve for GM & Ford Transmitters	25



SCHRADER TPMS TRANSMITTERS

A. Schrader TPMS Transmitters

- Includes transmitter, grommet, nut, cap & core



A

Ascot No.	Mfg. No.	O.E. No.	Description
461-20153	20153	15254101	GM Snap-In Type Repl. Transmitter - Complete Unit
461-20315	20315	9L3Z 1A189A	Ford 2009-10 Snap-In Transmitter
461-28461	28461	56029319AC	Chrysler DCA Snap-In Repl. Transmitter (Replaces 28154)
461-28204	28204	40700-JA01B	Nissan Repl. Transmitter
461-20158	20158	15268606	GM 2006 Repl. Transmitter
461-28155	28155	56029359AB	2009 Jeep Repl. Transmitter
461-28203	28203	28103AG01A	Subaru Snap-In Repl. Transmitter
461-20161	20161	40700CK001	Nissan Repl. Transmitter For Vehicles With Alloy Wheels
461-20107	20107	15114379	GM Large Truck Repl. Transmitter
461-28214	28214	0025408017	Mercedes Gen Alpha WALA Repl. Transmitter
461-20115	20115	15136883	GM 2004 Large SUV Repl. Transmitter
461-28981	28981	06421 S3V A02	Honda/Acura Repl. Transmitter
461-20096	20096	4L2T-1A150-BA	Ford Small Truck Repl. Transmitter
461-20028	20028	52088990AC	Chrysler Repl. Transmitter
461-20064	20064	40700CD001	Nissan Repl. Transmitter
461-20081	20081	28103AG00A	Subaru Repl. Transmitter
461-20131	20131	15122618	Hummer Repl. Transmitter
461-20116	20116	8257740060	GM Small Truck Repl. Transmitter
461-20117	20117	25773946	GM Cadillac & Corvette Repl. Transmitter
461-20069	20069	40700CK002	Nissan Repl. Transmitter For Vehicles With Steel Wheels
461-20087	20087	4313054J20	Suzuki Repl. Transmitter
461-20076	20076	25758220	GM 2006 Cadillac & Corvette Repl. Transmitter
461-28983	28983	529331F000	Hyundai Repl. Transmitter
461-20135	20135	5L1Z1A150AA	Ford Large Truck Repl. Transmitter
461-20156	20156	86517000	Volvo Repl. Transmitter
461-20335	20335	5127335AD	Chrysler Siemens Repl. Transmitter
461-20034	20034	MN103081	Mitsubishi Repl. Transmitter
461-28167	28167	40700JA01A	Nissan Repl. Transmitter
461-28006	28006	10438853	97-00 Corvette Repl. Transmitter
461-28078	28078	13172567	Saab Repl. Transmitter
461-28291	28291	56029400AB	2009 Chrysler Rep. Transmitter
461-28982	28982	06451 S3V A01	Honda Repl. Transmitter
461-28670	28670	426070C050	Toyota Repl. Transmitter
461-28720	28720	42753SNA83	2009 Honda Repl. Transmitter
461-28380	28380	42607AD010	Toyota Repl. Transmitter
461-28345	28345	4260735010	Lexus & Toyota Rep. Transmitter
461-28360	28360	4260706011	Toyota Repl. Transmitter
461-28210	28210	40700JK00B	Infiniti Repl. Transmitter
461-28305	28305	4260702C20	Toyota Repl. Transmitter
461-28310	28310	4260724010	Lexus Repl. Transmitter
461-28395	28395	8C2Z1A189A	Ford Banded Repl. Transmitter
461-28370	28370	4260733021	Lexus & Toyota Rep. Transmitter
461-28849	28849	529332F000	Hyundai/Kia Repl. Transmitter

Ascot No.	Mfg. No.	O.E. No.	Description
461-28129	28129	4250A030	Mitsubishi Repl. Transmitter
461-20077	20077	4D0907275C	Audi, Bentley, Ferrari, MB, Porsche, VW Repl. Transmitter Only
461-20078	20078	4F0907275B	Audi, Bentley, Porsche, VW Repl. Transmitter Only
461-20079	20079	4D0907275A	Audi, BMW, Mercedes, Porsche, VW Repl. Transmitter Only
461-20080	20080	36118378682	BMW Repl. Transmitter
461-20082	20082	4313086Z20	Daewoo Repl. Transmitter
461-20083	20083	36236781847	BMW, Mini, Porsche, Rolls Royce Repl. Transmitter Only
461-20084	20084	224551	Ferrari, Porsche, VW Repl. Transmitter Only
461-20085	20085	52933-4D200	Hyundai, Kia Beru Repl. Transmitter Only
461-20086	20086	52933-2G200	Hyundai, Kia Beru Repl. Transmitter Only
461-20088	20088	1K0907253D	Audi, VW Repl. Transmitter
461-20089	20089	68038945AA	Dodge Sprinter 2007-2009 Repl. Transmitter
461-20090	20090	XR855950	Jaguar, Land Rover Repl. Transmitter
461-20091	20091	LR018860	Jaguar, Land Rover Repl. Transmitter
461-20092	20092	529332M000	Kia Repl. Transmitter
461-20093	20093	GN3A-37-140B	Mazda Repl. Transmitter
461-20094	20094	0025408017	Mercedes Repl. Transmitter
461-20095	20095	0025408017	Mercedes Repl. Transmitter
461-20097	20097	31280297	Volvo Repl. Transmitter
461-20098	20098	42753-STK-A04	Acura, Honda Repl. Transmitter
461-20099	20099	42753-SWA-316	Honda Repl. Transmitter
461-20100	20100	42753-TP6-A82	Honda 2010 Crosstour Repl. Transmitter
461-20103	20103	4F0-907-275D	Beru Transmitter Only
461-20159	20159	13227143	Saab Repl. Transmitter
461-20398	20398	56029398AA	Chrysler Snap-In Repl. Transmitter
461-20720	20720	42753 TK4 A01	Acura Repl. Transmitter
461-28004	28004	4815132AB	Chrysler Prowler Repl. Transmitter
461-28081	28081	36106790054	BMW Repl. Transmitter Only
461-28082	28082	36146752128	BMW, Land Rover Repl. Transmitter Only
461-28087	28087	99760602120	Porsche Repl. Transmitter Only
461-28096	28096	4250A225	Mitsubishi Repl. Transmitter
461-28206	28206	12768826	GM Snap-In Repl. Transmitter - Complete Unit
461-28300	28300	426070C010	Toyota Repl. Transmitter
461-28308	28308	56053036AA	Chrysler Snap-In Repl. Transmitter
461-28315	28315	4260724020	Lexus Repl. Transmitter
461-28320	28320	4260724030	Lexus Repl. Transmitter
461-28325	28325	426724040	Lexus Repl. Transmitter
461-28335	28335	426724040	Lexus & Toyota Rep. Transmitter
461-28355	28355	42607AD020	Toyota Repl. Transmitter
461-28365	28365	4260733011	Lexus, Scion, Toyota Rep. Transmitter



DILL TPMS TRANSMITTERS



B. Dill TPMS Transmitters

- Includes transmitter, grommet, nut, cap & core

Ascot No.	Mfg. No.	O.E. No.	Description
461-01204	1204A	42607-33021	Aftermarket Pacific/Toyota Repl. Transmitter
461-01051	1051	4250A225	Siemens Chrysler Repl. Transmitter
461-01048	1048	6F2Z1Z189A	Lear Ford Banded Repl. Transmitter
461-01043	1043	68001698AA	Siemens 2008 Chrysler Repl. Transmitter
461-01056	1056	GN3A-37-140B	Siemens Mazda Repl. Transmitter
461-01052	1052	Check VIN	Siemens 2004 Chrysler Repl. Transmitter
461-01208	1208	42753-SWA-316	Honda Accord/CRV/Fit Repl. Transmitter
461-01053	1053	Check VIN	Siemens Volkswagen Repl. Transmitter
461-01209	1209	42753-STK-A04	Honda Pilot/Some Acura Repl. Transmitter
461-11206	1206A	42607-0C050	Aftermarket Pacific/Toyota Repl. Transmitter
461-01057	1057	06421-S3V-A02	Entire Acura/Honda Repl. Transmitter
461-01058	1058	0642SCVA00	Entire Hyundai/Kia Repl. Transmitter
461-01044	1044	30666931, 6G92-1A159-BB	2007-2008 Volvo Repl. Transmitter
461-01212	1212	42753-SNA-A83	Honda Civic Repl. Transmitter
461-01028	1028	529334D200	Lear Hyundai/Kia Repl. Transmitter
461-01029	1029	529332F000	Entire Kia Spectra/Rio Repl. Transmitter
461-01047	1047	10394110	Siemens 2007-2008 Clamp-In Repl. Transmitter
461-09007	9007	4F0907275	Beru RDE 007 Repl. Transmitter for Audi A6 - 433 MHz
461-01027	1027	36236779490	Lear BMW Repl. Transmitter
461-09002	9002	36118378682	Beru RDE 002 Repl. Transmitter for BMW 3/5/7 Series - 433 MHz
461-11048	1048HP	8C2Z1A189A	Lear High Pressure Ford Banded Repl. Transmitter
461-01054	1054	Check VIN	Siemens Mercedes Repl. Transmitter
461-01055	1055	Check VIN	Siemens Land Rover/Jaguar Repl. Transmitter
461-09001	9001	A0008223306	Beru RDE 003 Repl. Transmitter for Audi/Mercedes - 433MHz

Ascot No.	Mfg. No.	O.E. No.	Description
461-01059	1059	06421S9VA01	Entire Honda Repl. Transmitter
461-09003	9003	36146752128	Beru RDE 003 Repl. Transmitter for BMW X5/Land Rover - 433MHz
461-01068	1068	59233-2G200	Hyundai/Kia Repl. Transmitter
461-01203	1203	42607-0C010/ AD010	Toyota Repl. Transmitter
461-01216	1216	40700-1LA0A, 40700-1LA0B, 40700-1LA0C	Nissan Repl. Transmitter
461-09004	9004	A0008223406	Beru RDE 004 Repl. Transmitter for Mercedes
461-01041	1041	Check VIN	Volkswagen Repl. Transmitter w/ O-Ring Nut
461-01046	1046	Check VIN	Siemens Land Rover/Jaguar Repl. Transmitter - 433 MHz
461-01049	1049	Check VIN	Siemens Mercedes Repl. Transmitter - 433 MHz
461-01214	1214	42753-TK4-A01	Honda/Acura Repl. Transmitter
461-09012	9012	3610679 054	2010 BMW, Mini Cooper Repl. Transmitter
461-01042	1042	68006771AA	Dodge Sprinter Repl. Transmitter
461-01205	1205	42607-35010	Toyota Older 4Runner, Lexus GX-470 Repl. Transmitter
461-08004	8004	4815132AB, 4815132	Chrysler/Dodge/Jeep Repl. Transmitter
461-08006	8006	10438853	1997-2000 Corvette Repl. Transmitter
461-09005	9005	7L0907272	Beru RDE 005 Repl. Transmitter for Cayenne/Touareg - 433 MHz
461-09011	9011	4F0907275D	2010 Audi Repl. Transmitter
461-05507	5507	52933-2M000, 52933-2L500, 52933-2L700	Hyundai/Kia Repl. Transmitter
461-05511	5511	42753-TP6-A82, 42753-TP6-A82-M1	Honda/Acura Repl. Transmitter
461-09008	9008	997 606 021 20	Porsche 911 Repl. Transmitter

C. Beru TPMS Transmitters

- Valve insert & transmitter sold separately
- Two-piece design to adapt to rim configurations



For use with most European vehicles equipped with TPMS. Call for application information.

Ascot No.	Mfg. No.	Description
461-10001	RDE001	Audi, MB Replacement Transmitter
461-10002	RDE002	BMW Replacement Transmitter
461-10003	RDE003	Land Rover Replacement Transmitter

Ascot No.	Mfg. No.	Description
461-10005	RDE005	Select Porsche & VW Transmitter
461-10007	RDE007	Audi A4 Replacement Transmitter



ACCESSORIES & KITS

A. Schrader Accessory Kits

- The OEM requires that the four sealing components be replaced when re-installing a TPMS sensor. The replacement components are supplied in TPMS accessory kits, which are sensor specific.
- Each TPMS accessory kit contains: 1 Nut, 1 Valve Core, 1 Cap, 1 Grommet

Ascot No.	Mfg. No.	Description	Qty./Box
469-20008	20008	Replacement Snap-In Valve for Schrader 20153 Transmitter	50
469-20020	20020	Replacement Stem for Chrysler, Dodge, and Jeep Replacement Transmitters	25
469-20018	20018	Replacement Snap-In Valve for Schrader 20315 Ford Trans.	50
469-20030	20030	Accessory Kit for Chrysler/Siemens Transmitters	50
469-20032	20032	Accessory Kit for Toyota/Pacific Transmitters	50
469-20004	20004	TPMS Accessory Kit For GM Transmitters	50
469-20013	20013	Accessory Kit for Dodge Nitro Transmitters	50
469-20003	20003	TPMS Accessory Kit For Chrysler Transmitters	50
469-20036	20036	Accessory Kit for TRW Short Valve Transmitters	25
469-20014	20014	Accessory Kit for Nissan Transmitters	50
469-20007	20007	TPMS Accessory Kit For Alloy Wheel Nissan Transmitters	50
469-20031	20031	Accessory Kit for Pacific Transmitters	50
469-20002	20002	TPMS Accessory Kit For Ford Transmitters	50
469-20006	20006	TPMS Accessory Kit For Hummer Transmitters	50
469-20012	20012	Accessory Kit for Corvette Replacment Transmitter	50
469-20019	20019	Accessory Kit for 20019 Honda Replacement Transmitter	50
469-20005	20005	TPMS Accessory Kit For Steel Wheel Nissan Transmitters	50
469-20015	20015	Accessory Kit for GM/TRW Transmitters	50
469-20017	20017	Accessory Kit for Volkswagen/Siemens Transmitters	50
469-20016	20016	Accessory Kit for Mercedes Transmitters	50
469-20010	20010	Accessory Kit for Prowler Replacment Transmitter	50
469-20011	20011	Accessory Kit for Subaru Replacment Transmitter	50
469-20009	20009	Accessory Kit for Suzuki Replacment Transmitter	50
469-20021	20021	Accessory Kit for TRW Transmitters - No Valve	50
469-20022	20022	Accessory Kit for Hyundai, Kia Transmitters	50
469-20023	20023	Accessory Kit for Beru Transmitters - No Valve	50
469-20035	20035	Accessory Kit for TRW Long Valve Transmitters	25

SCHRADER TPMS ACCESSORY KITS



469-20020 Replacement Stem for Chrysler, Dodge & Jeep Replacement Transmitters



469-20097 Small Assortment Kit

B. Schrader Accessory Kit Assortments

- Contains all the parts you will need when servicing tires and wheels that are equipped with Schrader Original Equipment pressure monitoring transmitter valves. All components are individually packaged for easy identification by vehicle application and are stored in a handy plastic box.

Ascot No.	Mfg. No.	Description
469-20097	20097	Small Assortment Kit - 30 Bags (5 ea) Accessory Kits for Each Transmitter Size, 25 Plastic Valve Caps and Core Tool
469-20597	20597	TPMS Master Accessory Kit Assortment - Includes 8 Each of Accessory Kits 20002-20007, 20030-20031, 4 Each of Accessory Kits 20035 & 20036, 100 Cores and 25 Plastic Caps



469-20597 Master Accessory Kit Assortment

ACCESSORIES & KITS (CONT'D.)

C. Dill TPMS Accessory Kits

Ascot No.	Mfg. No.	Description	Qty./Box
469-01100	1100K	Compatible with Pacific Transmitters for Toyota/Lexus	25
469-01050	1050K	Siemens Kit for Chrysler	25
469-00950	VS-950	Rubber Snap-In Replacement Valve for GM & Ford Transmitters	25
469-01080	1080K	Compatible with Schrader 20003/20007/20117AK/20028AK	25
469-20025	2000K	Compatible with Entire Transmitters	25
469-01070	1070K	Compatible with Schrader 20004/20116AK/20115AK/20107AK	25
469-02040	2040K	Kit for Honda Civic	25
469-20030	2030K	Compatible with Schrader Transmitters for Chrysler, Dodge	25
469-01110	1110K	Compatible with Pacific Transmitters for Toyota	25
469-01060	1060K	Compatible with Schrader 20001/20002/20135AK/20096AK	25
469-01090	1090K	Compatible with Beru Transmitters	25
469-07000	7000K	TPMS Kit for Redi-Sensor	25
469-90660	9066-K	Chrysler TPMS Replacement Stem – Complete Kit	1
469-90661	9066-1	Chrysler TPMS Replacement Stem	1
469-01030	1030K	Siemens Kit for Volkswagen (Fits 1053 Transmitter)	25
469-01130	1130K	Compatible with Schrader 20005	25
469-20110	2010K	Compatible with Schrader Transmitters for Volvo	25
469-20120	2020K	Early 2007 GM Kit for Entire Transmitters	25
469-01040	1040K	Siemens Mercedes Assembled Valve	25
469-07020	7020K	2 Pc. Gray Seal and Washer for 2011 Volvo, Hyundai, Kia & Land Rover	25
469-01120	1120K	Compatible with Pacific Transmitters for Lexus	25
469-01031	1031K	Volkswagen Kit for Special Wheel Package	25
469-01098	1098K	Dodge Sprinter Replacement Valve	25
469-41010	VS-1010	TPMS Snap-In Valves for Hyundai Santa Fe	4
469-09305	950SC-4	Chrome Sleeves for VS-950 Rubber Snap-In Valve	4
469-00770	VS-70	Redi-Sensor Replacement Valve Stem w/ All Components	20
469-00771	VS-70B	Redi-Sensor Valve w/ Black Anodized Nut & Black Cap	20
469-00772	VS-70S	Redi-Sensor Valve Stem with Cap & Core Assembled	20
469-00925	VS-925A	Aluminum Metal Replacement Valve for GM Snap-In	20
469-01925	VS-925B	Black Nut/Black Cap Metal Replacement Valve for GM & Ford	20
469-02925	VS-925C	Chrome Plated Replacement Valve for GM & Ford Snap-Ins	20

DILL TPMS ACCESSORY KITS

D. Complete Dill Universal Sensor Package

- 12 Universal Sensors
- 128 Assorted Service Kits
- TPMS Tool Kit - 8100

Ascot No.	Mfg. No.	Description
469-11215	1215	Complete Dill Universal Sensor Package

469-11215
Complete Dill Universal
Sensor Package

ACCESSORIES & KITS (CONT'D.)

E. Dill TPMS Master Accessory Assortment

- Contains 76 kits, 3 tools, 20 cores, 20 caps and 4 chrome sleeves
- Tools included are a Torque Screwdriver, a Fishing Tool and a 4-way TPMS tool

Kit Number	Quantity	Kit Number	Quantity
1030K	4	2000K	6
1050K	6	2010K	4
1060K	6	2020K	4
1070K	6	2030K	4
1080K	6	2040K	4
1090K	4	VS-950	6
1100K	6	1 Pack Valve Caps	20 per pack
1110K	6	1 Pack Valve Cores	20 per pack
1130K	6	Chrome Sleeves	4



469-07100
Dill TPMS Master
Accessory Assortment

Ascot No.	Mfg. No.	Description
469-07100	7100	Dill TPMS Master Accessory Assortment

F. Schrader TPMS Valve Caps

Ascot No.	Mfg. No.	Description	Qty./Box
468-00050	20395	Plastic Valve Caps	100
468-20495	20495	Aluminum Valve Caps	100
468-20595	20595	Black TPMS Plastic Sealing Valve Caps for Snap-In Transmitters	100
468-20695	20695	Green TPMS Plastic Sealing Valve Caps for Snap-In Transmitters	100
468-59019	59-0019	Green Nitrogen Indicating Aluminum Valve Cap (100 per bag)	100
468-59021	59-0021	Chrome-Plated Brass Valve Caps	100
468-59023	59-0023	Universal Nitrogen Caps	100



VALVE CAPS

G. Rubber TPMS Snap-In Replacement Valves

- Rubber stem & attaching screw for Schrader 20153 snap-in transmitter
- Cap & core included
- Requires T-10 Torx Tool for assembly/disassembly

Ascot No.	Mfg. No.	Description	Qty./Box
469-00950	VS-950	Rubber Snap-In Replacement Valve for GM & Ford Transmitters	25
469-09305	950SC-4	TPMS Snap-In Valve Chrome Sleeve & Cap Kit	4
469-20008	20008	Replacement Snap-In Valve for Schrader 20153 Transmitter	50
469-20018	20018	Replacement snap-in valve for Schrader Ford 20315 transmitter	50

RUBBER TPMS SNAP-IN REPLACEMENT VALVES

469-20008
Replacement
Snap-In Valve for
Schrader 20153
Transmitter

469-09305
TPMS Snap-In
Valve Chrome
Sleeve & Cap Kit



E

F

G

TOOLS & TOOL KITS

A

468-20055
Electroless
Nickel Plated
Valve Cores



A. Schrader TPMS Valve Core

- Electroless Nickel-Plated valve core
- All valve caps packaged 100/box

Ascot No.	Mfg. No.	Description
468-20055	20055	Schrader TPMS Valve Core

B

TPMS VALVE INSERTS

461-59357

461-59387

461-59307

461-59337



B. Beru TPMS Valve Inserts

- Original equipment valve insert for the Beru Tire Safety System
- Each Insert comes complete with cap, core, grommet & grommet nut
- Colored bottom to differentiate inserts
- Applications - Audi, Bentley, BMW, Ferrari, Land Rover, Maserati, Maybach, Mercedes-Benz, Porsche, Volkswagen
- Requires TX-20EZ torx tool for assembly/disassembly

Ascot No.	Mfg. No.	Description
461-59307	59.0342	Green Insert
461-59337	59.0340	Silver Insert
461-59357	59.0346	Orange Insert
461-59387	59.0344	Black Insert
469-02020	TX-20EZ	Torx Screwdriver

C


468-01001
Electroless
Nickel Plated
Valve Core



468-06300
Plastic TPMS
Valve Cap

468-00635
Plastic Cap for
VS-930 TPMS
Snap-In Valve

468-00650
Small Plastic
TPMS Valve Cap



C. Dill TPMS Valve Caps & Cores

- All valve caps and cores packaged 100/box

Ascot No.	Mfg. No.	Description	Qty./Box
468-01001	100-TP	Electroless Nickel Plated Valve Core	100
468-06300	630N	Plastic TPMS Valve Cap	100
468-00635	635	Plastic Cap for VS-930 TPMS Snap-In Valve	100
468-00650	650	Small Plastic TPMS Valve Cap	100
468-00680	680	N2 Aluminum cap for TPMS	100
468-00690	690	N2 Plastic cap for TPMS	100

D

TPMS TORQUE WRENCHES & SOCKETS

D. TPMS Torque Wrenches and Sockets

- Perfect for tightening grommet nut to manufacturer specifications
- Periodic calibration recommended



Ascot No.	Mfg. No.	Description
168-01501	1501MRMH	1/4" Drive 20-150 In./Lbs. Torque Wrench
167-12110	1211D	1/4" Drive x 11mm x 12 mm Chrome Flip Socket
169-01002	1002E	1/4" Drive x 2" Chrome Extension
168-72100	72100	3/8" Drive, 20 - 200 In./Lbs.
168-72120	72120	3/8" Drive, 25 - 250 In./Lbs.
162-27211	27211	3/8" Drive x 11mm Socket
162-27212	27212	3/8" Drive x 12mm Socket

TOOLS & TOOL KITS (CONT'D.)

E. Valve Core Torque Tool

- Preset torque guarantees correct setting every time on all cores!
- Calibrated to 4 in.-lbs. of torque
- Meets the Tire & Rim Association (TRA) specifications for installing valve cores on TPMS applications
- Can be used to install and remove cores in standard valves

Ascot No.	Mfg. No.	Description
469-00044	TPMS-4VC	Valve Core Torque Tool


F. T-10 Torque Tools

- Installs replacement snap-in valve to Schrader 20153/20315 transmitter
- Preset to 12 in.-lbs. (1.3 nM)

Ascot No.	Mfg. No.	Description
469-20140	20140	T-10 Torque Tool
469-05415	5415	T-10 Torque Tool w/ Replaceable Tip
469-54151	5415-1	Replacement T-10 Tip

G. Tire Deflator Set for TPMS Valve Stems

- Simply replace a standard sized valve cap with this handy tool and the special design will depress the pin in the valve core.
- Large openings on the sides of the tool allow air to escape quickly from the tire.
- Tools are marked so tires can be returned to their original position on the vehicle so TPMS will not need to be reset.
- Also saves time since the valve core has not been removed from the sensor
- Set of 4



469-19860
Tire Deflator Set for
TPMS Valve Stems

Ascot No.	Mfg. No.	Description
469-19860	19860	Tire Deflator Set for TPMS Valve Stems

H. Tire Deflator/Valve Core Remover

- Screws on TPMS valve stems to deflate the tire without removing the valve core

Ascot No.	Mfg. No.	Description
469-00021	TL-615	Tire Deflator/Valve Core Remover



469-00021
Tire Deflator/
Valve Core
Remover

I. Valve Core Tools - Screwdriver Type & Standard Bore Long Valve

- Has a plastic screwdriver handle for better grip and leverage

Ascot No.	Mfg. No.	Description
469-00607	TL-615	Screwdriver Type Valve Core Tool
469-00612	612	Standard Bore Long Valve Core Tool



469-00612
Standard Bore
Long Valve
Core Tool



469-00044
Valve Core
Torque Tool



469-05415
T-10 Torque Tool
with ReplaceableTip



469-20140
T-10 Torque Tool

E

F

G

H

I

TOOLS & TOOL KITS (CONT'D.)

J

168-38325
Electronic TPMS
Torque Wrench



J. Electronic TPMS Torque Wrench

- Range 12–120 in.-lbs.
Accuracy \pm 2%.
- Green light for power on, red light and buzzer for reaching target signal, red flash for overload signal.
- Torque set quickly with unique slide bar on the scale.
- Rotate to 90° position to torque and leverage.
- Indexing head allows for use straight (screwdriver position) to spin nut down quickly.
- Torque limit LED flashes with audible beep.
- Power switch with LED indicator.
- Uses coin style batteries.
- Approximately 8.5" long

Ascot No.	Mfg. No.	Description
168-38325	3833-25	Electronic TPMS Torque Wrench

K

469-89111
3-Way TPMS Tool



K. 3-Way TPMS Tool

Ascot No.	Mfg. No.	Description
469-89111	8911-10	3-Way TPMS Tool

L

469-20144
Grommet
Installation/
Removal Tool



L. Grommet Installation/Removal Tool

Ascot No.	Mfg. No.	Description
469-20144	20144	Grommet Installation/Removal Tool

M

319-72521
1/4" Socket Driver



M. 1/4" Socket Driver

- Made in the USA. 6" Overall Length, 2-1/2" Shank Length
- Durable screwdriver handle and a chrome vanadium shank
- Ideal for use with the TPMS 11mm x 12mm flip socket

Ascot No.	Mfg. No.	Description
319-72521	7252100	1/4" Socket Driver

N

469-20250
Core /Cap
Removal Tool



N. Core/Cap Removal Tool

Ascot No.	Mfg. No.	Description
469-20250	20250	Core/Cap Removal Tool

O

469-08910
TPMS Valve System
Fishing Tool



O. TPMS Valve System Fishing Tool

- Secures TPMS sensor to wheel during demount
- One handle end can be used as a deflator; the other as a core remover
- 3" Overall length

Ascot No.	Mfg. No.	Description
469-08910	08910	TPMS Valve Fishing Tool

TOOLS & TOOL KITS (CONT'D.)

P. Bartec Mechanical Tool Kit

- Valve Core Torque Driver
- T-10 Torque Driver
- T-20 Torque Driver
- 3-Way Fishing Tool
- Grommet Tool
- Torque Wrench
- TPMS Toyota Reset Tool

All fitted in a plastic case

Ascot No.	Mfg. No.	Description
469-10300	WRTMT103	Bartec Mechanical Tool Kit



469-10300
Bartec Mechanical Tool Kit

Q. Dill TPMS Master Tool Kit

- 3/8" Torque Wrench
- 2 Sockets
- Valve Core Torque Tool
- Torque Screwdriver
- 3-way Valve Stem Fishing Tool
- Valve Nut Wrench
- Grommet Seating Tool
- 20 Valve Cores and 20 Valve Caps

Includes all the mechanical tools needed to properly remove and install TPMS sensors

Ascot No.	Mfg. No.	Description
469-08100	8100	Dill TPMS Master Tool Kit



469-08100
Dill TPMS Master Tool Kit

R. Digital Tire Inflator Gauge

- Range: 0-175 PSI
- Accurate to +/- 1.2 psi up to 59 psi; +/- 2.3 psi 59-145 psi; 3.6 psi more than 145 psi
- Covered with rubber sleeve for extra comfort and durability
- One button operation
- 3 in 1 function: inflate, deflate and measure tire pressure
- Long-life battery with low battery warning signal—Extra battery included
- Clip-on chuck with swivel hose to prevent kinking

Ascot No.	Mfg. No.	Description
477-00130	H-30	Digital Tire Inflator Gauge—21" Hose
477-00136	H-30-6	Digital Tire Inflator Gauge—6' Hose <ul style="list-style-type: none"> ▪ 1-Year warranty ▪ Equivalent to Rema H300532P



Digital Tire Inflator Gauge
477-00130 - 21" Hose
477-00136 - 6" Hose


P

Q

R

BANDED TPMS SYSTEMS & ACCESSORIES

A



469-0126
Plastic
Repl.
Clip

469-02723
Cradle with Clip

469-01426
Adjustable Band
for Banded
TPMS Sensors

B



461-01048
Lear Ford
Banded
Transmitter

469-05105
Complete Banded
Transmitter Package

C



461-11048
High Pressure
Ford Banded
Transmitter

469-15105
Ford Complete Banded High
Pressure Sensor Package

D



469-15105
Ford Complete Banded High
Pressure Sensor Package

A. TPMS Band Transmitter Accessories

- TPMS Band is adjustable to accommodate 14" - 26" wheels
- Plastic clip included with TPMS Cradle
- For use on vehicles equipped with banded transmitters

Ascot No.	Mfg. No.	Description
469-01426	TPSTRAP	14" - 26" Adjustable Band for Banded TPMS Sensors
469-02723	TPCRADLE	Cradle with Clip for Banded TPMS Sensors
469-01026	1026	Plastic Replacement Clip for TPMS Replacement Cradle

B. Ford Complete Banded Transmitter Package

- Includes 461-01048 transmitter, 469-02723 cradle/clip & 469-01426 band
- Replacement transmitter for Ford OE #6F2Z1A189A
- Equivalent to Dill part no. 5105
- Fits most popular 2006 - 2008 Ford vehicles

Ascot No.	Mfg. No.	Description
469-05105	5105	Complete Banded Transmitter Package

C. Ford Complete Banded High Pressure Sensor Package

- Includes 461-11048 transmitter w/ cradle and clip & 469-01426 band
- Replacement transmitter for Ford OE # 8C2Z-1A189A
- Equivalent to Dill part no. 5105HP
- Applications: Pre-June Ford F250/350/450 Super Duty Trucks
- Shipped together in a plastic bag

Ascot No.	Mfg. No.	Description
469-15105	5105HP	Ford Complete Banded High Pressure Sensor Package

D. Band Transmitter for Ford

Ascot No.	Mfg. No.	OE Part No.	Description
461-01048	1048	6F2Z1A189A	Lear Ford Banded Transmitter

E. High Pressure Ford Banded Transmitter

Ascot No.	Mfg. No.	OE Part No.	Description
461-11048	1048-HP	8C2Z1A189A	High Pressure Ford Banded Transmitter

F. Dill OEM Replacement Bands

Ascot No.	Mfg. No.	Description
469-19318	1193-18	18" OEM Replacement Band
469-19320	1193-20	20" OEM Replacement Band
469-19322	1193-22	22" OEM Replacement Band

TPMS CABINETS

A. TPMS Cabinet - Stocked and Ready!

THIS FULLY STOCKED CABINET INCLUDES THE FOLLOWING:

- 3 of each Sensors: 20028, 20064, 20069, 20076, 20096, 20107, 20115, 20116, 20117, 20131, 20135, 20158, 20161
- 50 of each Service Packs: 20002, 20003, 20004, 20005, 20006, 20007
- 100 TPMS Electroless Nickel Plated Cores (#20055)
- 100 TPMS Plastic Sealing Caps (#20395)
- 100 TPMS Metal Sealing Caps (#20495)
- Current Mitchell 1 Protocol Manual (#20136)

Ascot No.	Mfg. No.	Description	Dimensions
469-20190	20190	TPMS Cabinet	30.25" x 26.5" x 10"



469-20190
TPMS Cabinet

B. Dill TPMS Cabinets

- Dill cabinets are shipped empty

Ascot No.	Mfg. No.	Description	Dimensions
469-05112	5112	Counter-Top Style TPMS Cabinet	12" x 15" x 3.5"
469-32755	32755	Lockable Medicine Cabinet Style TPMS Cabinet	42" x 35" x 11"
469-32756	32756	Lockable Top TPMS Cabinet	43.5" x 35" x 11"



469-32756
Lockable Top
TPMS Cabinet



469-32755
Lockable Medicine
Cabinet Style
TPMS Cabinet



469-05112
Counter-Top Style
TPMS Cabinet

A

B



TPMS RETROFIT KITS



469-20256
Battery Operated Schrader
TPMS Retrofit Kit



469-20257
Hard-Wired Schrader
TPMS Retrofit Kit

A. Schrader TPMS Retrofit Kits

- For installation on vehicles not equipped with OE TPMS Systems
- Stand-alone kit includes dash mounted display
- Four wheel mounted transmitters and installation instructions

Ascot No.	Mfg. No.	Description
469-20256	20256	Battery Operated
469-20257	20257	Hard-Wired

B. Dill Trailer TPMS System

- Designed to be installed directly into trailer tires
- Provides accurate trailer tire air pressures and temperatures
- A warning will trigger if pressure falls below the set pressure
- Ability to set baseline pressure to desired PSI level
- Valve options for 0.453", 0.625", and 9.7mm rim holes
- Cigarette lighter adapter or hard-wired options



Transmitters



469-01504
Dill Trailer
TPMS System
with Four
Sensors



Ability to set baseline pressure



Valve options for 0.453", 0.625", and 7.7mm rim holes

Ascot No.	Mfg. No.	Description
469-01502	1502-453	Dill Trailer TPMS System With Two Sensors
469-01504	1504-453	Dill Trailer TPMS System With Four Sensors

TRAINING & PROMOTIONAL MATERIALS

A. TPMS Training Package

TRAINING PACKAGE INCLUDES:

- 90 minute, in-depth TPMS Training DVD
- Mitchell TPMS Service Guide
- TPMS Course Book (with test & certification application)
- CD Video Demos of each Bartec TPMS Tool

Ascot No.	Mfg. No.	Description
491-11112	WRTTRKIT3	TPMS Training Package
491-11113	WRTTRKIT4	TPMS Training Package - Spanish Version

B. Schrader TPMS Training DVD

- Available in both English and Spanish versions - call for more details

Ascot No.	Mfg. No.	Description
491-21355	21355	Training DVD - English Version
491-21357	21357	Training DVD - Spanish Version

C. TPMS Countertop Displays

- Three-dimensional countertop display to help educate consumers on TPMS and why these components should be replaced each time the tire is disassembled
- Dummy sensor included as a visual reference
- Display explains in common terms the individual components that are involved in the installation of sensors
- Provides a photograph of the universal "horseshoe" symbol that indicates the existence of TPMS
- Some assembly required
- Packaged 1 display per box

Ascot No.	Mfg. No.	Description
469-61589	61589	TPMS Countertop Display w/ Dummy Transmitter
469-61599	61599	Spanish TPMS Countertop Display w/ Dummy Transmitter

D. TPMS Tri-Fold Consumer Brochure, Brochure Holder

Ascot No.	Mfg. No.	Description
469-22006	469-22006	Schrader TPMS Consumer Brochure
717-00400	W40A	Clear Plastic Brochure Holder

E. Consumer Awareness Counter Mat

Ascot No.	Mfg. No.	Description
469-07011	N/A	Consumer Awareness Counter Mat



491-11112
TPMS Training Package



491-21355
Schrader TPMS Training DVD



TPMS
Countertop
Displays

469-22006
Schrader TPMS
Consumer
Brochure



717-00400
Clear Plastic
Brochure Holder

A

B

C

D

EZ-SENSOR ²⁰¹¹ TPMS APPLICATION GUIDE

VEHICLE APPLICATION COVERAGE: Part No. 33000 & 33100

	Model	Model Year	EZ-Sensor Part #	OE Sensor Part #	
Acura	CSX	2008-11	33000	42753-SNA-A83	
	Allure	2007	33000	15921013	
Buick	Allure	2008	33000	15921013	
	Allure	2009	33000	20923680	
	Allure	2010-11	33000	20923680	
	Enclave	2008	33000	15921013	
	Enclave	2009-11	33000	20923680	
	LaCrosse	2007	33000	15921013	
	LaCrosse	2008	33000	15921013	
	LaCrosse	2009	33000	20923680	
	LaCrosse	2010-11	33000	20923680	
	LeSabre	2007	33000	25799331	
	Lucerne	2007	33000	20923680	
	Lucerne	2008-10	33000	20923680	
	Rainier	2007	33000	25799331	
	Regal	2011	33000	20923680	
	Cadillac	CTS	2008-11	33000	20923680
		DTS	2006	33000	15268606
		DTS	2007-11	33000	20923680
Escalade		2007**	33000	15825475	
Escalade		2007*	33000	20923680	
Escalade		2008-11	33000	20923680	
SRX		2007-09	33000	20923680	
SRX		2010-11	33000	20923680	
STS		2010	33000	20923680	
STS		2011	33000	20923680	
STS		2009**	33000	15268606	
STS	2009*	33000	20923680		
Chevrolet	Avalanche All	2007**	33000	15825475	
	Avalanche All	2007*	33000	20923680	
	Avalanche All	2008-11	33000	20923680	
	Aveo	2007-11	33000	20923680	
	Camaro	2010-11	33000	20923680	
	Cobalt	2008	33000	15921013	
	Cobalt	2010	33000	20923680	
	Cobalt	2009**	33000	15921013	
	Cobalt	2009*	33000	20923680	
	Corvette	2010-11	33000	15268606	
	Cruze	2011	33000	20923680	
	Equinox	2007	33000	15921013	
	Equinox	2008-09	33000	15921013	
	Equinox	2010-11	33000	20923680	
	Express	2008-09	33000	15921013	
	Express	2010-11	33000	20923680	
	HHR	2008	33000	15268606	
	HHR	2009**	33000	15268606	
	HHR	2009*	33000	20923680	
HHR	2010-11	33000	20923680		

	Model	Model Year	EZ-Sensor Part #	OE Sensor Part #	
Chevrolet - Continued	Impala	2006	33000	15268606	
	Impala	2007**	33000	15268606	
	Impala	2007*	33000	20923680	
	Impala	2008-11	33000	20923680	
	Malibu	2009	33000	20923680	
	Malibu	2008**	33000	15921013	
	Malibu	2008*	33000	20923680	
	Malibu	2010-11	33000	20923680	
	Monte Carlo	2006	33000	15268606	
	Monte Carlo	2007**	33000	15268606	
	Monte Carlo	2007*	33000	20923680	
	Silverado All	2007*	33000	20923680	
	Silverado All	2007** (TRW)	33000	15825475	
	Silverado All	2008-11	33000	20923680	
	Suburban All	2007*	33000	20923680	
	Suburban All	2007** (TRW)	33000	15825475	
	Suburban All	2008-11	33000	20923680	
	Tahoe	2007*	33000	20923680	
	Tahoe	2007** (TRW)	33000	15825475	
	Tahoe	2008-11	33000	20923680	
	Traverse	2009-11	33000	20923680	
	Uplander	2008-09	33000	15268606	
	Van	2008-11	33000	15921013	
	Volt	2010-11	33000	20923680	
	Chrysler	300	2005-06	33000	56053030AB-AC
		300	2007 (315)	33000	68001696AA-AB
		300M	2002-04	33100	52088990AC-AD
		Aspen	2007	33000	56053030AB-AC
		Aspen	2008-11	33000	56029465AB
		Concorde	2002-04	33100	52088990AC-AD
Crossfire		2004	33100	52088990AC-AD	
Crossfire		2005-11 (CONTI)	33000	56053030AB-AC	
Crossfire		2005-11 (SCH)	33100	52088990AC-AD	
Intrepid		2002-04	33100	52088990AC-AD	
Pacifica		2003	33100	52088990AC-AD	
Pacifica		2004 (SCH)	33100	52088990AC-AD	
Pacifica		2006-08	33000	68001696AA-AB	
Prowler		2002	33100	52088990AC-AD	
PT Cruiser		2008-10	33000	68001696AA-AB	
Sebring		2007	33000	68001696AA-AB	
Sebring		2010	33000	68001696AA-AB	
Sebring		2008-09 (315)	33000	68001696AA-AB	
Town & Country		2006	33000	56053030AB-AC	
Town & Country		2007	33000	56053030AB-AC	
Town & Country	2002-03	33100	52088990AC-AD		
Town & Country	2008 (315)	33000	68001696AA-AB		
Voyager	2002-03	33100	52088990AC-AD		

* Snap-in
** Clamp-in

† With Chrome Rims
‡ Without Chrome Rims

VEHICLE APPLICATION COVERAGE:
Part No. 33000 & 33100

EZ-SENSOR 2011 TPMS APPLICATION GUIDE

Model	Model Year	EZ-Sensor Part #	OE Sensor Part #		
Dodge	Avenger	2007-11	33000	68001696AA-AB	
	Caliber	2007-11	33000	68001696AA-AB	
	Caravan	2006	33000	56053030AB-AC	
	Caravan	2007	33000	56053030AB-AC	
	Caravan	2002-03	33100	52088990AC-AD	
	Charger	2007	33000	68001696AA-AB	
	Charger	2005-06	33000	56053030AB-AC	
	Dakota	2008-11	33000	56029319AA-AB	
	Durango	2007-08	33000	56053030AB-AC	
	Durango	2009-10	33000	56029465AB	
	Grand Caravan	2006	33000	56053030AB-AC	
	Grand Caravan	2007	33000	56053030AB-AC	
	Grand Caravan	2002-03	33100	52088990AC-AD	
	Intrepid	2002-04	33100	52088990AC-AD	
	Magnum	2007	33000	68001696AA-AB	
	Magnum	2005-06	33000	56053030AB-AC	
	Nitro	2007-08	33000	56053030AB-AC	
	Nitro	2009-11	33000	56029465AB	
	Ram	2008	33000	56029319AA-AB	
	Ram	2009 (315)	33000	56029319AA-AB	
	Sprinter	2007-08	33000	68006771AA	
	Stratus	2007	33000	56053030AB-AC	
	Viper	2003-11	33100	52088990AC-AD	
	Ford	Crown Victoria	2006-08	33000	6F2Z-1A189A
		E-150	2007-09	33000	8C2Z-1A189A
		E-150	2010-11	33000	9L3Z-1A189-A
		E-250	2007-09	33000	8C2Z-1A189A
E-250		2010-11	33000	9L3Z-1A189-A	
E-350 SD		2007-09	33000	8C2Z-1A189A	
E-350 SD		2010-11	33000	9L3Z-1A189-A	
Edge		2011	33000	9L3Z-1A189-A	
Edge		2007-10 [†]	33000	6F2Z-1A189A	
Edge		2007-10 [‡]	33000	7L1Z-1A189A	
Escape		2005-08	33000	6F2Z-1A189A	
Escape		2009-11	33000	9L3Z-1A189-A	
Exp Sport Trac		2006-10	33000	6F2Z-1A189A	
Expedition		2011	33000	9L3Z-1A189-A	
Expedition		2003-04	33100	4L2Z-1A150-BA	
Expedition		2007-10 [†]	33000	6F2Z-1A189A	
Expedition		2007-10 [‡]	33000	7L1Z-1A189A	
Explorer		2011	33000	9L3Z-1A189-A	
Explorer		2002-05	33100	4L2Z-1A150-BA	
Explorer		2006-10	33000	6F2Z-1A189A	
F-150	2007-08	33000	6F2Z-1A189A		
F-150	2009-11	33000	9L3Z-1A189-A		

Model	Model Year	EZ-Sensor Part #	OE Sensor Part #		
Ford - Continued	F-250 SD	2008-09	33000	8C2Z-1A189A	
	F-250 SD	2010-11	33000	9L3Z-1A189-A	
	F-350 SD	2008-09	33000	8C2Z-1A189A	
	F-350 SD	2010-11	33000	9L3Z-1A189-A	
	Fiesta	2011	33000	9L3Z-1A189-A	
	Five Hundred	2006-07	33000	6F2Z-1A189A	
	Flex	2011	33000	9L3Z-1A189-A	
	Flex	2009-10	33000	7L1Z-1A189A	
	Focus	2007	33000	6F2Z-1A189A	
	Focus	2008-09	33000	7L1Z-1A189A	
	Focus	2010-11	33000	9L3Z-1A189-A	
	Freestar	2006-07	33000	6F2Z-1A189A	
	Fusion	2007-09	33000	6F2Z-1A189A	
	Fusion	2010-11	33000	9L3Z-1A189-A	
	Grand Marquis	2007-11	33000	6F2Z-1A189A	
	Mustang	2007-09	33000	6F2Z-1A189A	
	Mustang	2010-11	33000	9L3Z-1A189-A	
	Ranger	2007-11	33000	6F2Z-1A189A	
	Shelby GT500	2012	33000	9L3Z-1A189-A	
	Taurus	2011	33000	9L3Z-1A189-A	
	Taurus	2008-10	33000	7L1Z-1A189A	
	Taurus X	2008-09	33000	7L1Z-1A189A	
	Transit Connect	2010-11	33000	9L3Z-1A189-A	
	GMC	Acadia	2007-08	33000	15921013
		Acadia	2009-11	33000	20923680
		Envoy	2007** (TRW)	33000	15825475
		Envoy	2008-09*	33000	20923680
Savana		2008-09 (CONTI)	33000	15921013	
Savana		2010-11	33000	20923680	
Sierra All		2007*	33000	20923680	
Sierra All		2007** (TRW)	33000	15825475	
Sierra All		2008-11	33000	20923680	
Terrain		2010-11	33000	20923680	
Yukon All		2007*	33000	20923680	
Yukon All		2007** (TRW)	33000	15825475	
Yukon All		2008-11	33000	20923680	
Honda	Accord	2008-11	33000	42753-SWA-316	
	Civic	2008-11	33000	42753-SNA-A83	
	CR-V	2007-11 (Alloy)	33000	42753-SWA-316	
	CR-V	2007-11 (Steel)	33000	42753-SWA-315	
	CR-Z	2011	33000	42753-SNA-A83	
	Element	2009-11	33000	42753-SNA-A83	
	Fit	2008	33000	42753-SWA-316	
	Fit	2009-11	33000	42753-SNA-A83	
	Insight	2010-11	33000	42753-SNA-A83	

* Snap-in † With Chrome Rims
** Clamp-in ‡ Without Chrome Rims

EZ-SENSOR ²⁰¹¹ TPMS APPLICATION GUIDE

■ VEHICLE APPLICATION COVERAGE:
Part No. 33000 & 33100

	Model	Model Year	EZ-Sensor Part #	OE Sensor Part #	
Honda - Cont'd.	Odyssey	2011	33000	42753-SNA-A83	
	Odyssey Tour	2011	33000	42753-SNA-A83	
Hummer	S2000	2008-09	33000	42753-S2A-315	
	H2	2008-09	33000	20923680	
	EX35	2008	33000	40700-CD001	
	EX35	2009-10	33000	40700-JK00B	
	FX35	2003-08	33000	40700-CD001	
	FX35	2009-10	33000	40700-JK00B	
	FX45	2003-08	33000	40700-CD001	
	FX50	2009-10	33000	40700-JK00B	
	G35	2007	33000	40700-JA01B	
	G35	2008	33000	40700-JK00B	
	G35	2003-06	33000	40700-CD001	
	G37	2008-10	33000	40700-JK00B	
	M35	2006-08	33000	40700-CD001	
	M35	2009-10	33000	40700-JA01C	
	M45	2006-08	33000	40700-CD001	
	M45	2009-10	33000	40700-JA01C	
	Q45	2003-06	33000	40700-CD001	
	QX4	2003	33000	40700-CD001	
QX56	2004	33000	40700-CK002		
QX56	2007	33000	40700-CK002		
QX56	2005-06 (Alloy)	33000	40700-CK001		
QX56	2005-06 (Steel)	33000	40700-CK002		
QX56	2008-10	33000	40700-JA01B		
Isuzu	Rodeo	2004	33100	52088990AC-AD	
	Commander	2006	33000	56053030AB-AC	
	Commander	2007	33000	56053036AA	
	Compass	2007-11	33000	68001696AA-AB	
	Grand Cherokee	2007	33000	56053036AA	
	Grand Cherokee	2002-04	33100	52088990AC-AD	
	Grand Cherokee	2005-06	33000	56053030AB-AC	
	Jeep	Liberty	2002-04	33100	52088990AC-AD
		Liberty	2005-06	33000	56053030AB-AC
		Liberty	2007-08	33000	56053030AB-AC
		Liberty	2009 (315)	33000	56029465AB
		Liberty	2010-11	33000	56029465AB
		Patriot	2007-11	33000	68001696AA-AB
		Wrangler	2007-08	33000	56053030AB-AC
		Wrangler	2009*	33000	56029479AA
		Wrangler	2010-11	33000	56029479AA
		CT 200H	2011	33000	42607-33021
	Lexus	ES 350	2007-11	33000	42607-33021
GS 300		2005-11	33000	42607-33021	
GS 350		2007-11	33000	42607-33021	

	Model	Model Year	EZ-Sensor Part #	OE Sensor Part #	
Lexus - Continued	GS 430	2005	33000	42607-30030	
	GS 430	2007	33000	42607-33021	
	GS 430	2006 (Early)	33000	42607-30030	
	GS 430	2006 (Late)	33000	42607-33021	
	GS 450H	2007-11	33000	42607-33021	
	GS 460	2008-11	33000	42607-33021	
	GX 460	2010-11	33000	42607-33021	
	GX 470	2004-05	33000	42607-35010	
	GX 470	2006 (Early)	33000	42607-30030	
	GX 470	2006 (Late)	33000	42607-33021	
	GX 470	2007-09	33000	42607-33021	
	IS 250	2006-11	33000	42607-33021	
	IS 350	2006-11	33000	42607-33021	
	IS C	2006-11	33000	42607-33021	
	IS F	2006-11	33000	42607-33021	
	LS 460	2007-11	33000	42607-33021	
	LS 600H	2008-11	33000	42607-33021	
	LX 470	2006-07	33000	42607-33021	
	LX 570	2008-11	33000	42607-33021	
	RX 330	2006	33000	42607-33021	
	RX 350	2007-11	33000	42607-33021	
	RX 400H	2007-11	33000	42607-33021	
	Lincoln	Aviator	2003-05	33100	4L2Z-1A150-BA
		Mark LT	2009	33000	9L3Z-1A189-A
Mark LT		2007-08	33000	6F2Z-1A189A	
MKS		2011	33000	9L3Z-1A189-A	
MKS		2009-10	33000	7L1Z-1A189A	
MKT		2010	33000	7L1Z-1A189A	
MKT		2011	33000	9L3Z-1A189-A	
MKX		2011	33000	9L3Z-1A189-A	
MKX		2007-10 [†]	33000	6F2Z-1A189A	
MKX		2007-10 [‡]	33000	7L1Z-1A189A	
MKZ		2007-09	33000	6F2Z-1A189A	
MKZ		2010-11	33000	9L3Z-1A189-A	
Navigator		2011	33000	9L3Z-1A189-A	
Navigator		2003-04	33100	4L2Z-1A150-BA	
Navigator		2007-10	33000	7L1Z-1A189A	
Town Car		2006-11	33000	6F2Z-1A189A	
Mazda		B Pickup	2007-08	33000	6F2Z-1A189A
		Tribute	2006-08	33000	6F2Z-1A189A
	Tribute	2009-11	33000	9L3Z-1A189-A	
Mercury	Grand Marquis	2006-10	33000	6F2Z-1A189A	
	Mariner	2006-08	33000	6F2Z-1A189A	
	Mariner	2009-11	33000	9L3Z-1A189-A	
	Milan	2008-09	33000	6F2Z-1A189A	
Milan	2010-11	33000	9L3Z-1A189-A		

* Snap-in
** Clamp-in

[†] With Chrome Rims
[‡] Without Chrome Rims

VEHICLE APPLICATION COVERAGE:
Part No. 33000 & 33100

EZ-SENSOR 2011 TPMS APPLICATION GUIDE

	Model	Model Year	EZ-Sensor Part #	OE Sensor Part #	
Mercury - Cont'd.	Montego	2006-07	33000	6F2Z-1A189A	
	Monterey	2006-07	33000	6F2Z-1A189A	
	Mountaineer	2002-05	33100	4L2Z-1A150-BA	
	Mountaineer	2006-10	33000	6F2Z-1A189A	
	Sable	2008-09	33000	7L1Z-1A189A	
Mitsubishi	Eclipse	2006-07 (Alloy)	33000	MN103081	
	Eclipse	2006-07 (Steel)	33000	4250A030	
	Eclipse	2008-10	33000	MN103081	
	Eclipse	2011 (Steel)	33000	4250B875	
	Endeavor	2007 (315)	33000	MN103081	
	Endeavor	2008-10	33000	MN103081	
	Endeavor	2011 (Steel)	33000	4250B875	
	Galant	2010	33000	MN103081	
	Galant	2007-09 (Alloy)	33000	MN103081	
	Galant	2007-09 (Steel)	33000	4250A030	
	Galant	2011 (Steel)	33000	4250B875	
	Montero	2003-05	33000	MN103081	
	Raider	2008-09	33000	56029319AA-AB	
	Nissan	350Z	2003	33000	40700-CD001
		350Z	2004-06	33000	40700-CD001
		350Z	2007-08	33000	40700-JA01C
		370Z	2009-10	33000	40700-JK00C
Altima		2006-11	33000	40700-JA02B	
Armada		2005-06 (Alloy)	33000	40700-CK001	
Armada		2005-06 (Steel)	33000	40700-CK002	
Armada		2007-08	33000	40700-CK001	
Armada		2009-11	33000	40700-JA02B	
Cube		2009	33000	40700-JA01C	
Cube		2010	33000	40700-1AA0C	
Cube		2011 (non lkey)	33000	40700-1AA0C	
Frontier		2003-04	33000	40700-CD001	
Frontier		2005-07 (Alloy)	33000	40700-CK001	
Frontier		2008 (Alloy)	33000	40700-CK001	
Frontier		2005-07 (Steel)	33000	40700-CK002	
Frontier		2008 (Steel)	33000	40700-JA01B	
Frontier		2009-11	33000	40700-JA02B	
GT-R		2009-11	33000	40700-JA00C	
Juke		2011 (non lkey)	33000	40700-1AA0C	
Maxima		2006	33000	40700-CK001	
Maxima		2007 (Alloy)	33000	40700-CK001	
Maxima		2007 (Steel)	33000	40700-JA02B	
Maxima		2008-11	33000	40700-JA02B	
Murano		2003-06	33000	40700-CD001	
Murano		2007-09	33000	40700-JA02B	
Murano		2010-11	33000	40700-1AA0C	
Pathfinder		2003	33000	40700-CD001	
Pathfinder		2004 (Alloy)	33000	40700-CD001	

	Model	Model Year	EZ-Sensor Part #	OE Sensor Part #	
Nissan - Continued	Pathfinder	2004 (Steel)	33000	40700-CK002	
	Pathfinder	2005-06	33000	40700-CK001	
	Pathfinder	2007-11	33000	40700-JA02B	
	Quest	2004	33000	40700-CK002	
	Quest	2005-07 (Alloy)	33000	40700-CK001	
	Quest	2005-07 (Steel)	33000	40700-CK002	
	Quest	2008-09	33000	40700-JA02B	
	Rogue	2008-11	33000	40700-JA01C	
	Sentra	2007-08 (Alloy)	33000	40700-CK001	
	Sentra	2007-08 (Steel)	33000	40700-JA02B	
	Sentra	2009-11	33000	40700-JA02B	
	Titan	2004	33000	40700-CK002	
	Titan	2005-07 (Alloy)	33000	40700-CK001	
	Titan	2005-07 (Steel)	33000	40700-CK002	
	Titan	2008 (Alloy)	33000	40700-CD001	
	Titan	2008 (Steel)	33000	40700-JA02B	
	Titan	2009-11	33000	40700-JA02B	
	Versa	2012	33000	40700-1AA0C	
	Versa	2007-08 (Alloy)	33000	40700-CK001	
	Versa	2007-08 (Steel)	33000	40700-JA02B	
	Versa	2009-11	33000	40700-JA02B	
	Xterra	2005	33000	40700-CK001	
	Xterra	2003-04	33000	40700-CD001	
	Xterra	2006 (Alloy)	33000	40700-CK001	
	Xterra	2006 (Steel)	33000	40700-CK002	
	Xterra	2007-11	33000	40700-JA02B	
	Pontiac	G3	2009-10	33000	20923680
		G5	2008	33000	15921013
		G5	2009-10	33000	20923680
		G6	2008**	33000	15921013
G6		2008*	33000	20923680	
G6		2009-10	33000	20923680	
G8		2008-09	33000	20923680	
Grand Prix		2007	33000	15921013	
Grand Prix		2008**	33000	15921013	
Grand Prix		2008*	33000	20923680	
Montana		2008	33000	15268606	
Solstice		2008-10	33000	15921013	
Torrent		2007-09	33000	10394110	
Vibe		2008-10	33000	88974915	
Wave		2008-09	33000	20923680	
Saturn	Astra	2010	33000	20923680	
	Aura	2007	33000	15921013	
	Aura	2008**	33000	15921013	
	Aura	2008*	33000	20923680	
	Aura	2009-10	33000	20923680	
Lambda	2007-08	33000	15268606		

* Snap-in † With Chrome Rims
** Clamp-in ‡ Without Chrome Rims

EZ-SENSOR ²⁰¹¹ TPMS APPLICATION GUIDE

■ VEHICLE APPLICATION COVERAGE:
Part No. 33000 & 33100

	Model	Model Year	EZ-Sensor Part #	OE Sensor Part #	
Saturn - Cont'd.	Outlook	2007-08	33000	15921013	
	Outlook	2009-10	33000	20923680	
	Sky	2008-09	33000	15921013	
	Vue	2007-10	33000	20923680	
Scion	iQ	2012	33000	42607-33011	
	tC	2006-11	33000	42607-33011	
	xB	2007-11	33000	42607-33011	
	xD	2008-11	33000	42607-33011	
Subaru	B9 Tribeca	2006-11	33000	28103AG00A	
	Forester	2008-11	33000	28103AG01B	
	Impreza	2008-11	33000	28103AG01B	
	Legacy	2004-07	33000	28103AG00A	
	Legacy	2008-11	33000	28103AG01B	
	Outback	2004-07	33000	28103AG00A	
	Outback	2008-11	33000	28103AG01B	
	Tribeca	2008-11	33000	28103AG01B	
	Suzuki	Equator	2009-11	33000	43211-82Z00
		Forenza	2007-08	33000	43130-85Z03
Grand Vitara		2007-11	33000	43130-54J20	
Reno		2007-08	33000	43130-85Z00	
SX4		2007-11	33000	43130-54J20	
Verona		2005-06	33000	43130-86Z20	
XL-7		2005-06	33000	43130-54J20	
XL-7		2007-11	33000	43130-78J00	
Toyota	4Runner	2004-05	33000	42607-35010	
	4Runner	2006 (Early)	33000	42607-35010	
	4Runner	2006 (Late)	33000	42607-33011	
	4Runner	2007-11	33000	42607-33011	
	Avalon	2007-11	33000	42607-06011	
	Camry	2007-11 (USA made)	33000	42607-06011	
	Camry	2007-11 (Japan made)	33000	42607-33011	
	Camry Hybrid	2008-11	33000	42607-33011	
	Corolla	2007-11 (USA made)	33000	42607-06011	
	Corolla	2007-11 (Japan made)	33000	42607-33011	
	FJ Cruiser	2008-11	33000	42607-33011	
	Highlander	2007-11	33000	42607-33011	
	Highlander H	2008-11	33000	42607-33011	
	Land Cruiser	2005	33000	42607-33011	
	Land Cruiser	2006	33000	42607-33021	
	Land Cruiser	2007 (Early)	33000	42607-33021	
	Land Cruiser	2007 (Late)	33000	42607-33011	
	Land Cruiser	2008-11	33000	42607-33011	
	Matrix	2007-11 (USA made)	33000	42607-06011	

	Model	Model Year	EZ-Sensor Part #	OE Sensor Part #
Toyota - Continued	Matrix	2007-11 (Japan made)	33000	42607-33011
	Prius	2006-11	33000	42607-33011
	RAV4	2006	33000	42607-33011
	RAV4	2007-11	33000	42607-33021
	Sequoia	2004-07 (Alloy)	33000	42607-0C020
	Sequoia	2004-07 (Steel)	33000	42607-0C010
	Sequoia	2008 (Alloy)	33000	42607-08010
	Sequoia	2008 (Steel)	33000	42607-0C060
	Sequoia	2009-11	33000	42607-08010
	Sienna	2006-11	33000	42607-08010
	Solara	2006-11	33000	42607-06011
	Tacoma	2005 (Alloy)	33000	42607-AD020
	Tacoma	2005 (Steel)	33000	42607-04010
	Tacoma	2006 (Steel)	33000	42607-04010
	Tacoma	2006 Early (Alloy)	33000	42607-AD020
	Tacoma	2006 Late (Alloy)	33000	42607-06011
	Tacoma	2007-11 (Alloy)	33000	42607-06011
	Tacoma	2007-11 (Steel)	33000	42607-04010
	Tundra	2005 (Alloy)	33000	42607-0C020
	Tundra	2005 (Steel)	33000	42607-0C010
	Tundra	2006 (Alloy PAC)	33000	42607-0C020
	Tundra	2006 (Alloy TRW)	33000	42607-08010
	Tundra	2006 (Steel PAC)	33000	42607-0C010
	Tundra	2006 (Steel TRW)	33000	42607-0C060
	Tundra	2007-11 (Alloy)	33000	42607-08010
	Tundra	2007-11 (Steel)	33000	42607-0C060
	Venza	2009-11	33000	42607-06011
	Yaris	2008-11	33000	42607-33011

Application guides subject to change without notice.
Please refer to the manufacturer's websites for the most up-to-date application data.

* Snap-in
** Clamp-in

† With Chrome Rims
‡ Without Chrome Rims

REDI-SENSOR 2011 TPMS APPLICATION GUIDE

■ VEHICLE APPLICATION COVERAGE: Part No. 7001 & 7004

Model	Dill Sensor #	REDI-Sensor #	OE Sensor #	Model	Dill Sensor #	REDI-Sensor #	OE Sensor #	
Chrysler, Dodge & Jeep	1051	7001	68001696AA	Ford, Lincoln & Mercury - Cont'd.	9096	7004	4L2Z-1A150-BA	
			68001696AB				4L2T-1A150-BA	
			56053030AB				2L2Z-1A150-AA	
			56053030AC		1051	7001	425 0B 668	
			56053066AA				425 0A 225	
			56053036AA				425 0B 975	
			5139640AA		9028	7004	52088990AC	
			5142340AA				MN103033	
	56029465AB	56029319AA						
	68078861AA	ISUZU	7001		56029319AB			
	5127335AB			52088990AC				
	5127335AB			43130-78J00				
	5127335AC			43130-78J10				
	5127335AB			9153	7001	43130-85Z00		
	5127335AC					43130-85Z01		
	5127335AD					43130-85Z03		
	5127335AE			Suzuki	7001	43130-57L00		
	4727392AA					1051	7001	43130-57L00
	4727392AB					1056	7001	BBM2-37-140B
	4727392AC	FE01-37-140A						
4727392AD	GN3A-37-140B							
9154	7001	56029319AB	Mazda	1048	7001	ZZC1-37-140		
		56029319AA (Dakota Only)				6F2Z-1A189A		
		56029479AA				6L2T-1A150AA		
		56029479AB				9L3Z-1A189-A		
9308	7001	56029479AA	Buick, Cadillac, Chevrolet, GMC, Hummer, Pontiac, Saab & Saturn	9315	7001	ZZDA-37-140		
		56029479AB				1047	7001	10394110
1043	7004	68001698AA		Must drive vehicle following relearn	9153	7001	15921013	
		68001698AB					15268606	
		7B0 907 253					15825475	
		7B0 907 253A					25920615	
		56029359AA					15202272	
		56029359AB					12768826	
		56029359AC					25799331	
		56053031AA					15922396	
		56053031AB	15123145					
		56053031AC	15254101					
		56053031AD	20922900					
		56053031AE	25774006					
		68078768AA	25763677					
		9028	7004				52088990AA	9116
52088990AC	25774006							
5096808AA	25763677							
9315	7001	9L3Z-1A189-A (1/2 ton non-HD only)	9076	7001	25758220	10306573		
		9L3T-1A150-BD				10354988		
		9L3T-1A180-AF				10438853		
9135	7001	5L1Z-1A150-AA	8006	7001	25981210	52933-2L500		
		5L7T-1A150-AA				52933-2M000		
1048	7001	6F2Z-1A189A	5507	7001	25933-2L700	52933-2L700		
		6F2A-1A176AE				7B0907253		
		6F2T-1A150AE						
		7L1Z-1A189A						
1043	7004		1043	7004				

Application guides subject to change without notice. Please refer to the manufacturer's websites for the most up-to-date application data.

SCHRADER 2011 TPMS APPLICATION GUIDE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2011				
MDX	Sensor	-	20098	35, 4
RL	Sensor	-	28981	35, 4
	Service Pack	Includes Valve	20036	35, 4
	Service Pack	Does Not Include Valve	20021	35, 4
TL	Sensor	-	20720	35, 4
	Service Pack	-	20019	35, 4
TSX	Sensor	-	20098	35, 4
2010				
MDX, RDX	Sensor	-	20098	35, 4
RL	Sensor	-	28981	35, 4
	Service Pack	Includes Valve	20036	35, 4
	Service Pack	Does Not Include Valve	20021	35, 4
TL	Sensor	-	20720	35, 4
	Service Pack	-	20019	35, 4
TSX	Sensor	-	20098	35, 4
2009				
CSX	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28720	35, 4
	Service Pack	-	20019	35, 4
	Service Pack	-	20098	35, 4
MDX, RX	Sensor	-	20098	35, 4
RL	Sensor	-	28981	35, 4
	Service Pack	Includes Valve	20036	35, 4
	Service Pack	Does Not Include Valve	20021	35, 4
TL	Sensor	-	20720	35, 4
	Service Pack	-	20019	35, 4
TSX	Sensor	-	20098	35, 4
2008				
CSX	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2008 - Continued				
CSX - Cont'd.	Sensor	-	28720	35, 4
	Service Pack	-	20019	35, 4
2007				
MDX, RX	Sensor	-	20098	35, 4
RL, TL	Sensor	-	28981	35, 4
	Service Pack	Includes Valve	20036	35, 4
	Service Pack	Does Not Include Valve	20021	35, 4
TSX	Sensor	-	20098	35, 4
2006 - 2005				
MDX, RL, TL	Sensor	-	28981	35, 4
	Service Pack	Includes Valve	20036	35, 4
	Service Pack	Does Not Include Valve	20021	35, 4
2004				
MDX	Sensor	-	28981	35, 4
	Service Pack	Includes Valve	20036	35, 4
	Service Pack	Does Not Include Valve	20021	35, 4
2011				
A3, A4, A5	Sensor	-	20088	71, 8
	Service Pack	-	20017	71, 8
A6	Sensor	Includes Transmitter Only	20077	35, 4
	Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	W/48mm Green Insert	20038	35, 4
	Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	W/51mm Orange Insert	20040	35, 4
Q5	Sensor	-	20088	71, 8
	Service Pack	-	20017	71, 8
Q7	Sensor	Includes Transmitter Only	20077	35, 4
	Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	W/48mm Green Insert	20038	35, 4
	Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	W/51mm Orange Insert	20040	35, 4
R8	Sensor	-	20103	35, 4
	Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	W/48mm Green Insert	20038	35, 4
R8	Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	W/51mm Orange Insert	20040	35, 4
S4, S5	Sensor	-	20088	71, 8
	Service Pack	-	20017	71, 8
S6	Sensor	Includes Transmitter Only	20077	35, 4
	Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	W/48mm Green Insert	20038	35, 4

* Programming Tool Required ** Magnet Required to Activate Sensor

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2011 - Continued					2009 - Continued					
S6 - Cont'd.	Service Pack	W/49mm Black Insert	20039	35, 4	Q5	Sensor	-	20088	71, 8	
	Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	-	20017	71, 8	
TT	Sensor	-	20088	71, 8	Q7, R8, S4	Sensor	Includes Transmitter Only	20078	35, 4	
	Service Pack	-	20017	71, 8		Service Pack	Does Not Include Valve	20023	35, 4	
2010						Service Pack	W/43mm Silver Insert	20037	35, 4	
A3, A4, A5	Sensor	-	20088	71, 8		Service Pack	W/48mm Green Insert	20038	35, 4	
	Service Pack	-	20017	71, 8		Service Pack	W/49mm Black Insert	20039	35, 4	
A6	Sensor	Includes Transmitter Only	20103	35, 4		Service Pack	W/51mm Orange Insert	20040	35, 4	
	Service Pack	Does Not Include Valve	20023	35, 4		S5	Sensor	-	20088	71, 8
	Service Pack	W/43mm Silver Insert	20037	35, 4			Service Pack	-	20017	71, 8
	Service Pack	W/48mm Green Insert	20038	35, 4	S6	Sensor	Includes Transmitter Only	20078	35, 4	
	Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	Does Not Include Valve	20023	35, 4	
	Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	W/43mm Silver Insert	20037	35, 4	
A8	Sensor	Includes Transmitter Only	20077	35, 4		Service Pack	W/48mm Green Insert	20038	35, 4	
	Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	W/49mm Black Insert	20039	35, 4	
	Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/51mm Orange Insert	20040	35, 4	
	Service Pack	W/48mm Green Insert	20038	35, 4	S8	Sensor	Includes Transmitter Only	20077	35, 4	
	Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	Does Not Include Valve	20023	35, 4	
	Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	W/43mm Silver Insert	20037	35, 4	
Q5	Sensor	-	20088	71, 8		Service Pack	W/48mm Green Insert	20038	35, 4	
	Service Pack	-	20017	71, 8		Service Pack	W/49mm Black Insert	20039	35, 4	
Q7, R8	Sensor	Includes Transmitter Only	20103	35, 4		Service Pack	W/51mm Orange Insert	20040	35, 4	
	Service Pack	Does Not Include Valve	20023	35, 4	TT	Sensor	-	20088	71, 8	
	Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	-	20017	71, 8	
	Service Pack	W/48mm Green Insert	20038	35, 4	2008					
	Service Pack	W/49mm Black Insert	20039	35, 4	A3	Sensor	-	20088	71, 8	
	Service Pack	W/51mm Orange Insert	20040	35, 4	Service Pack	-	20017	71, 8		
S4, S5	Sensor	-	20088	71, 8	A4	Sensor	Includes Transmitter Only	20078	35, 4	
	Service Pack	-	20017	71, 8		Service Pack	Does Not Include Valve	20023	35, 4	
S6	Sensor	Includes Transmitter Only	20103	35, 4		Service Pack	W/43mm Silver Insert	20037	35, 4	
	Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	W/48mm Green Insert	20038	35, 4	
	Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/49mm Black Insert	20039	35, 4	
	Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/51mm Orange Insert	20040	35, 4	
	Service Pack	W/49mm Black Insert	20039	35, 4	A5	Sensor	-	20088	71, 8	
	Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	-	20017	71, 8	
TT	Sensor	-	20088	71, 8	A6	Sensor	Includes Transmitter Only	20078	35, 4	
	Service Pack	-	20017	71, 8		Service Pack	Does Not Include Valve	20023	35, 4	
2009						Service Pack	W/43mm Silver Insert	20037	35, 4	
A3, A4, A5	Sensor	-	20088	71, 8		Service Pack	W/48mm Green Insert	20038	35, 4	
	Service Pack	-	20017	71, 8		Service Pack	W/49mm Black Insert	20039	35, 4	
A6	Sensor	Includes Transmitter Only; Exc. Quattro	20078	35, 4		Service Pack	W/51mm Orange Insert	20040	35, 4	
	Sensor	Includes Transmitter Only; Quattro	20103	35, 4	A8	Sensor	Includes Transmitter Only	20077	35, 4	
	Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	Does Not Include Valve	20023	35, 4	
	Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/43mm Silver Insert	20037	35, 4	
	Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/48mm Green Insert	20038	35, 4	
	Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/49mm Black Insert	20039	35, 4	
Service Pack	W/51mm Orange Insert	20040	35, 4	Service Pack		W/51mm Orange Insert	20040	35, 4		
A8 A8	Sensor	Includes Transmitter Only	20077	35, 4	Q7, R8, RS4, S4	Sensor	Includes Transmitter Only	20078	35, 4	
	Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	Does Not Include Valve	20023	35, 4	
	Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/43mm Silver Insert	20037	35, 4	
	Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/48mm Green Insert	20038	35, 4	
	Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/49mm Black Insert	20039	35, 4	
	Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	W/51mm Orange Insert	20040	35, 4	

Audi - Continued

Audi - Continued

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
2003					2010-2006						
Audi - Continued	A4	Sensor	Includes Transmitter Only	20078	35, 4	Continental	Sensor	Includes Transmitter Only	20078	35, 4	
		Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	Does Not Include Valve	20023	35, 4	
		Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/43mm Silver Insert	20037	35, 4	
		Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/48mm Green Insert	20038	35, 4	
		Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/49mm Black Insert	20039	35, 4	
		Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	W/51mm Orange Insert	20040	35, 4	
	A8	Sensor	Includes Transmitter Only; Chassis No. 4E3000001 & After	20077	35, 4	Continental	2005-2003				
		Sensor	Includes Transmitter Only; Chassis No. 4D3004999 & Before	20079	35, 4		Sensor	Includes Transmitter Only	20077	35, 4	
		Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	Does Not Include Valve	20023	35, 4	
		Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/43mm Silver Insert	20037	35, 4	
		Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/48mm Green Insert	20038	35, 4	
		Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/49mm Black Insert	20039	35, 4	
Allroad Quattro	Service Pack	W/51mm Orange Insert	20040	35, 4	Service Pack	W/51mm Orange Insert	20040	35, 4			
		Sensor	Includes Transmitter Only	20079	35, 4	2011					
		Service Pack	Does Not Include Valve	20023	35, 4	128I	Sensor	Includes Transmitter Only	20083	31, 3.5	
		Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	Does Not Include Valve	20023	31, 3.5	
		Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/43mm Silver Insert	20037	31, 3.5	
		Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/48mm Green Insert	20038	31, 3.5	
Service Pack	W/51mm Orange Insert	20040	35, 4	Service Pack	W/49mm Black Insert		20039	31, 3.5			
Service Pack	W/51mm Orange Insert	20040	35, 4	Service Pack	W/51mm Orange Insert		20040	31, 3.5			
S8	Sensor	Includes Transmitter Only; Chassis No. 4E3000001 & After	20077	35, 4	328I, 335D, 335I	Sensor	Includes Transmitter Only	28081	31, 3.5		
		Sensor	Includes Transmitter Only; Chassis No. 4D3004999 & Before	20079		35, 4	Service Pack	Does Not Include Valve	20023	31, 3.5	
		Service Pack	Does Not Include Valve	20023		35, 4	Service Pack	W/43mm Silver Insert	20037	31, 3.5	
		Service Pack	W/43mm Silver Insert	20037		35, 4	Service Pack	W/48mm Green Insert	20038	31, 3.5	
		Service Pack	W/48mm Green Insert	20038		35, 4	Service Pack	W/49mm Black Insert	20039	31, 3.5	
		Service Pack	W/49mm Black Insert	20039		35, 4	Service Pack	W/51mm Orange Insert	20040	31, 3.5	
2002					BMW	528I	Sensor	Includes Transmitter Only	20083	31, 3.5	
A4	Sensor	Includes Transmitter Only	20078	35, 4		535I, 550I, 740I, 740LI, 750I, 750LI	Sensor	Includes Transmitter Only	20083	31, 3.5	
		Service Pack	Does Not Include Valve	20023			35, 4	Service Pack	Does Not Include Valve	20023	31, 3.5
		Service Pack	W/43mm Silver Insert	20037			35, 4	Service Pack	W/43mm Silver Insert	20037	31, 3.5
		Service Pack	W/48mm Green Insert	20038			35, 4	Service Pack	W/48mm Green Insert	20038	31, 3.5
		Service Pack	W/49mm Black Insert	20039			35, 4	Service Pack	W/49mm Black Insert	20039	31, 3.5
		Service Pack	W/51mm Orange Insert	20040			35, 4	Service Pack	W/51mm Orange Insert	20040	31, 3.5
A8, Allroad Quattro, S8	Service Pack	W/51mm Orange Insert	20040	35, 4		760LI	Sensor	Includes Transmitter Only	20083	31, 3.5	
		Sensor	Includes Transmitter Only	20079		35, 4	Alpina B7	Sensor	Includes Transmitter Only	20080	31, 3.5
		Service Pack	Does Not Include Valve	20023		35, 4		Service Pack	Does Not Include Valve	20023	31, 3.5
		Service Pack	W/43mm Silver Insert	20037		35, 4		Service Pack	W/43mm Silver Insert	20037	31, 3.5
		Service Pack	W/48mm Green Insert	20038		35, 4		Service Pack	W/48mm Green Insert	20038	31, 3.5
		Service Pack	W/49mm Black Insert	20039	35, 4	Service Pack		W/49mm Black Insert	20039	31, 3.5	
Service Pack	W/51mm Orange Insert	20040	35, 4	Service Pack	W/51mm Orange Insert	20040		31, 3.5			
2001					X3	Sensor	Includes Transmitter Only	20083	35, 4		
A8, Allroad Quattro, S8	Sensor	Includes Transmitter Only	20079	35, 4	X5	Sensor	Includes Transmitter Only	20083	35, 4		
		Service Pack	Does Not Include Valve	20023		35, 4	Service Pack	Does Not Include Valve	20023	35, 4	
		Service Pack	W/43mm Silver Insert	20037		35, 4	Service Pack	W/43mm Silver Insert	20037	35, 4	
		Service Pack	W/48mm Green Insert	20038		35, 4	Service Pack	W/48mm Green Insert	20038	35, 4	
		Service Pack	W/49mm Black Insert	20039		35, 4	Service Pack	W/49mm Black Insert	20039	35, 4	
		Service Pack	W/51mm Orange Insert	20040		35, 4	Service Pack	W/51mm Orange Insert	20040	35, 4	
A8, Allroad Quattro, S8	Service Pack	W/51mm Orange Insert	20040	35, 4	X6	Sensor	Includes Transmitter Only	20083	35, 4		
		Sensor	Includes Transmitter Only	20079	35, 4	Z4	Sensor	Includes Transmitter Only	20083	31, 3.5	
		Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	Does Not Include Valve	20023	31, 3.5	
		Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/43mm Silver Insert	20037	31, 3.5	
		Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/48mm Green Insert	20038	31, 3.5	
		Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/49mm Black Insert	20039	31, 3.5	
Service Pack	W/51mm Orange Insert	20040	35, 4	Service Pack	W/51mm Orange Insert		20040	31, 3.5			

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2010					2009 - Continued				
128I, 135I, 323I	Sensor	Includes Transmitter Only	20083	31, 3.5	X3, X5, X6	Sensor	Includes Transmitter Only	20083	35, 4
	Service Pack	Does Not Include Valve	20023	31, 3.5		Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	W/43mm Silver Insert	20037	31, 3.5		Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	W/48mm Green Insert	20038	31, 3.5		Service Pack	W/48mm Green Insert	20038	35, 4
	Service Pack	W/49mm Black Insert	20039	31, 3.5		Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/51mm Orange Insert	20040	35, 4
328I, 335D, 335I	Sensor	Includes Transmitter Only	28081	31, 3.5		Z4	Sensor	Includes Transmitter Only	20083
	Service Pack	Does Not Include Valve	20023	31, 3.5	Service Pack		Does Not Include Valve	20023	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	31, 3.5	Service Pack		W/43mm Silver Insert	20037	31, 3.5
	Service Pack	W/48mm Green Insert	20038	31, 3.5	Service Pack		W/48mm Green Insert	20038	31, 3.5
	Service Pack	W/49mm Black Insert	20039	31, 3.5	Service Pack		W/49mm Black Insert	20039	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	31, 3.5	Service Pack		W/51mm Orange Insert	20040	31, 3.5
528I, 535I, 550I, 650I, 750I, 750LI, 760LI	Sensor	Includes Transmitter Only	20083	31, 3.5	2008				
	Service Pack	Does Not Include Valve	20023	31, 3.5	128I, 135I, 323I, 328I, 328XI, 335I, 335XI, 528I, 528XI, 535I, 535XI, 550I, 650I, 750I, 750LI, 760LI, Alpina B7, M3, M5, M6	Sensor	Includes Transmitter Only	20083	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	31, 3.5		Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/48mm Green Insert	20038	31, 3.5		Service Pack	W/43mm Silver Insert	20037	31, 3.5
	Service Pack	W/49mm Black Insert	20039	31, 3.5		Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/49mm Black Insert	20039	31, 3.5
M3	Sensor	Includes Transmitter Only	28081	31, 3.5		Service Pack	W/51mm Orange Insert	20040	31, 3.5
	Service Pack	Does Not Include Valve	20023	31, 3.5		X3, X5, X6	Sensor	Includes Transmitter Only	20083
	Service Pack	W/43mm Silver Insert	20037	31, 3.5	Service Pack		Does Not Include Valve	20023	35, 4
	Service Pack	W/48mm Green Insert	20038	31, 3.5	Service Pack		W/43mm Silver Insert	20037	35, 4
	Service Pack	W/49mm Black Insert	20039	31, 3.5	Service Pack		W/48mm Green Insert	20038	35, 4
	Service Pack	W/51mm Orange Insert	20040	31, 3.5	Service Pack		W/49mm Black Insert	20039	35, 4
M5, M6	Sensor	Includes Transmitter Only	20083	31, 3.5	Service Pack		W/51mm Orange Insert	20040	35, 4
	Service Pack	Does Not Include Valve	20023	31, 3.5	Z4		Sensor	Includes Transmitter Only	20083
	Service Pack	W/43mm Silver Insert	20037	31, 3.5		Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/48mm Green Insert	20038	31, 3.5		Service Pack	W/43mm Silver Insert	20037	31, 3.5
	Service Pack	W/49mm Black Insert	20039	31, 3.5		Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/49mm Black Insert	20039	31, 3.5
X3, X5, X6	Sensor	Includes Transmitter Only	20083	35, 4		Service Pack	W/51mm Orange Insert	20040	31, 3.5
	Service Pack	Does Not Include Valve	20023	35, 4		2007			
	Service Pack	W/43mm Silver Insert	20037	35, 4	323I, 328I, 328XI, 335I, 335XI, 525I, 525XI, 530I, 530XI, 550I, 650I, 750I, 750LI, 760LI, Alpina B7, M5, M6	Sensor	Includes Transmitter Only	20083	31, 3.5
	Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/43mm Silver Insert	20037	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	W/48mm Green Insert	20038	31, 3.5
Z4	Sensor	Includes Transmitter Only	20083	31, 3.5		Service Pack	W/49mm Black Insert	20039	31, 3.5
	Service Pack	Does Not Include Valve	20023	31, 3.5		Service Pack	W/51mm Orange Insert	20040	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	31, 3.5		2009			
	Service Pack	W/48mm Green Insert	20038	31, 3.5	128I, 135I, 323I, 328I, 335D, 335I, 528I, 535I, 550I, 650I, 750I, 750LI, M3, M5, M6	Sensor	Includes Transmitter Only	20083	31, 3.5
	Service Pack	W/49mm Black Insert	20039	31, 3.5		Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/43mm Silver Insert	20037	31, 3.5
2009	Sensor	Includes Transmitter Only	20083	31, 3.5		Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	Does Not Include Valve	20023	31, 3.5		Service Pack	W/49mm Black Insert	20039	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	31, 3.5		Service Pack	W/51mm Orange Insert	20040	31, 3.5
	Service Pack	W/48mm Green Insert	20038	31, 3.5					
	Service Pack	W/49mm Black Insert	20039	31, 3.5					
	Service Pack	W/51mm Orange Insert	20040	31, 3.5					

BMW - Continued

BMW - Continued

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2007 - Continued					2005					
X3, X5	Sensor	Includes Transmitter Only	20083	35, 4	320I, 325CI, 325I, 325XI, 330CI, 330I, 330XI, 525I, 530I, 545I, 645CI, 745I, 745LI, 760I	Sensor	Includes Transmitter Only	20080	31, 3.5	
	Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	Does Not Include Valve	20023	31, 3.5	
	Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/43mm Silver Insert	20037	31, 3.5	
	Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/48mm Green Insert	20038	31, 3.5	
	Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/49mm Black Insert	20039	31, 3.5	
	Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	W/51mm Orange Insert	20040	31, 3.5	
Z4	Sensor	Includes Transmitter Only	20083	31, 3.5		760LI, M3	Sensor	Includes Transmitter Only	20083	31, 3.5
	Service Pack	Does Not Include Valve	20023	31, 3.5			Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	31, 3.5			Service Pack	W/43mm Silver Insert	20037	31, 3.5
	Service Pack	W/48mm Green Insert	20038	31, 3.5			Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	W/49mm Black Insert	20039	31, 3.5			Service Pack	W/49mm Black Insert	20039	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	31, 3.5	Service Pack		W/51mm Orange Insert	20040	31, 3.5	
2006					X5		Sensor	Includes Transmitter Only	20083	35, 4
323I	Sensor	Includes Transmitter Only; Jun. & Newer	20083	31, 3.5			Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	Does Not Include Valve; Jun. & Newer	20023	31, 3.5			Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	W/43mm Silver Insert; Jun. & Newer	20037	31, 3.5			Service Pack	W/48mm Green Insert	20038	35, 4
	Service Pack	W/48mm Green Insert; Jun. & Newer	20038	31, 3.5			Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	W/49mm Black Insert; Jun. & Newer	20039	31, 3.5		Service Pack	W/51mm Orange Insert	20040	35, 4	
	Service Pack	W/51mm Orange Insert; Jun. & Newer	20040	31, 3.5		Service Pack	W/51mm Orange Insert	20040	35, 4	
325CI, 325I, 325XI, 330CI, 330I, 330XI	Sensor	Includes Transmitter Only	20080	31, 3.5		Z4	Sensor	Includes Transmitter Only	20083	31, 3.5
	Service Pack	Does Not Include Valve	20023	31, 3.5			Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	31, 3.5			Service Pack	W/43mm Silver Insert	20037	31, 3.5
	Service Pack	W/48mm Green Insert	20038	31, 3.5			Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	W/49mm Black Insert	20039	31, 3.5	Service Pack		W/49mm Black Insert	20039	31, 3.5	
	Service Pack	W/51mm Orange Insert	20040	31, 3.5	Service Pack		W/51mm Orange Insert	20040	31, 3.5	
525I, 525XI, 530I, 530XI, 550I, 650I, 750I, 750LI, 760I, 760LI, M3, M5, M6	Sensor	Includes Transmitter Only	20083	31, 3.5	2004					
	Service Pack	Does Not Include Valve	20023	31, 3.5	320I, 325CI, 325I, 325XI, 330CI, 330I, 330XI, 525I, 530I, 545I, 645CI, 745I, 745LI, 760I		Sensor	Includes Transmitter Only	20080	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	31, 3.5			Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/48mm Green Insert	20038	31, 3.5			Service Pack	W/43mm Silver Insert	20037	31, 3.5
	Service Pack	W/49mm Black Insert	20039	31, 3.5			Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/49mm Black Insert	20039	31, 3.5	
Service Pack	W/51mm Orange Insert	20040	31, 3.5	Service Pack		W/51mm Orange Insert	20040	31, 3.5		
X3, X5	Sensor	Includes Transmitter Only	20083	35, 4		760LI, M3	Sensor	Includes Transmitter Only	20083	31, 3.5
	Service Pack	Does Not Include Valve	20023	35, 4			Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	35, 4			Service Pack	W/43mm Silver Insert	20037	31, 3.5
	Service Pack	W/48mm Green Insert	20038	35, 4			Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	W/49mm Black Insert	20039	35, 4			Service Pack	W/49mm Black Insert	20039	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	35, 4	Service Pack		W/51mm Orange Insert	20040	31, 3.5	
Z4	Sensor	Includes Transmitter Only	20083	31, 3.5	X5		Sensor	Includes Transmitter Only	28082	35, 4
	Service Pack	Does Not Include Valve	20023	31, 3.5			Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	W/43mm Silver Insert	20037	31, 3.5			Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	W/48mm Green Insert	20038	31, 3.5			Service Pack	W/48mm Green Insert	20038	35, 4
	Service Pack	W/49mm Black Insert	20039	31, 3.5			Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/51mm Orange Insert	20040	35, 4	

BMW - Continued

BMW - Continued

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2004 - Continued					2002 - Continued				
Z4	Sensor	Includes Transmitter Only	20083	31, 3.5	X5	Sensor	Includes Transmitter Only	28082	35, 4
	Service Pack	Does Not Include Valve	20023	31, 3.5		Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	W/43mm Silver Insert	20037	31, 3.5		Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	W/48mm Green Insert	20038	31, 3.5		Service Pack	W/48mm Green Insert	20038	35, 4
	Service Pack	W/49mm Black Insert	20039	31, 3.5		Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/51mm Orange Insert	20040	35, 4
2003						Z3	Service Pack	Does Not Include Valve	20023
320I, 325CI, 325I, 325XI, 330CI, 330I, 330XI, 525I, 530I, 540I, 745I, 745LI, 760LI, M3	Sensor	Includes Transmitter Only	20080	31, 3.5	Service Pack		W/43mm Silver Insert	20037	31, 3.5
	Service Pack	Does Not Include Valve	20023	31, 3.5	Service Pack		W/48mm Green Insert	20038	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	31, 3.5	Service Pack		W/49mm Black Insert	20039	31, 3.5
	Service Pack	W/48mm Green Insert	20038	31, 3.5	Service Pack		W/51mm Orange Insert	20040	31, 3.5
	Service Pack	W/49mm Black Insert	20039	31, 3.5	Z8	Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/43mm Silver Insert	20037	31, 3.5
M5	Sensor	Includes Transmitter Only; W/433 MHz Sensor	20080	31, 3.5		Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	Does Not Include Valve	20023	31, 3.5		Service Pack	W/49mm Black Insert	20039	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	31, 3.5	Service Pack	W/51mm Orange Insert	20040	31, 3.5	
	Service Pack	W/48mm Green Insert	20038	31, 3.5	2001				
	Service Pack	W/49mm Black Insert	20039	31, 3.5	320I, 325CI, 325I, 325XI, 330CI, 330I, 330XI, 525I, 530I, 540I, 740I, 740IL, 750IL, M3	Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/43mm Silver Insert	20037	31, 3.5
X5	Sensor	Includes Transmitter Only	28082	35, 4		Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	W/49mm Black Insert	20039	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/51mm Orange Insert	20040	31, 3.5
	Service Pack	W/48mm Green Insert	20038	35, 4	M5	Sensor	Includes Transmitter Only; W/433 MHz Sensor	20080	31, 3.5
	Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	W/43mm Silver Insert	20037	31, 3.5
Z4	Sensor	Includes Transmitter Only	20083	31, 3.5		Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	Does Not Include Valve	20023	31, 3.5		Service Pack	W/49mm Black Insert	20039	31, 3.5
	Service Pack	W/43mm Silver Insert	20037	31, 3.5	Service Pack	W/51mm Orange Insert	20040	31, 3.5	
	Service Pack	W/48mm Green Insert	20038	31, 3.5	X5	Sensor	Includes Transmitter Only	28082	35, 4
	Service Pack	W/49mm Black Insert	20039	31, 3.5		Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/43mm Silver Insert	20037	35, 4
Z8	Sensor	Includes Transmitter Only; W/433 MHz Sensor	20080	31, 3.5		Service Pack	W/48mm Green Insert	20038	35, 4
	Service Pack	Does Not Include Valve	20023	31, 3.5		Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	W/43mm Silver Insert	20037	31, 3.5	Service Pack	W/51mm Orange Insert	20040	35, 4	
	Service Pack	W/48mm Green Insert	20038	31, 3.5	Z3, Z8	Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/49mm Black Insert	20039	31, 3.5		Service Pack	W/43mm Silver Insert	20037	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/48mm Green Insert	20038	31, 3.5
2002						Service Pack	W/49mm Black Insert	20039	31, 3.5
320I, 325CI, 325I, 325XI, 330CI, 330I, 330XI, 525I, 530I, 540I, 745I, 745LI, 760LI, M3, M5	Sensor	Includes Transmitter Only; W/433 MHz Sensor	20080	31, 3.5	Service Pack	W/51mm Orange Insert	20040	31, 3.5	
	Service Pack	Does Not Include Valve	20023	31, 3.5	2000				
	Service Pack	W/43mm Silver Insert	20037	31, 3.5	323CI, 323I, 328CI, 328I, 528I, 540I, 740I, 740IL, 750IL	Service Pack	Does Not Include Valve	20023	31, 3.5
	Service Pack	W/48mm Green Insert	20038	31, 3.5		Service Pack	W/43mm Silver Insert	20037	31, 3.5
	Service Pack	W/49mm Black Insert	20039	31, 3.5		Service Pack	W/48mm Green Insert	20038	31, 3.5
	Service Pack	W/51mm Orange Insert	20040	31, 3.5		Service Pack	W/49mm Black Insert	20039	31, 3.5
						Service Pack	W/51mm Orange Insert	20040	31, 3.5

BMW - Continued

BMW - Continued

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2000 - Continued					2011 - Continued					
BMW - Continued	M5	Sensor	Includes Transmitter Only; W/433 MHz Sensor	20080	31, 3.5	Regal	EZ-Sensor	-	33000*	11.5, 1.3
		Service Pack	Does Not Include Valve	20023	31, 3.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		Service Pack	W/43mm Silver Insert	20037	31, 3.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Service Pack	W/48mm Green Insert	20038	31, 3.5		Sensor	-	28206	11.5, 1.3
		Service Pack	W/49mm Black Insert	20039	31, 3.5		Service Pack	-	20008	11.5, 1.3
		Service Pack	W/51mm Orange Insert	20040	31, 3.5		2010			
BMW - Continued	X5	Sensor	Includes Transmitter Only	28082	35, 4	Allure	EZ-Sensor	-	33000*	11.5, 1.3
		Service Pack	Does Not Include Valve	20023	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		Service Pack	W/43mm Silver Insert	20037	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Service Pack	W/48mm Green Insert	20038	35, 4		Sensor	-	28206	11.5, 1.3
		Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	-	20008	11.5, 1.3
		Service Pack	W/51mm Orange Insert	20040	35, 4		Enclave	EZ-Sensor	-	33000*
Z3, Z8	Service Pack	Does Not Include Valve	20023	31, 3.5	EZ-Sensor Service Pack	Almnm. Valve		34000	62, 7	
	Service Pack	W/43mm Silver Insert	20037	31, 3.5	EZ-Sensor Service Pack	Rubber Valve		20008	11.5, 1.3	
	Service Pack	W/48mm Green Insert	20038	31, 3.5	Sensor	-		20153	11.5, 1.3	
	Service Pack	W/49mm Black Insert	20039	31, 3.5	Service Pack	-		20008	11.5, 1.3	
Service Pack	W/51mm Orange Insert	20040	31, 3.5	LaCrosse	EZ-Sensor	-		33000*	11.5, 1.3	
1999 - 1997					EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
528i, 540i, 740i, 740iL, 750iL	Service Pack	Does Not Include Valve	20023		31, 3.5	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	W/43mm Silver Insert	20037		31, 3.5	Sensor	-	28206	11.5, 1.3	
	Service Pack	W/48mm Green Insert	20038		31, 3.5	Service Pack	-	20008	11.5, 1.3	
	Service Pack	W/49mm Black Insert	20039		31, 3.5	Lucerne	EZ-Sensor	-	33000*	11.5, 1.3
Service Pack	W/51mm Orange Insert	20040	31, 3.5	EZ-Sensor Service Pack	Almnm. Valve		34000	62, 7		
2006					EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
BMW - Continued	Veyron	Service Pack	Does Not Include Valve	20023	35, 4		Sensor	-	20153	11.5, 1.3
		Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	-	20008	11.5, 1.3
		Service Pack	W/48mm Green Insert	20038	35, 4		Lucerne	EZ-Sensor	-	33000*
		Service Pack	W/49mm Black Insert	20039	35, 4	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7
		Service Pack	W/51mm Orange Insert	20040	35, 4	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3
Sensor	-	20153	11.5, 1.3	Sensor	-	20153		11.5, 1.3		
Service Pack	-	20008	11.5, 1.3	Service Pack	-	20008		11.5, 1.3		
2011					2009					
Buick	Enclave	EZ-Sensor	-	33000*	11.5, 1.3	Allure, Enclave, LaCrosse, Lucerne	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Sensor	-	20153	11.5, 1.3		Sensor	-	20153	11.5, 1.3
		Service Pack	-	20008	11.5, 1.3		Service Pack	-	20008	11.5, 1.3
		Buick	LaCrosse	EZ-Sensor	-		33000*	11.5, 1.3	2008	
EZ-Sensor Service Pack	Almnm. Valve			34000	62, 7	Allure, Enclave, LaCrosse	EZ-Sensor	-	33000*	11.5, 1.3
EZ-Sensor Service Pack	Rubber Valve			20008	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Sensor	-			28206	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Service Pack	-			20008	11.5, 1.3		Sensor	-	20158	62, 7
Buick	Lucerne			EZ-Sensor	-		33000*	11.5, 1.3	Service Pack	W/Schrader Sensor
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	W/Siemens Sensor	20030	80, 9
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3					
		Sensor	-	20153	11.5, 1.3					
Service Pack	-	20008	11.5, 1.3							

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2008 - Continued					2011 - 2010 - Continued					
Lucerne	EZ-Sensor	-	33000*	11.5, 1.3	STS	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	20153	11.5, 1.3		Sensor	-	20153	11.5, 1.3	
	Service Pack	-	20008	11.5, 1.3		Service Pack	-	20008	11.5, 1.3	
2007					2009					
Allure, LaCrosse	EZ-Sensor	-	33000*	11.5, 1.3	CTS	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	20158	62, 7		Sensor	OEM Part No. 25920615; Exc. CTS V	20153	11.5, 1.3	
	Service Pack	W/Schrader Sensor	20004	62, 7		Sensor	OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20158	62, 7	
	Service Pack	W/Siemens Sensor	20030	80, 9		Service Pack	OEM Part No. 25920615; Exc. CTS V	20008	11.5, 1.3	
Lucerne	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20004	62, 7	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		DTS, Escalade, SRX	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor	-	20153	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Service Pack	-	20008	11.5, 1.3	Sensor	-		20153	11.5, 1.3		
Service Pack	-	20008	11.5, 1.3	Service Pack	-		20008	11.5, 1.3		
Rainier	Sensor	OEM Part No. 25774006	20116	62, 7	STS	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	-	20004	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
2006						XLR	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Rainier	Sensor	OEM Part No. 25774006	20116	62, 7			Sensor	OEM Part No. 25758220	20076	62, 7
Rainier	Service Pack	-	20004	62, 7	Service Pack	-	20004	62, 7		
	2011 - 2010					2008				
CTS	EZ-Sensor	-	33000*	11.5, 1.3	CTS, DTS, Escalade, SRX	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	OEM Part No. 25920615; Exc. CTS V	20153	11.5, 1.3		Sensor	-	20153	11.5, 1.3	
	Sensor	OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20158	62, 7	Service Pack	-	20008	11.5, 1.3		
	Service Pack	OEM Part No. 25920615; Exc. CTS V	20008	11.5, 1.3	STS, XLR	Service Pack	-	20004	62, 7	
	Service Pack	OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20004	62, 7		Sensor	OEM Part No. 25758220	20076	62, 7	
	DTS, Escalade	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20004	62, 7	
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	2007					
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	CTS	Sensor	OEM Part No. 25774006	20116	62, 7	
Sensor		-	20153	11.5, 1.3		Service Pack	-	20004	62, 7	
Service Pack		-	20008	11.5, 1.3	DTS	EZ-Sensor	-	33000*	11.5, 1.3	
SRX	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	-	20153	11.5, 1.3	
	Sensor	-	28206	11.5, 1.3	Service Pack	-	20008	11.5, 1.3		
	Service Pack	-	20008	11.5, 1.3						

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2007 - Continued					2004					
Escalade	EZ-Sensor	-	33000*	11.5, 1.3	CTS	Sensor	-	20116	62, 7	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	-	20004	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Deville	Sensor	-	20117**	62, 7	
	Sensor	Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	20158	62, 7		Service Pack	-	20003	62, 7	
	Sensor	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5, 1.3	Escalade	Sensor	-	20115	62, 7	
	Service Pack	Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	20015	80, 9		Service Pack	-	20004	62, 7	
	Service Pack	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008	11.5, 1.3	Seville	Sensor	-	20117**	62, 7	
						Service Pack	-	20003	62, 7	
SRX	EZ-Sensor	-	33000*	11.5, 1.3	SRX	Sensor	-	20116	62, 7	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	-	20004	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	XLR	Sensor	OEM Part No. 25758220	20076	62, 7	
	Sensor	-	20153	11.5, 1.3		Service Pack	-	20004	62, 7	
	Service Pack	-	20008	11.5, 1.3	2003 - 2001					
Service Pack	-	20004	62, 7	Deville, Seville	Sensor	-	20117**	62, 7		
					Service Pack	-	20003	62, 7		
2006					2011					
CTS	Sensor	OEM Part No. 25774006	20116	62, 7	Avalanche, Aveo	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	-	20004	62, 7		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
DTS	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Sensor	-	20153	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20008	11.5, 1.3	
	Sensor	-	20158	62, 7	Camaro	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	-	20004	62, 7		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
Service Pack	-	20004	62, 7	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		
Escalade	Sensor	-	20107	62, 7	Caprice	Sensor	-	28206	11.5, 1.3	
	Service Pack	-	20004	62, 7		Service Pack	-	20008	11.5, 1.3	
SRX	Sensor	OEM Part No. 25774006	20116	62, 7		Escalade	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20004	62, 7	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7	
STS, XLR	Sensor	OEM Part No. 25758220	20076	62, 7	Caprice		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	-	20004	62, 7		Sensor	-	20158	62, 7	
2005						Colorado	Service Pack	-	20004	62, 7
CTS	Sensor	-	20116	62, 7	Corvette		EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20004	62, 7			EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
Deville	Sensor	-	20117**	62, 7	Escalade	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	-	20003	62, 7		Sensor	-	20158	62, 7	
Escalade	Sensor	-	20107	62, 7		Service Pack	-	20004	62, 7	
	Service Pack	-	20004	62, 7		Cruze Equinox	EZ-Sensor	-	33000*	11.5, 1.3
SRX	Sensor	-	20116	62, 7			EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
	Service Pack	-	20004	62, 7	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
STS, XLR	Sensor	OEM Part No. 25758220	20076	62, 7	Sensor	-	28206	11.5, 1.3		
	Service Pack	-	20004	62, 7	Service Pack	-	20008	11.5, 1.3		

* Programming Tool Required ** Magnet Required to Activate Sensor

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2011 - Continued					2010 - Continued					
Chevrolet - Continued	Express, HHR, Impala, Malibu	EZ-Sensor	-	33000*	11.5, 1.3	Equinox	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Sensor	-	20153	11.5, 1.3		Sensor	-	28206	11.5, 1.3
		Service Pack	-	20008	11.5, 1.3		Service Pack	-	20008	11.5, 1.3
	Silverado Series Pickup	EZ-Sensor	-	33000*	11.5, 1.3	Express	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Sensor	W/Single Rear Wheels	20153	11.5, 1.3		Sensor	-	20153	11.5, 1.3
		Service Pack	W/Single Rear Wheels	20008	11.5, 1.3		Service Pack	-	20008	11.5, 1.3
		Suburban, Tahoe, Traverse	EZ-Sensor	-	33000*	11.5, 1.3	HHR	EZ-Sensor	-	33000*
	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3
	Sensor		-	20153	11.5, 1.3	Sensor		-	28206	11.5, 1.3
	Service Pack		-	20008	11.5, 1.3	Service Pack		-	20008	11.5, 1.3
	Volt	EZ-Sensor	-	33000*	11.5, 1.3	Impala	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Sensor		-	28206	11.5, 1.3	Sensor		-	20153	11.5, 1.3	
Service Pack		-	20008	11.5, 1.3	Service Pack		-	20008	11.5, 1.3	
2010					Chevrolet - Continued	Malibu	EZ-Sensor	-	33000*	11.5, 1.3
Avalanche, Aveo	EZ-Sensor	-	33000*	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			Sensor	-	28206	11.5, 1.3
	Sensor	-	20153	11.5, 1.3			Service Pack	-	20008	11.5, 1.3
	Service Pack	-	20008	11.5, 1.3		Silverado Series Pickup	EZ-Sensor	-	33000*	11.5, 1.3
Camaro, Cobalt	EZ-Sensor	-	33000*	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			Sensor	W/Single Rear Wheels	20153	11.5, 1.3
	Sensor	-	28206	11.5, 1.3			Service Pack	W/Single Rear Wheels	20008	11.5, 1.3
	Service Pack	-	20008	11.5, 1.3		Suburban, Tahoe, Traverse	EZ-Sensor	-	33000*	11.5, 1.3
Colorado	Sensor	-	20131	62, 7			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	-	20006	62, 7			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Corvette	EZ-Sensor	-	33000*	11.5, 1.3			Sensor	-	20153	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			Service Pack	-	20008	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		2009				
	Sensor	-	20158	62, 7		Avalanche, Aveo	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20004	62, 7			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
				EZ-Sensor Service Pack	Rubber Valve		20008	11.5, 1.3		
				Sensor	-		20153	11.5, 1.3		
				Service Pack	-		20008	11.5, 1.3		

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2009 - Continued					2009 - Continued				
Cobalt	EZ-Sensor	-	33000*	11.5, 1.3	Trail-blazer	Sensor	OEM Part No. 25774006	20116	62, 7
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	-	20004	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Traverse	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	Clamp-In Style Only; W/Almm. Valve Stem	20158	62, 7		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
	Sensor	Snap-In Style Only; W/Rubber Valve Stem	20153	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	Clamp-In Style Only; W/Almm. Valve Stem	20004	80, 9		Sensor	-	20153	11.5, 1.3
	Service Pack	Snap-In Style Only; W/Rubber Valve Stem	20008	11.5, 1.3		Service Pack	-	20008	11.5, 1.3
Colorado	Sensor	-	20131	62, 7	Uplander	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20006	62, 7		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
Corvette	Sensor	OEM Part No. 25758220	20076	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	-	20004	62, 7		Sensor	-	20158	62, 7
Equinox, Express	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20004	62, 7	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	2008				
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Avalanche, Aveo	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	20158	62, 7		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
	Service Pack	W/Schrader Sensor	20004	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	W/Siemens Sensor	20030	80, 9		Sensor	-	20153	11.5, 1.3
HHR	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	-	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	Cobalt	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
	Sensor	Clamp-In Style Only; W/Almm. Valve Stem	20158	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	Snap-In Style Only; W/Rubber Valve Stem	20153	11.5, 1.3		Sensor	Clamp-In Style Only; W/Almm. Valve Stem	20158	62, 7
	Service Pack	Clamp-In Style Only; W/Almm. Valve Stem	20004	80, 9		Sensor	Snap-In Style Only; W/Rubber Valve Stem	20153	11.5, 1.3
	Service Pack	Snap-In Style Only; W/Rubber Valve Stem	20008	11.5, 1.3		Service Pack	Clamp-In Style Only; W/Almm. Valve Stem	20004	80, 9
Impala, Malibu	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	Snap-In Style Only; W/Rubber Valve Stem	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	Colorado	Sensor	-	20131	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20006	62, 7
	Sensor	-	20153	11.5, 1.3	Corvette	Sensor	OEM Part No. 25758220	20076	62, 7
	Service Pack	-	20008	11.5, 1.3		Service Pack	-	20004	62, 7
Silverado Series Pickup	EZ-Sensor	-	33000*	11.5, 1.3	Equinox, Express	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	W/Single Rear Wheels	20153	11.5, 1.3		Sensor	-	20158	62, 7
	Service Pack	W/Single Rear Wheels	20008	11.5, 1.3		Service Pack	W/Schrader Sensor	20004	62, 7
Suburban, Tahoe	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	W/Siemens Sensor	20030	80, 9	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	HHR	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
	Sensor	-	20153	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Service Pack	-	20008	11.5, 1.3						

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2008 - Continued					2007 - Continued					
Chevrolet - Continued	HHR	Sensor	Clamp-In Style Only; W/Almm. Valve Stem	20158	62, 7	Avalanche - Cont'd.	Sensor	Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	20158	62, 7
		Sensor	Snap-In Style Only; W/Rubber Valve Stem	20153	11.5, 1.3		Sensor	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5, 1.3
		Service Pack	Clamp-In Style Only; W/Almm. Valve Stem	20004	80, 9		Service Pack	Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	20015	80, 9
		Service Pack	Snap-In Style Only; W/Rubber Valve Stem	20008	11.5, 1.3		Service Pack	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008	11.5, 1.3
	Impala	EZ-Sensor	-	33000*	11.5, 1.3		Aveo	EZ-Sensor	-	33000*
		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3
		Sensor	-	20153	11.5, 1.3	Sensor		Hatchback	20153	11.5, 1.3
		Malibu	Service Pack	-	20008	11.5, 1.3	Service Pack	-	20008	11.5, 1.3
	EZ-Sensor		-	33000*	11.5, 1.3	Colorado	Sensor	-	20131	62, 7
			Almm. Valve	34000	62, 7		Service Pack	-	20006	62, 7
	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Corvette	Sensor	OEM Part No. 25758220	20076	62, 7
			Sensor	Clamp-In Style Only; W/Almm. Valve Stem	20158		62, 7	Service Pack	-	20004
	Sensor		Snap-In Style Only; W/Rubber Valve Stem	20153	11.5, 1.3	Equinox	EZ-Sensor	-	33000*	11.5, 1.3
			Service Pack	Clamp-In Style Only; W/Almm. Valve Stem	20004		80, 9	EZ-Sensor Service Pack	Almm. Valve	34000
	Service Pack		Snap-In Style Only; W/Rubber Valve Stem	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Silverado Series Pickup	EZ-Sensor		-	33000*	11.5, 1.3		Sensor	-	20158	62, 7
	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7		Service Pack	W/Schrader Sensor	20004	62, 7
Suburban, Tahoe	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	W/Siemens Sensor	20030	80, 9		
		Sensor	W/Single Rear Wheels	20153	11.5, 1.3	Impala, Monte Carlo	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	W/Single Rear Wheels	20008	11.5, 1.3	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
		Sensor	-	20153	11.5, 1.3		Sensor	Clamp-In Style Only; W/Almm. Valve Stem	20158	62, 7
	Service Pack	-	20008	11.5, 1.3	Service Pack		Snap-In Style Only; W/Rubber Valve Stem	20153	11.5, 1.3	
Sensor		OEM Part No. 25774006	20116	62, 7	Service Pack	Clamp-In Style Only; W/Almm. Valve Stem	20004	62, 7		
Trail- blazer	Service Pack	-	20004	62, 7	Silverado Series Pickup	EZ-Sensor	-	33000*	11.5, 1.3	
	Uplander	EZ-Sensor	-	33000*		11.5, 1.3	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
EZ-Sensor Service Pack		Almm. Valve	34000	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		Sensor	Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic	20158	62, 7	
Sensor		-	20158	62, 7		Sensor	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic	20153	11.5, 1.3	
Service Pack	-	20004	62, 7	Service Pack	Classic	20107	62, 7			
2007					Service Pack	Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic	20015	80, 9		
Avalanche	EZ-Sensor	-	33000*	11.5, 1.3						
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7						
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3						

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2007 - Continued					2005 - Continued					
Silverado Series Pickup - Cont'd.	Service Pack	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic	20008	11.5, 1.3	Silverado Series Pickup, Suburban, Tahoe	Sensor	-	20107	62, 7	
	Service Pack	Classic	20004	62, 7		Service Pack	-	20004	62, 7	
Suburban, Tahoe	EZ-Sensor	-	33000*	11.5, 1.3	2004					
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	Avalanche	Sensor	-	20115	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20004	62, 7	
	Sensor	Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	20158	62, 7	Corvette	Sensor	-	20117**	62, 7	
	Sensor	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5, 1.3		Service Pack	-	20003	62, 7	
	Service Pack	Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	20015	80, 9	Silverado Series Pickup, Suburban, Tahoe	Sensor	-	20115	62, 7	
	Service Pack	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008	11.5, 1.3		Service Pack	-	20004	62, 7	
	Trail-blazer	Sensor	OEM Part No. 25774006	20116	62, 7	2003 - 2001				
Service Pack		-	20004	62, 7	Corvette	Sensor	-	20117**	62, 7	
2006						Service Pack	-	20003	62, 7	
Avalanche	Sensor	-	20107	62, 7	2000 - 1997					
	Service Pack	-	20004	62, 7	Corvette	Sensor	-	28006**	62, 7	
Corvette	Sensor	OEM Part No. 25758220	20076	62, 7		Service Pack	-	20012	62, 7	
	Service Pack	-	20004	62, 7	2011					
Impala, Monte Carlo	EZ-Sensor	-	33000*	11.5, 1.3	200	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	W/Alloy Wheels	20158	62, 7		Sensor	-	20066	58, 6.5	
	Service Pack	W/Alloy Wheels	20004	62, 7		Sensor	-	28308	11.5, 1.3	
	Sensor	-	20107	62, 7		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
	Service Pack	-	20004	62, 7		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	
	SSR	Sensor	OEM Part No. 25774006	20116		62, 7	300, Town & Country Van	Sensor	-	20398
Service Pack		-	20004	62, 7		Service Pack		-	20008	11.5, 1.3
Suburban, Tahoe	Sensor	-	20107	62, 7		2010				
	Service Pack	-	20004	62, 7	300	Sensor	-	28291	58, 6.5	
Trail-blazer	Sensor	OEM Part No. 25774006	20116	62, 7		Service Pack	Does Not Include Stem	20016	58, 6.5	
	Service Pack	-	20004	62, 7		Service Pack	Includes Stem Only	20020	58, 6.5	
2005					PT Cruiser	EZ-Sensor	-	33000*	11.5, 1.3	
Avalanche	Sensor	-	20107	62, 7		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
	Service Pack	-	20004	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
Corvette	Sensor	OEM Part No. 25758220	20076	62, 7		Sensor	-	20066	58, 6.5	
	Service Pack	-	20004	62, 7		Sensor	-	28308	11.5, 1.3	

* Programming Tool Required ** Magnet Required to Activate Sensor

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2010 - Continued					2008 - Continued				
PT Cruiser - Cont'd.	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	Crossfire	Sensor	-	20028**	35, 4
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		Service Pack	W/Schrader Sensor	20003	35, 4
	Service Pack	W/Siemens Sensor	20030	71, 8		Service Pack	W/Siemens Sensor	20030	35, 4
Sebring	EZ-Sensor	-	33000*	11.5, 1.3	Pacifica, PT Cruiser, Sebring	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	20066	58, 6.5		Sensor	-	20066	58, 6.5
	Sensor	-	28308	11.5, 1.3		Sensor	-	28308	11.5, 1.3
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5
	Service Pack	W/Siemens Sensor	20030	71, 8		Service Pack	W/Siemens Sensor	20030	71, 8
2009					Town & Country Van				
300	Sensor	-	28291	58, 6.5	Sensor	-	28155	58, 6.5	
	Service Pack	Does Not Include Stem	20016	58, 6.5	Sensor	-	28434	11.5, 1.3	
	Service Pack	Includes Stem Only	20020	58, 6.5	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
Aspen, PT Cruiser, Sebring	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	W/Siemens Sensor	20030	71, 8	
	Sensor	-	20066	58, 6.5	2007				
	Sensor	-	28308	11.5, 1.3	300, Aspen	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	W/Siemens Sensor	20030	71, 8		Sensor	-	20066	58, 6.5
Town & Country Van	Sensor	-	28155	58, 6.5		Sensor	-	28308	11.5, 1.3
	Sensor	-	28434	11.5, 1.3		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		Service Pack	W/Siemens Sensor	20030	71, 8
	Service Pack	W/Siemens Sensor	20030	71, 8	Crossfire	Sensor	-	20028**	35, 4
2008						Service Pack	W/Schrader Sensor	20003	35, 4
300	Sensor	-	28155	58, 6.5		Service Pack	W/Siemens Sensor	20030	35, 4
	Sensor	-	28434	11.5, 1.3	Pacifica, Sebring, Town & Country Van	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Service Pack	W/Siemens Sensor	20030	71, 8	Sensor		-	20066	58, 6.5	
Aspen	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	-	28308	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5
	Sensor	-	20066	58, 6.5		Service Pack	W/Siemens Sensor	20030	71, 8
	Sensor	-	28308	11.5, 1.3	2006				
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	300	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	W/Siemens Sensor	20030	71, 8		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Service Pack	W/Siemens Sensor	20030	71, 8	Sensor		-	20066	58, 6.5	

* Programming Tool Required ** Magnet Required to Activate Sensor

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
2006 - Continued					2004						
Chrysler - Continued	300 - Cont'd.	Sensor	-	28308	11.5, 1.3	300M, Concorde, Crossfire, Intrepid	Sensor	-	20028**	35, 4	
		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		Service Pack	W/Schrader Sensor	20003	35, 4	
		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		Service Pack	W/Siemens Sensor	20030	35, 4	
		Service Pack	W/Siemens Sensor	20030	71, 8	Pacifica	Sensor	OEM Part No. 04727392AD	20335	71, 8	
	Crossfire	Sensor	-	20028**	35, 4		Sensor	OEM Part No. 52088990AC	20028**	35, 4	
		Service Pack	W/Schrader Sensor	20003	35, 4		Service Pack	OEM Part No. 04727392AD	20030	71, 8	
		Service Pack	W/Siemens Sensor	20030	35, 4		Service Pack	OEM Part No. 52088990AC	20003	35, 4	
	Pacifica, Town & Country Van	EZ-Sensor	-	33000*	11.5, 1.3	Town & Country Van	Sensor	-	20335	71, 8	
		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	-	20030	71, 8	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	2003					
		Sensor	-	20066	58, 6.5	300M, Concorde, Intrepid	Sensor	-	20028**	35, 4	
		Sensor	-	28308	11.5, 1.3		Service Pack	W/Schrader Sensor	20003	35, 4	
Service Pack		W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	Service Pack		W/Siemens Sensor	20030	35, 4		
Service Pack		W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Town & Country Van, Voyager	Sensor	-	20028**	35, 4		
Service Pack		W/Siemens Sensor	20030	71, 8		Service Pack	-	20003	35, 4		
2005						2002					
300	EZ-Sensor	-	33000*	11.5, 1.3		300M, Concorde, Intrepid, Prowler	Sensor	-	20028**	35, 4	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	Service Pack		W/Schrader Sensor	20003	35, 4		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack		W/Siemens Sensor	20030	35, 4		
	Sensor	-	20066	58, 6.5	Town & Country Van, Voyager	Sensor	-	20028**	35, 4		
	Sensor	-	28308	11.5, 1.3		Service Pack	-	20003	35, 4		
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		2001					
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		Prowler	Sensor	-	28004	35, 4	
	Service Pack	W/Siemens Sensor	20030	71, 8	Service Pack		W/Black Sensor Body	20012	35, 4		
	Service Pack	W/Siemens Sensor	20030	71, 8	Service Pack		W/Red Sensor Body	20003	35, 4		
	Crossfire	EZ-Sensor	-	33000*	11.5, 1.3	2011					
		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	Dodge	Caliber	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		
Sensor		OEM Part No. 5142340AA	20066	58, 6.5	Sensor		-	20066	58, 6.5		
Sensor		OEM Part No. 5142340AA	28308	11.5, 1.3	Sensor		-	28308	11.5, 1.3		
Sensor		OEM Part No. 52088990AC	20028**	35, 4	Service Pack		W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		
Service Pack		OEM Part No. 5142340AA; Does Not Include Stem	20013	58, 6.5	Service Pack		W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		
Service Pack	OEM Part No. 5142340AA; Includes Stem Only	20020	58, 6.5								
Pacifica, Town & Country Van	Sensor	-	20335	71, 8							
	Service Pack	-	20030	71, 8							

* Programming Tool Required ** Magnet Required to Activate Sensor

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2011 - Continued					2010 - Continued				
Challenger	Sensor	W/Metal Stem Clamp-in Sensor	28291	58, 6.5	Caliber - Cont'd.	Sensor	-	20066	58, 6.5
	Sensor	W/Rubber Stem Snap-in Sensor	20398	11.5, 1.3		Sensor	-	28308	11.5, 1.3
	Service Pack	W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58, 6.5		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5
	Service Pack	W/Metal Stem Clamp-in Sensor; Includes Stem Only	20020	58, 6.5		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5
	Service Pack	W/Rubber Stem Snap-in Sensor	20008	11.5, 1.3		Service Pack	W/Siemens Sensor	20030	71, 8
Charger	Sensor	W/Rubber Stem Snap-in Sensor	20398	11.5, 1.3	Challenger, Charger	Sensor	W/Metal Stem Clamp-in Sensor	28291	58, 6.5
	Service Pack	W/Rubber Stem Snap-in Sensor	20008	11.5, 1.3		Sensor	W/Rubber Stem Snap-in Sensor	20398	11.5, 1.3
Dakota	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58, 6.5
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	W/Metal Stem Clamp-in Sensor; Includes Stem Only	20020	58, 6.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	W/Rubber Stem Snap-in Sensor	20008	11.5, 1.3
	Sensor	-	20066	58, 6.5	Dakota	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	28308	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	Does Not Include Stem	20013	58, 6.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	Includes Stem Only	20020	58, 6.5		Sensor	-	28154	58, 6.5
	Durango, Grand Caravan	Sensor	-	20398		11.5, 1.3	Sensor	-	28461
Service Pack		-	20008	11.5, 1.3		Service Pack	Does Not Include Stem	20013	58, 6.5
Journey, Nitro	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	Includes Stem Only	20020	58, 6.5
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Grand Caravan, Journey	Sensor	-	28155
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor		-	28434	11.5, 1.3
	Sensor	-	20066	58, 6.5	Service Pack		W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5
	Sensor	-	28308	11.5, 1.3	Service Pack		W/Schrader Sensor; Includes Stem Only	20020	58, 6.5
	Service Pack	Does Not Include Stem	20013	58, 6.5	Service Pack	W/Siemens Sensor	20030	71, 8	
	Service Pack	Includes Stem Only	20020	58, 6.5	Nitro	EZ-Sensor	-	33000*	11.5, 1.3
	Ram Series Pickup	Sensor	W/Rubber Stem Snap-in Sensor	20398		11.5, 1.3	EZ-Sensor Service Pack	Almnm. Valve	34000
Service Pack		W/Rubber Stem Snap-in Sensor	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
2010						Sensor	-	20066	58, 6.5
Avenger	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	-	28308	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	Does Not Include Stem	20013	58, 6.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	Includes Stem Only	20020	58, 6.5
	Sensor	-	20066	58, 6.5		Ram Series Pickup	Sensor	1500, 2500; W/Metal Stem Clamp-in Sensor	28155
	Sensor	-	28308	11.5, 1.3	Sensor		1500, 2500; W/Metal Stem Clamp-in Sensor	28434	11.5, 1.3
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	Sensor		W/Rubber Stem Snap-in Sensor	20398	11.5, 1.3
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Service Pack		1500, 2500; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20013	58, 6.5
	Caliber	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	1500, 2500; W/Metal Stem Clamp-in Sensor; Includes Stem Only	20020	58, 6.5
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	Service Pack	W/Rubber Stem Snap-in Sensor	20008	11.5, 1.3	
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Viper	Sensor	-	20028**	35, 4
				Service Pack		-	20003	35, 4	

* Programming Tool Required ** Magnet Required to Activate Sensor

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2009					2009 - Continued					
Avenger, Caliber	EZ-Sensor	-	33000*	11.5, 1.3	Sprinter	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	20066	58, 6.5		Sensor	-	20089	53, 6	
	Sensor	-	28308	11.5, 1.3		Service Pack	Does Not Include Valve	20021	53, 6	
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		Service Pack	Includes Valve	20036	53, 6	
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		Viper	Sensor	-	20028**	35, 4
	Service Pack	W/Siemens Sensor	20030	71, 8	Service Pack		-	20003	35, 4	
	Challenger, Charger	Sensor	-	28291	58, 6.5	2008				
Service Pack		Does Not Include Stem	20016	58, 6.5	Avenger, Caliber	EZ-Sensor	-	33000*	11.5, 1.3	
Service Pack		Includes Stem Only	20020	58, 6.5		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	
Dakota	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		Sensor	-	20066	58, 6.5	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	-	28308	11.5, 1.3	
	Sensor	-	28154	58, 6.5		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
	Sensor	-	28461	11.5, 1.3		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	
	Service Pack	Does Not Include Stem	20013	58, 6.5		Service Pack	W/Siemens Sensor	20030	71, 8	
	Service Pack	Includes Stem Only	20020	58, 6.5		Challenger	Sensor	-	28291	58, 6.5
	Durango	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	Does Not Include Stem	20016	58, 6.5
		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		Service Pack	Includes Stem Only	20020	58, 6.5
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Charger	Sensor	-	28155	58, 6.5	
Sensor		-	20066	58, 6.5		Sensor	-	28434	11.5, 1.3	
Sensor		-	28308	11.5, 1.3		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
Service Pack		Does Not Include Stem	20013	58, 6.5	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		
Service Pack		Includes Stem Only	20020	58, 6.5	Service Pack	W/Siemens Sensor	20030	71, 8		
Grand Caravan, Journey		Sensor	-	28155	58, 6.5	Dakota	EZ-Sensor	-	33000*	11.5, 1.3
		Sensor	-	28434	11.5, 1.3		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Sensor		-	28154	58, 6.5	
	Service Pack	W/Siemens Sensor	20030	71, 8	Sensor		-	28461	11.5, 1.3	
Nitro	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack		Does Not Include Stem	20013	58, 6.5	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Service Pack		Includes Stem Only	20020	58, 6.5	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Durango		EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	20066	58, 6.5			EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Sensor	-	28308	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	Does Not Include Stem	20013	58, 6.5		Sensor	-	20066	58, 6.5	
	Service Pack	Includes Stem Only	20020	58, 6.5		Sensor	-	28308	11.5, 1.3	
	Ram Series Pickup	Sensor	1500, 2500	28155		58, 6.5	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5
		Sensor	1500, 2500	28434		11.5, 1.3	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5
Service Pack		1500, 2500; Does Not Include Stem	20013	58, 6.5		Service Pack	W/Siemens Sensor	20030	71, 8	
Grand Caravan, Magnum		Service Pack	1500, 2500; Includes Stem Only	20020		58, 6.5	Sensor	-	28155	58, 6.5
		Sensor	-	28434	11.5, 1.3	Sensor	-	28434	11.5, 1.3	
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5						

* Programming Tool Required ** Magnet Required to Activate Sensor

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2008 - Continued					2006					
Grand Caravan, Magnum	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Caravan, Charger, Grand Caravan, Magnum	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	W/Siemens Sensor	20030	71, 8		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
Nitro	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Sensor	-	20066	58, 6.5	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	-	28308	11.5, 1.3	
	Sensor	-	20066	58, 6.5		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
	Sensor	-	28308	11.5, 1.3		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		Service Pack	W/Siemens Sensor	20030	71, 8	
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		Viper	Sensor	-	20028**	35, 4
	Service Pack	W/Siemens Sensor	20030	71, 8			Service Pack	-	20003	35, 4
Ram Series Pickup	EZ-Sensor	1500, 2500	33000*	11.5, 1.3	2005					
	EZ-Sensor Service Pack	1500, 2500; Almm. Valve	34000	62, 7	Caravan, Grand Caravan	Sensor	-	20335	71, 8	
	EZ-Sensor Service Pack	1500, 2500; Rubber Valve	20008	11.5, 1.3		Service Pack	-	20030	71, 8	
	Sensor	1500, 2500	28154	58, 6.5	Magnum	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	1500, 2500	28461	11.5, 1.3		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
	Service Pack	1500, 2500; Does Not Include Stem	20013	58, 6.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	1500, 2500; Includes Stem Only	20020	58, 6.5		Sensor	-	20066	58, 6.5	
	Sprinter	EZ-Sensor	-	33000*		11.5, 1.3	Sensor	-	28308	11.5, 1.3
EZ-Sensor Service Pack		Almm. Valve	34000	62, 7		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		
Sensor		-	20089	53, 6	Service Pack	W/Siemens Sensor	20030	71, 8		
Service Pack		Does Not Include Valve	20021	53, 6	Viper	Sensor	-	20028**	35, 4	
Service Pack		Includes Valve	20036	53, 6		Service Pack	-	20003	35, 4	
Viper	Sensor	-	20028**	35, 4	2004					
	Service Pack	-	20003	35, 4	Caravan, Grand Caravan	Sensor	-	20335	71, 8	
2007						Service Pack	-	20030	71, 8	
Caliber, Caravan, Charger, Durango, Grand Caravan, Magnum, Nitro	EZ-Sensor	-	33000*	11.5, 1.3	Intrepid, Viper	Sensor	-	20028**	35, 4	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	-	20003	35, 4	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	2003					
	Sensor	-	20066	58, 6.5	Caravan, Grand Caravan, Intrepid, Viper	Sensor	-	20028**	35, 4	
	Sensor	-	28308	11.5, 1.3		Service Pack	-	20003	35, 4	
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	2002					
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Caravan, Grand Caravan, Intrepid	Sensor	-	20028**	35, 4	
	Service Pack	W/Siemens Sensor	20030	71, 8		Service Pack	-	20003	35, 4	
	Sprinter	EZ-Sensor	-	33000*	11.5, 1.3					
		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7					
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3						
Sensor		-	20089	53, 6						
Service Pack		Does Not Include Valve	20021	53, 6						
Service Pack	Includes Valve	20036	53, 6							

* Programming Tool Required ** Magnet Required to Activate Sensor

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2009 - 2006					2011				
612 Scaglietti, F430	Sensor	Includes Transmitter Only	20077	35, 4	Crown Victoria	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	Does Not Include Valve	20023	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	W/43mm Silver Insert	20037	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	W/48mm Green Insert	20038	35, 4		Sensor	-	28385	27, 3
	Service Pack	W/49mm Black Insert	20039	35, 4		Sensor Clip	-	22100	-
	Service Pack	W/51mm Orange Insert	20040	35, 4		Sensor Cradle	-	22101	-
2005									
575M Maranello, 612 Scaglietti, F430	Sensor	Includes Transmitter Only	20077	35, 4					
	Service Pack	Does Not Include Valve	20023	35, 4					
	Service Pack	W/43mm Silver Insert	20037	35, 4					
	Service Pack	W/48mm Green Insert	20038	35, 4					
	Service Pack	W/49mm Black Insert	20039	35, 4					
	Service Pack	W/51mm Orange Insert	20040	35, 4					
2004									
575M Maranello, 612 Scaglietti	Sensor	Includes Transmitter Only	20077	35, 4					
	Service Pack	Does Not Include Valve	20023	35, 4					
	Service Pack	W/43mm Silver Insert	20037	35, 4					
	Service Pack	W/48mm Green Insert	20038	35, 4					
	Service Pack	W/49mm Black Insert	20039	35, 4					
	Service Pack	W/51mm Orange Insert	20040	35, 4					
Enzo	Sensor	Includes Transmitter Only	20084	-					
	Service Pack	Does Not Include Valve	20023	35, 4					
	Service Pack	W/43mm Silver Insert	20037	35, 4					
	Service Pack	W/48mm Green Insert	20038	35, 4					
	Service Pack	W/49mm Black Insert	20039	-					
	Service Pack	W/51mm Orange Insert	20040	-					
2003									
575M Maranello	Sensor	Includes Transmitter Only	20077	35, 4					
	Service Pack	Does Not Include Valve	20023	-					
	Service Pack	W/43mm Silver Insert	20037	-					
	Service Pack	W/48mm Green Insert	20038	-					
	Service Pack	W/49mm Black Insert	20039	-					
	Service Pack	W/51mm Orange Insert	20040	-					
Enzo	Sensor	Includes Transmitter Only	20084	-					
	Service Pack	Does Not Include Valve	20023	-					
	Service Pack	W/43mm Silver Insert	20037	-					
	Service Pack	W/48mm Green Insert	20038	-					
	Service Pack	W/49mm Black Insert	20039	-					
	Service Pack	W/51mm Orange Insert	20040	-					
2002									
550 Maranello, 575M Maranello,	Sensor	Includes Transmitter Only	20077	35, 4					
	Service Pack	Does Not Include Valve	20023	-					
	Service Pack	W/43mm Silver Insert	20037	-					
	Service Pack	W/48mm Green Insert	20038	-					
	Service Pack	W/49mm Black Insert	20039	-					
	Service Pack	W/51mm Orange Insert	20040	-					
550 Maranello	Sensor	Includes Transmitter Only	20077	35, 4					
	Service Pack	Does Not Include Valve	20023	-					
	Service Pack	W/43mm Silver Insert	20037	-					
	Service Pack	W/48mm Green Insert	20038	-					
	Service Pack	W/49mm Black Insert	20039	-					
	Service Pack	W/51mm Orange Insert	20040	-					
Ford									
					E Series Van, Edge	EZ-Sensor	-	33000*	11.5, 1.3
						EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
						EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
						Sensor	-	20315	13, 1.5
						Sensor	-	20315	13, 1.5
						Sensor	-	20315	13, 1.5
					Escape	EZ-Sensor	-	33000*	11.5, 1.3
						EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
						EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
						Sensor	-	20315	13, 1.5
						Sensor	-	20315	13, 1.5
						Sensor	-	20315	13, 1.5
					Expedition, Explorer, F Series Pickup	EZ-Sensor	-	33000*	11.5, 1.3
						EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
						EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
						Sensor	-	20315	13, 1.5
						Sensor	-	20315	13, 1.5
						Sensor	-	20315	13, 1.5
					Fiesta	EZ-Sensor	-	33000*	11.5, 1.3
						EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
						EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
						Sensor	-	20315	13, 1.5
						Service Pack	-	20018	13, 1.5
						Service Pack	-	20018	13, 1.5
					Flex	EZ-Sensor	-	33000*	11.5, 1.3
						EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
						EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
						Sensor	-	20315	13, 1.5
						Sensor	-	20315	13, 1.5
						Sensor	-	20315	13, 1.5
					Focus, Fusion	EZ-Sensor	-	33000*	11.5, 1.3
						EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
						EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
						Sensor	-	20315	13, 1.5
						Sensor	-	20315	13, 1.5
						Sensor	-	20315	13, 1.5
					Mustang	EZ-Sensor	-	33000*	11.5, 1.3
						EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
						EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
						Sensor	-	20315	13, 1.5
						Service Pack	-	20018	13, 1.5
						Service Pack	-	20018	13, 1.5
					Ranger	EZ-Sensor	-	33000*	11.5, 1.3
						EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2011 - Continued					2010 - Continued					
Ranger - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Edge	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	-	28385	27, 3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor Clip	-	22100	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor Cradle	-	22101	-		Sensor	-	28390	27, 3	
	Sensor Universal Band	-	22102	-		Sensor Clip	-	22100	-	
	Super Duty Pickup, Super Duty Van	EZ-Sensor	-	33000*		11.5, 1.3	Sensor Cradle	-	22101	-
		EZ-Sensor Service Pack	Almnm. Valve	34000		62, 7	Sensor Universal Band	-	22102	-
		EZ-Sensor Service Pack	Rubber Valve	20008		11.5, 1.3	Escape	EZ-Sensor	-	33000*
	Sensor	-	20315	13, 1.5		EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7
	Taurus	EZ-Sensor	-	33000*		11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	Sensor	-		20315	13, 1.5	
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Service Pack	-		20018	13, 1.5	
Sensor		-	20315	13, 1.5	Expedition	EZ-Sensor	-	33000*	11.5, 1.3	
Service Pack		-	20018	13, 1.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
Transit Connect	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	28390	27, 3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Clip	-	22100	-	
	Sensor	-	20315	13, 1.5	Sensor Cradle	-	22101	-		
2010					2010					
Crown Victoria	EZ-Sensor	-	33000*	11.5, 1.3	Explorer, Explorer Sport Trac	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	28385	27, 3		Sensor	-	28385	27, 3	
	Sensor Clip	-	22100	-		Sensor Clip	-	22100	-	
	Sensor Cradle	-	22101	-		Sensor Cradle	-	22101	-	
	Sensor Universal Band	-	22102	-		Sensor Universal Band	-	22102	-	
	E450 Super Duty	EZ-Sensor	-	33000*		11.5, 1.3	F450 Super Duty, F550 Super Duty	EZ-Sensor	-	33000*
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	EZ- sensor Service Pack	Almnm. Valve		34000	62, 7	
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	EZ- sensorService Pack	Rubber Valve		20008	11.5, 1.3	
Sensor		-	20315	13, 1.5	Sensor	-		28395	27, 3	
Service Pack		-	20018	13, 1.5	Sensor Clip	-		22100	-	
E Series Van	EZ-Sensor	W/Alloy Wheels	33000*	11.5, 1.3	Sensor Cradle	-	22101	-		
	EZ-Sensor Service Pack	W/Alloy Wheels; Almnm. Valve	34000	62, 7	Sensor Universal Band	-	22102	-		
	EZ-Sensor Service Pack	W/Alloy Wheels; Rubber Valve	20008	11.5, 1.3	F Series Pickup	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	W/Alloy Wheels	28395	27, 3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	W/Steel Wheels	20315	13, 1.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor Clip	W/Alloy Wheels	22100	-		Sensor	-	20315	13, 1.5	
	Sensor Cradle	W/Alloy Wheels	22101	-		Service Pack	-	20018	13, 1.5	
	Sensor Universal Band	W/Alloy Wheels	22102	-	Flex	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	W/Steel Wheels	20018	13, 1.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2010 - Continued					2010 - Continued				
Flex - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Super Duty Van	Sensor	W/Steel Wheels	20315	13, 1.5
	Sensor	-	28390	27, 3		Sensor Clip	W/Alloy Wheels	22100	-
	Sensor Clip	-	22100	-		Sensor Cradle	W/Alloy Wheels	22101	-
	Sensor Cradle	-	22101	-		Sensor Universal Band	W/Alloy Wheels	22102	-
	Sensor Universal Band	-	22102	-		Service Pack	W/Steel Wheels	20018	13, 1.5
Focus, Fusion	EZ-Sensor	-	33000*	11.5, 1.3	Taurus	EZ-Sensor	Apr. & Older	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Apr. & Older; Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Apr. & Older; Rubber Valve	20008	11.5, 1.3
	Sensor	-	20315	13, 1.5		Sensor	May & Newer	20315	13, 1.5
	Service Pack	-	20018	13, 1.5		Sensor	Apr. & Older	28390	27, 3
Grand Marquis	EZ-Sensor	-	33000*	11.5, 1.3		Sensor Clip	Apr. & Older	22100	-
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor Cradle	Apr. & Older	22101	-
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Universal Band	Apr. & Older	22102	-
	Sensor	-	28385	27, 3		Service Pack	May & Newer	20018	13, 1.5
	Sensor Clip	-	22100	-	Transit Connect	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Cradle	-	22101	-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor Universal Band	-	22102	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Sensor	-	28385	27, 3	Sensor		-	20315	13, 1.5	
Mustang	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20018	13, 1.5	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	2009				
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Crown Victoria	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	20315	13, 1.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	-	20018	13, 1.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Ranger	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	-	28385	27, 3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor Clip	-	22100	-
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Cradle	-	22101	-
	Sensor	-	28385	27, 3	Sensor Universal Band	-	22102	-	
	Sensor Clip	-	22100	-	E450 Super Duty, E Series Van	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Cradle	-	22101	-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor Universal Band	-	22102	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Super Duty Pickup	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	-	28395	27, 3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor Clip	-	22100	-
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor Cradle	-	22101	-	
	Sensor	-	28395	27, 3	Sensor Universal Band	-	22102	-	
	Sensor Clip	-	22100	-	Edge	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Cradle	-	22101	-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor Universal Band	-	22102	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Super Duty Van	EZ-Sensor	W/Alloy Wheels	33000*		11.5, 1.3	Sensor	-	28390
EZ-Sensor Service Pack		W/Alloy Wheels; Almnm. Valve	34000	62, 7		Sensor Clip	-	22100	-
EZ-Sensor Service Pack		W/Alloy Wheels; Rubber Valve	20008	11.5, 1.3	Sensor Cradle	-	22101	-	
Sensor		W/Alloy Wheels	28395	27, 3	Sensor Universal Band	-	22102	-	

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2009 - Continued					2009 - Continued					
Escape	EZ-Sensor	-	33000*	11.5, 1.3	Fusion, Grand Marquis, Mustang, Ranger	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	20315	13, 1.5		Sensor	-	28385	27, 3	
	Service Pack	-	20018	13, 1.5		Sensor Clip	-	22100	-	
Expedition	EZ-Sensor	-	33000*	11.5, 1.3		Sensor Cradle	-	22101	-	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor Universal Band	-	22102	-	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Super Duty Pickup, Super Duty Van	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	28390	27, 3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor Clip	-	22100	-			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor Cradle	-	22101	-	Sensor		-	28395	27, 3	
Sensor Universal Band	-	22102	-	Sensor Clip	-		22100	-		
Explorer, Explorer Sport Trac	EZ-Sensor	-	33000*	11.5, 1.3	Sensor Cradle		-	22101	-	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Sensor Universal Band		-	22102	-	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Taurus, Taurus X		EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	28385	27, 3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor Clip	-	22100	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor Cradle	-	22101	-		Sensor	-	28390	27, 3	
Sensor Universal Band	-	22102	-	Sensor Clip		-	22100	-		
F450 Super Duty	EZ-Sensor	-	33000*	11.5, 1.3		Sensor Cradle	-	22101	-	
	EZ-sensorService Pack	Almnm. Valve	34000	62, 7	Sensor Universal Band	-	22102	-		
	EZ-sensorService Pack	Rubber Valve	20008	11.5, 1.3	2008					
	Sensor	-	28395	27, 3	Crown Victoria	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor Clip	-	22100	-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor Cradle	-	22101	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor Universal Band	-	22102	-		Sensor	-	28385	27, 3	
	F Series Pickup	EZ-Sensor	-	33000*		11.5, 1.3	Sensor Clip	-	22100	-
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7		Sensor Cradle	-	22101	-	
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		Sensor Universal Band	-	22102	-	
Sensor		-	20315	13, 1.5		E450 Super Duty, E Series Van	EZ-Sensor	-	33000*	11.5, 1.3
Service Pack		-	20018	13, 1.5	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	
Flex, Focus	EZ-Sensor	-	33000*	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Sensor		-	28395	27, 3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor Clip		-	22100	-	
	Sensor	-	28390	27, 3	Sensor Cradle		-	22101	-	
	Sensor Clip	-	22100	-	Sensor Universal Band		-	22102	-	
	Sensor Cradle	-	22101	-	Edge		EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Universal Band	-	22102	-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
						EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
				Sensor		W/Chrome Plated Almnm. Wheels	28385	27, 3		

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
2008 - Continued					2008 - Continued						
Ford - Continued	Edge - Cont'd.	Sensor	W/O Chrome Plated Almm. Wheels	28390	27, 3	Focus	EZ-Sensor	-	33000*	11.5, 1.3	
		Sensor Clip	-	22100	-		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
		Sensor Cradle	-	22101	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
		Sensor Universal Band	-	22102	-		Sensor	-	28390	27, 3	
	Escape	EZ-Sensor	-	33000*	11.5, 1.3		Sensor Clip	-	22100	-	
		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Sensor Cradle	-	22101	-	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Universal Band	-	22102	-	
		Sensor	-	28385	27, 3		Fusion, Grand Marquis, Mustang, Ranger	EZ-Sensor	-	33000*	11.5, 1.3
		Sensor Clip	-	22100	-			EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
		Sensor Cradle	-	22101	-			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Sensor Universal Band	-	22102	-			Sensor	-	28385	27, 3
		Expedition	EZ-Sensor	-	33000*			11.5, 1.3	Sensor Clip	-	22100
	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7	Sensor Cradle		-	22101	-	
	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Sensor Universal Band		-	22102	-	
	Sensor		-	28390	27, 3	Super Duty Pickup, Super Duty Van		EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Clip		-	22100	-		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
	Sensor Cradle		-	22101	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor Universal Band	-	22102	-	Sensor		-	28395	27, 3		
	Explorer, Explorer Sport Trac	EZ-Sensor	-	33000*	11.5, 1.3		Sensor Clip	-	22100	-	
		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Sensor Cradle	-	22101	-	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Universal Band	-	22102	-	
		Sensor	-	28385	27, 3		Taurus, Taurus X	EZ-Sensor	-	33000*	11.5, 1.3
		Sensor Clip	-	22100	-	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7	
		Sensor Cradle	-	22101	-	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
		Sensor Universal Band	-	22102	-	Sensor		-	28390	27, 3	
		F450 Super Duty	EZ-Sensor	-	33000*	11.5, 1.3		Sensor Clip	-	22100	-
	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7	Sensor Cradle		-	22101	-	
	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Sensor Universal Band		-	22102	-	
Sensor	-		28385	27, 3	2007						
Sensor Clip	-		22100	-	Crown Victoria	EZ-Sensor	-	33000*	11.5, 1.3		
Sensor Cradle	-		22101	-		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		
Sensor Universal Band	-		22102	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
F Series Pickup	EZ-Sensor		-	33000*		11.5, 1.3	Sensor	-	28385	27, 3	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Sensor Clip	-	22100	-		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Cradle	-	22101	-		
	Sensor	W/H.D. Payload Pkg.	28395	27, 3		Sensor Universal Band	-	22102	-		
	Sensor	W/O H.D. Payload Pkg.	28385	27, 3		Edge	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor Clip	-	22100	-	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7		
	Sensor Cradle	-	22101	-	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		
	Sensor Universal Band	-	22102	-	Sensor		W/Chrome Plated Almm. Wheels	28385	27, 3		

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
2007 - Continued					2006						
Ford - Continued	Edge - Cont'd.	Sensor	W/O Chrome Plated Almm. Wheels	28390	27, 3	Crown Victoria, Escape	EZ-Sensor	-	33000*	11.5, 1.3	
		Sensor Clip	-	22100	-		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
		Sensor Cradle	-	22101	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
		Sensor Universal Band	-	22102	-		Sensor	-	28385	27, 3	
	Escape	EZ-Sensor	-	33000*	11.5, 1.3		Sensor Clip	-	22100	-	
		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Sensor Cradle	-	22101	-	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Universal Band	-	22102	-	
		Sensor	-	28385	27, 3		Expedition	Sensor	-	20135**	44, 5
		Sensor Clip	-	22100	-			Service Pack	-	20002	44, 5
		Sensor Cradle	-	22101	-		Explorer	EZ-Sensor	-	33000*	11.5, 1.3
		Sensor Universal Band	-	22102	-	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7	
		Expedition	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
			EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Sensor	-	28385	27, 3
	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Sensor Clip		-	22100	-	
	Sensor		-	28390	27, 3	Sensor Cradle		-	22101	-	
	Sensor Clip		-	22100	-	Sensor Universal Band		-	22102	-	
	Sensor Cradle		-	22101	-	Five Hundred		EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Universal Band		-	22102	-			EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
	Explorer, Explorer Sport Trac, F Series Pickup		EZ-Sensor	-	33000*		11.5, 1.3	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
			EZ-Sensor Service Pack	Almm. Valve	34000		62, 7	Sensor	-	28390	27, 3
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Clip	-	22100	-	
		Sensor	-	28385	27, 3		Sensor Cradle	-	22101	-	
		Sensor Clip	-	22100	-		Sensor Universal Band	-	22102	-	
		Sensor Cradle	-	22101	-		Freestar, Grand Marquis	EZ-Sensor	-	33000*	11.5, 1.3
		Sensor Universal Band	-	22102	-			EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
		Five Hundred	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
			EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Sensor	-	28385	27, 3
	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Sensor Clip		-	22100	-	
	Sensor		-	28390	27, 3	Sensor Cradle		-	22101	-	
	Sensor Clip		-	22100	-	Sensor Universal Band		-	22102	-	
	Sensor Cradle		-	22101	-	2005					
	Sensor Universal Band		-	22102	-	Escape		EZ-Sensor	-	33000*	11.5, 1.3
	Freestar, Fusion, Grand Marquis, Mustang, Ranger		EZ-Sensor	-	33000*		11.5, 1.3	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
			EZ-Sensor Service Pack	Almm. Valve	34000		62, 7	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	Oct. 3, 2005 & Newer	28385	27, 3	
		Sensor	-	28385	27, 3		Sensor Clip	-	22100	-	
		Sensor Clip	-	22100	-		Sensor Cradle	-	22101	-	
		Sensor Cradle	-	22101	-		Sensor Universal Band	-	22102	-	
		Sensor Universal Band	-	22102	-		Expedition	Sensor	-	20135**	44, 5
								Service Pack	-	20002	44, 5

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
Ford - Continued					2011 - 2010 - Continued						
Explorer	Sensor	-	20096**	44, 5	Yukon	EZ-Sensor	-	33000*	11.5, 1.3		
	Service Pack	-	20002	44, 5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
Freestar	Sensor	W/Almnm. Valve Stem	20135**	44, 5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
	Service Pack	W/Almnm. Valve Stem	20002	44, 5		Sensor	-	20153	11.5, 1.3		
2005 - Continued						2009					
Expedition, Explorer	Sensor	-	20096**	44, 5		Acadia	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	-	20002	44, 5	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7		
Freestar	Sensor	W/Almnm. Valve Stem	20135**	44, 5	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		
	Service Pack	W/Almnm. Valve Stem	20002	44, 5	Sensor		-	20153	11.5, 1.3		
2004					2008						
Expedition	Sensor	-	20096**	44, 5	Canyon	Sensor	-	20131	62, 7		
	Service Pack	-	20002	44, 5		Service Pack	-	20006	62, 7		
Freestar	Sensor	W/Almnm. Valve Stem	20135**	44, 5	Envoy	Sensor	OEM Part No. 25774006	20116	62, 7		
	Service Pack	W/Almnm. Valve Stem	20002	44, 5		Service Pack	-	20004	62, 7		
2003					GMC - Continued	Savana	EZ-Sensor	-	33000*	11.5, 1.3	
Expedition	Sensor	-	20096**	44, 5			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	-	20002	44, 5			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
Explorer	Sensor	Exc. Sport	20096**	44, 5			Sensor	-	20158	62, 7	
	Service Pack	Exc. Sport	20002	44, 5			Service Pack	W/Schrader Sensor	20004	62, 7	
2002						Sierra Series Pickup	EZ-Sensor	-	33000*	11.5, 1.3	
Explorer	Sensor	Exc. Sport	20096**	44, 5			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	Exc. Sport	20002	44, 5			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
2011 - 2010							Yukon	Sensor	W/Single Rear Wheels	20153	11.5, 1.3
Acadia	EZ-Sensor	-	33000*	11.5, 1.3				EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor		-	20153	11.5, 1.3	
	Sensor	-	20153	11.5, 1.3		Service Pack		W/Single Rear Wheels	20008	11.5, 1.3	
	Service Pack	-	20008	11.5, 1.3		Service Pack	-	20008	11.5, 1.3		
Canyon	Sensor	-	20131	62, 7		2008					
	Service Pack	-	20006	62, 7	Acadia	EZ-Sensor	-	33000*	11.5, 1.3		
Savana	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	-	20158	62, 7		
	Sensor	-	20153	11.5, 1.3		Service Pack	W/Schrader Sensor	20004	62, 7		
	Service Pack	-	20008	11.5, 1.3	Service Pack	W/Siemens Sensor	20030	80, 9			
Sierra Series Pickup	EZ-Sensor	-	33000*	11.5, 1.3	Canyon	Sensor	-	20131	62, 7		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	-	20006	62, 7		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Envoy	Sensor	OEM Part No. 25774006	20116	62, 7		
	Sensor	W/Single Rear Wheels	20153	11.5, 1.3		Service Pack	-	20004	62, 7		
	Service Pack	W/Single Rear Wheels	20008	11.5, 1.3							
Terrain	EZ-Sensor	-	33000*	11.5, 1.3							
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7							
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3							
	Sensor	-	28206	11.5, 1.3							
	Service Pack	-	20008	11.5, 1.3							

* Programming Tool Required ** Magnet Required to Activate Sensor

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2008 - Continued					2007 - Continued				
Savana	EZ-Sensor	-	33000*	11.5, 1.3	Yukon - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	Clamp-In Style Only; TRW Sensor; W/Almnm. Valve Stem	20158	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5, 1.3
	Sensor	-	20158	62, 7		Service Pack	Clamp-In Style Only; TRW Sensor; W/Almnm. Valve Stem	20015	62, 7
	Service Pack	W/Schrader Sensor	20004	62, 7		Service Pack	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008	11.5, 1.3
	Service Pack	W/Siemens Sensor	20030	80, 9		2006			
Sierra Series Pickup	EZ-Sensor	-	33000*	11.5, 1.3	Envoy	Sensor	OEM Part No. 25774006	20116	62, 7
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	-	20004	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sierra Series Pickup, Yukon	Sensor	-	20107	62, 7
	Sensor	W/Single Rear Wheels	20153	11.5, 1.3		Service Pack	-	20004	62, 7
	Service Pack	W/Single Rear Wheels	20008	11.5, 1.3	2005				
	Service Pack	-	20008	11.5, 1.3	Sierra Series Pickup, Yukon	Sensor	-	20107	62, 7
Service Pack	-	20008	11.5, 1.3	Service Pack		-	20004	62, 7	
2007					2004				
Acadia	EZ-Sensor	-	33000*	11.5, 1.3	Sierra Series Pickup, Yukon	Sensor	-	20115	62, 7
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	-	20004	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	2003				
	Sensor	-	20158	62, 7	Sierra Series Pickup, Yukon	Sensor	-	20115	62, 7
	Service Pack	W/Schrader Sensor	20004	62, 7		Service Pack	-	20004	62, 7
	Service Pack	W/Siemens Sensor	20030	80, 9	2002				
Canyon	Sensor	-	20131	62, 7	Sierra Series Pickup, Yukon	Sensor	-	20115	62, 7
	Service Pack	-	20006	62, 7		Service Pack	-	20004	62, 7
Envoy	Sensor	OEM Part No. 25774006	20116	62, 7	2001				
	Service Pack	-	20004	62, 7	Accord	EZ-Sensor	Exc. Crosstour	33000*	11.5, 1.3
Sierra Series Pickup	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Exc. Crosstour; Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Exc. Crosstour; Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	Exc. Crosstour	20099	35, 4
	Sensor	Clamp-In Style Only; TRW Sensor; W/Almnm. Valve Stem; Exc. Classic	20158	62, 7		Sensor	Crosstour	20100	35, 4
	Sensor	Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic	20153	11.5, 1.3		Service Pack	Exc. Crosstour	20032	35, 4
	Service Pack	Clamp-In Style Only; TRW Sensor; W/Almnm. Valve Stem; Exc. Classic	20015	80, 9	Civic	EZ-Sensor	-	33000*	11.5, 1.3
Service Pack	-	20008	11.5, 1.3	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	
Sensor	Classic	20107	62, 7	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Service Pack	-	20008	11.5, 1.3	Sensor		-	28720	35, 4	
Yukon	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20019	35, 4	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	CR-V	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor	-	20099	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Service Pack	-	20032	35, 4	Sensor		-	20099	35, 4	
Element, Fit, Insight, Odyssey	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20032	35, 4	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Element, Fit, Insight, Odyssey	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2011 - Continued					2009 - Continued					
Honda	Element, Fit, Insight, Odyssey - Cont'd.	Sensor	-	28720	35, 4	Accord - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Service Pack	-	20019	35, 4		Sensor	-	20099	35, 4
	Service Pack	-	20032	35, 4	Service Pack		-	20032	35, 4	
	Pilot	Sensor	Exc. LX	20098	35, 4	Civic	EZ-Sensor	-	33000*	11.5, 1.3
		Service Pack	Exc. LX	20032	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Ridgeline	Sensor	RT	28981	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Sensor	Exc. RT	28981	35, 4		Sensor	-	28720	35, 4
		Service Pack	RT; Includes Valve	20036	35, 4	Service Pack	-	20019	35, 4	
		Service Pack	Does Not Include Valve	20021	35, 4	CR-V	EZ-Sensor	W/Alloy Wheels	33000*	11.5, 1.3
	2010						EZ-Sensor Service Pack	W/Alloy Wheels; Almnm. Valve	34000	62, 7
Accord	EZ-Sensor	Exc. Crosstour	33000*	11.5, 1.3	EZ-Sensor Service Pack		W/Alloy Wheels; Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Exc. Crosstour; Almnm. Valve	34000	62, 7	Sensor		W/Alloy Wheels	20099	35, 4	
	EZ-Sensor Service Pack	Exc. Crosstour; Rubber Valve	20008	11.5, 1.3	Service Pack	-	20032	35, 4		
	Sensor	Exc. Crosstour	20099	35, 4	Element, Fit	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	Crosstour	20100	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	Exc. Crosstour	20032	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Civic	EZ-Sensor	-	33000*	11.5, 1.3	Sensor	-	28720	35, 4	
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	Service Pack	-	20019	35, 4		
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Odyssey	Sensor	-	28983	31-40, 3.5-4.5	
Sensor		-	28720	35, 4		Service Pack	Includes Valve	20036	31-40, 3.5-4.5	
CR-V	Service Pack	-	20019	35, 4	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		
	EZ-Sensor	-	33000*	11.5, 1.3	Pilot	Sensor	W/Alloy Wheels	20098	35, 4	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	W/Alloy Wheels	20032	35, 4	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Ridgeline	Sensor	-	28981	35, 4
	Sensor	-	20099	35, 4	Service Pack		Includes Valve	20036	35, 4	
	Service Pack	-	20032	35, 4	Service Pack		Does Not Include Valve	20021	35, 4	
Element, Fit, Insight	EZ-Sensor	-	33000*	11.5, 1.3	S2000	Service Pack	-	20032	35, 4	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		2008				
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Accord	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	-	28720	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	-	20019	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
Odyssey	Sensor	-	28983	31-40, 3.5-4.5		Sensor	-	20099	35, 4	
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5	Service Pack	-	20032	35, 4		
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5	Civic	EZ-Sensor	-	33000*	11.5, 1.3	
Pilot	Sensor	Exc. LX	20098	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	Exc. LX	20032	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
Ridgeline	Sensor	RT	28981	35, 4		Sensor	-	28720	35, 4	
	Sensor	Exc. RT	28981	35, 4	Service Pack	-	20019	35, 4		
	Service Pack	RT; Includes Valve	20036	35, 4	CR-V	EZ-Sensor	W/Alloy Wheels	33000*	11.5, 1.3	
	Service Pack	Does Not Include Valve	20021	35, 4		EZ-Sensor Service Pack	W/Alloy Wheels; Almnm. Valve	34000	62, 7	
2009						EZ-Sensor Service Pack	W/Alloy Wheels; Rubber Valve	20008	11.5, 1.3	
Accord	EZ-Sensor	-	33000*	11.5, 1.3						
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7						

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2008 - Continued					2006 - Continued					
CR-V - Cont'd.	Sensor	W/Alloy Wheels	20099	35, 4	Ridgeline	Sensor	RT	28982	35, 4	
	Service Pack	-	20032	35, 4		Sensor	RTL, RTS	28981	35, 4	
Element	Service Pack	Includes Valve	20036	35, 4		Service Pack	RT; Includes Valve	20035	35, 4	
	Service Pack	Does Not Include Valve	20021	35, 4		Service Pack	RTL, RTS; Includes Valve	20036	35, 4	
Fit	Service Pack	Does Not Include Valve	20021	35, 4		Service Pack	Does Not Include Valve	20021	35, 4	
	EZ-Sensor	-	33000*	11.5, 1.3	2005					
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Odyssey	Sensor	Touring	28981	35, 4	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	Touring; Includes Valve	20036	35, 4	
	Sensor	-	20099	35, 4		Service Pack	Touring; Does Not Include Valve	20021	35, 4	
Pilot	Service Pack	-	20032	35, 4	Pilot	Sensor	EX	28981	35, 4	
	Sensor	-	28981	35, 4		Sensor	LX; W/Long Stem Valve	28982	35, 4	
Ridgeline	Service Pack	Includes Valve	20036	35, 4		Sensor	LX; W/Short Stem Valve	28981	35, 4	
	Service Pack	Does Not Include Valve	20021	35, 4		Service Pack	EX; Includes Valve	20036	35, 4	
S2000	Sensor	RT	28982	35, 4		Service Pack	LX; W/Long Stem Valve; Includes Valve	20035	35, 4	
	Sensor	RTL, RTS, RTX	28981	35, 4	Service Pack	LX; W/Short Stem Valve; Includes Valve	20036	35, 4		
	Service Pack	RT; Includes Valve	20035	35, 4	Service Pack	Does Not Include Valve	20021	35, 4		
	Service Pack	RTL, RTS, RTX; Includes Valve	20036	35, 4	2010 - 2009					
CR-V	Service Pack	Does Not Include Valve	20021	35, 4	H2	EZ-Sensor	-	33000*	11.5, 1.3	
	2007					EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor	W/Alloy Wheels	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	W/Alloy Wheels; Almnm. Valve	34000	62, 7		Sensor	-	20153	11.5, 1.3	
	EZ-Sensor Service Pack	W/Alloy Wheels; Rubber Valve	20008	11.5, 1.3		Service Pack	-	20008	11.5, 1.3	
Element	Sensor	W/Alloy Wheels	20099	35, 4	H3, H3T	Sensor	-	20131	62, 7	
	Service Pack	-	20032	35, 4		Service Pack	-	20006	62, 7	
Odyssey	Service Pack	Includes Valve	20036	35, 4	2008					
	Service Pack	Does Not Include Valve	20021	35, 4	H2	EZ-Sensor	-	33000*	11.5, 1.3	
Pilot	Sensor	-	28981	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	Includes Valve	20036	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	Does Not Include Valve	20021	35, 4		Sensor	-	20153	11.5, 1.3	
Ridgeline	Service Pack	Does Not Include Valve	20021	35, 4		Service Pack	-	20008	11.5, 1.3	
	Sensor	RT	28982	35, 4	H3	Sensor	-	20131	62, 7	
	Sensor	RTL, RTS, RTX	28981	35, 4		Service Pack	-	20006	62, 7	
	Service Pack	RT; Includes Valve	20035	35, 4	2007 - 2006					
	Service Pack	RTL, RTS, RTX; Includes Valve	20036	35, 4	H3	Sensor	-	20131	62, 7	
Service Pack	Does Not Include Valve	20021	35, 4	Service Pack		-	20006	62, 7		
2006					2011					
Odyssey	Sensor	Touring	28981	35, 4	Accent	Sensor	-	28849	31-40, 3.5-4.5	
	Service Pack	Touring; Includes Valve	20036	35, 4		Service Pack	-	20022	31-40, 3.5-4.5	
	Service Pack	Touring; Does Not Include Valve	20021	35, 4	Azera	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5	
Pilot	Sensor	-	28981	35, 4		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5	
	Service Pack	Includes Valve	20036	35, 4		Service Pack	Includes Valve	20036	31-40, 3.5-4.5	
Service Pack	Does Not Include Valve	20021	35, 4	Elantra	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5		
2006					Equus	Sensor	-	28849	31-40, 3.5-4.5	
Odyssey	Sensor	Touring	28981	35, 4		Service Pack	-	20022	31-40, 3.5-4.5	
	Service Pack	Touring; Includes Valve	20036	35, 4	Genesis	Sensor	Coupe	20092	31-40, 3.5-4.5	
Service Pack	Touring; Does Not Include Valve	20021	35, 4	Sensor		Sedan	28849	31-40, 3.5-4.5		
Pilot	Sensor	-	28981	35, 4						
	Service Pack	Includes Valve	20036	35, 4						
Service Pack	Does Not Include Valve	20021	35, 4							

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2011 - Continued					2008 - Continued				
Sonata	Sensor	-	20092	31-40, 3.5-4.5	Entourage, Santa Fe	Sensor	Includes Transmitter Only	20085	31-40, 3.5-4.5
	Service Pack	-	20022	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
Tucson	Sensor	-	28849	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	-	20022	31-40, 3.5-4.5	Sonata, Tiburon, Tucson	Sensor	-	28983	31-40, 3.5-4.5
Veracruz	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5	Veracruz	Sensor	Includes Transmitter Only	20085	31-40, 3.5-4.5
2010						Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
Accent	Sensor	-	28849	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	-	20022	31-40, 3.5-4.5	2007				
Azera, Elantra	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5	Azera	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
Genesis	Service Pack	-	20022	31-40, 3.5-4.5	Entourage, Santa Fe	Sensor	Includes Transmitter Only	20085	31-40, 3.5-4.5
Santa Fe	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5	Sonata	Sensor	-	28983	31-40, 3.5-4.5
Sonata, Tucson	Sensor	-	28849	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
	Service Pack	-	20022	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
Veracruz	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5	Tiburon, Tucson	Sensor	-	28983	31-40, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
2009					Veracruz	Sensor	Includes Transmitter Only	20085	31-40, 3.5-4.5
Accent	Sensor	-	28849	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
	Service Pack	-	20022	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
Azera, Elantra	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5	2006				
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5	Azera	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
Service Pack	Includes Valve	20036	31-40, 3.5-4.5	Service Pack		Includes Valve	20036	31-40, 3.5-4.5	
Entourage	Sensor	Includes Transmitter Only	20085	31-40, 3.5-4.5	Tucson	Sensor	-	28983	31-40, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
Genesis	Service Pack	-	20022	31-40, 3.5-4.5	2010 - 2009				
Santa Fe	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5	EX35, FX35, FX50, G37	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Sonata	Sensor	-	28849	31-40, 3.5-4.5		Sensor	-	28210	66, 7.5
	Service Pack	-	20022	31-40, 3.5-4.5		Service Pack	-	20014	66, 7.5
Tucson	Sensor	-	28983	31-40, 3.5-4.5	M35, M45	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Veracruz	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5		Sensor	-	28204	66, 7.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		Service Pack	-	20014	66, 7.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5	QX56	EZ-Sensor	-	33000*	11.5, 1.3
2008						EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Accent	Sensor	-	28849	31-40, 3.5-4.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	-	20022	31-40, 3.5-4.5		Sensor	-	28204	49, 5.5
Azera, Elantra	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5		Service Pack	-	20014	49, 5.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5					
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5					

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2008					2007 - Continued				
EX35	EZ-Sensor	-	33000*	11.5, 1.3	M35, M45 - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	20064	66, 7.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20007	66, 7.5
	Sensor	-	28210	66, 7.5	QX56	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20014	66, 7.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
FX35, FX45	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	Apr. 1 & Newer	28204	49, 5.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	Mar. & Older	20161	49, 5.5
	Sensor	-	28204	66, 7.5	Service Pack	Apr. 1 & Newer	20014	49, 5.5	
Service Pack	-	20014	66, 7.5	Service Pack	Mar. & Older	20007	49, 5.5		
2006									
G35, G37	EZ-Sensor	-	33000*	11.5, 1.3	FX35, FX45	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28210	66, 7.5		Sensor	-	20064	66, 7.5
	Service Pack	-	20014	66, 7.5		Service Pack	-	20007	66, 7.5
M35, M45	EZ-Sensor	-	33000*	11.5, 1.3	G35	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28204	66, 7.5		Sensor	-	20064	61-72, 6.8-8.2
	Service Pack	-	20014	66, 7.5		Service Pack	-	20007	61-72, 6.8-8.2
QX56	EZ-Sensor	-	33000*	11.5, 1.3	M35, M45	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28204	49, 5.5		Sensor	-	20064	66, 7.5
	Service Pack	-	20014	49, 5.5		Service Pack	-	20007	66, 7.5
2007					Q45	EZ-Sensor	-	33000*	11.5, 1.3
FX35, FX45	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	Aug. & Newer	28204	66, 7.5
	Sensor	Jul. & Newer	28204	66, 7.5		Sensor	Jul. & Older	20064	66, 7.5
	Sensor	Jun. & Older	20064	66, 7.5	Service Pack	Aug. & Newer	20014	66, 7.5	
	Service Pack	Jul. & Newer	20014	66, 7.5	Service Pack	Jul. & Older	20007	66, 7.5	
	Service Pack	Jun. & Older	20007	66, 7.5	QX56	EZ-Sensor	-	33000*	11.5, 1.3
	G35	EZ-Sensor	-	33000*		11.5, 1.3	EZ-Sensor Service Pack	Almnm. Valve	34000
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		Sensor	W/Alloy Wheels	20161	49, 5.5
Sensor		Coupe	28204	66, 7.5		Sensor	W/Steel Wheels	20069	49, 5.5
Sensor		Sedan	28210	66, 7.5	Service Pack	W/Alloy Wheels	20007	49, 5.5	
Service Pack		-	20014	66, 7.5	Service Pack	W/Steel Wheels	20005	49, 5.5	
M35, M45	EZ-Sensor	-	33000*	11.5, 1.3					
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7					

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2005					2004 - Continued				
FX35, FX45	EZ-Sensor	-	33000*	11.5, 1.3	QX56 - Cont'd.	Sensor	-	20069	49, 5.5
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	-	20005	49, 5.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	2003				
	Sensor	-	20064	66, 7.5	FX35, FX45	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20007	66, 7.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
G35	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	20064	66, 7.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20007	66, 7.5
	Sensor	-	20064	61-72, 6.8-8.2	G35	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20007	61-72, 6.8-8.2		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Q45	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	Jun. & Newer	20064	61-72, 6.8-8.2
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	Jun. & Newer	20007	61-72, 6.8-8.2
	Sensor	-	20064	66, 7.5	M45, Q45, QX4	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20007	66, 7.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
QX56	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	20064	66, 7.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20007	66, 7.5
	Sensor	W/Alloy Wheels	20161	49, 5.5	2008 - 2007				
	Sensor	W/Steel Wheels	20069	49, 5.5	Ascender	Sensor	-	20116	62, 7
Service Pack	W/Alloy Wheels	20007	49, 5.5	Service Pack		-	20004	62, 7	
Service Pack	W/Steel Wheels	20005	49, 5.5	I-290, I-370	Sensor	-	20131	62, 7	
2004					Service Pack	-	20006	62, 7	
FX35, FX45	EZ-Sensor	-	33000*	11.5, 1.3	2006				
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Ascender	Sensor	-	20116	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20004	62, 7
	Sensor	-	20064	66, 7.5	2004				
	Service Pack	-	20007	66, 7.5	Rodeo	Sensor	-	20028**	62, 7
G35	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	-	20003	62, 7
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	2011 - 2010				
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	XF, XFR, XJ, XK, XKR	Sensor	W/315 MHz Sensor	20090	71, 8
	Sensor	-	20064	61-72, 6.8-8.2		Sensor	W/433 MHz Sensor	20091	71, 8
	Service Pack	-	20007	61-72, 6.8-8.2		Service Pack	-	20030	71, 8
M45, Q45	EZ-Sensor	-	33000*	11.5, 1.3	2009				
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Super V8, Vanden Plas, XF, XJ8, XJR, XK, XKR	Sensor	W/315 MHz Sensor	20090	71, 8
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	W/433 MHz Sensor	20091	71, 8
	Sensor	-	20064	66, 7.5		Service Pack	-	20030	71, 8
	Service Pack	-	20007	66, 7.5	2008				
QX56	EZ-Sensor	-	33000*	11.5, 1.3	S-Type, Super V8, Vanden Plas, X-Type, XJ8, XJR, XK, XKR	Sensor	W/315 MHz Sensor	20090	71, 8
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	W/433 MHz Sensor	20091	71, 8
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20030	71, 8

* Programming Tool Required ** Magnet Required to Activate Sensor

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2007					2010 - Continued					
Jaguar - Continued Super V8, Vanden Plas, XJ8, XJR, XK, XKR	Sensor	W/315 MHz Sensor	20090	71, 8	Compass	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	W/433 MHz Sensor	20091	71, 8		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	-	20030	71, 8		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
2006 - 2005						Sensor	-	20066	58, 6.5	
Super V8, Vanden Plas, XJ8, XJR	Sensor	W/315 MHz Sensor	20090	71, 8		Sensor	-	28308	11.5, 1.3	
	Sensor	W/433 MHz Sensor	20091	71, 8		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
	Service Pack	-	20030	71, 8		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	
2004						Service Pack	W/Siemens Sensor	20030	71, 8	
Vanden Plas, XJ8, XJR	Sensor	W/315 MHz Sensor	20090	71, 8		Grand Cherokee	Sensor	-	28155	58, 6.5
	Sensor	W/433 MHz Sensor	20091	71, 8		Sensor	-	28434	11.5, 1.3	
	Service Pack	-	20030	71, 8	Service Pack	Does Not Include Stem	20013	58, 6.5		
2011					Service Pack	Includes Stem Only	20020	58, 6.5		
Compass	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	Includes Stem Only	20020	58, 6.5		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Liberty	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
	Sensor	-	20066	58, 6.5	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
	Sensor	-	28308	11.5, 1.3	Sensor	-	20066	58, 6.5		
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	Sensor	-	28308	11.5, 1.3		
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Service Pack	Does Not Include Stem	20013	58, 6.5		
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Service Pack	Includes Stem Only	20020	58, 6.5		
	Grand Cherokee	Sensor	-	20398	11.5, 1.3	Service Pack	Includes Stem Only	20020	58, 6.5	
	Service Pack	-	20008	11.5, 1.3	2009					
Liberty	EZ-Sensor	-	33000*	11.5, 1.3	Commander	Sensor	-	28155	58, 6.5	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	28434	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	Does Not Include Stem	20013	58, 6.5	
	Sensor	-	20066	58, 6.5		Service Pack	Includes Stem Only	20020	58, 6.5	
	Sensor	-	28308	11.5, 1.3	Compass	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	Does Not Include Stem	20013	58, 6.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	Includes Stem Only	20020	58, 6.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Patriot, Wrangler	EZ-Sensor	-	33000*		11.5, 1.3	Sensor	-	20066	58, 6.5
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	28308	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
Sensor	-	20066	58, 6.5	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5			
Sensor	-	28308	11.5, 1.3	Service Pack	W/Siemens Sensor	20030	71, 8			
Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	2010						
Service Pack	Includes Stem Only	20020	58, 6.5	Commander	Sensor	-	28155	58, 6.5		
Patriot	EZ-Sensor	-	33000*		11.5, 1.3	Sensor	-	28434	11.5, 1.3	
EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	Does Not Include Stem	20013	58, 6.5		
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	Includes Stem Only	20020	58, 6.5		
Sensor	-	20066	58, 6.5	Compass	EZ-Sensor	-	33000*	11.5, 1.3		
Sensor	-	28308	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5		Sensor	-	20066	58, 6.5		
Service Pack	Includes Stem Only	20020	58, 6.5		Sensor	-	28308	11.5, 1.3		
Service Pack	Includes Stem Only	20020	58, 6.5		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		
Service Pack	Includes Stem Only	20020	58, 6.5	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5			
Service Pack	Includes Stem Only	20020	58, 6.5	Service Pack	W/Siemens Sensor	20030	71, 8			

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2009 - Continued					2008 - Continued					
Grand Cherokee	Sensor	-	28155	58, 6.5	Liberty, Patriot, Wrangler - Cont'd.	Sensor	-	20066	58, 6.5	
	Sensor	-	28434	11.5, 1.3		Sensor	-	28308	11.5, 1.3	
	Service Pack	Does Not Include Stem	20013	58, 6.5		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
	Service Pack	Includes Stem Only	20020	58, 6.5		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	
Liberty	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	W/Siemens Sensor	20030	71, 8	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	2007					
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Com-mander, Compass, Grand Cherokee, Liberty, Patriot, Wrangler	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	Exc. Sport	28155	58, 6.5		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
	Sensor	Exc. Sport	28434	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	Sport	20066	58, 6.5		Sensor	-	20066	58, 6.5	
	Sensor	Sport	28308	11.5, 1.3		Sensor	-	28308	11.5, 1.3	
	Service Pack	Does Not Include Stem	20013	58, 6.5		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
	Service Pack	Includes Stem Only	20020	58, 6.5		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	
	Patriot	EZ-Sensor	-	33000*		11.5, 1.3	Service Pack	W/Siemens Sensor	20030	71, 8
EZ-Sensor Service Pack		Almm. Valve	34000	62, 7		2006				
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		Com-mander, Grand Cherokee, Liberty	EZ-Sensor	-	33000*	11.5, 1.3
Sensor		-	20066	58, 6.5	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7	
Sensor		-	28308	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Service Pack		W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	Sensor		-	20066	58, 6.5	
Service Pack		W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Sensor		-	28308	11.5, 1.3	
Service Pack		W/Siemens Sensor	20030	71, 8	Service Pack		W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
Wrangler		Sensor	-	28155	58, 6.5		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5
		Sensor	-	28434	11.5, 1.3		Service Pack	W/Siemens Sensor	20030	71, 8
	Service Pack	Does Not Include Stem	20013	58, 6.5	2005					
	Service Pack	Includes Stem Only	20020	58, 6.5	Grand Cherokee, Liberty		EZ-Sensor	-	33000*	11.5, 1.3
2008						EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
Com-mander	Sensor	-	28155	58, 6.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	28434	11.5, 1.3		Sensor	-	20066	58, 6.5	
	Service Pack	Does Not Include Stem	20013	58, 6.5		Sensor	-	28308	11.5, 1.3	
	Service Pack	Includes Stem Only	20020	58, 6.5		Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	
Compass	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	W/Siemens Sensor	20030	71, 8	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		2004				
	Sensor	-	20066	58, 6.5		Grand Cherokee, Liberty	Sensor	-	20028**	64, 7
	Sensor	-	28308	11.5, 1.3	Service Pack		-	20003	64, 7	
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	2003 - 2002					
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Grand Cherokee	Sensor	-	20028**	64, 7	
	Service Pack	W/Siemens Sensor	20030	71, 8		Service Pack	-	20003	64, 7	
	Grand Cherokee	Sensor	-	28155	58, 6.5					
		Sensor	-	28434	11.5, 1.3					
Service Pack		Does Not Include Stem	20013	58, 6.5						
Service Pack		Includes Stem Only	20020	58, 6.5						
Liberty, Patriot, Wrangler	EZ-Sensor	-	33000*	11.5, 1.3						
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7						
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3						

* Programming Tool Required ** Magnet Required to Activate Sensor

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2011					2008 - Continued				
Borrego, Rio	Sensor	-	28849	35-35.7, 3.5-4.5	Magentis, Optima	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5
	Service Pack	-	20022	35-35.7, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
Sedona	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5	Rio	Sensor	-	28849	35-35.7, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5		Service Pack	-	20022	35-35.7, 3.5-4.5
Sorento, Soul	Sensor	-	20092	31-40, 3.5-4.5	Rondo	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5
	Sportage	Sensor	-	28849		31-40, 3.5-4.5	Service Pack	Does Not Include Valve	20021
Service Pack		-	20022	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
2010					Sedona	Sensor	Includes Transmitter Only	20085	31-40, 3.5-4.5
Borrego	Sensor	-	28849	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
	Service Pack	-	20022	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
Forte	Sensor	-	20092	31-40, 3.5-4.5	Sorento	Sensor	-	28983	35-35.7, 3.5-4.5
Magentis, Optima	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	35-35.7, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	35-35.7, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5	Spectra	Sensor	-	28849	35-35.7, 3.5-4.5
Rio	Sensor	-	28849	35-35.7, 3.5-4.5		Service Pack	-	20022	35-35.7, 3.5-4.5
	Service Pack	-	20022	35-35.7, 3.5-4.5	Sportage	Sensor	-	28983	31-40, 3.5-4.5
Rondo, Sedona	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5	2007				
Soul	Sensor	-	20092	31-40, 3.5-4.5	Amanti	Sensor	-	28983	35-35.7, 3.5-4.5
Sportage	Sensor	-	28849	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	35-35.7, 3.5-4.5
	Service Pack	-	20022	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	35-35.7, 3.5-4.5
2009					Optima	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5
Amanti	Sensor	-	28983	35-35.7, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
	Service Pack	Includes Valve	20036	35-35.7, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	35-35.7, 3.5-4.5	Rio	Sensor	-	28849	35-35.7, 3.5-4.5
Borrego	Sensor	-	28849	31-40, 3.5-4.5		Service Pack	-	20022	35-35.7, 3.5-4.5
	Service Pack	-	20022	31-40, 3.5-4.5	Rondo	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5
Magentis, Optima	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5	Sedona	Sensor	Includes Transmitter Only	20085	31-40, 3.5-4.5
Rio	Sensor	-	28849	35-35.7, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
	Service Pack	-	20022	35-35.7, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
Rondo, Sedona	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5	Sorento	Sensor	-	28983	35-35.7, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		Service Pack	Includes Valve	20036	35-35.7, 3.5-4.5
	Service Pack	Includes Valve	20036	31-40, 3.5-4.5		Service Pack	Does Not Include Valve	20021	35-35.7, 3.5-4.5
Sorento	Sensor	-	28983	35-35.7, 3.5-4.5	Spectra	Sensor	-	28849	35-35.7, 3.5-4.5
	Service Pack	Includes Valve	20036	35-35.7, 3.5-4.5		Service Pack	-	20022	35-35.7, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	35-35.7, 3.5-4.5		Sportage	Sensor	-	28983
Spectra	Sensor	-	28849	35-35.7, 3.5-4.5	Service Pack		Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	-	20022	35-35.7, 3.5-4.5	Service Pack		Does Not Include Valve	20021	31-40, 3.5-4.5
Sportage	Sensor	-	28849	31-40, 3.5-4.5	2006				
	Service Pack	-	20022	31-40, 3.5-4.5	Optima	Sensor	Includes Transmitter Only	20086	31-40, 3.5-4.5
2008						Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
Amanti	Sensor	-	28983	35-35.7, 3.5-4.5		Service Pack	Includes Valve	20036	31-40, 3.5-4.5
	Service Pack	Includes Valve	20036	35-35.7, 3.5-4.5	Sedona	Sensor	Includes Transmitter Only	20085	31-40, 3.5-4.5
	Service Pack	Does Not Include Valve	20021	35-35.7, 3.5-4.5		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5
Service Pack	Includes Valve	20036	31-40, 3.5-4.5	Service Pack		Includes Valve	20036	31-40, 3.5-4.5	
2008					Spectra	Sensor	-	28849	35-35.7, 3.5-4.5
Amanti	Sensor	-	28983	35-35.7, 3.5-4.5		Service Pack	-	20022	35-35.7, 3.5-4.5
	Service Pack	Includes Valve	20036	35-35.7, 3.5-4.5					
Service Pack	Does Not Include Valve	20021	35-35.7, 3.5-4.5						

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

▪ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
Kia - Continued					2011 - Continued						
Kia	Sportage	Sensor	-	28983	31-40, 3.5-4.5	HS250h	EZ-Sensor	-	33000*	11.5, 1.3	
		Service Pack	Includes Valve	20036	31-40, 3.5-4.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
		Service Pack	Does Not Include Valve	20021	31-40, 3.5-4.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	2005						IS250, IS350, IS F, LFA, LS460, LS600h, LX570, RX350, RX450h	Sensor	-	28345	35, 4
	Sportage	Sensor	Jun. 15, 2005 & Newer	28983	31-40, 3.5-4.5			Service Pack	-	20032	35, 4
		Service Pack	Jun. 15, 2005 & Newer; Includes Valve	20036	31-40, 3.5-4.5			EZ-Sensor	-	33000*	11.5, 1.3
Service Pack		Jun. 15, 2005 & Newer; Does Not Include Valve	20021	31-40, 3.5-4.5	EZ-Sensor Service Pack			Almnm. Valve	34000	62, 7	
2011 - 2010					ES350, GS350, GS450h, GS460, GX460			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
LR2	Sensor	-	20090	71, 8				Sensor	-	28370	35, 4
	Service Pack	-	20030	71, 8				Service Pack	-	20032	35, 4
LR4, Range Rover	Sensor	W/315 MHz Sensor	20090	71, 8		2010					
	Sensor	W/433 MHz Sensor	20091	71, 8		HS250h		EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20030	71, 8				EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
LR2	Sensor	-	20090	71, 8			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	-	20030	71, 8			Sensor	-	28370	35, 4	
	Sensor	W/315 MHz Sensor	20090	71, 8			Service Pack	-	20032	35, 4	
LR3, Range Rover	Sensor	W/315 MHz Sensor	20090	71, 8			IS250, IS350, IS F, LS460, LS600h, LX570	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	W/433 MHz Sensor	20091	71, 8	EZ-Sensor Service Pack	Almnm. Valve		34000	62, 7		
	Service Pack	-	20030	71, 8	EZ-Sensor Service Pack	Rubber Valve		20008	11.5, 1.3		
2009					RX350	Sensor		-	28370	35, 4	
LR2	Sensor	-	20090	71, 8		Service Pack		-	20032	35, 4	
	Service Pack	-	20030	71, 8		EZ-Sensor		-	33000*	11.5, 1.3	
LR3, Range Rover	Sensor	W/315 MHz Sensor	20090	71, 8		RX450h	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	W/433 MHz Sensor	20091	71, 8			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	-	20030	71, 8			Sensor	-	28370	35, 4	
2008					SC430		Service Pack	-	20032	35, 4	
LR2	Service Pack	-	20030	71, 8			EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	W/315 MHz Sensor	20090	71, 8			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
LR3, Range Rover	Sensor	W/315 MHz Sensor	20090	71, 8		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
	Sensor	W/433 MHz Sensor	20091	71, 8		Sensor	-	28370	35, 4		
	Service Pack	-	20030	71, 8		Service Pack	-	20032	35, 4		
2007 - 2006					2011						
LR3, Range Rover	Sensor	W/315 MHz Sensor	20090	71, 8	CT200h, ES350, GS350, GS450h, GS460, GX460	EZ-Sensor	-	33000*	11.5, 1.3		
	Sensor	W/433 MHz Sensor	20091	71, 8		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
	Service Pack	-	20030	71, 8		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
2005						Range Rover	Sensor	-	28370	35, 4	
LR3, Range Rover	Sensor	Includes Transmitter Only	28082	58, 6.5			Service Pack	-	20032	35, 4	
	Service Pack	Does Not Include Valve	20023	58, 6.5			Sensor	Models made in Japan.	28370	35, 4	
	Service Pack	W/43mm Silver Insert	20037	58, 6.5	Service Pack		-	20032	35, 4		
	Service Pack	W/48mm Green Insert	20038	58, 6.5	EZ-Sensor		-	33000*	11.5, 1.3		
	Service Pack	W/49mm Black Insert	20039	58, 6.5	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7		
	Service Pack	W/51mm Orange Insert	20040	58, 6.5	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			
2004 - 2002					Lexus	Sensor	-	28370	35, 4		
Range Rover	Sensor	Includes Transmitter Only	28082	58, 6.5		Service Pack	-	20032	35, 4		
	Service Pack	Does Not Include Valve	20023	58, 6.5		EZ-Sensor	-	33000*	11.5, 1.3		
	Service Pack	W/43mm Silver Insert	20037	58, 6.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
	Service Pack	W/48mm Green Insert	20038	58, 6.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
	Service Pack	W/49mm Black Insert	20039	58, 6.5		Sensor	-	28370	27, 3		
	Service Pack	W/51mm Orange Insert	20040	58, 6.5	Service Pack	-	20032	27, 3			

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2009 - 2008					2006 - Continued					
ES350, GS350, GS450h, GS460, GX470, IS250, IS350, IS F, LS460, LS600h, LX570	EZ-Sensor	-	33000*	11.5, 1.3	GS430	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	28370	35, 4		Sensor	Jul. & Newer	28370	35, 4	
	Service Pack	-	20032	35, 4		Sensor	Jun. & Older	28335	35, 4	
				Service Pack		Jul. & Newer	20032	35, 4		
RX350, RX400h	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	Jun. & Older	20031	35, 4		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	GX470	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	Models made in Japan.	28370	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	-	20032	35, 4		Sensor	Feb. & Newer; W/Valve Cap	28365	35, 4	
				Sensor		Feb. & Newer; W/O Valve Cap	28335	35, 4		
				Service Pack		Jan. 31 & Older	28345	35, 4		
SC430	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	Feb. & Newer	20032	35, 4		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Service Pack	Jan. 31 & Older	20031	35, 4		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	IS250, IS350	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	-	28370	27, 3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
Service Pack	-	20032	27, 3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		
				Sensor		Apr. 1 & Newer	28370	35, 4		
2007					LX470	Sensor	Mar. & Older	28335	35, 4	
ES350, GS350, GS430, GS450h, GX470, IS250, IS350, LS460, LX470	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	Apr. 1 & Newer	20032	35, 4	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	Mar. & Older	20031	35, 4	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		RX330	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	28370	35, 4			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	-	20032	35, 4			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
				Sensor	Aug. & Newer		28370	35, 4		
RX350, RX400h	EZ-Sensor	-	33000*	11.5, 1.3	Sensor	Jul. & Older	28365	35, 4		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Service Pack	Aug. & Newer	20032	35, 4		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	Jul. & Older	20031	35, 4		
	Sensor	Models made in Japan.	28370	35, 4	SC430	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
				EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		
				Sensor		Models made in Japan.; Feb. & Newer	28370	35, 4		
				Service Pack		Feb. & Newer	20032	35, 4		
				Service Pack		Jan. 31 & Older	20031	35, 4		
SC430	EZ-Sensor	-	33000*	11.5, 1.3	SC430	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	28370	27, 3		Sensor	Aug. & Newer	28370	27, 3	
	Service Pack	-	20032	27, 3		Sensor	W/White I.D. Mark; Jul. & Older	28310	27, 3	
2006					Sensor	W/Blue I.D. Mark; Jul. & Older	28315	27, 3		
GS300	EZ-Sensor	-	33000*	11.5, 1.3						
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7						
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3						
	Sensor	-	28335	35, 4						
	Service Pack	-	20031	35, 4						

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2006 - Continued					2010					
SC430 - Cont'd.	Sensor	W/Red I.D. Mark; Jul. & Older	28320	27, 3	MKS, MKT, MKX	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	W/Gold I.D. Mark; Jul. & Older	28325	27, 3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	Aug. & Newer	20032	27, 3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
2005						Sensor	-	28390	27, 3	
GS430	EZ-Sensor	-	33000*	11.5, 1.3		Sensor Clip	-	22100	-	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor Cradle	-	22101	-	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Universal Band	-	22102	-	
	Sensor	-	28335	35, 4		MKZ	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20031	35, 4			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	GX470	EZ-Sensor	-	33000*			11.5, 1.3	EZ-Sensor Service Pack	Rubber Valve	20008
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	Sensor		-	20315	13, 1.5	
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Service Pack	-	20018	13, 1.5		
Sensor		-	28345	35, 4	Navigator	EZ-Sensor	-	33000*	11.5, 1.3	
Service Pack	-	20031	35, 4	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7		
LX470	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	28390	27, 3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor Clip	-	22100	-		
	Sensor	-	28365	35, 4	Sensor Cradle	-	22101	-		
	Service Pack	-	20031	35, 4	Sensor Universal Band	-	22102	-		
SC430	Sensor	W/White I.D. Mark	28310	27, 3	Town Car	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	W/Blue I.D. Mark	28315	27, 3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	W/Red I.D. Mark	28320	27, 3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	W/Gold I.D. Mark	28325	27, 3		Sensor	-	28385	27, 3	
2004						Sensor Clip	-	22100	-	
GX470	EZ-Sensor	-	33000*	11.5, 1.3		Sensor Cradle	-	22101	-	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor Universal Band	-	22102	-	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		2009				
	Sensor	-	28345	35, 4		MKS, MKX	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20031	35, 4			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
SC430	Sensor	W/White I.D. Mark	28310	27, 3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
	Sensor	W/Blue I.D. Mark	28315	27, 3	Sensor		-	28390	27, 3	
	Sensor	W/Red I.D. Mark	28320	27, 3	Sensor Clip		-	22100	-	
	Sensor	W/Gold I.D. Mark	28325	27, 3	Sensor Cradle		-	22101	-	
2003 - 2002					Sensor Universal Band		-	22102	-	
SC430	Sensor	W/White I.D. Mark	28310	27, 3	MKZ		EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	W/Blue I.D. Mark	28315	27, 3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor	W/Red I.D. Mark	28320	27, 3			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	W/Gold I.D. Mark	28325	27, 3		Sensor	-	28385	27, 3	
2011						Sensor Clip	-	22100	-	
MKS, MKT, MKZ, Navigator, Town Car	EZ-Sensor	-	33000*	11.5, 1.3		Sensor Cradle	-	22101	-	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor Universal Band	-	22102	-	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		MKZ	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	20315	13, 1.5			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
							EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
					Sensor		-	28385	27, 3	
					Sensor Clip		-	22100	-	
					Sensor Cradle		-	22101	-	
					Sensor Universal Band	-	22102	-		

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2009 - Continued					2008 - Continued				
Navigator	EZ-Sensor	-	33000*	11.5, 1.3	Navigator - Cont'd.	Sensor	-	28390	27, 3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor Clip	-	22100	-
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Cradle	-	22101	-
	Sensor	-	28390	27, 3		Sensor Universal Band	-	22102	-
	Sensor Clip	-	22100	-	Town Car	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Cradle	-	22101	-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor Universal Band	-	22102	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Town Car	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	-	28385	27, 3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor Clip	-	22100	-
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor Cradle	-	22101	-	
	Sensor	-	28385	27, 3	Sensor Universal Band	-	22102	-	
	Sensor Clip	-	22100	-	2007				
	Sensor Cradle	-	22101	-	Mark LT	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Universal Band	-	22102	-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Mark LT	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	28385	27, 3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Clip	-	22100	-
	Sensor	-	28385	27, 3		Sensor Cradle	-	22101	-
	Sensor Clip	-	22100	-		Sensor Universal Band	-	22102	-
	Sensor Cradle	-	22101	-	MKX	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Universal Band	-	22102	-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
MKX	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	W/Chrome Plated Almnm. Wheels	28385	27, 3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	W/O Chrome Plated Almnm. Wheels	28390	27, 3
	Sensor	W/Chrome Plated Almnm. Wheels	28385	27, 3		Sensor Clip	-	22100	-
	Sensor	W/O Chrome Plated Almnm. Wheels	28390	27, 3		Sensor Cradle	-	22101	-
	Sensor Clip	-	22100	-		Sensor Universal Band	-	22102	-
	Sensor Cradle	-	22101	-		MKZ	EZ-Sensor	-	33000*
Sensor Universal Band	-	22102	-	EZ-Sensor Service Pack			Almnm. Valve	34000	62, 7
MKZ	EZ-Sensor	-	33000*	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Sensor		-	28385	27, 3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor Clip		-	22100	-
	Sensor	-	28385	27, 3	Sensor Cradle		-	22101	-
	Sensor Clip	-	22100	-	Sensor Universal Band		-	22102	-
	Sensor Cradle	-	22101	-	Navigator	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Universal Band	-	22102	-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Navigator	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	28390	27, 3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Clip	-	22100	-
Sensor	-	28390	27, 3	Sensor Cradle	-	22101	-		
Sensor Clip	-	22100	-	Sensor Universal Band	-	22102	-		
Sensor Cradle	-	22101	-						
Sensor Universal Band	-	22102	-						

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
2007 - Continued					2010						
Lincoln - Continued	Town Car	EZ-Sensor	-	33000*	11.5, 1.3	3, 5, 6, CX-7, CX-9, MX-5 Miata, RX-8	Sensor	-	20093	71, 8	
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	-	20030	71, 8	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Tribute	EZ-Sensor	-	33000*	11.5, 1.3	
		Sensor	-	28385	27, 3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
		Sensor Clip	-	22100	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
		Sensor Cradle	-	22101	-		Sensor	-	20315	13, 1.5	
		Sensor Universal Band	-	22102	-		Service Pack	-	20018	13, 1.5	
2006					2009						
Navigator	Sensor	-	20135**	44, 5	3, 5, 6	Sensor	-	20093	71, 8		
	Service Pack	-	20002	44, 5		Service Pack	-	20030	71, 8		
Town Car	EZ-Sensor	-	33000*	11.5, 1.3	B2300 Pickup, B4000 Pickup	EZ-Sensor	-	33000*	11.5, 1.3		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
	Sensor	-	28385	27, 3		Sensor	-	28385	27, 3		
	Sensor Clip	-	22100	-		Sensor Clip	-	22100	-		
	Sensor Cradle	-	22101	-		Sensor Cradle	-	22101	-		
	Sensor Universal Band	-	22102	-		Sensor Universal Band	-	22102	-		
2005					CX-7, CX-9, MX-5 Miata, RX-8	Sensor	-	20093	71, 8		
Aviator	Sensor	-	20096**	44, 5		Service Pack	-	20030	71, 8		
	Service Pack	-	20002	44, 5	Tribute	EZ-Sensor	-	33000*	11.5, 1.3		
Navigator	Sensor	-	20135**	44, 5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
	Service Pack	-	20002	44, 5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
2004 - 2003						Sensor	-	20315	13, 1.5		
Aviator, Navigator	Sensor	-	20096**	44, 5		Service Pack	-	20018	13, 1.5		
	Service Pack	-	20002	44, 5	2008						
2006					3, 5, 6	Sensor	-	20093	71, 8		
Maserati	Coupe, Gransport, MC12, Quattroporte, Spyder	Service Pack	Does Not Include Valve	20023		-	Service Pack	-	20030	71, 8	
		Service Pack	W/43mm Silver Insert	20037		-	B2300 Pickup, B3000 Pickup, B4000 Pickup	EZ-Sensor	-	33000*	11.5, 1.3
		Service Pack	W/48mm Green Insert	20038		-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		Service Pack	W/49mm Black Insert	20039		-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Service Pack	W/51mm Orange Insert	20040	-	Sensor		-	28385	27, 3	
2005 - 2004					Sensor Clip	-		22100	-		
Coupe, Gransport, Quattroporte, Spyder	Service Pack	Does Not Include Valve	20023	-	Sensor Cradle	-	22101	-			
	Service Pack	W/43mm Silver Insert	20037	-	Sensor Universal Band	-	22102	-			
	Service Pack	W/48mm Green Insert	20038	-	2011						
	Service Pack	W/49mm Black Insert	20039	-	2, 3, 6, CX-7, CX-9, MX-5 Miata, RX-8, Tribute	Sensor	-	20093	71, 8		
	Service Pack	W/51mm Orange Insert	20040	-		Service Pack	-	20030	71, 8		
2011					CX-7, CX-9, MX-5 Miata, RX-8	Sensor	-	20093	71, 8		
Mazda	2, 3, 6, CX-7, CX-9, MX-5 Miata, RX-8, Tribute	Sensor	-	20093		71, 8	Service Pack	-	20030	71, 8	
		Service Pack	-	20030	71, 8						

* Programming Tool Required ** Magnet Required to Activate Sensor

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2008 - Continued					2011 - Continued					
Tribute	EZ-Sensor	-	33000*	11.5, 1.3	G55, G550, GL350, GL450, GL550, GLK350, ML63, ML350, ML450, ML550, R350	Sensor	-	28214	58, 6.5	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	Mar. & Newer; Does Not Include Stem	20016	58, 6.5	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	Mar. & Newer; Includes Stem Only	20020	58, 6.5	
	Sensor	-	28385	27, 3		S63, S65, S400, S550, S600	Sensor	-	28214	58, 6.5
	Sensor Clip	-	22100	-			Service Pack	Does Not Include Stem	20016	58, 6.5
	Sensor Cradle	-	22101	-			Service Pack	Includes Stem Only	20020	58, 6.5
	Sensor Universal Band	-	22102	-			SL63, SL65	Sensor	-	20094
2007					SLK300, SLK350, SLS	Sensor	-	28214	58, 6.5	
3, 5	Sensor	-	20093	71, 8		Service Pack	Does Not Include Stem	20016	58, 6.5	
	Service Pack	-	20030	71, 8		Service Pack	Includes Stem Only	20020	58, 6.5	
B2300 Pickup, B3000 Pickup, B4000 Pickup	EZ-Sensor	-	33000*	11.5, 1.3	2010	C63, C300, C350, CL63, CL65, CL550, CL600	Sensor	-	28214	58, 6.5
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			Service Pack	Does Not Include Stem	20016	58, 6.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			Service Pack	Includes Stem Only	20020	58, 6.5
	Sensor	-	28385	27, 3		CLS63, CLS550	Sensor	-	20094	53, 6
	Sensor Clip	-	22100	-	Service Pack		Does Not Include Valve	20021	53, 6	
	Sensor Cradle	-	22101	-	Service Pack		Includes Valve	20036	53, 6	
	Sensor Universal Band	-	22102	-	E63, E350, E550, G55, G550, GL350, GL450, GL550, GLK350, ML63, ML350, ML450, ML550, R350	Sensor	-	28214	58, 6.5	
CX-7, CX-9, MX-5 Miata, RX-8	Sensor	-	20093	71, 8		Service Pack	Does Not Include Stem	20016	58, 6.5	
	Service Pack	-	20030	71, 8		Service Pack	Includes Stem Only	20020	58, 6.5	
2006					Mercedes-Benz - Continued	S63, S65, S400, S550, S600	Sensor	-	20094	53, 6
3, 5, MX-5 Miata, RX-8	Sensor	-	20093	71, 8			Service Pack	Does Not Include Valve	20021	53, 6
	Service Pack	-	20030	71, 8			Service Pack	Includes Valve	20036	53, 6
Tribute	EZ-Sensor	-	33000*	11.5, 1.3		SLK55, SLK300, SLK350	Sensor	-	28214	58, 6.5
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			Service Pack	Does Not Include Stem	20016	58, 6.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			Service Pack	Includes Stem Only	20020	58, 6.5
	Sensor	-	28385	27, 3		2009	C63, C300, C350	Sensor	-	28214
	Sensor Clip	-	22100	-	Service Pack			Does Not Include Stem	20016	58, 6.5
	Sensor Cradle	-	22101	-	Service Pack			Includes Stem Only	20020	58, 6.5
	Sensor Universal Band	-	22102	-	Sensor		-	28214	58, 6.5	
2005 - 2004					Mercedes-Benz	Service Pack	Does Not Include Stem	20016	58, 6.5	
3, RX-8	Sensor	-	20093	71, 8		Service Pack	Includes Stem Only	20020	58, 6.5	
	Service Pack	-	20030	71, 8		2009				
2011					Mercedes-Benz	C63, C300, C350	Sensor	-	28214	58, 6.5
C63, C300, C350, CL63, CL65, CL550	Sensor	-	28214	58, 6.5		Service Pack	Does Not Include Stem	20016	58, 6.5	
	Service Pack	Does Not Include Stem	20016	58, 6.5		Service Pack	Includes Stem Only	20020	58, 6.5	
	Service Pack	Includes Stem Only	20020	58, 6.5	2009					
CLS63, CLS550	Sensor	-	20094	53, 6	C63, C300, C350	Sensor	-	28214	58, 6.5	
	Service Pack	Does Not Include Valve	20021	53, 6		Service Pack	Does Not Include Stem	20016	58, 6.5	
	Service Pack	Includes Valve	20036	53, 6		Service Pack	Includes Stem Only	20020	58, 6.5	
E63, E350, E550	Sensor	-	28214	58, 6.5	2009					
	Service Pack	Does Not Include Stem	20016	58, 6.5	C63, C300, C350	Sensor	-	28214	58, 6.5	
	Service Pack	Includes Stem Only	20020	58, 6.5	Service Pack	Does Not Include Stem	20016	58, 6.5		
					Service Pack	Includes Stem Only	20020	58, 6.5		

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2009 - Continued					2008 - Continued				
CL63, CL65, CL550, CL600	Sensor	-	20094	53, 6	CLS63, CLS550, E63, E320	Sensor	-	20094	53, 6
	Service Pack	Does Not Include Valve	20021	53, 6		Service Pack	Does Not Include Valve	20021	53, 6
	Service Pack	Includes Valve	20036	53, 6		Service Pack	Includes Valve	20036	53, 6
CLK63, CLK350, CLK550	Sensor	-	28214	58, 6.5	E350, E550	Sensor	W/315 MHz Sensor	20094	53, 6
	Service Pack	Does Not Include Stem	20016	58, 6.5		Sensor	W/433 MHz Sensor	20095	53, 6
	Service Pack	Includes Stem Only	20020	58, 6.5		Service Pack	Does Not Include Valve	20021	53, 6
Service Pack	Includes Valve	20036	53, 6	Service Pack		Includes Valve	20036	53, 6	
CLS63, CLS550, E63, E320	Sensor	-	20094	53, 6	G55, G500	Sensor	-	28214	58, 6.5
	Service Pack	Does Not Include Valve	20021	53, 6		Service Pack	Does Not Include Stem	20016	58, 6.5
	Service Pack	Includes Valve	20036	53, 6		Service Pack	Includes Stem Only	20020	58, 6.5
E350, E550	Sensor	W/315 MHz Sensor	20094	53, 6	GL320, GL450, GL550, ML63, ML320, ML350, ML550, R320, R350	Sensor	-	20095	53, 6
	Sensor	W/433 MHz Sensor	20095	53, 6		Service Pack	Does Not Include Valve	20021	53, 6
	Service Pack	Does Not Include Valve	20021	53, 6		Service Pack	Includes Valve	20036	53, 6
	Service Pack	Includes Valve	20036	53, 6		Service Pack	Includes Valve	20036	53, 6
G55, G500	Sensor	-	28214	58, 6.5	R550	Service Pack	Does Not Include Valve	20023	53, 6
	Service Pack	Does Not Include Stem	20016	58, 6.5		Service Pack	W/43mm Silver Insert	20037	53, 6
	Service Pack	Includes Stem Only	20020	58, 6.5		Service Pack	W/48mm Green Insert	20038	53, 6
Sensor	-	20095	53, 6	Service Pack		W/49mm Black Insert	20039	53, 6	
Service Pack	Does Not Include Valve	20021	53, 6	Service Pack		W/51mm Orange Insert	20040	53, 6	
S63, S65, S550, S600, SL63, SL65, SL550, SL600	Sensor	-	20094	53, 6	S63, S65, S550, S600, SL55, SL65, SL550, SL600	Sensor	-	20094	53, 6
	Service Pack	Does Not Include Valve	20021	53, 6		Service Pack	Does Not Include Valve	20021	53, 6
	Service Pack	Includes Valve	20036	53, 6		Service Pack	Includes Valve	20036	53, 6
SLK55, SLK300, SLK350	Sensor	-	28214	58, 6.5	SLK55, SLK280, SLK350	Sensor	-	28214	58, 6.5
	Service Pack	Does Not Include Stem	20016	58, 6.5		Service Pack	Does Not Include Stem	20016	58, 6.5
	Service Pack	Includes Stem Only	20020	58, 6.5		Service Pack	Includes Stem Only	20020	58, 6.5
SLR McLaren	Sensor	-	20094	53, 6	SLR McLaren	Sensor	-	20094	53, 6
	Service Pack	Does Not Include Valve	20021	53, 6		Service Pack	Does Not Include Valve	20021	53, 6
	Service Pack	Includes Valve	20036	53, 6		Service Pack	Includes Valve	20036	53, 6
2008					2007				
C63, C300, C350	Sensor	-	28214	58, 6.5	C350	Sensor	Jun. & Newer	28214	58, 6.5
	Service Pack	Does Not Include Stem	20016	58, 6.5		Service Pack	Jun. & Newer; Does Not Include Stem	20016	58, 6.5
	Service Pack	Includes Stem Only	20020	58, 6.5		Service Pack	Jun. & Newer; Includes Stem Only	20020	58, 6.5
CL63, CL65, CL550, CL600	Sensor	-	20094	53, 6	CL63, CL550, CL600	Sensor	-	20094	53, 6
	Service Pack	Does Not Include Valve	20021	53, 6		Service Pack	Does Not Include Valve	20021	53, 6
	Service Pack	Includes Valve	20036	53, 6		Service Pack	Includes Valve	20036	53, 6
CLK63, CLK350, CLK550	Sensor	-	28214	58, 6.5	CLK63, CLK350, CLK550	Sensor	-	28214	58, 6.5
	Service Pack	Does Not Include Stem	20016	58, 6.5		Service Pack	Does Not Include Stem	20016	58, 6.5
	Service Pack	Includes Stem Only	20020	58, 6.5		Service Pack	Includes Stem Only	20020	58, 6.5

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2007 - Continued					2006 - Continued				
CLS63, CLS550, E63, E320	Sensor	-	20094	53, 6	E350 - Cont'd.	Service Pack	Does Not Include Valve	20021	53, 6
	Service Pack	Does Not Include Valve	20021	53, 6		Service Pack	Includes Valve	20036	53, 6
	Service Pack	Includes Valve	20036	53, 6	E500	Sensor	-	20094	53, 6
E350, E550	Sensor	W/315 MHz Sensor	20094	53, 6		Service Pack	Does Not Include Valve	20021	53, 6
	Sensor	W/433 MHz Sensor	20095	53, 6		Service Pack	Includes Valve	20036	53, 6
	Service Pack	Does Not Include Valve	20021	53, 6	ML350, ML500, R350, R500	Sensor	-	20095	53, 6
Service Pack	Includes Valve	20036	53, 6	Service Pack		Does Not Include Valve	20021	53, 6	
Service Pack	Includes Valve	20036	53, 6	Service Pack		Includes Valve	20036	53, 6	
G55, G500	Sensor	Mar. & Newer	28214	58, 6.5	S55, S65, S350, S430, S500, S600	Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	Mar. & Newer; Does Not Include Stem	20016	58, 6.5		Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	Mar. & Newer; Includes Stem Only	20020	58, 6.5		Service Pack	W/48mm Green Insert	20038	35, 4
GL320, GL450, ML63, ML320, ML350, ML500, R63, R320, R350, R500	Sensor	-	20095	53, 6		Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	Does Not Include Valve	20021	53, 6		Service Pack	W/51mm Orange Insert	20040	35, 4
	Service Pack	Includes Valve	20036	53, 6	SL55, SL65, SL500, SL600	Sensor	-	20094	53, 6
S63, S65, S550, S600, SL55, SL550, SL600	Sensor	-	20094	53, 6		Service Pack	Does Not Include Valve	20021	53, 6
	Service Pack	Does Not Include Valve	20021	53, 6		Service Pack	Includes Valve	20036	53, 6
	Service Pack	Includes Valve	20036	53, 6	SLR McLaren	Service Pack	Does Not Include Valve	20023	35, 4
SLK55, SLK280, SLK350	Sensor	May & Newer	28214	58, 6.5		Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	May & Newer; Does Not Include Stem	20016	58, 6.5		Service Pack	W/48mm Green Insert	20038	35, 4
	Service Pack	May & Newer; Includes Stem Only	20020	58, 6.5		Service Pack	W/49mm Black Insert	20039	35, 4
SLR McLaren	Service Pack	Does Not Include Valve	20023	53, 6		Service Pack	W/51mm Orange Insert	20040	35, 4
	Service Pack	W/43mm Silver Insert	20037	53, 6	2005				
	Service Pack	W/48mm Green Insert	20038	53, 6	CL55, CL65, CL500, CL600, E55, E320, E500, S55, S430, S500, S600, SL55, SL65, SL500, SL600, SLR McLaren	Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	W/49mm Black Insert	20039	53, 6		Service Pack	W/43mm Silver Insert	20037	35, 4
	Service Pack	W/51mm Orange Insert	20040	53, 6		Service Pack	W/48mm Green Insert	20038	35, 4
2006	Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/51mm Orange Insert	20040	35, 4
	Service Pack	W/48mm Green Insert	20038	35, 4	2004				
	Service Pack	W/49mm Black Insert	20039	35, 4	CL55, CL500, CL600, E55, E320, E500, S55, S430, S500, S600, SL55, SL500, SL600, SLR McLaren	Service Pack	Does Not Include Valve	20023	35, 4
	Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	W/43mm Silver Insert	20037	35, 4
CLK55, CLK350, CLK500	Sensor	-	28214	58, 6.5		Service Pack	W/48mm Green Insert	20038	35, 4
	Service Pack	Does Not Include Stem	20016	58, 6.5		Service Pack	W/49mm Black Insert	20039	35, 4
	Service Pack	Includes Stem Only	20020	58, 6.5		Service Pack	W/51mm Orange Insert	20040	35, 4
CLS55, CLS500, E55, E320	Sensor	-	20094	53, 6					
	Service Pack	Does Not Include Valve	20021	53, 6					
	Service Pack	Includes Valve	20036	53, 6					
E350	Sensor	W/315 MHz Sensor	20094	53, 6					
	Sensor	W/433 MHz Sensor	20095	53, 6					

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2003					2010 - Continued					
CL55, CL500, CL600, E55, E320, E500, S55, S430, S500, S600, SL55, SL500	Service Pack	Does Not Include Valve	20023	35, 4	Mariner, Milan	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	W/43mm Silver Insert	20037	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	W/48mm Green Insert	20038	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	W/49mm Black Insert	20039	35, 4		Sensor	-	20315	13, 1.5	
	Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	-	20018	13, 1.5	
2002 - 2001					Mountain- eer	EZ-Sensor	-	33000*	11.5, 1.3	
CL55, CL500, CL600, E55, E320, E430, S55, S430, S500, S600, SL500, SL600	Service Pack	Does Not Include Valve	20023	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	W/43mm Silver Insert	20037	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	W/48mm Green Insert	20038	35, 4		Sensor	-	28385	27, 3	
	Service Pack	W/49mm Black Insert	20039	35, 4		Sensor Clip	-	22100	-	
	Service Pack	W/51mm Orange Insert	20040	35, 4	Sensor Cradle	-	22101	-		
2000					Grand Marquis	Sensor Universal Band	-	22102	-	
CL500, E55, S430, S500	Service Pack	Does Not Include Valve	20023	35, 4		2009				
	Service Pack	W/43mm Silver Insert	20037	35, 4		EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	W/48mm Green Insert	20038	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	W/49mm Black Insert	20039	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	W/51mm Orange Insert	20040	35, 4	Sensor	-	28385	27, 3		
1999					Mercury - Continued	Sensor Clip	-	22100	-	
E55	Service Pack	Does Not Include Valve; Jul. & Newer	20023	35, 4		Sensor Cradle	-	22101	-	
	Service Pack	W/43mm Silver Insert; Jul. & Newer	20037	35, 4		Sensor Universal Band	-	22102	-	
	Service Pack	W/48mm Green Insert; Jul. & Newer	20038	35, 4		Mariner	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	W/49mm Black Insert; Jul. & Newer	20039	35, 4			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	W/51mm Orange Insert; Jul. & Newer	20040	35, 4	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
2011					Sensor		-	20315	13, 1.5	
Grand Marquis, Mariner, Milan	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack		-	20018	13, 1.5	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Milan, Mountain- eer	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	-	20315	13, 1.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	2010					Sensor	-	28385	27, 3	
Mercury	Grand Marquis	EZ-Sensor	-	33000*		11.5, 1.3	Sensor Clip	-	22100	-
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Sensor Cradle	-	22101	-	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor Universal Band	-	22102	-	
		Sensor	-	28385	27, 3	Sable	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Clip	-	22100	-	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	
	Sensor Cradle	-	22101	-	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
	Sensor Universal Band	-	22102	-	Sensor		-	28390	27, 3	

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2008					2006 - Continued					
Grand Marquis, Mariner, Milan, Mountaineer	EZ-Sensor	-	33000*	11.5, 1.3	Grand Marquis, Mariner - Cont'd.	Sensor Clip	-	22100	-	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor Cradle	-	22101	-	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor Universal Band	-	22102	-	
	Sensor	-	28385	27, 3		Montego	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor Clip	-	22100	-	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	
	Sensor Cradle	-	22101	-	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
	Sensor Universal Band	-	22102	-	Sensor		-	28390	27, 3	
Sable	EZ-Sensor	-	33000*	11.5, 1.3	Sensor Clip	-	22100	-		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Sensor Cradle	-	22101	-		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor Universal Band	-	22102	-		
	Sensor	-	28390	27, 3	Monterey Van, Mountaineer	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor Clip	-	22100	-		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor Cradle	-	22101	-		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor Universal Band	-	22102	-		Sensor	-	28385	27, 3	
2007					2005					
Grand Marquis, Mariner, Milan	EZ-Sensor	-	33000*	11.5, 1.3	Mariner	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	28385	27, 3		Sensor	Oct. 3, 2005 & Newer	28385	27, 3	
	Montego	Sensor Clip	-	22100	-	Sensor Clip	-	22100	-	
		Sensor Cradle	-	22101	-	Sensor Cradle	-	22101	-	
		Sensor Universal Band	-	22102	-	Sensor Universal Band	-	22102	-	
Monterey Van, Mountaineer		EZ-Sensor	-	33000*	11.5, 1.3	Monterey Van	Sensor	-	20135**	44, 5
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	-	20002	44, 5
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Mountaineer	Sensor	-	20096**	44, 5
		Sensor	-	28390	27, 3		Service Pack	-	20002	44, 5
	Sensor Clip	-	22100	-	2004					
	Sensor Cradle	-	22101	-	Monterey Van	Sensor	-	20135**	44, 5	
	Sensor Universal Band	-	22102	-		Service Pack	-	20002	44, 5	
Monterey Van, Mountaineer	EZ-Sensor	-	33000*	11.5, 1.3	Mountaineer	Sensor	-	20096**	44, 5	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	-	20002	44, 5	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	2003 - 2002					
	Sensor	-	28385	27, 3	Mountaineer	Sensor	-	20096**	44, 5	
	Sensor Clip	-	22100	-		Service Pack	-	20002	44, 5	
	Sensor Cradle	-	22101	-	2011					
	Sensor Universal Band	-	22102	-	Mini	Cooper	Sensor	Includes Transmitter Only	28081	35, 4
2006										
Grand Marquis, Mariner	EZ-Sensor	-	33000*	11.5, 1.3						
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7						
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3						
	Sensor	-	28385	27, 3						

* Programming Tool Required ** Magnet Required to Activate Sensor

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2010					2009 - Continued					
Mini - Continued	Cooper - Cont'd.	Sensor	Includes Transmitter Only	28081	35, 4	Eclipse - Cont'd.	Sensor	-	20034**	45-53, 5-6
		Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	-	20003	45-53, 5-6
		Service Pack	W/43mm Silver Insert	20037	35, 4	Galant	EZ-Sensor	-	33000*	11.5, 1.3
		Service Pack	W/48mm Green Insert	20038	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		Service Pack	W/49mm Black Insert	20039	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Service Pack	W/51mm Orange Insert	20040	35, 4		Sensor	W/Alloy Wheels	20034**	45-53, 5-6
2009 - 2008					Sensor		W/Steel Wheels	28129	45-53, 5-6	
Cooper	Sensor	Includes Transmitter Only	20083	35, 4	Service Pack		W/Alloy Wheels	20003	45-53, 5-6	
	Service Pack	Does Not Include Valve	20023	35, 4	Service Pack	W/Steel Wheels	20010	45-53, 5-6		
	Service Pack	W/43mm Silver Insert	20037	35, 4	Lancer, Outlander	Sensor	-	28096	71, 8	
	Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	-	20030	71, 8	
	Service Pack	W/49mm Black Insert	20039	35, 4	Raider	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	W/51mm Orange Insert	20040	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
2011						EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
Eclipse, Endeavor	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	-	28154	58, 6.5	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	28461	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	Does Not Include Stem	20013	58, 6.5	
	Sensor	-	20034**	49, 5.5	Service Pack	Includes Stem Only	20020	58, 6.5		
Galant	EZ-Sensor	-	33000*	11.5, 1.3	2008					
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Eclipse, Endeavor	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	W/Alloy Wheels	20034**	49, 5.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
Sensor	W/Steel Wheels	28129	45-53, 5-6	Sensor		-	20034**	45-53, 5-6		
Lancer, Outlander	Sensor	W/Alloy Wheels	20398	11.5, 1.3	Service Pack	-	20003	45-53, 5-6		
	Sensor	W/Steel Wheels	28096	71, 8	Galant	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	W/Steel Wheels	20030	71, 8		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Service Pack	W/Alloy Wheels	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
2010						Sensor	W/Alloy Wheels	20034**	45-53, 5-6	
Mitsubishi	Eclipse, Endeavor	EZ-Sensor	-	33000*	11.5, 1.3	Sensor	W/Steel Wheels	28129	45-53, 5-6	
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Service Pack	W/Alloy Wheels	20003	45-53, 5-6	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	W/Steel Wheels	20010	45-53, 5-6	
		Sensor	-	20034**	45-53, 5-6	Lancer, Outlander	Sensor	-	28096	71, 8
	Service Pack	-	20003	45-53, 5-6	Service Pack		-	20030	71, 8	
	Galant	EZ-Sensor	-	33000*	11.5, 1.3	Raider	EZ-Sensor	-	33000*	11.5, 1.3
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Sensor		W/Alloy Wheels	20034**	49, 5.5	Sensor		-	28154	58, 6.5	
Sensor	W/Steel Wheels	28129	45-53, 5-6	Sensor	-		28461	11.5, 1.3		
Lancer, Outlander	Sensor	-	28096	71, 8	Service Pack		Does Not Include Stem	20013	58, 6.5	
	Service Pack	-	20030	71, 8	Service Pack	Includes Stem Only	20020	58, 6.5		
2009					2007					
Eclipse	EZ-Sensor	-	33000*	11.5, 1.3	Eclipse	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3						

* Programming Tool Required ** Magnet Required to Activate Sensor

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
2007 - Continued					2005 - 2004 - Continued						
Eclipse - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Mitsubishi - Continued	Montero	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	W/Alloy Wheels	20034**	45-53, 5-6			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	W/Steel Wheels	28129	45-53, 5-6			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	W/Alloy Wheels	20003	45-53, 5-6			Sensor	-	20034**	45-53, 5-6	
	Service Pack	W/Steel Wheels	20010	45-53, 5-6			Service Pack	-	20003	45-53, 5-6	
Endeavor	EZ-Sensor	-	33000*	11.5, 1.3			2003				
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Mitsubishi - Continued	Montero	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	-	20034**	45-53, 5-6			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	-	20003	45-53, 5-6			Sensor	-	20034**	45-53, 5-6	
Service Pack	-	20003	45-53, 5-6	Service Pack			-	20003	45-53, 5-6		
Galant	EZ-Sensor	-	33000*	11.5, 1.3	2011						
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Mitsubishi - Continued	Altima	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	W/Alloy Wheels	20034**	45-53, 5-6			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	W/Steel Wheels	28129	45-53, 5-6			Sensor	-	28204	49, 5.5	
	Service Pack	W/Alloy Wheels	20003	45-53, 5-6			Service Pack	-	20014	71, 8	
	Service Pack	W/Steel Wheels	20010	45-53, 5-6			Mitsubishi - Continued	Armada	EZ-Sensor	-	33000*
Outlander	Sensor	-	28096	71, 8					EZ-Sensor Service Pack	Almnm. Valve	34000
Service Pack	-	20030	71, 8	EZ-Sensor Service Pack	Rubber Valve	20008			11.5, 1.3		
2006					Nissan	Armada	Sensor	-	28204	49, 5.5	
Eclipse	EZ-Sensor	-	33000*	11.5, 1.3			Service Pack	-	20014	49, 5.5	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			Cube	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3				EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor	W/Alloy Wheels	20034**	45-53, 5-6		EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
	Sensor	W/Steel Wheels	28129	45-53, 5-6		Sensor	-	28204	49, 5.5		
	Service Pack	W/Alloy Wheels	20003	45-53, 5-6		Service Pack	-	20014	71, 8		
	Service Pack	W/Steel Wheels	20010	45-53, 5-6		Frontier	EZ-Sensor	-	33000*	11.5, 1.3	
Endeavor	EZ-Sensor	-	33000*	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			Sensor	-	28204	49, 5.5	
	Sensor	Sept. 1 & Newer	20034**	45-53, 5-6			Service Pack	-	20014	49, 5.5	
	Sensor	Aug. & Older	20028**	45-53, 5-6		GT-R	EZ-Sensor	-	33000*	11.5, 1.3	
Service Pack	-	20003	45-53, 5-6	EZ-Sensor Service Pack			Almnm. Valve	34000	62, 7		
Galant	Sensor	-	20028**	45-53, 5-6			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	-	20003	45-53, 5-6			Sensor	-	28204	49, 5.5	
Montero	EZ-Sensor	-	33000*	11.5, 1.3			Service Pack	-	20014	71, 8	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Juke	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	-	20034**	45-53, 5-6			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	-	20003	45-53, 5-6	Sensor		-	28204	49, 5.5		
Service Pack	-	20003	45-53, 5-6	Service Pack	-		20014	49, 5.5			
2005 - 2004					Mitsubishi - Continued	Endeavor, Galant	Sensor	-	20028**	45-53, 5-6	
Endeavor, Galant	Service Pack	-	20003	45-53, 5-6			Service Pack	-	20003	45-53, 5-6	

* Programming Tool Required ** Magnet Required to Activate Sensor

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2011 - Continued					2010 - Continued					
Nissan - Continued	Maxima	EZ-Sensor	-	33000*	11.5, 1.3	Maxima	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Sensor	-	28204	49, 5.5		Sensor	-	28204	68, 7.7
		Service Pack	-	20014	71, 8		Service Pack	-	20014	68, 7.7
	Murano, Pathfinder, Rogue	EZ-Sensor	-	33000*	11.5, 1.3	Pathfinder	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Sensor	-	28204	49, 5.5		Sensor	-	28204	49, 5.5
		Service Pack	-	20014	49, 5.5		Service Pack	-	20014	49, 5.5
	Sentra	EZ-Sensor	-	33000*	11.5, 1.3	Sentra	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Sensor	-	28204	49, 5.5		Sensor	-	28204	68, 7.7
		Service Pack	-	20014	71, 8		Service Pack	-	20014	68, 7.7
	Titan	EZ-Sensor	-	33000*	11.5, 1.3	Titan	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Sensor	-	28204	49, 5.5		Sensor	-	28204	49, 5.5
		Service Pack	-	20014	49, 5.5		Service Pack	-	20014	49, 5.5
	Versa	EZ-Sensor	-	33000*	11.5, 1.3	Versa	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Sensor	-	28204	49, 5.5		Sensor	-	28204	71, 8
Service Pack		-	20014	71, 8	Service Pack		-	20014	71, 8	
Xterra	EZ-Sensor	-	33000*	11.5, 1.3	Xterra	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	28204	49, 5.5		Sensor	-	28204	49, 5.5	
	Service Pack	-	20014	49, 5.5		Service Pack	-	20014	49, 5.5	
2010					2009					
Altima	EZ-Sensor	-	33000*	11.5, 1.3	350Z	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	28204	71, 8		Sensor	-	28204	71, 8	
	Service Pack	-	20014	71, 8		Service Pack	-	20014	71, 8	
Armada, Frontier	EZ-Sensor	-	33000*	11.5, 1.3	370Z	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	28204	49, 5.5		Sensor	-	28210	71, 8	
	Service Pack	-	20014	49, 5.5		Service Pack	-	20014	71, 8	

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2009 - Continued					2009 - Continued				
Altima	EZ-Sensor	-	33000*	11.5, 1.3	Titan	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28204	71, 8		Sensor	-	28204	49, 5.5
	Service Pack	-	20014	71, 8		Service Pack	-	20014	49, 5.5
Armada	EZ-Sensor	-	33000*	11.5, 1.3	Versa	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28204	49, 5.5		Sensor	-	28204	71, 8
	Service Pack	-	20014	49, 5.5		Service Pack	-	20014	71, 8
Cube	EZ-Sensor	-	33000*	11.5, 1.3	Xterra	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28204	71, 8		Sensor	-	28204	49, 5.5
	Service Pack	-	20014	71, 8		Service Pack	-	20014	49, 5.5
Frontier	EZ-Sensor	-	33000*	11.5, 1.3	2008				
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	350Z, Altima	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor	-	28204	49, 5.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	-	20014	49, 5.5		Sensor	-	28204	71, 8
Service Pack	-	20014	49, 5.5	Service Pack		-	20014	71, 8	
GT-R	EZ-Sensor	-	33000*	11.5, 1.3	Armada	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28204	71, 8		Sensor	LE	28204	49, 5.5
	Service Pack	-	20014	71, 8		Sensor	SE	20161	49, 5.5
Maxima, Murano	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	LE	20014	49, 5.5	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Service Pack	SE	20007	49, 5.5	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Frontier	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	28204	68, 7.7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	-	20014	68, 7.7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Service Pack	-	20014	49, 5.5	Sensor		W/Alloy Wheels	20161	49, 5.5	
Service Pack	-	20014	49, 5.5	Sensor		W/Steel Wheels	28204	49, 5.5	
Pathfinder, Quest	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	W/Alloy Wheels	20007	49, 5.5	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Service Pack	W/Steel Wheels	20014	49, 5.5	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Maxima	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	28204	49, 5.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor	-	28204	49, 5.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Service Pack	-	20014	49, 5.5	Sensor		-	28204	68, 7.7	
Service Pack	-	20014	49, 5.5	Service Pack		-	20014	68, 7.7	
Rogue, Sentra	EZ-Sensor	-	33000*	11.5, 1.3	Pathfinder, Quest	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3					
	Sensor	-	28204	68, 7.7					
	Service Pack	-	20014	68, 7.7					

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.						
2008 - Continued					2007 - Continued										
Pathfinder, Quest - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Frontier - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3						
	Sensor	-	28204	49, 5.5		Sensor	W/Alloy Wheels	20161	49, 5.5						
	Service Pack	-	20014	49, 5.5		Sensor	W/Steel Wheels	20069	49, 5.5						
Rogue	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	W/Alloy Wheels	20007	49, 5.5						
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Service Pack	W/Steel Wheels	20005	49, 5.5						
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Maxima	EZ-Sensor	-	33000*	11.5, 1.3					
	Sensor	-	28204	68, 7.7	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7						
	Service Pack	-	20014	68, 7.7	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3						
	Sentra	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	Apr. 1 & Newer	28204	68, 7.7					
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	Sensor		Mar. & Older	20161	49, 5.5						
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Service Pack		Apr. 1 & Newer	20014	68, 7.7						
Sensor		-	28204	71, 8	Service Pack	Mar. & Older	20007	49, 5.5							
Titan	EZ-Sensor	-	33000*	11.5, 1.3	Murano	EZ-Sensor	-	33000*	11.5, 1.3						
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7						
Versa	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3						
	Sensor	-	28204	49, 5.5		Sensor	-	28204	71, 8						
	Service Pack	-	20014	49, 5.5	Service Pack	-	20014	71, 8							
	Xterra	EZ-Sensor	-	33000*	11.5, 1.3	Pathfinder	EZ-Sensor	-	33000*	11.5, 1.3					
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7						
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3						
Sensor		-	28204	49, 5.5	Sensor		OEM Part No. 40700JA01A	28167	49, 5.5						
Service Pack	-	20014	49, 5.5	Sensor	OEM Part No. 40700JA01B		28204	49, 5.5							
Nissan - Continued	2007				Nissan - Continued		Service Pack	-	20014	49, 5.5	Quest	EZ-Sensor	-	33000*	11.5, 1.3
	350Z, Altima	EZ-Sensor	-	33000*		11.5, 1.3	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000		62, 7	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	-	28204	49, 5.5
		EZ-Sensor Service Pack	Rubber Valve	20008		11.5, 1.3	Sensor	-	28204	49, 5.5		Service Pack	-	20014	49, 5.5
		Sensor	-	28204		71, 8	Sentra	EZ-Sensor	-	33000*	11.5, 1.3	EZ-Sensor	-	33000*	11.5, 1.3
		Service Pack	-	20014		71, 8		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Armada	EZ-Sensor	-	33000*		11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor	W/Alloy Wheels	20161	78, 8.8
		EZ-Sensor Service Pack	Almnm. Valve	34000		62, 7		Sensor	W/Steel Wheels	28204	71, 8	Sensor	W/Steel Wheels	28204	71, 8
		EZ-Sensor Service Pack	Rubber Valve	20008		11.5, 1.3		Service Pack	W/Alloy Wheels	20007	78, 8.8	Service Pack	W/Alloy Wheels	20007	78, 8.8
		Sensor	-	20161		49, 5.5		Service Pack	W/Steel Wheels	20014	71, 8	Service Pack	W/Steel Wheels	20014	71, 8
Frontier	EZ-Sensor	-	33000*	11.5, 1.3	Titan	EZ-Sensor	-	33000*	11.5, 1.3	EZ-Sensor	-	33000*	11.5, 1.3		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor	Apr. 1 & Newer	28204	49, 5.5		
						Sensor	Apr. 1 & Newer	28204	49, 5.5	Sensor	Mar. & Older	20161	49, 5.5		
						Sensor	Mar. & Older	20161	49, 5.5	Service Pack	Apr. 1 & Newer	20014	49, 5.5		
						Service Pack	Apr. 1 & Newer	20014	49, 5.5	Service Pack	Mar. & Older	20007	49, 5.5		

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2007 - Continued					2006 - Continued				
Versa	EZ-Sensor	-	33000*	11.5, 1.3	Pathfinder	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	OEM Part No. 40700JA01A	28167	71, 8		Sensor	-	20161	49, 5.5
	Sensor	OEM Part No. 40700JA01B	28204	71, 8		Service Pack	-	20007	49, 5.5
	Service Pack	-	20014	71, 8		Quest	EZ-Sensor	-	33000*
Xterra	EZ-Sensor	-	33000*	11.5, 1.3	EZ-Sensor Service Pack		Alnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor		W/Alloy Wheels	20161	78, 8.8
	Sensor	OEM Part No. 40700JA01A	28167	49, 5.5	Sensor		W/Steel Wheels	20069	78, 8.8
	Sensor	OEM Part No. 40700JA01B	28204	49, 5.5	Service Pack		W/Alloy Wheels	20007	78, 8.8
	Service Pack	-	20014	49, 5.5	Service Pack	W/Steel Wheels	20005	78, 8.8	
2006					Titan	EZ-Sensor	-	33000*	11.5, 1.3
350Z	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	-	20161	49, 5.5
	Sensor	-	20064	49, 5.5		Service Pack	-	20007	49, 5.5
	Service Pack	-	20007	49, 5.5		Xterra	EZ-Sensor	-	33000*
Altima	EZ-Sensor	-	33000*	11.5, 1.3	EZ-Sensor Service Pack		Alnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor		Exc. Submodel X	20161	49, 5.5
	Sensor	Oct. 1 & Newer	28204	71, 8	Sensor		Submodel X	20069	49, 5.5
Service Pack	Oct. 1 & Newer	20014	71, 8	Service Pack	Exc. Submodel X		20007	49, 5.5	
Armada, Frontier	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	Submodel X	20005	49, 5.5	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	2005				
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	350Z	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	W/Alloy Wheels	20161	49, 5.5		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Sensor	W/Steel Wheels	20069	49, 5.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	W/Alloy Wheels	20007	49, 5.5		Sensor	-	20064	49, 5.5
Service Pack	W/Steel Wheels	20005	49, 5.5	Service Pack		-	20007	49, 5.5	
Maxima	EZ-Sensor	-	33000*	11.5, 1.3		Armada, Frontier	EZ-Sensor	-	33000*
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	EZ-Sensor Service Pack		Alnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3
	Sensor	Jun. & Newer	20161	49, 5.5	Sensor		W/Alloy Wheels	20161	49, 5.5
	Service Pack	Jun. & Newer	20007	49, 5.5	Sensor		W/Steel Wheels	20069	49, 5.5
	Murano	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	W/Alloy Wheels	20007
EZ-Sensor Service Pack		Alnm. Valve	34000	62, 7	Service Pack	W/Steel Wheels	20005	49, 5.5	
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Murano	EZ-Sensor	-	33000*	11.5, 1.3
Sensor		-	20064	66, 7.5		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
Service Pack		-	20007	66, 7.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
				Sensor		-	20064	66, 7.5	
				Service Pack		-	20007	66, 7.5	

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2005 - Continued					2004 - Continued				
Pathfinder	EZ-Sensor	-	33000*	11.5, 1.3	Pathfinder - Cont'd.	EZ-Sensor	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		Sensor	Armada	20069	49, 5.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	Exc. Armada; Aug. & Newer	20069	49, 5.5
	Sensor	-	20161	49, 5.5		Sensor	Exc. Armada; Jul. & Older	20064	49, 5.5
	Service Pack	-	20007	49, 5.5		Service Pack	Armada	20005	49, 5.5
Quest	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	Exc. Armada; Aug. & Newer	20005	49, 5.5	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Service Pack	Exc. Armada; Jul. & Older	20007	49, 5.5	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Quest	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	W/Alloy Wheels	20161	78, 8.8		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Sensor	W/Steel Wheels	20069	78, 8.8		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	W/Alloy Wheels	20007	78, 8.8	Sensor	-	20069	78, 8.8	
	Service Pack	W/Steel Wheels	20005	78, 8.8	Service Pack	-	20005	78, 8.8	
Titan	EZ-Sensor	-	33000*	11.5, 1.3	Titan	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	Apr. 1 & Newer	20161	49, 5.5		Sensor	-	20069	49, 5.5
	Sensor	Mar. & Older	20069	49, 5.5		Service Pack	-	20005	49, 5.5
	Service Pack	Apr. 1 & Newer	20007	49, 5.5	Xterra	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	Mar. & Older	20005	49, 5.5		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
Xterra	EZ-Sensor	-	33000*	11.5, 1.3	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Sensor	-	20064	36-60, 4.1-6.8	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	-	20007	36-60, 4.1-6.8	
	Sensor	-	20161	36-60, 4.1-6.8	2003				
	Service Pack	-	20007	36-60, 4.1-6.8	350Z	EZ-Sensor	-	33000*	11.5, 1.3
2004						EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
350Z	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		Sensor	-	20064	49, 5.5
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20007	49, 5.5
	Sensor	-	20064	49, 5.5	Frontier	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20007	49, 5.5		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Frontier	EZ-Sensor	-	33000*	11.5, 1.3	Sensor	-	20064	36-60, 4.1-6.8	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Service Pack	-	20007	36-60, 4.1-6.8	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Murano	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	20064	36-60, 4.1-6.8		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Service Pack	-	20007	36-60, 4.1-6.8		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Murano	EZ-Sensor	-	33000*	11.5, 1.3	Sensor	-	20064	66, 7.5	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Service Pack	-	20007	66, 7.5	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Pathfinder	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	20064	66, 7.5		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Service Pack	-	20007	66, 7.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Pathfinder	EZ-Sensor	-	33000*	11.5, 1.3					
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7					

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2003 - Continued					2009 - Continued					
Nissan - Continued	Pathfinder - Cont'd.	Sensor	-	20064	49, 5.5	Vibe	EZ-Sensor	-	33000*	11.5, 1.3
		Service Pack	-	20007	49, 5.5		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
	Xterra	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Sensor	-	28360	35, 4
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20032	35, 4
		Sensor	-	20064	36-60, 4.1-6.8		2008			
Service Pack	-	20007	36-60, 4.1-6.8	G5, G6	EZ-Sensor	-	33000*	11.5, 1.3		
2001 - 1999					EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		
Plymouth	Prowler	Sensor	-		28004	35, 4	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Service Pack	W/Black Sensor Body		20012	35, 4	Sensor	-	20158	62, 7
		Service Pack	W/Red Sensor Body		20003	35, 4	Service Pack	W/Schrader Sensor	20004	62, 7
1997					G8	Service Pack	W/Siemens Sensor	20030	80, 9	
Prowler	Sensor	-	28004	35, 4		EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	W/Black Sensor Body	20012	35, 4		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
	Service Pack	W/Red Sensor Body	20003	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
2010						Grand Prix	Sensor	-	20153	62, 7
G3, G5, G6, G8	EZ-Sensor	-	33000*	11.5, 1.3			Service Pack	-	20008	62, 7
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	Grand		EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			EZ-Sensor Service Pack	Almm. Valve	34000	62, 7
	Sensor	-	20153	11.5, 1.3			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	-	20008	11.5, 1.3			Sensor	Clamp-In Style Only; W/ Almm. Valve Stem	20158	62, 7
Solstice	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	Snap-In Style Only; W/ Rubber Valve Stem	20153	11.5, 1.3	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	Clamp-In Style Only; W/ Almm. Valve Stem	20004	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	Snap-In Style Only; W/ Rubber Valve Stem	20008	11.5, 1.3		
	Sensor	-	20158	62, 7	Montana, Solstice, Torrent	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	W/Schrader Sensor	20004	62, 7		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
Service Pack	W/Siemens Sensor	20030	80, 9	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3		
Vibe	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	-	20158	62, 7	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	W/Schrader Sensor	20004	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	W/Siemens Sensor	20030	80, 9	
	Sensor	-	28360	35, 4	Vibe	EZ-Sensor	-	33000*	11.5, 1.3	
	Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	
2009						EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
G3, G3 Wave, G5, G6, G8	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	-	28360	35, 4	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	-	20032	35, 4	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Wave	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	20153	11.5, 1.3	EZ-Sensor Service Pack		Almm. Valve	34000	62, 7	
	Service Pack	-	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Montana, Solstice, Torrent	EZ-Sensor	-	33000*	11.5, 1.3	Sensor		-	20153	11.5, 1.3	
	EZ-Sensor Service Pack	Almm. Valve	34000	62, 7	Service Pack		-	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3						
	Sensor	-	20158	62, 7						
	Service Pack	W/Schrader Sensor	20004	62, 7						
Service Pack	W/Siemens Sensor	20030	80, 9							

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.			
2007					2009 - Continued							
Pontiac - Continued	Grand Prix, Torrent	EZ-Sensor	-	33000*	11.5, 1.3	911, Boxster, Cayenne - Cont'd.	Service Pack	W/49mm Black Insert	20039	31-40, 3.5-4.5		
		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	W/51mm Orange Insert	20040	31-40, 3.5-4.5		
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Cayman	Sensor	Includes Transmitter Only	28087	31-40, 3.5-4.5		
		Sensor	-	20158	62, 7		Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5		
		Service Pack	W/Schrader Sensor	20004	62, 7		Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5		
		Service Pack	W/Siemens Sensor	20030	80, 9		Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5		
				Service Pack	W/49mm Black Insert		20039	31-40, 3.5-4.5				
				Service Pack	W/51mm Orange Insert		20040	31-40, 3.5-4.5				
2011					2008							
Porsche	911, Boxster	Sensor	Includes Transmitter Only	20077	35, 4	911, Boxster, Cayenne, Cayman	Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5		
		Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5		
		Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5		
		Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/49mm Black Insert	20039	31-40, 3.5-4.5		
		Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/51mm Orange Insert	20040	31-40, 3.5-4.5		
		Service Pack	W/51mm Orange Insert	20040	35, 4		2007					
	Cayenne	Sensor	Includes Transmitter Only	20103	35, 4	911, Boxster, Cayman	Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5		
		Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5		
		Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5		
		Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/49mm Black Insert	20039	31-40, 3.5-4.5		
		Service Pack	W/51mm Orange Insert	20040	35, 4		Service Pack	W/51mm Orange Insert	20040	31-40, 3.5-4.5		
							2006					
	Cayman	Sensor	Includes Transmitter Only	20077	35, 4	911, Boxster, Carrera GT, Cayenne, Cayman	Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5		
		Service Pack	Does Not Include Valve	20023	35, 4		Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5		
		Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5		
		Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/49mm Black Insert	20039	31-40, 3.5-4.5		
		Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/51mm Orange Insert	20040	31-40, 3.5-4.5		
		Service Pack	W/51mm Orange Insert	20040	35, 4		2005					
		Panamera	Sensor	Includes Transmitter Only	28087		31-40, 3.5-4.5	911, Boxster, Carrera GT, Cayenne	Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5
			Service Pack	W/43mm Silver Insert	20037		31-40, 3.5-4.5		Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5
			Service Pack	W/48mm Green Insert	20038		31-40, 3.5-4.5		Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5
			Service Pack	W/49mm Black Insert	20039		31-40, 3.5-4.5		Service Pack	W/49mm Black Insert	20039	31-40, 3.5-4.5
			Service Pack	W/51mm Orange Insert	20040		31-40, 3.5-4.5		Service Pack	W/51mm Orange Insert	20040	31-40, 3.5-4.5
									2004			
2010					Porsche - Continued	Carrera GT, Cayenne	Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5		
911, Boxster	Sensor	Includes Transmitter Only	28087	31-40, 3.5-4.5			Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5		
	Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5			Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5		
	Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5			Service Pack	W/49mm Black Insert	20039	31-40, 3.5-4.5		
	Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5			Service Pack	W/51mm Orange Insert	20040	31-40, 3.5-4.5		
	Service Pack	W/49mm Black Insert	20039	31-40, 3.5-4.5			2003					
	Service Pack	W/51mm Orange Insert	20040	31-40, 3.5-4.5		Cayenne	Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5		
Cayenne	Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5			Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5		
	Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5			Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5		
	Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5			Service Pack	W/49mm Black Insert	20039	31-40, 3.5-4.5		
	Service Pack	W/49mm Black Insert	20039	31-40, 3.5-4.5			Service Pack	W/51mm Orange Insert	20040	31-40, 3.5-4.5		
	Service Pack	W/51mm Orange Insert	20040	31-40, 3.5-4.5		2010 - 2007						
	Cayman, Panamera	Sensor	Includes Transmitter Only	28087		31-40, 3.5-4.5	Phantom	Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5	
Service Pack		Does Not Include Valve	20023	31-40, 3.5-4.5		Service Pack		W/43mm Silver Insert	20037	31-40, 3.5-4.5		
Service Pack		W/43mm Silver Insert	20037	31-40, 3.5-4.5		Service Pack		W/48mm Green Insert	20038	31-40, 3.5-4.5		
Service Pack		W/48mm Green Insert	20038	31-40, 3.5-4.5		Service Pack		W/49mm Black Insert	20039	31-40, 3.5-4.5		
Service Pack		W/49mm Black Insert	20039	31-40, 3.5-4.5		Service Pack		W/51mm Orange Insert	20040	31-40, 3.5-4.5		
Service Pack		W/51mm Orange Insert	20040	31-40, 3.5-4.5		2009						
911, Boxster, Cayenne	Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5			Service Pack	Does Not Include Valve	20023	31-40, 3.5-4.5		
	Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5			Service Pack	W/43mm Silver Insert	20037	31-40, 3.5-4.5		
	Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5			Service Pack	W/48mm Green Insert	20038	31-40, 3.5-4.5		

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
2011 - 2010					2008 - Continued						
Saab	9-3, 9-5	Sensor	-	20159	88, 10	Aura - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
		Service Pack	-	20009	88, 10		Sensor	-	20153	11.5, 1.3	
	Service Pack	-	20008	11.5, 1.3	Service Pack		-	20008	11.5, 1.3		
	2009 - 2008					Saturn - Continued	Outlook	EZ-Sensor	-	33000*	11.5, 1.3
	9-3, 9-5	Sensor	-	20159	88, 10			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
		Service Pack	-	20009	88, 10			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	9-7X 9-7X	Sensor	-	20116	62, 7		Sensor	-	20158	62, 7	
		Service Pack	-	20004	62, 7		Service Pack	W/Schrader Sensor	20004	62, 7	
	2007 - 2005						Sky	Service Pack	W/Siemens Sensor	20030	62, 7
	9-3, 9-5	Sensor	-	28078	62, 7			EZ-Sensor	-	33000*	11.5, 1.3
		Service Pack	-	20009	62, 7			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	9-7X	Sensor	-	20116	62, 7			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Service Pack		-	20004	62, 7	Sensor			-	20158	62, 7	
2004 - 2003					VUE			Service Pack	W/Schrader Sensor	20004	62, 7
9-3, 9-5	Sensor	-	28078	62, 7				Service Pack	W/Siemens Sensor	20030	80, 9
	Service Pack	-	20009	62, 7		EZ-Sensor		-	33000*	11.5, 1.3	
2010 - 2009						Saturn		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Astra	EZ-Sensor	-	33000*	11.5, 1.3				EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7				Sensor	-	28206	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3				Service Pack	-	20008	11.5, 1.3
	Sensor	-	28206	11.5, 1.3			Aura, Outlook	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20008	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
Aura, Outlook	EZ-Sensor	-	33000*	11.5, 1.3			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			Sensor	-	20153	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			Service Pack	-	20008	11.5, 1.3	
	Sensor	-	20153	11.5, 1.3	2007		Aura, Outlook	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20008	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
Sky	EZ-Sensor	-	33000*	11.5, 1.3			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Sensor		-	20158	62, 7			
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack		W/Schrader Sensor	20004	62, 7			
Sky	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	W/Siemens Sensor	20030	80, 9			
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	2011	iQ, TC, XB, XD	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
	Sensor	-	20158	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
	Service Pack	W/Schrader Sensor	20004	62, 7		Sensor	-	28365	35, 4		
Service Pack	W/Siemens Sensor	20030	80, 9	Service Pack		-	20032	35, 4			
VUE	EZ-Sensor	-	33000*	11.5, 1.3	2010 - 2008	TC, XB, XD	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	20153	11.5, 1.3			Sensor	-	28365	35, 4	
	Service Pack	-	20008	11.5, 1.3			Service Pack	-	20032	35, 4	
2008					Saturn	TC	EZ-Sensor	-	33000*	11.5, 1.3	
Astra	EZ-Sensor	-	33000*	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			Sensor	-	28365	35, 4	
	Sensor	-	28078	80, 9			Service Pack	-	20032	35, 4	
	Service Pack	-	20009	80, 9	2007						
Aura	EZ-Sensor	-	33000*	11.5, 1.3	EZ-Sensor	-	33000*	11.5, 1.3			
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
2007 - Continued					2008 - Continued						
Scion - Continued	TC - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Outback	EZ-Sensor	-	33000*	11.5, 1.3	
		Sensor	-	28365	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
		Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	2006						Tribeca	Sensor	-	28203	11.5, 1.3
	TC	EZ-Sensor	-	33000*	11.5, 1.3			Service Pack	-	20008	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	
		Sensor	May & Newer	28365	35, 4	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
		Service Pack	May & Newer	20032	35, 4	Sensor		W/Metal Stem Clamp-in Sensor	20081	66, 7.5	
	2010 - 2008					Subaru - Continued	Sensor	W/Rubber Stem Snap-in Sensor	28203	11.5, 1.3	
Smart	Fortwo	Sensor	-	28214	53, 6		Service Pack	W/Metal Stem Clamp-in Sensor	20011	66, 7.5	
		Service Pack	Does Not Include Stem	20016	53, 6		Service Pack	W/Rubber Stem Snap-in Sensor	20008	11.5, 1.3	
		Service Pack	Includes Stem Only	20020	53, 6		2007				
2011					B9 Tribeca, Legacy		EZ-Sensor	-	33000*	11.5, 1.3	
Forester, Impreza, Legacy, Outback	EZ-Sensor	-	33000*	11.5, 1.3			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			Sensor	-	20081	66, 7.5	
	Sensor	-	28203	11.5, 1.3			Service Pack	-	20011	66, 7.5	
	Service Pack	-	20008	11.5, 1.3			2006				
Tribeca	EZ-Sensor	-	33000*	11.5, 1.3		B9 Tribeca, Legacy, Outback	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	28203	11.5, 1.3			Sensor	-	20081	66, 7.5	
	Service Pack	-	20011	66, 7.5	Service Pack		-	20011	66, 7.5		
2010 - 2009					2005 - 2004						
Subaru	Forester, Impreza, Legacy, Outback, Tribeca	EZ-Sensor	-	33000*	11.5, 1.3	Legacy, Outback	EZ-Sensor	-	33000*	11.5, 1.3	
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
		Sensor	-	28203	11.5, 1.3		Sensor	-	20081	66, 7.5	
		Service Pack	-	20008	11.5, 1.3		Service Pack	-	20011	66, 7.5	
2008					2011						
Forester, Impreza	EZ-Sensor	-	33000*	11.5, 1.3	Equator	EZ-Sensor	-	33000*	11.5, 1.3		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
	Sensor	-	28203	11.5, 1.3		Sensor	-	28204	49, 5.5		
	Service Pack	-	20008	11.5, 1.3		Service Pack	-	20014	49, 5.5		
Legacy	EZ-Sensor	-	33000*	11.5, 1.3	Suzuki	Grand Vitara	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7			EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	W/16" Or 17" Wheels	20081	66, 7.5			Sensor	-	20087	80, 9	
	Service Pack	W/16" Or 17" Wheels	20011	66, 7.5			Service Pack	-	20009	80, 9	
Service Pack	W/18" Wheels	28203	11.5, 1.3								
Service Pack	W/16" Or 17" Wheels	20011	66, 7.5								
Service Pack	W/18" Wheels	20008	11.5, 1.3								

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2011 - Continued					2009 - Continued				
Kizashi	EZ-Sensor	-	33000*	11.5, 1.3	XL-7 - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	20158	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	W/Schrader Sensor	20004	62, 7
	Sensor	-	20066	58, 6.5		Service Pack	W/Siemens Sensor	20030	62, 7
	Sensor	-	28308	11.5, 1.3	2008 - 2007				
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Forenza	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	W/Siemens Sensor	20030	71, 8		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	SX4	EZ-Sensor	-	33000*		11.5, 1.3	Sensor	-	20153
Grand Vitara	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Service Pack	-	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Grand Vitara	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	20087	80, 9		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	-	20009	80, 9		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	SX4	EZ-Sensor	-	33000*		11.5, 1.3	Sensor	-	20087
Grand Vitara	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Service Pack	-	20009	80, 9	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Reno	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	20087	80, 9		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Service Pack	-	20009	80, 9		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	SX4	EZ-Sensor	-	33000*		11.5, 1.3	Sensor	-	20153
Kizashi	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	SX4	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Sensor	-	20066	58, 6.5		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28308	11.5, 1.3		Sensor	-	20087	80, 9
	Service Pack	W/Schrader Sensor; Includes Stem Only	20020	58, 6.5	Service Pack	-	20009	80, 9	
	Service Pack	W/Schrader Sensor; Does Not Include Stem	20013	58, 6.5	XL-7	EZ-Sensor	-	33000*	11.5, 1.3
Service Pack	W/Siemens Sensor	20030	71, 8	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	
SX4	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Grand Vitara, SX4	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	20158	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	W/Schrader Sensor	20004	62, 7	
	Sensor	-	20087	80, 9	Service Pack	W/Siemens Sensor	20030	62, 7	
	Service Pack	-	20009	80, 9	2006 - 2005				
	Service Pack	-	20009	80, 9	Verona	EZ-Sensor	-	33000*	11.5, 1.3
XL-7	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Grand Vitara, SX4	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	20082	80, 9
XL-7	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20009	80, 9	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	XL-7	EZ-Sensor	-	33000*	11.5, 1.3
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	
Sensor	-	20087	80, 9	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Service Pack	-	20009	80, 9	Sensor		-	20087	80, 9	
XL-7	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20009	80, 9	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7					

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.			
2011					2011 - Continued							
Toyota	4 Runner	EZ-Sensor	-	33000*	11.5, 1.3	Matrix	EZ-Sensor	-	33000*	11.5, 1.3		
		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
		Sensor	-	28370	35, 4		Sensor	Models made in Japan.; OEM Part No. 4260733011	28365	35, 4		
		Service Pack	-	20032	35, 4		Sensor	Models made in USA.; OEM Part No. 4260706011	28360	35, 4		
	Avalon	EZ-Sensor	-	33000*	11.5, 1.3		Service Pack	-	20032	35, 4		
		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		Prius	EZ-Sensor	-	33000*	11.5, 1.3	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	
		Sensor	-	28360	35, 4			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
		Service Pack	-	20032	35, 4			Sensor	-	28365	35, 4	
	Camry	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack		-	20032	35, 4		
		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	RAV4	EZ-Sensor	-	33000*	11.5, 1.3		
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		
		Sensor	Models made in Japan.; OEM Part No. 4260733011	28365	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
		Sensor	Models made in USA.; OEM Part No. 4260706011	28360	35, 4		Sensor	-	28370	35, 4		
	Service Pack	-	20032	35, 4	Service Pack		-	20032	35, 4			
	Corolla	EZ-Sensor	-	33000*	11.5, 1.3	Sequoia, Sienna	EZ-Sensor	-	33000*	11.5, 1.3		
		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
		Sensor	Models made in Japan.; OEM Part No. 4260733011	28365	35, 4		Sensor	-	28670	35, 4		
		Sensor	Models made in Japan.; OEM Part No. 4260733021	28370	35, 4		Service Pack	-	20022	35, 4		
		FJ Cruiser	Sensor	Models made in USA.; W/15" Wheels	28365	35, 4	Tacoma	EZ-Sensor	-	33000*	11.5, 1.3	
			Sensor	Models made in USA.; W/16" Or 17" Wheels	28360	35, 4		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	
			Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
			Highlander	EZ-Sensor	-	33000*		11.5, 1.3	Sensor	W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35, 4
				EZ-Sensor Service Pack	Alnm. Valve	34000		62, 7	Sensor	W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35, 4
	EZ-Sensor Service Pack	Rubber Valve		20008	11.5, 1.3	Service Pack	-	20032	35, 4			
	Sensor	-		28365	35, 4	Tundra	EZ-Sensor	-	33000*	11.5, 1.3		
	Service Pack	-		20032	35, 4		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		
	Land Cruiser	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		
EZ-Sensor Service Pack		Alnm. Valve	34000	62, 7	Sensor		-	28670	35, 4			
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	Service Pack		-	20022	35, 4			
Sensor		-	28360	35, 4	Venza	EZ-Sensor	-	33000*	11.5, 1.3			
Service Pack		-	20032	35, 4		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7			
Yaris	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3			
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		Sensor	-	28360	35, 4			
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20032	35, 4			
	Sensor	-	28365	35, 4	EZ-Sensor	-	33000*	11.5, 1.3				
	Service Pack	-	20032	35, 4	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7				

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2011 - Continued					2010 - Continued				
Yaris - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Matrix - Cont'd.	Sensor	Models made in USA.; OEM Part No. 4260706011	28360	35, 4
	Sensor	-	28365	35, 4		Service Pack	-	20032	35, 4
	Service Pack	-	20032	35, 4	Prius	EZ-Sensor	-	33000*	11.5, 1.3
2010						EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
4 Runner	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	28365	35, 4
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20032	35, 4
	Sensor	-	28370	35, 4	RAV4	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Avalon	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	28370	35, 4
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	-	20032	35, 4	
	Sensor	-	28360	35, 4	Sequoia, Sienna	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Camry	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	-	28670	35, 4
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	-	20022	35, 4	
	Sensor	Models made in Japan.; OEM Part No. 4260733011	28365	35, 4	Tacoma	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	Models made in USA.; OEM Part No. 4260706011	28360	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Service Pack	-	20032	35, 4	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Corolla	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35, 4
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35, 4
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	-	20032	35, 4	
	Sensor	Models made in Japan.; OEM Part No. 4260733011	28365	35, 4	Tundra	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	Models made in Japan.; OEM Part No. 4260733021	28370	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Sensor	Models made in USA.; W/15" Wheels	28365	35, 4	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Sensor	Models made in USA.; W/16" Or 17" Wheels	28360	35, 4	Sensor		W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35, 4	
Service Pack	-	20032	35, 4	Service Pack		-	20022	35, 4	
FJ Cruiser, Highlander, Land Cruiser	EZ-Sensor	-	33000*	11.5, 1.3	Venza	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28365	35, 4		Sensor	-	28360	35, 4
	Service Pack	-	20032	35, 4		Service Pack	-	20032	35, 4
Matrix	EZ-Sensor	-	33000*	11.5, 1.3	Yaris	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Sensor	-	28365	35, 4		Sensor	-	28365	35, 4
	Service Pack	-	20032	35, 4		Service Pack	-	20032	35, 4

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
2009					2009 - Continued						
Toyota - Continued	4 Runner	EZ-Sensor	-	33000*	11.5, 1.3	Prius - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		Sensor	-	28365	35, 4	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20032	35, 4	
		Avalon	Sensor	W/Valve Cap	28365	35, 4	RAV4	EZ-Sensor	-	33000*	11.5, 1.3
			Sensor	W/O Valve Cap	28370	35, 4		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
			Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Camry		EZ-Sensor	-	33000*	11.5, 1.3	Sensor	-	28370	35, 4	
			EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Service Pack	-	20032	35, 4	
			EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sequoia, Sienna	EZ-Sensor	-	33000*	11.5, 1.3
		Sensor	Models made in Japan.; OEM Part No. 4260733011	28365	35, 4	EZ-Sensor Service Pack		Alnm. Valve	34000	62, 7	
		Sensor	Models made in USA.; OEM Part No. 4260706011	28360	35, 4	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
		Corolla	Service Pack	-	20032	35, 4	Sensor	-	28670	35, 4	
	4 Runner		EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20022	35, 4	
			EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Tacoma	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Alnm. Valve	34000	62, 7	
	Sensor		Models made in Japan.; OEM Part No. 4260733011	28365	35, 4	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
	FJ Cruiser, Highlander, Land Cruiser		Sensor	Models made in USA.; OEM Part No. 4260733021	28370	35, 4	Sensor	W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35, 4	
			Sensor	Models made in USA.; W/15" Wheels	28365	35, 4	Sensor	W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35, 4	
			Sensor	Models made in USA.; W/16" Or 17" Wheels	28360	35, 4	Service Pack	-	20032	35, 4	
			Service Pack	-	20032	35, 4	Tundra	EZ-Sensor	-	33000*	11.5, 1.3
			Matrix	EZ-Sensor	-	33000*		11.5, 1.3	EZ-Sensor Service Pack	Alnm. Valve	34000
		EZ-Sensor Service Pack		Alnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
		Prius	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor	W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35, 4	
			Sensor	-	28365	35, 4	Service Pack	-	20022	35, 4	
	Service Pack		-	20032	35, 4	Venza	EZ-Sensor	-	33000*	11.5, 1.3	
	4 Runner		EZ-Sensor	-	33000*		11.5, 1.3	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
			EZ-Sensor Service Pack	Alnm. Valve	34000		62, 7	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	4 Runner		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor	-	28360	35, 4	
			Sensor	Models made in Japan.; OEM Part No. 4260733011	28365	35, 4	Service Pack	-	20032	35, 4	
	4 Runner		Sensor	Models made in USA.; OEM Part No. 4260706011	28360	35, 4	Yaris	EZ-Sensor	-	33000*	11.5, 1.3
Service Pack			-	20032	35, 4	EZ-Sensor Service Pack		Alnm. Valve	34000	62, 7	
4 Runner	EZ-Sensor		-	33000*	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Sensor	-		28365	35, 4		
4 Runner	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	-	20032	35, 4			
	Sensor	W/Valve Cap; OEM Part No. 4260733011	28365	35, 4	2008						

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2008 - Continued					2008 - Continued				
4 Runner - Cont'd.	Sensor	W/O Valve Cap; OEM Part No. 4260733021	28370	35, 4	Solara	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Avalon	EZ-Sensor	-	33000*	11.5, 1.3	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Sensor	-	28360	35, 4	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	-	20032	35, 4	
	Sensor	-	28360	35, 4	Tacoma	EZ-Sensor	-	33000*	11.5, 1.3
Service Pack	-	20032	35, 4	EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7	
Camry, Corolla	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35, 4
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor	W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35, 4		
	Sensor	Models made in Japan.; OEM Part No. 4260733011	28365	35, 4	Service Pack	-	20032	35, 4	
	Sensor	Models made in USA.; OEM Part No. 4260706011	28360	35, 4	Tundra	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
FJ Cruiser, Highlander, Land Cruiser	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35, 4
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	-	20022	35, 4		
	Sensor	-	28365	35, 4	Yaris	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
	Matrix	EZ-Sensor	-	33000*		11.5, 1.3	EZ-Sensor Service Pack	Rubber Valve	20008
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7		Sensor	-	28365	35, 4
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	-	20032	35, 4		
	Sensor	Models made in Japan.; OEM Part No. 4260733011	28365	35, 4	2007				
	Sensor	Models made in USA.; OEM Part No. 4260706011	28360	35, 4	4 Runner	EZ-Sensor	-	33000*	11.5, 1.3
	Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
Prius	EZ-Sensor	-	33000*	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	W/Valve Cap	28365	35, 4
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor	W/O Valve Cap	28370	35, 4		
	Sensor	-	28365	35, 4	Service Pack	-	20032	35, 4	
	Service Pack	-	20032	35, 4	Avalon	EZ-Sensor	-	33000*	11.5, 1.3
	RAV4	EZ-Sensor	-	33000*		11.5, 1.3	EZ-Sensor Service Pack	Almnm. Valve	34000
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor		-	28360	35, 4	
	Sensor	-	28370	35, 4	Service Pack	-	20032	35, 4	
	Service Pack	-	20032	35, 4	Camry	EZ-Sensor	-	33000*	11.5, 1.3
	Sequoia, Sienna	EZ-Sensor	-	33000*		11.5, 1.3	EZ-Sensor Service Pack	Almnm. Valve	34000
EZ-Sensor Service Pack		Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Sensor		Models made in Japan.; OEM Part No. 4260733011	28365	35, 4	
	Sensor	-	28670	35, 4	Sensor	Models made in USA.; OEM Part No. 4260706011	28360	35, 4	
Service Pack	-	20022	35, 4	Service Pack	-	20032	35, 4		

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.
2007 - Continued					2007 - Continued				
Corolla	EZ-Sensor	-	33000*	11.5, 1.3	Sequoia - Cont'd.	Sensor	W/Steel Wheels; W/20 Deg. Angled Valve Sensor	28305	35, 4
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		Sensor	W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28300	35, 4
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Service Pack	-	20031	35, 4
	Sensor	Models made in Japan.; OEM Part No. 4260733011; Jun. & Newer	28365	35, 4	Sienna	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	Models made in USA.; OEM Part No. 4260706011; Jun. & Newer	28360	35, 4		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Service Pack	Jun. & Newer	20032	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
				Sensor		-	28670	35, 4	
High-lander	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20022	35, 4	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Solara	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Sensor	May & Newer	28365	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	May & Newer	20032	35, 4		Sensor	-	28360	35, 4
Land Cruiser	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20032	35, 4	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Tacoma	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Sensor	-	28365	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	-	20032	35, 4		Sensor	W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35, 4
Matrix	EZ-Sensor	-	33000*	11.5, 1.3	Sensor	W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35, 4	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Service Pack	-	20032	35, 4	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Tundra	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	Models made in Japan.; OEM Part No. 4260733011; Jun. & Newer	28365	35, 4		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Sensor	Models made in USA.; OEM Part No. 4260706011; Jun. & Newer	28360	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	Jun. & Newer	20032	35, 4	Sensor	W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35, 4	
Prius	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20022	35, 4	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	Yaris	EZ-Sensor	-	33000*	11.5, 1.3
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Sensor	-	28365	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
	Service Pack	-	20032	35, 4		Sensor	Aug. & Newer	28365	35, 4
RAV4	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	Aug. & Newer	20032	35, 4	
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7	2006				
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	4 Runner	EZ-Sensor	-	33000*	11.5, 1.3
	Sensor	-	28370	35, 4		EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7
	Service Pack	-	20032	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3
Sequoia	EZ-Sensor	-	33000*	11.5, 1.3		Sensor	OEM Part No. 4260733011	28365	35, 4
	EZ-Sensor Service Pack	Alnm. Valve	34000	62, 7		Sensor	OEM Part No. 4260733021	28370	35, 4
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	OEM Part No. 4260730030	28335	35, 4
	Sensor	W/Alloy Wheels	28305	35, 4		Sensor	OEM Part No. 4260735010	28345	35, 4

* Programming Tool Required

■ ALPHABETICAL LISTING

SCHRADER 2011 TPMS APPLICATION GUIDE

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2006 - Continued					2006 - Continued					
Avalon	EZ-Sensor	-	33000*	11.5, 1.3	Tundra - Cont'd.	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		Sensor	W/20 Deg. Angled Valve Sensor; Nov. 1 & Newer	28670	35, 4	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		Sensor	W/20 Deg. Angled Valve Sensor; Oct. 31 & Older	28305	35, 4	
	Sensor	Aug. & Newer	28360	35, 4		Sensor	W/40 Deg. Angled Valve Sensor; Oct. 31 & Older	28300	35, 4	
	Service Pack	Aug. & Newer	20032	35, 4		Service Pack	Nov. 1 & Newer	20022	35, 4	
Service Pack	Oct. 31 & Older	20031	35, 4	Service Pack		Oct. 31 & Older	20031	35, 4		
Land Cruiser	EZ-Sensor	-	33000*	11.5, 1.3	2005					
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	4 Runner	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	-	28365	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	Apr. 1 & Newer	20032	35, 4		Sensor	-	28345	35, 4	
Service Pack	Mar. & Older	20031	35, 4	Service Pack	-	20031	35, 4			
Prius, RAV4	EZ-Sensor	-	33000*	11.5, 1.3	Land Cruiser	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	-	28365	35, 4		Sensor	May & Newer	28365	35, 4	
	Service Pack	-	20032	35, 4	Service Pack	May & Newer	20031	35, 4		
Sequoia	EZ-Sensor	-	33000*	11.5, 1.3	Sequoia	EZ-Sensor	-	33000*	11.5, 1.3	
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Sensor	W/Alloy Wheels	28305	35, 4		Sensor	W/Alloy Wheels	28305	35, 4	
	Sensor	W/Steel Wheels; W/20 Deg. Angled Valve Sensor	28305	35, 4	Sensor	W/Steel Wheels; W/20 Deg. Angled Valve Sensor	28305	35, 4		
	Sensor	W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28300	35, 4	Sensor	W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28300	35, 4		
	Service Pack	-	20031	35, 4	Service Pack	-	20031	35, 4		
	Solara	EZ-Sensor	-	33000*	11.5, 1.3	Tacoma	EZ-Sensor	-	33000*	11.5, 1.3
		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7
EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	EZ-Sensor Service Pack		Rubber Valve	20008	11.5, 1.3	
Sensor		May & Newer	28360	35, 4	Sensor		W/20 Deg. Angled Valve Sensor; Dec. 1 & Newer	28355	35, 4	
Service Pack		May & Newer	20032	35, 4	Sensor		W/20 Deg. Angled Valve Sensor; Nov. 30 & Older	28305	35, 4	
Tacoma	EZ-Sensor	-	33000*	11.5, 1.3	Sensor	W/40 Deg. Angled Valve Sensor; Dec. 1 & Newer	28380	35, 4		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	Sensor	W/40 Deg. Angled Valve Sensor; Nov. 30 & Older	28300	35, 4		
	EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	Service Pack	-	20031	35, 4		
	Sensor	W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Aug. & Newer	28360	35, 4	Tundra	EZ-Sensor	-	33000*	11.5, 1.3	
	Sensor	W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Jul. & Older	28355	35, 4		EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7	
	Sensor	W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35, 4		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	
	Service Pack	Aug. & Newer	20032	35, 4		Sensor	W/20 Deg. Angled Valve Sensor	28305	35, 4	
Service Pack	Jul. & Older	20031	35, 4	Sensor	W/40 Deg. Angled Valve Sensor	28300	35, 4			
Tundra	EZ-Sensor	-	33000*	11.5, 1.3	Service Pack	-	20031	35, 4		
	EZ-Sensor Service Pack	Almnm. Valve	34000	62, 7						

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

■ ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.		
2004 - 2003					2009 - Continued						
Toyota - Continued	4 Runner	EZ-Sensor	-	33000*	11.5, 1.3	Touareg 2 - Cont'd.	Service Pack	W/49mm Black Insert	20039	35, 4	
		EZ-Sensor Service Pack	Almm. Valve	34000	62, 7		Service Pack	W/51mm Orange Insert	20040	35, 4	
		EZ-Sensor Service Pack	Rubber Valve	20008	11.5, 1.3	2008					
		Sensor	-	28345	35, 4	Beetle, Eos	Sensor	-	20088	71, 8	
		Service Pack	-	20031	35, 4		Service Pack	-	20017	71, 8	
2011					GLI	Service Pack	-	20017	71, 8		
CC, Eos, Tiguan	Sensor	-	20088	71, 8	Golf, GTI, Jetta	Sensor	-	20088	71, 8		
	Service Pack	-	20017	71, 8		Service Pack	-	20017	71, 8		
Touareg 2	Sensor	W/315 MHz Sensor; Includes Transmitter Only	20077	35, 4	Passat	Sensor	W/16" Or 17" Wheels	20088	71, 8		
	Sensor	W/433 MHz Sensor; Includes Transmitter Only	20103	35, 4		Service Pack	W/16" Or 17" Wheels	20017	71, 8		
	Service Pack	Does Not Include Valve	20023	35, 4	R32, Rabbit	Sensor	-	20088	71, 8		
	Service Pack	Does Not Include Valve; W/315 MHz Sensor	20023	35, 4		Service Pack	-	20017	71, 8		
	Service Pack	W/43mm Silver Insert	20037	35, 4	Touareg 2	Sensor	Includes Transmitter Only	20078	35, 4		
	Service Pack	W/43mm Silver Insert; W/315 MHz Sensor	20037	35, 4		Service Pack	Does Not Include Valve	20023	35, 4		
	Service Pack	W/48mm Green Insert; W/315 MHz Sensor	20038	35, 4		Service Pack	W/43mm Silver Insert	20037	35, 4		
	Service Pack	W/48mm Green Insert	20038	35, 4		Service Pack	W/48mm Green Insert	20038	35, 4		
	Service Pack	W/49mm Black Insert	20039	35, 4		Service Pack	W/49mm Black Insert	20039	35, 4		
	Service Pack	W/49mm Black Insert; W/315 MHz Sensor	20039	35, 4		Service Pack	W/49mm Black Insert	20039	35, 4		
	Service Pack	W/51mm Orange Insert	20040	35, 4	Service Pack	W/51mm Orange Insert	20040	35, 4			
	Service Pack	W/51mm Orange Insert; W/315 MHz Sensor	20040	35, 4	2007						
	2010					Volkswagen - Continued	Eos	Sensor	-	20088	71, 8
	Beetle, CC, Eos, Golf, GTI, Jetta, Passat, Tiguan	Sensor	-	20088	71, 8			Service Pack	-	20017	71, 8
Service Pack		-	20017	71, 8	GTI		Sensor	W/16" Or 17" Wheels	20088	71, 8	
Touareg 2	Sensor	Includes Transmitter Only	20103	35, 4			Service Pack	W/16" Or 17" Wheels	20017	71, 8	
	Service Pack	Does Not Include Valve	20023	35, 4	Jetta		Sensor	-	20088	71, 8	
	Service Pack	W/43mm Silver Insert	20037	35, 4			Service Pack	-	20017	71, 8	
	Service Pack	W/48mm Green Insert	20038	35, 4	Passat		Sensor	W/16" Or 17" Wheels	20088	71, 8	
	Service Pack	W/49mm Black Insert	20039	35, 4			Service Pack	W/16" Or 17" Wheels	20017	71, 8	
	Service Pack	W/51mm Orange Insert	20040	35, 4	Rabbit		Sensor	W/15" Wheels	20088	71, 8	
Service Pack	W/51mm Orange Insert	20040	35, 4	Service Pack			W/15" Wheels	20017	71, 8		
2009					Touareg		Service Pack	Does Not Include Valve	20023	62, 7	
Beetle, CC, Eos	Sensor	-	20088	71, 8			Service Pack	W/43mm Silver Insert	20037	62, 7	
	Service Pack	-	20017	71, 8			Service Pack	W/48mm Green Insert	20038	62, 7	
GLI	Service Pack	-	20017	71, 8			Service Pack	W/49mm Black Insert	20039	62, 7	
Golf, GTI, Jetta, Passat, Rabbit, Tiguan	Sensor	-	20088	71, 8		Service Pack	W/51mm Orange Insert	20040	62, 7		
	Service Pack	-	20017	71, 8		2006					
Touareg 2	Sensor	Includes Transmitter Only	20078	35, 4	Golf	Service Pack	GTI	20017	71, 8		
	Service Pack	Does Not Include Valve	20023	35, 4	GTI	Sensor	W/16" Or 17" Wheels	20088	71, 8		
	Service Pack	W/43mm Silver Insert	20037	35, 4		Service Pack	W/16" Or 17" Wheels	20017	71, 8		
	Service Pack	W/48mm Green Insert	20038	35, 4	Jetta	Sensor	-	20088	71, 8		
Service Pack	W/49mm Black Insert	20039	35, 4	Service Pack		-	20017	71, 8			
Phaeton	Sensor	Includes Transmitter Only; W/315 MHz Sensor	20077	35, 4	Passat	Sensor	W/16" Or 17" Wheels	20088	71, 8		
	Sensor	Includes Transmitter Only; W/433 MHz Sensor	20078	35, 4		Service Pack	W/16" Or 17" Wheels	20017	71, 8		
	Service Pack	Does Not Include Valve; W/315 MHz Sensor	20023	35, 4	Phaeton	Sensor	Includes Transmitter Only; W/315 MHz Sensor	20077	35, 4		
	Service Pack	W/43mm Silver Insert; W/315 MHz Sensor	20037	35, 4		Sensor	Includes Transmitter Only; W/433 MHz Sensor	20078	35, 4		
Service Pack	W/48mm Green Insert; W/315 MHz Sensor	20038	35, 4	Service Pack	Does Not Include Valve; W/315 MHz Sensor	20023	35, 4				
Service Pack	W/48mm Green Insert; W/315 MHz Sensor	20038	35, 4	Service Pack	W/43mm Silver Insert; W/315 MHz Sensor	20037	35, 4				
Service Pack	W/48mm Green Insert; W/315 MHz Sensor	20038	35, 4	Service Pack	W/48mm Green Insert; W/315 MHz Sensor	20038	35, 4				

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

ALPHABETICAL LISTING

Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	Model	Application	Details	Part #	Torque In-lbs, Torque N.m.	
2006 - Continued					2009 - Continued					
Phaeton - Cont'd.	Service Pack	W/49mm Black Insert; W/315 MHz Sensor	20039	35, 4	XC90	Sensor	W/315 MHz Sensor	20156	44, 5	
	Service Pack	W/51mm Orange Insert; W/315 MHz Sensor	20040	35, 4		Service Pack	W/315 MHz Sensor	20010	44, 5	
2005 - 2004					2008					
Phaeton	Sensor	Includes Transmitter Only; W/315 MHz Sensor	20077	35, 4	C30, C70, S40	Sensor	-	20097	71, 8	
	Sensor	Includes Transmitter Only; W/433 MHz Sensor	20078	35, 4		Service Pack	-	20030	71, 8	
	Service Pack	Does Not Include Valve; W/315 MHz Sensor	20023	35, 4	S60	Sensor	-	20156	44, 5	
	Service Pack	W/43mm Silver Insert; W/315 MHz Sensor	20037	35, 4		Service Pack	-	20010	44, 5	
	Service Pack	W/48mm Green Insert; W/315 MHz Sensor	20038	35, 4	S80	Sensor	-	20097	71, 8	
	Service Pack	W/49mm Black Insert; W/315 MHz Sensor	20039	35, 4		Service Pack	-	20030	71, 8	
	Service Pack	W/51mm Orange Insert; W/315 MHz Sensor	20040	35, 4	S80, V50, V70, XC80, XC90	Sensor	-	20097	71, 8	
Service Pack	W/49mm Black Insert; W/315 MHz Sensor	20039	62, 7	Service Pack		-	20030	71, 8		
2011					2007					
C30, C70, S40, S60, S80, V50, V70, XC60, XC70, XC90	Sensor	-	20097	71, 8	C30	Sensor	-	20097	71, 8	
	Service Pack	-	20030	71, 8		Service Pack	-	20030	71, 8	
	S60	Sensor	-	20156	44, 5	S60	Sensor	-	20156	44, 5
		Service Pack	-	20010	44, 5		Service Pack	-	20010	44, 5
	S80	Sensor	-	20156	44, 5	S80	Sensor	-	20097	71, 8
		Service Pack	-	20010	44, 5		Service Pack	-	20030	71, 8
V70, XC70, XC90	Sensor	W/315 MHz Sensor	20156	44, 5	V70, XC70, XC90	Sensor	W/315 MHz Sensor	20156	44, 5	
	Service Pack	W/315 MHz Sensor	20010	44, 5		Service Pack	W/315 MHz Sensor	20010	44, 5	
2010					2006					
C30, C70, S40, S80, V50, V70, XC60, XC70, XC90	Sensor	-	20097	71, 8	S60, S80	Sensor	-	20156	44, 5	
	Service Pack	-	20030	71, 8		Service Pack	-	20010	44, 5	
S60	Sensor	-	20156	44, 5	V70, XC70, XC90	Sensor	W/315 MHz Sensor	20156	44, 5	
	Service Pack	-	20010	44, 5		Service Pack	W/315 MHz Sensor	20010	44, 5	
S80, V50, V70, XC70	Sensor	-	20097	71, 8	2005					
	Service Pack	-	20030	71, 8	S60	Sensor	W/315 MHz Sensor	20156	44, 5	
2009						Service Pack	W/315 MHz Sensor	20010	44, 5	
C30, C70, S40	Sensor	-	20097	71, 8	S80	Sensor	-	20156	44, 5	
	Service Pack	-	20030	71, 8		Service Pack	-	20010	44, 5	
S60	Sensor	-	20156	44, 5	V70, XC70	Sensor	W/315 MHz Sensor	20156	44, 5	
	Service Pack	-	20010	44, 5		Service Pack	W/315 MHz Sensor	20010	44, 5	
S80, V50, V70, XC70	Sensor	-	20097	71, 8	XC90	Sensor	-	20156	44, 5	
	Service Pack	-	20030	71, 8		Service Pack	-	20010	44, 5	
2008					2004					
S60	Sensor	-	20156	44, 5	S60	Sensor	W/315 MHz Sensor	20156	44, 5	
	Service Pack	-	20010	44, 5		Service Pack	W/315 MHz Sensor	20010	44, 5	
S80	Sensor	-	20156	44, 5	S80	Sensor	-	20156	44, 5	
	Service Pack	-	20010	44, 5		Service Pack	-	20010	44, 5	
V70, XC70	Sensor	W/315 MHz Sensor	20156	44, 5	V70, XC70	Sensor	W/315 MHz Sensor	20156	44, 5	
	Service Pack	W/315 MHz Sensor	20010	44, 5		Service Pack	W/315 MHz Sensor	20010	44, 5	
XC90	Sensor	-	20156	44, 5	XC90	Sensor	-	20156	44, 5	
	Service Pack	-	20010	44, 5		Service Pack	-	20010	44, 5	

Application guides subject to change without notice. Please refer to the manufacturer's websites for the most up-to-date application data.

* Programming Tool Required

SCHRADER 2011 TPMS APPLICATION GUIDE

MANUFACTURER'S PART NUMBERS

OEM Sensor #	Schrader Sensor #	OEM Sensor #	Schrader Sensor #	OEM Sensor #	Schrader Sensor #	OEM Sensor #	Schrader Sensor #
C2C25519	20090	YBD000061	28082	40700-CK001	20161	4815132AB	28004
C2C40476	20090	ZZC137140	28385	40700-CK002	20069	4D0907275	20077
C2C40725	20091	ZZDA37140	20315	40700-JA00C	28204	4D0907275C	20077
C2S40710	20091	0009054100	28214	40700-JA00B	28204	4D0907275D	20079
C2Z15016	20091	0025406817	20094	40700-JA01A	28167	4F0907275B	20078
C2Z15017	20090	0025406917	20095	40700-JA01B	28204	4F0907275D	20103
GN3A37140B	20093	0025407917	20094	40700-JA01C	28204	4F0907275H	20077
GS1D37140	20093	0025408017	20095	40700-JA02B	28204	4L2Z 1A150 BA	20096
LR010532	20091	25409017	28214	40700-JK00B	28210	5096808AA	20028
LR010533	20090	0025408617	28214	40700-JK00A	28210	5127335AB	20335
LR018860	20090	0045421518	28214	40700-JK00C	28210	5127335AD	20335
LR018861	20091	06421S3VA01	28214	4250A030	28129	5142340AA	20066 / 28308
LR021936	20090	06421S3VA02	28981	4250A225	28096	52088990AC	20028
LR0500461	20090	06421S3VA03	28981	4250B668	20398	529331F000	28983
MN103033	20028	06421S3VA04	28981	4250B875	28129	529331FA00	28983
MN103081	20034	06421S9VA01	28982	4250B877	20034	529332F000	28849
RQH500461	20090	06421S9VA03	28982	4260702010	28365	529332G000	20086
RQH500471	20091	10394110	20158	4260704010	28380	529332G200	20086
XR855949	20091	10438853	28006	4260706011	28360	529332M000	20092
XR855950	20090	12768826	28206	4260708010	28670	529333E200	28983
YBD000060	28082	13172567	28078	426070C010	28300	529333X200	20086
YBD000061	28082	13227143	20159	426070C020	28305	529333D000	20085
ZZC137140	28385	15114379	20107	426070C030	28670	529334D200	20085
ZZDA37140	20315	15122618	20131	426070C050	28670	56029319AA	28154 / 28461
0009054100	28214	15136883	20115	426070E011	28370	56029319AB	28154 / 28461
0025406817	20094	15254101	20153	4260724010	28310	56029359AA	28155 / 28434
0025406917	20095	15268606	20158	4260724020	28315	56029359AB	28155 / 28434
0025407917	20094	15825475	20158	4260724030	28320	56029398AA	20398
0025408017	20095	15921013	20158	4260724040	28325	56029398AB	20398
25409017	28214	15922396	20153	4260730030	28335	56029400AB	28291
0025408617	28214	168833266	20153	4260733010	28365	56029400AC	28291
0045421518	28214	1K0907253D	20088	4260733011	28365	56029400AD	28291
06421S3VA01	28214	19155710	20158	4260733021	28370	56029465AB	20066 / 28308
06421S3VA02	28981	20922900	28206	4260735010	28345	56029465AC	20066 / 28308
06421S3VA03	28981	224549	20077	4260752010	28365	56029479AA	20066 / 28308
06421S3VA04	28981	224551	20084	4260775010	20101	56029479AB	28308
06421S9VA01	28982	24437708	28078	42607AD010	28380	56029481AB	28434
06421S9VA03	28982	25731358	20117	42607AD020	28355	56053030AB	20066 / 28308
10394110	20158	25758220	20076	42753SHJA53	28981	56053036AA	20066 / 28308
10438853	28006	25773946	20117	42753SNAA81	28720	56053036AA	20066 / 28308
12768826	28206	25774006	20116	42753SHJA82	28983	5L1Z 1A150 AA	20135
C2C25519	20090	25799331	20153	42753SNAA83	28720	68001696AA	20066 / 28308
C2C40476	20090	25858636	20153	42753STKA01	20098	68001696AB	20066 / 28308
C2C40725	20091	25920615	20153	42753STKA02	20098	68001698AA	28155 / 28434
C2S40710	20091	25952370	20153	42753STKA03	20098	68001698AB	28155 / 28434
C2Z15016	20091	28103AG00A	20081	42753STKA04	20098	68006771AA	20089
C2Z15017	20090	28103AG01A	28203	42753SVA306	20099	68038945AA	20089
GN3A37140B	20093	28103AG01B	28203	42753SVA316	20099	68078861AA	20066 / 28308
GS1D37140	20093	28103AG01C	28203	42753TKA01	20720	68137699AA	28461
LR010532	20091	28103SA001	28203	42753TL2A51	20098	6F2Z1A189A	28385
LR010533	20090	307489910	20156	42753TL2A52	20098	7L1Z1A189A	28390
LR018860	20090	312009230	20156	42753TP6A82	20100	7P0907275	20103
LR018861	20091	312802970	20097	4313054J20	20087	7P0907275A	20077
LR021936	20090	313020960	20097	4313054J21	20087	8257740060	20116
LR0500461	20090	36106790054	28081	4313078J00	20158	86517000	20156
MN103033	20028	36118378682	20080	4313078J10	20158	88974915	28360
MN103081	20034	36236779490	20083	4313085Z00	20153	8973271890	20028
RQH500461	20090	36146752128	28082	4313085Z01	20153	8C2Z1A189A	28395
RQH500471	20091	36236781847	20083	4313085Z03	20153	95536105300	20077
XR855949	20091	40700-1AA0B	28204	4313085Z04	20153	95836166100	20103
XR855950	20090	407001AA0C	28204	4313086Z20	20082	99760602120	28087
YBD000060	28082	40700-CD001	20064	4321182Z10	28204	9L3Z1A189A	20315
				4815132	28004	FE0137140A	20093

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Sensors/Transmitters

Part #	Model; Year; OEM Part #
20028 (433 MHz)	Chrysler
	300M; 2004-2002
	Concorde; 2004-2002
	Crossfire; 2008-2006
	Crossfire; 2005; OEM Part No. 52088990AC
	Crossfire; 2004
	Intrepid; 2004-2002
	Pacifica; 2004; OEM Part No. 52088990AC
	Prowler; 2002
	Town & Country Van; 2003-2002
	Voyager; 2003-2002
	Dodge
	Caravan; 2003-2002
	Grand Caravan; 2003-2002
	Intrepid; 2004-2002
	Viper; 2010-2008
	Viper; 2006-2003
Isuzu	
Rodeo; 2004	
Jeep	
Grand Cherokee; 2004-2002	
Liberty; 2004	
Mitsubishi	
Endeavor; 2006; Aug. & Older	
Endeavor; 2005-2004	
Galant; 2006-2004	
20034 (315 MHz)	Mitsubishi
	Eclipse; 2011-2008
	Eclipse; 2007-2006; W/Alloy Wheels
	Endeavor; 2011-2010
	Endeavor; 2008-2007
	Endeavor; 2006; Sept. 1 & Newer
	Galant; 2011-2007; W/Alloy Wheels
	Montero; 2006-2003
	Infiniti
	FX35; 2007; Jun. & Older
FX35; 2006-2003	
FX45; 2007; Jun. & Older	
FX45; 2006-2003	
G35; 2006-2004	
G35; 2003; Jun. & Newer	
M35; 2007-2006	
M45; 2007-2006	
M45; 2004-2003	
Q45; 2006; Jul. & Older	
Q45; 2005-2003	
QX4; 2003	
Nissan	
350Z; 2006-2003	
Frontier; 2004-2003	

Part #	Model; Year; OEM Part #
20064 (315 MHz) - Continued	Nissan - Continued
	Murano; 2006-2003
	Pathfinder; 2004; Exc. Armada; Jul. & Older
	Pathfinder; 2003
	Xterra; 2004-2003
	Chrysler
	200; 2011
	300; 2007-2005
	Aspen; 2009-2007
	Crossfire; 2005; OEM Part No. 5142340AA
Pacifica; 2008-2006	
PT Cruiser; 2010-2008	
Sebring; 2010-2007	
Town & Country Van; 2007-2006	
Dodge	
Avenger; 2010-2008	
Caliber; 2011-2007	
Caravan; 2007-2006	
Charger; 2007-2006	
Dakota; 2011	
Durango; 2009-2007	
Grand Caravan; 2007-2006	
Journey; 2011	
Magnum; 2007-2005	
Nitro; 2011-2007	
Jeep	
Commander; 2007-2006	
Compass; 2011-2007	
Grand Cherokee; 2007-2005	
Liberty; 2011-2010	
Liberty; 2009; Sport	
Liberty; 2008-2005	
Patriot; 2011-2007	
Wrangler; 2011	
Wrangler; 2008-2007	
Suzuki	
Kizashi; 2011-2010	
Infiniti	
QX56; 2006-2005; W/Steel Wheels	
QX56; 2004	
Nissan	
Armada; 2006-2005; W/Steel Wheels	
Frontier; 2007-2005; W/Steel Wheels	
Pathfinder; 2004; Armada	
Pathfinder; 2004; Exc. Armada; Aug. & Newer	
Quest; 2006-2005; W/Steel Wheels	
Quest; 2004	
Titan; 2005; Mar. & Older	
Titan; 2004	
Xterra; 2006; Submodel X	

Part #	Model; Year; OEM Part #
20076 (315 MHz)	Cadillac
	STS; 2008-2005; OEM Part No. 25758220
	XLR; 2009-2004; OEM Part No. 25758220
	Chevrolet
	Corvette; 2009-2005; OEM Part No. 25758220
	Audi
	A6; 2011
	A8; 2010-2004
	A8; 2003; Chassis No. 4E3000001 & After
	Q7; 2011
S6; 2011	
S8; 2009-2007	
S8; 2003; Chassis No. 4E3000001 & After	
Bentley	
Continental; 2005-2003	
Ferrari	
550 Maranello; 2002-2001	
575M Maranello; 2005-2002	
612 Scaglietti; 2009-2004	
F430; 2009-2005	
Porsche	
911; 2011	
Boxster; 2011	
Cayman; 2011	
Volkswagen	
Phaeton; 2006-2004; W/315 MHz Sensor	
Touareg 2; 2011; W/315 MHz Sensor	
Audi	
A4; 2008-2002	
A6; 2009; Exc. Quattro	
A6; 2008-2005	
Q7; 2009-2007	
R8; 2009-2008	
RS4; 2008-2007	
S4; 2009-2004	
S6; 2009-2007	
Bentley	
Bentley; Continental; 2010-2006	
Volkswagen	
Phaeton; 2006-2004; W/433 MHz Sensor	
Touareg 2; 2009-2008	
Audi	
A8; 2003; Chassis No. 4D3004999 & Before	
A8; 2002-2001	
Allroad Quattro; 2005-2001	
S8; 2003; Chassis No. 4D3004999 & Before	
S8; 2002-2001	
20078 (433 MHz)	Audi
	A4; 2008-2002
	A6; 2009; Exc. Quattro
	A6; 2008-2005
	Q7; 2009-2007
	R8; 2009-2008
	RS4; 2008-2007
	S4; 2009-2004
	S6; 2009-2007
	Bentley
Bentley; Continental; 2010-2006	
Volkswagen	
Phaeton; 2006-2004; W/433 MHz Sensor	
Touareg 2; 2009-2008	
Audi	
A8; 2003; Chassis No. 4D3004999 & Before	
A8; 2002-2001	
Allroad Quattro; 2005-2001	
S8; 2003; Chassis No. 4D3004999 & Before	
S8; 2002-2001	
20079 (315 MHz)	Audi
	A4; 2008-2002
	A6; 2009; Exc. Quattro
	A6; 2008-2005
	Q7; 2009-2007
	R8; 2009-2008
	RS4; 2008-2007
	S4; 2009-2004
	S6; 2009-2007
	Bentley
Bentley; Continental; 2010-2006	
Volkswagen	
Phaeton; 2006-2004; W/433 MHz Sensor	
Touareg 2; 2009-2008	
Audi	
A8; 2003; Chassis No. 4D3004999 & Before	
A8; 2002-2001	
Allroad Quattro; 2005-2001	
S8; 2003; Chassis No. 4D3004999 & Before	
S8; 2002-2001	

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Sensors/Transmitters

Part #	Model; Year; OEM Part #
20080 (433 MHz)	BMW
	320I; 2005-2003
	320I; 2002; W/433 MHz Sensor
	325CI; 2006-2003
	325CI; 2002; W/433 MHz Sensor
	325I; 2006-2003
	325I; 2002; W/433 MHz Sensor
	325XI; 2006-2003
	325XI; 2002; W/433 MHz Sensor
	330CI; 2006-2003
	330CI; 2002; W/433 MHz Sensor
	330I; 2006-2003
	330I; 2002; W/433 MHz Sensor
	330XI; 2006-2003
	330XI; 2002; W/433 MHz Sensor
	525I; 2005-2003
	525I; 2002; W/433 MHz Sensor
	530I; 2005-2003
	530I; 2002; W/433 MHz Sensor
	540I; 2003
	540I; 2002; W/433 MHz Sensor
	545I; 2005-2004
	645CI; 2005-2004
	745I; 2005-2003
	745I; 2002; W/433 MHz Sensor
	745LI; 2005-2003
745LI; 2002; W/433 MHz Sensor	
760I; 2005-2004	
760LI; 2003	
Alpina B7; 2011	
M3; 2003	
M3; 2002; W/433 MHz Sensor	
M5; 2003-2000; W/433 MHz Sensor	
Z8; 2003; W/433 MHz Sensor	
20081 (315 MHz)	Subaru
	B9 Tribeca; 2007-2006
	Legacy; 2008; W/16" Or 17" Wheels
	Legacy; 2007-2004
	Outback; 2006-2004
Tribeca; 2008; W/Metal Stem Clamp-in Sensor	
20082 (315 MHz)	Suzuki
Verona; 2006-2005	
20083 (315 MHz)	BMW
	128I; 2011-2008
	135I; 2010-2008
	323I; 2010-2007
	323I; 2006; Jun. & Newer
	328I; 2009-2007
	328XI; 2008-2007
	335D; 2009
	335I; 2009-2007
	335XI; 2008-2007

Part #	Model; Year; OEM Part #
20083 (315 MHz) - Continued	BMW - Continued
	525I; 2007-2006
	525XI; 2007-2006
	528I; 2011-2008
	528XI; 2008
	530I; 2007-2006
	530XI; 2007-2006
	535I; 2011-2008
	535XI; 2008
	550I; 2011-2006
	650I; 2010-2006
	740I; 2011
	740LI; 2011
	750I; 2011-2006
	750LI; 2011-2006
	760I; 2006
	760LI; 2011-2010
	760LI; 2008-2004
	Alpina B7; 2008-2007
	M3; 2009-2008
	M3; 2006-2004
	M5; 2010-2006
	M6; 2010-2006
	X3; 2011-2006
	X5; 2011-2005
	X6; 2011-2008
Z4; 2011-2003	
Mini	
Cooper; 2009-2008	
20084 (433 MHz)	Ferrari
Enzo; 2004-2003	
20085 (315 MHz)	Hyundai
	Entourage; 2009-2007
	Santa Fe; 2008-2007
	Veracruz; 2008-2007
Kia	
Sedona; 2008-2006	
20086 (315 MHz)	Hyundai
	Azera; 2011-2006
	Elantra; 2011-2008
	Santa Fe; 2010-2009
Veracruz; 2011-2009	
Kia	
Magentis; 2010-2008	
Optima; 2010-2006	
Rondo; 2010-2007	
Sedona; 2011-2009	
20087 (315 MHz)	Suzuki
	Grand Vitara; 2011-2007
	SX4; 2011-2007
XL-7; 2006-2005	

Part #	Model; Year; OEM Part #	
20088 (315 MHz)	Audi	
	A3; 2011-2008	
	A4; 2011-2009	
	A5; 2011-2008	
	Q5; 2011-2009	
	S4; 2011-2010	
	S5; 2011-2008	
	TT; 2011-2008	
	Beetle; 2010-2008	
	CC; 2011-2009	
	Eos; 2011-2007	
	Golf; 2010-2008	
	GTI; 2010-2008	
	GTI; 2007-2006; W/16" Or 17" Wheels	
	Jetta; 2010-2006	
	Passat; 2010-2009	
	Passat; 2008-2006; W/16" Or 17" Wheels	
	R32; 2008	
	Rabbit; 2009-2008	
	Rabbit; 2007-2006; W/15" Wheels	
	Tiguan; 2011-2009	
	20089 (315 MHz)	Dodge
	Sprinter; 2009-2007	
	20090 (315 MHz)	Jaguar
		S-Type; 2008; W/315 MHz Sensor
		Super V8; 2009-2005; W/315 MHz Sensor
Vanden Plas; 2009-2004; W/315 MHz Sensor		
X-Type; 2008; W/315 MHz Sensor		
XF; 2011-2009; W/315 MHz Sensor		
XFR; 2011-2010; W/315 MHz Sensor		
XJ; 2011-2010; W/315 MHz Sensor		
XJ8; 2009-2004; W/315 MHz Sensor		
XJR; 2009-2004; W/315 MHz Sensor		
XK; 2011-2007; W/315 MHz Sensor		
XKR; 2011-2007; W/315 MHz Sensor		
Land Rover		
	LR2; 2011-2009	
	LR3; 2009-2006; W/315 MHz Sensor	
	LR4; 2011-2010; W/315 MHz Sensor	
Range Rover; 2011-2006; W/315 MHz Sensor		
20091 (315 MHz)	Jaguar	
	S-Type; 2008; W/433 MHz Sensor	
	Super V8; 2009-2005; W/433 MHz Sensor	
	Vanden Plas; 2009-2004; W/433 MHz Sensor	
	X-Type; 2008; W/433 MHz Sensor	
	XF; 2011-2009; W/433 MHz Sensor	
	XFR; 2011-2010; W/433 MHz Sensor	
	XJ; 2011-2010; W/433 MHz Sensor	
	XJ8; 2009-2004; W/433 MHz Sensor	
	XJR; 2009-2004; W/433 MHz Sensor	
XK; 2011-2007; W/433 MHz Sensor		
XKR; 2011-2007; W/433 MHz Sensor		

NUMERICAL LISTING: Sensors/Transmitters

SCHRADER 2011 TPMS APPLICATION GUIDE

Part #	Model; Year; OEM Part #
20091 (315 MHz) - Cont'd.	Land Rover
	LR3; 2009-2006; W/433 MHz Sensor
	LR4; 2011-2010; W/433 MHz Sensor
20092 (315 MHz)	Range Rover; 2011-2006; W/433 MHz Sensor
	Hyundai
	Genesis; 2011; Coupe
	Sonata; 2011
	Kia
20093 (315 MHz)	Forté; 2010
	Sorento; 2011
	Soul; 2011-2010
	Mazda
	2; 2011
	3; 2011-2004
	5; 2010-2006
	6; 2011-2008
	CX-7; 2011-2007
	CX-9; 2011-2007
MX-5 Miata; 2011-2006	
RX-8; 2011-2004	
Tribute; 2011	
20094 (433 MHz)	Mercedes-Benz
	CL63; 2009-2007
	CL65; 2009-2008
	CL550; 2009-2007
	CL600; 2009-2007
	CLS55; 2006
	CLS63; 2011-2007
	CLS500; 2006
	CLS550; 2011-2007
	E55; 2006
	E63; 2009-2007
	E320; 2009-2006
	E350; 2009-2006; W/315 MHz Sensor
	E500; 2006
	E550; 2009-2007; W/315 MHz Sensor
	S63; 2010-2007
	S65; 2010-2007
	S400; 2010
	S550; 2010-2007
	S600; 2010-2007
SL55; 2008-2006	
SL63; 2011	
SL63; 2009	
SL65; 2011	
SL65; 2009-2006	
SL500; 2006	
SL550; 2009-2007	
SL600; 2009-2006	
SLR McLaren; 2009-2008	
20095 (433 MHz)	Mercedes-Benz
	E350; 2009-2006; W/433 MHz Sensor
	E550; 2009-2007; W/433 MHz Sensor
	GL320; 2009-2007

Part #	Model; Year; OEM Part #	
20095 (433 MHz) - Continued	Mercedes-Benz - Continued	
	GL450; 2009-2007	
	GL550; 2009-2008	
	ML63; 2009-2007	
	ML320; 2009-2007	
	ML350; 2009-2006	
	ML500; 2007-2006	
	ML550; 2009-2008	
	R63; 2007	
	R320; 2009-2007	
	R350; 2009-2006	
	R500; 2007-2006	
	20096 (433 MHz)	Ford
Expedition; 2004-2003		
Explorer; 2005-2004		
Explorer; 2003-2002; Exc. Sport		
Lincoln		
20096 (433 MHz)	Aviator; 2005-2003	
	Navigator; 2004-2003	
20096 (433 MHz)	Mercury	
	Mountaineer; 2005-2002	
20097 (433 MHz)	Volvo	
	C30; 2011-2007	
	C70; 2011-2008	
	S40; 2011-2008	
	S60; 2011	
	S80; 2011-2007	
	V50; 2011-2008	
	V70; 2010-2008	
	XC60; 2011-2010	
	XC70; 2011-2008	
	XC90; 2011-2010	
	XC90; 2008	
	20098 (315 MHz)	Acura
		MDX; 2011-2007
RDX; 2010-2007		
TSX; 2011-2007		
20098 (315 MHz)	Honda	
	Pilot; 2011-2010; Exc. LX	
	Pilot; 2009; W/Alloy Wheels	
20099 (315 MHz)	Honda	
	Accord; 2011-2010; Exc. Crosstour	
	Accord; 2009-2008	
	CR-V; 2011-2010	
	CR-V; 2009-2007; W/Alloy Wheels	
	Fit; 2008	
20100 (315 MHz)	Honda	
	Accord; 2011-2010; Crosstour	
20103 (433 MHz)	Audi	
	A6; 2010	
	A6; 2009; Quattro	
	Q7; 2010	

Part #	Model; Year; OEM Part #
20103 (433 MHz) - Continued	Audi - Continued
	R8; 2011
	R8; 2010
	S6; 2010
20103 (433 MHz) - Continued	Porsche
	Cayenne; 2011
20103 (433 MHz) - Continued	Volkswagen
	Touareg 2; 2011; W/433 MHz Sensor
	Touareg 2; 2010
20107 (315 MHz)	Cadillac
	Escalade; 2006-2005
	Chevrolet
	Avalanche; 2006-2005
	Silverado Series Pickup; 2007; Classic
20107 (315 MHz)	Silverado Series Pickup; 2006-2005
	Suburban; 2006-2005
	Tahoe; 2006-2005
	GMC
	Sierra Series Pickup; 2007; Classic
20107 (315 MHz)	Sierra Series Pickup; 2006-2005
	Yukon; 2006-2005
	Cadillac
	Escalade; 2004
	Chevrolet
20115 (315 MHz)	Avalanche; 2004
	Silverado Series Pickup; 2004
	Suburban; 2004
	Tahoe; 2004
	GMC
20115 (315 MHz)	Sierra Series Pickup; 2004
	Yukon; 2004
	Buick
	Rainier; 2007-2006; OEM Part No. 25774006
	Cadillac
20116 (315 MHz)	CTS; 2007-2006; OEM Part No. 25774006
	CTS; 2005-2004
	SRX; 2006; OEM Part No. 25774006
	SRX; 2005-2004
	Chevrolet
20116 (315 MHz)	SSR; 2006; OEM Part No. 25774006
	Trailblazer; 2009-2006; OEM Part No. 25774006
	GMC
	Envoy; 2009-2006; OEM Part No. 25774006
	Isuzu
20116 (315 MHz)	Ascender; 2008-2006
	Saab
	9-7X; 2009-2005
20117 (315 MHz)	Cadillac
	Deville; 2005-2001
	Seville; 2004-2001
	Chevrolet
20117 (315 MHz)	Corvette; 2004-2001

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Sensors/Transmitters

Part #	Model; Year; OEM Part #
20131 (315 MHz)	Chevrolet
	Colorado; 2011-2007
	GMC
	Canyon; 2011-2007
	Hummer
	H3; 2010-2006
	H3T; 2010-2009
	Isuzu
I-290; 2008-2007	
I-370; 2008-2007	
20135 (315 MHz)	Ford
	Expedition; 2006-2005
	Freestar; 2005-2004; W/Almm. Valve Stem
	Lincoln
	Navigator; 2006-2005
	Mercury
Monterey Van; 2005-2004	
20153 (315 MHz)	Buick
	Allure; 2009
	Enclave; 2011-2009
	LaCrosse; 2009
	Lucerne; 2011-2007
	Cadillac
	CTS; 2011-2009; OEM Part No. 25920615; Exc. CTS V
	CTS; 2008
	DTS; 2011-2007
	Escalade; 2011-2008
	Escalade; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
	SRX; 2009-2007
	STS; 2011-2010
	STS; 2009; OEM Part No. 25920615; Exc. STS V
	Chevrolet
	Avalanche; 2011-2008
Avalanche; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	
Aveo; 2011-2008	
Aveo; 2007; Hatchback	
Cobalt; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem	
Express; 2011-2010	
HHR; 2011	
HHR; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem	
Impala; 2011-2008	
Impala; 2007; Snap-In Style Only; W/Rubber Valve Stem	
Malibu; 2011	
Malibu; 2009	
Malibu; 2008; Snap-In Style Only; W/Rubber Valve Stem	
Monte Carlo; 2007; Snap-In Style Only; W/Rubber Valve Stem	
Silverado Series Pickup; 2011-2008; W/Single Rear Wheels	

Part #	Model; Year; OEM Part #
20153 (315 MHz) - Continued	Chevrolet - Continued
	Silverado Series Pickup; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic
	Suburban; 2011-2008
	Suburban; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
	Tahoe; 2011-2008
	Tahoe; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
	Traverse; 2011-2009
	GMC
	Acadia; 2011-2009
	Savana; 2011-2010
	Sierra Series Pickup; 2011-2008; W/Single Rear Wheels
	Sierra Series Pickup; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic
	Yukon; 2011-2008
	Yukon; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
	Hummer
	H2; 2010-2008
Pontiac	
G3; 2010-2009	
G3 Wave; 2009	
G5; 2010-2009	
G6; 2010-2009	
G8; 2010-2008	
Grand Prix; 2008; Snap-In Style Only; W/Rubber Valve Stem	
Wave; 2008	
Saturn	
Aura; 2010-2008	
Outlook; 2010-2009	
VUE; 2010-2008	
Suzuki	
Forenza; 2008-2007	
Reno; 2008-2007	
Volvo	
S60; 2009-2006	
S60; 2005-2004; W/315 MHz Sensor	
S80; 2006-2004	
V70; 2007-2004; W/315 MHz Sensor	
XC70; 2007-2004; W/315 MHz Sensor	
XC90; 2009; W/315 MHz Sensor	
XC90; 2007-2005; W/315 MHz Sensor	
XC90; 2004	
Buick	
Allure; 2008-2007	
Enclave; 2008	
LaCrosse; 2008-2007	
Cadillac	
CTS; 2011-2009; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	
DTS; 2006	

Part #	Model; Year; OEM Part #
20158 (315 MHz) - Continued	Cadillac - Continued
	Escalade; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem
	Chevrolet
	Avalanche; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem
	Caprice; 2011
	Cobalt; 2009-2008; Clamp-In Style Only; W/Almm. Valve Stem
	Corvette; 2011-2010
	Equinox; 2009-2007
	Express; 2009-2008
	HHR; 2009-2008; Clamp-In Style Only; W/Almm. Valve Stem
	Impala; 2007; Clamp-In Style Only; W/Almm. Valve Stem
	Impala; 2006; W/Alloy Wheels
	Malibu; 2008; Clamp-In Style Only; W/Almm. Valve Stem
	Monte Carlo; 2007; Clamp-In Style Only; W/Almm. Valve Stem
	Monte Carlo; 2006; W/Alloy Wheels
	Silverado Series Pickup; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic
Suburban; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	
Tahoe; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	
Uplander; 2009-2008	
GMC	
Acadia; 2008-2007	
Savana; 2009-2008	
Sierra Series Pickup; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic	
Yukon; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	
Pontiac	
G5; 2008	
G6; 2008	
Grand Prix; 2008; Clamp-In Style Only; W/Almm. Valve Stem	
Grand Prix; 2007	
Montana; 2009-2008	
Solstice; 2010-2008	
Torrent; 2009-2007	
Saturn	
Aura; 2007	
Outlook; 2008-2007	
Sky; 2010-2008	
Suzuki	
XL-7; 2009-2007	
Saab	
Saab; 9-3; 2011-2008	
Saab; 9-5; 2011-2008	

20159 (433 MHz)

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Sensors/Transmitters

Part #	Model; Year; OEM Part #	Part #	Model; Year; OEM Part #	Part #	Model; Year; OEM Part #			
20161 (315 MHz)	Infiniti	20335 (315 MHz)	Chrysler	28087 (433 MHz)	Porsche			
	QX56; 2007; Mar. & Older		Pacifica; 2005		911; 2010			
	QX56; 2006-2005; W/Alloy Wheels		Pacifica; 2004; OEM Part No. 04727392AD		Boxster; 2010			
	Nissan		Town & Country Van; 2005-2004		Cayman; 2010-2009			
	Armada; 2008; SE		Dodge		Panamera; 2011-2010			
	Armada; 2007		Caravan; 2005-2004		Mitsubishi			
	Armada; 2006-2005; W/Alloy Wheels		Grand Caravan; 2005-2004		Lancer; 2011; W/Steel Wheels			
	Frontier; 2008-2005; W/Alloy Wheels		Chrysler		Lancer; 2010-2008			
	Maxima; 2007; Mar. & Older		300; 2011		Outlander; 2011; W/Steel Wheels			
	Maxima; 2006; Jun. & Newer		Town & Country Van; 2011		Outlander; 2010-2007			
	Pathfinder; 2006-2005		Dodge		Mitsubishi			
	Quest; 2006-2005; W/Alloy Wheels		Challenger; 2011-2010; W/Rubber Stem Snap-in Sensor		Eclipse; 2007-2006; W/Steel Wheels			
	Sentra; 2007; W/Alloy Wheels		Charger; 2011-2010; W/Rubber Stem Snap-in Sensor		Galant; 2011-2007; W/Steel Wheels			
	Titan; 2007; Mar. & Older		Durango; 2011		Dodge			
	Titan; 2006		Grand Caravan; 2011		Dakota; 2010-2008			
	Titan; 2005; Apr. 1 & Newer		Ram Series Pickup; 2011-2010; W/Rubber Stem Snap-in Sensor		Ram Series Pickup; 2008; 1500, 2500			
	Xterra; 2006; Exc. Submodel X		Jeep		Mitsubishi			
	Xterra; 2005		Grand Cherokee; 2011		Raider; 2009-2008			
	20315 (315 MHz)		Ford		20398 (433 MHz)	Mitsubishi	28154 (315 MHz)	Chrysler
			E450 Super Duty; 2010			Lancer; 2 011; W/Alloy Wheels		300; 2008
			E Series Van; 2011			Outlander; 2011; W/Alloy Wheels		Town & Country Van; 2009-2008
E Series Van; 2010; W/Steel Wheels		Acura	Dodge					
Edge; 2011		Acura; TL; 2011-2009	Charger; 2008					
Escape; 2011-2009		Chrysler	Grand Caravan; 2010-2008					
Expedition; 2011		Prowler; 2001	Journey; 2010-2009					
Explorer; 2011		Plymouth	Magnum; 2008					
F Series Pickup; 2011-2009		Prowler; 2001-1999	Ram Series Pickup; 2010; 1500, 2500; W/ Metal Stem Clamp-in Sensor					
Fiesta; 2011		Prowler; 1997	Ram Series Pickup; 2009; 1500, 2500					
Flex; 2011		Chevrolet	Jeep					
Focus; 2011-2010		Corvette; 2000-1997	Commander; 2010-2008					
Fusion; 2011-2010		Saab	Grand Cherokee; 2010-2008					
Mustang; 2011-2010		9-3; 2007-2003	Liberty; 2009; Exc. Sport					
Super Duty Pickup; 2011		9-5; 2007-2003	Wrangler; 2010-2009					
Super Duty Van; 2011		Saturn	Nissan					
Super Duty Van; 2010; W/Steel Wheels		Astra; 2008	Pathfinder; 2007; OEM Part No. 40700JA01A					
Taurus; 2011		BMW	Versa; 2007; OEM Part No. 40700JA01A					
Taurus; 2010; May & Newer		328i; 2011-2010	Xterra; 2007; OEM Part No. 40700JA01A					
Transit Connect; 2011-2010		335D; 2011-2010	Subaru					
Lincoln		335i; 2011-2010	Forester; 2011-2008					
MKS; 2011	M3; 2010	Impreza; 2011-2008						
MKT; 2011	Mini	Legacy; 2011-2009						
MKX; 2011	Cooper; 2011-2010	Legacy; 2008; W/18" Wheels						
MKZ; 2011-2010	BMW	Outback; 2011-2008						
Navigator; 2011	X5; 2004-2000	Tribeca; 2011-2009						
Town Car; 2011	Land Rover	Tribeca; 2008; W/Rubber Stem Snap-in Sensor						
Mazda	LR3; 2005	Infiniti						
Tribute; 2010-2009	Range Rover; 2005-2002	FX35; 2008						
Mercury		FX35; 2007; Jul. & Newer						
Grand Marquis; 2011		FX45; 2008						
Mariner; 2011-2009		FX45; 2007; Jul. & Newer						
Milan; 2011-2010		G35; 2007; Coupe						
		M35; 2010-2008						

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Sensors/Transmitters

Part #	Model; Year; OEM Part #
28204 (315 MHz)	Infiniti - Continued
	M45; 2010-2008
	Q45; 2006; Aug. & Newer
	QX56; 2010-2008
	QX56; 2007; Apr. 1 & Newer
	Nissan
	350Z; 2009-2007
	Altima; 2011-2007
	Altima; 2006; Oct. 1 & Newer
	Armada; 2011-2009
	Armada; 2008; LE
	Cube; 2011
	Cube; 2009
	Frontier; 2011-2009
	Frontier; 2008; W/Steel Wheels
	GT-R; 2011
	GT-R; 2009
	Juke; 2011
	Maxima; 2011-2008
	Maxima; 2007; Apr. 1 & Newer
	Murano; 2011
	Murano; 2009
	Murano; 2007
	Pathfinder; 2011-2008
	Pathfinder; 2007; OEM Part No. 40700JA01B
	Quest; 2009-2007
	Rogue; 2011
	Rogue; 2009-2008
	Sentra; 2011-2008
	Sentra; 2007; W/Steel Wheels
	Titan; 2011-2008
	Titan; 2007; Apr. 1 & Newer
	Versa; 2011-2008
Versa; 2007; OEM Part No. 40700JA01B	
Xterra; 2011-2008	
Xterra; 2007; OEM Part No. 40700JA01B	
Suzuki	
Equator; 2011	
Buick	
Allure; 2010	
LaCrosse; 2011-2010	
Regal; 2011	
Cadillac	
SRX; 2011-2010	
Chevrolet	
Camaro; 2011-2010	
Cobalt; 2010	
Cruze; 2011	
Equinox; 2011-2010	
HHR; 2010	
Malibu; 2010	
Volt; 2011	
GMC	
Terrain; 2011-2010	
Saturn	
Astra; 2010-2009	

Part #	Model; Year; OEM Part #
28210 (315 MHz)	Infiniti
	EX35; 2010-2008
	FX35; 2010-2009
	FX50; 2010-2009
	G35; 2008
	G35; 2007; Sedan
	G37; 2010-2008
	Nissan
	370Z; 2009
	Mercedes-Benz
28214 (433 MHz)	C63; 2011-2008
	C300; 2011-2008
	C350; 2011-2008
	C350; 2007; Jun. & Newer
	CL63; 2011-2010
	CL65; 2011-2010
	CL550; 2011-2010
	CL600; 2010
	CLK55; 2006
	CLK63; 2009-2007
	CLK350; 2009-2006
	CLK500; 2006
	CLK550; 2009-2007
	E63; 2011-2010
	E350; 2011-2010
	E550; 2011-2010
	G55; 2011-2008
	G55; 2007; Mar. & Newer
	G500; 2008
	G500; 2007; Mar. & Newer
	G550; 2011-2009
	GL350; 2011-2010
	GL450; 2011-2010
	GL550; 2011-2010
	GLK350; 2011-2010
	ML63; 2011-2010
	ML350; 2011-2010
	ML450; 2011-2010
	ML550; 2011-2010
	R350; 2011-2010
	S63; 2011
	S65; 2011
	S400; 2011
S550; 2011	
S600; 2011	
SLK55; 2010-2008	
SLK55; 2007; May & Newer	
SLK280; 2008	
SLK280; 2007; May & Newer	
SLK300; 2011-2009	
SLK350; 2011-2008	
SLK350; 2007; May & Newer	
SLS; 2011	
Smart	
Fortwo; 2010-2008	

Part #	Model; Year; OEM Part #
28291 (433 MHz)	Chrysler
	300; 2010-2009
	Dodge
	Challenger; 2011-2010; W/Metal Stem Clamp-in Sensor
	Challenger; 2009-2008
	Charger; 2010; W/Metal Stem Clamp-in Sensor
Charger; 2009	
Toyota	
Sequoia; 2007-2005; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	
Tacoma; 2005; W/40 Deg. Angled Valve Sensor; Nov. 30 & Older	
Tundra; 2006; W/40 Deg. Angled Valve Sensor; Oct. 31 & Older	
Tundra; 2005; W/40 Deg. Angled Valve Sensor	
Toyota	
Sequoia; 2007-2005; W/Alloy Wheels	
Sequoia; 2007-2005; W/Steel Wheels; W/20 Deg. Angled Valve Sensor	
Tacoma; 2005; W/20 Deg. Angled Valve Sensor; Nov. 30 & Older	
Tundra; 2006; W/20 Deg. Angled Valve Sensor; Oct. 31 & Older	
Tundra; 2005; W/20 Deg. Angled Valve Sensor	
Chrysler	
200; 2011	
300; 2007-2005	
Aspen; 2009-2007	
Crossfire; 2005; OEM Part No. 5142340AA	
Pacifica; 2008-2006	
PT Cruiser; 2010-2008	
Sebring; 2010-2007	
Town & Country Van; 2007-2006	
Dodge	
Avenger; 2010-2008	
Caliber; 2011-2007	
Caravan; 2007-2006	
Charger; 2007-2006	
Dakota; 2011	
Durango; 2009-2007	
Grand Caravan; 2007-2006	
Journey; 2011	
Magnum; 2007-2005	
Nitro; 2011-2007	
Jeep	
Commander; 2007-2006	
Compass; 2011-2007	
Grand Cherokee; 2007-2005	
Liberty; 2011-2010	
Liberty; 2009; Sport	
Liberty; 2008-2005	
Patriot; 2011-2007	
Wrangler; 2011	
Wrangler; 2008-2007	
Suzuki	
Kizashi; 2011-2010	

NUMERICAL LISTING: Sensors/Transmitters

SCHRADER 2011 TPMS APPLICATION GUIDE

Part #	Model; Year; OEM Part #
28310 (315 MHz)	Lexus
	SC430; 2006; W/White I.D. Mark; Jul. & Older SC430; 2005-2002; W/White I.D. Mark
28315 (315 MHz)	Lexus
	SC430; 2006; W/Blue I.D. Mark; Jul. & Older SC430; 2005-2002; W/Blue I.D. Mark
28320 (315 MHz)	Lexus
	SC430; 2006; W/Red I.D. Mark; Jul. & Older SC430; 2005-2002; W/Red I.D. Mark
28325 (315 MHz)	Lexus
	SC430; 2006; W/Gold I.D. Mark; Jul. & Older SC430; 2005-2002; W/Gold I.D. Mark
28335 (315 MHz)	Lexus
	GS300; 2006
	GS430; 2006; Jun. & Older
	GS430; 2005
	GX470; 2006; Feb. & Newer; W/O Valve Cap
	IS250; 2006; Mar. & Older
	IS350; 2006; Mar. & Older
Toyota	
4 Runner; 2006; OEM Part No. 4260730030	
28345 (315 MHz)	Lexus
	GX470; 2006; Jan. 31 & Older
	GX470; 2005-2004 HS250h; 2011-2010
28355 (315 MHz)	Toyota
	4 Runner; 2006; OEM Part No. 4260735010 4 Runner; 2005-2003
28355 (315 MHz)	Toyota
	Tacoma; 2006; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Jul. & Older Tacoma; 2005; W/20 Deg. Angled Valve Sensor; Dec. 1 & Newer
28360 (315 MHz)	Pontiac
	Vibe; 2010-2008
	Toyota
	Avalon; 2011-2007 Avalon; 2006; Aug. & Newer
	Camry; 2011-2007; Models made in USA.; OEM Part No. 4260706011
	Corolla; 2011-2009; Models made in USA.; W/16" Or 17" Wheels
	Corolla; 2008; Models made in USA.; OEM Part No. 4260706011
	Corolla; 2007; Models made in USA.; OEM Part No. 4260706011; Jun. & Newer
	Highlander; 2011
	Matrix; 2011-2008; Models made in USA.; OEM Part No. 4260706011
	Matrix; 2007; Models made in USA.; OEM Part No. 4260706011; Jun. & Newer
	Solara; 2008-2007 Solara; 2006; May & Newer

Part #	Model; Year; OEM Part #
28360 (315 MHz) - Continued	Toyota - Continued
	Tacoma; 2011-2007; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor
	Tacoma; 2006; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Aug. & Newer Venza; 2011-2009
28365 (315 MHz)	Lexus
	GX470; 2006; Feb. & Newer; W/Valve Cap
	LX470; 2006; Jul. & Older
	LX470; 2005
	Scion
	iQ; 2011
	TC; 2011-2007
	TC; 2006; May & Newer
	XB; 2011-2008
	XD; 2011-2008
28370 (315 MHz)	Toyota
	4 Runner; 2009; W/Valve Cap
	4 Runner; 2008; W/Valve Cap; OEM Part No. 4260733011
	4 Runner; 2007; W/Valve Cap
	4 Runner; 2006; OEM Part No. 4260733011
	Camry; 2011-2007; Models made in Japan.; OEM Part No. 4260733011
	Corolla; 2011-2008; Models made in Japan.; OEM Part No. 4260733011
	Corolla; 2011-2009; Models made in USA.; W/15" Wheels
	Corolla; 2007; Models made in Japan.; OEM Part No. 4260733011; Jun. & Newer
	FJ Cruiser; 2011-2008
	Highlander; 2010-2008
	Highlander; 2007; May & Newer
	Land Cruiser; 2011-2006
	Land Cruiser; 2005; May & Newer
	Matrix; 2011-2008; Models made in Japan.; OEM Part No. 4260733011
Matrix; 2007; Models made in Japan.; OEM Part No. 4260733011; Jun. & Newer	
Prius; 2011-2006	
RAV4; 2006	
Yaris; 2011-2008	
Yaris; 2007; Aug. & Newer	
28370 (315 MHz)	Lexus
	CT200h; 2011
	ES350; 2011-2007
	GS350; 2011-2007
	GS430; 2007
	GS430; 2006; Jul. & Newer
	GS450h; 2011-2007
	GS460; 2011-2008
	GX460; 2011-2010
	GX470; 2009-2007
	IS250; 2011-2007
	IS250; 2006; Apr. 1 & Newer
	IS350; 2011-2007
IS350; 2006; Apr. 1 & Newer	

Part #	Model; Year; OEM Part #
28370 (315 MHz) - Continued	Lexus- Continued
	IS F; 2011-2008
	LFA; 2011
	LS460; 2011-2007
	LS600h; 2011-2008
	LX470; 2007
	LX470; 2006; Aug. & Newer
	LX570; 2011-2008
	RX330; 2006; Models made in Japan.; Feb. & Newer
	RX350; 2011
28380 (315 MHz)	Toyota
	RX350; 2010-2007; Models made in Japan.
	RX400h; 2009-2007; Models made in Japan.
	RX450h; 2011-2010
	SC430; 2010-2007
	SC430; 2006; Aug. & Newer
	Toyota
	4 Runner; 2011-2010
	4 Runner; 2009; W/O Valve Cap
	4 Runner; 2008; W/O Valve Cap; OEM Part No. 4260733021
4 Runner; 2007; W/O Valve Cap	
4 Runner; 2006; OEM Part No. 4260733021	
Corolla; 2011-2009; Models made in Japan.; OEM Part No. 4260733021	
RAV4; 2011-2007	
28385 (315 MHz)	Toyota
	Tacoma; 2011-2006; W/Steel Wheels; W/40 Deg. Angled Valve Sensor
	Tacoma; 2005; W/40 Deg. Angled Valve Sensor; Dec. 1 & Newer
	Ford
	Crown Victoria; 2011-2006
	Edge; 2008-2007; W/Chrome Plated Almm. Wheels
	Escape; 2008-2006
	Escape; 2005; Oct. 3, 2005 & Newer
	Explorer; 2010-2006
	Explorer Sport Trac; 2010-2007
F Series Pickup; 2008; W/O H.D. Payload Pkg.	
F Series Pickup; 2007	
Freestar; 2007-2006	
Fusion; 2009-2007	
Grand Marquis; 2010-2006	
Mustang; 2009-2007	
Ranger; 2011-2007	
28385 (315 MHz)	Lincoln
	Mark LT; 2008-2007
	MKX; 2008-2007; W/Chrome Plated Almm. Wheels
	MKZ; 2009-2007
	Town Car; 2010-2006
	Mazda
B2300 Pickup; 2009-2007	
B3000 Pickup; 2008-2007	

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Sensors/Transmitters

Part #	Model; Year; OEM Part #
28385 (315 MHz) - Continued	- Mazda - Continued
	B4000 Pickup; 2009-2007
	Tribute; 2008
	Tribute; 2006
	Mercury
	Grand Marquis; 2010-2006
	Mariner; 2008-2006
	Mariner; 2005; Oct. 3, 2005 & Newer
	Milan; 2009-2007
	Monterey Van; 2007-2006
	Mountaineer; 2010-2006
	Ford
Edge; 2010-2009	
Edge; 2008-2007; W/O Chrome Plated Almm. Wheels	
Expedition; 2010-2007	
Five Hundred; 2007-2006	
Flex; 2010-2009	
Focus; 2009-2008	
Taurus; 2010; Apr. & Older	
Taurus; 2009-2008	
Taurus X; 2009-2008	
Lincoln	
MKS; 2010-2009	
MKT; 2010	
MKX; 2010-2009	
MKX; 2008-2007; W/O Chrome Plated Almm. Wheels	
Navigator; 2010-2007	
Mercury	
Montego; 2007-2006	
Sable; 2009-2008	
Ford	
E450 Super Duty; 2009-2008	
E Series Van; 2010; W/Alloy Wheels	
E Series Van; 2009-2008	
F450 Super Duty; 2010-2008	
F550 Super Duty; 2010	
F Series Pickup; 2008; W/H.D. Payload Pkg.	
Super Duty Pickup; 2010-2008	
Super Duty Van; 2010; W/Alloy Wheels	
Super Duty Van; 2009-2008	
Chrysler	
300; 2008	
Town & Country Van; 2009-2008	
Dodge	
Charger; 2008	
Grand Caravan; 2010-2008	
Journey; 2010-2009	
Magnum; 2008	
Ram Series Pickup; 2010; 1500, 2500; W/ Metal Stem Clamp-in Sensor	
Ram Series Pickup; 2009; 1500, 2500	

Part #	Model; Year; OEM Part #
28434 (433 MHz) - Continued	Jeep
	Commander; 2010-2008
	Grand Cherokee; 2010-2008
	Liberty; 2009; Exc. Sport
Wrangler; 2010-2009	
Dodge	
Dakota; 2010-2008	
Ram Series Pickup; 2008; 1500, 2500	
Mitsubishi	
Raider; 2009-2008	
Toyota	
Sequoia; 2011-2008	
Sienna; 2011-2007	
Tundra; 2011	
Tundra; 2010-2007; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	
Tundra; 2006; W/20 Deg. Angled Valve Sensor; Nov. 1 & Newer	
Acura	
CSX; 2009-2008	
Honda	
Civic; 2011-2008	
Element; 2011-2009	
Fit; 2011-2009	
Insight; 2011-2010	
Odyssey; 2011	
Hyundai	
Accent; 2011-2008	
Equus; 2011	
Genesis; 2011; Sedan	
Sonata; 2010-2009	
Tucson; 2011-2010	
Kia	
Borrego; 2011-2009	
Rio; 2011-2007	
Spectra; 2009-2006	
Sportage; 2011-2009	
Acura	
MDX; 2006-2004	
RL; 2011-2005	
TL; 2008-2005	
Honda	
Odyssey; 2007-2005; Touring	
Pilot; 2008-2006	
Pilot; 2005; EX	
Pilot; 2005; LX; W/Short Stem Valve	
Ridgeline; 2011-2010; Exc. RT	
Ridgeline; 2011-2010; RT	
Ridgeline; 2009	
Ridgeline; 2008-2007; RTL, RTS, RTX	
Ridgeline; 2006; RTL, RTS	

Part #	Model; Year; OEM Part #
28982 (315 MHz)	Honda
	Pilot; 2005; LX; W/Long Stem Valve
Ridgeline; 2008-2006; RT	
Honda	
Odyssey; 2010-2009	
Hyundai	
Sonata; 2008-2007	
Tiburon; 2008-2007	
Tucson; 2009-2006	
Kia	
Amanti; 2009-2007	
Sorento; 2009-2007	
Sportage; 2008-2006	
Sportage; 2005; Jun. 15, 2005 & Newer	
28983 (315 MHz)	

Application guides subject to change without notice. Please refer to the manufacturer's websites for the most up-to-date application data.

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Service Packs

Part #	Model; Year; Sensor
20002	Ford
	Expedition; 2006-2003
	Explorer; 2005-2004
	Explorer; 2003-2002; Exc. Sport
	Freestar; 2005-2004; W/Almm. Valve Stem
	Lincoln
	Aviator; 2005-2003
	Navigator; 2006-2003
	Mercury
	Monterey Van; 2005-2004
Mountaineer; 2005-2002	
20003	Cadillac
	Deville; 2005-2001
	Seville; 2004-2001
	Chevrolet
	Corvette; 2004-2001
	Chrysler
	300M; 2004-2002; W/Schrader Sensor
	Concorde; 2004-2002; W/Schrader Sensor
	Crossfire; 2008-2006; W/Schrader Sensor
	Crossfire; 2005; OEM Part No. 52088990AC
Crossfire; 2004; W/Schrader Sensor	
Intrepid; 2004-2002; W/Schrader Sensor	
Pacifica; 2004; OEM Part No. 52088990AC	
Prowler; 2002; W/Schrader Sensor	
Prowler; 2001; W/Red Sensor Body	
Town & Country Van; 2003-2002	
Voyager; 2003-2002	
Dodge	
Caravan; 2003-2002	
Grand Caravan; 2003-2002	
Intrepid; 2004-2002	
Viper; 2010-2008	
Viper; 2006-2003	
Isuzu	
Rodeo; 2004	
Jeep	
Grand Cherokee; 2004-2002	
Liberty; 2004	
Mitsubishi	
Eclipse; 2010-2008	
Eclipse; 2007-2006; W/Alloy Wheels	
Endeavor; 2010	
Endeavor; 2008-2004	
Galant; 2009-2007; W/Alloy Wheels	
Galant; 2006-2004	
Montero; 2006-2003	
Plymouth	
Prowler; 2001-1999; W/Red Sensor Body	
Prowler; 1997; W/Red Sensor Body	

Part #	Model; Year; Sensor
20004	Buick
	Allure; 2008-2007; W/Schrader Sensor
	Enclave; 2008; W/Schrader Sensor
	LaCrosse; 2008-2007; W/Schrader Sensor
	Rainier; 2007-2006
	Cadillac
	CTS; 2011-2009; OEM Part No. 15268606; CTS V; W/315 MHz Sensor
	CTS; 2007-2004
	DTS; 2006
	Escalade; 2006-2004
SRX; 2006-2004	
STS; 2008-2005	
XLR; 2009-2004	
Chevrolet	
Avalanche; 2006-2004	
Caprice; 2011	
Cobalt; 2009-2008; Clamp-In Style Only; W/ Almm. Valve Stem	
Corvette; 2011-2005	
Equinox; 2009-2007; W/Schrader Sensor	
Express; 2009-2008; W/Schrader Sensor	
HHR; 2009-2008; Clamp-In Style Only; W/ Almm. Valve Stem	
Impala; 2007; Clamp-In Style Only; W/ Almm. Valve Stem	
Impala; 2006; W/Alloy Wheels	
Malibu; 2008; Clamp-In Style Only; W/ Almm. Valve Stem	
Monte Carlo; 2007; Clamp-In Style Only; W/ Almm. Valve Stem	
Monte Carlo; 2006; W/Alloy Wheels	
Silverado Series Pickup; 2007; Classic	
Silverado Series Pickup; 2006-2004	
SSR; 2006	
Suburban; 2006-2004	
Tahoe; 2006-2004	
Trailblazer; 2009-2006	
Uplander; 2009-2008	
GMC	
Acadia; 2008-2007; W/Schrader Sensor	
Envoy; 2009-2006	
Savana; 2009-2008; W/Schrader Sensor	
Sierra Series Pickup; 2007; Classic	
Sierra Series Pickup; 2006-2004	
Yukon; 2006-2004	
Isuzu	
Ascender; 2008-2006	
Pontiac	
G5; 2008; W/Schrader Sensor	
G6; 2008; W/Schrader Sensor	
Grand Prix; 2008; Clamp-In Style Only; W/ Almm. Valve Stem	

Part #	Model; Year; Sensor
20004 - Continued	Pontiac - Continued
	Grand Prix; 2007; W/Schrader Sensor
	Montana; 2009-2008; W/Schrader Sensor
	Solstice; 2010-2008; W/Schrader Sensor
	Torrent; 2009-2007; W/Schrader Sensor
	Saab
	9-7X; 2009-2005
	Saturn
	Aura; 2007; W/Schrader Sensor
	Outlook; 2008-2007; W/Schrader Sensor
Sky; 2010-2008; W/Schrader Sensor	
Suzuki	
XL-7; 2009-2007; W/Schrader Senso	
Infiniti	
QX56; 2006-2005; W/Steel Wheels	
QX56; 2004	
Nissan	
Armada; 2006-2005; W/Steel Wheels	
Frontier; 2007-2005; W/Steel Wheels	
Pathfinder; 2004; Armada	
Pathfinder; 2004; Exc. Armada; Aug. & Newer	
Quest; 2006-2005; W/Steel Wheels	
Quest; 2004	
Titan; 2005; Mar. & Older	
Titan; 2004	
Xterra; 2006; Submodel X	
Chevrolet	
Chevrolet; Colorado; 2011-2007	
GMC	
Canyon; 2011-2007	
Hummer	
H3; 2010-2006	
H3T; 2010-2009	
Isuzu	
I-290; 2008-2007	
I-370; 2008-2007	
Infiniti	
FX35; 2007; Jun. & Older	
FX35; 2006-2003	
FX45; 2007; Jun. & Older	
FX45; 2006-2003	
G35; 2006-2004	
G35; 2003; Jun. & Newer	
M35; 2007-2006	
M45; 2007-2006	
M45; 2004-2003	
Q45; 2006; Jul. & Older	
Q45; 2005-2003	
QX4; 2003	
QX56; 2007; Mar. & Older	
QX56; 2006-2005; W/Alloy Wheels	

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Service Packs

Part #	Model; Year; Sensor
20007 - Continued	Nissan
	350Z; 2006-2003
	Armada; 2008; SE
	Armada; 2007
	Armada; 2006-2005; W/Alloy Wheels
	Frontier; 2008-2005; W/Alloy Wheels
	Frontier; 2004-2003
	Maxima; 2007; Mar. & Older
	Maxima; 2006; Jun. & Newer
	Murano; 2006-2003
	Pathfinder; 2006-2005
	Pathfinder; 2004; Exc. Armada; Jul. & Older
	Pathfinder; 2003
	Quest; 2006-2005; W/Alloy Wheels
	Sentra; 2007; W/Alloy Wheels
	Titan; 2007; Mar. & Older
Titan; 2006	
Titan; 2005; Apr. 1 & Newer	
Xterra; 2006; Exc. Submodel X	
Xterra; 2005-2003	
20008	Buick
	Allure; 2010-2009
	Enclave; 2011-2009
	LaCrosse; 2011-2009
	Lucerne; 2011-2007
	Regal; 2011
	Cadillac
	CTS; 2011-2009; OEM Part No. 25920615; Exc. CTS V
	CTS; 2008
	DTS; 2011-2007
	Escalade; 2011-2008
	Escalade; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
	SRX; 2011-2007
	STS; 2011-2010
	STS; 2009; OEM Part No. 25920615; Exc. STS V
	Chevrolet
	Avalanche; 2011-2008
	Avalanche; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
	Aveo; 2011-2007
	Camaro; 2011-2010
	Cobalt; 2010
	Cobalt; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem
	Cruze; 2011
	Equinox; 2011-2010
Express; 2011-2010	
HHR; 2011-2010	
HHR; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem	
Impala; 2011-2008	
Impala; 2007; Snap-In Style Only; W/Rubber Valve Stem	
Malibu; 2011-2009	

Part #	Model; Year; Sensor
20008 - Continued	Chevrolet - Continued
	Malibu; 2008; Snap-In Style Only; W/Rubber Valve Stem
	Monte Carlo; 2007; Snap-In Style Only; W/Rubber Valve Stem
	Silverado Series Pickup; 2011-2008; W/Single Rear Wheels
	Silverado Series Pickup; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic
	Suburban; 2011-2008
	Suburban; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
	Tahoe; 2011-2008
	Tahoe; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
	Traverse; 2011-2009
	Volt; 2011
	Chrysler
	300; 2011
	Town & Country Van; 2011
	Dodge
	Challenger; 2011-2010; W/Rubber Stem Snap-in Sensor
	Charger; 2011-2010; W/Rubber Stem Snap-in Sensor
	Durango; 2011 r
	Grand Caravan; 2011
Ram Series Pickup; 2011-2010; W/Rubber Stem Snap-in Sensor	
GMC	
Acadia; 2011-2009	
Savana; 2011-2010	
Sierra Series Pickup; 2011-2008; W/Single Rear Wheels	
Sierra Series Pickup; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic	
Terrain; 2011-2010	
Yukon; 2011-2008	
Yukon; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	
Hummer	
H2; 2010-2008	
Jeep	
Grand Cherokee; 2011	
Mitsubishi	
Lancer; 2011; W/Alloy Wheels	
Outlander; 2011; W/Alloy Wheels	
Pontiac	
G3; 2010-2009	
G3 Wave; 2009	
G5; 2010-2009	
G6; 2010-2009	
G8; 2010-2008	
Grand Prix; 2008; Snap-In Style Only; W/Rubber Valve Stem	
Wave; 2008	

Part #	Model; Year; Sensor
20008 - Continued	Saturn
	Astra; 2010-2009
	Aura; 2010-2008
	Outlook; 2010-2009
	VUE; 2010-2008
	Subaru
	Forester; 2011-2008
	Impreza; 2011-2008
	Legacy; 2011-2009
	Legacy; 2008; W/18" Wheels
Outback; 2011-2008	
Tribeca; 2010-2009	
Tribeca; 2008; W/Rubber Stem Snap-in Sensor	
Suzuki	
Forenza; 2008-2007	
Reno; 2008-2007	
Saab	
9-3; 2011-2003	
9-5; 2011-2003	
Saturn	
Astra; 2008	
Suzuki	
Grand Vitara; 2011-2007	
SX4; 2011-2007	
Verona; 2006-2005	
XL-7; 2006-2005	
Mitsubishi	
Eclipse; 2007-2006; W/Steel Wheels	
Galant; 2009-2007; W/Steel Wheels	
Volvo	
S60; 2009-2006	
S60; 2005-2004; W/315 MHz Sensor	
S80; 2006-2004	
V70; 2007-2004; W/315 MHz Sensor	
XC70; 2007-2004; W/315 MHz Sensor	
XC90; 2009; W/315 MHz Sensor	
XC90; 2007-2005; W/315 MHz Sensor	
XC90; 2004	
Subaru	
B9 Tribeca; 2007-2006	
Legacy; 2008; W/16" Or 17" Wheels	
Legacy; 2007-2004	
Outback; 2006-2004	
Tribeca; 2008; W/Metal Stem Clamp-in Sensor	
Chevrolet	
Corvette; 2000-1997	
Chrysler	
Prowler; 2001; W/Black Sensor Body	
Plymouth	
Prowler; 2001-1999; W/Black Sensor Body	
Prowler; 1997; W/Black Sensor Body	

■ NUMERICAL LISTING: Service Packs

SCHRADER 2011 TPMS APPLICATION GUIDE

Part #	Model; Year; Sensor
20013	Chrysler
	200; 2011; W/Schrader Sensor
	300; 2008-2005; W/Schrader Sensor
	Aspen; 2009-2007; W/Schrader Sensor
	Crossfire; 2005; OEM Part No. 5142340AA
	Pacifica; 2008-2006; W/Schrader Sensor
	PT Cruiser; 2010-2008; W/Schrader Sensor
	Sebring; 2010-2007; W/Schrader Sensor
	Town & Country Van; 2009-2006; W/Schrader Sensor
	Dodge
	Avenger; 2010-2008; W/Schrader Sensor
	Caliber; 2011-2007; W/Schrader Sensor
	Caravan; 2007-2006; W/Schrader Sensor
	Charger; 2008-2006; W/Schrader Sensor
	Dakota; 2011-2008
	Durango; 2009
	Durango; 2008-2007; W/Schrader Sensor
	Grand Caravan; 2010-2006; W/Schrader Sensor
	Journey; 2011
Journey; 2010-2009; W/Schrader Sensor	
Magnum; 2008-2005; W/Schrader Sensor	
Nitro; 2011-2009	
Nitro; 2008-2007; W/Schrader Sensor	
Ram Series Pickup; 2010; 2500; W/Metal Stem Clamp-in Sensor	
Ram Series Pickup; 2009-2008; 2500	
Jeep	
Commander; 2010-2008	
Commander; 2007-2006; W/Schrader Sensor	
Compass; 2011-2007; W/Schrader Sensor	
Grand Cherokee; 2010-2008	
Grand Cherokee; 2007-2005; W/Schrader Sensor	
Liberty; 2011-2009	
Liberty; 2008-2005; W/Schrader Sensor	
Patriot; 2011-2007; W/Schrader Sensor	
Wrangler; 2011; W/Schrader Sensor	
Wrangler; 2010-2009	
Wrangler; 2008-2007; W/Schrader Sensor	
Mitsubishi	
Raider; 2009-2008	
Suzuki	
Kizashi; 2011-2010; W/Schrader Sensor	
Infiniti	
EX35; 2010-2008	
FX35; 2010-2008	
FX35; 2007; Jul. & Newer	
FX45; 2008	
FX45; 2007; Jul. & Newer	
FX50; 2010-2009	
G35; 2008-2007	
G37; 2010-2008	
M35; 2010-2008	
M45; 2010-2008	
Q45; 2006; Aug. & Newer	
QX56; 2010-2008	
QX56; 2007; Apr. 1 & Newer	

Part #	Model; Year; Sensor
20014 - Continued	Nissan
	350Z; 2009-2007
	370Z; 2009
	Altima; 2011-2007
	Altima; 2006; Oct. 1 & Newer
	Armada; 2011-2009
	Armada; 2008; LE
	Cube; 2011
	Cube; 2009
	Frontier; 2011-2009
	Frontier; 2008; W/Steel Wheels
	GT-R; 2011
	GT-R; 2009
	Juke; 2011
	Maxima; 2011-2008
	Maxima; 2007; Apr. 1 & Newer
	Murano; 2011
	Murano; 2009
	Murano; 2007
	Pathfinder; 2011-2007
Quest; 2009-2007	
Rogue; 2011	
Rogue; 2009-2008	
Sentra; 2011-2008	
Sentra; 2007; W/Steel Wheels	
Titan; 2011-2008	
Titan; 2007; Apr. 1 & Newer	
Versa; 2011-2007	
Xterra; 2011-2007	
Suzuki	
Equator; 2011	
Cadillac	
Escalade; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	
Chevrolet	
Avalanche; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	
Silverado Series Pickup; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic	
Suburban; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	
Tahoe; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	
GMC	
Sierra Series Pickup; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic	
Yukon; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	
Chrysler	
300; 2010-2009	
Dodge	
Challenger; 2011-2010; W/Metal Stem Clamp-in Sensor	
Challenger; 2009-2008	
Charger; 2010; W/Metal Stem Clamp-in Sensor	
Charger; 2009	

Part #	Model; Year; Sensor
20016 - Continued	Mercedes-Benz
	C63; 2011-2008
	C300; 2011-2008
	C350; 2011-2008
	C350; 2007; Jun. & Newer
	CL63; 2011-2010
	CL65; 2011-2010
	CL550; 2011-2010
	CL600; 2010
	CLK55; 2006
	CLK63; 2009-2007
	CLK350; 2009-2006
	CLK500; 2006
	CLK550; 2009-2007
	E63; 2011-2010
	E350; 2011-2010
	E550; 2011-2010
	G55; 2011; Mar. & Newer
	G55; 2010-2008
	G55; 2007; Mar. & Newer
	G500; 2008
	G500; 2007; Mar. & Newer
	G550; 2011; Mar. & Newer
	G550; 2010-2009
	GL350; 2011; Mar. & Newer
	GL350; 2010
	GL450; 2011; Mar. & Newer
	GL450; 2010
	GL550; 2011; Mar. & Newer
	GL550; 2010
	GLK350; 2011; Mar. & Newer
	GLK350; 2010
	ML63; 2011; Mar. & Newer
	ML350; 2011; Mar. & Newer
	ML350; 2010
	ML450; 2011; Mar. & Newer
	ML450; 2010
ML550; 2011; Mar. & Newer	
ML550; 2010	
R350; 2011; Mar. & Newer	
R350; 2010	
S63; 2011	
S65; 2011	
S400; 2011	
S550; 2011	
S600; 2011	
SLK55; 2010-2008	
SLK55; 2007; May & Newer	
SLK280; 2008	
SLK280; 2007; May & Newer	
SLK300; 2011-2009	
SLK350; 2011-2008	
SLK350; 2007; May & Newer	
SLS; 2011	
Smart	
Fortwo; 2010-2008	

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Service Packs

Part #	Model; Year; Sensor
20017	Audi
	A3; 2011-2008
	A4; 2011-2009
	A5; 2011-2008
	Q5; 2011-2009
	S4; 2011-2010
	S5; 2011-2008
	TT; 2011-2008
	Volkswagen
	Beetle; 2010-2008
CC; 2011-2009	
Eos; 2011-2007	
GLI; 2009-2008	
Golf; 2010-2008	
Golf; 2006; GTI	
GTI; 2010-2008	
GTI; 2007-2006; W/16" Or 17" Wheels	
Jetta; 2010-2006	
Passat; 2010-2009	
Passat; 2008-2006; W/16" Or 17" Wheels	
R32; 2008	
Rabbit; 2009-2008	
Rabbit; 2007-2006; W/15" Wheels	
Tiguan; 2011-2009	
20018	Ford
	E450 Super Duty; 2010
	E Series Van; 2010; W/Steel Wheels
	Escape; 2010-2009
	F Series Pickup; 2010-2009
	Fiesta; 2011
	Focus; 2010
	Fusion; 2010
	Mustang; 2011-2010
	Super Duty Van; 2010; W/Steel Wheels
	Taurus; 2011
	Taurus; 2010; May & Newer
	Transit Connect; 2010
	Lincoln
	MKZ; 2010
Mazda	
Tribute; 2010-2009	
Mercury	
Mariner; 2010-2009	
Milan; 2010	
20019	Acura
	CSX; 2009-2008
	TL; 2011-2009
	Honda
	Civic; 2011-2008
Element; 2011-2009	
Fit; 2011-2009	
Insight; 2011-2010	
Odyssey; 2011	
20020	Chrysler
	200; 2011; W/Schrader Sensor
	300; 2010-2009
	300; 2008-2005; W/Schrader Sensor
	Aspen; 2009-2007; W/Schrader Sensor

Part #	Model; Year; Sensor
20020 - Continued	Chrysler - Continued
	Crossfire; 2005; OEM Part No. 5142340AA
	Pacifica; 2008-2006; W/Schrader Sensor
	PT Cruiser; 2010-2008; W/Schrader Sensor
	Sebring; 2010-2007; W/Schrader Sensor
	Town & Country Van; 2009-2006; W/Schrader Sensor
	Dodge
	Avenger; 2010-2008; W/Schrader Sensor
	Caliber; 2011-2007; W/Schrader Sensor
	Caravan; 2007-2006; W/Schrader Sensor
	Challenger; 2011-2010; W/Metal Stem Clamp-in Sensor
	Challenger; 2009-2008
	Charger; 2010; W/Metal Stem Clamp-in Sensor
	Charger; 2009
	Charger; 2008-2006; W/Schrader Sensor
	Dakota; 2011-2008
	Durango; 2009
	Durango; 2008-2007; W/Schrader Sensor
	Grand Caravan; 2010-2006; W/Schrader Sensor
	Journey; 2011
Journey; 2010-2009; W/Schrader Sensor	
Magnum; 2008-2005; W/Schrader Sensor	
Nitro; 2011-2009	
Nitro; 2008-2007; W/Schrader Sensor	
Ram Series Pickup; 2010; 2500; W/Metal Stem Clamp-in Sensor	
Ram Series Pickup; 2009-2008; 2500	
Jeep	
Commander; 2010-2008	
Commander; 2007-2006; W/Schrader Sensor	
Compass; 2011-2007; W/Schrader Sensor	
Grand Cherokee; 2010-2008	
Grand Cherokee; 2007-2005; W/Schrader Sensor	
Liberty; 2011-2009	
Liberty; 2008-2005; W/Schrader Sensor	
Patriot; 2011-2007; W/Schrader Sensor	
Wrangler; 2011; W/Schrader Sensor	
Wrangler; 2010-2009	
Wrangler; 2008-2007; W/Schrader Sensor	
Mercedes-Benz	
C63; 2011-2008	
C300; 2011-2008	
C350; 2011-2008	
C350; 2007; Jun. & Newer	
CL63; 2011-2010	
CL65; 2011-2010	
CL550; 2011-2010	
CL600; 2010	
CLK55; 2006	
CLK63; 2009-2007	
CLK350; 2009-2006	
CLK500; 2006	
CLK550; 2009-2007	
E63; 2011-2010	
E350; 2011-2010	
E550; 2011-2010	
G55; 2011; Mar. & Newer	

Part #	Model; Year; Sensor
20020 - Continued	Mercedes-Benz - Continued
	G55; 2010-2008
	G55; 2007; Mar. & Newer
	G500; 2008
	G500; 2007; Mar. & Newer
	G550; 2011; Mar. & Newer
	G550; 2010-2009
	GL350; 2011; Mar. & Newer
	GL350; 2010
	GL450; 2011; Mar. & Newer
	GL450; 2010
	GL550; 2011; Mar. & Newer
	GL550; 2010
	GLK350; 2011; Mar. & Newer
	GLK350; 2010
	ML63; 2011; Mar. & Newer
	ML63; 2010
	ML350; 2011; Mar. & Newer
	ML350; 2010
	ML450; 2011; Mar. & Newer
	ML450; 2010
	ML550; 2011; Mar. & Newer
	ML550; 2010
	R350; 2011; Mar. & Newer
	R350; 2010
	S63; 2011
	S65; 2011
	S400; 2011
	S550; 2011
	S600; 2011
SLK55; 2010-2008	
SLK55; 2007; May & Newer	
SLK280; 2008	
SLK280; 2007; May & Newer	
SLK300; 2011-2009	
SLK350; 2011-2008	
SLK350; 2007; May & Newer	
SLS; 2011	
Mitsubishi	
Raider; 2009-2008	
Smart	
Smart; Fortwo; 2010-2008	
Suzuki	
Kizashi; 2011-2010; W/Schrader Sensor	
Acura	
MDX; 2006-2004	
RL; 2011-2005	
TL; 2008-2005	
Dodge	
Sprinter; 2009-2007	
Honda	
Element; 2008-2007	
Odyssey; 2010-2009	
Odyssey; 2007	
Odyssey; 2006-2005; Touring	
Pilot; 2008-2005	
Ridgeline; 2011-2006	

■ NUMERICAL LISTING: Service Packs

SCHRADER 2011 TPMS APPLICATION GUIDE

Part #	Model; Year; Sensor
Hyundai	
	Azera; 2011-2006
	Elantra; 2010-2008
	Entourage; 2009-2007
	Santa Fe; 2010-2007
	Sonata; 2008-2007
	Tiburon; 2008-2007
	Tucson; 2009-2006
	Veracruz; 2011-2007
Kia	
	Amanti; 2009-2007
	Magentis; 2010-2008
	Optima; 2010-2006
	Rondo; 2010-2007
	Sedona; 2011-2006
	Sorento; 2009-2007
	Sportage; 2008-2006
	Sportage; 2005; Jun. 15, 2005 & Newer
Mercedes-Benz	
	CL63; 2009-2007
	CL65; 2009-2008
	CL550; 2009-2007
	CL600; 2009-2007
	CLS55; 2006
	CLS63; 2011-2007
	CLS500; 2006
	CLS550; 2011-2007
	E55; 2006
	E63; 2009-2007
	E320; 2009-2006
	E350; 2009-2006
	E500; 2006
	E550; 2009-2007
	GL320; 2009-2007
	GL450; 2009-2007
	GL550; 2009-2008
	ML63; 2009-2007
	ML320; 2009-2007
	ML350; 2009-2006
	ML500; 2007-2006
	ML550; 2009-2008
	R63; 2007
	R320; 2009-2007
	R350; 2009-2006
	R500; 2007-2006
	S63; 2010-2007
	S65; 2010-2007
	S400; 2010
	S550; 2010-2007
	S600; 2010-2007
	SL55; 2008-2006
	SL63; 2009
	SL65; 2009-2006
	SL500; 2006
	SL550; 2009-2007
	SL600; 2009-2006
	SLR McLaren; 2009-2008

20021 - Continued

Part #	Model; Year; Sensor
Hyundai	
	Accent; 2011-2008
	Equus; 2011
	Genesis; 2010-2009
	Sonata; 2010-2009
	Tucson; 2011-2010
Kia	
	Borrego; 2011-2009
	Rio; 2011-2007
	Spectra; 2009-2006
	Sportage; 2011-2009
Toyota	
	Sequoia; 2011-2008
	Sienna; 2011-2007
	Tundra; 2011-2007
	Tundra; 2006; Nov. 1 & Newer
Audi	
	A4; 2008-2002
	A6; 2011-2005
	A8; 2010-2001
	Allroad Quattro; 2005-2001
	Q7; 2011-2007
	R8; 2010-2008
	RS4; 2008-2007
	S4; 2009-2004
	S6; 2011-2007
	S8; 2009-2007
	S8; 2003-2001
Bentley	
	Continental; 2010-2003
BMW	
	128i; 2011-2008
	135i; 2010-2008
	320i; 2005-2001
	323Ci; 2000
	323i; 2010-2007
	323i; 2006; Jun. & Newer
	323i; 2000
	325Ci; 2006-2001
	325i; 2006-2001
	325Xi; 2006-2001
	328Ci; 2000
	328i; 2011-2007
	328i; 2000
	328Xi; 2008-2007
	330Ci; 2006-2001
	330i; 2006-2001
	330Xi; 2006-2001
	335D; 2011-2009
	335i; 2011-2007
	335Xi; 2008-2007
	525i; 2007-2001
	525Xi; 2007-2006
	528i; 2010-2008
	528i; 2000-1997
	528Xi; 2008
	530i; 2007-2001

20023

Part #	Model; Year; Sensor
BMW - Continued	
	530Xi; 2007-2006
	535i; 2011-2008
	535Xi; 2008
	540i; 2003-1997
	545i; 2005-2004
	550i; 2011-2006
	645Ci; 2005-2004
	650i; 2010-2006
	740i; 2011
	740i; 2001-1997
	740iL; 2001-1997
	740Li; 2011
	745i; 2005-2002
	745Li; 2005-2002
	750i; 2011-2006
	750iL; 2001-1997
	750Li; 2011-2006
	760i; 2006-2004
	760Li; 2010
	760Li; 2008-2003
	Alpina B7; 2011
	Alpina B7; 2008-2007
	M3; 2010-2008
	M3; 2006-2001
	M5; 2010-2006
	M5; 2003-2000
	M6; 2010-2006
	X3; 2010-2006
	X5; 2011-2000
	X6; 2010-2008
	Z3; 2002-2000
	Z4; 2011-2003
	Z8; 2003-2000
Bugatti	
	Veyron; 2006
Ferrari	
	550 Maranello; 2002-2001
	575M Maranello; 2005-2002
	612 Scaglietti; 2009-2004
	Enzo; 2004-2003
	F430; 2009-2005
Land Rover	
	LR3; 2005
	Range Rover; 2005-2002
Maserati	
	Coupe; 2006-2004
	Gransport; 2006-2004
	MC12; 2006
	Quattroporte; 2006-2004
	Spyder; 2006-2004
Mercedes-Benz	
	CL55; 2006-2001
	CL65; 2006-2005
	CL500; 2006-2000
	CL600; 2006-2001
	E55; 2005-2000

20023 - Continued

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Service Packs

Part #	Model; Year; Sensor	
20023 - Continued	Mercedes-Benz - Continued	
	E55; 1999; Jul. & Newer	
	E320; 2005-2001	
	E430; 2002-2001	
	E500; 2005-2003	
	R550; 2008	
	S55; 2006-2001	
	S65; 2006	
	S350; 2006	
	S430; 2006-2000	
	S500; 2006-2000	
	S600; 2006-2001	
	SL55; 2005-2003	
	SL65; 2005	
	SL500; 2005-2001	
	SL600; 2005-2004	
	SL600; 2002-2001	
	SLR McLaren; 2007-2004	
		Mini
		Cooper; 2010-2008
	Porsche	
	911; 2011-2005	
	Boxster; 2011-2005	
	Carrera GT; 2006-2004	
	Cayenne; 2010-2008	
	Cayenne; 2006-2003	
	Cayman; 2011-2006	
	Panamera; 2010	
	Rolls-Royce	
	Phantom; 2010-2007	
	Volkswagen	
	Phaeton; 2006-2004; W/315 MHz Sensor	
	Touareg; 2007-2004	
	Touareg 2; 2011-2008	
	Touareg 2; 2011; W/315 MHz Sensor	
20030	Buick	
	Allure; 2008-2007; W/Siemens Sensor	
	Enclave; 2008; W/Siemens Sensor	
	LaCrosse; 2008-2007; W/Siemens Sensor	
	Chevrolet	
	Equinox; 2009-2007; W/Siemens Sensor	
	Express; 2009-2008; W/Siemens Sensor	
	Chrysler	
	300; 2008-2005; W/Siemens Sensor	
	300M; 2004-2002; W/Siemens Sensor	
	Aspen; 2009-2007; W/Siemens Sensor	
	Concorde; 2004-2002; W/Siemens Sensor	
	Crossfire; 2008-2006; W/Siemens Sensor	
	Crossfire; 2004; W/Siemens Sensor	
	20030 - Continued	
	Intrepid; 2004-2002; W/Siemens Sensor	
	Pacifica; 2008-2006; W/Siemens Sensor	
	Pacifica; 2005	
	Pacifica; 2004; OEM Part No. 04727392AD	
	Prowler; 2002; W/Siemens Sensor	
PT Cruiser; 2010-2008; W/Siemens Sensor		

Part #	Model; Year; Sensor
20030 - Continued	Chrysler - Continued
	Sebring; 2009-2007; W/Siemens Sensor
	Town & Country Van; 2009-2006; W/Siemens Sensor
	Town & Country Van; 2005-2004
	Dodge
	Avenger; 2009-2008; W/Siemens Sensor
	Caliber; 2010-2007; W/Siemens Sensor
	Caravan; 2007-2006; W/Siemens Sensor
	Caravan; 2005-2004
	Charger; 2008-2006; W/Siemens Sensor
	Durango; 2008-2007; W/Siemens Sensor
	Grand Caravan; 2010-2006; W/Siemens Sensor
	Grand Caravan; 2005-2004
	Journey; 2010-2009; W/Siemens Sensor
	Magnum; 2008-2005; W/Siemens Sensor
	Nitro; 2008-2007; W/Siemens Sensor
	GMC
	Acadia; 2008-2007; W/Siemens Sensor
	Savana; 2009-2008; W/Siemens Sensor
	Jaguar
S-Type; 2008	
Super V8; 2009-2005	
Vanden Plas; 2009-2004	
X-Type; 2008	
XF; 2011-2009	
XFR; 2011-2010	
XJ; 2011-2010	
XJ8; 2009-2004	
XJR; 2009-2004	
XK; 2011-2007	
XKR; 2011-2007	
Jeep	
Commander; 2007-2006; W/Siemens Sensor	
Compass; 2010-2007; W/Siemens Sensor	
Grand Cherokee; 2007-2005; W/Siemens Sensor	
Liberty; 2008-2005; W/Siemens Sensor	
Patriot; 2010-2007; W/Siemens Sensor	
Wrangler; 2008-2007; W/Siemens Sensor	
Land Rover	
LR2; 2011-2008	
LR3; 2009-2006	
LR4; 2011-2010	
Range Rover; 2011-2006	
Mazda	
2; 2011	
3; 2011-2004	
5; 2010-2006	
6; 2011-2008	
CX-7; 2011-2007	
CX-9; 2011-2007	
MX-5 Miata; 2011-2006	
RX-8; 2011-2004	
Tribute; 2011	

Part #	Model; Year; Sensor
20030 - Continued	Mitsubishi
	Lancer; 2011; W/Steel Wheels
	Lancer; 2010-2008
	Outlander; 2011; W/Steel Wheels
	Outlander; 2010-2007
	Pontiac
	G5; 2008; W/Siemens Sensor
	G6; 2008; W/Siemens Sensor
	Grand Prix; 2007; W/Siemens Sensor
	Montana; 2009-2008; W/Siemens Sensor
	Solstice; 2010-2008; W/Siemens Sensor
	Torrent; 2009-2007; W/Siemens Sensor
	Saturn
	Aura; 2007; W/Siemens Sensor
	Outlook; 2008-2007; W/Siemens Sensor
	Sky; 2010-2008; W/Siemens Sensor
	Suzuki
	Kizashi; 2011-2010; W/Siemens Sensor
	XL-7; 2009-2007; W/Siemens Sensor
	Volvo
Volvo; C30; 2011-2007	
Volvo; C70; 2011-2008	
Volvo; S40; 2011-2008	
S60; 2011	
S80; 2011-2007	
V50; 2011-2008	
V70; 2010-2008	
XC60; 2011-2010	
XC70; 2011-2008	
XC90; 2011-2010	
XC90; 2008	
Lexus	
GS300; 2006	
GS430; 2006; Jun. & Older	
GS430; 2005	
GX470; 2006; Jan. 31 & Older	
GX470; 2005-2004	
IS250; 2006; Mar. & Older	
IS350; 2006; Mar. & Older	
LX470; 2006; Jul. & Older	
LX470; 2005	
RX330; 2006; Jan. 31 & Older	
Toyota	
4 Runner; 2006; May & Older	
4 Runner; 2005-2003	
Land Cruiser; 2006; Mar. & Older	
Land Cruiser; 2005; May & Newer	
Sequoia; 2007-2005	
Tacoma; 2006; Jul. & Older	
Tacoma; 2005	
Tundra; 2006; Oct. 31 & Older	
Tundra; 2005	
Honda	
Accord; 2011-2010; Exc. Crosstour	
Accord; 2009-2008	
CR-V; 2011-2007	
Fit; 2008	

■ NUMERICAL LISTING: Service Packs

SCHRADER 2011 TPMS APPLICATION GUIDE

Part #	Model; Year; Sensor
20032 - Continued	Honda - Continued
	Pilot; 2011-2010; Exc. LX
	Pilot; 2009; W/Alloy Wheels
	S2000; 2009-2008
	Lexus
	CT200h; 2011
	ES350; 2011-2007
	GS350; 2011-2007
	GS430; 2007
	GS430; 2006; Jul. & Newer
	GS450h; 2011-2007
	GS460; 2011-2008
	GX460; 2011-2010
	GX470; 2009-2007
	GX470; 2006; Feb. & Newer
	HS250h; 2011-2010
	IS250; 2011-2007
	IS250; 2006; Apr. 1 & Newer
	IS350; 2011-2007
	IS350; 2006; Apr. 1 & Newer
	Lexus - Continued
	IS F; 2011-2008
	LFA; 2011
	LS460; 2011-2007
	LS600h; 2011-2008
	LX470; 2007
	LX470; 2006; Aug. & Newer
	LX570; 2011-2008
	RX330; 2006; Feb. & Newer
	RX350; 2011-2007
	RX400h; 2009-2007
	RX450h; 2011-2010
	SC430; 2010-2007
	SC430; 2006; Aug. & Newer
	Pontiac
	Vibe; 2010-2008
	Scion
	iQ; 2011
	TC; 2011-2007
	TC; 2006; May & Newer
	XB; 2011-2008
	XD; 2011-2008
	Toyota
	4 Runner; 2011-2007
	4 Runner; 2006; Jun. & Newer
	Avalon; 2011-2007
	Avalon; 2006; Aug. & Newer
	Camry; 2011-2007
Corolla; 2011-2008	
Corolla; 2007; Jun. & Newer	
FJ Cruiser; 2011-2008	
Highlander; 2011-2008	
Highlander; 2007; May & Newer	
Land Cruiser; 2011-2007	
Land Cruiser; 2006; Apr. 1 & Newer	
Matrix; 2011-2008	
Matrix; 2007; Jun. & Newer	

Part #	Model; Year; Sensor	
20032 - Continued	Toyota - Continued	
	Prius; 2011-2006	
	RAV4; 2011-2006	
	Solara; 2008-2007	
	Solara; 2006; May & Newer	
	Tacoma; 2011-2007	
	Tacoma; 2006; Aug. & Newer	
	Venza; 2011-2009	
	Yaris; 2011-2008	
	Yaris; 2007; Aug. & Newer	
	20035	Honda
		Pilot; 2005; LX; W/Long Stem Valve
Ridgeline; 2008-2006; RT		
20036	Acura	
	MDX; 2006-2004	
	RL; 2011-2005	
	TL; 2008-2005	
Dodge		
Sprinter; 2009-2007		
Honda		
Element; 2008-2007		
Odyssey; 2010-2009		
Odyssey; 2007		
Odyssey; 2006-2005; Touring		
Pilot; 2008-2006		
Pilot; 2005; EX		
Pilot; 2005; LX; W/Short Stem Valve		
Ridgeline; 2011-2010; RT		
Ridgeline; 2009		
Ridgeline; 2008-2007; RTL, RTS, RTX		
Ridgeline; 2006; RTL, RTS		
Hyundai		
Azera; 2011-2006		
Elantra; 2010-2008		
Entourage; 2009-2007		
Santa Fe; 2010-2007		
Sonata; 2008-2007		
Tiburon; 2008-2007		
Tucson; 2009-2006		
Veracruz; 2011-2007		
Kia		
Amanti; 2009-2007		
Magentis; 2010-2008		
Optima; 2010-2006		
Rondo; 2010-2007		
Sedona; 2011-2006		
Sorento; 2009-2007		
Sportage; 2008-2006		
Sportage; 2005; Jun. 15, 2005 & Newer		
Mercedes-Benz		
CL63; 2009-2007		
CL65; 2009-2008		
CL550; 2009-2007		
CL600; 2009-2007		
CLS55; 2006		

Part #	Model; Year; Sensor
20036 - Continued	Mercedes-Benz - Continued
	CLS63; 2011-2007
	CLS500; 2006
	CLS550; 2011-2007
	E55; 2006
	E63; 2009-2007
	E320; 2009-2006
	E350; 2009-2006
	E500; 2006
	E550; 2009-2007
	GL320; 2009-2007
	GL450; 2009-2007
	GL550; 2009-2008
	ML63; 2009-2007
	ML320; 2009-2007
	ML350; 2009-2006
	ML500; 2007-2006
	ML550; 2009-2008
	R63; 2007
	R320; 2009-2007
	R350; 2009-2006
	R500; 2007-2006
	S63; 2010-2007
	S65; 2010-2007
	S400; 2010
	S550; 2010-2007
	S600; 2010-2007
	SL55; 2008-2006
	SL63; 2009
	SL65; 2009-2006
	SL500; 2006
	SL550; 2009-2007
SL600; 2009-2006	
SLR McLaren; 2009-2008	
Audi	
A4; 2008-2002	
A6; 2011-2005	
A8; 2010-2001	
Allroad Quattro; 2005-2001	
Q7; 2011-2007	
R8; 2011-2008	
RS4; 2008-2007	
S4; 2009-2004	
S6; 2011-2007	
S8; 2009-2007	
S8; 2003-2001	
Bentley	
Continental; 2010-2003	
BMW	
128i; 2011-2008	
135i; 2010-2008	
320i; 2005-2001	
323Ci; 2000	
323i; 2010-2007	
323i; 2006; Jun. & Newer	
323i; 2000	
325Ci; 2006-2001	
325i; 2006-2001	

20037 (W/43mm Silver Insert)

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Service Packs

Part #	Model; Year; Sensor
BMW - Continued	
	325XI; 2006-2001
	328CI; 2000
	328I; 2011-2007
	328I; 2000
	328XI; 2008-2007
	330CI; 2006-2001
	330I; 2006-2001
	330XI; 2006-2001
	335D; 2011-2009
	335I; 2011-2007
	335XI; 2008-2007
	525I; 2007-2001
	525XI; 2007-2006
	528I; 2010-2008
	528I; 2000-1997
	528XI; 2008
	530I; 2007-2001
	530XI; 2007-2006
	535I; 2011-2008
	535XI; 2008
	540I; 2003-1997
	545I; 2005-2004
	550I; 2011-2006
	645CI; 2005-2004
	650I; 2010-2006
	740I; 2011
	740I; 2001-1997
	740IL; 2001-1997
	740LI; 2011
	745I; 2005-2002
	745LI; 2005-2002
	750I; 2011-2006
	750IL; 2001-1997
	750LI; 2011-2006
	760I; 2006-2004
	760LI; 2010
	760LI; 2008-2003
	Alpina B7; 2011
	Alpina B7; 2008-2007
	M3; 2010-2008
	M3; 2006-2001
	M5; 2010-2006
	M5; 2003-2000
	M6; 2010-2006
	X3; 2010-2006
	X5; 2011-2000
	X6; 2010-2008
	Z3; 2002-2000
	Z4; 2011-2003
	Z8; 2003-2000
Bugatti	
	Veyron; 2006
Ferrari	
	550 Maranello; 2002-2001
	575M Maranello; 2005-2002
	612 Scaglietti; 2009-2004
	Enzo; 2004-2003
	F430; 2009-2005

20037 (W/43mm Silver Insert) - Continued

Part #	Model; Year; Sensor
Land Rover	
	LR3; 2005
	Range Rover; 2005-2002
Maserati	
	Coupe; 2006-2004
	Gransport; 2006-2004
	MC12; 2006
	Quattroporte; 2006-2004
	Spyder; 2006-2004
Mercedes-Benz	
	CL55; 2006-2001
	CL65; 2006-2005
	CL500; 2006-2000
	CL600; 2006-2001
	E55; 2005-2000
	E55; 1999; Jul. & Newer
	E320; 2005-2001
	E430; 2002-2001
	E500; 2005-2003
	R550; 2008
	S55; 2006-2001
	S65; 2006
	S350; 2006
	S430; 2006-2000
	S500; 2006-2000
	S600; 2006-2001
	SL55; 2005-2003
	SL65; 2005
	SL500; 2005-2001
	SL600; 2005-2004
	SL600; 2002-2001
	SLR McLaren; 2007-2004
Mini	
	Cooper; 2010-2008
Porsche	
	911; 2011-2005
	Boxster; 2011-2005
	Carrera GT; 2006-2004
	Cayenne; 2011-2008
	Cayenne; 2006-2003
	Cayman; 2011-2006
	Panamera; 2011-2010
Rolls-Royce	
	Phantom; 2010-2007
Volkswagen	
	Phaeton; 2006-2004; W/315 MHz Sensor
	Touareg; 2007-2004
	Touareg 2; 2011-2008
	Touareg 2; 2011; W/315 MHz Sensor
Audi	
	A4; 2008-2002
	A6; 2011-2005
	A8; 2010-2001
	Allroad Quattro; 2005-2001

20037 (W/43mm Silver Insert) - Continued

20038 (W/48mm Green Insert)

Part #	Model; Year; Sensor
Audi - Continued	
	Q7; 2011-2007
	R8; 2011-2008
	RS4; 2008-2007
	S4; 2009-2004
	S6; 2011-2007
	S8; 2009-2007
	S8; 2003-2001
Bentley	
	Continental; 2010-2003
BMW	
	128I; 2011-2008
	135I; 2010-2008
	320I; 2005-2001
	323CI; 2000
	323I; 2010-2007
	323I; 2006; Jun. & Newer
	323I; 2000
	325CI; 2006-2001
	325I; 2006-2001
	325XI; 2006-2001
	328CI; 2000
	328I; 2011-2007
	328I; 2000
	328XI; 2008-2007
	330CI; 2006-2001
	330I; 2006-2001
	330XI; 2006-2001
	335D; 2011-2009
	335I; 2011-2007
	335XI; 2008-2007
	525I; 2007-2001
	525XI; 2007-2006
	528I; 2010-2008
	528I; 2000-1997
	528XI; 2008
	530I; 2007-2001
	530XI; 2007-2006
	535I; 2011-2008
	535XI; 2008
	540I; 2003-1997
	545I; 2005-2004
	550I; 2011-2006
	645CI; 2005-2004
	650I; 2010-2006
	740I; 2011
	740I; 2001-1997
	740IL; 2001-1997
	740LI; 2011
	745I; 2005-2002
	745LI; 2005-2002
	750I; 2011-2006
	750IL; 2001-1997
	750LI; 2011-2006
	760I; 2006-2004
	760LI; 2010
	760LI; 2008-2003

20038 (W/48mm Green Insert) - Continued

■ NUMERICAL LISTING: Service Packs

SCHRADER 2011 TPMS APPLICATION GUIDE

Part #	Model; Year; Sensor
BMW - Continued	
	Alpina B7; 2011
	Alpina B7; 2008-2007
	M3; 2010-2008
	M3; 2006-2001
	M5; 2010-2006
	M5; 2003-2000
	M6; 2010-2006
	X3; 2010-2006
	X5; 2011-2000
	X6; 2010-2008
	Z3; 2002-2000
	Z4; 2011-2003
	Z8; 2003-2000
Bugatti	
	Veyron; 2006
Ferrari	
	550 Maranello; 2002-2001
	575M Maranello; 2005-2002
	612 Scaglietti; 2009-2004
	Enzo; 2004-2003
	F430; 2009-2005
Land Rover	
	LR3; 2005
	Range Rover; 2005-2002
Maserati	
	Coupe; 2006-2004
	Gransport; 2006-2004
	MC12; 2006
	Quattroporte; 2006-2004
	Spyder; 2006-2004
Mercedes-Benz	
	CL55; 2006-2001
	CL65; 2006-2005
	CL500; 2006-2000
	CL600; 2006-2001
	E55; 2005-2000
	E55; 1999; Jul. & Newer
	E320; 2005-2001
	E430; 2002-2001
	E500; 2005-2003
	R550; 2008
	S55; 2006-2001
	S65; 2006
	S350; 2006
	S430; 2006-2000
	S500; 2006-2000
	S600; 2006-2001
	SL55; 2005-2003
	SL65; 2005
	SL500; 2005-2001
	SL600; 2005-2004
	SL600; 2002-2001
	SLR McLaren; 2007-2004
Mini	
	Cooper; 2010-2008

20038 (W/48mm Green Insert) - Continued

Part #	Model; Year; Sensor
Porsche	
	911; 2011-2005
	Boxster; 2011-2005
	Carrera GT; 2006-2004
	Cayenne; 2011-2008
	Cayenne; 2006-2003
	Cayman; 2011-2006
	Panamera; 2011-2010
Rolls-Royce	
	Phantom; 2010-2007
Volkswagen	
	Phaeton; 2006-2004; W/315 MHz Sensor
	Touareg; 2007-2004
	Touareg 2; 2011-2008
	Touareg 2; 2011; W/315 MHz Sensor
Audi	
	A4; 2008-2002
	A6; 2011-2005
	A8; 2010-2001
	Allroad Quattro; 2005-2001
	Q7; 2011-2007
	R8; 2011-2008
	RS4; 2008-2007
	S4; 2009-2004
	S6; 2011-2007
	S8; 2009-2007
	S8; 2003-2001
Bentley	
	Continental; 2010-2003
BMW	
	128i; 2011-2008
	135i; 2010-2008
	320i; 2005-2001
	323Ci; 2000
	323i; 2010-2007
	323i; 2006; Jun. & Newer
	323i; 2000
	325Ci; 2006-2001
	325i; 2006-2001
	325Xi; 2006-2001
	328Ci; 2000
	328i; 2011-2007
	328i; 2000
	328Xi; 2008-2007
	330Ci; 2006-2001
	330i; 2006-2001
	330Xi; 2006-2001
	335D; 2011-2009
	335i; 2011-2007
	335Xi; 2008-2007
	525i; 2007-2001
	525Xi; 2007-2006
	528i; 2010-2008
	528i; 2000-1997
	528Xi; 2008
	530i; 2007-2001
	530Xi; 2007-2006
	535i; 2011-2008

20039 (W/49mm Black Insert)

Part #	Model; Year; Sensor
BMW - Continued	
	535Xi; 2008
	540i; 2003-1997
	545i; 2005-2004
	550i; 2011-2006
	645Ci; 2005-2004
	650i; 2010-2006
	740i; 2011
	740i; 2001-1997
	740iL; 2001-1997
	740Li; 2011
	745i; 2005-2002
	745Li; 2005-2002
	750i; 2011-2006
	750iL; 2001-1997
	750Li; 2011-2006
	760i; 2006-2004
	760Li; 2010
	760Li; 2008-2003
	Alpina B7; 2011
	Alpina B7; 2008-2007
	M3; 2010-2008
	M3; 2006-2001
	M5; 2010-2006
	M5; 2003-2000
	M6; 2010-2006
	X3; 2010-2006
	X5; 2011-2000
	X6; 2010-2008
	Z3; 2002-2000
	Z4; 2011-2003
	Z8; 2003-2000
Bugatti	
	Veyron; 2006
Ferrari	
	550 Maranello; 2002-2001
	575M Maranello; 2005-2002
	612 Scaglietti; 2009-2004
	Enzo; 2004-2003
	F430; 2009-2005
Land Rover	
	LR3; 2005
	Range Rover; 2005-2002
Maserati	
	Coupe; 2006-2004
	Gransport; 2006-2004
	MC12; 2006
	Quattroporte; 2006-2004
	Spyder; 2006-2004
Mercedes-Benz	
	CL55; 2006-2001
	CL65; 2006-2005
	CL500; 2006-2000
	CL600; 2006-2001
	E55; 2005-2000
	E55; 1999; Jul. & Newer

20039 (W/49mm Black Insert) - Continued

SCHRADER 2011 TPMS APPLICATION GUIDE

NUMERICAL LISTING: Service Packs

Part #	Model; Year; Sensor	
20039 (W/49mm Black Insert) - Continued	Mercedes-Benz - Continued	
	E320; 2005-2001	
	E430; 2002-2001	
	E500; 2005-2003	
	R550; 2008	
	S55; 2006-2001	
	S65; 2006	
	S350; 2006	
	S430; 2006-2000	
	S500; 2006-2000	
	S600; 2006-2001	
	SL55; 2005-2003	
	SL65; 2005	
	SL500; 2005-2001	
	SL600; 2005-2004	
	SL600; 2002-2001	
	SLR McLaren; 2007-2004	
		Mini
	Cooper; 2010-2008	
		Porsche
911; 2011-2005		
Boxster; 2011-2005		
Carrera GT; 2006-2004		
Cayenne; 2011-2008		
Cayenne; 2006-2003		
Cayman; 2011-2006		
Panamera; 2011-2010		
	Rolls-Royce	
Phantom; 2010-2007		
	Volkswagen	
Phaeton; 2006-2004; W/315 MHz Sensor		
Touareg; 2007-2004		
Touareg 2; 2011-2008		
Touareg 2; 2011; W/315 MHz Sensor		
20040 (W/51mm Orange Insert)	Audi	
	A4; 2008-2002	
	A6; 2011-2005	
	A8; 2010-2001	
	Allroad Quattro; 2005-2001	
	Q7; 2011-2007	
	R8; 2011-2008	
	RS4; 2008-2007	
	S4; 2009-2004	
	S6; 2011-2007	
	S8; 2009-2007	
	S8; 2003-2001	
		Bentley
	Continental; 2010-2003	
		BMW
	128i; 2011-2008	
	135i; 2010-2008	
	320i; 2005-2001	
	323Ci; 2000	
	323i; 2010-2007	
323i; 2006; Jun. & Newer		

Part #	Model; Year; Sensor
20040 (W/51mm Orange Insert) - Continued	BMW - Continued
	323i; 2000
	325Ci; 2006-2001
	325i; 2006-2001
	325Xi; 2006-2001
	328Ci; 2000
	328i; 2011-2007
	328i; 2000
	328Xi; 2008-2007
	330Ci; 2006-2001
	330i; 2006-2001
	330Xi; 2006-2001
	335D; 2011-2009
	335i; 2011-2007
	335Xi; 2008-2007
	525i; 2007-2001
	525Xi; 2007-2006
	528i; 2010-2008
	528i; 2000-1997
	528Xi; 2008
	530i; 2007-2001
	530Xi; 2007-2006
	535i; 2011-2008
	535Xi; 2008
	540i; 2003-1997
	545i; 2005-2004
	550i; 2011-2006
	645Ci; 2005-2004
	650i; 2010-2006
	740i; 2011
	740i; 2001-1997
	740iL; 2001-1997
	740Li; 2011
	745i; 2005-2002
	745Li; 2005-2002
	750i; 2011-2006
	750iL; 2001-1997
	750Li; 2011-2006
	760i; 2006-2004
	760Li; 2010
760Li; 2008-2003	
Alpina B7; 2011	
Alpina B7; 2008-2007	
M3; 2010-2008	
M3; 2006-2001	
M5; 2010-2006	
M5; 2003-2000	
M6; 2010-2006	
X3; 2010-2006	
X5; 2011-2000	
X6; 2010-2008	
Z3; 2002-2000	
Z4; 2011-2003	
Z8; 2003-2000	
	Bugatti
Veyron; 2006	

Part #	Model; Year; Sensor	
20040 (W/51mm Orange Insert) - Continued	Ferrari	
	550 Maranello; 2002-2001	
	575M Maranello; 2005-2002	
	612 Scaglietti; 2009-2004	
	Enzo; 2004-2003	
	F430; 2009-2005	
		Land Rover
	LR3; 2005	
	Range Rover; 2005-2002	
		Maserati
	Coupe; 2006-2004	
	Gransport; 2006-2004	
	MC12; 2006	
	Quattroporte; 2006-2004	
	Spyder; 2006-2004	
		Mercedes-Benz
	CL55; 2006-2001	
	CL65; 2006-2005	
	CL500; 2006-2000	
	CL600; 2006-2001	
	E55; 2005-2000	
	E55; 1999; Jul. & Newer	
	E320; 2005-2001	
	E430; 2002-2001	
	E500; 2005-2003	
	R550; 2008	
	S55; 2006-2001	
	S65; 2006	
	S350; 2006	
	S430; 2006-2000	
	S500; 2006-2000	
	S600; 2006-2001	
	SL55; 2005-2003	
	SL65; 2005	
	SL500; 2005-2001	
	SL600; 2005-2004	
	SL600; 2002-2001	
	SLR McLaren; 2007-2004	
		Mini
	Cooper; 2010-2008	
	Porsche	
911; 2011-2005		
Boxster; 2011-2005		
Carrera GT; 2006-2004		
Cayenne; 2011-2008		
Cayenne; 2006-2003		
Cayman; 2011-2006		
Panamera; 2011-2010		
	Rolls-Royce	
Rolls-Royce; Phantom; 2010-2007		
	Volkswagen	
Phaeton; 2006-2004; W/315 MHz Sensor		
Touareg; 2007-2004		
Touareg 2; 2011-2008		
Touareg 2; 2011; W/315 MHz Sensor		

Application guides subject to change without notice. Please refer to the manufacturer's websites for the most up-to-date application data.

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Acura	CSX	08-09	35	TRW	—	—	1212	2040K	Lt Blue	42753-SNA-A83
	MDX	04-06	35	TRW	—	—	1057	2000K	Yellow	06421-S3V-A04
	MDX	07-11	35	Pacific	—	—	1209	1100K	Purple	42753-STK-A04
	RDX	07-11	35	Pacific	—	—	1209	1100K	Purple	42753-STK-A04
	RL	05-08	35	TRW	—	—	1057	2000K	Yellow	06421-S3V-A04
	RL	09-11	35	TRW	—	—	1057	2040K or 2000K	Lt Blue Yellow	42753-SHJ-A53
	TL	05-08	35	TRW	—	—	1057	2000K	Yellow	06421-S3V-A04
	TL (Hi-Line)	09-12	35	TRW	—	—	1214	2040K	Lt Blue	42753-TK4-A01
	TSX	07-11	35	Pacific	—	—	1220	1100K	Purple	42753-TL2-A52
	ZDX (Hi-Line)	10-11	35	TRW	—	—	1214	2040K	Lt Blue	42753-TK4-A01
Audi	Allroad (315 Mhz)	01-05	35	Beru	—	—	9004	1090K	Gray	4D0 907 275A
	A6 Allroad (433 Mhz)	01-06	35	Beru	—	—	9001	1090K	Gray	4D0 907 275C
	A6 Allroad (433 Mhz)	07-09	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B
	A6 Allroad(433 Mhz) Post June 2009	10	35	Beru	—	—	9011	1090K	Gray	4F0 907 275D
	A3 (315 Mhz)	06-11	71	Siemens	—	—	1053	1030K	Orange	1K0907253D
	A4 (433 Mhz)	02-08	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B
	A4 (315 Mhz)	09-11	71	Continental	—	—	1053	1030K	Orange	1K0907253D
	A5 (315 Mhz)	08-11	71	Siemens	—	—	1053	1030K	Orange	1K0907253D
	A6 (315 Mhz)	02-04	35	Beru	—	—	9004	1090K	Gray	4D0 907 275A
	A6 (433 Mhz)	05-09	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B
	A6 (433 Mhz) Post June 2009	10-11	35	Beru	—	—	9011	1090K	Gray	4F0 907 275D
	A8 (315 Mhz)	00-07	35	Beru	—	—	9004	1090K	Gray	4D0 907 275A
	A8 (433 Mhz)	00-11	35	Beru	—	—	9001	1090K	Gray	4D0 907 275C
	Q5 (315 Mhz)	09-11	71	Continental	—	—	1053	1030K	Orange	1K0907253D
	Q7 (433 Mhz)	05-09	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B
	Q7 (433 Mhz) Post June 2009	10-11	35	Beru	—	—	9011	1090K	Gray	4F0 907 275D
	R8 (433 Mhz)	08-09	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B
	R8 (433 Mhz) Post June 2009	10-11	35	Beru	—	—	9011	1090K	Gray	4F0 907 275D
	RS4 (433 Mhz)	07-09	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B
	RS6 (315 Mhz)	01-05	35	Beru	—	—	9004	1090K	Gray	4D0 907 275A
	RS6 (433 Mhz)	01-05	35	Beru	—	—	9001	1090K	Gray	4D0 907 275C
	S4 (433 Mhz)	02-08	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B
	S4 (315 Mhz)	10-11	71	Siemens	—	—	1053	1030K	Orange	1K0907253D
	S5 (315 Mhz)	08-11	71	Siemens	—	—	1053	1030K	Orange	1K0907253D
	S6 (433 Mhz)	04-09	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B
	S6 (433 Mhz) Post June 2009	10-11	35	Beru	—	—	9011	1090K	Gray	4F0 907 275D
	S8 (315 Mhz)	01-07	35	Beru	—	—	9004	1090K	Gray	4D0 907 275A
	S8 (433 Mhz)	00-09	35	Beru	—	—	9001	1090K	Gray	4D0 907 275C
	TT (315 Mhz)	08-11	71	Siemens	—	—	1053	1030K	Orange	1K0907253D

DILL 2011 TPMS APPLICATION **GUIDE**

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Bentley	Continental GT (433 Mhz)	03-05	35	Beru	—	—	9001	1090K	Gray	4D0 907 275C
	Continental GT(433 Mhz) <i>Post May</i>	05-11	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B
	Azure (433 Mhz)	07-09	35	Beru	—	—	9007	1090K	—	4F0 907 275B
	Mulsanne (433 Mhz)	11-12	35	Beru	—	—	9007	1090K	—	4F0 907 275B
	Flying Spur (433 Mhz)	05-10	35	Beru	—	—	9007	1090K	—	4F0 907 275B
BMW	1 Series (433 Mhz)	07-11	35	Beru	—	—	1027	1090K	Gray	36 23 6 781 847
	1 Series (433 Mhz) <i>September 2010</i>	11	35	Beru	—	—	9012	2000K	Gray	36 10 6 790 054
	3 Series (315 Mhz)	00-02	35	Beru	—	—	9004	1090K	Gray	36 11 8 378 681
	3 Series (433 Mhz)	00-04	35	Beru	—	—	9002	1090K	Gray	36 11 8 378 682
	3 Series (433 Mhz)	07-10	35	Beru	—	—	1027	1090K	Gray	36 23 6 781 847
	3 Series (433 Mhz) <i>September 2009</i>	10-11	35	Beru	—	—	9012	2000K	Gray	36 10 6 790 054
	5 Series (315 Mhz)	00-02	35	Beru	—	—	9004	1090K	Gray	36 11 8 378 681
	5 Series (433 Mhz)	02-05	35	Beru	—	—	9002	1090K	Gray	36 11 8 378 682
	5 Series (433 Mhz)	06-11	35	Beru	—	—	1027	1090K	Gray	36 23 6 781 847
	5 Series (433 Mhz) <i>September 2010</i>	11	35	Beru	—	—	9012	2000K	Gray	36 10 6 790 054
	6 Series (433 Mhz)	06-10	35	Beru	—	—	1027	1090K	Gray	36 23 6 781 847
	7 Series (315 Mhz)	00-01	35	Beru	—	—	9004	1090K	Gray	36 11 8 378 681
	7 Series (433 Mhz)	02-05	35	Beru	—	—	9002	1090K	Gray	36 11 8 378 682
	7 Series (433 Mhz)	06-11	35	Beru	—	—	1027	1090K	Gray	36 23 6 781 847
	7 Series (433 Mhz) <i>September 2010</i>	11	35	Beru	—	—	9012	2000K	Gray	36 10 6 790 054
	M Series (433 Mhz)	06-10	35	Beru	—	—	1027	1090K	Gray	36 23 6 781 847
	M Series (433 Mhz) <i>September 2009</i>	10-11	35	Beru	—	—	9012	2000K	Gray	36 10 6 790 054
	X3 (433 Mhz)	06-10	35	Beru	—	—	1027	1090K	Gray	36 23 6 781 847
	X3 (433 Mhz)	11	35	Beru	—	—	9012	2000K	Gray	36 10 6 790 054
	X5 (433 Mhz)	01-04	35	Beru	—	—	9003	1090K	Gray	36 14 6 752 128
	X5 (433 Mhz)	05-11	35	Beru	—	—	1027	1090K	Gray	36 23 6 781 847
	X5 (433 Mhz) <i>October 2010</i>	11	35	Beru	—	—	9012	2000K	Gray	36 10 6 790 054
	X6 (433 Mhz)	08-11	35	Beru	—	—	1027	1090K	Gray	36 23 6 781 847
	X6 (433 Mhz) <i>October 2010</i>	11	35	Beru	—	—	9012	2000K	Gray	36 10 6 790 054
	Z Series (433 Mhz)	06-10	35	Beru	—	—	1027	1090K	Gray	36 23 6 781 847
	Z Series (433 Mhz) <i>September 2009</i>	10-11	35	Beru	—	—	9012	2000K	Gray	36 10 6 790 054
Bugatti	Alpina (433 Mhz)	04-08	35	Beru	—	—	9002	1090K	Gray	36 11 8 378 682
	Veyron	05-06	NA	Beru	—	—	NA	1090K	Gray	NA
Buick	Allure	07-08	80	Siemens	7001	7020K	1047	1050K	White	15921013
	Allure	09	—	Schrader	7001	7020K	9153	VS950	NA	12768826
	Enclave	08	80	Siemens	7001	7020K	1047	1050K	White	15921013
	Enclave	09-12	—	Schrader	7001	7020K	9153	VS950	NA	20923680
	LaCrosse	07-08	80	Siemens	7001	7020K	1047	1050K	White	15921013
	LaCrosse	09-12	—	Schrader	7001	7020K	9153	VS950	NA	12768826
	Lesabre	07	—	Schrader	7001	7020K	9153	VS950	NA	25799331
	Lucerne	07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	Ranier	06-07	62	Schrader	7001	7020K	9116	1070K	Blue	25774006
	Ranier	07	—	Schrader	7001	7020K	9153	VS950	NA	25799331
Regal	11-12	—	Schrader	7001	7020K	9153	VS950	NA	12768826	
Cadillac	CTS	04-07	62	Schrader	7001	7020K	9116	1070K	Blue	25774006
	CTS	08-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	CTS-V	09-11	—	Schrader	7001	7020K	1047	1050K	White	15268606
	Deville	01-05	62	Schrader	—	—	9117	1080K	Green	25773946

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Cadillac - Continued	DTS	06	80	Schrader	7001	7020K	1047 *	1050K or 1070K	White Blue	15268606
	DTS	07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	Escalade-ESV-EXT	04	62	Schrader	—	—	9115	1070K	Blue	15136883
	Escalade-ESV-EXT	05-06	62	Schrader	—	—	9107	1070K	Blue	15114379
	Escalade-ESV-EXT	07	62	TRW	7001	7020K	NA	2020K	Pink	15825475
	Escalade-ESV-EXT	07	80	Siemens	7001	7020K	1047	1050K	White	TRW Sensor Replacement
	Escalade-ESV-EXT	07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	Seville	01-04	62	Schrader	—	—	9117	1080K	Green	25773946
	SRX	04-06	62	Schrader	7001	7020K	9116	1070K	Blue	25774006
	SRX	07-11	—	Schrader	7001	7020K	9153	VS950	NA	12768826
	STS	05-09	62	Schrader	7001	7020K	9076	1070K	Blue	25758220
	STS	09	80	Schrader	7001	7020K	1047 *	1050K or 1070K	White Blue	15268606
	STS	09-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	XLR	04-09	62	Schrader	7001	7020K	9076	1070K	Blue	25758220
	Chevrolet	Avalanche	04	62	Schrader	—	—	9115	1070K	Blue
Avalanche		05-06	62	Schrader	—	—	9107	1070K	Blue	15114379
Avalanche		07	62	TRW	7001	7020K	NA	2020K	Pink	15825475
Avalanche		07	80	Siemens	7001	7020K	1047	1050K	White	TRW Sensor Replacement
Avalanche		07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
Aveo		07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
Camaro		10-12	—	Schrader	7001	7020K	9153	VS950	NA	12768826
Cobalt		08-10	80	Siemens	7001	7020K	1047	1050K	White	15268606
Cobalt		08-10	—	Schrader	7001	7020K	9153	VS950	NA	12768826
Colorado		07-12	62	Schrader	—	—	9131	1110K	Teal	15122618
Corvette		97-00	62	Schrader	—	—	8006	1077K	Lt Blue	10438853
Corvette-C5-Z6		01-04	62	Schrader	—	—	9117	1080K	Green	25773946
Corvette-C6		05-09	62	Schrader	7001	7020K	9076	1070K	Blue	25758220
Corvette		10-11	80	Schrader	7001	7020K	1047 *	1050K or 1070K	White Blue	15268606
Cruze		11	—	Schrader	7001	7020K	9153	VS950	NA	12768826
Equinox		07-09	80	Siemens	7001	7020K	1047	1050K	White	15921013
Equinox		10-11	—	Schrader	7001	7020K	9153	VS950	NA	12768826
Express Series		08-09	80	Siemens	7001	7020K	1047	1050K	White	15921013
Express Series (1500)		10-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
Express Series (2500/3500)		10-11	—	Schrader	—	—	9153	VS950	—	25920615
G Series		08	80	Siemens	7001	7020K	1047	1050K	White	15921013
HHR		08-09	80	Schrader	7001	7020K	1047 *	1050K or 1070K	White Blue	15268606
HHR		08-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
Impala		06-07	80	Schrader	7001	7020K	1047 *	1050K or 1070K	White Blue	15268606
Impala		07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
Malibu <10/14/07		08	80	Siemens	7001	7020K	1047	1050K	White	15921013
Malibu		08-11	—	Schrader	7001	7020K	9153	VS950	NA	12768826

* The 1050K is to be used on the Siemens sensors
& the 1070K is to be used on the Schrader sensors.

DILL 2011 TPMS APPLICATION **GUIDE**

Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Monte Carlo	06-07	80	Schrader	7001	7020K	1047 *	1050K or 1070K	White	15268606
								Blue	
Monte Carlo	07	—	Schrader	7001	7020K	9153	VS950	NA	25920615
Silverado	04	62	Schrader	—	—	9115	1070K	Blue	15136883
Silverado	05-06	62	Schrader	—	—	9107	1070K	Blue	15114379
Silverado	07	62	TRW	7001	7020K	NA	2020K	Pink	15825475
Silverado	07	80	Siemens	7001	7020K	1047	1050K	White	TRW Sensor Replacement
Silverado (1500)	07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
Silverado (2500/3500)	07-11	—	Schrader	—	—	9153	VS950	NA	25920615
Sonic	12	—	Schrader	7001	7020K	9153	VS950	NA	20922900
SSR	06-07	62	Schrader	7001	7020K	9116	1070K	Blue	25774006
Suburban	04	62	Schrader	—	—	9115	1070K	Blue	15136883
Suburban	05-06	62	Schrader	—	—	9107	1070K	Blue	15114379
Suburban	07	62	TRW	7001	7020K	NA	2020K	Pink	15825475
Suburban	07	80	Siemens	7001	7020K	1047	1050K	White	TRW Sensor Replacement
Suburban (1500)	07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
Suburban (2500)	07-11	—	Schrader	—	—	9153	VS950	NA	25920615
Tahoe	04	62	Schrader	—	—	9115	1070K	Blue	15136883
Tahoe	05-06	62	Schrader	—	—	9107	1070K	Blue	15114379
Tahoe	07	62	TRW	7001	7020K	NA	2020K	Pink	15825475
Tahoe	07	80	Siemens	7001	7020K	1047	1050K	White	TRW Sensor Replacement
Tahoe	07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
Trailblazer	06-09	62	Schrader	7001	7020K	9116	1070K	Blue	25774006
Traverse	09-11	62	Schrader	7001	7020K	9153	VS950	NA	25920615
Uplander	08-09	80	Schrader	7001	7020K	1047 *	1050K or 1070K	White	15268606
								Blue	
Volt	10-11	—	Schrader	7001	7020K	9153	VS950	NA	12768826
200	11-12	71	Continental	7001	7020K	1051	7020K	—	68078861AA
300	05-07	71	Siemens	7001	7020K	1051	1050K	White	68111696AA
300 (433 Mhz)	08	71	Continental	7004	7020K	1043	1050K	White	68001698AB
300 (433 Mhz)	09-12	53	Schrader	—	—	9214	2030K	Lt Grey	56029400AD
300 (Alloy)	10-12	—	Schrader	—	—	9398	VS950	NA	56029398AB
300M (433 Mhz)	02-04	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
Aspen	07-09	71	Schrader	7001	7020K	1051 **	1050K or 2030K	White	56029465AB
								Lt Grey	
Concorde (433 Mhz)	02-04	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
Crossfire (433 Mhz)	04-05	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
Crossfire	05	35	Schrader	7001	7020K	1051 **	1050K or 2030K	White	56053030AB
								Lt Grey	
Crossfire (433 Mhz)	06-08	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
Crossfire	06-08	71	Siemens	7001	7020K	1051	1050K	White	56053030AB
Pacifica (433 Mhz)	04	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
Pacifica	04-05	71	Siemens	7001	7020K	1052	1050K	White	04727392AB
Pacifica	06-08	71	Siemens	7001	7020K	1051	1050K	White	68001696AB
Prowler	01	35	Schrader	—	—	8004	1080K	—	4815132AB
Prowler (433 Mhz)	02	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
PT Cruiser	08-10	71	Siemens	7001	7020K	1051	1050K	White	68001696AB
Sebring (433 Mhz)	08-09	71	Continental	7004	7020K	1043	1050K	White	68001698AB

Chevrolet - Continued

Chrysler

* The 1050K is to be used on the Siemens sensors & the 1070K is to be used on the Schrader sensors.

** The 1050K is to be used on the Siemens sensors & the 2030K is to be used on the Schrader sensors.

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Chrysler - Continued	Sebring (315 Mhz)	07-10	71	Siemens	7001	7020K	1051	1050K	White	68001696AB
	Sebring (315 Mhz)	10	71	Continental	7001	7020K	1051	7000K	—	68078861AA
	Town & Country (433 Mhz)	02-03	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
	Town & Country	04-05	71	Siemens	7001	7020K	1052	1050K	White	04727392AB
	Town & Country	06-08	71	Siemens	7001	7020K	1051	1050K	White	56053030AB
	Town & Country (433 Mhz)	08-10	71	Continental	7004	7020K	1043	1050K	White	68001698AB
	Town & Country (433 Mhz)	10	71	Continental	7004	7020K	1043	7000K	—	68078768AA
	Town & Country (433 Mhz)	11-12	—	Schrader	—	—	9398	VS950	—	56029398AB
	Voyager (433 Mhz)	02-03	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
Dodge	Avenger	08-10	71	Siemens	7001	7020K	1051	1050	White	68001696AB
	Avenger	10-12	71	Continental	7001	7020K	1051	7000K	—	68078861AA
	Caliber	07-10	71	Siemens	7001	7020K	1051	1050K	White	68001696AB
	Caliber	10-12	71	Continental	7001	7020K	1051	7000K	—	68078861AA
	Caliber	12	71	Continental	7004	7020K	1043	7000K	—	68078768AA
	Caravan (433 Mhz)	02-03	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
	Caravan	04-05	71	Siemens	7001	7020K	1052	1050K	White	04727392AB
	Caravan	06-07	71	Siemens	7001	7020K	1051	1050K	White	56053030AB
	Challenger (433 Mhz)	08	71	Continental	7004	7020K	1043	1050K	White	68001698AB
	Challenger-SRT (433 Mhz)	09-12	53	Schrader	—	—	9214	2030K	Lt Grey	56029400AD
	Challenger	10-12	—	Schrader	—	—	9398	VS950	NA	56029398AB
	Charger	06-07	71	Siemens	7001	7020K	1051	1050K	White	68001696AB
	Charger (433 Mhz)	08	71	Continental	7004	7020K	1043	1050K	White	68001698AB
	Charger-SRT (433 Mhz)	09-12	53	Schrader	—	—	9214	2030K	Lt Grey	56029400AC
	Charger (Alloy)	10-12	—	Schrader	—	—	9398	VS950	NA	56029398AB
	Dakota	08-10	53	Schrader	7001	7020K	9154	2030K	Lt Grey	56029319AC
	Dakota	11	—	Schrader	7001	7020K	9308	VS950	NA	56029479AA
	Dakota	11	71	Schrader	7001	7020K	1051	1050K	White	Sensor Replacement Only
	Durango	07-09	71	Schrader	7001	7020K	1051 **	1050K or 2030K	White Lt Grey	56029465AB
	Durango	11-12	—	Schrader	—	—	9398	VS950	NA	56029398AB
	Grand Caravan (433 Mhz)	02-03	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
	Grand Caravan	04-05	71	Siemens	7001	7020K	1052	1050K	White	04727392AB
	Grand Caravan	06-07	71	Siemens	7001	7020K	1051	1050K	White	56053030AB
	Grand Caravan (433 Mhz)	08-10	71	Continental	7004	7020K	1043	1050K	White	68001698AB
	Grand Caravan (433 Mhz)	10-11	71	Continental	7004	7020K	1043	7000K	—	68078768AA
	Grand Caravan	11-12	—	—	—	—	—	VS950	NA	56029398AB
	Intrepid (433 Mhz)	02-04	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
	Journey (433 Mhz)	09-10	71	Continental	7004	7020K	1043	1050K	White	68001698AB
	Journey (433 Mhz)	10-11	71	Continental	7004	7020K	1043	7000K	—	68078768AA
	Journey	12	—	—	—	—	—	VS950	NA	56029398AA
	Magnum	05-07	71	Siemens	7001	7020K	1051	1050K	White	68001696AB
	Magnum (433 Mhz)	08	71	Continental	7004	7020K	1043	1050K	White	68001698AB
	Magnum (433 Mhz)	09	53	Schrader	—	—	9214	2030K	Lt Grey	56029400AD
Nitro	07-11	71	Schrader	7001	7020K	1051 **	1050K or 2030K	White Lt Grey	56029465AB	
Nitro (Alloy)	10-11	—	Schrader	7001	7020K	9308	VS950	NA	56029479AA	
Nitro (Alloy)	10-11	—	Schrader	7001	7020K	1051	1050K	White	Sensor Replacement Only	

** The 1050K is to be used on the Siemens sensors & the 2030K is to be used on the Schrader sensors.

DILL 2011 TPMS APPLICATION **GUIDE**

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Dodge - Continued	Ram (HP-315 Mhz) 1500/2500	08-09	53	Schrader	—	—	9154	2030K	Lt Grey	56029319AC (Check VIN)
	Ram (433 Mhz) 1500	09	71	Continental	7004	7020K	1043	1050K	White	56029359AC
	Ram (433 Mhz) 1500/2500	10-11	—	Schrader	—	—	9398	VS950	NA	56029398AB
	Sprinter	07-10	54	Siemens	—	—	1042	1098K	Reddish/Purple	68038945AA
	Stratus	07	71	Siemens	7001	7020K	1051	1050K	White	56053030AB
	Viper (433 Mhz)	03-10	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
Ferrari	430 (433 Mhz)	06-07	—	Beru	—	—	9001	1090K	Gray	22 45 49
	430 (433 Mhz)	08-11	—	Beru	—	—	9007	1090K	Gray	23 92 98
	458 (433 Mhz)	10-11	—	Beru	—	—	9008	1090K	Gray	24 88 87
	550 (433 Mhz)	02-10	—	Beru	—	—	9001	1090K	Gray	22 45 49
	575 (433 Mhz)	02-06	—	Beru	—	—	9001	1090K	Gray	22 45 49
	575 (315 Mhz)	02-05	—	Beru	—	—	9004	1090K	Gray	22 45 48
	599	04-10	—	Beru	—	—	9001	1090K	Gray	22 45 49
	612 (433 Mhz)	04-10	—	Beru	—	—	9001	1090K	Gray	22 45 49
	California (433 Mhz)	10-11	—	Beru	—	—	9008	1090K	Gray	24 88 87
	Enzo (433 Mhz)	03-09	—	Beru	—	—	9005	1090K	Gray	22 45 51
	FXX (433 Mhz)	03-09	—	Beru	—	—	9005	1090K	Gray	22 45 51
	Spider (433 Mhz)	02-09	—	Beru	—	—	9001	1090K	Gray	22 45 49
	500	11-12	—	Schrader	—	—	9398	VS950	—	56029398AB
	Crown Victoria	06-11	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	E Series	07-09	—	Lear	—	—	1048-HP	NA	NA	8C2Z-1A189A
	E Series (HP)	10-12	—	Schrader	—	—	9315	VS950	NA	9L3Z-1A189-A
	Edge	07-10	—	Lear	7001	7020K	1048	NA	NA	7L1Z-1A189A
	Edge	11	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	Escape	06-08	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
Escape	09-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A	
Expedition (433 Mhz)	03-04	44	Schrader	*7004	7020K	9096	1060K	Rubine Red	4L2T1A150BA	
Expedition (315 Mhz)	05-06	44	Schrader	7001	7020K	9135	1060K	Rubine Red	5L1ZA150AB	
Expedition	07-10	—	Lear	7001	7020K	1048	NA	NA	7L1Z-1A189A	
Expedition	11-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A	
Explorer (433 Mhz)	02-05	44	Schrader	*7004	7020K	9096	1060K	Rubine Red	4L2T1A150BA	
Ford	Explorer	06-10	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	Explorer	11	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	Explorer Sport Trac	07-10	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	F 150	07-08	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	F 150	09-11	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	Fiesta	11-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	500	08-09	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	Flex	09-10	—	Lear	7001	7020K	1048	NA	NA	7L1Z-1A189A
	Flex	11-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	Focus	07-09	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A/ 7L1Z-1A189A
	Focus	10-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	Freestar (315 Mhz)	04-05	44	Schrader	7001	7020K	9135	1060K	Rubine Red	5L1ZA150AB
	Freestar	06-07	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	Fusion	07-09	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A

* Redi-Sensor relearn must be performed with scan tool and not magnet.

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Ford - Continued	Fusion	10-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	Mustang	07-09	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	Mustang	10-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	Ranger	07-11	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	Super Duty (250/350/450) Pre-June 2009	07-10	—	Lear	—	—	1048HP	NA	NA	8C2Z-1A189A
	Super Duty (250/350/450) Post-June 2009	10-12	—	Schrader	—	—	9315	VS950	NA	9L3Z-1A189-A
	Taurus Pre-May 2010	08-10	—	Lear	7001	7020K	1048	NA	NA	7L1Z-1A189A
	Taurus Post-May 2010	11-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	Taurus X	08-09	—	Lear	7001	7020K	1048	NA	NA	7L1Z-1A189A
Transit	10-11	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A	
GMC	Acadia	07-08	80	Siemens	7001	7020K	1047	1050K	White	15921013
	Acadia	09-12	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	Canyon	07-12	62	Schrader	—	—	9131	1110K	Teal	15122618
	Envoy	05-07	62	Schrader	7001	7020K	9116	1070K	Blue	25774006
	Envoy	07-09	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	Savana	08-09	80	Siemens	7001	7020K	1047	1050K	White	15921013
	Savana (1500)	10-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	Savana (2500/3500)	10-11	—	Schrader	—	—	9153	VS950	NA	25920615
	Sierra	04	62	Schrader	—	—	9115	1070K	Blue	15136883
	Sierra	05-06	62	Schrader	—	—	9107	1070K	Blue	15114379
	Sierra	07	62	TRW	7001	7020K	NA	2020K	Pink	15825475
	Sierra	07	80	Siemens	7001	7020K	1047	1050K	White	TRW Sensor Replacement
	Sierra (1500)	07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	Sierra (2500/3500)	07-11	—	Schrader	—	—	9153	VS950	NA	25920615
	Terrain	10-12	—	Schrader	7001	7020K	9153	VS950	NA	12768826
	Yukon	04	62	Schrader	—	—	9115	1070K	Blue	15136883
	Yukon	05-06	62	Schrader	—	—	9107	1070K	Blue	15114379
	Yukon	07	62	TRW	7001	7020K	NA	2020K	Pink	15825475
	Yukon	07	80	Siemens	7001	7020K	1047	1050K	White	TRW Sensor Replacement
	Yukon (1500)	07-11	—	Schrader	7001	7020K	9153	VS950	NA	25920615
Yukon (2500)	07-11	—	Schrader	—	—	9153	VS950	NA	25920615	
Honda	Accord	08-12	35	Pacific	—	—	1208	1100K	Purple	42753-SWA-315/316
	Civic	08-11	35	TRW	—	—	1212	2040K	Lt Blue	42753-SNA-A83
	Civic	12	35	TRW	—	—	1212	2040K	—	42753-TRO-A81
	CR-V	07-11	35	Pacific	—	—	1208	1100K	Purple	42753-SWA-315/316
	CR-Z	11	35	TRW	—	—	1212	2040K	Lt Blue	42753-SNA-A83
	Crosstour	10-11	71	Continental	—	7020K	5511	7000K	—	42753-TP6-A82
	Element	06-07	35	TRW	—	—	1058	2000K	Yellow	06421-SCV-A01
	Element	08	35	TRW	—	—	1058	2040K or 2000K	Lt Blue	42753-SHJ-A82
	Element	09-11	35	TRW	—	—	1212	2040K	Lt Blue	42753-SNA-A83
	Fit	08	35	Pacific	—	—	1208	1100K	Purple	42753-SWA-315/316
	Fit	09-12	35	TRW	—	—	1212	2040K	Lt Blue	42753-SNA-A83

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Honda - Continued	Insight	10-11	35	TRW	—	—	1212	2040K	Lt Blue	42753-SNA-A83
	Odyssey EX, EX-L, LX	06-07	35	TRW	—	—	1058	2000K	Yellow	06421-SCV-A00
	Odyssey EX, EX-L, LX	08-10	35	TRW	—	—	1058	2040K or 2000K	Lt Blue Yellow	42753-SHJ-A82
	Odyssey EX, EX-L, LX	11-12	35	TRW	—	—	1212	2040K	Lt Blue	42753-SNA-A83
	Odyssey Touring	05-07	35	TRW	—	—	1057	2000K	Yellow	06421-S3V-A04
	Odyssey Touring	08-10	35	TRW	—	—	1057	2040K or 2000K	Lt Blue Yellow	42753-SHJ-A53
	Odyssey Touring	11-12	35	TRW	—	—	1212	2040K	Lt Blue	42753-SNA-A83
	Pilot (Steel)-2.25"	05	35	TRW	—	—	1059	2000K	Yellow	06421-S9V-A02
	Pilot-1.75"	05-08	35	TRW	—	—	1057	2000K	Yellow	06421-S3V-A04
	Pilot	09-12	35	Pacific	—	—	1209	1100K	Purple	42753-STK-A04
	Pilot (Steel)	09-12	35	Pacific	—	—	1219	1100K	—	42753-SZA-A12
	Ridgeline (RT)-2.25"	06-08	35	TRW	—	—	1059	2000K	Yellow	06421-S9V-A02
	Ridgeline-1.75"	06-11	35	TRW	—	—	1057	2000K	Yellow	06421-S3V-A04
	Ridgeline (Alloy)	09-11	35	TRW	—	—	1057	2040K or 2000K	Lt Blue Yellow	42753-SHJ-A53
S2000	08-09	35	Pacific	—	—	1221	1100K	Purple	42753-S2A-315	
Hummer	H2	08-09	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	H3	06-10	62	Schrader	—	—	9131	1110K	Teal	15122618
	H3T	09-10	62	Schrader	—	—	9131	1110K	Teal	15122618
Hyundai	Accent (Lo-Line)	08-11	31-40	TRW	1206-A	1100K	1029**	2040K	Lt Blue	52933-2F000
	Accent	12	71	Continental	7001	7020K	5507	7020K	—	52933-2M000
	Azera	07-11	31-40	Beru	—	—	1068	2000K	Yellow	52933-2G200
	Elantra	07-10	31-40	Beru	—	—	1068	2000K	Yellow	52933-2G200
	Elantra (Post Nov)	11-12	—	TRW	—	—	NEW	—	—	52933-3X200
	Elantra (Touring)	10-12	71	Continental	7001	7020K	5507	1050K or 7020K	White	52933-2L500 or 52933-2M000
	Entourage	07-10	31-40	Beru	—	—	1028	2000K	Yellow	52933-4D200
	Equus (Hi-Line)	11	31-40	TRW	—	1100K	1029	2040K	Lt Blue	52933-2F000
	Genesis (Hi-line)	09-12	31-40	TRW	—	1100K	1029	2040K	Lt Blue	52933-2F000
	Genesis Coupe	10-12	71	Continental	7001	7020K	5507	7020K	White	52933-2M000
	Santa Fe Thru July 2007	07-08	31-40	Beru	—	—	1028	2000K	Yellow	52933-4D200
	Santa Fe Thru September 2009	08-10	31-40	Beru	—	—	1068	2000K	Yellow	52933-2G200
	Santa Fe October 2009	10-12	11	Lear	—	—	NEW	VS1010	—	52933-0W100
	Santa Fe October 2009	10-12	31-40	—	—	—	1068	2000K	—	Sensor Replacement Only
	Sonata	07-08	31-40	TRW	—	—	1058	2000K	Yellow	52933-3E000
	Sonata (Lo-Line) Late '08 Builds	08-10	31-40	TRW	1206-A	1100K	1029**	2040K	Lt Blue	52933-2F000
	Sonata	11-12	71	Continental	7001	7020K	5507	7020K	White	52933-2M000
	Tiburon	07-08	31-40	TRW	—	—	1058	2000K	Yellow	52933-3E000
	Tucson	07-10	31-40	TRW	—	—	1058	2000K	Yellow	52933-3E000
	Tucson	10-12	31-40	TRW	1206-A	1100K	1029	2040K	Lt Blue	52933-2F000
Velostar	12	—	—	—	—	NEW	—	—	52933-2V00	
Veracruz	06-08	31-40	Beru	—	—	1028	2000K	Yellow	52933-4D200	
Veracruz	08-11	31-40	Beru	—	—	1068	2000K	Yellow	52933-2G200	

Note: Use "TRW LoLine Fxd Dly" function on BarTec 400 or 400P to program the sensors.

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #	
Infiniti	EX35	08-10	66	Pacific	*7001	7020K	9204	2030K	Lt Grey	40700-JK00C	
	EX35	11-12	—	Pacific	—	—	1216	1100K	—	40700-1LA0C	
	FX35 <i>Pre-June</i>	03-07	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001	
	FX35 <i>Post-June</i>	07-10	66	Pacific	*7001	7020K	9204	2030K	Lt Grey	40700-JK00C	
	FX35	11	—	Pacific	—	—	1216	1100K	—	40700-1LA0C	
	FX45 <i>Pre-June</i>	03-07	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001	
	FX45 <i>Post-June</i>	07-08	66	Pacific	*7001	7020K	9204	2030K	Lt Grey	40700-JK00C	
	FX50	09-10	66	Pacific	*7001	7020K	9204	2030K	Lt Grey	40700-JK00C	
	FX50	11	—	Pacific	—	—	1216	1100K	—	40700-1LA0C	
	G25	11-12	—	Pacific	—	—	1216	1100K	—	40700-1LA0C	
	G35	03-06	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001	
	G35	07-08	66	Pacific	*7001	7020K	9204	2030K	Lt Grey	40700-JK00C	
	G37	08-10	66	Pacific	*7001	7020K	9204	2030K	Lt Grey	40700-JK00C	
	G37	11-12	—	Pacific	—	—	1216	1100K	—	40700-1LA0C	
	M35	06-07	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001	
	M35	08-10	66	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0C	
	M37	11-12	—	Pacific	—	—	1216	1100K	—	40700-1LA0C	
	M45	03-07	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001	
	M45	08-10	66	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0C	
	M56	11	—	Pacific	—	—	1216	1100K	—	40700-1LA0C	
	Q45 <i>Pre-July</i>	03-06	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001	
	Q45 <i>Post-August</i>	06	66	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-JA01B	
	QX4	03	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001	
	QX56 (Steel)	05-06	49	Schrader	—	—	9069	1130K	Burgundy	40700-CK002	
	QX56 (Alloy)	04-07	49	Schrader	—	—	9161	1080K	Green	40700-CK001	
	QX56 <i>Post-April</i>	07-10	66	Pacific	*7001	7020K	9204	2030K	Lt Grey	40700-JK00C	
	Q56	11-12	—	Pacific	—	—	1216	1100K	—	40700-1LA0C	
	Isuzu	Ascender	06-08	62	Schrader	7001	7020K	9116	1070K	Blue	25774006
		I-290	07-08	62	Schrader	—	—	9131	1110K	Teal	15122618
		I-370	07-08	62	Schrader	—	—	9131	1110K	Teal	15122618
		Rodeo (433 Mhz)	04	35	Schrader	7004	7020K	9028	1080K	Green	52088990AC
	Jaguar	S (315 Mhz)	05-09	71	Siemens	—	7020K	1055	1050K	White	C2Z15017
S (433 Mhz)		05-09	71	Siemens	—	7020K	1046	1050K	White	C2Z15016	
XF (315 Mhz)		09-10	71	Siemens	—	7020K	1055	1050K	White	C2Z15017	
XF (315 Mhz)		10-12	71	Continental	—	7020K	1055	7020K	—	C2Z15017	
XF (433 Mhz)		09-10	71	Siemens	—	7020K	1046	1050K	White	C2Z15016	
XF (433 Mhz)		10-11	71	Continental	—	7020K	1046	7020K	—	C2Z15016	
XJ (315 Mhz)		04-10	71	Siemens	—	7020K	1055	7020K	—	C2Z15017	
XJ (315 Mhz)		10-11	71	Continental	—	7020K	1055	7020K	—	C2Z15017	
XJ (433 Mhz)		04-10	71	Siemens	—	7020K	1046	1050K	White	C2Z15016	
XJ (433 Mhz)		10-11	71	Continental	—	7020K	1046	7020K	—	C2Z15016	
XK (315 Mhz)		05-10	71	Siemens	—	7020K	1055	7020K	—	C2Z15017	
XK (315 Mhz)		10-12	71	Continental	—	7020K	1055	7020K	—	C2Z15017	
XK (433 Mhz)		07-10	71	Siemens	—	7020K	1046	1050K	White	C2Z15016	
XK (433 Mhz)		10-11	71	Continental	—	7020K	1046	7020K	—	C2Z15016	

* Utilize the ATEQ VT-55 or Bartec OBD-enabled tools (Rev 45) for the vehicle relearn.

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Jeep	Commander	06-07	71	Siemens	7001	7020K	1051	1050K	White	56029465AB
	Commander (433 Mhz)	08-10	71	Schrader	7004	7020K	1043**	1050K or 2030K	White Lt Grey	56029359AB
	Compass	07-10	71	Siemens	7001	7020K	1051	1050K	White	68001696AB
	Compass	10-11	71	Continental	7001	7020K	1051	7000K	—	68078861AA
	Grand Cherokee (433 Mhz)	02-04	64	Schrader	7004	7020K	9028	1080K	Green	52088990AC
	Grand Cherokee	05-07	71	Siemens	7001	7020K	1051	1050K	White	68001696AB
	Grand Cherokee (433 Mhz)	08-10	71	Schrader	7004	7020K	1043**	1050K or 2030K	White Lt Grey	56029359AB
	Grand Cherokee	11	—	Schrader	—	—	9398	VS950	NA	56029398AA
	Liberty (433 Mhz)	04	64	Schrader	7004	7020K	9028	1080K	Green	52088990AC
	Liberty	05-06	71	Siemens	7001	7020K	1051	1050K	White	56029465AB
	Liberty	07-08	71	Schrader	7001	7020K	1051**	1050K or 2030K	White Lt Grey	56029465AB
	Liberty (433 Mhz)	09	71	Schrader	7004	7020K	1043**	1050K or 2030K	White Lt Grey	56029359AB
	Liberty	10	—	Schrader	7001	7020K	1051	1050K	White	68001696AA
	Liberty	10-11	—	Schrader	7001	7020K	9308	VS950	NA	56029479AA
	Liberty	12	—	Schrader	—	—	9481	VS950	NA	56029481AB
	Patriot	07-10	71	Siemens	7001	7020K	1051	1050K	White	68001696AB
	Patriot	10-11	71	Continental	7001	7020K	1051	7000K	—	68078861AA
	Wrangler (Alloy)	07-09	71	Schrader	7001	7020K	1051**	1050K or 2030K	White Lt Grey	56029465AB
	Wrangler	10	—	Schrader	7001	7020K	9308	VS950	NA	56029479AA
	Wrangler (433 Mhz)	11	—	Schrader	—	—	9481	VS950	NA	56029481AB
KIA	Amanti	07-08	31-40	TRW	—	—	1057	2000K	Yellow	52933-1FA00
	Amanti	09	31-40	TRW	—	—	1058	2000K	Yellow	52933-3E000
	Borrego (Lo-Line)	09	31-40	TRW	1206-A	1100K	1029**	2040K	Lt Blue	52933-2F000
	Forte	10-12	71	Continental	7001	7020K	5507	7020K	White	52933-1M000
	Magentis	08-10	31-40	Beru	—	—	1068	2000K	Yellow	52933-2G200
	Mohave	09	31-40	TRW	1206-A	1100K	1029**	2040K	Lt Blue	52933-2F000
	Optima (Lo-Line)	06-10	31-40	Beru	—	—	1068	2000K	Yellow	52933-2G200
	Optima	11	71	Continental	7001	7020K	5507	7020K	White	52933-2M000
	Rio (Lo-Line)	08-11	31-40	TRW	1206-A	1100K	1029**	2040K	Lt Blue	52933-2F000
	Rio 5 (Lo-Line) Post 7/2/07	08-11	31-40	TRW	1206-A	1100K	1029**	2040K	Lt Blue	52933-2F000
	Rondo (Lo-Line)	07-09	31-40	Beru	—	—	1068	2000K	Yellow	52933-2G200
	Sedona (Hi-Line)	06-08	31-40	Beru	—	—	1028	2000K	Yellow	52933-4D200
	Sedona (Lo-Line)	09-12	31-40	Beru	—	—	1068	2000K	Yellow	52933-2G200
	Sorento	05-09	31-40	TRW	—	—	1057	2000K	Yellow	52933-1FA00
	Sorento	09	31-40	TRW	—	—	1058	2000K	Yellow	52933-3E000
	Sorento	11-12	71	Continental	7001	7020K	5507	7020K	White	52933-2M000
	Soul	10-12	71	Continental	7001	7020K	5507	7020K	White	52933-2M000
	Spectra-5 (Lo-Line)	07-09	31-40	TRW	1206-A	1100K	1029**	2040K	Lt Blue	52933-2F000
	Sportage	06-08	31-40	TRW	—	—	1058	2000K	Yellow	52933-3E000
	Sportage (Lo-Line)	09-12	31-40	TRW	1206-A	1100K	1029**	2040K	Lt Blue	52933-2F000
Tuscany	07-08	31-40	TRW	—	—	1058	2000K	Yellow	Enhanced/Basic	
Land Rover	LR2 (315 Mhz)	08-09	71	Siemens	—	—	1045	1050K	White	—
	LR2 (315 Mhz)	11	71	Continental	—	—	1045	1050K or 7020K	—	LR021936
	LR3 (433 Mhz)	11	71	Continental	—	—	1046	7020K	—	LR018861

Note: Use "TRW LoLine Fxd Dly" function on BarTec 400 or 400P to program the sensors.

** The 1050K is to be used on the Siemens sensors & the 2030K is to be used on the Schrader sensors.

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Land Rover - Continued	LR3 (433 Mhz)	02-05	58	Beru	—	—	9003	1090K	Gray	YDB 0000 60
	LR3 (315 Mhz)	06-09	71	Siemens	—	—	1055	1050K	White	LR018860
	LR3 (433 Mhz)	06-09	71	Siemens	—	—	1046	1050K	White	LR018861
	LR4 (315 Mhz)	10-11	71	Continental	—	—	1045	1050K or 7020K	White	LR021936
	LR4 (433 Mhz)	11	71	Continental	—	—	1046	1050K	White	LR018861
	Range Rover (315 Mhz)	06-09	71	Siemens	—	—	1055	1050K	White	LR018860
	Range Rover (315 Mhz)	10-11	71	Continental	—	—	1045	1050K or 7020K	White	LR021936
	Range Rover (433 Mhz)	06-09	71	Siemens	—	—	1046	1050K	White	LR018861
	Range Rover (433 Mhz)	10-11	71	Continental	—	—	1046	7020K	White	LR018861
	Range Rover Sport (315 Mhz)	06-09	71	Siemens	—	—	1055	1050K	White	LR021936
	Range Rover Sport (315 Mhz)	10-11	71	Continental	—	—	1045	1050K or 7020K	White	LR021936
	Range Rover Sport (433 Mhz)	06-09	71	Siemens	—	—	1046	1050K	White	LR018861
	Range Rover Sport (433 Mhz)	10-11	71	Continental	—	—	1046	7020K	White	LR018861
Lexus	CT	11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33021
	ES	07-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33021
	GS	05-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33021
	GX470	04-06	35	Pacific	1204-A	1100K	1205	1110K	Teal	42607-35010
	GX	06-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33021
	HS Series	10	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-75010
	IS Series	06-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33021
	LS	07-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33021
	LX	05-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33021
	RX	06-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33021
	SC430	02-07	27	Pacific			NA	1120K	Gold	42607-24040
	SC	07-10	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33021
	Aviator (433 Mhz)	03-05	44	Schrader	*7004	7020K	9096	1060K	Rubine Red	4L2T1A150-BA
Lincoln	Mark LT	07-08	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	MKS	09-10	—	Lear	7001	7020K	1048	NA	NA	7L1Z-1A189A
	MKS	11-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	MKT	10	—	Lear	7001	7020K	1048	NA	NA	7L1Z-1A189A
	MKT	11-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	MKX	07-10	—	Lear	7001	7020K	1048	NA	NA	7L1Z-1A189A
	MKX	11	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	MKZ	07-09	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	MKZ	10-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
	Navigator (433 Mhz)	03-04	44	Schrader	*7004	7020K	9096	1060K	Rubine Red	4L2T1A150-BA
	Navigator (315 Mhz)	05-06	44	Schrader	7001	7020K	9135	1060K	Rubine Red	5L1Z1A150-AB
	Navigator	07-10	—	Lear	7001	7020K	1048	NA	NA	7L1Z-1A189A
	Navigator	11-12	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
Town Car	06-11	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A	
Maserati	Quattroporte Thru December	04-09	35	Beru	—	—	9001	1090K	—	22 45 49
	Quattroporte Post January	10-11	35	Beru	—	—	9008	1090K	—	24 88 87
	Coupe Thru June	09	35	Beru	—	—	9001	1090K	—	22 45 49
	Coupe Post July	09-11	35	Beru	—	—	9008	1090K	—	24 88 87
Mazda	B Series	07-09	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	2	11	71	Continental	7001	7020K	1056	7020K	NA	BBM2-37-140B
	3	04	71	Siemens-Fixed Angle	7001	7020K	1056	NA	NA	FE01-37-140A/ GN3A-37-140B

* Redi-Sensor relearn must be performed with scan tool & not magnet.

DILL 2011 TPMS APPLICATION
GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Mazda - Continued	3	05-10	71	Siemens	7001	7020K	1056	1050K	White	BBM2-37-140B
	3	10-12	71	Continental	7001	7020K	1056	7020K	—	BBM2-37-140B
	5	06-10	71	Siemens	7001	7020K	1056	1050K	White	BBM2-37-140B
	5	10-12	71	Continental	7001	7020K	1056	7020K	—	BBM2-37-140B
	6	05-10	71	Siemens	7001	7020K	1056	1050K	White	BBM2-37-140B
	6	10-12	71	Continental	7001	7020K	1056	7020K	—	BBM2-37-140B
	CX-7	07-10	71	Siemens	7001	7020K	1056	1050K	White	BBM2-37-140B
	CX-7	10-11	71	Continental	7001	7020K	1056	7020K	—	BBM2-37-140B
	CX-9	07-10	71	Siemens	7001	7020K	1056	1050K	White	BBM2-37-140B
	CX-9	10-11	71	Continental	7001	7020K	1056	7020K	—	BBM2-37-140B
	MX-5 Miata	06-10	71	Siemens	7001	7020K	1056	1050K	White	BBM2-37-140B
	MX-5 Miata	10-12	71	Continental	7001	7020K	1056	7020K	—	BBM2-37-140B
	RX-8	04	71	Siemens-Fixed Angle	7001	7020K	1056	NA	NA	FE01-37-140A/ GN3A-37-140B
	RX-8	05-10	71	Siemens	7001	7020K	1056	1050K	White	BBM2-37-140B
	RX-8	10-11	71	Continental	7001	7020K	1056	7020K	—	BBM2-37-140B
	Speed 3	10-12	71	Siemens	7001	7020K	1056	7020K	White	BBM2-37-140B
	Speed 6	07-08	71	Siemens	7001	7020K	1056	1050K	White	BBM2-37-140B
	Tribute	06-08	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
	Tribute	09-11	—	Schrader	7001	7020K	9315	VS950	NA	ZZDA-37-140
	Mercedes-Benz	C Class (433 Mhz)	07-12	53	Schrader	—	—	9214	2030K	Lt Grey
CL Class (315 Mhz)		00-06	35	Beru	—	—	9004	1090K	Gray	000 822 34 06
CL Class (433 Mhz)		00-06	35	Beru	—	—	9001	1090K	Gray	000 822 3306
CL Class (433 Mhz)		09-10	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
CL 63-65-550-600 (315 Mhz)		07-11	53	Siemens	—	—	1054	1040K	Pantone Brown	002 540 7917
CL 63-65-550-600 (433 Mhz)		07-11	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
CLKClass (315 Mhz)		06-07	35	Beru	—	—	9004	1090K	Gray	000 822 34 06
CLK Class (433 Mhz)		08-09	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
CLS 55-63-500-550 (315 Mhz)		06-11	53	Siemens	—	—	1054	1040K	Pantone Brown	002 540 7917
CLS 55-63-500-550 (433 Mhz)		06-09	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
CLS Class (433 Mhz)		08-10	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
CLS Class (433 Mhz)		11	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
E Class (315 Mhz)		00-05	35	Beru	—	—	9004	1090K	Gray	000 822 34 06
E Class (433 Mhz)		00-05	35	Beru	—	—	9001	1090K	Gray	000 822 33 06
E Class (315 Mhz)		06-10	53	Siemens	—	—	1054	1040K	Pantone Brown	002 540 7917
E Class (433 Mhz)		06-10	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
E Class (433 Mhz)		10-11	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
G Class (433 Mhz)		07-10	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
GL Class (315 Mhz)		07-09	53	Siemens	—	—	1054	1040K	Pantone Brown	002 540 7917
GL Class (433 Mhz)		07-09	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
GL (433 Mhz)		10-11	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
GLK (433 Mhz)		10-11	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
ML Class (315 Mhz)		06-10	53	Siemens	—	—	1054	1040K	Pantone Brown	002 540 7917
ML Class (433 Mhz)		06-10	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
ML Class (433 Mhz)		10-11	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Mercedes-Benz - Continued	R Class (315 Mhz)	06-09	53	Siemens	—	—	1054	1040K	Pantone Brown	002 540 7917
	R Class (433 Mhz)	06-09	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
	R Class (433 Mhz)	10	35	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
	R Class (433 Mhz)	11	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
	S Class (315 Mhz)	00-06	35	Beru	—	—	9004	1090K	Gray	000 822 34 06
	S Class (433 Mhz)	00-06	35	Beru	—	—	9001	1090K	Gray	000 822 33 06
	S Class (315 Mhz)	07-11	53	Siemens	—	—	1054	1040K	Pantone Brown	002 540 7917
	S Class (433 Mhz)	07-10	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
	S (433 Mhz)	10-11	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
	SL Class (315 Mhz)	00-05	35	Beru	—	—	9004	1090K	Gray	000 822 34 06
	SL Class (433 Mhz)	00-05	35	Beru	—	—	9001	1090K	Gray	000 822 33 06
	SL Class (315 Mhz)	06-11	53	Siemens	—	—	1054	1040K	Pantone Brown	002 540 7917
	SL Class (433 Mhz)	06-09	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
	SLK Class (433 Mhz)	08-11	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
	SLR Class (315 Mhz)	04-06	35	Beru	—	—	9004	1090K	Gray	000 822 34 06
	SLR Class (433 Mhz)	00-06	35	Beru	—	—	9001	1090K	Gray	000 822 33 06
	SLR Class (315 Mhz)	08-09	53	Siemens	—	—	1054	1040K	Pantone Brown	002 540 7917
	SLR Class (433 Mhz)	08-09	53	Siemens	—	—	1049	1040K	Pantone Brown	002 540 8017
	SLS (433 mhz)	11	53	Schrader	—	—	9214	2030K	—	003 540 0217
	Mercury	Grand Marquis	07-10	—	Lear	7001	7020K	1048	NA	NA
Mariner		06-08	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
Mariner		09-11	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
Milan		08-09	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
Milan		10-11	—	Schrader	7001	7020K	9315	VS950	NA	9L3Z-1A189-A
Montego		06-07	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
Monterey (315 Mhz)		04-05	44	Schrader	7001	7020K	9135	1060K	Rubine Red	5L1Z1A150-AB
Monterey		06-07	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
Mountaineer (433 Mhz)		02-05	44	Schrader	*7004	7020K	9096	1060K	Rubine Red	4L2T1A150-BA
Mountaineer		06-10	—	Lear	7001	7020K	1048	NA	NA	6F2Z-1A189A
Sable		08-09	—	Lear	7001	7020K	1048	NA	NA	7L1Z-1A189A
Mini		All (433 Mhz)	07-10	35	Beru	—	—	1027	1090K	Gray
	All (433 Mhz) (September 2009)	10-12	35	Beru	—	—	9012	1090K	Gray	36 10 6 790 054
Mitsubishi	Eclipse (Alloy)	06-10	45-53	Schrader	7001	7020K	9034	1080K	Green	MN103081
	Eclipse (Steel)	06-07	45-53	Schrader	—	—	9069	1130K	Burgundy	4250A030
	Eclipse	11	71	Continental	7001	7020K	1051	7000K	White	425 0B 975
	Endeavor (433 Mhz)	04-06	45-53	Schrader	7004	7020K	9028	1080K	Green	52088990AC
	Endeavor September +	06-11	45-53	Schrader	7001	7020K	9034	1080K	Green	425 0B 877
	Galant (433 Mhz)	04-06	45-53	Schrader	7004	7020K	9028	1080K	Green	MN103033
	Galant	07-11	45-53	Schrader	7001	7020K	9034	1080K	Green	425 0B 877
	Galant (Steel)	07-09	45-53	Schrader	—	—	9069	1130K	Burgundy	4250A030
	Lancer	08-10	71	Continental	7001	7020K	1051	1050K	White	425 0B 668/975
	Lancer	10-11	71	Continental	7001	7020K	1051	7000K	—	425 0B 668/975
	Montero	03-05	45-53	Schrader	7001	7020K	9034	1080K	Green	MN103081
	Outlander	07-10	71	Siemens	7001	7020K	1051	1050K	White	425 0B 668/975
	Outlander	10-11	71	Continental	7001	7020K	1051	7000K	—	425 0B 668/975
	Raider(HP)	08-09	53	Schrader	—	—	9154	2030K	Lt Grey	56029319AB

* Redi-Sensor relearn must be performed with scan tool & not magnet.

DILL 2011 TPMS APPLICATION GUIDE

Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #	
Nissan	350Z	04-06	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001
	350Z	07-09	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0C
	370Z (Base)	09-10	50-70	Pacific	*7001	7020K	9204	2030K	—	40700-JK00C
	370Z (Base)	11	50-70	Pacific	—	—	1216	1100K	—	40700-1LA0C
	Altima	06-12	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-JA01B
	Armada (Alloy) SE	05-08	49	Schrader	—	—	9161	1080K	Green	40700-CK001
	Armada (Steel)	05-06	49	Schrader	—	—	9069	1130K	Burgundy	40700-CK002
	Armada-LE	08-12	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B
	Cube	09-11	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B
	Frontier	03-04	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001
	Frontier (Alloy)	05-08	49	Schrader	—	—	9161	1080K	Green	40700-CK001
	Frontier (Steel)	05-07	49	Schrader	—	—	9069	1130K	Burgundy	40700-CK002
	Frontier (Steel)	08-11	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B
	GT-R	09-12	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0C
	Juke	11	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B
	Leaf	11	—	Pacific	—	—	1216	1100K	—	40700-1LA0C
	Maxima (Alloy)	06-07	49	Schrader	—	—	9161	1080K	Green	40700-CK001
	Maxima Post-April	07-12	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B
	Murano	03-06	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001
	Murano	07-12	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B
	NV 1500/2500HD/3500HD	12	—	Schrader	—	—	NEW	—	—	40700-1PA0A
	Pathfinder	03-04	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001
	Pathfinder (Steel)	04	49	Schrader	—	—	9069	1130K	Burgundy	40700-CK002
	Pathfinder	05-06	49	Schrader	—	—	9161	1080K	Green	40700-CK001
	Pathfinder	07-11	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B
	Quest (Steel)	04-07	49	Schrader	—	—	9069	1130K	Burgundy	40700-CK002
	Quest (Alloy)	05-06	78	Schrader	—	—	9161	1080K	Green	40700-CK001
	Quest	07-09	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-JA01B
	Quest	11-12	—	Pacific	—	—	1216	1100K	—	40700-1LA0C
	Rogue	08-11	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B
	Sentra (Alloy)	07-08	75	Schrader	—	—	9161	1080K	Green	40700-CK001
	Sentra (Steel)	07-12	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0D
	Titan (Alloy)	05-07	49	Schrader	—	—	9161	1080K	Green	40700-CK001
	Titan (Steel)	04-05	49	Schrader	—	—	9069	1130K	Burgundy	40700-CK002
	Titan(Steel) Post April	07-12	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B
Versa-HB	07-12	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B	
Versa-Sedan	12	—	—	—	—	NEW	—	—	40700-3AN0A	
Xterra	03-04	45-60	Schrader	—	—	9064	1080K	Green	40700-CD001	
Xterra	05-06	49	Schrader	—	—	9161	1080K	Green	40700-CK001	
Xterra (Steel)	06-07	49	Schrader	—	—	9069	1130K	Burgundy	40700-CK002	
Xterra	07-11	50-70	Schrader	*7001	7020K	9204	2030K	Lt Grey	40700-1AA0B	
Pontiac	G3	09	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	G5	08	80	Siemens	7001	7020K	1047	1050K	White	15921013
	G5	09-10	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	G6 Pre-10/15	08	80	Siemens	7001	7020K	1047	1050K	White	15921013
	G6 Post-10/15	08-10	—	Schrader	7001	7020K	9153	VS950	NA	25920615
	G8	08-09	—	Schrader	7001	7020K	9153	VS950	NA	25920615

* Utilize the ATEQ VT-55 or Bartec OBD-enabled tools (Rev 45) for the vehicle relearn.

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #	
Pontiac - Continued	Grand Prix	07-08	80	Siemens	7001	7000K	1047	1050K	White	15921013	
	Grand Prix	08	—	Schrader	7001	7000K	9153	VS950	NA	259220615	
	Montana	08	80	Schrader	7001	7000K	1047 *	1050K or 1070K	White Blue	15268606	
	Solstice	08-09	80	Siemens	7001	7000K	1047	1050K	White	15921013	
	Torrent	07-09	80	Siemens	7001	7000K	1047	1050K	White	10394110	
	Vibe	08-10	35	Pacific	1204-A	1100K	1204	1100K	Purple	88974915	
	Wave	08	—	Schrader	7001	7000K	9153	VS950	NA	25920615	
Porsche	911 (433 Mhz)	06-08	31-40	Beru	—	—	9001	1090K	Gray	997 606 021 01	
	911 (433 Mhz)	09-10	31-40	Beru	—	—	9008	1090K	Gray	997 606 021 20	
	911 (433 Mhz)	11	31-40	Beru	—	—	9011	1090K	Gray	958 361 661 00	
	911 (315 Mhz)	06-08	31-40	Beru	—	—	9004	1090K	Gray	—	
	Boxster (433 Mhz)	06-08	31-40	Beru	—	—	9001	1090K	Gray	997 606 021 01	
	Boxster (433 Mhz) Post November 2008	09-11	31-40	Beru	—	—	9008	1090K	Gray	997 606 021 20	
	Boxster (315 Mhz)	06-08	31-40	Beru	—	—	9004	1090K	Gray	—	
	Carrera GT (433 Mhz)	02-06	31-40	Beru	—	—	9001	1090K	Gray	997 606 021 01	
	Cayenne (433 Mhz)	02-06	31-40	Beru	—	—	9005	1090K	Gray	955 361 661 01	
	Cayenne (315 Mhz)	09-10	31-40	Beru	—	—	9004	1090K	Gray	955 606 023 01	
	Cayenne (433 Mhz)	07-09	31-40	Beru	—	—	9007	1090K	Gray	955 606 021 00	
	Cayenne (433 Mhz)	10-12	31-40	Beru	—	—	9011	1090K	Gray	958 361 661 00	
	Cayman (433 Mhz)	06-08	31-40	Beru	—	—	9001	1090K	Gray	997 606 021 01	
	Cayman (433 Mhz)	09-10	31-40	Beru	—	—	9008	1090K	Gray	997 606 021 20	
	Cayman (433 Mhz)	11-12	31-40	Beru	—	—	9011	1090K	Gray	958 361 661 00	
	GT3	07-09	31-40	Beru	—	—	9001	1090K	—	997 606 021 01	
	GT3	10-11	31-40	Beru	—	—	9008	1090K	—	997 606 021 20	
	Panamera (315 Mhz)	10-12	31-40	Beru	—	—	9004	1090K	Gray	997 606 023 21	
	Panamera (433 Mhz)	10-12	31-40	Beru	—	—	9008	1090K	Gray	997 606 021 20	
	Rolls Royce	Phantom (433 Mhz)	07-10	31-40	Beru	—	—	1027	1090K	Gray	NA
Cabrio (433 Mhz)		07-10	31-40	Beru	—	—	1027	1090K	Gray	NA	
Saab	9-3 (433 Mhz)	04-07	62	Schrader	—	—	9078	2010K	Lt Brown	13172567	
	9-3 (433 Mhz)	08-11	62	Schrader	—	—	—	2010K	Lt Brown	13227143	
	9-5 (433 Mhz)	04-07	62	Schrader	—	—	9078	2010K	Lt Brown	13172567	
	9-5 (433 Mhz)	08-10	62	Schrader	—	—	—	2010K	Lt Brown	13227143	
	9-7X (315 Mhz)	05-09	62	Schrader	7001	7020K	9116	1070K	Blue	25774006	
Saturn	Astra (433 Mhz)	08-09	62	Schrader	—	—	9078	2010K	Lt Brown	13172567	
	Aura <10/14/07	07-08	80	Siemens	7001	7020K	1047	1050K	White	15921013	
	Aura >10/14/07	08-09	—	Schrader	7001	7020K	9153	VS950	NA	25920615	
	Lamda Crossover	07-08	80	Schrader	7001	7020K	1047 *	1050K or 1070K	White Blue	15268606	
	Outlook	07-08	80	Siemens	7001	7020K	1047	1050K	White	15921013	
	Outlook	09-10	—	Schrader	7001	7020K	9153	VS950	NA	25920615	
	Sky	08-09	80	Siemens	7001	7020K	1047	1050K	White	15921013	
	Vue	07-10	—	Schrader	7001	7020K	9153	VS950	NA	25920615	
	Scion	TC	06-12	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33011
		IQ	12	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33011
XB		08-12	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33011	
XD		08-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33011	

* The 1050K is to be used on the Siemens sensors
& the 1070K is to be used on the Schrader sensors.

DILL 2011 TPMS APPLICATION **GUIDE**

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #
Smart	Fortwo (433 Mhz)	08	53	Siemens	—	—	1049	1040K	Pantone Brown	004 542 1518
	Fortwo (433 Mhz)	08-11	53	Schrader	—	—	9214	2030K	Lt Grey	003 540 0217
Subaru	B9 Tribeca	06-07	66	Schrader	—	—	9081	1080K	Green	28103AG00A
	Forester	08-11	—	Schrader	—	—	9203	VS950	NA	28103AG01C
	Impreza	08-12	—	Schrader	—	—	9203	VS950	NA	28103AG01C
	Legacy	04-07	66	Schrader	—	—	9081	1080K	Green	28103AG00A
	Legacy	08-11	—	Schrader	—	—	9203	VS950	NA	28103AG01C
	Outback	04-07	66	Schrader	—	—	9081	1080K	Green	28103AG00A
	Outback	08-11	—	Schrader	—	—	9203	VS950	NA	28103AG01C
	Tribeca	08-11	—	Schrader	—	—	9203	VS950	NA	28103AG01C
Suzuki	Equator	09-11	68	Schrader	*7001	7000K	9204	2030K	Lt Grey	43211-82Z00
	Forenza	07-08	—	Schrader	7001	7020K	9153	VS950	NA	43130-85Z03
	Grand Vitara	07-11	80	Schrader	—	—	9087	2010K	Lt Brown	43130-54J21
	Kizashi	10-12	62	Continental	7001	7020K	1051	7000K	White	43130-57L00
	Reno	07-08	—	Schrader	7001	7020K	9153	VS950	NA	43130-85Z00
	SX4	07-12	80	Schrader	—	—	90 87	2010K	Lt Brown	43130-54J21
	Verona	05-06	80	Schrader	—	—	9082	2010K	Lt Brown	43130-86Z20
	XL-7	05-06	80	Schrader	—	—	9087	2010K	Lt Brown	43130-54J21
	XL-7	07-09	62	Siemens	7001	7020K	1047	1050K	White	43130-78J10
	Roadster	10	40-50	Baolong	—	—	2112	2020K	Pink	6004985
Tesla	4 Runner	03-05	35	Pacific	1204-A	1100K	1205	1110K	Teal	42607-35010
	4 Runner	06-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33021
	Avalon	07-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-06011/ 33011
	Camry	07-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607- 06011/33011
	Camry	12	—	—	—	—	1218	—	—	42607-06020
	Corolla	07-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607- 06011/33011/33021
	FJ Cruiser	08-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33011
	Highlander	07-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-06011
	Land Cruiser	05-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33011
	Matrix	07-10	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-06011/ 33011
	Prius	06-12	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-06011
	RAV 4	06-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-06011
	Sequoia (20 Degrees)	04-07	35	Pacific	1204-A	1100K	1204	1110K	Teal	42607-0C020
	Sequoia (40 Degrees)	04-07	35	Pacific	1204-A	1100K	1203	1110K	Teal	42607-0C010
	Sequoia (20 Degrees)	08-11	35	TRW	1206-A	1100K	1206	1110K	Teal	42607-0C050/ 08010
	Sequoia (40 Degrees)	08	35	TRW	1206-A	1100K	1206	1110K	Teal	42607-0C060
	Sienna (20 Degrees)	06-11	35	TRW	1206-A	1100K	1206	1110K	Teal	42607-0C050/ 42607-08010
	Solara	06-08	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-06011
	Tacoma (20 Degrees)	05-06	35	Pacific	1204-A	1100K	1204	1110K	Teal	42607-0C020/ AD020
	Tacoma (40 Degrees)	05-11	35	Pacific	1204-A	1100K	1203	1110K	Teal	42607-0C010/ AD010/04010
	Tacoma (20 Degrees)	07-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-06011
	Tundra (20 Degrees)	05-06	35	Pacific	1204-A	1100K	1204	1110K	Teal	42607-0C020
	Tundra (40 Degrees)	05-06	35	Pacific	1204-A	1100K	1203	1110K	Teal	42607-0C010
	Tundra (20 Degrees)	06-11	35	TRW	1206-A	1100K	1206	1110K	Teal	42607-0C050/ 08010
	Tundra (40 Degrees)	06-11	35	TRW	1206-A	1100K	1206	1110K	Teal	42607-0C060
	Venza	09-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-06011
	Yaris	07-11	35	Pacific	1204-A	1100K	1204	1100K	Purple	42607-33011
	Yaris	12	—	Pacific	—	—	1218	1100K	—	42607-52020

* Utilize the ATEQ VT-55 or Bartec OBD-enabled tools (Rev 45) for the vehicle relearn.

DILL 2011 TPMS APPLICATION GUIDE

	Model	Model Year	Torque In-Lbs	OE Supplier	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	Kit Color	OE Sensor Part #	
Volkswagen	Beetle	08-11	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	CC	09-12	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	EOS	07-12	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	GLI	08-09	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	Golf	10-11	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	GTI (Standard Hex)	06-11	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	GTI (O-ring Hex)	06-07	71	Siemens	—	—	1041	1031K	Lt Green	1K0907253E	
	Jetta (Standard Hex)	06-11	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	Passat (Standard Hex)	06-10	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	Passat (433 Mhz)	11	35	Beru	—	—	NEW	1090K	Gray	3AA 907 275	
	Passat (O-ring Hex)	06-08	71	Siemens	—	—	1041	1031K	Lt Green	1K0907253E	
	Phaeton (433 Mhz) Thru May 2007	02-07	35	Beru	—	—	9001	1090K	Gray	4D0 907 275C	
	Phaeton (433 Mhz) June 2007	07-10	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B	
	Phaeton (433 Mhz)	11	35	Beru	—	—	9011	1090K	Gray	4F0 907 275D	
	Phaeton (315 Mhz)	03 -07	35	Beru	—	—	9004	1090K	Gray	4D0 907 275A	
	R32	08-10	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	Rabbit (Standard Hex)	06-10	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	Rabbit (O-ring Hex)	06-07	71	Siemens	—	—	1041	1031K	Lt Green	1K0907253E	
	Routan (433 Mhz)	09-10	71	Siemens	7004	7020K	1043	1050K	White	7B0907253A	
	Routan(433 Mhz)	11	—	Siemens	—	—	9398	VS950	White	7B0907253B	
	Tiguan	09-11	71	Siemens	—	—	1053	1030K	Orange	1K0907253D	
	Touareg (433 Mhz)	02-06	35	Beru	—	—	9005	1090K	Gray	7L0 907 275B	
	Touareg 2 (433 Mhz)	07-10	35	Beru	—	—	9007	1090K	Gray	4F0 907 275B	
	Touareg 2 (433 Mhz)	11	35	Bere	—	—	9011	1090K	Gray	4F0 907 275D	
	Volvo	C30 (433 Mhz)	07-10	71	Siemens	—	7020K	1044	1050K	White	31302096
		C30 (433 Mhz)	10-12	71	Continental	—	7020K	1044	7020K	—	31302096
		C70 (433 Mhz)	07-10	71	Siemens	—	7020K	1044	1050K	White	31302096
		C70 (433 Mhz)	10-12	71	Continental	—	7020K	1044	7020K	—	31302096
S40 (433 Mhz)		07-10	71	Siemens	—	7020K	1044	1050K	White	31302096	
S40 (433 Mhz)		10-12	71	Continental	—	7020K	1044	7020K	—	31302096	
S60 (315 Mhz)		04-10	44	Schrader	—	—	9156	2010K	Lt Brown	31200923	
S60 (433 Mhz)		11-12	71	Siemens	—	7020K	1044	7020K	White	31302096	
S80 (315 Mhz)		04-07	44	Schrader	—	—	9156	2010K	Lt Brown	31200923	
S80 (433 Mhz)		07-10	71	Siemens	—	7020K	1044	1050K	White	31302096	
S80 (433 Mhz)		10-12	71	Continental	—	7020K	1044	7020K	—	31302096	
V50 (433 Mhz)		08-10	71	Siemens	—	7020K	1044	1050K	White	31302096	
V50 (433 Mhz)		10-11	71	Continental	—	7020K	1044	7020K	—	31302096	
V70 (315 Mhz)		04-07	44	Schrader	—	—	9156	2010K	Lt Brown	31200923	
V70 (433 Mhz)		08-10	71	Siemens	—	7020K	1044	1050K	White	31302096	
XC60		09-10	44	Schrader	—	—	9156	2010K	Lt Brown	31200923	
XC60		11-12	—	Continental	—	7020K	1044	7020K	—	31302096	
XC70 (315 Mhz)		04-07	44	Schrader	—	—	9156	2010K	Lt Brown	31200923	
XC70 (433 Mhz)		08-10	71	Siemens	—	7020K	1044	1050K	White	31302096	
XC70 (433 Mhz)		10-11	71	Continental	—	7020K	1044	7020K	—	31302096	
XC90 (315 Mhz)		05-09	44	Schrader	—	—	9156	2010K	Lt Brown	31200923	
XC90 (433 Mhz)		08	71	—	—	7020K	1044	1050K	White	31302096	
XC90 (433 Mhz)		10-11	71	Continental	—	7020K	1044	7020K	—	31302096	



Bartec is a leader in TPMS, something we take very seriously.
Our goal is continuous improvement in all that we do.



BRINGING



TPMS

**INTO
FOCUS**

Here's how Bartec Brings TPMS into Focus!

Superior Diagnostic Tools!

TPMS Technician Forums!

TPMS Dealer Locator!

Industry leading Technical Support!

TPMS TUESDAYS!

On-Board TPMS Relearn Procedures!

TPMS: Vehicle Of The Month!

Model Year 2012 Coverage!

How-to Videos!

TPMS Training!

WHYTPMS.COM

Mechanical Tools!

TPMS Website Support!



EZ-Sensor™ is a trademark of Schrader International, Inc

ASCOT™

SUPPLY CORPORATION

Sensors Service Kits Tools & Accessories

*The Most Comprehensive Line of
TPMS Replacement Products*

Dill provides Tire Pressure Monitoring Systems (TPMS) and a complete range of valves, valve cores, and valve-related products and tools to a variety of OEM and replacement market customers throughout the world



Featuring REDI-Sensor

- Installs right out of the box
- Works with all major scan tools
- Adjustable valve stem design
- Reduces sensor SKU's
- No programming required
- Fits most Ford, GM, Chrysler Nissan and Infiniti Applications

Dill® Air
Controls
Products

www.dillvalves.com



Ask Your Sales Representative For Your Copy of the **Complete Ascot Buyer's Guide!**

Your ASCOT TPMS One Stop Shop Distributor:
Attention Service Manager:



©Ascot Supply Corporation
TPMS1011

