

1979 Piper Seneca II PA-34 N2855U
Located in Boise, ID (BOI)



Airframe

Serial: 34-7970294
Total Time: 6990

Engines

Continental

Model: TSIO-360-EB19
Serial: 818494-R
TBO: 1800
SRFM: 580 / 2002 by TCM

LTSIO-360-EB10
807753-R
1800
580hrs / 2002 by TCM

Propeller

Hartzell 3-Blade

Model: 3AF34C503-B
Hub Serial: 791408
SPOH: 580

Additional Features

- Electric Pitch Trim
- De-Ice boots (has patches but works well)
- Prop De-Ice
- De-Ice Windshield Plate

This aircraft and its owner are being EXCLUSIVELY represented by Chase Aviation Company, LLC. The specifications contained are intended to be used as preliminary information only. A pre-purchase inspection should be performed by a third party maintenance facility to determine the accuracy of this spec sheet and overall mechanical condition of this aircraft.

1979 Piper Seneca II PA-34 N2855U
Located in Boise, ID (BOI)



Avionics

- Garmin MX20 Multi-Function Display
- Garmin GNS 430
- Garmin SL30 Nav/Com
- Dual Garmin GI-106A Course Deviation Indicators
- Altimatic IIIC Autopilot



This aircraft and its owner are being EXCLUSIVELY represented by Chase Aviation Company, LLC. The specifications contained are intended to be used as preliminary information only. A pre-purchase inspection should be performed by a third party maintenance facility to determine the accuracy of this spec sheet and overall mechanical condition of this aircraft.

1979 Piper Seneca II PA-34 N2855U
Located in Boise, ID (BOI)



Interior

The interior features seating for six with aft club in cream and green vinyl. The plastics appear to be free from major cracking. Dozens of close-up photos are available for closer review.



This aircraft and its owner are being EXCLUSIVELY represented by Chase Aviation Company, LLC. The specifications contained are intended to be used as preliminary information only. A pre-purchase inspection should be performed by a third party maintenance facility to determine the accuracy of this spec sheet and overall mechanical condition of this aircraft.

1979 Piper Seneca II PA-34 N2855U
Located in Boise, ID (BOI)



Exterior

The paint appears to be original to the aircraft but in better than expected condition for the age. It does not "need paint" but leading edges of panels exposed to high camber airflow are missing paint in places. Overall glossiness is starting to fade.



This aircraft and its owner are being EXCLUSIVELY represented by Chase Aviation Company, LLC. The specifications contained are intended to be used as preliminary information only. A pre-purchase inspection should be performed by a third party maintenance facility to determine the accuracy of this spec sheet and overall mechanical condition of this aircraft.

1979 Piper Seneca II PA-34 N2855U
Located in Boise, ID (BOI)



Maintenance

- Annual Inspection complied with: February, 2015.
- 91.411 Pitot Static Check complied with: February 21st, 2013.
- 91.413 ATC Transponder check complied with: February 21st, 2013.
- 91.207(d) ELT Check complied with: January 28th, 2013 at 6756.2hrs.
- Logbooks prior to 1999 are missing; engine logbooks since overhaul are complete. Check with FAA for complete records. No known or previously found damage history.

PIPER SENECA II

Performance Data

Cruise Speed (knots): 190
Stall Speed (knots): 61
Range in Nautical Miles: 850
Service Ceiling (feet): 25000
Rate of Climb (feet per minute): 1340
Take over 50 foot obstacle (feet): 1240
Landing over 50 foot obstacle (feet): 2090
Take Off Normal (feet): 900
Landing Normal (feet): 1380

Average Empty Wt (pounds): 2857
Gross Wt (pounds): 4570
Fuel Regular (Gallons): 98
Fuel Max (Gallons): 128

This aircraft and its owner are being EXCLUSIVELY represented by Chase Aviation Company, LLC. The specifications contained are intended to be used as preliminary information only. A pre-purchase inspection should be performed by a third party maintenance facility to determine the accuracy of this spec sheet and overall mechanical condition of this aircraft.

1979 Piper Seneca II PA-34 N2855U
Located in Boise, ID (BOI)



Chase Aviation Company is proud to be the EXCLUSIVE sales Agent for this aircraft and its owner. More information can be obtained by visiting our website at

www.ChaseAviation.com

Chase Aviation Company, LLC
6060 S. Aviation Ave Suite 106
North Charleston, SC 29406
Office: 843-628-7406
Fax: 843-628-7410

aircraftsales@ChaseAviation.com

Located at the Charleston Int'l Airport (KCHS)