CHAPTER 1

FINITE ELEMENT METHOD IN DESIGN ANALYSIS

1.1 INTRODUCTION

The finite element method has been a powerful tool for the numerical solution of a wide range of engineering problems. Application range from deformation and stress analysis of automotive, aircraft, building, defense, missile, and bridge structures to the field analysis of dynamics, stability, fracture mechanics, heat flux, fluid flow, magnetic flux, seepage and other flow problems. With the advances in computer technology and CAD systems Complex problems can be modeled with relative ease. Several alternate configurations can be tried out on a computer before the first prototype is built. The basics in engineering field is must to idealize the given structure for the required behavior. The proven knowledge in the typical problem area, modeling techniques, data transfer and integration, computational aspects of the finite element method is essential.

Most often it is not possible to ascertain the behavior of complex continuous system without some sort of approximation. For simple members like uniform beams, plates etc., Classical solutions can be sought by forming differential and/or integral equations through structures like machine tool frames. Pressure vessels, automobile bodies, ships, aircraft structures, domes etc, need some approximate treatment to arrive at their behavior, be it static deformation, dynamic properties or heat conducting property. Indeed these are continuous systems with their mass and elasticity being continuously distributed. The classical differential equation solution approach leads to intractability. To overcome this engineers and mathematicians have form time to time proposed complex structure is defined using a finite number of well-defined components. Such systems are then regarded as discrete systems. The discretization method could be finite difference approximation, various residual procedures etc.

Finite element method comes under this category of discretization methods. R.W. Clough appears to be the first to use this term of finite element since 1960s there has been much progress in the method. The method requires a large number of computations requiring a fast computer. In fact digital computer advances have been responsible for the expanding usage of the finite element method. The finite element method was initially developed to solve structural problems. Its use of late, has been rapidly extended to various fields. The delivery of applications of the method can be

seen from the following table 2.1, which still by no means can be claimed as complete since fields of usage are being continuously diversified.

1.2 METHODS OF ENGINEERING ANALYSIS

The general methods for solving the practical problems can be classified as shown in figure:




Fig.1.1. Block diagram of engineering analysis

- Exact method Provides exact solution to the problems, but the limitation of this method is that all practical problems cannot be solved and even if they can be solved, they may have very complex solution.
- Approximate analytical methods are alternative to the exact methods, in which certain functions are assumed to satisfy the geometric boundary conditions, but not necessary the governing equilibrium equations. These assumed functions, which are simpler, are then solved by any conventional method available. The solutions obtained from these methods have limited range of values of variables for which the approximate solution is nearer to the exact solution.
- Numerical method has been developed to solve almost all types of practical problems. The two common numerical methods used to solve the governing equations of practical problems are numerical integration and finite element technique.

- Numerical integration methods such as Runge-Kutta, Miline's method etc. adopt averaging of slopes of given function at the given initial values. These methods yield better solutions over the entire field width but sometimes laborious.
- Finite difference method the differential equations are approximated by finite difference equation. Thus the given governing equation is converted to a set of algebraic equations. These simultaneous equations can be solved by any simple method such as Gauss Elimination, gauss-Seidal iteration method, Crout's method etc. the method of finite difference yield fairly good results and are relatively easy to program. Hence, they are popular in solving heat transfer and fluid flow problems. However, it is not suitable for problems with irregular geometry and not suitable for problems of rapidly changing variables such as stress concentration problems.
- Finite Element Method (F.E.M) has emerged out to be powerful method for all kinds of practical problems. In this method the solution region is considered to be built up of many small-interconnected sub regions, called finite elements. These elements are applied with an interpolation model, which is simplified version of substitute to the governing equation of the material continuum property. The stiffness matrices obtained for these elements are assembled together and the boundary conditions of the actual problems are satisfied to obtain the solution all over the body or region FEM is well suited for computer programming.
- Boundary element method (B.E.M) like finite method is being used in all engineering fields. In this approach, the governing differential equations are transformed into integral identities applicable over the surface or boundary. These integral identities are integrated over the boundary, which is divided into small boundary segments. As in finite element method provided that the boundary conditions are satisfied, set of linear algebraic equations emerges, for which a unique solution is obtained.

1.3 INTRODUCTION TO FEM

In the field of engineering, it is necessary to obtain the unknown field parameters like displacement or forces, which can describe the behavior of structures. These unknowns can be obtained by using exact analytical solutions or energy methods, which are formulated with governing equilibrium equations of analytical solutions on the basis of solid mechanics. However in practice the real structure viz., aircraft/automobiles, civil, naval architecture, offshore and nuclear engineering are large in size with irregular shapes, intermediate in nature, possessing geometrical material non-linearity and having complicated loading or boundary conditions.

In these cases, to reduce the continuous system to a discrete one by conventional method, a lot of effort and assumption must be made, which are

cumbersome and error prone. The advent of high-speed electronic computer has given tremendous opportunity to the numerical method approach. The most commonly used numerical technique in solving engineering problems is FEM, because

- 1. Algebraic work corresponding to the solid mechanics is programmed in systematic matrix calculations and formulated into mathematical model. User need not work with complicated algebra but only to deal with the discredited geometry of the physical structural.
- 2. Ability to consider alternate loading and bending condition for the same geometry.

- 3. Accuracy of data mainly depends on the number of approximations. Since in FEM we can make lesser number of assumptions, degree of accuracy will be high with a minimum percentage or error from the exact value.
- 4. Faster and automatic calculations, which are repetitive in nature, simultaneous display of modification and part processing results.
- 5. Accurate prediction with adequate details for identifying critical areas of interest like highly stressed regions.

1.4 FINITE ELEMENT METHOD

The given system or structure is divided into small elements of units interconnected at grid points. Each element is solved variable, inherently making use of classical procedures and analytical. This process of breaking down of continuum of finite discrete elements and solving for the variable (velocity, displacement, stress and loads etc) is called finite element analysis.

The two methods used for the analysis of a problem in FEM are:

- (a) Force method: Here the forces are unknown (minimum complimentary energy method)
- (b) **Displacement Method**: Here the displacements are unknown (minimum potential energy method)

The analysis by FEM involves the following steps.

1. Pre-processing: It is the act of preparation of data such as nodal locations, element connectivity co-ordinates imposing boundary conditions applications of load and providing material information to element etc. one can decide in this stage regarding the number of nodes, elements, types with their order and the pattern of FE mesh.

2. Processing: This stage involves stiffness generation, stain energy calculation and solutions of equations resulting in the evolution of nodal variables, induced elemental forces, strains and stresses.

3. Post-Processing: The geometric deformation and distribution of forces, stresses and strains in the structure, here the aspect of plotting a displaced plotting nodal date in the form of contour plots, such as isotherms and isobars, and conversion of element oriented data into best fitting nodal values is discussed.

Preprocessing and post processing are integral parts of finite element analysis. The general purpose mesh generation scheme can model a variety of complex regions.

The node numbering gives spars matrices and in many cases should given minimum bandwidth proper block representation.

Mesh plotting shows the element layout.

1.5 WHAT IS FEA?


Finite Element Analysis is a way to simulate loading conditions on a design and determine the design's response to those conditions.

- The design is modeled using discrete building blocks called elements.
 - Each element has exact equations that describe how it responds to a certain load.

- The "sum" of the response of all elements in the model gives the total response of the design.
- The elements have a finite number of unknowns, hence the name finite elements.

The finite element model, which has a finite number of unknowns, can only approximate the response of the physical system, which has infinite unknowns. So the question arises: How good is the approximation?

Unfortunately, there is no easy answer to this question. It depends entirely on what you are simulating and the tools you use for the simulation. We will, however, attempt to give you guidelines throughout this training course.




Physical System

F.E. Model

1.6 DEGREES OF FREEDOM

Degrees of freedom (DOFs) characterize the response of a field.

Discipline	DOF
Structural	Displacement
Thermal	Temperature
Electrical	Voltage
Fluid	Pressure
Magnetic	Magnetic Potential



Structural DOFs

1.7 BASIC CONCEPTS OF FINITE ELEMENT METHOD

- > Full field is divided into finite number of elements.
- > Knowing the behavior of one/many elements one can predict the assemblage.
- > It is to predict the behavior of individual elements under load.
- > Minimum potential energy principle is used to evaluate element stiffness.
- > Independent of the problem to be solved, stiffness of the element can be obtained.

1.8 TERMINOLOGY IN THE FINITE ELEMENT METHOD

The commonly used terminologies in FE analysis are as follows.

1. Discritization

The physical structure has to be represented by a mathematical model in such way that it simplify the construction and easy to analyze. In modeling the given global domain is divided into sub-domains called elements. This process of modeling is termed as discrimination, which includes proper selection of type and density of the elements, the location of the nodal points for applying loads/boundary conditions, to extract the results from the areas of interest.

2. Grids

The point in space used for defining the geometry and connecting the elements. These points are useful to specify the displacement, force and boundary conditions of the structure.

3. Displacement

Displacement defines the deformation or the movement caused by an external force. There are six displacements for an element in space. These are three translations vectors u; v and w and are three rotational vectors with respect to x, y and z. co-ordinate system. These nodal variables are referred to as degrees of freedom.

4. Co-ordinate System

A co-ordinate system is the reference, which can specify the position of a point or an element in a space. The co-ordinate systems used are.

- Global co-ordinate system (Cartesian i.e. x. y. z.)
- Local co-ordinate system.
- Polar co-ordinate system(r. 0)
- Cylindrical co-ordinate system(r. 0. z)

- Spherical co-ordinate system(r. 0)
- Can be Cartesian also (x. y. z)

5. Boundary Conditions/Constraints

Resistance (reaction) offered at grid points due to the motion of the structure being constrained by the applied forces.

These reactions can be obtained with respect to the specified co-ordinate System.

- To prevent the rigid body motion there by reducing the continuous structure to discrete system(avoiding the phenomena of mechanism)
- These constraints can be zero (u. v. w. x. y. z = 0) or non-Zero and specified enforced displacement at grid points.

1.9 Steps Involved in FEM

The basic steps involved in finite element method are as follows.

1. Modeling

The basic idea of finite element modeling is to discretize the region and expresses the displacement in terms of values at discrete points.

2. Discritization

Discritization means division of a given structure into finite number elements of better approximations. This forms the first step in the analysis of complicated structural system.

3. Formulation of elemental equation and convergence test

The properties of the elements are formulated and combined to obtain the solution for the entire body or structure. For e.g. in the displacement formulation widely adopted in FE analysis, simple functions known as shape functions are chosen to approximate the variation of the displacement at the nodes of the element.

Convergence test is done to know that how much the approximate solution converges to the exact value and the errors are calculated.

4. Determination of

- a. Elemental stiffness matrix [K_e]
- b. Elemental nodal displacement vector [Qe]
- c. Elemental load vector [F_e]
- **5.** Equilibrium equations are imposed so that each of the elements is in a state of Equilibrium

$$[K_e] [Q_e] = [F_e]$$

6. Assembly of

- a. Stiffness matrix of all the elements [K]
- b. Nodal displacements of all the elements [Q]
- c. Nodal forces of all elements [f]
- d. Overall stiffness matrix is formed by global addition of element stiffness matrices.

7. Assembled Equilibrium Equation

The equation of equilibrium for the entire structure of body is then obtained by combining the equilibrium equation of each element such that the continuity of displacement is ensured at each node where the elements are connected.

$$[K] [Q] = [F]$$

8. Application of boundary conditions to the overall equilibrium equation.

The necessary conditions are imposed and the equations of equilibrium are solved for the nodal displacements. There are two approaches of applying the boundary conditions.

a. Elimination technique

In this technique after imposing the boundary conditions, whichever displacement is Zero, the corresponding row and column of the overall equilibrium is eliminated.

b. Penalty approach

A second approach for handling boundary condition is the penalty approach. This approach easily implemented in a computer program and retains its simplicity even when considering general boundary conditions where a large value of C is added to the highest diagonal elements. On applying the boundary conditions, the overall equilibrium equation gets modified.

c. Solution of the modified overall equilibrium equation by gauss elimination method

The value of nodal displacements will be obtained in this step. Thus knowing of all the nodal displacements, stain of each element will be computed. From these values elemental stresses are obtained.

Computation of Stains:

For each element stain calculated is given by the overall equation

 $[\epsilon] = \{b\} \{q\}$

Where $[\varepsilon] =$ Strain Matrix

- {b} = Strain Displacement Matrix where be is unique for each element
- $\{q\}$ = Elemental Nodal Displacement Vector.

Computation of Stress:

Knowing the strain, the stress is calculated as follows

i.e., $[\sigma] = \{D\} \{\varepsilon\}$ Where $[\sigma] =$ Stress Matrix

{D} = Constitutive Matrix for plane stress

 $\{\varepsilon\}$ = Strain Matrix

These are the main steps carried out in structural problems where the analysis is simple. It becomes complicated thereafter for each and every problem, which includes dynamic analysis where the forces and all the conditions vary with time. In thermal, it is transient analysis and in fluid flow situations, it is turbulent flow analysis. The finite element method was initially developed on a physical basis for the analysis of problems in structural mechanics; however, it was soon recognized that the method can be applied equally well to the solution of many other classes or problems.

1.10 MERITS OF FEM

The merits of finite element method are:

- > The systematic generality of finite procedure makes it a powerful and versatile tool for a wide range of problems. Thus flexible, general-purpose computer programs can be developed and can be applied to various problems with little or no modification.
- > FEM can be easily interpreted in physical terms and it has a strong mathematical base. Hence, finite element method can be easily applied to any problem with a proper

knowledge of the physical system under consideration and can be solved to a greater accuracy by the application of proper mathematical tool.


- Non-homogeneous continuum can also be dealt with by merely assigning different properties to different elements. It is even possible to vary the properties within an element according to the polynomial applied.
- Finite element method accommodates complex geometry with ease and is capable of handling non-linear and time dependent system also.
- In finite element method, since boundary conditions are introduced in the assembled equations, it requires only to specify the geometric boundary conditions without regarding its effects on interior elements. Since the boundary conditions do not enter into the individual finite element equations, the field variable models need not be changed, when the boundary conditions change.
- Finite element method considers the multidimensional continuity of the body. Hence it does not require separate interpolation process to extend the approximate solution to every point with in the continuum. Also it does not require the trial solutions that must all apply to the entire multidimensional continuum.

1.11 LIMITATIONS OF FEM


- FEM has been developed as a very high solution technique. However, the solution obtained from FEM can be realistic if and only if the material properties are known precisely.
- The major draw back of FEM is sensitivity of the solution on the geometry of the element such as type, shape and orientation of elements used.
- The compute programs yield a large amount of data as results it is very difficult to separate out the required results from the pile of numbers.

1.12 ERRORS INHERENT IN FEM FORMULATION

1. Geometry is simplified.



2. Field quantity is assumed to be a polynomial over an element. (Which is not true)



3. The computer carries only a finite number of digits.

4. The computer carries only a finite number of digits. e.g: $\sqrt{2} = 1.41421356$ $\pi = 3.14159265$

Mistakes by Users

- 1. Elements are of the wrong type: e.g.) Shell elements are used where solid elements are needed
- 2. Distorted elements
- 3. Supports are insufficient to prevent all rigid-body motions
- 4. Inconsistant units (e.g. E=200 GPa, Force = 100 lbs)

Element Properties: The discretization of the structure or body into Finite Elements forms the basic first step in the analysis of a complicated structural system.

Rules For Discretization Of The Structure Into Elements: Sub-division of a body or structure into Finite Elements should satisfy the following requirements:

- 1. Two distinct elements can have common points only on their common boundaries if such boundaries exist. No overlapping is allowed. Common boundaries can be points, lines or surfaces.
- 2. The assembled element should leave no holes within the two elements and approximate the geometry of the real body or structure as closely as possible to do.


When the boundary of a structure or body cannot be exactly represented by the elements selected, an error cannot be avoided. Such error is called Geometric Discretization Error and it can be decreased by reducing the size of the elements or by using elements allowing boundaries to become curved.

Mesh Generators: The finite element models for practical analysis can contain tens of thousands or even hundreds of thousands degrees of freedom. It is not possible to create such meshes manually. Mesh generator is a software tool, which divides the solution domain into many Sub domains – finite elements. Mesh generators can be of different types.


For two-dimensional problems, we want to mention two types: block mesh generators and triangulates.


Block Mesh Generators require some initial form of gross partitioning. The solution domain is partitioned in some relatively small number of blocks. Each block should have some standard form The mesh inside block is usually generated by mapping technique.

Triangulators typically generate irregular mesh inside arbitrary domains. Voronoi polygons and Delaunay triangulation are widely used to generate mesh. Later triangular mesh can be transformed to the mesh consisting of quadrilateral elements. Delaney triangulation can be generalized for three dimensional domains.



Finite Element Model of Gear tooth





Linear element


7

Quadratic element

-1

_η 1↑

-1



Linear element

Quadratic element

2

6

η

1ξ






Fig. 1.2: Comparison of Finite Element Solution & Exact Solution



Triangular Finite Element is the Simplest Two - Dimensional Element



Three-dimensional stress on an element.

PICTORIAL SUMMARY OF ELEMENTS TYPES

Refer ANSYS Help


COMMERICAL FEM SOFTWARE PACKAGES AVAILABLE

- ANSYS (General Purpose, PC and workstations).
- SDRC/I-DEAS-- (Complete CAD/CAM/CAE Package).
- Nastran (General purpose FEA on main frames)
- ABAQUS—(Non linear and dynamic analyses)
- ALGOR (PC & Workstations).
- DYNA-3D (Crash/Impact analysis).

Chapter 2

INTRODUCTION TO ANSYS

- ANSYS is a complete FEA software package used by engineers worldwide in virtually all fields of engineering:
 - o Structural
 - Thermal
 - Fluid, including CFD (Computational Fluid Dynamics)
 - Electrical / Electrostatics
 - Electromagnetics
- ✤ A partial list of industries in which ANSYS is used:
 - \circ Aerospace
 - o Automotive
 - o Biomedical
 - Bridges & Buildings
- ANSYS/Multiphysics is the flagship ANSYS product which includes all capabilities in all engineering disciplines.




There are three main component products derived from ANSYS/Multiphysics:

- ANSYS/Mechanical structural & thermal capabilities
- ANSYS/Emag electromagnetics
- ANSYS/FLOTRAN CFD capabilities
- Other product lines:
 - ANSYS/LS-DYNA for highly nonlinear structural problems
 - DesignSpace an easy-to-use design and analysis tool meant for quick analysis within the CAD environment
 - ANSYS/ProFEA for ANSYS analysis & design optimization within Pro/ENGINEER

- Structural analysis: is used to determine deformations, strains, stresses, and reaction forces.
- Static analysis
 - Used for static loading conditions.
 - Nonlinear behavior such as large deflections, large strain, contact, plasticity, hyper elasticity, and creep can be simulated
- Dynamic analysis
 - Includes mass and damping effects.
 - <u>Modal analysis</u> calculates natural frequencies and mode shapes.
 - <u>Harmonic analysis</u> determines a structure's response to sinusoidal loads of known amplitude and frequency.
 - <u>Transient Dynamic analysis</u> determines a structure's response to time-varying loads and can include nonlinear behavior.
- Other structural capabilities
 - Spectrum analysis
 - Random vibrations
 - Eigenvalue buckling
 - Substructuring, submodeling
- Explicit Dynamics with ANSYS/LS-DYNA
 - Intended for very large deformation simulations where inertia forces are dominant.
 - Used to simulate impact, crushing, rapid forming, etc.
- Thermal analysis: is used to determine the temperature distribution in an object. Other quantities of interest include amount of heat lost or gained, thermal gradients, and thermal flux. All three primary heat transfer modes can be simulated: conduction, convection, radiation.
 - Steady-State
 - Time-dependent effects are ignored.
 - o Transient
 - To determine temperatures, etc. as a function of time.
 - Allows phase change (melting or freezing) to be simulated.
 - \circ Electromagnetic analysis is used to calculate magnetic fields in electromagnetic devices.
 - Static and low-frequency electromagnetics
 - To simulate devices operating with DC power sources, low-frequency AC, or low-frequency transient signals.
 - Computational Fluid Dynamics (CFD)
 - To determine the flow distributions and temperatures in a fluid.
 - ANSYS/FLOTRAN can simulate laminar and turbulent flow, compressible and incompressible flow, and multiple species.
 - Applications: aerospace, electronic packaging, automotive design

Typical quantities of interest are velocities, pressures, temperatures, and film coefficients.

2.2 THE GUI LAYOUT



Utility Menu

Contains functions which are available throughout the ANSYS session, such as file controls, selecting, graphics controls, parameters, and exiting.

Toolbar Menu

Contains push buttons for executing commonly used ANSYS commands and functions. Customized buttons can be created.

Graphics Area

Displays graphics created in ANSYS or imported into ANSYS.

Input Line

Displays program prompt messages and a text field for typing commands. All previously typed commands appear for easy reference and access.

<u>Main Menu</u>

Contains the primary ANSYS functions, organized by processors (preprocessor, solution, general postprocessor, etc.)

<u>Output</u>

Displays text output from the program. It is usually positioned behind the other windows and can be raised to the front when necessary.

Resume:

This is opening a previously saved database. It is important to know that if you simply resume a database, it doesn't change the job name. For example: You start ANSYS with a job name of "file". Then you resume my model.db, do some work, then save. That save is done to file.db! Avoid this issue by always resuming using the icon on the toolbar. If you open

mymodel.db using this method, it resumes the model and automatically changes the job name to my model.

Plotting:

Contrary to the name, this has nothing to do with sending an image to a plotter or printer. Plotting in ANSYS refers to drawing something in the graphics window. Generally you plot one type of entity (lines, elements, etc.) to the screen at a time. If you want to plot more than one kind of entity use, "Plot \rightarrow Multiplot", which by default will plot everything in your model at once.

Plot Controls:

This refers to how you want your "plot" to look on the screen (shaded, wire frame, entity numbers on or off, etc). Other plot control functions include sending an image to a graphics file or printer.

Creating Geometry:

Geometry in ANSYS is created from "Main Menu \rightarrow Preprocessor \rightarrow Modeling \rightarrow Create" and has the following terminology,

KEYPOINTS: These are points, locations in 3D space.

- LINES: This includes straight lines, curves, circles, spline curves, etc. Lines are typically defined using existing keypoints.
- AREAS: This is a surface. When you create an area, it's associated lines and keypoints are automatically created to border it.
- VOLUMES: This is a solid. When you create a volume, it's associated areas, lines and keypoints are automatically created.
- SOLID MODEL: In most packages this would refer to the volumes only, but in ANSYS this refers to your geometry. Any geometry. A line is considered a "solid model".

You can't delete a child entity without deleting its parent, in other words you can't delete a line if it's part of an area, can't delete a key point if it's the end point of a line, etc.

Boolean Operations:

Top Down style modeling can be a very convenient way to work. Instead of first creating keypoints, then lines from those keypoints, then areas from the lines


and so on (bottom up modeling), start with volumes of basic shapes and use Boolean operations to add them, subtract them, divide them etc. Even if you are creating a shell model, for example a box, you could create the box as a volume (a single command) and then delete the volume keeping the existing areas, lines and keypoints.

These kinds of operations are found under "Main Menu \rightarrow Preprocessor \rightarrow Modeling \rightarrow Operate \rightarrow Booleans" with some common ones being:

Add: Take two entities that overlap (or are at least touching) and make them one.

Subtract: Subtract one entity from another. To make a hole in a plate, create the plate (area

of volume) then create a circular area or cylinder and subtract it from the plate. **Glue:** Take two entities that are touching and make them contiguous or congruent so that when meshed they will share common nodes. For example, using default mesh parameters,



Meshing without gluing areas.

Meshing after gluing areas.

Note: In case of Meshing after gluing areas. The coincident nodes on the common line between the two areas will be automatically merged. You don't have to manually equivalence them like in some other codes.

The Working Plane:

All geometry is created with respect to the working plane, which by default is aligned with the global Cartesian coordinate system. The "Working Plane" is actually the XY plane of the working coordinate system. The working coordinate system ID is coordinate system 4 in ANSYS. Global Cartesian is ID 0, Global Cylindrical is ID 1, and Global Spherical is ID 2. **Working Plane Hints:**

Turn on the working plane so you can see it with, "Utility Menu \rightarrow Work Plane \rightarrow Display Working Plane". Change the way the working plane looks or adjust the snap settings under "Utility Menu \rightarrow Work Plane \rightarrow WP Settings...". Move the working plane around using

WP Settings ⓒ Cartesian ⓒ Polar		
Grid and Triad Grid Only Triad Only		
🔽 Enable S	ònap	
Snap Incr Snap Ang	0.05	
Spacing	0.1	
Minimum	-1	
Maximum 1		
Tolerance	0.003	
OK	Apply	
Reset	Cancel	
Help		

"Utility Menu \rightarrow Work Plane \rightarrow Offset WP to...".

Align the working plane with various parts of the model using

"Utility Menu \rightarrow Work Plane \rightarrow Align WP with...".

If you select more than one node or keypoint to offset the working plane to, it will go to the average location of the selected entities. VERY handy!

Use the working plane to slice and dice your model. For example to cut an area in pieces use

"Main Menu \rightarrow Modeling \rightarrow Operate \rightarrow Booleans \rightarrow Divide \rightarrow Area by WrkPlane". Do this for lines and volumes as well.

Select Logic:

Selecting is an important and fundamental concept in ANSYS. Selected entities are your active entities. All operations (including Solving) are performed on the selected set. In many operations you select items "on the fly"; ANSYS prompts for what volumes to mesh for example, you pick them with the mouse, and ANSYS does the meshing.

However there are many times when you need to select things in more sophisticated ways. Also, in an ANSYS input file or batch file you can't select things with the mouse!

Examples where this would be useful:

- You have many different areas at Z = 0 you want to constrain. You could select them all one by one when applying the constraint, or select "By Location" beforehand, then say "Pick All" in the picking dialog.
- You have a structure with many fastener holes that you want to constrain. Again, you could select them all one by one when applying the constraint, or select lines "By Length/Radius", type in the radius of the holes to select all of them in one shot, then "Pick All" in the picking dialog when applying the constraint.

After working with the selected set,

"Utility Menu \rightarrow Select \rightarrow Everything" to make the whole model active again.

Select Entities Dialog Box Terminology:

From Full: Select from the entire set of entities in the model.

Reselect: Select a subset from the currently selected entities.

Also Select: Select in addition to (from the whole model) the set you have currently selected. Unselect: Remove items from the selection set.

- Select All: This is not the same as "Utility Menu \rightarrow Select \rightarrow Everything". This selects all of whatever entity you have specified at the top of the dialog.
- **Invert:** Reverses the selected and unselected entities (just the entities specified at the top of the dialog).
- **OK:** This does the select operation (or brings up a picker dialog so that you can pick with the mouse) and then dismisses the dialog.

Apply: This does the operation but keeps the dialog box. Typically use this so the dialog stays active.

Replot: Replots whatever is active in the graphics window.



Plot: Plots only the entity specified at the top of the dialog.

Organizing Your Model Using Components:

If you select a group of entities and think that you might want to use that selection set again, create a component out of it. Components are groups of entities but hold only one kind of entity at a time. Components can themselves be grouped into Assemblies, so this is how you group different types of entities together. Use "Utility Menu \rightarrow Select \rightarrow Comp/Assembly \rightarrow Create Component…" to create a component. The new Component Manager in Release 8.0 makes it very easy to manage and manipulate groups and select/plot what you want to see to the screen. This is found under "Utility Menu \rightarrow Select \rightarrow Component Manager"

\Lambda Component N	Manager		×
🖻 🛃 🖄 🗷	i 🖄 🕅 🕅 🖄	<u></u>	
Components	Display Comp	onent/Assembly	۲
Name	Туре	Count	*
ELEMENTS	Element	42	
LINES	Line	8	
4			Þ

Creating a Material:

Create the material properties for your model in

"Main Menu \rightarrow Preprocessor \rightarrow Material Props \rightarrow Material Models". This gives you this dialog box where all materials can be created,

A Define Material Model Behavior	
Material Edit Favorite Help	
Material Models Defined	
Material Model Number 1 Material Model Number 1	-
Elastic	
Linear Isotropic Properties for Material Number 1 🗴 😵 Isotropic	
😣 Orthotropic	
Linear Isotropic Material Properties for Material Number 1 😣 😣 Anisotropic	
🔞 Nonlinear	
T1 🛞 Density	
Temperatures 🛛 🙀 Thermal Expansion	
EX 10e6 😵 Damping	
PRXY .33 8 Friction Coefficient	
🙀 User Material Options	
Thermal	
CFD	
Add Temperature Delete Temperature Graph Electromagnetics	_
OK Cancel Help	

Double click on items in the right hand pane of this window to get to the type of material model you want to create. All properties can be temperature dependant. Click OK to create the material and it will appear in the left hand pane. Create as many different materials as you need for your analysis.

Selecting an Element Type:

ANSYS has a large library of element types. Why so many? Elements are organized into groups of similar characteristics. These group names make up the first part of the element name (BEAM, SOLID, SHELL, etc). The second part of the element name is a number that is more or less (but not exactly) chronological. As elements have been created over the past 30 years the element numbers have simply been incremented. The earliest and simplest elements have the lowest numbers (LINK1, BEAM3, etc), the more recently developed ones have higher numbers. The "18x" series of elements (SHELL181, SOLID187, etc) are the newest and most modern in the ANSYS element library.

Tell ANSYS what elements you are going to use in your model using "Main Menu \rightarrow Element Type \rightarrow Add/Edit/Delete"

Library of Element Types			X
Library of Element Types		Structural Mass Link Beam Pipe Solid Shell Constraint Hyperelastic	Elastic 4node 63 8node 93 Plastic 4node 143 Hyper 4node 181 Plastic 4node 43 4node 181
Element type reference number		2	
ОК	Apply	Cancel	Help

Later, when meshing or creating elements manually you will need to tell ANSYS what type of elements you want to create.

Creating Properties

A solid element (brick or tet) knows its thickness, length, volume, etc by virtue of its geometry, since it is defined in 3D space. Shell, beam and link (truss) elements do not know this information since they are a geometric idealization or engineering abstraction. Properties in ANSYS are called Real Constants. Define real constants using "Main Menu \rightarrow Real Constants \rightarrow Add/Edit/Delete".

Real Constant Set Number 1, for SHELL63	×	▲ Real Constants for BEAM3	×
Element Type Reference No. 1		Element Type Reference No. 3	
Real Constant Set No.	1	Real Constant Set No.	1
Shell thickness at node I TK(I)	.1		
at node J TK(J)		Cross-sectional area AREA	.52
at node K TK(K)		Area moment of inertia IZZ	1.56
at node L_TK(L)		Tatal bases baight UET/CUT	
Elastic foundation stiffness EFS		Total beam height HEIGHT	4.0
Element X-axis rotation THETA		Shear deflection constant SHEARZ	
Bending mom of inertia ratio RMI		Initial strain ISTRN	
Dist from mid surf to top CTOP			
Dist from mid surf to bot CBOT		Added mass/unit length ADDMAS	
Added mass/unit area ADMSUA			
OK Apply Cancel	Help	OK Apply Cancel	Help
CAMA-LAB (VOMELO/)		20 VI	JEMESTEK

Creating the Finite Elements Model - Meshing:


If you are just starting out in FEA, it is important to realize that your geometry (called the solid model in ANSYS) is not your finite element model. In the finite element method we take an arbitrarily complex domain, impossible to describe fully with a classical equation, and break it down into small pieces that we can describe with an equation. These small pieces are called finite elements. We essentially sum up the response of all these little pieces into the response of our entire structure The solver works with the elements. The geometry we create is simply a vehicle used to tell ANSYS where we want our nodes and elements to go. While you can create nodes and elements one by one in a manual fashion (called direct generation in ANSYS) most people mesh geometry because it is much another very good reason we mesh geometry is that we assign materials and properties to that geometry.

Then any element created on or in that geometric entity gets those attributes. If we don't like the mesh we can clear it and re-mesh, without having to re-assign the attributes.

Steps for Creating the Finite Elements:

- Assign Attributes to Geometry (materials, real constants, etc).
- Specify Mesh Controls on the Geometry (element sizes you wa
- Mesh.

Most of the meshing operations can be done within the MeshTool, so that will be examined in some detail now. Start it from "Main Menu \rightarrow Preprocessor \rightarrow Meshing \rightarrow MeshTool".



Applying Loads and Boundary Conditions:

Loads and boundary conditions can be applied in both the Preprocessor

("Main Menu \rightarrow Preprocessor \rightarrow Loads \rightarrow Define Loads \rightarrow Apply"), and the Solution processor

("Main Menu \rightarrow Solution \rightarrow Define Loads \rightarrow Apply").

- 1. Select the kind of constraint you want to apply.
- 2. Select the geometric entity where you want it applied.
- 3. Enter the value and direction for it.

There is no "modify" command for loads and B.C.'s. If you make a mistake simply apply it again with a new value (the old one will be replaced if it's on the same entity), or delete it and reapply it.

Loads: Forces, pressures, moments, heat flows, heat fluxes, etc.

Constraints: Fixities, enforced displacements, symmetry and anti-symmetry conditions, temperatures, convections, etc.

Although you can apply loads and boundary conditions to nodes or elements, it's generally better to apply all B.C.'s to your geometry. When the solve command is issued, they will be automatically transferred to the underlying nodes and elements. If B.C.'s are put on the geometry, you can re-mesh that geometry without having to reapply them

Solving:

Solution is the term given to the actual simultaneous equation solving of the mathematical model. The details of how this is done internally is beyond the scope of this guideline but is addressed in a separate "ANSYS Tips" white paper. For the moment, it is sufficient to say that the basic equation of the finite element method that we are solving is, $[K]{u}={F}$

where [K] is the assembled stiffness matrix of the structure,

{u} is the vector of displacements at each node, and

 $\{F\}$ is the applied load vector. This is analogous to a simple spring and is the essence of small deflection theory.

To submit your model to ANSYS for solving, go to "Main Menu \rightarrow Solution \rightarrow Solve \rightarrow Current LS". LS stands for load step. A load step is a loading "condition".

This is a single set of defined loads and boundary conditions (And their associated solution results. More on this in the next section). Within an interactive session the first solve you do is load step 1, the next solution is load step 2, etc.

If you leave the solution processor after solving to do post-processing for example, the load step counter gets set back to one. You can also define and solve multiple load steps all at once.


There are several solvers in ANSYS that differ in the way that the system of equations is solved for the unknown displacements. The two main solvers are the sparse solver and the PCG solver. If the choice of solvers is left to "program chosen" then generally ANSYS will use the sparse solver. The PCG (preconditioned conjugate gradient) solver works well for models using all solid elements. From a practical perspective one thing to consider is that the sparse solver doesn't require a lot of RAM but swaps out to the disk a lot. Disk I/O is very slow. If you have a solid model and lots of RAM the PCG solver could be significantly faster since the solution runs mostly in core memory

Postprocessing:

The General Postprocessor is used to look at the results over the whole model at one point in time. This is the final objective of everything we have discussed so far; finding the stresses, deflections, temperature distributions, pressures, etc. These results can then be compared to some criteria to make an objective evaluation of the performance of your design. The solution results will be stored in the results file as result "sets". For a linear static analysis like we are talking about, the correlation between Load Step numbers and Results Set numbers will be one to one as shown below. Only one set of results can be stored in the database at a time, so when you want to look at a particular set, you have to read it in from the results file. Reading it in clears the previous results set from active memory.

****	INDEX OF DA	TA SETS ON RI	ESULTS FIL	E xxxxx	
SET	TIME/FREQ	LOAD STEP	SUBSTEP	CUMULATIVE	
1	1.0000	1	1	1	
	2.0000	$\overline{2}$	ī	$\overline{2}$	
	3.0000	3	ī	3	
- Ă	4.0000	4	ī	4	
	5.0000	5	ī	5	
	6.0000	Ğ	ī	6	
Ž	7.0000	Ž	ī	7	
	8.0000	8	ī	8	
<u>9</u>	9.0000	9	ī	9	
10	10.000	10	ī	10	
11	11.000	11	ī	11	
12	12.000	12	ī	12	

To read in a results set from the results file (not needed if you have run only a single load step) use "Main Menu \rightarrow General Postproc \rightarrow Read Results \rightarrow First Set, or By Pick". Most results are displayed as a contour plot as shown below. To generate a plot of stresses use "Main Menu \rightarrow General Postproc \rightarrow Plot Results \rightarrow Contour Plot \rightarrow Nodal Solution", then pick the stresses you want to see



There are many, many other ways to look at your results data including:

- Listing them to a file.
- Querying with the mouse to find a result at a particular node.
- Graphing results along a path.
- Combining different load cases.
- Summing forces at a point.
- Extracting data and storing it an APDL array that you can do further operations with.


Animate any result on the deformed shape with "Utility Menu \rightarrow Plot Ctrls \rightarrow Animate". This is very helpful for understanding if your model is behaving in a reasonable way.

ANSYS EXERCISE (PART – A)

PART A.1:STRESS ANALYSIS OF BARS OF CONSTANT CROSS SECTION AREA

Problem 1

A steel rod subjected to compression is modeled by two bar elements, as shown in Figure. Determine the nodal displacements and the axial stress in each Element. E=207 GPa, $A = 500 \text{ mm}^2$



Procedure:

- 1. **Utility Menu > File > Change Jobname >** Enter 'Bar Analysis'
- 2. **Utility Menu > File > Change Title >** Enter Bar Analysis.
- 3. Preprocessor> Element type>Add/Edit/Delete>Add> Link1
- 4. Preprocessor> Real constant> Add/Edit/Delete>Add>Ok> Area>500
- 5. Preprocessor>Material Property> Young's Modulus > Enter Ex = 2e5.
- 6. **Preprocessor > Modeling > Create>node > In active CS > Create three nodes at Location** (0, 0, 0) (500, 0, 0) and (1000, 0, 0).
- 7. **Preprocessor** > **Modeling** > **Create** > **Element** > **Auto numbered** > **Thru node** > (Pick nodes (1, 2), (2, 3) and create element).
- 8. **Preprocessor** > **Load** > **Define** load > **Apply** > **Structural** > **Displacement**> **Select** Node number 1 and apply 'ALL DOF'.
- Preprocessor > Load > Define load > Apply> Structural > Force / moment on nodes > Select node number 3 and Enter value Fx = -12000 N.
- 10. Solution > Solve > Current LS
- 11. General postprocessor > Plot Results > Deform shape
- 12. Postprocessor> Contour plot> Nodal solution> Displacement vector sum.
- 13. Postprocessor>Element Table>Define Table>Add>By sequence num>LS 1
- 14. Postprocessor>Element Table>List Elem table>LS 1>ok

Comparison between theoretical and Ansys values

	Ansys	Theoretical
Deformation		
Stress		
Reaction		

Problem 2:

For the simple bar shown in the figure determine the displacements, stress and the reaction. The cross section of the bar is 500 mm², length is 1000mm and the Young's modulus is $E = 2x10^5$ N/mm². Take load = 1000N




Comparison between Ansys and Theoretical Results

	Ansys	Theoretical
Deformation		
Stress		
Reaction		

PART A. 2: STRESS ANALYSIS OF BARS OF TAPERED CROSS SECTION AREA

Problem 3

Obtain nodal displacements for the tapered bar. Use the following numerical values: $E = 10 \times 106$ lb/in2, A0=4 in2, L = 20 in, P = 4000 lb.



Procedure:

- 1. **Utility Menu > File >** Change Jobname
- 2. **Utility Menu > File >** Change Title
- 3. Preprocessor> Element type>Add/Edit/Delete>Add> Link1.
 4. Preprocessor> Real constant> Add/Edit/Delete>Add>Ok> Area>
- (create 2 set of Real Constant) > A1 = 3.5 in² and A2 = 2.5 in².
- 5. Preprocessor>Material Property> Young's Modulus > Enter Ex= 10e6.

6. **Preprocessor > modeling > Create > Node > In active CS> Create 3 Nodes >** (0, 0, 0),

(0,-10, 0) and (0,-20, 0).

- 7. **Preprocessor>Modeling >Create>Element> Element Attributes** (you can set Real Constant number set to 1).
- 8. **Preprocessor>Modeling >Create>Element >Auto numbered >Thru Node>** (Pick nodes and create element between nodes 1 and 2)

9. Repeat the procedures given in 7 and 8 set Real constant number to 2 and create element between nodes 2 and 3.

10. **Preprocessor>Load>Define load> Apply> Structural> Displacement>** on nodes and

select node 1 and **Apply 'ALL DOF'** in the wizard.

- 11. Preprocessor>Load>Define load> Apply> Structural>Force / moments > on Nodes >
- Select node number '3' and **Apply a force Fy = -4000**.
- 12. Solution> Solve> Current LS.
- 13. General postprocessor > Plot Result > Deform shape
- 14. Postprocessor > Contour plot > Nodal solution > Displacement vector sum.


Comparison between theoretical and Ansys values

	Ansys	Theoretical
Deformation		
Stress		
Reaction		

Problem 4


For the tapered bar shown in the figure determine the displacement, stress and reaction in the bar.

Given $A_1 = 1000 \text{ mm}^2$ and $A_2 = 500 \text{ mm}^2$, $E = 2x10^5 \text{ N/mm}^2$



The Tapered bar is modified into 2 elements as shown below with modified area of cross section

 $(1000+500)/2 = 750 \text{ mm}^2$ A₁ = (1000+750)/2 = 875 mm² A₂ = (750+500)/2 = 625 mm²




Comparison between Ansys and Theoretical Results

	Ansys	Theoretical
Deformation		
Stress		
Reaction		

PART A.3: STRESS ANALYSIS OF A STEPPED BAR Problem 5

Determine the nodal displacements and Reaction forces for the Stepped bar shown below.



Procedure:


- 1. Utility Menu > File > Change Job name
- 2. Utility Menu > File > Change Title
- 3. Preprocessor> Element type>Add/Edit/Delete>Add> Link1.
- 4. **Preprocessor > Real constant> Add/Edit/Delete > Add > Ok> Area >** (create 2 set of real constants).
- 5. Preprocessor>Material Property>Material Models> Young's Modulus >Enter Ex= 15e6 Under Material Models>Material>New Model (define the second property) Enter Ex = 10e6.
- 6. **Preprocessor > Modeling > Create > Node > In active CS> Create 3 Nodes** (0, 0, 0),(20, 0, 0) and (40, 0, 0).
- Preprocessor>Modeling > Create>Element> Element Attributes
 (you can see 2 real Constant sets and 2 material properties select the real constant
 number 1 and create element).
- 8. **Preprocessor>Modeling >Create>Element >Auto numbered >Thru Node>** (pick nodes 1 and 2 and create element).
- 9. Repeat the procedure given in 7 and 8 by choosing material number 2 and real Constant number 2 and create element between nodes 2 and 3.
- 10.*Preprocessor>Load>Define load> Apply> Structural> Displacement > on Nodes >* Pick node number 1 and apply 'All Dof'.
- 11. Preprocessor>Load>Define load> Apply> Structural >Force > on Nodes > Apply
 - $F_{X} = 2000.$
- 12. Solution > Solve > Current LS
- 13. General postprocessor > Plot Result > Deform shape.
- 14. Postprocessor> Contour plot> Nodal solution> Displacement vector sum.
- 15. General Post processor >List Result > Reaction solu >All structural force 'F'.

	Ansys	Theoretical
Deformation		
Stress		
Reaction		

Comparison between theoretical and Ansys values

Problem 6:

A Stepped bar is subjected to axial load as shown in the figure find the Stress Reactions for the following following problem using Link 1 Element. Given Data: $A_1 = 40 \text{ mm}^2$, $A_2 = 20 \text{ mm}^2$




Comparison between Ansys and Theoretical Results

	Ansys	Theoretical
Deformation		
Stress		
Reaction		

Problem 7:

Consider the bar in figure. Determine the nodal displacements, element stresses & support reactions. The Temperature is then raised to $60^{\circ}C E = 200 \times 10^{9} \text{ N/m}^{2}$

Solution:




When temperature raised to 60° C.

	Element	Deflection		Load/ Reaction (KN)		Stress N/mm ²	
No	No	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							

Problem 8:

- a. Determine the displacements, stresses & Support reactions
- b. In the structure is subjected to an increase in Temperature of 80°C. Determine the Displacements, Support Reactions & Stresses



Solution:

	Element No	Deflection		Load/ Reaction (KN)		Stress N/mm ²	
No	INU	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							


When temperature raised to 80° C.

	Element Deflection		ection	Load/ Reaction (KN)		Stress N/mm ²	
No	No	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							

CAMA-LAB (06MEL67)

Problem 9:

An Axial load $P = 300 \times 10^3$ N is applied at 20°C to the rod as shown in figure. Determine the nodal Displacements, Reaction & Stresses.




Solution:

Node	Element	Deflection		Load/ Reaction (KN)		Stress N/mm ²	
No	No	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							

Problem 10:

a. An axial load of $P = 300 \times 10^3$ N is applied at 20°C to the rod as shown in Figure. Determine the nodal Displacements, reactions & Stresses

b. In the temperature is raised to 60°C. Determine the Displacements, Support Reactions & Stresses



Solution:

Node	Element Deflection		ection	Load/ Reaction (KN)		Stress N/mm ²	
No	No	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							


In the temperature is raised to 60°C.

Node	Element Deflection		Load/ Reaction (KN)		Stress N/mm ²		
No	No	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							

CAMA-LAB (06MEL67)

Problem 11:

Consider the bar shown in figure. An axial load $p = 200 \times 10^9$ N is applied as shown. Determine the nodal displacements and the reaction forces




Solution:

	Element	Deflection		Load/ Reaction (KN)		Stress N/mm ²	
No	No	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							

Problem 12:

Determine the displacement field, support reactions and stress in the body shown as loaded. Use 1D bar element E=20Gpa, A=250mm², P=60KN



CASE A


Node	Element No	Deflection		Load/ Reaction (KN)		Stress N/mm ²	
No	INU	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							

CASE B: When the displacement g =1.2mm is given

Node	Element Deflection		ection	Load/ Reaction (KN)		Stress N/mm ²	
No	No	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							

Problem 13:

An axial load $P= 500 \times 10^3$ N is applied at 40° c to the rod as shown in figure. Determine the nodal displacements, reaction and stresses.




Solution:

Node	Element	Deflection		Load/ Reaction (KN)		Str N/n	ress nm ²
No	No	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							

Problem 14:

Determine the Nodal displacement and Maximum stress in a 1D stepped bar made of steel and aluminum subjected to point load and thermal load with the boundary conditions as shown.

 $\begin{array}{l} T_{o} = 20^{0}\text{C and } T_{f} = 80^{0}\text{C}, \\ E_{steel} = 2e5 \ \text{N/mm}^{2} \\ E_{Al} = 0.7e5 \ \text{N/mm}^{2} \\ \text{Area of steel}, \qquad A_{steel} = 1000 \text{mm}^{2} \\ \text{Area of aluminum } A_{al} = 500 \text{mm}^{2} \\ \alpha_{steel} \qquad = 11.7e\text{-}6/^{0}\text{C} \\ \alpha_{aluminum} = 23e\text{-}6/^{0}\text{C} \end{array}$




Solution:

Node No	Element	Element Deflection		Load/ R (K	Reaction N)	Str N/n	
INO	INU	Theory	Ansys	Theory	Ansys	Theory	Ansys
1							
2							
3							
4							

PART A. 4: ANALYSIS OF TRUSSES Problem 15

The two-element truss in Figure is subjected to external loading as shown. Using the same node and element numbering as in Figure, determine the displacement components of node 3, the reaction force components at nodes 1 and 2, and the element displacements, stresses and forces. The elements have modulus of elasticity $E1 = E2 = 10 \times 106$ lb/in2 and cross-sectional areas A1 = A2 = 1.5 in2.



Procedure:

- 1. Utility Menu > File > Change Job name
- 2. Utility Menu > File > Change Title
- 3. Preprocessor> Element type>Add/Edit/Delete>Add> Link1.
- 4. Preprocessor> Real constant> Add/Edit/Delete>Add>Ok> Area>1.5.
- 5. Preprocessor>Material Property> Young's Modulus > Enter 10e6.
- 6. **Preprocessor > Modeling > Create > Node >In Active CS >** Create 3 nodes Node 1 = (0, 0, 0), Node 2 (0, 40, 0) and Node 3 (40, 40, 0).
- 7. **Preprocessor>modeling >create>element >auto numbered >thru node>** (pick nodes and create element between nodes (1, 3) and (2, 3)).

8. Preprocessor>Load>Define load> Apply> Structural> Displacement> on

nodes >

- Select nodes 1 and 2.
- 9. **Preprocessor > Load > Define load > Apply > Structural > Force/ moment on nodes >**
 - Select node number 3 and Apply a force Fy' = 300
- 10. Solution > Solve > Current LS
- 11. General postprocessor > plot Result > Deform shape
- 12. Postprocessor> Contour plot> Nodal solution> Displacement vector sum.
- 13. General Postprocessor > List Result > Reaction Solu > All 'struc forcF'.

Results

1. Nodal solution and Displacements

Node No	Ux (Theory)	Ux (ANSYS)	Uy (Theory)	Uy (ANSYS)
1				
2				
3				
4				


2. Elemental Solution and Displacement

Element No	Stress (Theory)	Stress (ANSYS)
1		
2		
3		
4		

Node No	Fx (Theory)	Fx (ANSYS)	Fy (Theory)	Fy (ANSYS)
1				
2				
3				
4				

Problem 16:

For the two bar truss shown in figure, determine the reaction forces, nodal displacement and element Stress.



Results

1. Nodal solution and Displacements

Node No	Ux (Theory)	Ux (ANSYS)	Uy (Theory)	Uy (ANSYS)
1				
2				
3				
4				


2. Elemental Solution and Displacement

Element No	Stress (Theory)	Stress (ANSYS)
1		
2		
3		
4		

Node No	Fx (Theory)	Fx (ANSYS)	Fy (Theory)	Fy (ANSYS)
1				
2				
3				
4				

Problem 17:

For the two bar truss shown in figure, determine the reaction forces, nodal displacement and element Stress.



Results

1. Nodal solution and Displacements

Node No	Ux (Theory)	Ux (ANSYS)	Uy (Theory)	Uy (ANSYS)
1				
2				
3				
4				

2. Elemental Solution and Displacement


Element No	Stress (Theory)	Stress (ANSYS)
1		
2		
3		
4		

Node No	Fx (Theory)	Fx (ANSYS)	Fy (Theory)	Fy (ANSYS)
1				
2				
3				
4				

Problem 18:

For the Pin jointed configuration shown in figure

- a. Calculate the reaction forces
- b. Nodal Displacements
- c. Element Stresses.



Results

1. Nodal solution and Displacements

Node No	Ux (Theory)	Ux (ANSYS)	Uy (Theory)	Uy (ANSYS)
1				
2				
3				
4				


2. Elemental Solution and Displacement

Element No	Stress (Theory)	Stress (ANSYS)
1		
2		
3		
4		

Node No	Fx (Theory)	Fx (ANSYS)	Fy (Theory)	Fy (ANSYS)
1				
2				
3				
4				

Problem 19:

Consider the four bar truss shown in figure. It is given that E=200 Gpa and Area= 625 mm² for all elements. Calculate the reaction forces, Nodal displacement and element stresses.



Results

1. Nodal solution and Displacements

Node No	Ux (Theory)	Ux (ANSYS)	Uy (Theory)	Uy (ANSYS)
1				
2				
3				
4				


2. Elemental Solution and Displacement

Element No	Stress (Theory)	Stress (ANSYS)
1		
2		
3		
4		

Node No	Fx (Theory)	Fx (ANSYS)	Fy (Theory)	Fy (ANSYS)
1				
2				
3				
4				

Problem 20:

For truss shown in figure an horizontal load of P= 18KN is applied in the direction at Node 2. Calculate the reaction forces, Nodal displacement and element stresses.



Results

1. Nodal solution and Displacements

Node No	Ux (Theory)	Ux (ANSYS)	Uy (Theory)	Uy (ANSYS)
1				
2				
3				
4				

2. Elemental Solution and Displacement


Element No	Stress (Theory)	Stress (ANSYS)
1		
2		
3		
4		

Node No	Fx (Theory)	Fx (ANSYS)	Fy (Theory)	Fy (ANSYS)
1				
2				
3				
4				

Problem 21:

Two bar truss shown in fig. Determine the nodal displacements and the stress in each member.

Take E = 210 X 10⁹ Pa, Area A= 0.01m²



Results

1. Nodal solution and Displacements

Node No	Ux (Theory)	Ux (ANSYS)	Uy (Theory)	Uy (ANSYS)
1				
2				
3				
4				

2. Elemental Solution and Displacement


Element No	Stress (Theory)	Stress (ANSYS)
1		
2		
3		
4		

Node No	Fx (Theory)	Fx (ANSYS)	Fy (Theory)	Fy (ANSYS)
1				
2				
3				
4				

Problem 22:

Consider a 4 Bar Truss as shown in the below figure. And solve the problem for displacement stress and Reaction Forces

Data: $A=100 \text{ mm}^2$, $E=2x10^5 \text{ N/mm}^2$, Poisson ratio is 0.3.



Results

1. Nodal solution and Displacements

Node No	Ux (Theory)	Ux (ANSYS)	Uy (Theory)	Uy (ANSYS)
1				
2				
3				
4				


2. Elemental Solution and Displacement

Element No	Stress (Theory)	Stress (ANSYS)
1		
2		
3		
4		

Node No	Fx (Theory)	Fx (ANSYS)	Fy (Theory)	Fy (ANSYS)
1				
2				
3				
4				

Problem 23:

Consider a 3 Bar Truss as shown in the below figure. And solve the problem for displacement stress and Reaction Forces The cross-sectional area of each member is 0.01 m, the Young's modulus is $200 \times 10^9 \text{ N/m}^2$ and Poisson ratio is 0.3.



Results

1. Nodal solution and Displacements

Node No	Ux (Theory)	Ux (ANSYS)	Uy (Theory)	Uy (ANSYS)
1				
2				
3				
4				


2. Elemental Solution and Displacement

Element No	Stress (Theory)	Stress (ANSYS)
1		
2		
3		
4		

Node No	Fx (Theory)	Fx (ANSYS)	Fy (Theory)	Fy (ANSYS)
1				
2				
3				
4				


Problem 24: (For Practice)

The below figure shows a truss with a roller support at node 4. The area of cross section of the elements of the truss is 120 Sq.mm. The force acting on the nodes are shown in the figure. It is supported at node 1 by a hinged joint, Node 4 is supported on a roller arrangement and the support allows a freedom of movement at an angle of 30° . Determine the nodal displacement, reactions and stresses in the truss member shown in figure.




Problem 25: (For Practice)

The figure shows a truss element loaded with 500N at node 2. All horizontal members have an area of 100 Sq.mm and inclined members an area of 80 sq.mm. Young's modulus (E) of element 3= 80Gpa and other element is 210 Gpa. Determine the nodal displacement, reactions and stresses in the truss member shown in figure.




Problem 26: (For Practice)

Consider a Truss as shown in the below figure. And solve the problem for displacement stress and Reaction Forces Cross-sectional area of truss members = $3.0E-4 \text{ m}^2$; Modulus of Elasticity = $2.07E11 \text{ N/m}^2$. Circled numbers shown are node numbers



PART A. 5: STRESS ANALYSIS OF BEAMS Problem 27

Consider a cantilever beam of length 1000mm, subjected to uniformly varying load 0 to 500N/mm. Young's modulus 2e5 N/mm2. The cross section is rectangular with Breadth and Height of 10mm. Obtain the shear force and bending moment diagrams. Obtain the values of deflection, bending moment, maximum bending stress.



Procedure:

1. Utility Menu > File > Change Job name

- 2. Utility Menu > File > Change Title > Cantilever Beam
- 3. **Preprocessor> Element type > Add/Edit/Delete > Add > Beam3**
- 4. Preprocessor > Real constant >Add/Edit/Delete > Add > OK > Area = 100 > Area

moment of inertia = 833.33> Height = 10.

- 5. **Preprocessor >Material Property > Material models > Young's Modulus >** Enter Ex = 2e5.
- 6. **Preprocessor > Modeling > Create > Nodes >In Active CS > Create three nodes**

Node number 1 = (0, 0, 0)

Node number 2 = (1000, 0, 0)

7. **Preprocessor >modeling > create>element >auto numbered >thru node>** (Pick nodes (1, 2) and create one element).

8. Preprocessor>Load>Define load> Apply> Structural> Displacement> On Nodes >

Select node 1 > Apply `ALL DOF'.

9. **Preprocessor > Load > Define load > Apply > Structural>pressure>on beam> Select**

the First element > OK >give the pressure value '0' in VALI and '500' in VALJ. 10. *Solution > Solve> Current LS.*

12. General postprocessor > plot Result > Deform shape

13. Postprocessor> Contour plot> Nodal solution> Displacement vector sum.

14. To find Bending moment

Postprocessor>element table>Define table> add>by sequence number>SMISC 6>ok

Postprocessor>element table>Define table> add>by sequence number>SMISC 12>ok

14. To plot the Bending moment results

General Postprocessor > Contour plot > Line elem Res

15. Similarly for shear force, max and min stress

Postprocessor>element table>create table> add>by sequence number>SMISC 2>ok

Postprocessor>element table>create table> add>by sequence number>SMISC 8>ok


Postprocessor>element table>create table> add>by sequence number>NMISC 1>ok

Postprocessor>element table>create table> add>by sequence number>NMISC 3>ok Postprocessor>element table>create table> add>by sequence number>NMISC 2>ok Postprocessor>element table>create table> add>by sequence number>NMISC4>ok

Loading	Deflection (mm)		Bending Moment (N/mm)		Max.Bending Stress (N/mm ²)	
	ANSYS	Theory	ANSYS	Theory	ANSYS	Theory
1						
2						
3						

Problem 28:


The figure shows a loaded beam subjected to various types of loading. E = 200Gpa & I = 4×10^6 mm⁴.



Result	Node No	Deflection (mm)	Node No	Beding Moment (N-mm)	Element No	Max. Bending Stress (N/mm ²)
	1		1		1-2	
	2		2		2-3	
	3		3		3-4	
	4		4		4-5	
ANSYS	5		5		5-6	
	6		6		6-7	
	7		7		7-8	
	8		8		8-9	
	9		9			
	1		1		1-2	
	2		2		2-3	
	3		3		3-4	
	4		4		4-5	
Theory	5		5		5-6	
-	6		6		6-7	
	7		7		7-8	
	8		8		8-9	
	9		9			

Problem 29:

Determine the end forces of a clamped beam due to a 25mm settlement at the right end. A = 50 x 50 Sq. E = 200 Gpa $I = 2mm^4$



Result	Node No	Deflection (mm)	Node No	Beding Moment (N-mm)	Element No	Max. Bending Stress (N/mm ²)
	1		1		1-2	
	2		2		2-3	
ANSYS	3		3		3-4	
	4		4		4-5	
	5		5			
	1		1		1-2	
Theory	2		2		2-3	
-	3		3		3-4	
	4		4		4-5	
	5		5			

Problem 30:

A 2m Long Cantilever with rectangular section (60mmx90mm) is subjected to concentrated load of 4KN at the free end of the beam. Determine the Deflection, maximum stress due to bending, Bending moment and Shear Force. Take E = 200Gpa. $P = 4 \times 10^3$ N, Length L = 2m = 2000 mm




Results:

Loading	Deflection (mm)		Bending Moment (N/mm)		Max.Bending Stress (N/mm ²)	
	ANSYS	Theory	ANSYS	Theory	ANSYS	Theory
1						

Problem 31:


A 2m Long Cantilever with rectangular section (60mmx90mm) is subjected to Uniformly Distributed load of 4 KN/m through out its Length. Determine the Deflection, maximum stress due to bending, Bending moment and Shear Force. Take E = 200Gpa. Length L = 2m = 2000 mm



Loading	Deflection (mm)		Bending Moment (N/mm)		Max.Bending Stress (N/mm ²)	
	ANSYS	Theory	ANSYS	Theory	ANSYS	Theory
1						

Problem 32:

A distributed load of 1000 N/m (1 N/mm) will be applied to a solid steel beam with a rectangular cross section as shown in the figure below. The cross-section of the beam is (10mm x 10mm) while the modulus of elasticity of the steel is 200GPa. Determine the Deflection, maximum stress due to bending,




Results:

Loading Deflection (mm)		on (mm)	Max.Bending Stress (N/mm ²)		
	ANSYS	Theory	ANSYS	Theory	
1					

Problem 33:

A simply supported Beam of 3m Span as shown in the figure is subjected to a load of 5 kN/m. determine the max deflection and Stress E=200 Gpa, $I=10^8$ mm⁴



Loading	Deflectio	on (mm)	Max.Bending Stress (N/mm ²)		
	ANSYS	Theory	ANSYS	Theory	
1					

Problem 34:

Loads will not be applied to the beam shown below the beam is to be made of steel with a modulus of elasticity of 200 GPa. Find the max deflection and Stress due to the Self Weight of the Beam.



Loading	Deflection (mm)		Max.Bending Stress (N/mm ²)	
	ANSYS	Theory	ANSYS	Theory
1				


Chapter 4

ANSYS EXERCISE (PART – B)

PART B.1: STRESS ANALYSIS OF RECTANGULAR PLATE WITH A CIRCULAR HOLE

Problem 35

Stress analysis of a rectangular Plate with Hole. Let 2w = 100 mm, 2h = 50 mm, a = 10 mm, $\sigma_0 = 100$ Mpa.



Procedure -

- 1. Utility Menu > File > Change Job name
- 2. Utility Menu > File > Change Title > Stress analysis of a Plate
- 3. Preprocessor > Element type > Add/Edit/Delete > Add > Solid > Quad 4 node 42
- 4. Preprocessor>Material Property> Young's Modulus > Enter Ex = 2e5 and Poisson's ratio = 0.3.
- 5. The model is symmetric we are going to create ¼ of the model. Preprocessor>modeling >create> Area > Rectangle> By Dimensions> 0, 100 (X1, X2) (0, 50) for (Y1, Y2).
- 6. Preprocessor>Modeling > Create> Area >Circle > Solid circle > (define dimensions). Enter WP X = 50, WP Y = 25, Radius = 10.
- 6. Preprocessor>modeling>operate>Booleans>subtract>areas> (select the bigger Area first click apply and select the smaller one and click OK).
- 8. Preprocessor >Meshing>Mesh tool>Smart size ON>Free> Quad >Mesh > Pick all.
- 9. Preprocessor>Load>apply>Structural>Displacement>symmetry B.C>on line (Select the line on X coordinates Zero and Y coordinates Zero and apply Symmetric BCs).
- 10. **Preprocessor>Load>apply>Structural> pressure> on line > Enter VALI = 100.**
- 11. Solution > Solve > Current LS

12. General postprocessor > Plot Result > Deform shape

- 13. General postprocessor> Plot Result> Contour Plot> Nodal Solution>Displacement Vector Sum.
- 14. General postprocessor > Plot Result > Contour Plot > Nodal Solution >Stress >von Misses stress


15. To Expand the Model.

Plot control > Style > Symmetry Expansion > Periodic /Cyclic Symmetry>1/4 Expansion > OK.

	ANSYS	Theory
Deformation		
Stress		

Problem 36


Determine the location and magnitude of the maximum stress in the plate as shown in figure.



	ANSYS	Theory
Deformation		
Stress		

Problem 37


Determine the location and magnitude of the maximum stress in the plate as shown in figure.



	ANSYS	Theory
Deformation		
Stress		

Problem 38:

Determine the maximum stress for a rectangular plate of 50mm x 80 mm with hole of 10 mm diameter in the center is loaded in axial tension. Thickness of the Plate is 10mm. Take E = 200 GPa



Analytical Solution

$\sigma_{nom} = F / (w - a) t = 10000 / (50 - 10) 10 = 25 N/mm^2$ Results:

Stress concentration factor K_{σ} = σ _{max} / σ _{nom}

$$2.5 = \sigma_{max} / 25$$

$$\sigma_{max}$$
 = 2.5 x 25 = 62.5 N/mm²

	ANSYS	Theory
Deformation		
Stress		


Problem 39: (For Practice)

We will model the bracket as a solid 8 node plane stress element. By a plane stress element we are assuming that there are no stresses in the thickness direction of the bracket.

Geometry: The thickness of the bracket is 3.125 mm


Material: Assume the structure is made of steel with modulus of elasticity E=200 GPa. Boundary conditions: The bracket is fixed at its left edge.

Loading: The bracket is loaded uniformly along its top surface. The load is 2625 N/meter.



PART B.2: THERMAL ANALYSIS Problem 40

For the rectangular slab shown in the above figure find out the temperature distributions for the boundary conditions indicated. Assume material to be made of Copper.



- 1. Change Job name
- 2. Utility Menu > File > Change Title > Thermal Analysis.

3. Preprocessor> Element type>Add/Edit/Delete>Add>Thermal>solid>plane55

4. Preprocessor>Material Property>Thermal> Conductivity>Isotropic>

(Give conductivity value in Kxx) > Enter Kxx = 386 W/mK

5. **Preprocessor>Modeling>create>Area>Rectangle>By Dimension >(give dimension) X2=10 and Y2=20.**

6. **Preprocessor>Meshing>Mesh tool>smart size ON>Free>Quad>Mesh>pick all** 7. **Preprocessor>Load>Apply>Thermal>Temperature>on line>Give 100 for 3** *lines and for the top line give 200.*

8. Solution>Solve>Current LS.

9. General Postprocessor > Plot Result>contour Plot>Nodal Solution>DOF Solution > Nodal Temperature

ii) In this example you will learn to model a 2D block subjected to varying boundary conditions. Using ANSYS will allow you to output the temperature distribution in an extremely simple and accurate way. By using any combination of these boundary conditions one can model almost any 2D heat transfer situation. We assume that our block is a rectangle (1m x 2m) made entirely of steel.

Boundary Conditions:

1) The top is insulated.

2) The right side has a constant temperature of 100K.

- 3) The left side has constant heat flux into the block of 50 W/m^2.
- 4) The bottom side is exposed to a convective boundary layer.

Material Properties: (Steel)
Convection film coeff h = 50 W/ (m^2*K)
Thermal conductivity k = 20 W/m K.
Objective: To determine the nodal temperature distribution and create contour plot.
1. Utility Menu > File > Change Job name.
2. Utility Menu > File > Change Title.
3. Preprocessor> Element type>Add/Edit/Delete>Add>Thermal>Solid>

Plane55 4. Preprocessor>Material Property>Thermal> Conductivity>Isotropic>

(Give conductivity value in Kxx = 20 W/M K)

5. **Preprocessor>Modeling>create>Area>Rectangle>By Dimension> (give dimension) X2=1m and Y2=2m**

6. **Preprocessor>Meshing>Mesh tool>smart size ON>Free>Quad>Mesh>pick all** 7. **Preprocessor>Load>Apply>Thermal>Temperature>on line> Give 100 to** *right side Line.*

8. Preprocessor>Load>Apply>Thermal>Convection>on line> Select the bottom line and Enter values for film coefficient = 50 and bulk temperature = 200K. 9. Preprocessor>Load>Apply>Thermal>Heat Flux>On line> Enter the value = 50.


10. Solution>Solve>Current LS.

11. General Postprocessor>Plot Result>contour Plot>Nodal Solution>DOF Solution >Nodal Temperature.

Quantity	ANSYS	Theory
T ₂		
T ₃		
T ₄		
T ₅		

Problem 41:

A furnace wall is made of inside Silica brick (K = 1.5 W/mk) and outside magnesia brick (K= 4.9 W/mK), each 10 cm thick. The inner and outer surfaces are exposed to fluids at temperature of 820 0 C and 110 0 C respectively. The contact resistance for inner and outside surfaces is equal to 35 w/m²k. Find the heat flow through the wall per unit area per unit time and temperature distribution across the wall



$$k_{1} = 1.5 \text{ W/mK}$$

$$k_{3} = 4.9 \text{ W/mK}$$

$$L_{1} = L_{2} = 100 \text{mm}$$

$$T_{1} = 820^{\circ}\text{C}$$

$$T_{6} = 110^{\circ}\text{C}$$


$$R_{c} = 0.001 \text{m}^{2}\text{K/W}.$$

$$h_{1} = h_{4} = 35 \text{ W/m}^{2}\text{K}.$$

$$R_{c} = \frac{L_{2}}{K_{2}A}$$

Take $L_2 = 1mm$, $k_2 = 1W/mK$ $A = 1m^2$

COMPOSITE WALL1- ANSYS analysis



For FE model,		
Element no.	Element Type	
2,3,4	LINK 32	
1,5	LINK 34	

COMPOSITE WALL1 – Theoretical solution:

$$Q = \frac{(T_1 - T_6)}{\frac{1}{A} \left(\frac{1}{h_1} + \frac{L_1}{K_1} + \frac{L_2}{K_2} + \frac{L_3}{K_3} + \frac{1}{h_4} \right)} = 4889.21W/m^2$$

$$Q = h_1 A(T_1 - T_2) \Rightarrow T_2 = 680.31^{\circ}C$$

$$Q = \frac{k_1 A(T_2 - T_3)}{L_1} \Rightarrow T_3 = 354.36^{\circ}C$$


$$T_1 = \frac{k_2 A(T_3 - T_4)}{L_2} \Rightarrow T_4 = 349.47^{\circ}C$$

$$Q = \frac{k_3 A(T_4 - T_5)}{L_2} \Rightarrow T_5 = 249.69^{\circ}C$$

Quantity	ANSYS	Theory
T ₂		
T ₃		
T4		
T ₅		
Heat flow		

Problem 42:


A plane wall 'X' (K = 75 W/mk) is 60mm thick and has volumetric heat generation of 1.5×10^6 w/m3. It is insulated on one side while the other side is in contact with surface of another wall 'Y' (k = 150 W/mk) which is 30 mm thick and has no heat generation. The free surface of wall 'Y' is exposed to a cooling fluid at 20 $^{\circ}$ C with a convection coefficient of 950W/m²k. find steady state temperatures at salient points across the composite wall



 $\label{eq:kx} \begin{array}{l} k_x = 75 \mbox{W/mK} \\ k_y = 150 \mbox{ W/mK} \\ L_x = 60 \mbox{mm} \\ L_y = 30 \mbox{mm} \\ T_f = 20^{\circ} \mbox{C} \\ q_g = 1.5 \mbox{x} 10^6 \mbox{ W/m}^3 \\ h = 950 \mbox{ W/m}^2 \mbox{K}. \\ A = 1 \mbox{m}^2 \end{array}$

COMPOSITE WALL with heat generation – Theoretical solution:

$$\begin{aligned} Q_g &= q_g A = 90000W / m^2 (= Q) \\ Q &= hA(T_3 - T_f) \Rightarrow T_3 = 114.7^{\circ}C \end{aligned} \qquad \begin{bmatrix} \mathbf{X} & \mathbf{Y} \\ \mathbf{q}_g \\ \mathbf{k}_x & \mathbf{k}_y \\ \mathbf{L}_x & \mathbf{L}_y \end{bmatrix}^{\mathbf{h}} \\ Q &= \frac{k_y A(T_2 - T_3)}{L_y} \Rightarrow T_2 = 132.7^{\circ}C \\ T_1 &= \frac{q_g}{2k_x} L_x^2 + T_2 \Rightarrow T_1 = 168.7^{\circ}C \end{aligned}$$




<u>For FE mode</u> (for areas A₁,A₂) Element Type : PLANE 55 (quad 4node) Option: Plane Thickness

Quantity	ANSYS	Theory
T ₁		
T ₂		
T ₃		

PART B.3: FLUID FLOW ANALYSIS Problem 43: Fluid flow analysis in 2D bodies

Air travels between two infinite plates. For the sake of modeling, these plates will be assumed to be 1.5 m long and 5 cm apart. All units are S.I. Boundary Conditions: Air enters between the plates at a uniform velocity of 0.1 m/s. Material Properties: Air: Density = 1.23 Kg/m3 Viscosity = 1.79 e -5 Dimensions Length = 1.5 m Width = 0.05 m

Objective: Find the nodal velocity distribution within the air gap between the two plates.



Preprocessing:

1. Start ANSYS

Go to Start > All Programs > ANSYS 11.0 > ANSYS Product launcher Specify the working directory and job name and click `Run'.

2. Create areas.

After opening ANSYS,

Click **Preprocessor>-Modeling->** and create the block as shown below.

Hint: Use key points and then create the outer area and the plate within it....OR... Create the large area using the **Create>Areas>Rectangle** (1.5m x 0.05m) command, then create the small plate and subtract the small plate from the large area.

3. Define the material properties.

Go to Preprocessor>Flotran Set Up>Fluid Properties.

On the box, shown below, change the first two input fields to **AIR-SI**, and then click on **OK**. Another box will appear. Accept all defaults on that box by clicking on **OK**.

Go to the ANSYS Main Menu.

Click **Preprocessor > Material Props > Material Models**. The following window will appear as shown below, in this menu

Choose **CFD>Density** and enter the value 1.23 and choose **CFD>Viscosity** and enter 1.79e-5.

4. Define fluid element type.

(2D Flotran 141 element, which is a 2-D element for fluid analysis)

Click **Preprocessor>Element Type>Add/Edit/Delete**... In the 'Element Types' window that opens click on Add... The following window opens.

Type **1** in the **Element type reference number**.

Click on **Flotran CFD** and select **2D Flotran 141**. Click **OK**. Close the **Element types** window. So now we have selected Element type **1** to be solved using **Flotran**, the

computational fluid dynamics portion of ANSYS. This finishes the selection of element type.

5. Specify meshing controls / Mesh the areas to create nodes and elements.

Under Ansys Main menu Choose > Meshing > Mesh tool > Set the smart size value to 1'.

Solution:

6. Specify boundary conditions.

Go to Preprocessor>Loads>Define Loads>Apply>Fluid CFD>Velocity>on lines. Pick

the left edge of the outer block and Click **OK**. The following window comes up. Enter 0.1 in the VX value field and click OK. The 0.1 corresponds to the velocity of 0.1 meter per second of air flowing from the left side. Repeat the above and **set the Velocity to ZERO** for the air along all of the edges of the flat plate. (VX=VY=0 for all sides). Now Atmospheric Pressure must be set for the top, bottom, and right side of the outer area. T o d o t h i s , s e l e c t **Preprocessor>Loads>Define Loads>Apply>Fluid**

CFD>Pressure DOF>on lines. Click the right most line.

Enter **0** for the constant pressure value for these faces and click **OK**. This sets the pressure to Atmospheric.

Once all the Boundary Conditions have been applied, the boundary conditions on the plates should look like this:

7. Specify number of solution iterations.

Go to ANSYS **Main Menu>Solution>Flotran Set Up>Execution Ctrl**. The following window appears. Change the first input field value to **20**, as shown. No other changes are needed. Click **OK**. (The reason behind setting the iterations so high is that when you run the Flotran Analysis, it stops only when the solution converges, or the solution reaches the number of iterations).

8. Solve.

Go to Solution>Run FLOTRAN.

9. Postprocessing:

Plot the contour plot of the velocity distribution.

Go to General Postproc >Read Results>Last Set.


T h e n g o t o **General Postproc>Plot Results>Contour Plot>Nodal Solution**. The following window appears –

10. Exit:

Toolbar > QUIT Utility Menu > File > Exit Use the /EXIT command in the Input Window

Problem 44:


The fluid is air, with density, ρ =1.23 kg/m₃, and dynamic viscosity, μ =1.79E-5 N-s/m₂.The plate is 1 m long, as shown, and is very thin. It will be modeled with a thickness of 0.001m.The plate is modeled in a square field, with edge lengths of 2 m. The 2 m edge length dimensions are arbitrary. These lengths are chosen large enough such that the effects of the flatplate on the flow are captured completely within the square field. Also, the flow velocity in alldirections is zero along the sides of the flat plate.



Problem 45:

Compute and plot the Velocity and Temperature distribution of a flow of air over a flat plate. Dimensions:

- The plate is **1 m long**.
- The flow area is **1 m by .25 m**. This arbitrary size serves to set up the boundary conditions of air traveling over the plate.
- The velocity of the air at infinite distance from the plate is 0.5 m/s.
- Atmospheric pressure is assumed on all faces except the face where velocity is input into the system.



Problem 46:

Air at 100 degrees Celsius travels between two infinite plates. For the sake of modeling, these plates will be assumed to be 1.5 m long and 5 cm apart. All units are S.I. Boundary Conditions:

1) Air enters between the plates at a uniform velocity of 0.1 m/s and 20 degrees Celsius.


2) The wall temperature is 100 degrees Celsius

Material Properties: AIR-SI

Dimensions

Length = 1.5 m

Width = 0.05 m




Problem 47:

Compute and plot the velocity distribution of a flow

Dimensions:

- The duct has an entrance region of **1m by 0.5m** and an exit region of **1m by 1m**. These two regions are separated by a horizontal distance of **1m**.
- The velocity of the air at infinite distance from the plate is 3 mm/s (0.003m/s). This velocity best demonstrates the recirculation zone while keeping the flow inside the duct laminar.




Problem 48:

Compute and plot the velocity distribution of a flow of air over an infinite cylinder.

Dimensions:

- The cylinder is **0.25 m** in diameter
- Because of symmetry, the problem is simplified so that only half of the cylinder is computed. The results are assumed to be the same on the other side of the x axis (axis of symmetry)
- The flow area is **2 m by 0.5 m**. This arbitrary size serves to set up the boundary conditions of flow over a cylinder.
- The velocity of the air at infinite distance from the plate is 5 mm/s (0.005m/s).



PART B.4: DYNAMIC ANALYSIS Problem 49:

Obtain the first five natural frequencies for the beam show below. Take material Properties young's modulus 2e5N/mm2, Density 7800e-12 Tonns/mm3.length of the Beam 1000mm cross section 10X10mm.



- 1. Utility Menu > File > Change Job name > Give Job name 'Simply supp'
- 2. Utility Menu > File > Change Title
- 3. Preprocessor > Element type >Add/Edit/Delete > Add>Beam3
- 4. Preprocessor> Real constant > Add/edit/delete > Add > Ok > Area (100) > Area Moment of Inertia (833.33)> Height (10)
- 5. Preprocessor>Material Property>structural>Linear>Elastic>Isotropic>give value for Young's Modules, Poisson ratio and density

6. Preprocessor > Modeling > Create > Key points > In Active CS> Enter the co-ordinates Here.

7. Preprocessor > Modeling > Create > Lines > Lines > Straight Line > Create a line between Key point 1 and Key point 2 and so on.

8. Preprocessor>Meshing>Mesh tool>Line set>No of division 10> Preprocessor>Meshing >Mesh tool>Mesh>pick all


9. Preprocessor>Load>Define load> Apply> Structural> Displacement> select key points on either side and constrain 'ALL DOF'.

10. Solution>Analysis Type>New Analysis>Set to Modal

- 11. Solution> Analysis Type> Analysis Option> No. of .modes to extract (10)> No of modes to expand 10>ok>ok
- 12. Solution>Solve>Current LS.
- 13. General Postprocessor > Read Results>By Pick> (you can see the frequency values)
- 14. Postprocessor> Contour plot> Nodal solution> Displacement vector sum.

SI No	Frequency
1	
2	
3	
4	
5	


Problem 50:



Results : Value (VS) Frequency Graph

Problem 51:

A Rectangular plate of dimensions 100x40x3is fixed at one its ends. It is subjected to 2 point loads at its free end. It is required to determine the natural frequencies and the frequency response of the plate. Also transient analysis is carried out.



Material Properties

 $E = 10000 \text{ kg/mm}^2$

v = 0.27

Density = $7.920e-10 \text{ kg/mm}^3$

Loading(in Z-direction)

F1 = 0.5 kg

F2 = 0.5 Kg


Analysis Type(s): Mode-frequency Analysis

Mode Superposition Harmonic Response Analysis

Mode Superposition Transient analysis

Problem 52:

The problem considered here is the vibration analysis of the right-angle frame.



Problem 53:


In this example we will find the first five natural modes and frequencies of a square plate with simply supported edges and a circular hole at its center, shown in Figure 6.1.

E = 70e9 (70 GPa) and

v = 0.3.

 $\rho = 2.7e3$ (2700 kg/cubic meter).


Dimension = 1 m x 1 mCircle = 0.2 m



MODE	Frequency
1	
2	
3	
4	
5	

Problem 54:

Simple Modal Analysis of a Cantilever Beam as shown below , Objective is to get the Frequency and Different modes of Vibration





To Determine the Natural Frequencies of a Cantilever Beam

Length	$\mathbf{L} =$	1	m
Breath	B =	0.1	m
Depth	D =	0.1	m
Young's Modulus	$\mathbf{E} =$	2.00E+11	N/m ²
Density	ρ=	7.830E+03	Kg/m ³
Aceln due to gravity	g =	9.810	m/Sec ²
PIE	$\pi =$	3.143	
Area	A =	0.01	m ²
M.I	I =	8.33333E-06	m ⁴
Density/L	$\rho_l =$	7.830E+01	Kg/m
S-Density	ο =	7.982E+02	Kg-Sec ² /m ⁴

Given Data

Theoretical Results:

Beam Constant

$(\beta_1 \mathbf{l})^2$	$(\beta_2 \mathbf{l})^2$	(β ₃ l) ²
3.52	22.00	61.70


Circular Frequency

$\omega_{n1} =$	(β ₁ l)²√(El)/(ρl⁴)	1.608E+03
$\omega_{n2} =$	(β ₂ l)²√(El)/(ρl⁴)	1.005E+04
$\omega_{n3} =$	(β ₃ l)²√(El)/(ρl⁴)	2.819E+04

Natural Frequencies	$\mathbf{f}_{\mathbf{n1}} =$	$\omega_{n1}^{}/2\pi =$	255.89749
	$\mathbf{f}_{n2} =$	$\omega_{n2}^{}/2\pi ~=~$	1599.3593
	$\mathbf{f}_{n3} =$	$\omega_{n3}^{}/2\pi =$	4485.4759

Mode	ANSYS (Frequency)	Theory(Frequency)
1		
2		
3		

Problem 55: Determine the Modal Deflections for the Truss System below E = 200GPa, $A = 3250 \text{ mm}^2$



Mode	Frequency
1	
2	
3	
4	

COMPUTER AIDED MODELING AND ANALYSIS LAB VIVA QUESTIONS

- 1. What is the total degree of freedom of Ansys commercial package.
- 2. What are the different menus in ANSYS.
- 3. What is Work space and Swap space.
- 4. What is default value of worksplace and Swapspace?
- 5. What file format ANSYS can support
- 6. What is the current ANSYS version
- 7. What is optimization in ANSYS.
- 8. What is sub structuring and adaptive meshing.
- 9. Which package is better ANSYS or NASTRAN.
- 10.What is Resume in ANSYS.
- 11. What is P-method and H-method
- 12. What is scalar parameters in ANSYS.
- 13. What are primary nodes and Secondary nodes.
- 14. What is Mirror (Reflection).
- 15.What is subroutines.

VIVA QUESTIONS ON FEM

Q.1) What are the different approximate solution methods.

Different approximate solution methods are

- 1. Functional approximation
- 2.Finite Difference method
- 3. Finite Element method

Q.2) What do you mean by continuum. Structure which is considered for analysis is called continuum.

Q.3) Define term node

The element which is connected with another element at junction is called node.

Q.4) Define term element Descritised structure is called an element .

Q.5) What is convergence Process of achieving value to actual solution.

Q.6) What are the types convergence p-convergence h-convergence

Q.7) What is p- convergence Convergence by increasing the elements Q.8) What is h convergence Convergence by increasing nodes

Q.9) What is higher order elements

The element which contain more no. of nodes are called higher order element .

Q.10) Give example for higher order elements

Higher order elements are CST, Quadrilateral element.

Q.11) What do you mean by compatible elements.

Elements, which are compatible with adjacent element, like no discontinuity, overlap or sudden slope.

Q.12) What is geometric invariance.

The property in which the shape of the element will not change with change in local coordinates is called geometric invariance.

Q.13) Why do we use Pascal's triangle in FEA

If the displacement equation doesn't contain all the required terms then balancing is done by the Pascal's triangle.

Q.14) What are the steps involved in FEA

- Steps involved in FEA:
- 1.Modelling
- 2.Descritization of structure
- 3.Derivation of elemental stiffness matrix.
- 4. Assembly of elemental equation
- 5. Applying boundary conditions
- 6.Computation of stress and strain
- 7.Interpretation of results

Q.15) what is stiffness matrix

The matrix when contain parameters like E, A, displacement and applied force is stiffness matrix

.Q16) How to obtain stiffness matrix

Stiffness matrix can be obtained by applying condition of minimum potential energy to potential energy equation.

Q.17) What is displacement function

: Displacement function is the assumed polynomial equation, which satisfies boundary conditions.

Q.18) How to identify order of elements

Order of elements depends on the no. of nodes.

Q.19) Mention different types of elements

Different types of elements are bar elements, beam element, truss element, shell element, axis symmetric.

Q.20) Mention some application of FEA Mechanical, Aerospace, Civil, structure analysis, biomedical, geo -mechanic, electromagnetic.

Q.21) What is connectivity. Relation between the connected elements is connectivity.

Q.22) What are the methods to improve problem solution Problem solution can be improved by increasing no. of elements or no. of nodes .

Q.23) Define symmetry in matrix It is the square matrix in which the element of the row are same as that of element of column.

Q.24) What is plane stress Stress acting on 2-D element.

Q.25) What is plane strain Strain occurring in 2-D element.

Q.26) Compare FEA with solid mechanics complicated irregular structures are difficult in solid mechanics but FEA it's easier with greater accuracy.

Q.27) What are the packages available for FEA packages available for FEA: ANSYS, I-DEAS,NASTRAN,ABAQUS, COSMOS,ALGOL,PATRAN.

Q.28) Define potential energy Energy possessed by the body due to it's position

Q.29) Define minimum potential energy

for consertive system of all kinematically admissible displacement field those corresponding to equilibrium extremise the total potential energy if extreme condition is a minimum the equilibrium state is stable

Q.30) Write potential energy equation for cantilever beam $\Pi = EI/2 \int (d2y/dx^2) dx - pie$

Q.31) Mention 2 different methods to approach the model of physical system . Discrete system , continuum

Q.32) Difference between global co ordinate and local co ordinate

Global co-ordinate	Local co ordinate
1.Contain 2 degrees of freedom	Contain 1 degrees of freedom
2. Represented without prime	Represented with prime
3. Systematic schemes are used	No schemes are used
-	

Q.33) What is local coordinate

local coordinate contains 1-D.O.F. at each node.

Q.34) What is global co ordinate Global coordinate contains 2-D.O.F. at each node.

Q.35) General assumption made in stressAssumptions:1.Truss elements are connected by fracture less pin.2.Load is applied on the load.3.Only two forces compressive and tensile are considered.

Q.36)What is shape function

It is mathematical polynomial, which gives displacement within the element.

Q.37)What are two general natural coordinate Two general co-ordinates are $\eta(\text{eeta})$ and zeeta.

Q.38) Mention the range of natural co-ordinate Range of natural coordinates is -0 to 1 and -1 to 1.

Q.39) Number of shape function in CST Number of shape function in CST are three.

Q.40) Number of shape function in quadrilateral Number of shape function in quadrilateral are 4.

Q.41) Why we are using natural integration we are using natural integration to simplify the problem.

Q.42) Explain one point formula 1-point shape function contains one term $\int f(x)dx = w.f(x)$

Q.43) Explain two point formula 2-point shape function contains two term $\int f(x).dx = w1f(x1) w2f(x2)$

Q.44) Why we are using polynomial equation in FEA Polynomial equation gives continuous solution & it is simple to solve problem.

Q.45) What are the two important characteristics in stiffness matrix Characteristics of stiffness matrix is symmetric and bonded

Q.46) Mention two schemes to represent band width 2-Schemes are Horizontal numbering Vertical numbering

Q.47)What are forces involved in work potential Forces involved are Body force, Traction force and Point force

Q.48)What are the different methods to apply boundary condition

Elimination, multiconstraint, penalty method

Q.49) What is isoparametric elements

These are those the S.F. used to define variables of displacement equal to S.F. used to represent geometry.

Q.50) What is orthotropic elements

Material which has three orthogonal planes of symmetry said to be orthotropic elements. Only nine constants are required to describe constituent equation

Q.51) What is anisotropic elements The material which doesn't contain any plane of symmetry

Q.52) What is isotropic elements isotropic material is one in which every plane is plane of symmetry only two constants are enough to describe constituent equation

Q.53) What is super parametric elements GSF > DSF (geometric shape function, displacement shape function Q.54) What is sub parametric elements GSF < DSF

Q.55) Different coordinates involved in chain rule. Different coordinates involved in chain rule are normal, local and displacement coordinates.

Q.56) What are the 2 different approaches to study elasticity ? Strength of material , Theory of elasticity

Q.57) Mention any two methods to solve continuum problems.

1. Raleighritz method

2. Galerkin method

Q.58) List the properties of shape functions. SF for 1D bar element N1=0, N2= 0 at node 1 N1=0 N2= 1 at node 2 . Diff. Of S.F. S.F are constant

Q.59) Define truss. Structural member which is subjected to either tensile or compression

Q.60)What is weighted residual methods. It's a method in FEA for accurate solution avoiding error (residue = error)

Q.61)Different methods to solve weighed residual problem. Point allocation, Sub domain , Galerkein,least square.

Q.62)Explain the principle of virtual work.

If the force and displacement are unrelated by cause effect relation then the work is said to be virtual work.

Q.63) Explain the principle of virtual displacement.

Actual displacement is considered without bothering amount of force is called virtual displacement.

Q.64)What are different types of shape functions. Diff types are Lagarangian and Hermite Shape function

Q.65) Differentiate two types of shape functions. Lagarangian shape function only for variable Hermite shape function is for both variable and its derivative

Q.66) Mention some advantages of FEA over solid mechanics. 1.Applied for complicated structure

- 2. Analysis is simple
 - 3. More accurate solution

Q.67) Define Young's Modulus and Poisson's Ratio.

- E it is the ratio of stress and strain
- μ- It is the ratio of lateral strain and longitudinal strain

Q.68) Mention different types of elastic constants. Young's modulus, shear modulus, bulk modulus

Q.69)Specify the terms required to solve FEA problem. Meshing , properties of material, boundry condition and initial condition.

Q.70) What are the assumptions made in linear static problems. all displacement is small, material is isotrpic, linear, elastic solid with E and μ

Q.71) Which is the most accepted form of numerical integration in FEM? Gaussian Quadrature

Q.72)List the different approaches to derive integral equation Direct method , variation method, weighed residual method, energy method

Q.73)What are the advantages of symmetrical matrix. symmetrical matrix simplifies the calculation

Q.74) What are the different types of errors in FEA? Modeling error , Descritized and Numerical error

Q.75) What are the advantages of isoparametric elements Useful in modeling structure with curved edges They are versatile & they are used in 2-D and 3-D elasticity problems

Q.76). Define frontal method for finite element matrices.

In 3- dimensional problems, the size of the stiffness matrix increases rapidly even with the banded method of modeling. An alternative direct method that results in considerable saving in the use of computer memory is called frontal method.

Q.77) What is the another name of the 3-dimensional frames Space frames.

Q.78). Define beam elements.

Beam elements are slender members that are used for supporting transverses loading.

Q.79) Explain preprocessor steps. Determining the Nodal coordinates, connectivity, boundary condition, material information

Q.80) Explain processing steps. Stiffness generation, modification, solutions to the equation resulting in evolution.

Q.81) Explain post processing steps. Deformation confirmation, mode shapes, temperature and stress distribution, interpretation

Q.82) What are the difference b/w beams and plane frames. It is similar to beams expect that axial loads &axial deformations are present. The elements also have different orientation.

Q.83) Mention some common material properties. Isotropic, orthrotropic, ductility, brittleness

Q.84) What are the different types of analysis. Thermal, structural (load), fluid, electromagnetic analysis

Q.85) Define steady state analysis. The analysis carried out at constant temperature.

Q.86) What is the advantage of subjecting solids to axisymmetric loading. Axisymmetric loading reduces the 3-D problem into 2-D problems because of total symmetry about the z-axis.

Q.87) Define CST elements.

The constant strain triangle is that where the displacement inside an element is represented by 3-nodal displacement (3-shape functions).

Q.88) How to generate the data files for larger problems in FEA. Using MESHGEN program generates data files.

Q.89) Define mesh plotting

It is the convenient way of reviewing the coordinate and connectivity data is by plotting it using computer.

Q.90) Explain lumped mass matrices.

It is the total element mass in each direction is distributed equally to the nodes of the element, and the masses are associated with translational degrees of freedom.

Q.91) Briefly explain steps involved in Lagrangian method

- Formulation of potential energy function. assuming displacement function
- Checking displacement function considering boundary condition
- Substitute differential function in potential energy equation
- Potential energy function is minimized
- Unknown parameters are determined and substituted in assumed equation

Q.92) Explain steps involved in Gallerkins method.

Formulate differential equation of the equilibrium

Assume trial function, which satisfies boundary conditions

Substitute displacement function in differential equation then assume the difference due to approx. function be 'R' (residue)

Use gallerkin formula

Determine unknown terms and then substitute in differential function

Q.93) Define jacobian matrix.

The matrix which is defined explicitly in terms of the local coordinate is known as jacobian(J).

Q.94) Mention six components of stress. 3 linear stress along x, y, z direction 3 lateral stress along x, y, z direction

Q.95) Mention six components of strain. 3 linear strain along x, y, z direction 3 lateral strain along x, y, z direction

Q.96) Define Winkler foundations.

Large beams are supported on soil form a class of applications known as winkler foundations.

Q.97) Define variational principle

The problem which specifies a scalar quantity potential energy is defined in an integral form.

Q.98) How to solve the prismatic problems.

The coefficient of the ordinary differential equation are independent of one of the coordinate and the solution of the system can frequently carried out efficiently by standard analytical methods.

Q.99) Define stress & strain. Stress is the ratio of applied load to its area. Strain is the ratio of change in length to its original length.

Q.100) Mention the two distinct procedures available for obtaining the approximation in the integral forms. Method weighed residuals.

Method of variation functional.