



Formerly "Dealer Only" Parts, Now Available in the Aftermarket





DORMAN ENGINEERED SOLUTIONS DESIGNED TO CORRECT KNOWN OF FAILURE MODES

LOOK INSIDE FOR PARTS ENGINEERED TO SAVE YOU TIME AND MONEY

TO LEARN MORE, VISIT: WWW.DORMANPRODUCTS.COM/OEFIX

Suspension Air Compressors

Inflates and regulates active air suspension shock absorbers

Over 10 SKUs Available • Additional Coverage Coming Soon!

- 100% NEW, not remanufactured
- Includes additional components that are often not available separately, such as mounting bracket, motor, dryer, heat shield and air tubing (where applicable)
- Direct-fit plug for an easier and more secure connection

Failure Mode:

- Environment contamination, water intrusion and motor burnout
- Failure results in sagging suspension and dash trouble codes displayed



949-001

Cadillac 2013-07, Chevrolet 2013-07, GMC 2013-07



AVOID USING WORN OR RUSTED ORIGINAL BRACKETS

Dorman unit is fully assembled with brackets, and ready-to-install — no additional bench time needed!

NEW SUSPENSION COMPRESSOR COVERAGE:



Includes full bracket with sound/heat shield (not available separately from the Dealer)

949-009Buick Lucerne 2011-06, Cadillac DTS 2011-06



Includes vent tube to replace failure-prone original unit (not available separately from the Dealer)

949-200

Ford 2011-03, Lincoln 2011-03, Mercury 2011-03



Coverage for popular Ford applications with high original unit failure rates

949-202

Ford Expedition 2013-07, Lincoln Navigator 2013-07



Convertible Tops

5 SKUs Available



convertible tops

· High quality materials match OE form ,fit and function

• Features DOT compliant rear window

926-500

Mazda Miata 2005-99, Mazda Miata 1997-90

Brake Lights - High Mount

Direct replacement for a damaged brake light

Over 60 SKUs Available



 Features integrated LED bulbs to provide up to 10 times more brightness than standard bulbs

Failure Mode:

- · Original lamp burns out over time
- Collision

OE PROBLEM:

Original units are frequently replaced due to failed ballasts



Completely redesigned lamp features LEDs which eliminate the ballast failures commonly associated with original unit



Air Bag Clock Springs

Relays power to steering wheel functions and air bag

Over 60 SKUs Available

525-027

Buick 2004, Chevrolet 2004-02, GMC 2004-02, Oldsmobile 2004-02



Auto Trans Shift Tube Lever Pin

Retains shifter lever to steering column

924-440

Ford 2015-90, Lincoln 2004-90, Mercury 2007-90



Cables - Door Latch

Connects door handle to door latch mechanism

20 SKUs Available

924-481

Chevrolet 2014-10, GMC 2014-10

Center Console Hinge Repair Kit

Repair kit for a broken or damaged center dash console



 New money saving solution for center dash console hinge repairs



924-450

Toyota Corolla 2008-02

Failure Mode:

- Components on door break
- Failure results in center console door not functioning properly

OE PROBLEM:

Once the original console hinge fails, the Dealer's only repair is a complete replacement of the entire console assembly



Dorman's repair kit allows for the replacement of just the failed original hinge, saving time and money

SEVERAL COLORS AVAILABLE:

Black

Gray

Beige / Ian

Console Lid Kits

Replacement lid for center consoles

Over 15 SKUs Available

- **Complete Kit** Includes all hardware for a complete repair (where applicable)
- **Reduce Repair Cost** Replace just the broken lid, instead of replacing the entire console
- Available in a variety of colors to match the interior design of vehicle

924-376

Toyota Prius 2006-04



Center Console Latches

Over 5 SKUs Available

924-822

Volkswagen Beetle 2010-98, Volkswagen Jetta 2005-99, Volkswagen Passat 2001-99

Door Lock Actuator Motors

Electric motor located inside the door housing used to lock and unlock vehicle

Over 265 SKUs Available



931-081Chrysler 2008, Dodge 2010-08,
Ram 2015-11

- Aftermarket leading application coverage for today's most in-demand vehicles
- Engineered with high quality electric motor

Failure Mode:

- Motor wear and excessive mechanical stress leads to failure
- Failure results in lock becoming inoperable

ALSO AVAILABLE:



931-318 Cadillac Escalade, Chevrolet Silverado, Avalanche, GMC Yukon, Sierra 2007-00



931-333 Chevrolet Impala 2011-06



931-334Chevrolet Malibu 2012-08,
Saturn Aura 2009-08

RIGOROUS TESTING ENSURES HIGH QUALITY AND DURABILITY

- Crash Test Simulation
- Tensile Testing
- Salt Spray Testing

- Temperature Testing
- Cycle Testing

BACKED BY DORMAN'S LIMITED LIFETIME WARRANTY

FOR ADDITIONAL INFORMATION PLEASE VISIT US AT:
WWW.DORMANPRODUCTS.COM/IDLASOLUTIONS



Liftgate Glass Hinges

3 SKUs Available

924-124

Ford Escape 2007-01, Mercury Mariner 2007-05



Liftgate Release Switches

5 SKUs Available

901-471

Jeep Grand Cherokee 2013-11



Tailgate Latches

Properly secures tailgate

Over 10 SKUs Available

38677

Chevrolet 2015-07, GMC 2015-07, Hummer 2010-09



Tailgate Lock Actuator Motors

Over 15 SKUs Available

937-663

Ford Escape 2012-09, Mercury Mariner 2011-09

Trunk Lock Actuator Motors

Controls the remote locking and unlocking of vehicle's trunk

Over 15 SKUs Available

- Housing material protects motor from damage, ensuring a longer service life
- High quality electric motor



Failure Mode:

- Original actuator arm breaks and requires replacement
- Failure results in the inability to open trunk

931-860

Toyota Camry 2011-07

Truck Bed Floor Supports

Supports the bed of the truck

2 SKUs Available



RUST 924-257

Ford F-250 Super Duty, F-350 Super Duty 2011-99, Ford F-450 Super Duty 2011-08

- Direct replacements for popular Ford truck applications
- Includes bed hardware for a complete repair

Failure Mode:

- Rust corrodes original cross members making them unstable
- Failure results in loose truck bed

ALSO AVAILABLE

924-256

Ford F-250 Super Duty 2011-99, Ford F-350 Super Duty 2011-99

OE PROBLEM:

Original bed supports corrode easily, and the Dealer does not offer as a separate replacement option



Dorman's repair saves money by replacing only the rusted original supports, not an entire truck bed assembly



Truck Cab Mounts

Mounts truck cab body to truck frame

3 SKUs Available

924-422

Ford Ranger 1997-90



Undercar Shields

Mounts to undercar to protect drivetrain from road debris

Over 5 SKUs Available

924-048

Chrysler 300 2010-07, Dodge Charger 2010-07, Dodge Magnum 2008-07



Spare Tire Hoists

Device used to retain, raise and lower spare tire

Over 15 SKUs Available

924-529

Toyota Tundra 2006-00



Power Sliding Door Cables

2 SKUs Available

924-550

Toyota Sienna 2010-04

OE PROBLEM:

The OE Dealer does not offer cable separately. When the original snaps, entire motor and cable assembly must be replaced



Dorman saves money offering the replacement cable separately, avoiding the need for a complete assembly purchase.



Sliding Door Roller Brackets

3 SKUs Available

924-142

Chevrolet 2013-96, GMC 2013-96



Switch - Power Sunroof

901-150

Chevrolet Cobalt 2010-05, Pontiac G5 2009-07



Sunroof Switch Bezel

924-821

Chevrolet Cobalt 2010-05, Pontiac G5 2010-07, Pontiac Pursuit 2006-05

Horn Contacts

Electrical contact that controls horn function

2 SKUs Available

- To assist with installation, all necessary components are included for a complete horn contact repair (where applicable)
- An immediate "must-fix" item replacement required to pass state inspection



- Contact spring breaks
- Failure results in vehicle horn not functioning properly



924-088

Various GM 2009-02, Saab 2009-05



Door Seals (Weather-Stripping)

Provides a secure seal around vehicle door to prevent water and debris from entering vehicle interior

Over 5 SKUs Available

 Complete Kit - Includes installation components for a complete repair (where applicable)

924-443

Jeep Wrangler 2006-97



Power Seat Track Repair Kits

Provides power from seat motor to the seat track, restoring the ability to properly adjust seat

3 SKUs Available

924-074


Infiniti I30 2001-00, Infiniti I35 2004-02, Nissan Maxima 2003-00

OE PROBLEM:

Failed original power seat gears require expensive replacement of the whole seat track assembly through the Dealer



Dorman's fix makes it possible to replace just the stripped originate quar, instead of an entire assembly



Windshield Washer Hoses

4 SKUs Available

- Hose constructed of stronger grade material for increased durability
- Easy to install

924-316

Ford 2010-08

ALSO AVAILABLE BODY/INTERIOR SOLUTIONS:



AIR BAG LAMP



IGNITION LOCK CYLINDERS



REAR APPLIQUE PANELS




Brake Hydraulic Lines – Stainless Steel Brake Lines

65 GM Truck SKUs Available

- Direct fit pre-bent stainless steel brake lines carry pressurized fluid from the master cylinder to the brake caliper or cylinder at the wheel
- Materials upgraded to stainless steel to resist corrosion
- Includes all lines and fittings for a complete brake line repair
- Dorman's stainless steel brake lines are preformed to specific application, saving time by eliminating bending, cutting and flaring

Failure Mode:

- Rust, corrosion and deterioration from exposure to environmental debris
- Near 100% failure rate in rust belt region



919-102

Chevrolet Silverado 1500 2002-99, GMC Sierra 1500 2002-99

FOR ALL STAINLESS STEEL BRAKE LINE DETAILS PLEASE VISIT US AT: WWW.DORMANPRODUCTS.COM/STEEL-LINES



ABS Tone Rings

Over 20 SKUs Available

917-557

Subaru Forester 2002-98, Subaru Impreza 2001-94, Subaru Legacy 1999-94



Brake Proportioning Valves

5 SKUs Available

905-962

Buick 1999-91, Cadillac 2002-97, Cadillac 1993-91, Oldsmobile 1999-91. Pontiac 1999-91

ALSO AVAILABLE BRAKE SOLUTIONS:



PARKING BRAKE ACTUATOR GEAR KITS



PARKING BRAKE BELL CRANKS



BRAKE MASTER CYLINDER CAPS



ABS SENSORS



Control Arm Bumpers

Attaches to the frame, preventing control arm from contacting vehicle frame

Over 10 SKUs Available

• Improved design for a longer service life

523-084

Ford Excursion, E-Series, F-Series 2007-92



Control Arm Bushings

Connects the control arm to vehicle frame via bolt running through the bushing

Over 15 SKUs Available

 Reduce Repair Cost - Replace just the worn bushing, instead of the entire control arm

RUST

523-047

Buick Enclave 2015-08, Chevrolet Traverse 2015-09, GMC Acadia 2015-07, Saturn Outlook 2010-07



Shock Absorber Mount Bushings

Mounting point between the control arm and shock

Over 5 SKUs Available

• **Reduce Repair Cost** - Replace just the failed bushing, instead of the entire shock assembly

523-078

Dodge Dakota 2010-05, Mitsubishi Raider 2009-06, Ram Dakota 2011-10



Trailing Arm Bushings

Mounting point for the front and/or rear axle to vehicle frame

10 SKUs Available

 Complete Kit - Includes necessary components for a complete repair (where applicable)

523-032

Pontiac Vibe 2008-03, Toyota Corolla 2008-03, Toyota Matrix 2008-03



Suspension Knuckle Bushings

Mounting point between the knuckle and mating chassis parts

10 SKUs Available

905-538

Chrysler Pacifica 2008-04

OE PROBLEM:

Dealer does not offer a bushing only replacement, forcing customers to purchase entire Knuckle Assembly



Dorman offers replacements for the failure-prone original bushing, avoiding the need for an entire Knuckle Assembly purchase



Suspension Shock Mounting Kit

Shock mount isolator kit

 Complete Kit - Includes all necessary components for a complete repair

RUST

905-544

Chrysler Cirrus 2000-99, Chrysler Sebring 2006-01, Dodge Stratus 2006-99, Plymouth Breeze 2000-99



Suspension Stabilizer Bar Brackets

Mounts sway bar to the chassis and absorbs vibration


Over 30 SKUs Available

• Complete Kit - Includes mounting bolts for a complete repair

RUST

928-331

Scion tC 2010-05



Suspension Track Bars

Supports vehicle suspension

Over 5 SKUs Available

 Complete Kit - Ball joints and bushings included for a complete installation, saving time and labor (where applicable)

RUST

905-808

Ford Mustang 2014-05

Steering ShaftsRestores steering to proper function

Over 40 SKUs Available



Chevrolet Malibu 2012-04, Pontiac G6 2010-05, Saturn Aura 2009-07

- **Exclusive Aftermarket Solution**
- · Direct replacement for a proper fit every time
- In-demand replacement parts due to high failure prone original parts

Failure Mode:

- Clunking and/or binding in steering column
- · Failure results in the inability to steer properly



Axle Support Bushings

Attaches differential to vehicle frame

4 SKUs Available

523-030

Dodge Durango 2014-11, Jeep Grand Cherokee 2014-11



Differential Dynamic Dampeners

Absorbs torsional vibration

2 SKUs Available

924-441

Honda CR-V 2006-02, Honda Element 2010-03



Differential Mount

Attaches differential to vehicle frame

905-539

Honda CR-V 2011-02, Honda Element 2011-03



Leaf Spring Bumpers

Prevents damage to vehicle's suspension during heavy impact

2 SKUs Available

- · Replacement eliminates knocking noise from leaf spring
- · Easy to install

523-085

Ford Excursion 2005-02



Leaf Spring Hangers

Attaches the leaf spring to the frame of the vehicle

Over 20 SKUs Available

• Complete Kit - Includes all necessary hardware for a complete repair (where applicable)

RUST

722-216

Dodge Dakota 2004-97



Leaf Spring Shackles

Bracket that mounts to the frame and holds the leaf spring in place

Over 20 SKUs Available

- Complete Kit Includes all necessary hardware for a complete repair
- Shackle and hardware are powder-coated for long-lasting corrosion protection

RUST

722-036

Toyota Tundra 2006-00

ALSO AVAILABLE CHASSIS/SUSPENSION SOLUTIONS:



JOUNCE BUMPER - REAR



SWAY BAR KITS



WHEEL HUBS



POWER STEERING PULLEYS

Diesel Emissions Fluid (DEF) Heaters

Restore proper drivability with Dorman's direct-replacement DEF Heaters





- · Complete Kit Includes all necessary components for a complete DEF heater repair
- Quality tested to ensure trouble free installation, performance and durability

904-372

Ford F-250, F-350, F-450 Super Duty 6.7L 2015-11

Failure Mode:

- Original DEF heating element fails
 - Failure results in drivability



Diesel Glow Plug Wiring Harness

Supplies power to glow plugs

- Direct replacement
- No special tools required

904-249

Ford 6.0L 2004-03



Air Intake Heater Relay

Restores intake heater to proper operation

• Designed from high-quality materials for sustained reliability

904-300

Dodge 6.7L 2010-08, Ram 6.7L 2014-11

Turbocharger Cartridges

Replacement prevents oil and coolant from entering the vehicle's intake or exhaust

7 SKUs Available

- Complete Kit Includes O-rings for a complete repair
- Balance tested individually with results included in product packaging

Failure Mode:

- Original shaft seals wear out, or bearings fail from improper oil flow
- Failure results in low engine power and internal leaks



667-001 Ford 7.31 2003-99



OE PROBLEM:

Original turbocharger assemblies wear over time, and the Dealer only offers complete assembly replacements



Dorman enables technicians to replace just the worn original turbo cartridge, without the expense of purchasing a new housing



Turbocharger Oil Lines

Feeds oil to turbocharger unit

10 SKUs Available

904-137

Chevrolet 6.6L 2010-06, GMC 6.6L 2010-06



Turbocharger Oil Return Tubes

Carries oil away from turbocharger unit

5 SKUs Available

904-350

Dodge 6.7L 2013-07, Ram 6.7L 2015-10



Turbocharger Vane Position Sensor

Monitors turbo vane position

904-235

Chevrolet 6.6L 2015-06, GMC 6.6L 2015-06



EGR Coolers

Cools recirculating exhaust gas

Over 10 SKUs Available

- Complete Kit Includes all gaskets and O-rings for a complete repair
- Re-engineered with a spiral tube core to eliminate clogging

904-311

Dodge Ram 2500 6.7L 2009-07, Dodge Ram 3500 6.7L 2009-07



Fuel Coolers

Cools and regulates diesel fuel temperatures

2 SKUs Available

• Direct replacement

RUST

904-180

Chevrolet 6.6L 2011-01, GMC 6.6L 2011-01



Fuel Injector Lines

Delivers pressurized fuel from the high pressure fuel rail to the fuel injector connector tube

Over 10 SKUs Available

- Commonly replaced when servicing injectors or related parts
- Complete Kit Includes inlet and return lines and mounting hardware for a complete repair

904-325

Dodge Ram 2500 5.9L 2009-03, Dodge Ram 3500 5.9L 2009-03

ALSO AVAILABLE DIESEL SOLUTIONS:



ENGINE OIL HOSES (HIGH PRESSURE PUMP)



OIL STAND PIPE



INJECTOR FEED LINES



WATER IN FUEL SENSOR



Auto Trans Pressure Sensor Transducer

Provides feedback to the vehicles PCM/TCM used in shifting

· Plug and Play for easy installation

601-016

Dodge 2007-00, Jeep 2004-00



Auto Transmission Shifter Repair Kit

Helps shift vehicle into gear smoothly

 Complete Kit - Includes necessary components for a complete repair

924-783

Lincoln Aviator 2005-03

OE PROBLEM:

Original plastic shifter wears over time, and a trip to the Dealer results in an entire shifter assembly replacement



Dorman provides a solution to replace only the failed original shifter mechanism with a more durable metal version, saving time and money



Transfer Case Control Modules

Restores the ability to shift vehicle in and out of four-wheel drive (4WD)

Over 10 SKUs Available

- Reduce repair costs by eliminating programming time
- Fully remanufactured and vehicle simulator tested for durability and quality assurance
- Plug and play for easy installation no programming required

599-192

Chevrolet 2014-07, GMC 2014-07





Highly recommended for use with Dorman's Differential Bearing Kits (697-108 & 697-116)

Differential Ring & Pinions

Transmits power from prop shaft to axle shafts

Over 95 SKUs Available

- Direct-fit replacement for original equipment designs
- Made from durable steel construction for long-lasting performance

697-309

Chrysler 2009-07, Chrysler 1981-70, Dodge 2010-66, Plymouth 1981-67

Drive Shaft Couplers

Connects prop shaft to transmission or rear differential

30 SKUs Available

- Complete Kit Includes bolts and washers for a complete repair (where applicable)
- Made from high-quality rubber for a longer service life
- Direct-fit replacement for original equipment designs

935-107

Porsche Cayenne 2010-08, Porsche Cayenne 2006-03, Volkswagen Touareg 2010-04



Switches - 4 Wheel Drive

Operates 4WD system

Over 10 SKUs Available

Easy to install - Direct replacement plugs into mating component

901-154

Chevrolet 2000-96, GMC 2000-96

ALSO AVAILABLE DRIVETRAIN SOLUTIONS:



SHIFT FORK KITS



SLIP YOKES



CENTER SUPPORT BEARINGS



DIFFERENTIAL COVERS

Blind Spot Detection Module

Detects objects and vehicles in close proximity to the vehicle

 Plug-and-Play design requires no programming



Failure Mode:

 Corrosion results in failure to detect vehicles and objects approaching drivers blind spot



601-035

Chrysler 2012-11, Dodge 2013-11, Jeep 2013-11, Ram 2012



Body Control Modules

Monitors and controls various electronic accessories

7 SKUs Available

- Completely remanufactured and tested for durability and quality assurance
- 100% replacement of relays, resistors, capacitors and soldering joints (where applicable)

502-006

Buick 2007-04, Chevrolet 2009-02, GMC 2009-06, GMC 2004-02, Oldsmobile 2004-02



Xenon Headlight Control Modules

Restores headlights to proper operation

Over 10 SKUs Available

- Re-engineered and consolidated to fit a variety of popular part numbers
- · Plug and play for easy installation

601-057

Lexus 2015-07, Toyota 2012-05

Transmission Control Solenoids

Receives signal from the vehicle's TCM to shift the transmission in and out of gear

4 SKUs Available



- Fully remanufactured and tested for durability and quality assurance
- Ready to Install Plug and play design requires no programming

609-040

Chrysler 2009-07, Dodge 2013-00, Jeep 2011-99, Mitsubishi 2009-06, Ram 2013-11

Failure Mode:

- Original gaskets deteriorate, leading to transmission fluid contamination
- Failure results in erratic or hard shifting

TRANSMISSION CONTROL SOLENOIDS ALSO AVAILABLE:



609-041Dodge Durango 2005-04,
Jeep Liberty 2005-03,
Jeep Wrangler 2005-03



609-042Dodge Durango 2003-00,
Dodge Ram 1500 2003-02



609-043Chrysler 2015-07,
Dodge 2015-08,
Ram 2015-14

LIVE CUSTOMER SERVICE & TECH SUPPORT AVAILABLE!



www.DormanProducts.com



Email techlinemarketing@ dormanproducts.com



Phone **1-866-933-2911**

HOURS: MON-THU 8am-7pm EST; FRI 8am-5pm EST



Airbag Impact Sensors

Sensor reliably signals the vehicle's onboard computer system during sudden, extreme deceleration

Over 30 SKUs Available

- Plug and play design for an easy installation
- Helps restore airbag system to proper operation

590-258

Hyundai Elantra 2012-09, Hyundai Sonata 2014-08, Kia Optima 2015-11



Electronic Load Detector

Monitors the amount of current draw pulling from the vehicle battery

- Replacement helps to protect against wear and tear on the vehicle's battery and alternator
- Plug and Play Easily plugs into the fuse block

601-019

Acura RSX 2006, Honda Civic 2005-01, Honda CR-V 2006-02, Honda Element 2011-06, Honda Fit 2008-07



Suspension Ride Height Sensors

Direct replacement sensor restores vehicle suspension height

Over 10 SKUs Available

 Complete Kit - Includes all hardware needed for a complete repair

924-771

Lexus LX570 2013-08

ALSO AVAILABLE COMPLEX ELECTRONICS SOLUTIONS:



OE REPLACEMENT RADIOS



TOUCH SCREEN
INFOTAINMENT DISPLAYS



HVAC CONTROL MODULES



Air Intake Hoses

Over 60 SKUs Available

696-001

Acura TL 2006-04, Honda Accord 2007-03



Coolant Reservoirs

Over 185 SKUs Available

603-099

Cadillac CTS 2006-03




Drive Belt Idler Pulley Adjustment Bolt Kits

3 SKUs Available

917-122

Nissan Murano 2007-03, Nissan Quest 2009-04



Ignition Knock (Detonation) Sensor Connectors

5 SKUs Available

917-141

Infiniti 2002-90, Nissan 2001-90

Engine Cylinder Deactivation Solenoid

Manages the cylinder deactivation function for optimized fuel economy and engine efficiency



Failure Mode:

performance

a complete repair

 Original solenoids stick or leak internally

 Latest design used to ensure durability and long lasting

Includes all necessary hardware for

 Failure results in poor performance and reduced fuel economy

917-162

GM 2015-05, Isuzu 2006-05, Saab 2009-05

Engine Variable Timing Eccentric Shaft Sensor

Detects angle of eccentric shaft





SPOT WELDS

 Direct replacement for popular BMW applications



Failure Mode:

- Oil leaks into electronics
- Failure results in vehicle misfire and illumination of the check engine light

917-030 BMW 2013-06

OE PROBLEM:

The original design utilizes spot welds, which commonly allow oil to seep into unit; leading to electronic failure



Dorman's design uses a stronger ultrasonic weld, preventing oil from contaminating internal electronics



Distributor Seal Kit

917-136

Honda 2002-75



Exhaust Manifold to Cylinder Head Repair Clamps

2 SKUs Available

917-142

Cadillac 2006-02, Chevrolet 2009-99, GMC 2009-99, Hummer 2007-03

OE PROBLEM:

Manifold Studs commonly break, requiring a very time and labor intensive job of extracting broken studs.



Dorman's Manifold Clamp eliminates the need to extract broken studs by providing an external clamping solution.



Intake Manifold Kits

Over 45 SKUs Available

 Complete Kit - Includes all necessary components for a complete repair

615-268

Ford 2008-04, Lincoln 2008-05



Engine Oil Pressure Filter

• Direct replacement for a proper fit every time

917-143

Buick 2009-05, Cadillac 2014-09, Cadillac 2007, Chevrolet 2015-05, GMC 2014-05, Pontiac 2009-05



Oil Cooler Line Assemblies

Over 200 SKUs Available

 Material upgraded from steel or rubber to corrosion-resistant aluminum (where applicable)

625-340

Cadillac 2006-05, Chevrolet 2007-05, GMC 2007-05, Hummer 2007-05



Turbocharger Oil Return Tubes

7 SKUs Available

- **Complete Kit** Includes all necessary components for a complete repair
- Constructed of durable materials for corrosion-resistance

RUST

625-805

Subaru Baja 2006-04



Turbocharger Up Pipe Kits

3 SKUs Available

• **Complete Kit** - Includes gaskets and hardware for a complete repair (where applicable)

679-014

Ford E-350 Econoline 1998, Ford E-350 Econoline Club Wagon 1998,

Ford Econoline Super Duty 1998

VVT TECHNOLOGY SOLUTIONS PROGRAM

Engine Variable Timing Solenoids

Actuates variable valve timing by controlling oil flow and pressure

Over 70 SKUs Available



- 100% tested All Dorman variable valve timing solenoids have undergone vehicle testing and laboratory testing for quality assurance
- Plug and play easily plugs into the electrical harness
- Includes all gaskets needed for a complete repair (where applicable)

Failure Mode:

- Oil sludge builds up on screens and/or electrical failure
- Rough idle, loss of power, illumination of the check engine light





Chrysler Sebring 2010,
Dodge Avenger 2010, Dodge Journey 2010,
Jeep Compass 2010, Jeep Patriot 2010



Engine Variable Timing Sprockets

ALSO KNOWN AS: CAMSHAFT PHASERS Adjusts camshaft timing for optimal engine performance and efficiency



Over 15 SKUs Available

917-255

Buick 2004, Chevrolet 2004-02, GMC 2004-02, Isuzu 2004-03, Oldsmobile 2004-02



Engine Variable Timing Solenoid Gaskets

Gasket used to seal the variable valve timing solenoid into the cam housing

4 SKUs Available

917-170

Acura CL 1997, Honda Accord 1997-94

ALSO AVAILABLE ENGINE SOLUTIONS:



EXHAUST MANIFOLD KITS



EGR TUBES



CRANKCASE VENT VALVE



TRANSFER CASE HOUSING



EGR Tube Connectors

3 SKUs Available

917-416

Ford 2014-98, Lincoln 2011-03, Mercury 2011-03



EGR Valve Control Solenoids

4 SKUs Available

911-403

Volkswagen Beetle 2001-99, Volkswagen Jetta 1999-97, Volkswagen Passat 1997-96



Fuel Injector Wiring Harness

911-089

Chrysler Town & Country 2003-01, Chrysler Voyager 2003-01, Dodge Caravan 2003-01, Dodge Grand Caravan 2003-01

Evaporative Emissions System Leak Detection Pumps Monitors the EVAP system for leaks



Upgraded internal magnet for increased performance (where applicable)

Failure Mode:

Chrysler Sebring 2004-03, Dodge Stratus 2004-03, Jeep Grand Cherokee 2001

310-203

 Corrosion to internal and electrical components

 Failure results in vacuum leaks and illumination of the check engine light

Vacuum Pumps


Provides vacuum source for brake booster

Over 10 SKUs Available

- Re-engineered radial ball bearing provides a greater load capacity for improved durability
- Includes mounting grommets (where applicable)
- Mechanical and electric vacuum pumps available

Failure Mode:

- Original unit commonly fails due to internal bearing wear • Failure results in loss of power
- brake assist



904-814 Ford F-150 2012-11



Engine Crankcase Vent Valves

Over 5 SKUs Available

911-113

BMW 323i 1999. BMW 328i 1999-96. BMW 528i 1998-97, BMW Z3 2000-97



Intake Manifold Actuator

911-904

Chrysler 300 2010-07, Dodge Challenger 2010-09, Dodge Charger 2010-07, Dodge Magnum 2008-07



Intake Manifold Control Valves

Over 10 SKUs Available

911-928

Ford Taurus 2007-96, Mercury Sable 2005-96





PCV Valve Diaphragms

2 SKUs Available

911-115

BMW 2014-12

Vapor Canisters

Stores excess fuel vapor from the gas tank until ready to be released into the combustion chamber

Over 30 SKUs Available



911-617Lexus ES300 1999, Toyota Camry 1999

- Redesigned with an extra hose to consolidate two OE numbers into one Dorman part (where applicable)
- Extensive durability, functionality and emissions tested

Failure Mode:

- Physical damage, valve failure and over filling of fuel tank
- Failure results in illumination of the check engine light



Secondary Air Injection Check Valves

Over 5 SKUs Available

911-152

Chevrolet Cobalt 2008-06, Pontiac G5 2008-06, Saturn Ion 2007-06



Vapor Canister Purge Valves

Over 50 SKUs Available

911-855

Mercedes-Benz 2013-02



Vapor Canister Vent Solenoids

Over 40 SKUs Available

911-511

Infiniti 2002-96, Nissan 2004-95

ALSO AVAILABLE FUEL & EMISSIONS SOLUTIONS:



AIR FILTER BOXES



AIR PUMP MOUNTS



INTAKE MANIFOLD FLAP MOTOR



INTAKE MANIFOLD RUNNER CONTROL VALVES



A/C Compressor Control Valve

Regulates A/C pressure

- Reduce Repair Cost Replace just the failed valve, instead of the entire assembly
- Gasket included to assist with installation

917-275

Chevrolet Equinox 2005, Ford Five Hundred 2007-05, Ford Freestyle 2007-05, Mercury Montego 2007-05



Air Door Actuators

Electronic motor that controls the opening and closing of a variety of temperature control settings

Over 200 SKUs Available

- Re-engineered with an upgraded motor and internal materials for improved durability and performance (where applicable)
- Reduce Repair Cost Replace just the failed actuator, instead of the entire assembly

604-918

Ford Contour 2000-95, Ford Mystique 2000-95, Mercury Cougar 2002-99, Mercury Mystique 2000-95



Coolant Thermostat Housings

Transfers coolant

Over 100 SKUs Available

- Designed to withstand extreme changes in temperature that frequently cause original housing to become brittle, crack and leak
- 0-ring included to assist with installation

902-812

Mini Cooper 2013-07, Mini Cooper Countryman 2013-11, Mini Cooper Paceman 2015-13



Engine Cooling Fan Module

Controls the radiator cooling fan motors and A/C clutch by monitoring the coolant temp sensor, ambient temp sensor, pressure sensor and A/C switch

• Plug and play for easy installation

902-419

Audi 2006-00, Volkswagen 2012-00



HVAC Control Modules

Controls a variety of cabin temperature options

Over 60 SKUs Available

- Completely remanufactured and tested
- 100% backlight bulb and 0-ring replacement (where applicable)
- Ready to install Plug and play design requires no programming

599-152

Volkswagen 2006-97



Power Steering Coolers

Cools power steering fluid flowing through cooler

Over 10 SKUs Available

Save shop time by eliminating the need for customizing a universal cooler to fit the vehicle

918-318

Jeep Commander 2010-06, Jeep Grand Cherokee 2012-05

ALSO AVAILABLE HEATING & COOLING SOLUTIONS:









TRANSMISSION OIL COOLERS

WATER OUTLETS

Hybrid Drive Batteries

A battery pack that assists the engine by providing power to maximize fuel economy

Over 10 SKUs Available



- Ready to install Direct Replacements no programming required
- Includes modules (such as ECU) no need to reuse from old battery
- Completely remanufactured and tested
- Each unit and individual cell is thoroughly tested and balanced to confirm optimal battery pack performance

Failure Mode:

- Over time battery cells lose their ability to hold a charge
- Hybrid malfunction indicator illuminates on dash and decreased fuel economy



587-009Honda CR-Z 2012-11,
Honda Insight 2014-10



587-007Lexus CT200h 2013-11, Toyota Prius 2013-09, Toyota Prius V 2013-12

DORMAN. THE LEADER IN REPLACEMENT HYBRID DRIVE BATTERIES

TOYOTA



587-002 Toyota Camry 2011-07

HONDA



587-004 Honda Civic 2005-03

FORD



587-013Ford Escape 2009-05,
Mercury Mariner 2009-06

FOR MORE HYBRID INFORMATION, VISIT DORMANHYBRID.COM

ALSO AVAILABLE HYBRID SOLUTIONS:



INVERTER ASSEMBLIES



ELECTRIC MOTOR TRANSMISSION STATOR



HYBRID SAFETY PLUGS



INVERTER COOLERS



A full line of merchandised parts offering direct-replacements for a wide variety of in-demand fixes.

HUNDREDS OF HARD TO FIND SKUS AVAILABLE • WWW.FINDDORMANHELP.COM





Antenna Mast

76840 Honda 2014-02



Audio / Video Jacks

3 SKUs Available

57014

Toyota 2013-07



Auto / Manual Trans Shift Boots

4 SKUs Available

76802

Honda Civic 2011-08



Auto Trans Shift Indicator Cable Brackets

Retains shift indicator cable to shift mechanism

2 SKUs Available

70041

Ford Crown Victoria 1995-92, Lincoln Town Car 1992, Mercury Grand Marquis 1995-92



Bumper Cap

Improves vehicle aesthetic by covering hitch opening

54410

Cadillac 2014-07, Chevrolet 2014-07, GMC 2014-07



Cup Holders

Over 15 SKUs Available

41021

Toyota Highlander 2007-01



Dashboard Air Vent

Easy replacement for original units that warp over time

57900

Chevrolet 2005-98, GMC 2004-98, Oldsmobile 2001-98



Door Interior Reflectors

Safety feature to increase visibility in low lighting conditions

3 SKUs Available

74367

Cadillac 2006-03, Chevrolet 2007-03, GMC 2007-03



Seat Belt Buckle Button Stops

Small device that prevents seat belt from retracting too far

3 SKUs Available

74358

Lexus 2014-05, Scion 2014-12, Subaru 2014-93, Toyota 2014-02



Sun Visor Clips

5 SKUs Available

74437

Honda Civic 2005-01, Honda CR-V 2001-97, Honda Fit 2008-07, Honda Insight 2003-00

KEYLESS REMOTE SOLUTIONS

Keyless Entry Remotes

Quick and easy solution to lost or broken key fobs



Over 30 SKUs Available



99157

Buick Lucerne 2011, Chevrolet Impala 2013-11

- Programming new remote to existing vehicle takes just minutes
- Direct Replacement Fit, form and function
- Instructions included



OE PROBLEM:

OE unit requires a trip to the Dealer for programming

OE)FIX

Dorman's units includes a programming tool*, eliminating the time and cost of a trip to the Dealer

*where applicat



REPLACE JUST THE CASE!



Keyless Remote Cases

Does your Keyless Entry Remote still work, but the case is damaged?



- **Reduce Repair Cost** Replace the broken or cracked keyless remote case, instead of the entire key fob
- No special tools required

13655

Toyota 2013-04

CUSTOMIZE TO FIT YOUR STYLE!

AVAILABLE IN A VARIETY OF STYLES









13734

Buick 2007-04, Chevrolet 2009-02, GMC 2009-02, Oldsmobile 2004-02



13739

Cadillac 2002, Chevrolet 2004-01, GMC 2004-01



13745


Buick 2005-01, Chevrolet 2005-01, Oldsmobile 2004-01, Pontiac 2005-01

FOR ALL KEYLESS REMOTE & CASE SOLUTIONS PLEASE VISIT US AT:

WWW.DORMANPRODUCTS.COM/KEYLESS

Product Training and Videos... JUST A CLICK AWAY!






- Door Lock Actuators NEW!
- Fuel & Emissions
- Hybrid Batteries
- Steel Brake Lines
- VVT Technology
- Diesel Overview
- and Much More!



Sign Up Today at DormanUniversity.com!

VISIT DORMANT ON YOU TUDE!



INSTANT ACCESS TO A LIBRARY OF VIDEOS, INCLUDING:

- Installation
- Product Spotlights
- Training
- and Much More!



YouTube.com/DormanProducts



STAY CONNECTED WITH **DORMAN**

- Maintenance / Safety Tips
- Quizzes / Games
- Product Alerts
- Special Announcements





