## **BEECH 18 PRODUCTION LIST**

Compiled by Geoff Goodall

## PART 4: BEECH SUPER 18: E18S, G18S & Super H18

(Built at Wichita, Kansas 1953-1969)



Production E18S N53S (c/n BA-293) at Denver CO in December 1960.

Photo by Eddie Coates



The final production model of the Beech 18 line, this H18 N34AP (c/n BA-746) was built in 1967 for Japan Air Lines with factory-fitted Volpar trigear. Seen at Lanai, Hawaii on an early morning All Hawaii Air freight run from Honolulu delivering freshly baked bread to Hawaiian islands in September 1979. Photo by Geoff Goodall

The final developments of the Beech 18 line, the E18S, G18S and ultimate Super H18 were built at Wichita, Kansas between 1953 and 1968. Aimed squarely at the business aircraft market, they were advertised as *Beech Super 18s*, featuring a raised roof and enlarged cockpit windows. Many were retro-fitted with the

popular Volpar trigear undercarriage modification, and Beech offered the final model, the *Super H18* with factory fitted Volpar trigear.

The Super 18s had increased wingspan and improved performance, extended range, and all models had larger windows and door. The initial E18S had a All Up Weight of 9300 pounds, 550 pounds more than the current production D18S. Payload was further increased with later models.

Model E18S-9700 had AUW increased to 9700 lbs, and was first model with 3 bladed propellers. A larger centre cabin window was introduced during the last third of the G18S production. The H18 was fitted with three-bladed Hartzell propellers as standard.

Beech used the BA- prefix for the construction numbers of all models of *Super 18s*, presented in documentation and aircraft plates with and without the hyphen:



Typical Beech construction plate: BA-81 N3781B, VH-CIJ. (courtesy Ron Cuskelly)

BA-1	E18S	N3460B	Beech Aircraft Corp, Wichita KS	12.53/55
_,			(first E18S, first flight Wichita 10.12.53)	
			(certification flight trials, then demonstrator)	
			Air Orlando Inc. Orlando FL	63
			George H. Bailey Co/ Bailey Leasing Corp, Ft Wayne IN	64/66
			Albany Air Service, Albany GA	69
			Jack Adams Aircraft Sales, Walls MS	70
		N511WP (1	rereg	
		N3460B	Albany Air Service, Albany GA	70
		XA-BEK	Perez Morales, Guerrero Negro	10.70/77
			Aerolineas California Pacifico SA - ACAPSA,	
			Guerrero Negro, Baja California	78/89
	XA-BEK n	oted Guerrero N	ed .55 in Beech advertising for new Super 18; legro, Mexico 3.78; id unknown file;	
BA-2	E18S	N500V N992	Atlantic Aviation, Wilmington DE: delivered new	8.54
BA-2	E18S	N500V N992 N9921	Atlantic Aviation, Wilmington DE: delivered new rereg Bahnson Co, Winston Salem NC	8.54

BA-3	E18S	N3606B	J. D. Reed Co, Houston TX	13.1.55
			Lyle Cashion Co	10.55/60
			Serio-Punches Oil Co, Natchez MS	5.12.60/64
			Jim Hankins Air Service, Jackson MS	14.1.64
	PacAero		Credit Life Agency	1.9.64/66
	Tradewind		Cutter Aviation, Phoenix AZ	11.66/71
			op: Combs Airways, Billings MT	71
			Claude R. Erickson	1.4.71/72
			op: Valley Airlines, San Jose CA: delivered	5.71
			Van Dusen Acceptance Corp, Minneapolis MN	5.6.72/74
			Hamilton Aircraft Co, Tucson AZ	.74
			(cargo floor & cockpit door installed 2.74)	
			Panorama Air Tours, Honolulu HI	2.74/75
			PBF Enterprises Inc, North Canton OH	10.6.75/79
			Executive Aviation Inc, Detroit MI	28.2.79/86
			gear collapsed landing, Fenton MO	20.7.82
			Jet Services Inc, Chesterfield MO	9.86/90
			Peoples Bank & Trust Co, Troy MO	3.12.90/91
			(PBTCo advised FAA: dismantled for scrap by 8.91)	
			William Pobanz: "all parts & equipment of BA-3"	27.8.91/93
			struck-off USCR	27.8.91
			Keith R. Vineyard	7.3.93
			sold to Canada by	8.93
			(dismantled hulk trucked from Oklahoma to	
			Redditt ONT, rebuilt as tailwheel E18S freighter using	
			components from another aircraft: probably BA-23 que s	e)
	E18S	C-FMQS	Gold Belt Air Transport, Pickle Lake ONT	26.10.93/95
			crashed after takeoff, Pickle lake ONT	27.4.95
	(note: no ref	. to conv. to l	PacAero Tradewind in FAA file)	
	1		t Dayton OH airshow 7.55;	
		ed Detroit MI		

N3606B accident report 20.7.82: Executive Aviation Inc, a small post crash engine fire was extinguished:

extinguished; C-FMQS rebuilt at Redditt ONT by Rollie Hammerstedt of Redditt Aviation, who were Beech 18 overhaul specialists;

BA-4	E18S	N3605B	built	.55
			Roselie Shumaker, Moab UT	64/71
			(last annual inspection report 8.55)	
6			struck-off USCR	15.7.71
BA-5	E18S	N3612B	built	.55
			Empire State Airlines, Syracuse NY	63/70
			op: Command Airways	67
			struck vehicle taxying, New York-JFK NY	20.2.67
			Flight Service Inc, Syracuse-Hancock Field NY	15.10.70/72
			Brandt Air/ Alii Air Hawaii, Honolulu HI	26.2.73/81
			(retired, stripped, Honolulu 77/79)	
			struck-off USCR	5.10.81
	accident r	eport 20.2.67: C	MD 15.6.63 Empire State Airlines; Command Airways, struck vehicle while taxying for take	
	accident n N3612B p N3612B n N3612B n with other	eport 20.2.67: C hoto c67: "Emp loted Van Nuys loted Honolulu 1 Beech 18s and	MD 15.6.63 Empire State Airlines; Command Airways, struck vehicle while taxying for take ire State Airlines" titles, tailwheel; CA 6.1.72; 1.9.79, wfu stripped tailwheel, in Brandt aircraft storage	eoff;
	accident r N3612B p N3612B n N3612B n with other N3612B n	eport 20.2.67: C hoto c67: "Emp loted Van Nuys loted Honolulu 1 Beech 18s and loted Honolulu 1	MD 15.6.63 Empire State Airlines; Command Airways, struck vehicle while taxying for take ire State Airlines" titles, tailwheel; CA 6.1.72; 1.9.79, wfu stripped tailwheel, in Brandt aircraft storage Dove; 12.11.79 Brandt Air retired, stripped;	eoff; e compound
BA-6	accident n N3612B p N3612B n N3612B n with other	eport 20.2.67: C hoto c67: "Emp loted Van Nuys loted Honolulu 1 Beech 18s and	MD 15.6.63 Empire State Airlines; Command Airways, struck vehicle while taxying for take ire State Airlines" titles, tailwheel; CA 6.1.72; 1.9.79, wfu stripped tailwheel, in Brandt aircraft storage Dove; 12.11.79 Brandt Air retired, stripped; Atlantic Aviation Corp: CofA issued	eoff; e compound 2.9.54/55
BA-6	accident r N3612B p N3612B n N3612B n with other N3612B n	eport 20.2.67: C hoto c67: "Emp loted Van Nuys loted Honolulu 1 Beech 18s and loted Honolulu 1	MD 15.6.63 Empire State Airlines; Command Airways, struck vehicle while taxying for take ire State Airlines" titles, tailwheel; CA 6.1.72; 1.9.79, wfu stripped tailwheel, in Brandt aircraft storage Dove; 12.11.79 Brandt Air retired, stripped; Atlantic Aviation Corp: CofA issued L. P. Graner Inc	eoff; e compound 2.9.54/55 26.4.55
BA-6	accident r N3612B p N3612B n N3612B n with other N3612B n	eport 20.2.67: C hoto c67: "Emp loted Van Nuys loted Honolulu 1 Beech 18s and loted Honolulu 1	MD 15.6.63 Empire State Airlines; Command Airways, struck vehicle while taxying for take ire State Airlines" titles, tailwheel; CA 6.1.72; 1.9.79, wfu stripped tailwheel, in Brandt aircraft storage Dove; 12.11.79 Brandt Air retired, stripped; Atlantic Aviation Corp: CofA issued	eoff; e compound 2.9.54/55
BA-6	accident r N3612B p N3612B n N3612B n with other N3612B n	eport 20.2.67: C hoto c67: "Emp loted Van Nuys loted Honolulu 1 Beech 18s and loted Honolulu 1	MD 15.6.63 Empire State Airlines; Command Airways, struck vehicle while taxying for take ire State Airlines" titles, tailwheel; CA 6.1.72; 1.9.79, wfu stripped tailwheel, in Brandt aircraft storage Dove; 12.11.79 Brandt Air retired, stripped; Atlantic Aviation Corp: CofA issued L. P. Graner Inc Philips Gloeilampenfabrieken NV, Netherlands (del. to Netherlands via Prestwick 6.5.55)	eoff; e compound 2.9.54/55 26.4.55
BA-6	accident r N3612B p N3612B n N3612B n with other N3612B n	eport 20.2.67: C hoto c67: "Emp loted Van Nuys loted Honolulu 1 Beech 18s and loted Honolulu 1 N3600B	MD 15.6.63 Empire State Airlines; Command Airways, struck vehicle while taxying for take ire State Airlines" titles, tailwheel; CA 6.1.72; 1.9.79, wfu stripped tailwheel, in Brandt aircraft storage Dove; 12.11.79 Brandt Air retired, stripped; Atlantic Aviation Corp: CofA issued L. P. Graner Inc Philips Gloeilampenfabrieken NV, Netherlands	eoff; e compound 2.9.54/55 26.4.55 6.5.55

(PH-ILA) PH-LPS (HB-GBD) CN-MAQ N9886A	from Eindhoven throughout Europe and UK) ntu: Philips NV Philips NV, Eindhoven damaged in accident, Woodvale Aerodrome UK Transair Switzerland ntu: Transair Switzerland Directeur Generale de la Securite Nationale, Rabat (CofA expired 10.71, parked in open Malaga, Spain 71/7 struck-off Register David C. Tallichet & John R. Hawke/ Euroworld California Inc, Long Beach CA	.57 57/65 3.7.57 27.10.65 11.65/67 3.67/78 77) 12.10.77 20.1.78/80
	David C. Tallichet/ Visionair International, Miami FL David C. Tallichet/ Military Aircraft Restoration Corp, Chino CA (abandoned, open storage, Malaga Spain 79/96) (no CofA issued as N9886A) Fundacion Infante de Orleans Museum, Cuatro Vientos AB, Spain Museo Nacional De Aeropuettos Y transporte Aereo, Malaga, Spain	20.1.78/80 3.7.80/83 24.6.83/90 .90/95 98/16
its own corporate aircraft a During first year the E18S Dove PH-ILI delivered 29. then Heron PH-ILA 1.59.	The E18S served for 10 years before replaced by a Falco	E18S. t was
PH-LPS visited Blackbush PH-LPS visited Blackbush PH-LPS visited Dublin, Ire PH-LPS visited Renfrew L PH-LPS visited Southamp PH-LPS noted Kidlington	ne 3.9.56 in visitors' park for 56 Farnborough Air Show; eland 3.8.56 Philips NV; JK 8.5.57 Philips NV; oton 22.4.58 Philips NV; Manchester 28.8.58; UK 25.4.59; oton 7.10.59 Philips NV to Eindhoven next day;	
PH-LPS visited Birmingha PH-LPS visited Gatwick 4 PH-LPS visited Southend PH-LPS noted Heathrow PH-LPS flew Eindhoven-L PH-LPS overflew Sidmout PH-LPS visited London-H	.3.64, 28.5.64; Manchester-Yeadon 17.9.64; 16.12.64 from Gatwick, to Eindhoven 17.12.64; 18.12.64 Philips Electronics; .eeds Bradford-Eindhoven 7.5.65 Philips Electronics; th UK 15.7.65; eathrow 14.10.65 Philips Electronics;	
CN-MAQ noted Cannes 1 N9886A noted stored Mal N9886A noted Malaga 8.9 N9886A noted Malaga 7.1 EC-ASJ noted Malaga 7.1 "EC-ASJ" noted Cuatro Vie "EC-ASJ" noted Malaga 8 wheels jacked up, under s	91 derelict on airfield with Dove N9888A; .8.93 semi-derelict; 11.99 dispayed near GA terminal; ntos 23.10.98 with FldOM, rep. plate "AT-764"; 2.4.00 "SPANTAX S.A.", excellent condition, 3 bladed prop	
"EC-ASJ Spantax" noted	Malaga 26.6.02 on display (no sun cover);	

BA-7	E18S	N3611B	Alamo Aviation, San Antonio TX	20.9.54
			H. B. Zachry Co	10.54/56
			Gulf Interstate Gas Co	17.1.56
		N30G (1	Gulf Interstate Gas Co	27.6.57/58
			Columbia Gulf Transmission Co	12.58/59
		N155JH	Commandair Inc	30.10.59/60
			Starflite Inc	31.3.60/62
	Graubart	N426SF	Graubart Aviation, Valparaiso IN	1.11.62/64
	Aviation		(Volitan Aviation installed Volpar trigear 2.63:	
	Trigear		other mods. comprising Graubart Aviation Trigear)	

(N588YA) N426SF	Guaranty Financial Corp gear collapsed landing, Chicago-Miway IL ntu: Yegen Associates Midwest Inc, Northfield IL Yegen Associates Midwest Inc/ Bonav Corp, Northfield IL	
	Executaire Inc, Cincinatti-Lunkin OH R. J. Paguette Co	7.10.68/69 26.6.69/70
	Hamilton Aircraft Co. Tucson AZ	22.7.70/71
	Flint Air Inc, Flint MI	24.6.71/72
	(cargo floor and cargo door installed 2.72)	
	op: Great Lakes Commuter, Chicago IL	72
	Richard A. Carroll	8.1.73/78
	First Tennessee Bank, Johnson TN: restored USCR	4.78
	K & K Aircraft Inc, Bridgewater VA	26.6.78
	Brennan Air Freight Inc Wayne Sturman Aircraft Sales, Merritt Island FL	28.7.78/80 31.5.80/06
	struck-off USCR	10.8.06

Graubart Avtn: see Beech 18 by Parmerter p.354; N426SF photo 12.64 Graubart Aviation Trigear; N426SF noted Chicago-O'Hare 15.6.72 Great Lakes Commuter, trigear;

BA-8	E18S	N3613B	Page Airways, Rochester NY	24.9.54
			National Home Corp	4.11.54/59
		N444Z	Page Airways, Rochester NY	19.2.59/61
			Ontario Airways, Auburn NY	23.1.61/64
			T. R. Carpenter/ Flight Service Inc/ Empire State Airlin	nes,
			Syracuse-Hancock Field NY	1.12.64/72
			Richard Visser/ Twin Brook Aviation	5.1.72
			Richard Visser/ Sky-Train Inc	16.5.72/76
			Wilbur W. Martin	8.1.76
			Carol Dean Kyle, Elba AL	22.6.76
			State of Utah: forfeited by court order	17.1.78
			Leonard W. Bartish	1.8.78
			Aerospace Products Inc, North Hollywood CA	3.8.78
			Charles E. Bush/ Bush Aviation, Ft Lauderdale FL lost without trace en route Fort Lauderdale FL to	4.9.78/79
			Cat Island, Bahamas	2.4.79
			struck-off USCR	3.86

N444Z noted New York-JFK 5.4.66 Empire State AL;

N444Z went missing on flight by pilot Jim Catron who flew to Bahamas regularly;

3A-9	E18S	N3614B	J. D. Reed Co, Houston TX	8.10.54/55
			Growers Ice & Development Co	15.1.55/59
			O. R. Burden Construction Corp, Tulsa OK	23.3.59/64
			Southeastern Beechcraft Inc, Kingsport TN	1.6.64/65
	trigear		(Volitan Aviation installed Volpar trigear 6.64)	
			Mack Trucks Inc, Montville NJ	13.4.65/66
		N1021B	Mack Trucks Inc, Montville NJ	3.66
		N10216	Mack Trucks Inc, Montville NJ	11.66/67
			Princeton Aviation Corp, Princeton NJ	31.1.67/69
			East Coast Aviation, Hackensack NJ	7.5.69/73
			Thomas Werner	4.5.73/74
			International Airmotive Corp	12.74/75
			International Sales & Leasing, Warrenton OR	31.1.75
			Ram Air Charter Ltd, Inuvik NWT	3.9.75
		C-GWYJ	Ram Air Charter Ltd, Inuvik NWT	1.12.75/79
			Sam Haladay/ The Air Ranger Ltd	81
		N8535X	Bill Walker & Associates, St Simons Island GA	3.1.81
			Paul O'Conner: sale documention not completed	22.1.81
		N10216	International Sales & Leasing, Warrenton OR	3.93
			sale reported, McAllen TX: USCR	95/02

C-GWYJ noted WInnipeg MAN 10.5.79 visitor, Ram-Air Charter, Inuvik NWT;

BA-10	E18S	N3615B	Anderson Air Activities	29.9.54/55
			Malvern Co	30.7.55/57
			Western Tool & Stamping Co, Des Moines IA	1.11.57/64
			Corey Custom Airtravel Inc	27.8.64
		N501J	Tobey Inc, Simsbury CT	2.11.64/66
		N911E	Tobey Inc, Simsbury CT	10.66/76
			(cargo floor, cargo airstair cabin door and cockpit	
			hatch installed 10.73)	
			struck snowbank landing, Boston-Logan MA	24.12.75
			gear collapsed during landing, Simsbury CT	24.6.76
			Brennan & Hargreaves Inc, Hartford CT	6.7.76/80
			Hamilton Aviation, Tucson AZ	27.5.80
			Leo J. Crum/ Pronto Aviation Services, El Paso TX	12.80/82
			Atorie Air Inc, El Paso TX	10.82/83
			Flying Fish Inc, El Paso TX	21.9.83/84
			G. W. Griffin, Reno NV	17.2.84/85
			Union Flights, Sacramento CA	2.8.85/89
			minor damage in ground collision with PA32 at LAX	21.12.87
			Michael C. Lauver, San Clemente CA	20.6.89/90 10.90/95
			Aeronautical Services Inc, Friday Harbour WA op: Catalina Flying Boats Inc, Long Beach CA	90/95
			Robert A. Younkin/ Younkin Air Service, Spingdale AR	18.9.97/98
		(N22YA)	ntu: Younkin Air Service: reg. reserved	10.1.98
		N911E	Southern Cross Aviation Inc, Lake Placid FL	1.4.98/99
			Beer & Morgan LLC, Warsaw IN	22.4.99
			Mark Hathaway/ C-Tiger Enterprises Ltd, Wilmington DE	
		(N369GB)	ntu: C Tiger Enterprises	12.99
		N911E	sale rep, Wilmington DE: USCR	17
			sale rep, Pasadena TX: struck-off USCR	1.6.18
			rport, Providence RI 14.8.74;	
			12.75: Tobey Inc, flight Windsor Locks CT to Boston, 5.13a	am;
			. 11.3.84 Flying Fish Exclusive Charters;	
			5 Union Flights; Executive CA 7.7.87;	
			p Union Flights, ground collision with PA32 N75397 at LA	Y
			talina Flying Boats);	Λ,
			CA 7.91 at Catalina Flying Boats ramp;	
	N911E noted	-		
	N911E noted			
			R 8.97 "Catalina Flying Boats" titles, owned Bobby Younk	in,
	plate BA-10 b	ouilt 9.54;	· - ·	
	N911E at flyir	n Lakeland FL	11.4.99 owned Southern Cross Aviation;	
	N911F noted	Et Lauderdal	e FL 4 4 01.	

N911E noted Ft Lauderdale FL 4.4.01; N911E noted Ft Lauderdale FL 11.8.05 in service;

BA-11	E18S	N3616B	built	.54
			Union Producing Co, Shreveport LA	63/66
			Mississippi School Supply Co, Jackson MS	69/70
			Jim Hankins Air Service, Jackson MS	72
			op: Flight Express Cargo, Essington PA	74
			damaged mid-air collision with Bell 47G N54397 on	
			approach to Detroit MI	27.6.74
			Flight Express Cargo, Essington PA	18.4.75/77
			ditched due fuel exhaustion, Buckeye Lake OH	17.8.77
	then Detr N3616B I	oit,impact with I noted Detroit-Ci report 17.8.77: 1	Flight Express, flight Olive Branch MS to Bowling Greer Bell over Detroit city area, 11pm; ty Airport MI 24.5.76; flight Philadelphia to Columbus OH, fuel exhaustion 5.2	

BA-12	E18S	N3610B	built	.54
		N206C	Castleton Inc, Detroit MI: USCR	63/66
		CF-OYT	reg	.62
			M. Loeb Ltd, Ottawa ONT	65/66

N702H	Midstate Airlines, Chicago IL	68
	op: Hub Airlines, Fort Wayne IN	69
	Marshfield Airways, Marshfield WI	69/70
	op: Midstate Commuter, Chicago IL	70
N310WA	Air Iowa	72/73
	structural failure of right spar, right wing folded in flight,	
	crashed destroyed, Davenport IA	19.4.73

N206C USCR63: FAA inspection 10.62; N702H noted Chicago-O'Hare 29.3.68 Midstate AL; N310W accident report 19.4.73: Air Iowa, flight Muscatine IA to Chicago, spar crack had not been detected in 6 years of inspections, 6k;

BA-13	E18S	N3617B	Atlantic Aviation Service	12.10.54
			Sun Oil Co, Philadelphia PA	10.54/55
		N30S	Sun Oil Co, Philadelphia PA	28.2.55/62
		N148G	Virginia Coal & Iron Co, Big Stone Gap VA	17.7.62/65
			Aircraft Owners Inc, Miami FL	14.9.65/67
			Harry H. Bassett	25.8.67/68
			Kentucky Fried Chicken of Florida, Miami FL	19.3.68/77
			Thomas E. Kirchner: sale documentation not completed	23.2.77
			sale reported, Audubon NJ: USCR	8.80/91
			-	

N148G noted Opa Locka FL 6.10.68 & 23.8.71;

BA-14	E18S	N3618B	Bobby Manziel, Tyler TX	63/72			
DA-14	E103	INSU IOD	Walter Fuller Aircraft Sales	75			
		C-GWSV	Millardair Ltd, Toronto ONT: delivered	9.2.75/93			
		C-GW3V	,	28.4.93			
			sold to USA, struck-off Canadian Register				
		N118SA	reg. candidate	12.5.93			
			reg.	1.94			
			Steve Culbertson, Lakeport CA	28.4.97/02			
			Jay A. Danford, Chico CA	7.6.04/05			
			Marici P. Reid, San Jose CA, later Independence OR	06/20			
	C-GWSV no	oted Toronto 9	.2.75, delivery date to Millardair;				
	C-GWSV no	oted Toronto 1	5.9.79 "Millardair" titles;				
	C-GWSV no	oted Toronto 9	.81 full Millardair scheme & titles,				
	C-GWSV noted Toronto 10.86 Millardair;						
	C-GWSV noted Toronto 18.7.90 "Millardair" titles in service;						
	BA-14 noted Lakeport CA 10.96 under rebuild, being reskinned: plate BA-14 built 10.54;						
			CA 12.9.01 smart colour scheme, plate BA-14;	,			
			7.15, all metallic;				
BA-15	E18S	HI-30	Porfirio Rubirosa, Dominican Embassy, Paris	10.54/57			
			(name Moineau Flier above windows)				
			Luciene Benitez Rexach, Ciudad Trujillo, DR	57			
		N93V	reg				
		N93U	rereq				
	PacAero	N402T	G. C. Landry, East Troy WI	63/66			
	Turbo		Eastern Aviation Corp, Baltimore MD	69			
	Tradewind		Jack Wall Aircraft Sales, Memphis TN	70/72			
	nadewind		Export Airmotive Inc, Miami FL	19.1.72			
			sold to Colombia, struck-off USCR	7.3.72			
		HK-1419P		3.72			
			Transportes Aereos Nacionales - TANA, Bogota	-			
		HK-1419	Transportes Aereos Nacionales - TANA, Bogota	74/76			
			Aerolineas Especiales de Colombia Ltda - AE Colombia,				
			Bogota-El Dorado	77/84			
			(retired at Medellin, Colombia 79/85,				
			under maintenance Tucson AZ 87/90)				

*HI-30 noted at Blackbushe 12.54 Dominican Embassy Paris, "Moineau Flier" above windows; HI-30 reported as a regular visitor to Heathrow during 1955: Dominican Embassy, Paris; HI-30 noted London Airport 9.2.55, 13.3.56 Dominican Embassy, Paris "Moineau Flier";* 

HI-30 noted Blackbushe 23.6.57;

HI-30 noted Prestwick 25.6.57 Dominican Embassy in Paris; HK-1419 noted Bogota 29.9.72 TANA (note: TANA also quoted as Taxi Aereo Nacional) HK-1419 noted San Andres, Colombia 2.78 "Aerolineas Especiales" titles BA-15 noted Tucson AZ 10.87: rep as last production Hamilton-Liner HK-1419 noted Tucson 4.6.80 AE Colombia colour scheme & titles (not rep. as trigear); BA-15 noted Tucson AZ 31.5.90 no registration;

BA-16	E18S	N3642B	Roscoe Turner Aeronautical Corp	11.54
	E103	N3042D	Stokely-Van Camp Inc	11.54/60
			L. C. Cassidy & Son Inc	13.2.60/62
		N255DC	L. C. Cassidy & Son Inc	15.2.62
		N255D	Merchants National Bank, Indianapolis IN	28.9.62/68
		NZOOD	Clanton Air Carriers, Clanton AL	11.68/70
			Aircraft Acceptance Corp, Columbus OH	15.9.70/72
			Robert L. Smith	21.1.72/73
			C. O. Williams	31.7.73/74
			Associated Airways	14.2.74
			damaged forced landing, Atlanta-Fulton County GA	17.4.74
			(reported stored damaged Charle Brown GA 78)	74
			National Independent Insurance Co	74
			Hill Aircraft & Leasing Corp	10.74/75
			John R. Jackson	15.4.75/80
			Allen Fadel	25.2.80
			Palm Beach County Sheriff's Office FL: seized	10.80
			(forfeited from Michael McGovern along with	
			D18S N90562/A-414) Missionany Elighte & Services Inc	12.80/83
			Missionary Flights & Services Inc Air Cargo America Inc, Miami FL	7.6.83
			(arrived Miami 8.6.83 on delivery)	1.0.03
			James R. Bell, Miami FL	12.83/89
			(cargo door & cockpit entrance door, both ex	12.03/03
			BA-120/N171LG, installed 6.84)	0.44.00/00
			Aaron Pirani/ Mangalji Airways, Miami FL	3.11.89/96
			op: Eagle Wings, St. Lucia	90/96
			Eagle Air Charter, Miami FL	11.9.96/99
			South Florida Aircraft Leasing, Opa Locka FL	22.4.99/02
			Alan G. Foster, Anchorage AK	19.2.04/14
			struck-off USCR	22.9.14
			Beach FL 19.7.81;	
	N255D note	ed Miami FL 2	2.3.87 Air Cargo America; Miami 11.87;	
	N255D note N255D note	ed Miami FL 2 ed Miami FL 8	2.3.87 Air Cargo America; Miami 11.87; .6.83 arrived on delivery to Air Cargo America;	
	N255D note N255D note N255D note	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2.	2.3.87 Air Cargo America; Miami 11.87; .6.83 arrived on delivery to Air Cargo America; 90 "Eagle Wings",	
	N255D note N255D note N255D note N255D note	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2. ed Opa Locka	2.3.87 Air Cargo America; Miami 11.87; .6.83 arrived on delivery to Air Cargo America; 90 "Eagle Wings", FL 7.6.90, 9.90 & 2.12.90 all "Eagle Wings St Lucia" title	
	N255D note N255D note N255D note N255D note N255D note	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2. ed Opa Locka ed Opa Locka	2.3.87 Air Cargo America; Miami 11.87; .6.83 arrived on delivery to Air Cargo America; 90 "Eagle Wings", FL 7.6.90, 9.90 & 2.12.90 all "Eagle Wings St Lucia" title FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express	s Airways;
	N255D note N255D note N255D note N255D note N255D note N255D note	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2. ed Opa Locka ed Opa Locka ed Opa Locka	2.3.87 Air Cargo America; Miami 11.87; .6.83 arrived on delivery to Air Cargo America; 90 "Eagle Wings", FL 7.6.90, 9.90 & 2.12.90 all "Eagle Wings St Lucia" title FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aaro	s Airways;
	N255D note N255D note N255D note N255D note N255D note N255D note Opa Locka	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2. ed Opa Locka ed Opa Locka ed Opa Locka ed Opa Locka 1.97,11.4.97,	2.3.87 Air Cargo America; Miami 11.87; .6.83 arrived on delivery to Air Cargo America; 90 "Eagle Wings", FL 7.6.90, 9.90 & 2.12.90 all "Eagle Wings St Lucia" title FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aaro 9.97 faded "Eagle Wings St Lucia" titles, all metallic;	s Airways;
	N255D note N255D note N255D note N255D note N255D note Opa Locka N255D note	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2. ed Opa Locka ed Opa Locka ed Opa Locka 1.97,11.4.97, ed Opa Locka	2.3.87 Air Cargo America; Miami 11.87; .6.83 arrived on delivery to Air Cargo America; 90 "Eagle Wings", FL 7.6.90, 9.90 & 2.12.90 all "Eagle Wings St Lucia" title FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aaro 9.97 faded "Eagle Wings St Lucia" titles, all metallic; FL 4.4.01, all metallic, plate BA-16;	s Airways;
	N255D note N255D note N255D note N255D note N255D note Opa Locka N255D note N255D note	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2. ed Opa Locka ed Opa Locka ed Opa Locka 1.97,11.4.97, ed Opa Locka ed Anchorage	2.3.87 Air Cargo America; Miami 11.87; .6.83 arrived on delivery to Air Cargo America; 90 "Eagle Wings", FL 7.6.90, 9.90 & 2.12.90 all "Eagle Wings St Lucia" title FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aaro 9.97 faded "Eagle Wings St Lucia" titles, all metallic; FL 4.4.01, all metallic, plate BA-16; -Lake Hood strip 17.4.04, airworthy;	s Airways; n Pirani;
	N255D note N255D note N255D note N255D note N255D note Opa Locka N255D note N255D note N255D note N255D note	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2. ed Opa Locka ed Opa Locka ed Opa Locka 1.97,11.4.97, ed Opa Locka ed Anchorage ed Anchorage	2.3.87 Air Cargo America; Miami 11.87; .6.83 arrived on delivery to Air Cargo America; 90 "Eagle Wings", FL 7.6.90, 9.90 & 2.12.90 all "Eagle Wings St Lucia" title FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aaro 9.97 faded "Eagle Wings St Lucia" titles, all metallic; FL 4.4.01, all metallic, plate BA-16; -Lake Hood strip 17.4.04, airworthy; -Lake Hood strip 11.9.04, tailwheel, windows faired over,	s Airways; n Pirani; in service
	N255D note N255D note N255D note N255D note N255D note Opa Locka N255D note N255D note N255D note N255D note	d Miami FL 2 d Miami FL 8 d St. Lucia 2. d Opa Locka d Opa Locka d Opa Locka 1.97,11.4.97, d Opa Locka d Anchorage d Anchorage d AnC-Lake	2.3.87 Air Cargo America; Miami 11.87; .6.83 arrived on delivery to Air Cargo America; 90 "Eagle Wings", FL 7.6.90, 9.90 & 2.12.90 all "Eagle Wings St Lucia" title FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aaro 9.97 faded "Eagle Wings St Lucia" titles, all metallic; FL 4.4.01, all metallic, plate BA-16; -Lake Hood strip 17.4.04, airworthy;	s Airways; n Pirani; in service
BA-17	N255D note N255D note N255D note N255D note N255D note Opa Locka N255D note N255D note N255D note N255D note N255D note	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2. ed Opa Locka ed Opa Locka ed Opa Locka 1.97,11.4.97, ed Opa Locka ed Anchorage ed Anchorage ed Anchorage ed ANC-Lake ed Homer AK	<ul> <li>2.3.87 Air Cargo America; Miami 11.87;</li> <li>6.83 arrived on delivery to Air Cargo America;</li> <li>90 "Eagle Wings",</li> <li>FL 7.6.90, 9.90 &amp; 2.12.90 all "Eagle Wings St Lucia" title</li> <li>FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express</li> <li>FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aaro</li> <li>9.97 faded "Eagle Wings St Lucia" titles, all metallic;</li> <li>FL 4.4.01, all metallic, plate BA-16;</li> <li>Lake Hood strip 17.4.04, airworthy;</li> <li>Lake Hood strip 11.9.04, tailwheel, windows faired over,</li> <li>Hood strip 7.4.06 no windows, all metal finish, tailwheel;</li> <li>6.6.13 all metal finish, control surfaces removed;</li> </ul>	s Airways; n Pirani; in service also 6.08, 6.10;
BA-17	N255D note N255D note N255D note N255D note N255D note Opa Locka N255D note N255D note N255D note N255D note	d Miami FL 2 d Miami FL 8 d St. Lucia 2. d Opa Locka d Opa Locka d Opa Locka 1.97,11.4.97, d Opa Locka d Anchorage d Anchorage d AnC-Lake	<ul> <li>2.3.87 Air Cargo America; Miami 11.87;</li> <li>6.83 arrived on delivery to Air Cargo America;</li> <li>90 "Eagle Wings",</li> <li>FL 7.6.90, 9.90 &amp; 2.12.90 all "Eagle Wings St Lucia" title</li> <li>FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express</li> <li>FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aaro</li> <li>9.97 faded "Eagle Wings St Lucia" titles, all metallic;</li> <li>FL 4.4.01, all metallic, plate BA-16;</li> <li>Lake Hood strip 17.4.04, airworthy;</li> <li>Lake Hood strip 11.9.04, tailwheel, windows faired over,</li> <li>Hood strip 7.4.06 no windows, all metal finish, tailwheel;</li> <li>6.6.13 all metal finish, control surfaces removed;</li> </ul>	s Airways; n Pirani; in service
BA-17	N255D note N255D note N255D note N255D note N255D note Opa Locka N255D note N255D note N255D note N255D note N255D note	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2. ed Opa Locka ed Opa Locka ed Opa Locka 1.97,11.4.97, ed Opa Locka ed Anchorage ed Anchorage ed Anchorage ed ANC-Lake ed Homer AK	<ul> <li>2.3.87 Air Cargo America; Miami 11.87;</li> <li>6.83 arrived on delivery to Air Cargo America;</li> <li>90 "Eagle Wings",</li> <li>FL 7.6.90, 9.90 &amp; 2.12.90 all "Eagle Wings St Lucia" title</li> <li>FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express</li> <li>FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aaro</li> <li>9.97 faded "Eagle Wings St Lucia" titles, all metallic;</li> <li>FL 4.4.01, all metallic, plate BA-16;</li> <li>Lake Hood strip 17.4.04, airworthy;</li> <li>Lake Hood strip 11.9.04, tailwheel, windows faired over,</li> <li>Hood strip 7.4.06 no windows, all metal finish, tailwheel;</li> <li>6.6.13 all metal finish, control surfaces removed;</li> </ul>	s Airways; n Pirani; in service also 6.08, 6.10; .54
BA-17	N255D note N255D note N255D note N255D note N255D note Opa Locka N255D note N255D note N255D note N255D note N255D note	ed Miami FL 2 ed Miami FL 8 ed St. Lucia 2. ed Opa Locka ed Opa Locka ed Opa Locka 1.97,11.4.97, ed Opa Locka ed Anchorage ed Anchorage ed Anchorage ed ANC-Lake ed Homer AK	<ul> <li>2.3.87 Air Cargo America; Miami 11.87;</li> <li>2.6.83 arrived on delivery to Air Cargo America;</li> <li>90 "Eagle Wings",</li> <li>FL 7.6.90, 9.90 &amp; 2.12.90 all "Eagle Wings St Lucia" title</li> <li>FL 30.4.95 Eagle Wings St Lucia" reportedly op. Express</li> <li>FL 1.96 faded "Eagle Wings St Lucia" titles, op. by Aaro</li> <li>9.97 faded "Eagle Wings St Lucia" titles, all metallic;</li> <li>FL 4.4.01, all metallic, plate BA-16;</li> <li>Lake Hood strip 17.4.04, airworthy;</li> <li>Lake Hood strip 7.4.06 no windows, all metal finish, tailwheel;</li> <li>6.6.13 all metal finish, control surfaces removed;</li> <li>built</li> <li>Manhattan Construction Co, Muskogee OK</li> </ul>	s Airways; n Pirani; in service also 6.08, 6.10; .54 63/66

accident report 15.5.70: flight San Jose CA to Oxbow OR, complete engine power loss, 7k;

BA-18	E18S	N3602B	Currey Sanders Aircraft Co	8.11.54
			Carthage Co	8.11.54/56
			Hudson Gas & Oil Corp	1.9.56/63
			San Jacinto Petroleum Corp, Shreveport LA	15.1.63/64
			Aircraftsmen Inc. Oklahoma City OK	27.4.64/70

	(Beech cargo door installed 4.68)	
	Engborg Leasing Corp	15.8.70/72
	Banner Flight Ltd	4.3.72/75
	(Hamilton cargo floor installed 7.74)	
	undercarriage collapsed landing, Toronto ONT	3.12.74
	Ridder Air Enterprises Inc, Whitman MA	5.3.75/83
	(cockpit crew door installed 5.75)	
	Crow Inc/ Crow Executive Air Charter, Millbury OH	26.8.83/89
	Central Business Brokers/ Gateway Air Service,	
	Mt Pleasant MI	29.3.89/90
N666AK	Gateway Air Services, Mt Pleasant MI	20.4.90/96
	Kenneth R. Phillips, Brackettville TX	16.7.98/99
	Beechnut Inc, Wilmington DE	19.9.01/05
	Kenneth R. Phillips, Brackettville TX	9.3.05/10
	William E. Signs, Dallas TX	2.10/12
N7BS	William E. Signs, Dallas TX	12/15
	Runyon Aviation, Fort Worth TX	1.9.15/20

N3602B noted Stewart NY 11.8.74;

N3602B accident report 3.12.74: gear collapsed due mechanical fault, 4.50am; N666AK noted Mt Pleasant MI 10.96 Gateway AS; Claire MI 6.98; N666AK noted Victoria TX 7.5.03;

Bill Signs purchased N666AK from Ken Phillips at Del Rio TX in January 2010, also Dumod Liner N445DM (AF-152). N666AK was retired and needed restoration: parts source was Ken Phillips' E18S N2083C stored damaged dismantled at Brackettville TX, plus parts from all over USA; N7BS restored and repainted visited Oshkosh 28.7.14 flown by Bill Signs; Oshkosh 7.15, 7.16;

BA-19 E18S N3622B reg N712 rereg N721D (2 Butler Drilling Co, Houston TX struck-off USCR	15.2.63/65 22.5.65
---------------------------------------------------------------------------------------------------	-----------------------

BA-19 has been reported as having first reg N700N but that was Beech G17S c/n B-19;

BA-20	E18S	CF-IOP	built	.54			
		CF-HOP	Canadian Breweries Ltd	58			
			Dominion Tar & Chemical Co, Montreal QUE	60/65			
			Canadian Inspection & Testing Co Ltd, Montreal QUE	14.4.65/70			
			(converted by Aircraft Industries of Canada, St Johns QU	E			
	AIC/Howard		to PT-6A-20s with Volpar Mk.IV trigear completed 2.67,				
	Jobmaster		marketed as Jobmaster Prop-Jet 18)				
	Prop-Jet 18		(AIC demos to RCAF 3.67 offering conversion program)				
	trigear		dam. landing Iles aux Ruaux airstrip QUE	19.10.68			
			Omni Aircraft Sales, Washington DC	9.12.70			
			(ferry permit 12,70 St Jean QUE to Baltimore MD)				
		(N13173)	ntu: Omni Investment Corp, Washington DC	12.70			
		N11AB	Omni Investment Corp/ Omni Aircraft Sales,				
			Washington DC	9.12.70			
			Howard A. Weiss, Chicago IL	12.70/73			
			(cargo floor installed 7.71, cockpit door 11.73)				
			Arkansas Aero Inc	25.7.73			
			op: Sierra West Airlines, Oxnard CA	73			
			Great Western Airlines, Tulsa OK	10.74/82			
	Westwind III		(Volpar Mk.IV trigear replaced with original				
	long nose/		Beech tail gear & extended nose installed 10.74)				
	tailgear		Hamilton Aircraft Co, Tucson AZ	10.9.82/83			
			(FAA report 4.89: aircraft salvaged for parts)				
			struck-off USCR	31.5.89			
	N11AB photo	o 5.71 trigear	r turbines, no titles;				
	N11AB noted	l Tucson AZ	20.9.74 inside Hamilton hangar under rebuild to Westwind	with			
	,	0	installed, Hamilton extended nose installed;				
			PA 10.75, turbines, tailwheel, extended nose, no titles;				
	N11AB noted Wichita KS 6.6.76 Westwind;						

BA-21	E18S	N3647B N1234X	built Pillsbury Mills	.54
		N1234G	Jen Mar Construction Co, Minneapolis MN	63/64
			National Music Service, Spokane WA	66
			C. W. Nuggent, Houston TX	69
			Vercoa Air Service/ Allegheny Commuter, Danville IL	70
			Combs Airways, Billings-Logan MT	70/72
			Burlington Airways/ Burl Air Freight, Burlington WI	30.4.66/79
			crashed destroyed on takeoff, Chicago-O'Hare IL	3.4.79
			3.4.79: Burlington Air Freight: flight Chicago to Indianapol ce, destroyed, fire after impact 4.39am, pilot minor injuries	
BA-22	E18S	N3604B	J.F.Anderson Lumber Co, Minneapolis MN	4.12.61/63
			sold to Mexico, struck-off USCR	21.10.63
		N3604B	Great Lakes Aviation Corp, Chicago IL	69/70
			op: Great Lakes Airlines, Chicago IL	69/70
			crashed, destroyed by fire, forced landing New Carlisle	IN 10.12.70
	N3604B no N3604B no accident re	oted Chicago-N port 10.12.70:	D'Hare 11.3.69 Great Lakes Airlines; Midway IL 9.8.70 "Great Lakes Airlines: titles, tailwheel; Great Lakes Aviation, struck trees in forced landing due t	
BA-23	E18S	N3620B	Atlantic Aviation Corp	24.11.54
	-9700		Merritt-Chapman & Scott Corp	11.54/60
			Shulton Inc	1.6.60/63
			Gopher Aviation, Rochester Airport MN	25.2.63/64
	trigear		(Volpar tricycle gear installed 5.63)	
			Hylan Flying Service, Rochester NY	3.8.64/83
			(Aerospace Products cargo door installed 2.82)	
			Ray Hylan School of Aeronautics, Rochester NY	12.83/86
			Detor Properties Inc, Rochester NY	1.87
			Jerry L. Englund/ Englund Aviation, Mobile AL	19.2.87/91
			539561 Ontario Ltd ONT	27.12.91
			sold to Canada: struck-off USCR	15.4.92
	N3620B nc	oted Youngsto	wn OH 12.1.83 Hylan Flying Service;	
BA-24	E18S	N3625B	R. L. Manning Co	14.9.55/58
			crashed, struck-off USCR	19.2.58
BA-25	E18S	N3650B	built	.55
		N127H	rereg	
		N127W	rereg	
		N1900W	rereg	
		N1900R	Belton Bagging Co, Belton SC	63/64
			S. W. Sisk/ Orion Airways, St Louis MO	68/69
			Sisk Aviation Activities Inc, St Louis MO	70
			op: Golden Eagle Aviation	.70
			Harry W. Wardell, Billings MT	72
			Van Dusen Acceptance Corp, Minneapolis MN	14.6.72/73
			op: Buckeye Air Service, Elyria OH	.72/73

\_\_\_\_

			op: Buckeye Air Service, Elyria OH lost without trace en route Cleveland OH-Detroit MI	14.6.72773 .72/73 20.3.73
BA-26	E18S	N3644B	built	.55
			K C Tractor & Implement Co, Springfield MO	63/66
			S. W. Sisk/ Orion Airways, St Louis MO	68/69
			Sisk Aviation Activities Inc, St Louis MO	70
			Skyway Aviation, Fort Leonardwood MO gear collapsed during landing with engine fire,	71/73
			Fort Leonardwood MO	5.11.73
BA-27	E18S	OO-SUM	Union Miniere du Haut Katanga, Elizabethville	13.8.55/57
			struck-off Register	11.10.57

F-BFDR	Sud Aviation, Paris-Le Bourget	26.12.57/71
	Air Continent, Cannes-Mandelieu	17.9.71/75
	Aviasud, Nice	28.3.75/79
	retired Nice: CofA expired	17.2.75
	Nantes Aviation, Nantes	4.4.79
	struck-off register	24.10.79

OO-SUM noted Blackbushe 6.9.55 & 3.9.56 visitor for Farnborough air show; F-BFDR visited London-Heathrow 1.5.59 Sud Aviation; 21.1.60 Sud Aviation; F-BFDR visited Bristol-Filton 27.4.60 Sud Aviation; F-BFDR noted Gatwick 6.9.61 Sud Aviation, Farnborough visitor; F-BFDR noted Paris-Orly 11.7.62; Hucknall 17.4.63 Sud Aviation; Bristol 22.11.63; F-BFDR visited London-Gatwick 23.6.64, 8.9.64; F-BFDR visited Bristol-Filton 3.10.64; F-BFDR visited Filton 11.1.65, flew Filton-Tolouse 12.1.65; flew Filton-Le Bourget 3.2.65; F-BFDR overflew London 23.3.65; noted Filton 9.9.65 & 10.5.66, F-BFDR visited London-Heathrow 25.1.67; F-BFDR visited Dublin 15.4.67 rep op by Escadrille Mercure, visiting for football match; F-BFDR visited Yeadon 25.4.67 rep as Sud Aviation; F-BFDR noted Paris-Le Bourget 1.6.67; F-BFDR visited Heathrow 18.1.68 Sud Aviation; F-BFDR visited Heathrow 18.1.68 owner reported as Sud Aviation; F-BFDR visited London-Heathrow 21.5.68; Le Bourget 27.12.68; F-BFDR visited Bournemouth-Hurn 26.2.70; F-BFDR visited London-Gatwick 6.1.72; F-BFDR noted Toussus c6.73, Air Continent, visitor;

BA-28	E18S	N3626B	Ohio Aviation Co, Dayton OH	6.12.54/55				
			White Motor Co, Cleveland OH	13.7.55/60				
			Donges Aircraft Sales	25.1.60/61				
			Cleveland Hangars Inc, Cleveland-Hopkins OH	21.3.61/62				
			Robert Gore	11.62/63				
			Appliance Buyers Credit Corp, St Joseph MO	64				
			Bernard Little/ Angels Inc	10.1.64				
		N18T (1	Addison Products Co, Addison TX	22.2.64				
		N3626B	Addison Products Co, Addison TX	11.64/65				
			Airline Management Corp, Chicago IL	12.4.65/67				
			Executive Airlines	14.8.67/68				
			Horizon Aviation Enterprises Inc, Chicago IL	12.68/71				
			American Turbine Aircraft Co, Long Beach CA	71				
			Aircraft Rebuilders Inc, Long Beach CA	19.5.71/73				
			Volpar Inc, Van Nuys CA	6.7.73/74				
	Volpar		(converted to Volpar Turboliner II: tricycle gear,					
	Turboliner II		AiResearch TPE331 turbines, 81.5 inch fuselage					
			extension, completed 28.3.74)					
		N700WA	William E. Winship/ Winship Air Service, Anchorage AK	11.2.74/82				
			op: Troy Air Inc, Anchorage AK	79/82				
			Troy Air Inc, Anchorage AK	11.82/90				
			Connie Kalitta Services, Willow Run MI	30.5.90				
			American International Airways, Willow Run MI	10.90/92				
			Connie Kalitta Service, Willow Run MI	1.1.92				
			Kalitta Flying Service, Willow Run MI	11.92/99				
			op: FS Air Service, Anchorage AK	94/96				
			gear collapsed after landing, Van Curler mine strip,					
			Chena Hot Springs via Fairbanks AK	6.7.96				
			Kitty Hawk Charters Inc, Morristown TN	15.6.99				
			stripped for parts .99, struck-off USCR	30.11.99				
			(stripped hulk on belly still near mine strip 6.04)					
			ge 3.7.76, 1.9.76;					
		N700WA noted Anchorage 13.9.79 & 6.9.81: both "Troy Air" titles, "Volpar Turbo						
		Liner" small titles; N700WA noted Anchorage 27.5.90 Turboliner, no titles;						
			ge AK 8.94 Turboliner, op. FS Air Services;	n Cualeale Dea				
	accident report 6.7.96: badly damaged, ran off gravel runway landing Fairbanks-Van Curler's Bar,							
	operator FS Air Service, Garrett TPE-331turbines;							

photo 13.6.04 on belly near mine strip, completely stripped: red & white;

BA-29	E18S	N3627B	Beech Aircraft Corp, Wichita KS	12.54/55
			Capitol Air Sales Inc	28.4.55
			Super Service Motor Freight Co	28.4.55/58
			Bowman Transportation Inc, East Gadsden AL	6.3.58/66
			Air Journeys Inc, Little Rock AR	3.1.67
			John W. Pennington	28.6.67
			Stella Aircraft Investment Co, Santee CA	15.2.68/69
			Florida Airmotive Inc, Lantana-Palm Beach FL	23.4.69/70
		N333FL	Florida Airmotive Inc, Lantana-Palm Beach FL	21.8.70
			Frank E. Fairchild/ F.E.F. Enterprises Inc,	
			Port Washington NY	1.11.70/76
			Ronald L. Simmons & Richard B. Neff	17.9.76/77
			Robert L. Johnson, Louisville KY	19.4.77/78
			Blackhawk Airways, Janesville WI	12.78/80
			(cargo floor & door, cockpit hatch installed 8.79)	
			International Trade & Investments, Orem UT	28.5.80/91
			crashed on takeoff off icy runway, Candle AK	3.10.80
			(wreck stored dism. Fairbanks Airport 90)	
			Chenna Marina, Fairbanks AK: wreck	06

N333FL accident report 3.10.80: no operator quoted, pax flight Candle to Kotzebue AK, unable to get airborne ran into brush at end of runway, pilot & 4 pax unhurt; N333FL fuselage noted Fairbanks AK 25.5.90;

BA-30	E18S	N3646B	Atlantic Aviation Corp	29.12.54
			New York Wire Cloth Co	12.54/56
			Lee Wilson Engineering Co, Cleveland OH	12.56/73
			(visited Africa & UK, via Prestwick 8.8.60)	
			mid-air collision with PA-23 N4165P, emergency landing	],
			Fremont OH	31.8.66
			(E18S cabin roof torn open & tail badly damaged)	
			Air Best de Puerto Rico, San Juan, Puerto Rico	8.73/81
			retired derelict, San Juan, Puerto Rico	78/79
			Julio F. Morales: \$1000 at auction	30.6.81/82
			Jorge A. Toledo, Villa Andalucia, Puerto Rico	18.6.82/83
			Julio A. Colon, St Croix, US Virgin Islands	24.8.83/91
	N3646B ar N3646B vis N3646B nc N3646B ph titles: see B	rived Heathrow sited Dakar, Se oted Heathrow 1 noto 8.66 after i Beech 18 by Pa	x 8.8.60 ex Keflavik, to Cardiff-Rhoose, Lee Wilson, Cleve y 11.8.60 from Rhoose, Lee Wilson, departed 13.8.60 to F ynegal 4.10.60 to Natal, Lee Wilson Co; 27.9.60 Lee Wilson; midair collision: roof & tail wrecked. "Lee Wilson Engineer armerter p.286, 287; PR 30.12.79 Air Best de PR, retired;	Paris;
BA-31	E18S	N80008	Tulsair Distributors Inc	12.54/55
			Williams Brothers Co	11.55/56
		N108WB	Williams Brothers Co Williams Brothers Co	
		N108WB YV-P-EPC	Williams Brothers Co	11.55/56
			Williams Brothers Co	11.55/56 10.56/57
		YV-P-EPC	Williams Brothers Co Williams Brothers Sudamericana Ltd	11.55/56 10.56/57 2.57/58
		YV-P-EPC N107WB	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co	11.55/56 10.56/57 2.57/58 11.4.58/62
		YV-P-EPC N107WB	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64
		YV-P-EPC N107WB N475AB	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69
		YV-P-EPC N107WB N475AB N13JC	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK Jaqueline Cochran, Indio CA	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69 12.3.69/71
		YV-P-EPC N107WB N475AB N13JC	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK Jaqueline Cochran, Indio CA Merv Griffin/ Anthony Productions Inc, Hollywood CA	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69 12.3.69/71 29.4.71/78
		YV-P-EPC N107WB N475AB N13JC N333MG	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK Jaqueline Cochran, Indio CA Merv Griffin/ Anthony Productions Inc, Hollywood CA James H. Bond/ Bond Operating Co, Las Vegas NV	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69 12.3.69/71 29.4.71/78 15.2.79
		YV-P-EPC N107WB N475AB N13JC N333MG	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK Jaqueline Cochran, Indio CA Merv Griffin/ Anthony Productions Inc, Hollywood CA James H. Bond/ Bond Operating Co, Las Vegas NV James H. Bond/ Gemini Resources, Las Vegas NV US Customs Service CA: seized	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69 12.3.69/71 29.4.71/78 15.2.79 1.7.79/83
		YV-P-EPC N107WB N475AB N13JC N333MG	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK Jaqueline Cochran, Indio CA Merv Griffin/ Anthony Productions Inc, Hollywood CA James H. Bond/ Bond Operating Co, Las Vegas NV James H. Bond/ Gemini Resources, Las Vegas NV	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69 12.3.69/71 29.4.71/78 15.2.79 1.7.79/83
		YV-P-EPC N107WB N475AB N13JC N333MG	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK Jaqueline Cochran, Indio CA Merv Griffin/ Anthony Productions Inc, Hollywood CA James H. Bond/ Bond Operating Co, Las Vegas NV James H. Bond/ Gemini Resources, Las Vegas NV US Customs Service CA: seized Tarrant County Junior College, Fort Worth-Meacham Field TX	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69 12.3.69/71 29.4.71/78 15.2.79 1.7.79/83 7.83/85
		YV-P-EPC N107WB N475AB N13JC N333MG	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK Jaqueline Cochran, Indio CA Merv Griffin/ Anthony Productions Inc, Hollywood CA James H. Bond/ Bond Operating Co, Las Vegas NV James H. Bond/ Gemini Resources, Las Vegas NV US Customs Service CA: seized Tarrant County Junior College,	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69 12.3.69/71 29.4.71/78 15.2.79 1.7.79/83 7.83/85
		YV-P-EPC N107WB N475AB N13JC N333MG N444GR	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK Jaqueline Cochran, Indio CA Merv Griffin/ Anthony Productions Inc, Hollywood CA James H. Bond/ Bond Operating Co, Las Vegas NV James H. Bond/ Gemini Resources, Las Vegas NV US Customs Service CA: seized Tarrant County Junior College, Fort Worth-Meacham Field TX (instructional airframe: donated by USCS) Tarrant County College, Ft Worth-Meacham Field TX	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69 12.3.69/71 29.4.71/78 15.2.79 1.7.79/83 7.83/85 3.10.85/12
		YV-P-EPC N107WB N475AB N13JC N333MG N444GR	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK Jaqueline Cochran, Indio CA Merv Griffin/ Anthony Productions Inc, Hollywood CA James H. Bond/ Bond Operating Co, Las Vegas NV James H. Bond/ Gemini Resources, Las Vegas NV US Customs Service CA: seized Tarrant County Junior College, Fort Worth-Meacham Field TX (instructional airframe: donated by USCS)	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69 12.3.69/71 29.4.71/78 15.2.79 1.7.79/83 7.83/85 3.10.85/12
		YV-P-EPC N107WB N475AB N13JC N333MG N444GR	Williams Brothers Co Williams Brothers Sudamericana Ltd Williams Brothers Co Arkansas Best Fast Freight System, Fort Smith AR Central Plains Enterprises Inc, Tulsa OK Jaqueline Cochran, Indio CA Merv Griffin/ Anthony Productions Inc, Hollywood CA James H. Bond/ Bond Operating Co, Las Vegas NV James H. Bond/ Gemini Resources, Las Vegas NV US Customs Service CA: seized Tarrant County Junior College, Fort Worth-Meacham Field TX (instructional airframe: donated by USCS) Tarrant County College, Ft Worth-Meacham Field TX (rest. to airworthy by Tarrant County College Aviation	11.55/56 10.56/57 2.57/58 11.4.58/62 8.11.62/64 5.1.65/69 12.3.69/71 29.4.71/78 15.2.79 1.7.79/83 7.83/85 3.10.85/12

N333MG noted Long Beach CA 8.6.71 tailwheel; N444GR noted Ft Worth-Meacham TX 30.3.87, 10.87 in technical school grounds; N444GR noted Tarrant County Junior College 9.5.03 at Meacham Field & 12.8.03, plate BA-31 built 12.54;

BA-32	E18S	N3651B	J. R. Gray Co, Dallas TX H. L. Brown	23.12.54 17.1.55/62
	E18S-9800		Fort Worth National Bank, Fort Worth TX	17.4.62/66
		N22T (1	Fort Worth National Bank, Fort Worth TX	8.1.66
		N205A (2	O. P. Leonard, Fort Worth TX	9.6.66/71
		,	The Windy Co, Fort Worth TX	19.4.71/72
			Roy A. Rogers	12.72/74
			Ginners Aviation	10.74/77
			Deanie Montgomery, Coriscana TX	3.5.77/79
			Southern Aero Traders, Miami FL	8.1.80/83
		(N205Z)	ntu: Southern Aero Traders. Miami FL	3.80
		N205A	House of Sesame Inc, Miami FL	16.2.83/89
			(noted impounded Boscobal, Jamaica 12.83)	
			Ben R. Bradley/ Ben Air Ltd, Frostproof FL	1.9.89/90
			Valentine Aviation, Pompano Beach FL	2.90
		N929DV	Valentine Aviation, Fort Lauderdale FL	6.90/91
			(fitted wings removed from N68V BA-282 c86)	
			Ben Air Ltd, Frostproof FL	.91
			Billy J. Wallace, Evergreen CO	2.10.91/92
			Styles Aviation, Lagrangeville NY	1.94
			Rand W. Siegfried, Palo Alto CA	7.3.94/20
BA-33	N205A note N929DV at I N929DV at I	Beech Flyin 1 Ted Richards- Oshkosh WI 3 Sed Edwards Glyin Lakelanc Oshkosh WI 8 Sted Beech Fl Oshkosh 30.7 Beech Flyin, Ted Janesville Beech flyin To Oshkosh 30.7 Beech flyin To	lamaica 12.83; Fullahoma TN 10.94, 13.10.95; Gebaur AFB near Kansas City MO 7.97: plate BA-32 built 7.96 won classic award. Rand Siegried; AFB CA for period in 97 for evaluation by USAF Test Pilot I FL 7.4.97; 8.97; Wichita KS 9.10.97; yIn Wichita KS 11.10.97; 98 Rand Siegfried, Palo Alto CA, plate BA-32 built 12.54, p 7.00 Rand Siegfried; Tullahoma TN 18.10.00;	t School; plate:
BA-33	E185	N3648B N45CM	Fort Worth National Bank, Fort Worth TX	63
		N49UC	Union Bag Camp Paper Corp, New York NY	63
		N499C	Wimbish Aviation, Greensboro NC	69/70
			John L. Wesley, Niles MI	72
			Stockert Flying Service, South Bend IN	20.7.77/82
			struck-off USCR	.82
BA-34	E18S	N3628B	Gopher Aviation, Rochester Airport MN	30.12.54
	-9700		Beloit Iron Works, West Orange NJ	12.54/68
			Earl W. Fugate, Janesville WI	10.68/70
			Russell L. Ingram	10.70/71
			Pullman Bank & Trust Co, Chicago IL	12.2.71/72
			Robert L. Mishler/ Four Winds Aviation	10.1.72/73
			Air Best de Puerto Rico Inc, San Juan, Puerto Rico	11.5.73
			crashed forced landing on highway due weather,	40.44 =0
			San Juan, Puerto Rico	13.11.73
			Banco Commercial de Mayaguez:	70
			derelict San Juan-Isla Grade Puerto Rico	79

70USCR quotes owner Pullman Bank & Trust! N3628B accident report 13.11.73: Air Best de PR, flight St Thomas-San Juan, continued VFR flight into adverse weather, refused SPC VFR by ATC, did not divert, pilot & 10 pax minor injuries;

BA-35	E18S	N3623B	Mountain States Aviation	6.1.55
	-9700	NIGODO	Colorado Oil & Gas Corp, Houston TX	6.1.55/58
		N203C	Colorado Oil & Gas Corp, Houston TX R. C. Hitchcock & Sons/ Hitchcock Industries,	26.6.58/64
			Minneapolis MN	7.5.64/72
			Carl V. Hass/ Kingston Enterprises Inc	11.7.72/73
			Torry Service Distributors Inc	17.9.73/75
			Nevada Pacific Airlines, Las Vegas NV	9.4.75/79
			gear collapsed landing, Grand Canyon AZ	24.8.75
			Aircraft Associates	11.1.79
			ARL Flying Service	5.79/81
			Ruiz Fernando O'Brien	12.1.81
			George B. Carlton, El Paso TX	24.1.81/91
			(FAA report 1.81: Carlton gave false address)	
			stripped airframe at Globe-San Carlos Apache AZ	97/18
	photo 01: N	V203C derelict	4.8.75: Nevada Pacific, mechanical failure, 8 unhurt; at desert airstrip with 3 other Beech 18s; irfield 12.17 stripped hulk;	
3A-36	E18S	N3333C	Metallurgical Inc, Minneapolis MN	63/64
			General United Leasing Corp, Bettendorf IA	66/69
			registration pending: USCR	70
			crashed destroyed by fire, Delavan WI after takeoff	
			from Lake Lawn Strip WI	25.7.70
BA-37	E18S	N3456B (2	reg	
		N117S	rereg	
		N274TW	Transwestern Pipeline Co, Houston TX	63/63
	trigear	N403FW	Rolair Corp/ Wright Air Lines, Cleveland OH	9.7.66/70
			damaged in ground collision with parked Beech Bonanza	
			N3421B, Cleveland-Burke Lakefront OH	27.9.67
			Shenandoah Airlines, Baltimore MD: leased	70
			Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport,	70
			Shenandoah Airlines, Baltimore MD: leased	
	accident re	port 27.9.67 V	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier;	70 3.2.70
	accident re	port 3.2.70: SI	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA,	70 3.2.70
	accident re	port 3.2.70: SI	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier;	70 3.2.70
BA-38	accident re	port 3.2.70: SI	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA,	70 3.2.70
3A-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons	70 3.2.70 26.1.55 17.5.55
3A-38	accident re forced land	port 3.2.70: Sl ling off-airport	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons	70 3.2.70 26.1.55 17.5.55 1.12.58/60
3A-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61
3A-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68
3A-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71
3A-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72
IA-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B N700R	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73
IA-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill Frank A. Hill	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73 11.73/74
A-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B N700R	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill Frank A. Hill John S. Glitsky/ Airplane Leasing Inc	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73 11.73/74 12.7.74/81
3A-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B N700R	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill Frank A. Hill John S. Glitsky/ Airplane Leasing Inc James A. Price, Fort Lauderdale FL	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73 11.73/74 12.7.74/81 21.9.81/84
3A-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B N700R	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill Frank A. Hill John S. Glitsky/ Airplane Leasing Inc James A. Price, Fort Lauderdale FL Sun Air Services Ltd, Bahamas	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73 11.73/74 12.7.74/81 21.9.81/84 11.84/87
3A-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B N700R	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill Frank A. Hill John S. Glitsky/ Airplane Leasing Inc James A. Price, Fort Lauderdale FL Sun Air Services Ltd, Bahamas Lucaya Beach Air Services Ltd, Bahamas	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73 11.73/74 12.7.74/81 21.9.81/84 11.84/87 20.2.87
3A-38	accident re forced land	port 3.2.70: SI ling off-airport N3702B N700R	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; nenandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill Frank A. Hill John S. Glitsky/ Airplane Leasing Inc James A. Price, Fort Lauderdale FL Sun Air Services Ltd, Bahamas	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73 11.73/74 12.7.74/81 21.9.81/84 11.84/87
3A-38	accident re forced land E18S	port 3.2.70: SI ling off-airport N3702B N700R N10PK	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; henandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill Frank A. Hill John S. Glitsky/ Airplane Leasing Inc James A. Price, Fort Lauderdale FL Sun Air Services Ltd, Bahamas Lucaya Beach Air Services Ltd, Bahamas Kym Pitts: sale documentation not completed sale reported, Freeport, Bahamas: USCR	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73 11.73/74 12.7.74/81 21.9.81/84 11.84/87 20.2.87 9.9.87 91
	accident re forced land	port 3.2.70: SI ling off-airport N3702B N700R	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; henandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill Frank A. Hill John S. Glitsky/ Airplane Leasing Inc James A. Price, Fort Lauderdale FL Sun Air Services Ltd, Bahamas Lucaya Beach Air Services Ltd, Bahamas Kym Pitts: sale documentation not completed sale reported, Freeport, Bahamas: USCR	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73 11.73/74 12.7.74/81 21.9.81/84 11.84/87 20.2.87 9.9.87 91 25.1.55
3A-38 3A-39	accident re forced land E18S	port 3.2.70: SI ling off-airport N3702B N700R N10PK	Shenandoah Airlines, Baltimore MD: leased crashed dest. in forced landing off-airport, struck hill, fence & barn, Weyers Cave VA /right Airlines, commuter air carier; henandoah Air, flight Washington DCA to Weyers Cave VA, during landing approach; Wings Inc Dexter D. Coffin/ C. H. Dexter & Sons C. H. Dexter & Sons Atlantic Aviation Corp Consolidated Aircraft Repair Inc, Fort Wayne IN Comfo-Air Corp, Wakarusa IN Skystream Inc, Plymouth IN Frank A. Hill Frank A. Hill John S. Glitsky/ Airplane Leasing Inc James A. Price, Fort Lauderdale FL Sun Air Services Ltd, Bahamas Lucaya Beach Air Services Ltd, Bahamas Kym Pitts: sale documentation not completed sale reported, Freeport, Bahamas: USCR	70 3.2.70 26.1.55 17.5.55 1.12.58/60 1.3.60/61 12.61/68 29.1.68/71 72 12.71/73 11.73/74 12.7.74/81 21.9.81/84 11.84/87 20.2.87 9.9.87 91

N144NK	American Enka Corp/Enka Foundation, Enka NC	19.1.60/71
N144NB	Asheville Flying Service, Asheville NC	9.7.71/86
	O. D. Griffin, Asheville NC	23.9.86/88
	Eagle Neck Aviation, Townsend GA	1.9.88/90
	Bradley Flying Service, Wethersfield CT	22.6.90/91
	Sacramento Aviation, Sacramento CA	12.2.91
	F1 Systems Inc, Bandon OR	5.93/94
	Wiley C. Sanders, Troy AL	1.4.94/20

N144NB noted Oshkosh WI 27.7.89, plate BA-39 ; N144NB noted Troy AL 7.97; N144NB noted Troy AL 13.8.98, plate: BA-39 built 1.55 owner Wiley Sanders;

BA-40	E18S	N3704B	Atlantic Aviation Service	2.2.55
		N83CP (1	Atlantic Aviation Service	11.55/56
		N83Q	Linden Flight Service	24.9.56
			Cornell Dubilier Electric Corp	12.56/59
			Airfactors Corp	15.9.59/60
		Wiles-Holloway Inc, Baton Rouge LA	29.6.60/61	
			H. O. Montag/ American Air Lease, The Dalles OR	27.3.61/65
			Cummins Oregon Diesel Inc, Portland OR	11.2.65/69
			Flightcraft Inc, Portland OR	69
			Midstate Aviation, Ellensburg WA	28.5.69/74
			Roger E. Hirst/ Pacific West Transportation/ Sintak Inc	5.5.74/81
			Eagle Aero Services, Carson City NV	10.81/82
			Victor L. Hawkins, Carmichael CA	2.8.82/14
			struck-off USCR	19.11.14
BA-41	E18S	N3705B	J. D. Reed Co, Houston TX	7.2.55/56
			Bridwell Oil Co	13.7.56/57
			G. L. Rowsey	26.7.57/59
			Moss-Gordin Lint Cleaner Co	4.6.59/61
		N75140	Moss-Gordin Lint Cleaner Co	22.3.61/64
			Botany Industries Inc, Dallas TX	63/64
			Continental Gin Co, Dallas TX	22.9.64/70
			Ralph E. Smelser, Memphis TN	20.5.70/72
			Seminole Flying Service	17.8.72/73
			Jack L. Rhoades/ Rhoades Aviation, Columbus IN	11.73/78
			(cargo floor installed 5.74, cockpit door 2.78)	
		N138JR	Rhoades Aviation/ Rhoades International Inc,	
			Seymour IN	31.8.78/88
			Centre Airlines, Centre Hall PA	3.4.88/89
			crashed into house after takeoff, destroyed,	
			Baltimore-Washington International MD	19.7.89
		N138JJ	Centre Airlines, Centre Hall PA: USCR	20.7.89/90
			struck-off USCR	18.6.90

N138JR accident report 19.7.89: fire in cockpit after takeoff, crashed into house while attempting to return for landing, Centre Airlines;

BA-42	E18S	N3706B	Atlantic Aviation Corp	2.2.55
			Coats & Clarks Operations Inc	10.2.55/57
	N380	Coats & Clarks Operations Inc	10.9.57/60	
		Richardson Homes Corp, Elkhart IN	21.9.60/66	
			Ohio Aviation Co, Dayton OH	10.3.66/68
		Abrams Aerial Survey Corp, Lansing MI	11.7.68/78	
		(conv. for aerial photographic survey 12.68)		
		Jeffrey J. Welch/ J & J Enterprises	11.78/80	
			Stanrich Aviation	29.1.80/90
	op: Eighth Air Cargo Centre Air Inc, Greenville SC Thomas A. Faulkner, Ooltewah TN	Centre Air Inc, Greenville SC	81	
			18.3.90	
			Thomas A. Faulkner, Ooltewah TN	12.4.91/14
			Southern Cross Aviation Inc, Wilmington DE	1.10.15/16
			Tessos Air Service, Wilmington DE	23.2.17/20

N380 noted Oshawa ONT 10.5.79 Abrams Aerial Survey;

N380 noted Stewart NY 16.1.81 Eight Air Cargo, operating for Emery; N380 noted La Guardia NY 11.8.81 Eighth Air Cargo; N380 at flyin Lakeland FL 8.4.97; N380 at Beech flyin Tullahoma TN 18.10.98 tailwheel, Pete Faulkner, Ooltawah TN; N380 at Beech FlyIn, Tullahoma TN 18.10.00;

Lufkin Foundry & Machine Co5.3.55Southland Paper Mills Inc, Lufkin TX24.6.55/63Malone Freight Lines, Birmingham AL12.7.63/64N282M (1Malone Freight Lines, Birmingham AL29.6.64/68Albany Air Service, Albany GA11.9.68/70N711DNRobert Nelson/Air Transportation Co19.4.70Sherno Research Centre Inc, Cresco PA12.70/72Robert W. Trainer & J. William Bohmier18.1.72Hamilton Aircraft Co, Tucson AZ28.8.72SMB Stage Line Inc, Des Moines IA12.72/88Hamilton(conversion to Hamilton Westwind III, PT-6A-20 turbines, completed by Hamilton Aircraft Co 9.3.73)Shark Aviation11.88/89Aero Tech, Molalla OR28.9.89/90Lawrence E, Hill/ Para Drop, Coolidge AZ29.5.90/93Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use)struck-off USCRN711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;14.8.11N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles; In K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH Vestort Inc, Calcot Ltd, Bakersfield CA31.7.59/76 Polestar Inc, San Diego CAKart Machines & Service Inc, St James MO14.8.8/485 (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cockpit hatch	BA-43	E190	NIOZOOD		
Lufkin Foundry & Machine Co 5.3.55 Southland Paper Mills Inc, Lufkin TX 24.6.55/63 Malone Freight Lines, Birmingham AL 29.6.64/68 Albany Air Service, Albany GA 11.9.68/70 N711DN Robert Nelson/Air Transportation Co 19.4.70 Sherno Research Centre Inc, Cresco PA 12.70/72 Robert W. Trainer & J. William Bohmier 18.1.72 Hamilton Aircraft Co, Tucson AZ 28.8.72 SMB Stage Line Inc, Des Moines IA 12.72/88 Hamilton (conversion to <i>Hamilton Westwind III</i> , PT-6A-20 turbines, completed by Hamilton Aircraft Co 9.3.73) Shark Aviation 11.88/89 Aero Tech, Molalla OR 28.9.89/90 Lawrence E. Hill/ Para Drop, Coolidge AZ 29.5.90/93 Para Drop, Las Vegas NV 3.92/93 damaged in groundloop on takeoff, Eloy AZ 15.4.92 K & K Aircraft Inc, Bridgewater VA 99, spares use) struck-off USCR 4.8.11 N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted DSM 26.8.7 "SMB Stage Lines" titles; N711DN noted DSM 26.8.7 "SMB Stage Lines" titles; Nestwind III tailwheel; N711DN noted DSM 26.8.7 "SMB Stage Lines" titles; Nestwind III tailwheel; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles; Nestwind III tailwheel; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles; Nestwind III tailwheel; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed; BA-44 E18S N3710B Ohio Aviation Co, Dayton OH 28.7.55 North American Van Lines Inc 28.7.55/59 Westcot Inc' Calcot Ltd, Bakersfield CA 31.7.59/76 Polestar Inc, San Diego CA 11.76/84 Air Machines & Service Inc, St James MO 14.8.84/85 (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cockpit hatch installed 7.85) Hoganair Inc, Hamilton OH 22.7.85/90		E103	N3703B		31.1.55
Malone Freight Lines, Birmingham AL12.7.63/64N282M (1Malone Freight Lines, Birmingham AL29.6.64/68Albany Air Service, Albany GA11.9.68/70N711DNRobert Nelson/Air Transportation Co19.4.70Sherno Research Centre Inc, Cresco PA12.70/72Robert W. Trainer & J. William Bohmier18.1.72Hamilton Aircraft Co, Tucson AZ28.8.72SMB Stage Line Inc, Des Moines IA12.72/88Hamilton(conversion to Hamilton Aircraft Co 9.3.73)Shark Aviation11.88/89Aero Tech, Molalla OR29.5.90/93Lawrence E. Hill/ Para Drop, Coolidge AZ29.5.90/93Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use)struck-off USCRN711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles;N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles; in K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH28.7.55/59Westcoi Inc/ Calcot Ltd, Bakersfield CA31.7.59/76Polestar Inc, San Diego CA11.7.6/84Air Machines & Service Inc, St James MO14.8.84/85(Aerospace Products cockpit hatch installed 10.84, Aerospace Products cockpit hatch installed 7.85)14.8.84/85Hamilton Aircraft Co, CHage Products cockpit hatch installed 7.85)Hoganair Inc, Hamilton OH22.7.85/90				Lufkin Foundry & Machine Co	5.3.55
N282M (1Malone Freight Lines, Birmingham AL29.6.64/68 Albany Air Service, Albany GA11.9.68/70N711DNRobert Nelson/Air Transportation Co19.4.70Sherno Research Centre Inc, Cresco PA12.70/72 Robert W. Trainer & J. William Bohmier18.1.72 L.2.70/72Hamilton Aircraft Co, Tucson AZ28.8.72 SMB Stage Line Inc, Des Moines IA12.72/68 L.2.72/68Hamilton(conversion to Hamilton Westwind III, PT-6A-20 turbines, completed by Hamilton Aircraft Co 9.3.73) Shark Aviation11.88/89 Aero Tech, Molalla ORAero Tech, Molalla OR28.9.89/90 Lawrence E. Hill/ Para Drop, Coolidge AZ29.5.90/93 Para Drop, Las Vegas NVAg2/93 damaged in groundloop on takeoff, Eloy AZ15.4.92 K & K Aircraft Inc, Bridgewater VA2.2.93/11 (stored dismantled Bridgewater VA 99, spares use) struck-off USCRN711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles in K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH Westcot Inc/ Calcot Ltd, Bakersfield CA Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Produc				Southland Paper Mills Inc, Lufkin TX	24.6.55/63
N282M (1       Malone Freight Lines, Birmingham AL       29.6.64/68         Albany Air Service, Albany GA       11.9.68/70         N711DN       Robert Nelson/Air Transportation Co       19.4.70         Sherno Research Centre Inc, Cresco PA       12.70/72         Robert W. Trainer & J. William Bohmier       18.1.72         Hamilton Aircraft Co, Tucson AZ       28.8.72         SMB Stage Line Inc, Des Moines IA       12.72/88         (conversion to Hamilton Westwind III, PT-6A-20 turbines, completed by Hamilton Aircraft Co 9.3.73)       11.88/89         Shark Aviation       11.88/89         Aero Tech, Molalla OR       28.9.89/90         Lawrence E. Hill/ Para Drop, Coolidge AZ       29.5.90/93         Para Drop, Las Vegas NV       3.92/93         damaged in groundloop on takeoff, Eloy AZ       15.4.92         K & Kaircraft Inc, Bridgewater VA       2.2.93/11         (stored dismantled Bridgewater VA 99, spares use)       struck-off USCR         N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;       N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;         N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles, in K&K storage shed;       34.44         E18S       N3710B       Ohio Aviation Co, Dayton OH       28.7.55         North American Van Lines Inc       28.7.55       No				Malone Freight Lines, Birmingham AL	12.7.63/64
Albany Air Service, Albany GĂ 11.9.68/70 N711DN Robert Nelson/Air Transportation Co 19.4.70 Sherno Research Centre Inc, Cresco PA 12.70/72 Robert W. Trainer & J. William Bohmier 18.1.72 Hamilton Aircraft Co, Tucson AZ 28.8.72 SMB Stage Line Inc, Des Moines IA 12.72/88 Hamilton (conversion to <i>Hamilton Westwind III</i> , PT-6A-20 turbines, Westwind III conversion to <i>Hamilton Aircraft Co</i> 9.3.73) Shark Aviation Aircraft Co 9.3.73) Shark Aviation Co 7.200, Coolidge AZ 29.5.90/93 Para Drop, Las Vegas NV 3.92/93 damaged in groundloop on takeoff, Eloy AZ 15.4.92 K & K Aircraft Inc, Bridgewater VA 99, spares use) struck-off USCR 4.8.11 N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed; BA-44 E18S N3710B Ohio Aviation Co, Dayton OH 28.7.55 North American Van Lines Inc 28.7.55/59 Westcot Inc/ Calcot Ltd, Bakersfield CA 31.7.59/76 Polestar Inc, San Diego CA 11.76/84 Air Machines & Service Inc, St James MO 14.8.84/85 (Aerospace Products cockpit hatch installed 10.84, Aerospace Products c			N282M (1	Malone Freight Lines, Birmingham AL	29.6.64/68
N711DNRobert Nelson/Air Transportation Co19.4.70Sherno Research Centre Inc, Cresco PA12.70/72Robert W. Trainer & J. William Bohmier18.1.72Hamilton Aircraft Co, Tucson AZ28.8.72SMB Stage Line Inc, Des Moines IA12.72/88Hamilton(conversion to Hamilton Westwind III, PT-6A-20 turbines, completed by Hamilton Aircraft Co 9.3.73)Shark Aviation11.88/89Aero Tech, Molalla OR28.9.89/90Lawrence E, Hill/ Para Drop, Coolidge AZ29.5.90/93Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use) struck-off USCR4.8.11N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles; N711DN noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH Polestar Inc, San Diego CA28.7.55BA-44E18SN3710BOhio Aviation Co, Dayton OH Polestar Inc, San Diego CA28.7.55Air Machines & Service Inc, St James MO (Aerospace Products cargo door installed 10.84, Aerospace Products cockpit hatch installed 10.84, Aerospace Products cockpit on stalled 7.85) Hoganair Inc, Hamilton OH22.7.85/90			,		
Sherno Research Centre Inc, Cresco PA12.70/72Robert W. Trainer & J. William Bohmier18.1.72Hamilton Aircraft Co, Tucson AZ28.8.72SMB Stage Line Inc, Des Moines IA12.72/88(conversion to Hamilton Westwind III, PT-6A-20 turbines, westwind IIIcompleted by Hamilton Aircraft Co 9.3.73)Shark Aviation11.88/89Aero Tech, Molalla OR28.9.89/90Lawrence E, Hill/ Para Drop, Coolidge AZ29.5.90/93Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismanted Bridgewater VA 99, spares use)struck-off USCRN711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles in K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH28.7.55 North American Van Lines IncBA-44E18SN3710BOhio Aviation Co, Dayton OH28.7.55/59Westort Inc/ Calcot Ltd, Bakersfield CA31.7.59/76 Polestar Inc, San Diego CA11.76/84 Air Machines & Service Inc, St James MO14.8.84/85 (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cockpit hatch installed 10.84, Aerospace Products cockpit hatch installed 10.84, Aerospace Products cockpit hatch installed 7.85) Hoganair Inc, Hamilton OH22.7.85/90			N711DN		
Robert W. Trainer & J. William Bohmier18.1.72Hamilton Aircraft Co, Tucson AZ28.8.72SMB Stage Line Inc, Des Moines IA12.72/88Hamilton(conversion to Hamilton Westwind III, PT-6A-20 turbines, completed by Hamilton Aircraft Co 9.3.73)Westwind IIIcompleted by Hamilton Aircraft Co 9.3.73)Shark Aviation11.88/89Aero Tech, Molalla OR28.9.89/90Lawrence E. Hill/ Para Drop, Coolidge AZ29.5.90/93Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use) struck-off USCR4.8.11N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH North American Van Lines Inc28.7.55/50 Westcot Inc/ Calcot Ltd, Bakersfield CA Air Machines & Service Inc, St James MO (Aerospace Products cargo door installed 10.84, Aerospace Products cargo door installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH22.7.85/90					
Hamilton Aircraft Co, Tucson AZ28.8.72SMB Stage Line Inc, Des Moines IA12.72/88Hamilton(conversion to Hamilton Westwind III, PT-6A-20 turbines, completed by Hamilton Aircraft Co 9.3.73)Westwind IIIShark Aviation11.88/89Aero Tech, Molalla OR28.9.89/90Lawrence E. Hill/ Para Drop, Coolidge AZ29.5.90/93Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use) struck-off USCR4.8.11N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles in K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH Noth American Van Lines Inc28.7.55/59 Westcot Inc/ Calcot Ltd, Bakersfield CA Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cockpit hatch					
SMB Stage Line Inc, Des Moines IA12.72/88Hamilton(conversion to Hamilton Westwind III, PT-6A-20 turbines, completed by Hamilton Aircraft Co 9.3.73) Shark Aviation11.88/89Aero Tech, Molalla OR28.9.89/90Lawrence E. Hill/ Para Drop, Coolidge AZ29.5.90/93Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use) struck-off USCR4.8.11N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles in K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH North American Van Lines Inc28.7.55 S9BA-44E18SN3710BOhio Aviation Co, Dayton OH North American Van Lines Inc28.7.55/59 Westcot Inc/ Calcot Ltd, Bakersfield CA Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cockpit hatch					
Hamilton(conversion to Hamilton Westwind III, PT-6A-20 turbines, completed by Hamilton Aircraft Co 9.3.73) Shark Aviation11.88/89 Aero Tech, Molalla OR Lawrence E. Hill/ Para Drop, Coolidge AZ 29.5.90/93 Para Drop, Las Vegas NV damaged in groundloop on takeoff, Eloy AZ K & K Aircraft Inc, Bridgewater VA Struck-off USCR11.88/89 29.5.90/93 2.2.93/11 (stored dismantled Bridgewater VA struck-off USCR28.9.89/90 2.2.93/11 (stored dismantled Bridgewater VA 4.8.11N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH Westcot Inc/ Calcot Ltd, Bakersfield CA Air Machines & Service Inc, St James MO (Aerospace Products cargo door installed 10.84, Aerospace Products cargo door installed 10.84, Aerospace Products cargo door installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH22.7.85/90					
Westwind III       completed by Hamilton Aircraft Co 9.3.73)         Shark Aviation       11.88/89         Aero Tech, Molalla OR       28.9.89/90         Lawrence E. Hill/ Para Drop, Coolidge AZ       29.5.90/93         Para Drop, Las Vegas NV       3.92/93         damaged in groundloop on takeoff, Eloy AZ       15.4.92         K & K Aircraft Inc, Bridgewater VA       2.2.93/11         (stored dismantled Bridgewater VA 99, spares use)       11.88/89         struck-off USCR       4.8.11         N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel;       N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;         N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;       N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles;         N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;       34.44         BA-44       E18S       N3710B       Ohio Aviation Co, Dayton OH       28.7.55/59         Westcot Inc/ Calcot Ltd, Bakersfield CA       31.7.59/76       Polestar Inc, San Diego CA       11.76/84         Air Machines & Service Inc, St James MO       14.8.84/85       (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cordpit door installed 7.85)       4.8.785         Hoganair Inc, Hamilton OH       22.7.85/90       2.7.85/90		Llomilton			
Shark Aviation11.88/89Aero Tech, Molalla OR28.9.89/90Lawrence E. Hill/ Para Drop, Coolidge AZ29.5.90/93Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use)struck-off USCRN711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel;N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles in K&K storage shed;3A-44E18SN3710BOhio Aviation Co, Dayton OH28.7.55North American Van Lines Inc28.7.55/59Westcot Inc/ Calcot Ltd, Bakersfield CA31.7.59/76Polestar Inc, San Diego CA11.76/84Air Machines & Service Inc, St James MO14.8.84/85(Aerospace Products cockpit hatch installed 10.84, Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85)22.7.85/90					,
Aero Tech, Molalla OR28.9.89/90Lawrence E. Hill/ Para Drop, Coolidge AZ29.5.90/93Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use)struck-off USCRN711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel;N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles in K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH28.7.55Westcot Inc/ Calcot Ltd, Bakersfield CA31.7.59/76Polestar Inc, San Diego CA11.76/84Air Machines & Service Inc, St James MO14.8.84/85(Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85)12.7.85/90Hoganair Inc, Hamilton OH22.7.85/90		westwind III			44.00/00
Lawrence E. Hill/ Para Drop, Coolidge AZ29.5.90/93Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use) struck-off USCR4.8.11N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" Westwind turboprop; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;BA-44E18SN3710BOhio Aviation Co, Dayton OH North American Van Lines Inc28.7.55 North American Van Lines Inc28.7.55/59 Westcot Inc/ Calcot Ltd, Bakersfield CA Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH22.7.85/90					
Para Drop, Las Vegas NV3.92/93damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use)struck-off USCRN711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel;4.8.11N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;4.8.11N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles;4.8.15N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" titles in K&K storage shed;3.444BA-44E18SN3710BOhio Aviation Co, Dayton OH North American Van Lines Inc28.7.55 North American Van Lines Inc28.7.55/59 Vestcot Inc/ Calcot Ltd, Bakersfield CA Air Machines & Service Inc, St James MO (Aerospace Products cargo door installed 10.84, Aerospace Products cargo door installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH22.7.85/90					
damaged in groundloop on takeoff, Eloy AZ15.4.92K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use) struck-off USCR4.8.11N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" Westwind turboprop; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;3A-44E18SN3710BOhio Aviation Co, Dayton OH North American Van Lines Inc Polestar Inc, San Diego CA Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH22.7.85/90					
K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use) struck-off USCR4.8.11N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" Westwind turboprop; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;3A-44E18SN3710BOhio Aviation Co, Dayton OH North American Van Lines Inc28.7.55 North American Van Lines Inc28.7.55/59 Nestcot Inc/ Calcot Ltd, Bakersfield CA Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH22.7.85/90					3.92/93
K & K Aircraft Inc, Bridgewater VA2.2.93/11(stored dismantled Bridgewater VA 99, spares use) struck-off USCR4.8.11N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" Westwind turboprop; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;3A-44E18SN3710BOhio Aviation Co, Dayton OH North American Van Lines Inc28.7.55 North American Van Lines Inc28.7.55/59 Nestcot Inc/ Calcot Ltd, Bakersfield CA Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH22.7.85/90				damaged in groundloop on takeoff, Eloy AZ	15.4.92
(stored dismantled Bridgewater VA 99, spares use) struck-off USCR 4.8.11 N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" Westwind turboprop; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed; 3A-44 E18S N3710B Ohio Aviation Co, Dayton OH 28.7.55 North American Van Lines Inc 28.7.55/9 Westcot Inc/ Calcot Ltd, Bakersfield CA 31.7.59/76 Polestar Inc, San Diego CA 11.76/84 Air Machines & Service Inc, St James MO 14.8.84/85 (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH 22.7.85/90					2.2.93/11
struck-off USCR4.8.11N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" Westwind turboprop; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;3A-44E18SN3710BOhio Aviation Co, Dayton OH North American Van Lines Inc28.7.55 28.7.55/59 Westcot Inc/ Calcot Ltd, Bakersfield CA Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH22.7.85/90					
N711DN noted Syracuse NY 23.6.77 "SMB Stage Lines" titles, Westwind III tailwheel; N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles; N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" Westwind turboprop; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed; 3A-44 E18S N3710B Ohio Aviation Co, Dayton OH 28.7.55 North American Van Lines Inc 28.7.55/9 Westcot Inc/ Calcot Ltd, Bakersfield CA 31.7.59/76 Polestar Inc, San Diego CA 11.76/84 Air Machines & Service Inc, St James MO 14.8.84/85 (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH 22.7.85/90					4811
N711DN noted DSM 26.8.80 Westwind III, "SMB Stage Lines" titles;         N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" Westwind turboprop;         N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;         3A-44       E18S       N3710B       Ohio Aviation Co, Dayton OH       28.7.55         North American Van Lines Inc       28.7.55/59       Westcot Inc/ Calcot Ltd, Bakersfield CA       31.7.59/76         Polestar Inc, San Diego CA       11.76/84       Air Machines & Service Inc, St James MO       14.8.84/85         (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85)       Hoganair Inc, Hamilton OH       22.7.85/90		NZ11DN pot	d Curroquaa	NV 22 6 77 "SMD Store Lines" titles Meetwind III toilube	-1:
N711DN noted Dallas-Ft Worth TX 10.87, "SMB Stage Lines" Westwind turboprop; N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;         BA-44       E18S       N3710B       Ohio Aviation Co, Dayton OH       28.7.55         North American Van Lines Inc       28.7.55/59       Westcot Inc/ Calcot Ltd, Bakersfield CA       31.7.59/76         Polestar Inc, San Diego CA       11.76/84       Air Machines & Service Inc, St James MO       14.8.84/85         (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85)       22.7.85/90					<del>,</del>
N711DN fuselage noted Bridgewater VA 11.8.99 "Skydive" titles in K&K storage shed;         BA-44       E18S       N3710B       Ohio Aviation Co, Dayton OH       28.7.55         North American Van Lines Inc       28.7.55/59       Westcot Inc/ Calcot Ltd, Bakersfield CA       31.7.59/76         Polestar Inc, San Diego CA       11.76/84       Air Machines & Service Inc, St James MO       14.8.84/85         (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85)       Hoganair Inc, Hamilton OH       22.7.85/90					
3A-44       E18S       N3710B       Ohio Aviation Co, Dayton OH       28.7.55         North American Van Lines Inc       28.7.55/59         Westcot Inc/ Calcot Ltd, Bakersfield CA       31.7.59/76         Polestar Inc, San Diego CA       11.76/84         Air Machines & Service Inc, St James MO       14.8.84/85         (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85)       22.7.85/90					d.
North American Van Lines Inc28.7.55/59Westcot Inc/ Calcot Ltd, Bakersfield CA31.7.59/76Polestar Inc, San Diego CA11.76/84Air Machines & Service Inc, St James MO14.8.84/85(Aerospace Products cockpit hatch installed 10.84,Aerospace Products cargo door installed 7.85)Hoganair Inc, Hamilton OH22.7.85/90		INT I DIN IUSE	lage noted i	Shugewaler VA 11.0.99 Skyulve lilles in Kak slorage she	u,
North American Van Lines Inc28.7.55/59Westcot Inc/ Calcot Ltd, Bakersfield CA31.7.59/76Polestar Inc, San Diego CA11.76/84Air Machines & Service Inc, St James MO14.8.84/85(Aerospace Products cockpit hatch installed 10.84,Aerospace Products cargo door installed 7.85)Hoganair Inc, Hamilton OH22.7.85/90	3A-44	F18S	N3710B	Ohio Aviation Co. Davton OH	28.7.55
Westcot Inc/ Calcot Ltd, Bakersfield CA31.7.59/76Polestar Inc, San Diego CA11.76/84Air Machines & Service Inc, St James MO14.8.84/85(Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85)22.7.85/90		2.00			
Polestar Inc, San Diego CA11.76/84Air Machines & Service Inc, St James MO14.8.84/85(Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85)22.7.85/90					
Air Machines & Service Inc, St James MO14.8.84/85(Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH22.7.85/90					
(Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH 22.7.85/90					11.70/04
Aerospace Products cargo door installed 7.85)Hoganair Inc, Hamilton OH22.7.85/90					44004/05
Hoganair Inc, Hamilton OH 22.7.85/90				Air Machines & Service Inc, St James MO	14.8.84/85
				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84,	14.8.84/85
lim West/ Sky Dive Green County Inc. Venia OH 24.00/02				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85)	
				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH	22.7.85/90
Parawings LLC, Frankfort KY 18.2.04/06				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH	
Endless Mountain Skydivers Inc, Dalton PA 23.4.07/20				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH	22.7.85/90
				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY	22.7.85/90 2.4.90/02
				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA	22.7.85/90 2.4.90/02 18.2.04/06
				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA	22.7.85/90 2.4.90/02 18.2.04/06
titles "Sky Dive The Legend, Xenia OH";		N3710B note	d Green Cou	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; Unty OH 6.8.99 Skydive, being flown by owner Jim West,	22.7.85/90 2.4.90/02 18.2.04/06
		N3710B note	d Green Cou	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; Unty OH 6.8.99 Skydive, being flown by owner Jim West,	22.7.85/90 2.4.90/02 18.2.04/06
3A-45 FT85 N3709B J. K. GRAV CO. Dallas LX 31.1.55		N3710B note titles "Sky Div	d Green Cou /e The Lege	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; unty OH 6.8.99 Skydive, being flown by owner Jim West, nd, Xenia OH";	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20
	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; unty OH 6.8.99 Skydive, being flown by owner Jim West, nd, Xenia OH"; J. R. Gray Co, Dallas TX	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55
-9700 N62T Frank Wood Associates Inc 8.2.55	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; unty OH 6.8.99 Skydive, being flown by owner Jim West, nd, Xenia OH"; J. R. Gray Co, Dallas TX Frank Wood Associates Inc	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B N62T	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; unty OH 6.8.99 Skydive, being flown by owner Jim West, nd, Xenia OH"; J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B N62T	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; Inty OH 6.8.99 Skydive, being flown by owner Jim West, Ind, Xenia OH"; J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B N62T	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B N62T	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B N62T	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Leger N3709B N62T N62TP	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>A 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>XA 12.8.84 Polestar Inc;</i> <i>Inty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75)	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75)	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75)	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75)	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN 79 op: Mountain Air Cargo, Denver NC 80	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN op: Mountain Air Cargo, Denver NC	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81 79 80
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN 79 op: Mountain Air Cargo, Denver NC 80 ground collision with Cessna 421, Norfolk VA 22.12.80	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN op: Mountain Air Cargo, Denver NC ground collision with Cessna 421, Norfolk VA	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81 79 80 22.12.80
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN 79 op: Mountain Air Cargo, Denver NC 80 ground collision with Cessna 421, Norfolk VA 22.12.80 Equipment Leasing Corp of SC, Greenville SC 10.2.81/82	<del>3</del> A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>Unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN op: Mountain Air Cargo, Denver NC ground collision with Cessna 421, Norfolk VA Equipment Leasing Corp of SC, Greenville SC	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81 79 80 22.12.80 10.2.81/82
				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY	22.7.85/90 2.4.90/02 18.2.04/06
N3710B noted Burbank CA 12.8.84 Polestar Inc; N3710B noted Green County OH 6.8.99 Skydive, being flown by owner, lim West				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA	22.7.85/90 2.4.90/02 18.2.04/06
N3710B noted Green County OH 6.8.99 Skydive, being flown by owner Jim West,				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA	22.7.85/90 2.4.90/02 18.2.04/06
titles "Sky Dive The Legend, Xenia OH";				Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA	22.7.85/90 2.4.90/02 18.2.04/06
		N3710B note	d Green Cou	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; Unty OH 6.8.99 Skydive, being flown by owner Jim West,	22.7.85/90 2.4.90/02 18.2.04/06
3A-45 F18S N3709B J. R. Grav Co. Dallas TX 31.1.55		N3710B note titles "Sky Div	d Green Cou /e The Lege	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; unty OH 6.8.99 Skydive, being flown by owner Jim West, nd, Xenia OH";	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20
	A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; unty OH 6.8.99 Skydive, being flown by owner Jim West, nd, Xenia OH"; J. R. Gray Co, Dallas TX	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55
-9700 N62T Frank Wood Associates Inc 8.2.55	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; unty OH 6.8.99 Skydive, being flown by owner Jim West, nd, Xenia OH"; J. R. Gray Co, Dallas TX Frank Wood Associates Inc	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55
-9700 N62T Frank Wood Associates Inc 8.2.55	BA-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; unty OH 6.8.99 Skydive, being flown by owner Jim West, nd, Xenia OH"; J. R. Gray Co, Dallas TX Frank Wood Associates Inc	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55
-9700N62TFrank Wood Associates Inc8.2.55Texas Pacific Coal & Oil Co, Fort Worth TX2.5.55/64	A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B N62T	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; unty OH 6.8.99 Skydive, being flown by owner Jim West, nd, Xenia OH"; J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64
-9700N62TFrank Wood Associates Inc8.2.55Texas Pacific Coal & Oil Co, Fort Worth TX2.5.55/64N62TPTexas Pacific Oil Co, Dallas TX10.64/69	SA-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B N62T	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA CA 12.8.84 Polestar Inc; Inty OH 6.8.99 Skydive, being flown by owner Jim West, Ind, Xenia OH"; J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73	A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B N62T	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74	A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Lege N3709B N62T	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74	A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Leger N3709B N62T N62TP	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74	JA-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>A 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81	<del>}</del> A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>XA 12.8.84 Polestar Inc;</i> <i>Inty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor	}A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>A 12.8.84 Polestar Inc;</i> <i>Inty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75)	3A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75)	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN 79	<del>}</del> A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN 79 op: Mountain Air Cargo, Denver NC 80	JA-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN op: Mountain Air Cargo, Denver NC	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81 79 80
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN 79 op: Mountain Air Cargo, Denver NC 80 ground collision with Cessna 421, Norfolk VA 22.12.80	A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN op: Mountain Air Cargo, Denver NC ground collision with Cessna 421, Norfolk VA	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81 79 80 22.12.80
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN 79 op: Mountain Air Cargo, Denver NC 80 ground collision with Cessna 421, Norfolk VA 22.12.80 Equipment Leasing Corp of SC, Greenville SC 10.2.81/82	A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>Unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN op: Mountain Air Cargo, Denver NC ground collision with Cessna 421, Norfolk VA Equipment Leasing Corp of SC, Greenville SC	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81 79 80 22.12.80 10.2.81/82
-9700 N62T Frank Wood Associates Inc 8.2.55 Texas Pacific Coal & Oil Co, Fort Worth TX 2.5.55/64 N62TP Texas Pacific Oil Co, Dallas TX 10.64/69 Lamb Rental Tools Inc, Lafayette LA 28.4.69/73 Festus Flying Service, Festus MO 25.2.73/74 Telles Inc 22.5.74 (N62TS) ntu: Telles Inc 8.74 N62TP Southern National Leasing Corp, Charlotte NC 12.75/81 (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN 79 op: Mountain Air Cargo, Denver NC 80 ground collision with Cessna 421, Norfolk VA 22.12.80 Equipment Leasing Corp of SC, Greenville SC 10.2.81/82	A-45	N3710B note titles "Sky Div E18S	d Green Cou /e The Legen N3709B N62T N62TP (N62TS)	Air Machines & Service Inc, St James MO (Aerospace Products cockpit hatch installed 10.84, Aerospace Products cargo door installed 7.85) Hoganair Inc, Hamilton OH Jim West/ Sky-Dive Green County Inc, Xenia OH Parawings LLC, Frankfort KY Endless Mountain Skydivers Inc, Dalton PA <i>CA 12.8.84 Polestar Inc;</i> <i>Unty OH 6.8.99 Skydive, being flown by owner Jim West,</i> <i>nd, Xenia OH";</i> J. R. Gray Co, Dallas TX Frank Wood Associates Inc Texas Pacific Coal & Oil Co, Fort Worth TX Texas Pacific Oil Co, Dallas TX Lamb Rental Tools Inc, Lafayette LA Festus Flying Service, Festus MO Telles Inc ntu: Telles Inc Southern National Leasing Corp, Charlotte NC (Aerospace Products cargo door & floor installed 12.75) op: General Aviation Inc, Greenville TN op: Mountain Air Cargo, Denver NC ground collision with Cessna 421, Norfolk VA Equipment Leasing Corp of SC, Greenville SC	22.7.85/90 2.4.90/02 18.2.04/06 23.4.07/20 31.1.55 8.2.55 2.5.55/64 10.64/69 28.4.69/73 25.2.73/74 22.5.74 8.74 12.75/81 79 80 22.12.80

Lafayette Aviation, Pontiac MI John R. Fick/ Freight West Airways, Eagle River AK Ryan Air Service, Anchorage AK	25.3.85/88 1.6.88/95 15.3.95
Arctic Transportation Services, Anchorage AK	15.3.95/99
Catalina Flying Boats, Long Beach CA	10.2.00/02
dismantled at Long Beach CA due corrosion	3.01
struck-off USCR	22.4.03
Mark Thomson/ Aviation Warehouse, El Mirage CA (on truck at El Mirage 8.04)	04

N62TP accident report 22.12.80: Mountain Air Cargo, taxying for flight to Baltimore MD, 6.45pm, struck C421 in dark run-up area; N62TP noted Anchorage-Merrill Field AK 27.5.90, 5.5.91: both "Freight West Airways", nose wheel;

N62TP noted Anchorage-Merrill Field AK 27.5.90, 5.5.91: both "Freight West Airways", nose wheel; N62TP noted Long Beach CA 17.8.99 parked, at Catalina Flying Boats ramp, stripped of parts;

N62TP noted Long Beach CA 10.3.01 broken up due corrosion;

N62TP noted Long Beach CA 13.8.02 fuselage standing on gear;

N95CNew York Belting & Packing Co6.1Broyhill Furniture Factories, Lenoir NC11N561SPinellas Aircraft Inc, St Petersburg FL29Goldways Inc, Winter Park FL10Nevada Aviation, Las Vegas NV12	3.3.55/56 .6.56/57 1.5.57/67 9.5.67 0.67/69
Broyhill Furniture Factories, Lenoir NC11N561SPinellas Aircraft Inc, St Petersburg FL29Goldways Inc, Winter Park FL10Nevada Aviation, Las Vegas NV12	1.5.57/67 9.5.67 0.67/69
Broyhill Furniture Factories, Lenoir NC11N561SPinellas Aircraft Inc, St Petersburg FL29Goldways Inc, Winter Park FL10Nevada Aviation, Las Vegas NV12	9.5.67 0.67/69
Goldways Inc, Winter Park FL 10 Nevada Aviation, Las Vegas NV 12	0.67/69
Nevada Aviation, Las Vegas NV 12	
	2 00/74
Druge K. Dettlegen Cente Ang CA	2.69/71
Bruce K. Battleson, Santa Ana CA 8.	.10.71/76
William M. Meyers 1.	.12.76/77
damaged parachute jumper struck tailplane, Chino CA 30	0.4.77
Richard V. Gerdau, Los Angeles CA 4.	.6.77/84
Air Machines & Services Inc 15	5.2.84
op: St Louis Flight System Inc 84	4
crashed after takeoff, Marion IL 11	1.5.84
Central Air Parts Inc, Staunton IL 7.	.7.84
struck-off USCR .8-	34
N561S Central Air Parts Inc, Staunton IL: rest. to USCR 2.	.92/95
sale reported, House Springs MO: USCR 98	8/12
struck-off USCR 24	4.9.12

N561S noted Orange County CA 13.4.72, 22.5.73;

N561S noted Rubidoux-Flabob CA 2.9.81 blue & white, tailwheel, named The Yukon Jack:

BA-47	E18S	N3716B	Ohio Aviation Co, Dayton OH Airgo Inc	9.2.55 9.2.55/58
			0	
		N250RP	Rea Magnet Wire Co, Fort Wayne IN	10.58/67
			R. L. Taege & Associates Inc, Barrington IL	2.5.67/73
			Bennett C. Pollard/ Central Air Charter/	
			Midnight Air Express	2.2.73/77
			damaged struck unlit tug while taxying after landing	
			at night, Chicago-O'Hare IL	7.6.73
			Stuart E. Aegler	10.6.77/78
			Joseph Kubick, North Jackson OH	10.2.78
			Southern National Leasing Corp, Charlotte NC	22.6.78/83
			op: General Aviation Inc, Greenville TN	80
			op: Mountain Air Cargo, Denver NC	81/83
			Mountain Air Cargo, Denver NC	12.83/85
			Equipment Leasing Corp, Greenville SC	3.84
			J. Richard Wixom/ Blackhawk Airways, Janesville WI	20.3.85/91
			Methow Aviation, Everett WA	2.10.91/95
			crashed into mountain, near Butte MT	26.1.95

N250RP accident report 7.6.73: Central Air Charter: midnight, pilot unhurt;

BA-48	E18S	N3719B	J. D. Reed Co, Houston TX	22.4.55/58
			Union Producing Co, Shreveport LA	17.3.58/67
			Sidney K. Herold & Henry E. Linam	26.6.67/68
			S. W. Sisk/ Orion Airways, St Louis MO	30.8.68/69

Maplewood Bank & Trust Co: repossessed	3.11.69/70	
Sisk Aviation Activities Inc, St Louis MO	14.1.70/74	
Hattiesburg Aviation, Hattiesburg MS	27.7.74/81	
(Beech cargo door installed 8.76)		
Roy E. Ray Airport Inc: documentation not completed	21.5.81	
struck-off USCR	10.81	

N3719B noted St Louis-Downtown MO 1.6.76;

BA-49	E18S	N3721B	built	.55
			Helms Express Inc, Pittsburgh PA	63
			Quarnstrom Land Co, Detroit MI	19.9.63/66
			crashed destroyed on takeoff, Charlevoix MI	25.9.66
			crash date 15.5.73: not correct;	
	NTSB acc	ident report 25	.9.66 struck embankment on takeoff, destroyed, 2k;	
BA-50	E18S	JA5014	Yomiuri Shimbunsha Newspaper, Tokyo	5.55/60
			(delivered across Pacific by Fleetaway)	
			Maritime Safety Agency "The Yomiuri"	70
			retired, broken-up 21.12.73: struck-off Register	27.12.72
BA-51	E18S	N3769B	Union Lumber Co, Fort Bragg CA	63/69
			Victory Assembly of God, Beaumont TX	70
			Red Val Industries, Garland AR	72
		N777AF	Jack Counts, Dallas TX	22.2.78/85
			op: Horizon Cargo Transport Inc, Honolulu HI	79
			renamed: Kahila Airlines, Honolulu HI	.79
			damaged landing Lanai HI (repaired)	29.5.80
			op: Island Airlines Hawaii, Honolulu HI	81
			(retired, stripped Honolulu HI 81/83)	
			struck-off USCR	27.6.85
	N777AF n N777AF n	oted Honolulu	23.8.81 engineless "Horizon";	
BA-52	N777AF n N777AF n	oted Honolulu oted Honolulu	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX	11.3.55
BA-52	N777AF n N777AF n N777AF n	oted Honolulu oted Honolulu oted Honolulu	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick	12.3.55/56
BA-52	N777AF n N777AF n N777AF n E18S	oted Honolulu oted Honolulu oted Honolulu	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX	12.3.55/56 13.9.56/57
BA-52	N777AF n N777AF n N777AF n E18S	oted Honolulu oted Honolulu oted Honolulu	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN	12.3.55/56 13.9.56/57 23.1.57/62
BA-52	N777AF n N777AF n N777AF n E18S	oted Honolulu oted Honolulu oted Honolulu N3723B	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62
BA-52	N777AF n N777AF n N777AF n E18S	oted Honolulu oted Honolulu oted Honolulu N3723B	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN)	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N15C	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc,	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N15C	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX AI Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN AI Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Northern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N15C	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Sorthern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N15C	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Sorthern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78 7.11.78/79
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N15C	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Sorthern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan K &amp; K Aircraft Inc, Bridgewater VA</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N15C	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Sorthern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan K & K Aircraft Inc, Bridgewater VA retired, broken-up for parts	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78 7.11.78/79 .79/88
BA-52	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N15C	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Sorthern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan K &amp; K Aircraft Inc, Bridgewater VA</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78 7.11.78/79
BA-52 BA-53	N777AF n N777AF n N777AF n E18S -9700	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N15C	12.11.79; 23.8.81 engineless "Horizon"; 9.83 derelict; J. D. Reed Co, Houston TX Wyatt C. Hedrick J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Sorthern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan K & K Aircraft Inc, Bridgewater VA retired, broken-up for parts	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78 7.11.78/79 .79/88 4.4.88 7.6.55
	N777AF n N777AF n N777AF n E18S -9700 trigear	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N1FC N1FN	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Sorthern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan K &amp; K Aircraft Inc, Bridgewater VA retired, broken-up for parts struck-off USCR</li> <li>Roscoe Turner Aeronautical Corp Cape Hosiery Inc</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78 7.11.78/79 .79/88 4.4.88
	N777AF n N777AF n N777AF n E18S -9700 trigear	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N1FC N1FN	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Northern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan K &amp; K Aircraft Inc, Bridgewater VA retired, broken-up for parts struck-off USCR</li> <li>Roscoe Turner Aeronautical Corp Cape Hosiery Inc Wayne Knitting Mills</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78 7.11.78/79 .79/88 4.4.88 7.6.55 7.6.55 6.7.55
	N777AF n N777AF n N777AF n E18S -9700 trigear E18S	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N1FC N1FN	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Northern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan K &amp; K Aircraft Inc, Bridgewater VA retired, broken-up for parts struck-off USCR</li> <li>Roscoe Turner Aeronautical Corp Cape Hosiery Inc Wayne Knitting Mills</li> <li>Wayne Knitting Mills</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78 7.11.78/79 .79/88 4.4.88 7.6.55 7.6.55
	N777AF n N777AF n N777AF n E18S -9700 trigear	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N1FC N1FN N1FN	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Northern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan K &amp; K Aircraft Inc, Bridgewater VA retired, broken-up for parts struck-off USCR</li> <li>Roscoe Turner Aeronautical Corp Cape Hosiery Inc Wayne Knitting Mills Wayne Knitting Mills</li> <li>Wayne Knitting Mills</li> <li>(Beech JATO jet assisted takeoff kit fitted 12.60)</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78 7.11.78/79 .79/88 4.4.88 7.6.55 7.6.55 6.7.55 11.4.56/62
	N777AF n N777AF n N777AF n E18S -9700 trigear E18S	oted Honolulu oted Honolulu oted Honolulu N3723B N137AJ N1FC N1FN	<ul> <li>12.11.79;</li> <li>23.8.81 engineless "Horizon";</li> <li>9.83 derelict;</li> <li>J. D. Reed Co, Houston TX Wyatt C. Hedrick</li> <li>J. D. Reed Co, Houston TX Al Johnson Construction Co, Minneapolis MN damaged when ran off icy runway, Evansville IN Al Johnson Construction Co, Minneapolis MN (Volpar Mk.IV trigear installed 8.62 by Gopher Aviation, Rochester Airport MN) Twin Cities Aviation, Minneapolis MN Pemton Inc, Minneapolis MN Fingerhut Corp, Minneapolis MN Fingerhut Corp, Minneapolis MN Northern Airmotive Inc Allen W. Mobey/ 18 Inc/ Airmergency Inc/ MPC Inc, St Paul MN Exec-u-air Inc Jack D. Sloan K &amp; K Aircraft Inc, Bridgewater VA retired, broken-up for parts struck-off USCR</li> <li>Roscoe Turner Aeronautical Corp Cape Hosiery Inc Wayne Knitting Mills</li> <li>Wayne Knitting Mills</li> </ul>	12.3.55/56 13.9.56/57 23.1.57/62 15.3.60 18.6.62/69 10.69/70 6.4.70/71 25.6.71/72 2.72/73 7.2.73 2.3.73/78 30.6.78 7.11.78/79 .79/88 4.4.88 7.6.55 7.6.55 6.7.55

		W. G. Thomas	21.9.67/68
		Walter Miller & Dan Auclair Associates, Waco TX	30.8.68/70
			50.0.00/70
		(cabin furnishings removed to carry mail 10.68,	
		convertable pax/cargo interior installed 2.70)	
		S I Industries Inc	11.70/71
		op: Miller Aircraft Inc, Waco TX	71
		Freedom Airlines, Buffalo NY	26.7.71/73
		Gilley Airways Corp, Fulton NY	11.4.73/77
		landed gear-up, Syracuse-Hancock NY	11.11.74
		Aero American Aviation	26.10.77
		Robert Z. Blue, Mount Prospect IL	12.77/78
		Trujillo-Ramirez Investment Co	10.78/79
		Henry Oliver III, Santa Fe NM	7.5.79/83
		(FAA report 11.82: aircraft destroyed or scrapped)	
		struck-off USCR	26.3.83
	N924W noted Syn	chester NY 3.11.73 Gilley Airways; acuse NY 27.8.74 Gilley Airways; eport 11.11.74: Gilley AW, failed to extend gear 6.29pm, pilot un	hurt;
		DW Desses Turner Astensuties Corp	0.2.55
BA-54	E18S N70		9.3.55
		Inland Container Corp	9.3.55/61
		Beverly Agency Inc, Chicago IL: USCR	63
		Modern Welding Co, Owensboro KY	9.2.62/73
		SMB Stage Line Inc, Des Moines IA	27.8.73/81
		Jason C. Springer, Dallas TX	21.7.81
		Federated Air Freight Corp, Medford OR	29.9.81/82
		crashed on takeoff from clearing, landing gear	
		struck concrete cattle trough, San Miguel Ranch,	
			8.3.82
		Charlotte TX (aircraft stolen, abandoned by crew, drugs on board)	0.3.02
		(aircraft stolen, abandoned by crew, drugs on board)	0.3.02
	N700W noted Ott	(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)	0.0.02
	reported still in se	(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX:	0.0.02
BA-55	reported still in sei N700W hulk store	(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97) Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; rvice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;	
3A-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>umwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>Gopher Aviation, Rochester Airport MN</li> </ul>	10.3.55
BA-55	reported still in sei N700W hulk store	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>umwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>Gopher Aviation, Rochester Airport MN Alexander Construction Co</li> </ul>	10.3.55 10.3.55/58
3A-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>unwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall</li> </ul>	10.3.55 10.3.55/58 23.7.58/59
3A-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62
BA-55	reported still in sea N700W hulk store E18S N46	(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97) Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09; 41A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>41A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68)</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>41A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>41A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA landed gear locked-up, Albany GA</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>41A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Ianded gear locked-up, Albany GA Central Flying Service, Little Rock AR</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70
3A-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Ianded gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70)</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>amwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>41A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Ianded gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69
3A-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>Alaxander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Ianded gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79)</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79
3A-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>IAA Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Ianded gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>IAA Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Ianded gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell Paul Milam</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82 29.1.82/83
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>IAA Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Ianded gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82
BA-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>IAA Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Ianded gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell Paul Milam</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82 29.1.82/83
3A-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>Imwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>IAA Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Ianded gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell Paul Milam Mid-South Operations Inc, Fayetteville AR op: Richards Aviation, Memphis TN</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82 29.1.82/83 4.5.83/88 84
3A-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>amwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>41A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Landed gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell Paul Milam Mid-South Operations Inc, Fayetteville AR op: Richards Aviation, Memphis TN M. Corley Tedder, Texarkana TX</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82 29.1.82/83 4.5.83/88 84 2.8.88/99
3A-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>umwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>41A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA landed gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell Paul Milam Mid-South Operations Inc, Fayetteville AR op: Richards Aviation, Memphis TN M. Corley Tedder, Texarkana TX op: May Air Xpress, Texarkana TX</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82 29.1.82/83 4.5.83/88 84 2.8.88/99 97/98
BA-55	reported still in sel N700W hulk store E18S N46 -9700	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>umwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>411A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA Ianded gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell Paul Milam Mid-South Operations Inc, Fayetteville AR op: Richards Aviation, Memphis TN M. Corley Tedder, Texarkana TX op: May Air Xpress, Texarkana TX Air Calypso, San Juan, Puerto Rico</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82 29.1.82/83 4.5.83/88 84 2.8.88/99 97/98 22.9.99/00
3A-55	reported still in sea N700W hulk store E18S N46	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>umwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81;</li> <li>d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>441A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall</li> <li>King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA landed gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell Paul Milam Mid-South Operations Inc, Fayetteville AR op: Richards Aviation, Memphis TN M. Corley Tedder, Texarkana TX op: May Air Xpress, Texarkana TX Air Calypso, San Juan, Puerto Rico</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82 29.1.82/83 4.5.83/88 84 2.8.88/99 97/98 22.9.99/00 31.7.00/06
BA-55	reported still in sel N700W hulk store E18S N46 -9700	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li><i>umwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel;</i> vice with SMB Stage Line 81; d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>41A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA landed gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell Paul Milam Mid-South Operations Inc, Fayetteville AR op: Richards Aviation, Memphis TN M. Corley Tedder, Texarkana TX Air Calypso, San Juan, Puerto Rico</li> <li>9T MBD Corp, San Juan, Puerto Rico</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82 29.1.82/83 4.5.83/88 84 2.8.88/99 97/98 22.9.99/00 31.7.00/06 13.4.05
BA-55	reported still in sel N700W hulk store E18S N46 -9700	<ul> <li>(aircraft stolen, abandoned by crew, drugs on board) Tradewinds Aircraft Salvage Inc, San Antonio TX: (hulk noted stored in their yard with DC-3s 10.97)</li> <li>umwa IA 29.8.79 "SMB Stage Lines" titles, tailwheel; vice with SMB Stage Line 81;</li> <li>d in Tradewinds Aircraft Salvage yard 8.09;</li> <li>441A Gopher Aviation, Rochester Airport MN Alexander Construction Co Arthur W. Mall</li> <li>King-Stevenson Oil Co Alsam Inc, Youngstown OH Mark Aero Inc, St Louis MO Carmen Di Orio, Philadelphia PA James B. Kelly/ Speedbird Aircraft Corp (mods installed for aerial survey 1.68) Albany Air Service, Albany GA landed gear locked-up, Albany GA Central Flying Service, Little Rock AR (converted to all-cargo configuration 4.70) Catalina Air Freight (Aerospace Products cargo door installed 9.79) Newton B. Collinson &amp; Richard T. Farrell Paul Milam Mid-South Operations Inc, Fayetteville AR op: Richards Aviation, Memphis TN M. Corley Tedder, Texarkana TX op: May Air Xpress, Texarkana TX Air Calypso, San Juan, Puerto Rico</li> </ul>	10.3.55 10.3.55/58 23.7.58/59 21.7.59/62 23.3.62/63 12.63/64 28.5.64/66 27.4.66/68 12.68/70 25.8.69 7.4.70/79 20.3.79 12.79/82 29.1.82/83 4.5.83/88 84 2.8.88/99 97/98 22.9.99/00 31.7.00/06

accident report 25.8.69: Albany Air Service, gear jammed by mechanical failure, 4.30am;

N4641A noted Dallas-FTW 12.93, at cargo terminal; N4641A noted Dallas-FTW 26.4.95, 9.95; N4641A noted Texarkana AR 8.97 May Air Xpress: plate BA-55 built 2.55; noted Texarkana AR 6.8.98 rep operated by May Air Xpress; N749T noted San Juan PR 15.1.03 all metallic no titles, tailwheel, flying; N749T noted San Juan PR 26.2.06 all metallic freighter, tailwheel, in service; N749T noted St Thomas 1.2.08 all silver, no windows, appears in service;

BA-56	E18S	N3737B	Flightcraft Inc	17.3.55
	-9700		Weyerhaeuser Timber Co	17.3.55/57
			(right wing replaced 9.57 due accident damage)	
			Freeway Equipment Co	28.9.57/62
			Union Oil Co of California, Los Angeles CA	1.10.62/63
		N1776U	Union Oil Co of California, Los Angeles CA	8.1.63/74
	trigear		(Volpar Mk.IV trigear installed 2.63)	
	U U	N54BT	Brown Tool & Supply Co	6.4.74/75
			Piper Corporate Aircraft Southeast	11.75/76
			James Noel Flying Service	11.76/77
			Alroco Services Inc	11.76/78
			Edward W. Strotman/ Strotman Aviation	12.5.78/81
			Ronald W. Smith/ Smithair, Sharpsburg GA later	
			Fort Myers FL	3.12.81/95
			Jim Hankins Air Service, Jackson MS	18.8.95/97
			Blu Sky Enterprises, Overland Park KS	25.2.97
			op: Polaris Aviation	97
			crashed destroyed, Elkins WV	6.3.97

N1776U noted Oakland CA 1.64 trigear, no titles; N54BT noted Pontiac MI 17.9.78

BA-57	E18S	N3728B	Anderson Air Activities	15.3.55
	-9700		Inland Steel Co, Chicago IL	15.3.55/66
	Trigear		(Volpar Mk.IV tricycle landing gear installed	
			by Gopher Aviation, Rochester MN 12.62)	
			Hartzog-Schneck Aviation, Rockford IL	20.1.66
			D. C. Aircraft Inc, Detroit MI	23.9.66/68
			Hartzog-Schneck Aviation, Rockford IL	1.3.68/70
			Burnside-Ott Aviation Training Centre	16.6.70
			Executive Airway Leasing Inc	5.10.70/71
			Crow Inc, Millbury OH	3.71/72
		N57AE	Air East Inc	25.2.72/74
			Hollywood Flying Service	10.6.74/75
			International Transfer Corp/ Pro-Air Service,	
			Opa Locka FL	10.75/77
			op: Shawnee Airlines, Fort Lauderdale FL	77
			William E. Hauck, Fort Lauderdale FL	18.2.77/80
			op: Air International Airlines, Miami FL	77
			William E. Hauck/ Hawk Aviation Corp	6.2.80/83
			•	11.83/85
			International Aircraft Corp, Princeton FL	11.03/03
			(cabin interior converted for cargo 9.84)	05
			op: Air South, Miami FL	85
			crashed destroyed landing, West Palm Beach FL	6.5.85

N3728B photo 63 trigear, Inland Steel Co titles; N57AE visited Miami FL 27.4.85 Air South, no titles; accident report 6.5.85: crashed WPB during landing on passenger flight op Air South Inc;

BA-58	E18S	N3731B	reg	.55
		N4F (2	Latrobe Construction Co, Earlington PA	30.3.55/57
			written-off: struck-off USCR	18.6.57
BA-59	E18S	N3773B	J. R. Gray Co, Dallas TX	23.3.55
	-9700		Aztec Oil & Gas Co	1.4.55
		(N73R)	ntu: Aztec Oil & Gas Co	10.56
		N3773B	Aztec Oil & Gas Co, Dallas TX	10.56/69
			AiResearch Aviation Co	24.3.69

	The Aggie Club, College Station TX	9.69/72
	Belvon Leasing Inc	28.2.73/76
	Mike Spivey/ Limestone Aviation	10.9.76/77
	Westark Air Service	19.8.77/78
(N16FB)	ntu: Westark Air Service	1.78
N3773B	Stone Air Freight, Fort Smith AR	1.3.78/80
	Stewart Aviation Service	10.80/83
	Mayan Marble & Tile	18.2.83/85
	Parker Harrington, Sherwood AR	10.6.85/86
	Jose Martinez-Alegria, Cooper City FL	6.1.86/87
	Samuel Smith, Miami FL	18.3.87/89
	Julio A. Guell & Enrique A. Mejia, Miami FL	8.89
	Mario A. Enriquez, Miami FL	22.11.89/13
	struck-off USCR	13.8.13

N3773B noted Opa Locka FL 22.3.87, 4.11.87;

BA-60 E	E18S	N3734B	built	.55
			Lane Construction Corp, Meriden CT	63/72
			Alaska Air Service, Anchorage AK crashed into river on takeoff from beach,	9.12.74/75
			Montague Island AK	27.4.75

N3734B Alaska Air Service, took off 9.30pm, aborted, gear collapsed, 3 unhurt;

BA-61	E18S	N3730B	built	.55
			Sunray DX Oil Co, Tulsa OK	63/66
			Pioneer Airlines, Washington DC	69/70
			Combs Airways, Billings-Logan MT	72
			Courtesy Air Service, Glen Falls NY	76
			ran off runway landing, struck trees, Manahawkin NJ (Courtesy advise FAA 11.76: sold for parts)	29.1.76
			United Counties Trust Corp, Elizabeth NJ	22.4.76
			struck-off USCR	1.12.76

BA-62	E18S		(to FA Colombiana as FAC521)	
BA-63	E18S	HK-1815X HK-1850X	(to FA Colombiana as FAC522) reg Aerolineas Especiales de Colombia Ltda, Forencia crashed Isla de Providencia	.76/78 13.9.78

HK-1850 noted Bogota 3.10.76 id. BA-63; HK-1850 noted Opa Locka FL 12.3.77;

BA-64	E18S	N3751B	John D. Askew, Fayetteville AR	63/64
		N503J	Lawrence R. Lippert, Alma MI	69
			Jim Hankins Air Service, Jackson MS	70/72
			Van Dusen Acceptance Corp, Minneapolis MN	26.7.72/73
			Isd: Buckeye Air Service, Elyria OH	72/73
			wrecked in forced landing wheels-up, off-airport, Ger	neva IL 13.12.73

not on published USCR 1966 as either reg;

N503J accident report 13.12.73: Buckeye Air Service, flight Omaha NB-Des Moines-Chicago, intended wheels-up landing in snow storm, right engine failed, left reduced power, pilot unhurt;

BA-65	E18S	N3753B	J. R. Gray Co, Dallas TX	8.4.55
			Perkins-Prothro Co	10.55/61
			damaged on takeoff, Boulder CO	14.7.60
			J. W. Duff Aircraft Co, Denver CO	13.1.61/63
			Volitan Aviation, Van Nuys CA	17.6.63
		N340V (1	Volpar Inc, Van Nuys CA	4.12.63/67
	Volpar	, , , , , , , , , , , , , , , , , , ,	(prototype Volpar Super Turbo 18:	

Super Turbo 18		experimental CofA 10.64: R&D for type certification, AiResearch TPE-331 developmental turbines; trigear, windows replacing portholes 11.64; G18S cab & windows, ff Van Nuys 12.64 as	
		Volpar Super Turbo 18; installation of TPE-331-25 production turbines completed 2.66, FAA STC issued 17.2.66)	2.67
Volpar Turboliner		Ransome Air, Philadelphia PA: leased (further conversion to prototype <i>Volpar Turboliner</i> , ff Van Nuys 12.4.67: TPE-331-1-101Bs & fuselage lengthened by 81.5 inches)	3.67
		Central Trust Leasing, Cleveland OH (further Turboliner mods. completed 8.69, conv. #014) Ransome Air/ Allegheny Commuter,	67
		Philadelphia PA <i>Flagship Trenton</i> propeller blade separated in flight, landed safely,	2.9.69/74
Turboliner II		Philadelphia PA (converted 12.71 to <i>Volpar Turboliner II</i> )	20.10.69
		Fairbanks Flight Service, Fairbanks AK (forward cargo door modified to hinge upward,	5.2.74/76
		pilot cockpit entrance door installed 4.74) damaged on takeoff, Fairbanks AK	23.2.75
		Polar Airways, Anchorage-Merrill Field AK	3.76
	N114PA	Polar Airways, Anchorage-Merrill Field AK Soonair Lines, Tulsa OK	24.3.76/78 19.4.78
	N16SL	Soonair Lines, Tulsa OK Soonair Lines, Tulsa OK	11.78/81
		Connie Kalitta Services, Willow Run MI	2.6.81/90
		American International Airways, Willow Run MI	10.90/92
		Kalitta Flying Service, Detroit-Willow Run MI Kitty Hawk Charters Inc, Morristown TN	1.1.92/99 6.5.99/01
		(sold at Kitty Hawk auction 10.01 for parts)	0.0.00.010
		sale reported: USCR	24.6.02/13
		struck-off USCR by FAA	18.4.13
Steve Darke Type Certific	states: N340 cate issued 1	ech 18 by Parmerter p.385-387 & 389; DV prototype: flying Spring 65 with TPE-331-25, FAA Supp 7.2.66; around this time engines replaced by TPE-331-47 placed again around 68 with TPE-331-101 at 605shp	lemental rated at the
giving cruise	speed 280m	nph;	
		ndo Valley CA 23.2.65 & 3.3.65;	
		A 8.66 as demonstrator Volpar Super Turbo 18, no titles; D.10.69: Ransome Airlines, prop blade separated from righ	t
engine, dam	aged engine	nacelle, landed safely;	
		a PA 13.4.70 Turboliner "Ransome Airlines" titles; Philadelphia PA 14.9.70 "Allegheny Commuter" titles;	
		n-DCA 30.9.70 Ransome AL/Allegheny Commuter;	
N340V phot	o Wichta KS .	.70 Turboliner, "Allegheny Commuter" titles;	
		CA 28.12.71 Allegheny Commuter, Turboliner;	
		eing Field WA 4.74 Turboliner, no titles; 3.2.75: Volpar 18, Fairbanks Flight Service, took off with fro	ost on
		t, flight to Bettles AK;	
		ro 1.9.79 "Soonair" titles, Turboliner, freighter;	
N16SL note	d Youngstow d Indianapolis	n IN 3.5.83 Volpar Turboliner, Connie Kalitta Services; s IN 7.9.84 Turboliner freighter Connie Kalitta titles;	
		6.2.85 turbines, Kalitta, op. for Zantop;	
		MI 3.8.89 Connie Kalitta Air Services, Turboliner;	
		91 Connie Kalitta, turbine trigear, plates BA-65, Volpar #0 96 Kalitta, as Turboliner; Willow Run 5.98 Turboliner, Kalitt	
		TN 5.05: had been sold by Kitty Hawk but not picked up;	;
		TN 3.8.05 open storage engines removed, "Kitty Hawk	
Charter" on	rear fuselage	in small letters;	
E18S	(N3759B)	ntu: Beech Aircraft Corp	4.55
-9700	N28S	•	19.4.55

BA-66	E18S	(N3759B)	ntu: Beech Aircraft Corp	4.55
	-9700	N28S	J. R. Gray Co, Dallas TX	19.4.55
			Sun Oil Co/ Sun Pipe Line Co, Philadelphia PA	3.5.55/67
		N284S	Houston Beechcraft Inc, Houston TX	23.2.67
			Armair Inc, Coral Gables FL	10.67/69

	Air Saint Pierre, St. Pierre et Miquelon	29.4.70
F-OCPG	Air Saint Pierre, St. Pierre et Miquelon	19.1.71/79
	CofA expired 7.74, struck-off Register	29.10.79
C-GLQF	reg	
N9152F	Herbert A. Hartley, Brownsville FL	13.7.81/82
	Roy D. Hartley	20.4.82/86
	(FAA report 2.86: aircraft destroyed or scrapped)	
	struck-off USCR	4.86

N284S noted Ft Lauderdale FL 6.10.68; F-OCPG noted Montreal-Dorval 30.6.70;

BA-67	E18S	N3760B N86E N49891 N7891 N277U CF-QCD	Atlantic Aviation Corp Shea Chemical Corp Shea Chemical Corp Hooker Chemical Corp Ontario Airways, Porterville NY Valley Equipment Corp, Paducah KY Green River Rural Electric Cooperative Corp, Owensboro KY Univair Corp, Milwaukee WI Fontana Aviation Aviation Sales International Canada Ltd Labelle Touristair, Laval QUE dam. emergency belly landing on frozen lake surface, Matagami QUE (9 on board unhurt) Parachute School of Toronto Ltd, Toronto ONT sold to USA, struck-off Canadian Register	21.4.55 7.6.55/57 30.4.57/58 29.5.58/60 22.1.60/63 10.63/65 12.65/68 23.5.68/71 2.10.71/72 4.72 73/74 18.2.73 83/85 13.1.85
		N16CL	Charles E. Leonard, Covington LA Samuel N. Nipper, Fayetteville GA Midland College, Midland TX Mark Lee, Floydada TX Ray Lee, Plainview TX Texas Air Museum, Slaton TX	14.1.85/90 28.9.90/91 6.12.91/95 7.5.98/04 23.1.04/15 25.3.15/20
BA-68	E18S	N3741B BA-68	Beech Aircraft Corp, Wichita KS sold to France, struck-off USCR French Air Force/Armee de l'Air as BA-68 "F-RAEL" (delivered to Paris 5.55 by Fleetaway) Chateaudun AB: retired, stored	55 31.5.55 5.55/73 72/73
	BA-68 visite BA-68 & BA BA-68 visite BA-68 visite BA-68 note BA-68 note BA-68 note BA-68 note BA-68 note BA-68 note BA-68 note	ed Blackbushe A-70 both Frei ed London-He ed RAF Northe 70, 83 listed v d Le Bourget d Hamburg 6. d stored Chat e de l'Air, Le SF stored Du		58
BA-69	E18S	BA-69	French Air Force/ Armee de l'Air as BA-69 "F-RAEM" (delivered by Fleetaway to Paris 5.55)	5.55/75
	BA-69 visite BA-69 Fren Ba-69 Fren BA-69 Fren BA-69 Fren BA-68, 69,7	ed Blackbushe ch AF visited ch AF visited ch AF visited ch AF noted B 70, 83 listed w	Chateaudun AB: retired, stored ewild NY 9.5.55 on del to France; e 3.9.56 in visitors park for 1956 Farnborough Air Show; RAF Northolt 22.8.61; RAF Northolt & RAF Odiham both 5.9.62 tailwheel; RAF Northolt 22.5.66; Brussels 26.3.68; ith 60th Escadre, Escadron 2/60 based Villacoublay AB ir eaudun AB 7.72, 3.6.73, 6.75;	72/75 n 68;

75 Air Show; illacoublay AB in 68; 6.5.55 22.8.55/68 hway, Tulsa OK 22.3.67 ee OK 22.5.68/77					
6.5.55 22.8.55/68 1way, Tulsa OK 22.3.67					
6.5.55 22.8.55/68 1way, Tulsa OK 22.3.67					
6.5.55 22.8.55/68 nway, Tulsa OK 22.3.67					
6.5.55 22.8.55/68 nway, Tulsa OK 22.3.67					
22.8.55/68 way, Tulsa OK 22.3.67					
22.8.55/68 way, Tulsa OK 22.3.67					
22.8.55/68 way, Tulsa OK 22.3.67					
nway, Tulsa OK 22.3.67					
ee OK 2.8.77/79 7.8.79					
7.0.70					
7.9.79 amaica 83					
15.6.55/61					
21.9.61					
.61/67 11.67					
11.07					
6.55					
40.7.50					
13.7.56 7.56					
Monica CA 7.12.56/62					
Monica CA 7.12.56/62 neva, Switzerland 58/62					
27.7.62 .62					
.02 64					
gister 1.71					
N34L photo Santa Monica CA 58 no titles, tailwheel;					
N34L visited Croydon Aerodrome, London 8.9.59 Lear Inc; N34L noted at Blackbushe 11.9.59 "LIFE";					
N34L visited Shoreham UK several times during 1960, "L.I.F.E." titles (for Lear					
Integrated Flight Equipment) with Bill Lear on board; N34L noted Gatwick 4.3.60, 1.2.61,					
N34L visited Gatwick 4.9.61 named "Chessy", Farnborough visitor;					
N34L noted Manchester 29.5.61 Life Magazine; N34L displayed at Paris Air Show, Le Bourget 3.6.61 with E18S F-BERT;					
HB-GAV visited Gatwick 16.1.63; Milan, Italy 24.7.63;					
1 7 55					
1.7.55					
of the					
of the Beech)					

		N279SC	damaged struck metal stand taxying, Newark NJ W. C. Grant CoPunta Gorda FL Business Aircraft Leasing Corp, Gainsville FL Isd: Satterfield Construction Co Satterfield Construction Co, Greenwood SC Frank Cannavo/ Aero Taxi, Lester PA Frank Cannavo/Aero Taxi-Rockford IL forced landing gear-up in soy bean field, due fuel exhaustion, Rockford IL (Hamilton cockpit door installed 10.78) Sally B. Stewart, Chandler AZ Triton Holding Corp, Wilmington DE Scott H. Gloodt, Orland Park IL	30.9.60 28.9.61/63 3.10.63/67 3.10.63/67 10.7.68/69 29.5.70/72 11.73/00 19.7.70 15.5.01/05 20.12.05/06 22.8.06/20
	N279SC n N279SC n N279SC n N279SC n N279SC n N279SC n N279SC a N279SC a	noted Rockford noted Rockford noted Rockford noted Rockford noted Rockford noted Rockford nt Beech flyin T nt Beech flyin T	19.7.70: Aero Taxi: flight Philadelphia to Rockford, mino IL 23.7.71; IL 7.91 plate BA-74; IL 7.97 plate BA-74 built 5.55 i/s with Aero Taxi; IL 3.8.98 Aero Taxi; 26.7.99 based Rockford with Aero Taxi Rockford IL, flyi IL 30.7.00 Aero Taxi; ullahoma TN 16.10.02; ullahoma TN 16.10.03; noted at Janesville WI 25.7.08; are Co: see Beech 18 by Parmerter p.290;	
BA-75	E18S	N3771B	Tulsair Distributors Inc, Tulsa OK Sunray Mid-Continent Oil Co, Tulsa OK Sunray DX Oil Co/ Sun Oil Co, Tulsa OK Robert R. Haack/ Spirit Lake Airways, Okoboji IA (9 pax high-density seating installed 25.2.70) SMB Stage Line, Des Moines IA Central Northern Ltd (cargo door installed 4.75) Cal-North Construction, Klondike Line AK sale documentation not completed sale reported, Anchorage AK: USCR forced landing after takeoff, Anchorage AK	20.5.55 20.5.55/62 8.5.62/69 28.2.69/70 16.5.70/75 27.3.75 10.75/76 2.76 8.12.76
			8.12.76: Klondike Line, forced landing gear down off airr tto Bethel AK, pilot unhurt;	port
BA-76	E18S trigear	N3774B	Tulsair Distributors Inc, Tulsa OK Sunray Mid-Continent Oil Co Big Chief Drilling Co Jack Richards Aircraft Sales, Oklahoma City OK Isd: Arkansas Valley Industries Inc Aircraftsmen Inc, Oklahoma City OK (Volpar Mk.IV trigear installed 2.65) Tulakes Aviation, Bethany OK Ceco Corp	31.5.55 31.5.55/60 12.60/61 12.61/64 1.3.62 20.5.64/65 26.8.65/66 3.1.67/68
		N471CM	Corley Manufacturing Co, Chattanooga TN Corley Manufacturing Co, Chattanooga TN (noted painted as N471CM by 8.71) W. F. Huston/ Huston Aviation John Decker/ Occidental Land Research, West Covina CA	28.2.68/73 4.4.73 3.7.73/75 4.11.75/83
			gear inadvertantly retracted on takeoff run,	

	West Covina CA
	gear inadvertantly retracted on takeoff run,
	Laverne-Brackett Field CA
	Antonio G. Ginard, Rockaway NJ
	WTK Aviation, Miami FL
	Michele Martin-Remesz, Boca Raton FL
1CM noted Et Lau	derdale FL 24.8.71:

16.12.79 24.9.83/00 3.4.02 20.1.05/20

N4710

N471CM noted Long Beach CA 26.7.81 trigear; N471CM noted Ft Lauderdale FL 9.90 & 5.92;

N471CM noted Ft Lauderdale 2.1.98 stored, no reg;

BA-77     E18S     HK-1111G     Ministerio de Obras Publicas Colombia (built 5.55, US Export Certificate 27.5.55) Institute Geographique (noted Bogota Airport 2.75 with damaged rear fuselage)     72       Atternative version Hamilton     (noted Bogota Airport 2.75 with damaged rear fuselage)     72       Atternative version Hamilton     (rebuilt at Tucson AZ as Hamilton HA-1 Turboliner completed 4.80)     80       HA-1     (rebuilt at Tucson AZ as Hamilton Aircraft Co, Tucson AZ rep. Di US Border Patrol, based Florida Rep. Di: US Border Patrol, Based State Rep. Direct Ducson AZ 4.6, 80       HK-1111 noted Tucson AZ 4.6, 108 ore pa s BA-77 Herolineas Especiales; HK-1111 noted Tucson 9.11.81 trigear 'AE', operational; Note: E18S BA-77 manufacturers plate offered for sale on EBay 7.12.04 by a Waco TX resident; Robert Parmetre advises (1/07); BA-57 w/o in Bogota, rear fuse at Bogota 2.75. No link to HK-1111 HK-1111 (2 HA-1 Turboliner mose gear was 3596       BA-78     E18S     N3768B     L. A. Greiling, Tyler TX crashed 5.56, struck-off USCR     8.7.55/56       BA-79     E18S     N3768B     L. A. Greiling, Tyler TX crashed 5.56, struck-off USCR     7.5.5/56       BA-79     E18S     N3768B     L. A. Grelling, Colorado Springs CO     14.10.76   <		N471CM no N471CM no N471CM no N471CM no	ited Opa Lock ited Opa Lock ited Opa Lock ited Opa Lock	a FL 6.9.98 trigear; a 22.10.98 all white, hand-painted reg; Opa Locka 8.12.98 a 5.2.99 allover white, trigear; a FL 4.4.01 trigear; a FL 4.11.04, o FL 10.8.05 trigear, plate BA-76 built 5.55 all metallic;	,	
Alternative version       Hamilton Aircraft Co, Tucson AZ       80         Hamilton       (rebuilt Tucson AZ as Hamilton HA-1 Turboliner completed 4.80)       80         Turboliner       HK-1111 (2 Aerolineas Especiales de Colombia, Florencia       80         HAMILTON       (rebuilta Tucson AZ as Hamilton Aircraft Co, Tucson AZ       80         HK-1111 (2 Aerolineas Especiales de Colombia, Florencia       80         rep. or: US Border Patrol, based Florida       80/81         rep. torbum up for parts Tucson AZ       81         rep. torbum up for parts Tucson AZ       81         rep. torbum up for parts Tucson AZ       81         HK-1111 noted Tucson AZ 4.6 80 rep as BA-77 Hamilton Aircraft Co, Tucson AZ       81         HK-1111 noted Tucson AZ 4.6 80 rep as BA-77 Hamilton Aircraft Co, Tucson AZ       81         HK-1111 noted Tucson AZ 4.8 00 rep as BA-77 Hamilton HA-1 Aerolineas Especiales;       HK-1111 noted Tucson 9.11.81 rigear 'AE', operational;         Note: E18S BA-77 manufacturers plate offered for sale on EBay 7.12.04 by a Waco TX resident;       Robert Parmetre advises (107):         BA-78       E18S       N3768B       L.A. Greiling, Tyler TX       8.7.55/56         BA-79       E18S       N3768B       L.A. Greiling, Tyler TX       8.7.55/56         BA-79       E18S       N3768B       L.A. Greling, Colorado Springs CO       14.1	BA-77	E18S	HK-1111G		5.55	
Hamilton     (rebuilt at Tucson AZ     80       HA-1     completed 4.80)     80       Turboliner     HK-1111 (2 Aerolineas Especiales de Colombia, Florencia     .80       Turboliner     HK-1111 (2 Aerolineas Especiales de Colombia, Florencia     .80       rep. proUS Border Patrol, based Florida     80/81       rep. broken up for parts Tucson AZ     81       HK-1111 noted Tucson AZ 28.60 rep as BA-77 trigger turbine, AE Colombia scheme but no titles;       HK-1111 noted Tucson AZ 28.10.80 rep as BA-77 trigger turbine, AE Colombia scheme but no titles;       HK-1111 noted Tucson AZ 28.10.80 rep as BA-77 trigger turbine, AE Colombia scheme but no titles;       HK-1111 noted Tucson 5.11.81 rep as BA-77 Aerolineas Especiales;       HK-1111 noted Tucson 9.11.81 trigger 'AE'; operational;       Note: E18S BA-77 manufacturers plate offered for sale on EBay 7.12.04 by a Waco TX resident;       Robert Parmerter advises (1/07);       BA-78     E18S       BA-78     E18S       N3768B     L. A. Grelling, Tyler TX       crashed 5.56, struck-off USCR     30.756       BA-79     E18S       N3768B     L. A. Grelling, Colorado Springs CO       14.6.73     gear collapsed landing, Colorado Springs CO       14.6.73     gear collapsed landing, Colorado Springs CO       14.6.73     gear-collapsed landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt; <t< td=""><td></td><td></td><td></td><td>Institute Geographique</td><td>72</td></t<>				Institute Geographique	72	
Hamilton HA-1       (rebuilt at Tucson AZ as Hamilton HA-1 Turboliner completed 4.80)       80         Turboliner       HK-1111 (2 Aerolineas Especiales de Colombia, Florencia rep. op. US Border Patrol, based Florida Rep. tertumed to Hamilton Aircraft Co, Tucson AZ       80         HK-1111 Roted Barranquilla, Colombia 30.9 72 Inst. Geo. HK-1111 noted Tucson AZ 4.6.80 rep as BA-77 Hamilton HA-1 Aerolineas Especiales freighter, converted from E18S in 4.80, HK-1111 noted Tucson AZ 28.10.80 rep as BA-77 Hamilton HA-1 Aerolineas Especiales; HK-1111 noted Tucson 5.11.81 rep as BA-77 Aerolineas Especiales; HK-1111 (Washind III taliwitheel was BA-157 HK-1111 (2 HA-11 Turboliner nose gear was 3596         BA-78       E18S       N3768B       L. A. Grelling, Tyler TX crashed 5.56, struck-off USCR       8.7.55/56 30.7.56         BA-79       E18S       N3772B       built       .55 00 on Inig Box Co, Milwaukee WI Duncan Aviation, Lincoln NE Pocono Aritines/ Allegheny Commuter       69/70 20/72         M136C       Downing Box Co, Milwaukee WI Bamilton Airation, Hamilton OH Pocono Aritines/ Allegheny Commuter       63/69 63/69         M136C       N136C       Juncan Aviation, struck N179L while taxying after lending, 1.45am: N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after lending, 1.45am: N136C accident report 14.6.73: Hamilton Aviation, str	Alternati	ive version				
HK-1111 noted Tucson AZ 4 6.80 rep as BA-77 trigear turbine, AE Colombia scheme but no titles;         HK-1111 noted Tucson AZ 28.10.80 rep as BA-77 Hamilton HA-1 Aerolineas Especiales         freighter, converted from E18S in 4.80;         HK-1111 noted Tucson 5.11.81 rep as BA-77 Aerolineas Especiales;         HK-1111 noted Tucson 9.11.81 trigear "AE", operational;         Note: E18S BA-77 manufacturers plate offered for sale on EBay 7.12.04 by a Waco TX resident;         Robert Parmeter advises (1/07):         BA-57 woin Bogota, rear fuse at Bogota 2.75. No link to HK-1111         HK-1111 (2 HA-1 Turboliner nose gear was 3996         BA-78       E18S         N3772B       built         N136C       Downing Box Co, Milwaukee WI         63/69       Pocono Airlines/ Allegheny Commuter         69/70       Duncan Aviation, Hamilton OH         Duncan Aviation, Lincoln NE       7072         Mamilton Aviation, Hamilton OH       73         minor damage in ground collision with Beech 18 N179L, Covington KY       46.673         gear collapsed landing, Oclorado Springs CO       14.10.76         Eagle Air Inc, St Louis MO       5.2.79         M36C accident report 14.6.73: Hamilton Aviation, struck N179L while taxiying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;         BA-80		HA-1	HK-1111 (2	<ul> <li>(rebuilt at Tucson AZ as Hamilton HA-1 Turboliner completed 4.80)</li> <li>Aerolineas Especiales de Colombia, Florencia rep. op: US Border Patrol, based Florida rep. returned to Hamilton Aircraft Co, Tucson AZ</li> </ul>	.80 80/81	
Robert Parmerter advises (1/07): BA-57 w/o in Bogota, rear fuse at Bogota 2.75. No link to HK-1111 HK-1111 (1 Westwind III tailwheel was BA-157 HK-1111 (2 HA-1 Turboliner nose gear was 3596BA-78E18SN3768BL. A. Grelling, Tyler TX crashed 5.56, struck-off USCR8.7.55/56 30.7.56BA-79E18SN3772B N136Cbuilt.55 Downing Box Co, Milwaukee WI Pocono Airlines/ Allegheny Commuter Duncan Aviation, Lincoln NE Hamilton Aviation, Lincoln NE To/72 Hamilton Aviation, Lincoln NE To/72 Hamilton Aviation, Lincoln NE Minor damage in ground collision with Beech 18 N179L, Covington KY gear collapsed landing, Colorado Springs CO Eagle Air Inc, St Louis MO destroyed in forced landing off-airport, Dayton OH 11.7.7914.6.73 gear collapsed landing, off-airport, Dayton OH 11.7.79N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;.55 63/72 63.76BA-80E18SN4277B built forced landing gear-up on rough terrain near Shafter TX, destroyed by fire.55 63.76N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;5.55		HK-1111 nc HK-1111 nc freighter, co HK-1111 nc	ited Tucson Á. ited Tucson A. inverted from I ited Tucson 5.	Z 4.6.80 rep as BA-77 trigear turbine, AE Colombia schem Z 28.10.80 rep as BA-77 Hamilton HA-1 Aerolineas Espec E18S in 4.80; 11.81 rep as BA-77 Aerolineas Especiales;		
BA-57 w/o in Bogota, rear fuse at Bogota 2.75. No link to HK-1111 HK-1111 (1 Westwind III tailwheel was BA-157 HK-1111 (2 HA-1 Turboliner nose gear was 3596         BA-78       E18S       N3768B       L. A. Grelling, Tyler TX crashed 5.56, struck-off USCR       8.7.55/56 30.7.56         BA-79       E18S       N3772B       built       .55         Downing Box Co, Milwaukee WI       63/69       Pocono Airlines/ Allegheny Commuter       69/70         Duncan Aviation, Lincoln NE       70/72       Hamilton Aviation, Hamilton OH       73         minor damage in ground collision with Beech 18 N179L, Covington KY       14.6.73       2.2.79         destroyed in forced landing off-airport, Dayton OH       11.7.79       11.7.9         N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.0.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;         BA-80       E18S       N4277B       built Champion Steel Corp, Orwell OH Swift Air Charter, Elyria OH forced landing gear-up on rough terrain near Shafter TX, destroyed by fire       .55         N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;       5.55		Note: E18S	BA-77 manuf	acturers plate offered for sale on EBay 7.12.04 by a Waco	TX resident;	
BA-79E18SN3772Bbuilt.55BA-79E18SN3772Bbuilt.55N136CDowning Box Co, Milwaukee WI63/69Pocono Airlines/ Allegheny Commuter69/70Duncan Aviation, Lincoln NE70/72Hamilton Aviation, Hamilton OH73minor damage in ground collision with Beech 18 N179L, Covington KY14.6.73gear collapsed landing, Colorado Springs CO14.10.76Eagle Air Inc, St Louis MO5.2.79destroyed in forced landing off-airport, Dayton OH11.7.79N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;.55BA-80E18SN4277Bbuilt Champion Steel Corp, Orwell OH Swift Air Charter, Elyria OH forced landing gear-up on rough terrain near Shafter TX, destroyed by fire.55N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;5.55		BA-57 w/o i HK-1111 (1	n Bogota, reai Westwind III t	r fuse at Bogota 2.75. No link to HK-1111 tailwheel was BA-157		
N136CDowning Box Co, Milwaukee WI63/69Pocono Airlines/ Allegheny Commuter69/70Duncan Aviation, Lincoln NE70/72Hamilton Aviation, Lincoln NE70/72Hamilton Aviation, Hamilton OH73minor damage in ground collision with Beech 18 N179L, Covington KY14.6.73gear collapsed landing, Colorado Springs CO14.10.76Eagle Air Inc, St Louis MO5.2.79destroyed in forced landing off-airport, Dayton OH11.7.79N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;.55BA-80E18SN4277Bbuilt.55BA-80E18SN4277Bbuilt.55Avit Champion Steel Corp, Orwell OH forced landing gear-up on rough terrain near Shafter TX, destroyed by fire6.3.76N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;5.55BA-81E18SN3781Bbuilt5.55	BA-78	E18S	N3768B			
Pocono Airlines/ Allegheny Commuter69/70Duncan Aviation, Lincoln NE70/72Hamilton Aviation, Lincoln NE73minor damage in ground collision with Beech 18 N179L, Covington KY14.6.73gear collapsed landing, Colorado Springs CO14.10.76Eagle Air Inc, St Louis MO5.2.79destroyed in forced landing off-airport, Dayton OH11.7.79N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;BA-80E18SN4277Bbuilt Champion Steel Corp, Orwell OH Swift Air Charter, Elyria OH forced landing gear-up on rough terrain near Shafter TX, destroyed by fire.55N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;5.55	BA-79	E18S	N3772B	built	.55	
Duncan Aviation, Lincoln NE70/72Hamilton Aviation, Hamilton OH73minor damage in ground collision with Beech 18 N179L, Covington KY14.6.73gear collapsed landing, Colorado Springs CO14.10.76Eagle Air Inc, St Louis MO5.2.79destroyed in forced landing off-airport, Dayton OH11.7.79N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;.55BA-80E18SN4277Bbuilt Champion Steel Corp, Orwell OH forced landing gear-up on rough terrain near Shafter TX, destroyed by fire.55N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;5.55				Downing Box Co, Milwaukee WI	63/69	
Hamilton Aviation, Hamilton OH73minor damage in ground collision with Beech 18 N179L, Covington KY14.6.73 gear collapsed landing, Colorado Springs COgear collapsed landing, Colorado Springs CO14.10.76 Eagle Air Inc, St Louis MOEagle Air Inc, St Louis MO5.2.79 destroyed in forced landing off-airport, Dayton OHN136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;BA-80E18SN4277BBA-80E18SN4277Bbuilt.55 Champion Steel Corp, Orwell OH Swift Air Charter, Elyria OH forced landing gear-up on rough terrain near Shafter TX, destroyed by fire6.3.76N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;5.55						
minor damage in ground collision with Beech 18 N179L, Covington KY gear collapsed landing, Colorado Springs CO14.6.73 14.10.76 5.2.79 destroyed in forced landing off-airport, Dayton OH11.76 11.7.79N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;.55BA-80E18SN4277Bbuilt Champion Steel Corp, Orwell OH Swift Air Charter, Elyria OH forced landing gear-up on rough terrain near Shafter TX, destroyed by fire.55N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;5.55						
Covington KY14.6.73gear collapsed landing, Colorado Springs CO14.10.76Eagle Air Inc, St Louis MO5.2.79destroyed in forced landing off-airport, Dayton OH11.7.79N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;BA-80E18SN4277Bbuilt.55Champion Steel Corp, Orwell OH63/72Swift Air Charter, Elyria OH7.5.74/76forced landing gear-up on rough terrain near Shafter TX, destroyed by fire6.3.76N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;BA-81E18SN3781Bbuilt5.55				•	10	
Eagle Air Inc, St Louis MO5.2.79destroyed in forced landing off-airport, Dayton OH11.7.79N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;BA-80E18SN4277B Swift Air Charter, Elyria OH.55 63/72 Swift Air Charter, Elyria OHN4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;BA-81E18SN3781Bbuilt5.55				Covington KY		
destroyed in forced landing off-airport, Dayton OH11.7.79N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flightfrom Chicago, 4pm, pilot unhurt;BA-80E18SN4277Bbuilt.55Champion Steel Corp, Orwell OH63/72Swift Air Charter, Elyria OH7.5.74/76forced landing gear-up on rough terrain near Shafter TX, destroyed by fire6.3.76N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;5.55						
N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am; N136C accident report 14.10.76: swerved during landing during wind gust, tailwheel unlocked, flight from Chicago, 4pm, pilot unhurt;         BA-80       E18S       N4277B       built       .55         Champion Steel Corp, Orwell OH       63/72         Swift Air Charter, Elyria OH       7.5.74/76         forced landing gear-up on rough terrain near Shafter TX, destroyed by fire       6.3.76         N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;       5.55						
BA-80       E18S       N4277B       built       .55         Champion Steel Corp, Orwell OH       63/72         Swift Air Charter, Elyria OH       7.5.74/76         forced landing gear-up on rough terrain near Shafter TX,       6.3.76         N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin,       6.3.76         N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin,       5.55		N136C accident report 14.6.73: Hamilton Aviation, struck N179L while taxying after landing, 1.45am;				
Champion Steel Corp, Orwell OH       63/72         Swift Air Charter, Elyria OH       7.5.74/76         forced landing gear-up on rough terrain near Shafter TX,       6.3.76         N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin,       6.3.76         BA-81       E18S       N3781B       built       5.55		from Chicag	jo, 4pm, pilot i	unhurt;		
N4277B accident report 6.3.76: unapproved three 80 gallon tanks installed in cabin, flight from unknown location to eventual destination Pontiac MI, 2 unhurt;BA-81E18SN3781Bbuilt5.55	BA-80	E18S	N4277B	Champion Steel Corp, Orwell OH Swift Air Charter, Elyria OH forced landing gear-up on rough terrain near Shafter TX,	63/72 7.5.74/76	
				.3.76: unapproved three 80 gallon tanks installed in cabin,	0.0.10	
	RA-81	F18S	N3781R	huilt	5 55	
	D/ 1-0 1					

	mechanical fa	ailure of gear	Richard R. Bogenreif, Las Vegas NV op: Air Vegas Airlines, Las Vegas NV gear collapsed landing, Grand Canyon AZ (retired derelict Van Nuys CA 87/92) Aerospace Products Inc, North Hollywood CA Glenn A. Bagley, Honolulu HI sold to Micronesia: struck-off USCR Caroline Pacific Air, Pohnpei, Palau Bob Keys, Palau (flew in Palau mispainted as "N7581B", changed to N3781B during maintenance prior to ferry to Australia; delivered Palau to Bundaberg QLD via Cairns 22.8.98, parked open storage Bundaberg 98/05 as N3781B) Robert H. Keys, Noosa Heads QLD (no CofA, stored Bundaberg 02/13 as N3781B) Queensland Air Museum, Caloundra Airport QLD (arr. on truck at museum 1.2.14 ex Bundaberg, outer wings moved earlier 30.12.13)	78/91 78 9.11.78 4.92 29.10.92/95 12.96 .96 98/02 16.6.00/13 16.12.13/20
	N3781G note FAA quote ca N3781B del.v tailwheel, yel noted Bunda 9600lbs 5.4.6 N3781B note & 9.99 parket N3781B outs N3781B note Note: photog Palau prior to	d Van Nuys ad Van Nuys ancellation da via Pt Morest low/white; berg 29.8.98 32; d Bundaberg d Bundaberg raph taken b o the ferry flig	CA 10.87 derelict; CA 23.4.92: prob this acft (GG); ate USCR as 5.11.97; by-Cairns 22.8.98 to Bundaberg 23.8.98 for maintenance, ,19.9.98,15.10.98: plate E18S BA81 built 5.55 conv. to g 30.1.99,11.2.99, 4.99, 5.99 outside yellow & white; 7.99	ul on this E18S at paint scheme but
BA-82	E18S	N2939B	built Copeland Refrigeration Corp, Sidney OH Southern Aviation, Lawton OK ground-loop landing, gear collapsed, Oklahoma City OK struck-off USCR	.55 63/70 7.6.71/75 13.12.73 11.11.75
	accident repo pilot unhurt;	ort 13.12.73:	Southern Aviation: mail flight, Lawton-OKC-Tulsa-Kansas	City MO,
BA-83	E18S		(to Armee de l'Air as BA-83) "F-RAEO" (delivered by Fleetway to Paris 7.55)	7.55/68
	BA-83 Frenci BA-83 Frenci BA-83 noted	h AF visited I h AF visited I RAF Northol	Blackbushe 25.7.59; Heathrow 27.10.60, c/n BA-63 callsign "F-RAEO"; London-Heathrow 5.5.63 "F-RAEO"; t 19.5.66; ith 60th Escadre, Escadron 2/60 based Villacoublay AB in	68;
BA-84	E18S Hamilton Westwind extended nos	N3545B N100X (1 N180X	Currey Sanders Aircraft Co: CofA issued American Snuff Co Jebco Inc, Shreveport LA Falco Inc, Shreveport LA M. O. Rasberry/ Rasberry & Rasberry Firmin Wilkinson, Detroit MI Shorter Airlines, Miami FL (Hamilton extended nose installed 5.73) R.C.D. Inc Swift Air Charter, Cleveland OH	22.6.55 4.12.55/62 30.7.62/64 4.3.64/67 1.3.67/68 10.68/72 25.5.72/74 25.3.74/77 30.8.77/78

op: Flight Express Cargo, Philadelphia PA	78/79
nosed over on takeoff, Middletown PA	17.2.78
M & K Aviation	8.5.78
Perkiomen Airways, Reading PA:	
sale documentation not completed	8.5.78

N180X noted San Antonio TX 31.8.73 Hamilton conversion, Shorter Airlines; N180X accident report 17.2.78: Flight Express Cargo, cargo flight Middletown to Pittsburgh PA, took off in fog 11.32pm, groundlooped, nosed over, pilot unhurt; USCR 95/99: reg. pending, Reading PA;

BA-85	E18S	N3785B	Anderson Air Activities	23.6.55
			Allis Chalmers Manufacturing Co	24.6.55/61
			Robert B. Phillips, Tulsa OK	6.7.61/66
			Marshfield Airways, Marshfield WI	9.8.66/70
			op: Midstate Air Commuter, Chicago IL	66/69
			hit trees landing, Ashland WI, diverted to Duluth	12.10.69
			Skyway Aviation/ Skyway Airlines, Ft Leonardwood MO	11.70/80
			landed gear locked-up, Fort Leonardwood MO	25.7.79
			Nevada Aircraft Leasing Corp	4.4.80/81
			Nolan F. Carter, El Paso TX	23.4.81/95
			struck-off USCR	6.12.95
BA-86	E18S	N50W (2	Page Airways, Rochester NY: delivered new	.55
			D. W. Winkelman Co, Syracuse NY	14.7.55/72
			crashed after takeoff, Skaneateles NY	6.4.72
			ok off from strip too short to obtain minimum speed in snov ngine lost power, slid into ground off-airport, 3k 3 hurt;	v storm, near `
3A-87	E18S	N3787B	Southern Airways Co	7.11.55/56
	-9700		American Leasing Corp, Hartford CT	24.1.56/60
			lsd: Anaconda Wire & Cable Co, Hastings NY	23.6.56/60
			Anaconda Wire & Cable Co, Hastings NY	25.1.60/67
			Pardue University, Lafayette IN	8.11.67/72
			Twin City Airways Corp	13.9.72/74

	Twin City Allways Colp	13.9.12/14
	Hamilton Aviation, Hamilton OH	17.1.74/77
	Sue A. Swenson	2.8.77/78
	Air Service Center, Hamilton OH	8.4.78/79
	tailwheel torn off landing, Beaver Falls PA	11.5.79
	John T. Hogan/ Hoganair Inc, Hamilton OH	1.7.79
N87HA	HoganAir Inc, Hamilton OH	19.6.80/86
N8711H	HoganAir Inc, Hamilton OH	10.86
	The Eagle & The Hawks Inc, Middletown OH	1.11.86/94
	Miami Valley Aviation, Middletown OH	18.3.94/98
	The Eagle & The Hawks Inc, Middletown OH	29.5.98/07
	op: Miami Valley Aviation, Middletown OH	98/05
	Seven Stars Air Cargo Corp, Carolina, Puerto Rico	07/20

N3787B accident report 11.5.79: Air Service Centre, cargo flight Gainsville GA to Buffalo NY, groundloop landing Beaver Falls, tailplane & tailwheel damaged, 8.10pm; N87HA noted Hamilton OH 13.5.85 no titles; N8711H noted Middletown OH 2.92 MVA tailwheel, large fuse freight doors, no titles; N8711H noted Middletown OH 5.97 "Miami Valley"; N8711H noted Middletown OH 1.1.98 & 22.7.98 no titles; N8711H noted Middletown OH 6.8.99 Miami Valley Aviation, plate BA-87 built 6.55; N8711H noted Middletown OH 6.8.99 Miami Valley Aviation; N8711H noted Middletown OH 6.8.99 Miami Valley Aviation; N8711H noted Middletown OH 20.7.02 Miami Valley Aviation; N8711H noted Middletown OH 1.8.05, for sale with N9669N, Miami Valley Aviation has ceased ops; N8711H noted Columbus-Bolton Field OH 11.8.06, not titles, tailwheel; N8711H noted Columbus OH 8.07 "Seven Stars Air Cargo" titles;

BA-88	E18S	N3789B N135W (1 N739F (2 N135X	Florida Airmotive Inc Stockton, Whatley, Davin & Co Winn-Dixie Stores Inc, Charlotte NC George H. Bailey Co, Fort Wayne IN Hatteras Yacht Co North American Rockwell Corp Conner Homes Corp, Newport NC Hausserman Aviation J. C. Sales Corp, Brownsville TX Herbert A. Hartley & Eduardo Pizana/ Aircraft Leasing & Pilot Service, Brownsville TX (owner reported 4.82 N135X destroyed or scrapped) struck-off USCR	7.7.55 7.7.55/60 9.8.60/66 25.2.66 7.3.66/68 14.5.68/69 25.1.69/73 26.5.73/78 23.2.78 30.9.78/82 12.8.82
BA-89	E18S N4906B note	N4906B ed Pontiac Mi	built Puerto Rico Water Resources Authority, San Juan T. W. Henley, Birmingham AL struck fence landing, Geiger AL Morrey L. Wyman/ Wyman Pilot Service, Pontiac MI (retired, derelict Pontiac MI 77/80) struck-off USCR	.55 63/64 69/72 8.5.69 24.8.73/77 6.7.77
BA-90	E18S	N3794B N153GP (1 N164F	Pacific Aircraft Sales Co California Eastern Aviation Kaiser Services Georgia-Pacific Corp, Portland OR Bailey Leasing Corp, Fort Wayne IN Isd: Standard Airways (executive interior replaced by 9 pax seats 7.66) op: Hub Airlines, Ft Wayne IN Eastern Aviation/ Shenandoah Airlines, Baltimore MD landed gear partially locked-up, Roanoke VA Jack Walls Aircraft Sales, Memphis TN Vercoa Air Service/ Allegheny Commuter, Danville IL Executive Air Travel Inc, Sioux Falls SD op: Pro Airlines Southern Aviation Southern Aero Services, Montgomery AL Aerospace Products Inc, North Hollywood CA (cargo door & cockpit hatch installed 1.79) V. L. Wilson, Atlanta GA	14.7.55/56 13.4.56/60 15.4.60/61 10.4.61/66 3.6.66/68 7.6.66/68 c68 8.8.68/69 31.1.69 12.69/70 23.9.70/71 21.1.71/73 73 12.73/77 10.77/78 8.12.78/79 24.2.79/91
	previous reti	raction, lande	.1.69 Eastern Aviation, night mail flight, 6.45am, landing g d partially extended, minor damage only; 'L 4.8.73 Pro Airlines;	lear jammed during
BA-91	E18S -9700 <i>CF-FEM Su</i>	N3788B CF-IJI CF-FEM N244D	Beech Aircraft Corp, Wichita KS Field Aviation Co Ltd, Oshawa ONT Sky Harbour Air Services Sales, Goderich ONT Jack Adams Aircraft Sales, Walls MS Chattanooga Aviation, Chattanooga TN Welding Gas Products Co, Chattanooga TN Amherst Airways, Buffalo NY Buffalo Aeronautical Corp, Buffalo NY Crow Inc, Millbury OH Crow Executive Air Inc, Millbury OH Josephs Four Inc, Fayetteville GA Daniel E. Disbrow, Texas City TX destroyed in hangar fire, Conroe TX struck-off USCR	8.7.55 19.8.55 65/66 19.5.65 21.9.65 20.1.66/68 12.68/71 4.2.71/83 9.9.83/91 20.10.91 4.93/94 17.5.94 12.6.94 11.8.94

BA-92	E18S	N3797B	Southern Airways Co Colonial Oultry Co	12.9.55 11.55/56
			Brazos Engineering Co	11.56/57
			William D. P. Carey/ Packaging Corp of America,	
			Hutchinson KS	12.57/61
		N300W	Packaging Corp of America, Hutchinson KS	4.1.61/73
			Eureka Aero Industries, Eureka CA	28.6.73/76
			(cargo floor & cockpit door installed 5.74)	
			Nor-Cal Aviation, Novato CA	14.6.76/77
			op: Nor-Cal Airlines, Redding CA	76/77
			Hill Aircraft & Leasing Corp, Atlanta GA	11.1.78/79
			(cabin cargo door installed 2.78)	
			Specialty Leasing System Inc	25.6.79/82
			op: General Aviation Inc, Greenville TN	80/81
			J. W. Evans, Hamilton AL	12.4.82/85
			Aero Taxi-Rockford Inc, Rockford IL	22.3.85/88
			emergency landing due engine fire, ran off runway,	
			struck building, Cynthiana KY	29.4.88

N300W noted Benton CA 24.7.76 Norcal Avtn; N300W noted Youngstown OH 4.9.81 General Aviation Inc;

			Burlington Airways, Burlington WI crashed destroyed landing, Burlington WI .76: Burlington Airways, stalled on approach after flight fi ing, 8.20pm, pilot k;	5.11.75/76 1.3.76 rom
			Sisk Aviation Activities, St Louis MO	14.1.70/72
			Maplewood Bank & Trust Co: repossessed	3.11.69/70
			George Sisk/ Orion Airways, St Louis MO	68/69
			Jetco Contracting Co, Mobile AL	66
			Malcolm Jacobs Co, St Louis MO	64
		N386 (2	Morris Grain Corp, Evansville IN	63
BA-95	E18S	N80D (1	Youngstown Airways/Lease Air, Youngstown OH	
			d Heathrow 27.8.55, dep for Tangiers 31.8.55; Rhodesia 16.12.64;	
			k 25.8.55 on delivery to Tangiers by Fleetaways;	
		9Q-CHK	Union Miniere du Haut Katanga, Elizabethville	13.3.63/65
		OO-CHK	Union Miniere du Haut Katanga, Elizabethville	10.9.62/63
		90-CHK	Union Miniere du Haut Katanga, Elizabethville	.61/62
071-34	E103	00-011K	(del. to Tangier via Prestwick 25.8.55)	20.9.00/00
BA-94	E18S	, ОО-СНК	Union Miniere du Haut Katanga, Elizabethville	28.9.55/63
	accident r	eport 13.2.86: (	crashed during go-around, Pacific Air Express;	
			struck-off USCR	7.86
			crashed destroyed during landing, Kalaupapahi HI	13.2.86
			Pacific Air Express, Honolulu HI	12.6.84/86
			(cargo floor & cabin door installed 5.84)	-
			Aerospace Products Inc, North Hollywood CA	2.2.84
			State of Florida: forfeited by court action	17.2.82/84
			Sol Levine	26.4.79/82
			Gilley Airways Corp, Fulton NY	10.1.79
			Donald E. Watson, Washington DC	7.4.72/79
			American Aero Leasing Corp, Elizabeth NJ	9.12.65/72
			AFLC Inc, Birmingham AL	12.64/65
		N30Y	American Aero Leasing Corp, Elizabeth NJ	1.8.63/64
	trigear	112070	(Volpar Mk.IV trigear installed 6.64)	21.0.00,00
		N2979	General Foods Corp, White Plains NY	21.8.58/63
	E18S	N4905B	Atlantic Aviation Corp General Foods Corp, White Plains NY	27.7.55 27.7.55/58

BA-96	E18S	N4966B	Roscoe Turner Aeronautical Corp	1.9.55/56
			Ebco Manufacturing Co, Columbus OH	31.1.56

			Howard Aero Inc, San Antonio TX	22.4.56
			Columbus Aviation	23.4.56/59
			Baldwin Piano Co	5.6.59/62
			Hidden Splendor Mining Co/ Atlas Corp,	04700/05
			Salt Lake City UT	24.7.62/65
			damaged taxying after landing, Moab UT Alpena Flying Service/ Detroit Northern Airlines,	15.1.64
			Alpena MI	3.5.65/72
		N101SA	Shorter Airlines, Miami FL	17.3.72/75
	Hamilton		(9 passenger interior fitted 9.72,	
	extended n	ose	Hamilton extended nose installed 4.73)	
			Package Express	17.9.75/76
			Stanner Air Inc, Hollister CA	23.7.76/83
			(owner reported 2.83 aircraft destroyed/scrapped)	
			struck-off USCR	8.6.83
	N101SA nc	oted Ft Lauder	dale FL 15.9.76 long nose, all metallic;	
3A-97	E18S	N42B	Vernon L. Wright, Dartmouth MA	63/64
	trigear	N6308	Vernon L. Wright, Dartmouth MA	66/69
		N4012	Hendrix Aviation, Oxford AL	70
			gear collapsed landing, Anniston AL	3.10.70
			Jack Wall Aircraft Sales, Memphis TN	72
			Gary V. Covington, Las Vegas NV Mexico City Airport, Mexico: retired, inst. airframe	3.12.75/85 85
			אופאונט טונץ הויףטונ, אופאונט. ופנוופט, ווואנ. מווומווופ	00
3A-98	E18S	N37M	Arnold O. Morgan, Corpus Christi TX	63/79
	trigear		Richard T. Mitchell, Broussard LA	3.82
	-		swung landing, nose gear collapsed, Corpus Christi TX	12.8.82
			Robert J. Pate, Mission TX	5.1.84
			struck-off USCR	30.4.84
	N37M note	d Corpus Chri	sti TX 10.5.73 trigear;	
BA-99	E18S	N18X (1	Joy Manufacturing Co, Pittsburgh PA	63/64
		N918X	C. W. Mathews Constructing Co, Marietta GA	12.1.66/67
			crashed in water after wing spar structural failure,	
			Acworth GA	28.4.67
	N918X note	ed Detroit City	Airport MI 7.4.65;	
3A-100	E18S	N27M	built	.55
		N27MD	rereg	
		N135J	J. E. Green Co, Johnson City TN	63
			Southeastern Beechcraft Inc, Kingsport TN	64
		N135FC	rereg	<u></u>
		N633DN	Valley Co, Chattanooga TN	66 69/70
			Vercoa Air Service/ Allegheny Commuter, Danville IL op: Pennsylvania Commuter	70
			Semo Aviation/ Semo Airways, Malden MO	20.12.71/76
			crashed landing in fog, Blountville TN	8.10.76
			on-DCA 29.4.70 Pennsylvania Commuter; TN 22.5.72 Semo Airways;	
			8.10.76: Semo Aviation, crashed on approach in weather b	elow minimums,
	fog, struck	fence 4.05am	flight from Memphis, pilot unhurt;	
BA-101	E18S	N45A	Atlantic Aviation Corp	20.9.55/56
	-9700		American Leasing Corp, Hartford CT	2.3.56/60
			Isd: Ratner Manufacturing Co	2.3.56/60
			Lee Ratner	5.3.60
			damaged in gear-up landing. Alva Fl	15 9 60

Lee Ratner5.3.60damaged in gear-up landing, Alva FL15.9.60Equilease Corp13.7.61Graubart Aviation, Valparaiso IN10.62/63Robinson Manufacturing Inc, Coleman MI5.2.63/68

S. W. Sisk/ Orion Airways, St Louis MO Maplewood Bank & Trust Co: repossessed Sisk Aviation Activities, St Louis MO Golden Eagle Aviation Combs Airways, Billings-Logan MT	11.68/69 3.11.69 14.1.70 .70 .70/71
(converted to all-cargo interior 3.71)	
Employee Benefits Inc, Billings MT	30.3.71/72
Van Dusen Acceptance Corp, Minneapolis MN	5.6.72/74
Hamilton Aircraft Co, Tucson AZ	16.1.74
(Hamilton cargo door, cockpit door installed 1.74)	
Flightways Corp	25.1.74/75
Precision Valley Aviation, Springfield VT	16.4.75/84
Rockingham Aviation Corp, Bridgewater VA	21.6.84/86
Robert A. Youkin/ Youkin Air Service, Lowell AR	9.1.86/87
Porsche Galesburg Inc, Galesburg IL	4.87
Robert A.Younkin/ Younkin Air Service, Springdale AR	7.87/88
op: Midwest Executive	88
crashed, destroyed near Vienna MO	3.3.88

N45A noted Wilmington OH 2.9.74;

BA-102	E18S	N22X (1	built	.55
			New York Conservation Department, Albany NY	63/64
		N422X (2	Page Airways, Rochester NY	64
			Charlottesville & Albermarle Bus Co, Charlottesville VA	66
		N882L	Robert A. Goodman, Memphis TN	70
			UC Leasing Inc, Memphis TN	72
			Scott M. Niswonger	75
			crashed, destroyed by fire, Charlotte NC	1.10.75

USCR69: not listed as N422X or N882L;

BA-103	E18S	N24K (1	built	.55
		N791AA	rereg	
		N791A	Mahlon C. Kline, Philadelphia PA	63
			Ritz Craft Inc, Argos IN	64/66
			Skystream Inc, Plymouth IN	69
			Duncan Aviation, Lincoln NE	70/72
			Hamilton Aviation, Hamilton OH	3.3.73/75
			crashed destroyed after takeoff, Toledo-Express OH	26.6.75
BA-104	E18S	N43B	reg	
		CF-LPD	reg	
		CF-ALL	Lamothe Transport Co	
			crashed dest. by fire, 5 miles south Val-d'Or Airport QUE	16.6.60
BA-105	E18S	N21X	Tulsair Distributors Inc	10.10.55
	-9700		Winthrop Rockefeller, Little Rock AR	23.1.56/59
			Rebsamen & East Inc, Little Rock AR	5.1.59/69
	ATE		(rebuilt as American Turbine Engine Co ATE Westwind I:	
	Westwind I		PT6A turbines, trigear completed 6.66, CofA issued 23.6.	66)
	trigear		windscreen struck by large bird, Walnut Ridge AR	21.9.67
		N521GP	Georgia-Pacific Corp, Portland OR	31.1.69/74
			Dole Aviation	26.3.74/75
	Hamilton		(rebuilt at Tucson AZ 7.74 by Hamilton Aircraft Co as	
	Westwind III		Hamilton Westwind III: Volpar trigear replaced by	
	tailgear		conventional tailgear, Hamilton extended cargo nose	
			& cargo door, cockpit hatch)	
			Great Western Airlines, Tulsa OK	3.11.75/81
			damaged when hit snowbank on takeoff, Springfield IL	27.1.79
			Mark Peterson/ Desert Flying Service, Tonopah NV	1.5.81
			Gold Creek Mining & Development Corp deliberately destroyed by fire on ground Mexico,	20.7.81
			after attempted overloaded takeoff with drugs	.81
			(Peterson arrested by DEA: Gold Creek Mining was a bogus sale)	

N21X noted Prestwick, Scotland 21.6.56 owned W. Rockefeller; N521GP noted Brownsville TX 8.5.79 freighter no titles, turbine tailwheel, extended nose;

BA-106	E18S	N46M	Elliot Flying Service	14.10.55
			Collins Radio Co, Cedar Rapids IA	10.55/65
			Wiles Holloway Inc, Baton Rouge LA	26.2.65/68
			struck powerlines landing, Fairhope AL	17.2.67
			King's Flying Service, Olathe KS	19.8.68/69
			Avonics Inc	12.69/70
			Broadcast Industries Inc, Philadelphia PA	10.70/72
			Virginia Aviation	20.7.72/74
			US Government: forfeited by court order	22.4.74
			Leon Redman/ Lee's Motor City	19.6.74
			Volpar Inc, Van Nuys CA	24.7.74
	Volpar		(conversion to <i>Volpar Turboliner II</i> completed 11.7.75:	21.1.1
	Turboliner I		turbines, 81" fuselage extension, Volpar trigear)	
				0775
	trigear	N900WA	Volpar Inc, Van Nuys CA	2.7.75
	(#19)		William E. Winship/ Winship Air Service/ Aircon Co,	
			Anchorage AK Alaskan Trader	10.75/82
			Troy Air Inc, Anchorage AK	11.82/85
		N900TH	Troy Air Inc, Anchorage AK	8.7.85/90
			op: FS Flying Service, Anchorage AK	90
			emergency landing wheels-up, Anchorage AK	15.1.90
			Connie Kalitta Services, Willow Run MI	30.5.90
			renamed: American International Airways, Willow Run MI	
			renamed: Kalitta Flying Service, Detoit-Willow Run MI	1.1.92/99
			(stored damaged Willow Run 91/98, dismantled 98)	1.1.32/33
				15 6 00/04
			Kitty Hawk Charters Inc, Morristown TN	15.6.99/04
			"sold for scrap 9.01", struck-off USCR	1.7.04
	N900WA no N900TH ac N900TH no N900TH no plates: BA-1	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa	t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cono r conversion #19;	
	N900WA no N900TH ac N900TH no N900TH no plates: BA-1	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond	
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued	lition, 26.10.55/63
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN	lition, 26.10.55/63 63
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued	lition, 26.10.55/63
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN	lition, 26.10.55/63 63
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc	lition, 26.10.55/63 63 4.6.63/65
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation,	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL	lition, 26.10.55/63 63 4.6.63/65
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68)	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA	26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL	26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70
BA-107	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL	26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70
	N900WA no N900TH ac N900TH no N900TH no plates: BA-1 N900TH no E18S	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70
	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F N29W	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 29.9.70 72/91
-	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	N45B N125 N102MC	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 72/91 .55 62/64
	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	oted Anchor cident repor ted Anchior ted Willow F 106 & Volpa ted Willow F N29W	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 72/91 .55 62/64 66
	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	N45B N125 N102MC	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR built Commonwealth Plan Inc, Boston MA Trostel Aviation Co, Milwaukee WI Gweneth C. Landry, East Troy WI	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 72/91 .55 62/64 66 69/72
	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	N45B N125 N102MC	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR built Commonwealth Plan Inc, Boston MA Trostel Aviation Co, Milwaukee WI Gweneth C. Landry, East Troy WI Business Aircraft Leasing, East Troy WI	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 72/91 .55 62/64 66 69/72 79
	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	N45B N125 N102MC	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR built Commonwealth Plan Inc, Boston MA Trostel Aviation Co, Milwaukee WI Gweneth C. Landry, East Troy WI Business Aircraft Leasing, East Troy WI Mode Air Enterprises, Delray Beach FL	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 72/91 .55 62/64 66 69/72 79 1.82
	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	N45B N125 N102MC	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR built Commonwealth Plan Inc, Boston MA Trostel Aviation Co, Milwaukee WI Gweneth C. Landry, East Troy WI Business Aircraft Leasing, East Troy WI Mode Air Enterprises, Delray Beach FL George K. Armagost/ Pro Air Services, Opa Locka FL	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 72/91 .55 62/64 66 69/72 79 1.82 6.82/83
	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	N45B N125 N102MC	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR built Commonwealth Plan Inc, Boston MA Trostel Aviation Co, Milwaukee WI Gweneth C. Landry, East Troy WI Business Aircraft Leasing, East Troy WI Mode Air Enterprises, Delray Beach FL George K. Armagost/ Pro Air Services, Opa Locka FL Pamela E. Shanks, Woodland CA	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 72/91 .55 62/64 66 69/72 79 1.82 6.82/83 22.2.83
	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	N45B N405T	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR built Commonwealth Plan Inc, Boston MA Trostel Aviation Co, Milwaukee WI Gweneth C. Landry, East Troy WI Business Aircraft Leasing, East Troy WI Mode Air Enterprises, Delray Beach FL George K. Armagost/ Pro Air Services, Opa Locka FL Pamela E. Shanks, Woodland CA sold to Canada, struck-off USCR	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 72/91 .55 62/64 66 69/72 79 1.82 6.82/83 22.2.83 31.8.83
	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	N45B N125 N102MC	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR built Commonwealth Plan Inc, Boston MA Trostel Aviation Co, Milwaukee WI Gweneth C. Landry, East Troy WI Business Aircraft Leasing, East Troy WI Mode Air Enterprises, Delray Beach FL George K. Armagost/ Pro Air Services, Opa Locka FL Pamela E. Shanks, Woodland CA sold to Canada, struck-off USCR	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 72/91 .55 62/64 66 69/72 79 1.82 6.82/83 22.2.83
BA-107 BA-108	N900WA nc N900TH ac N900TH no plates: BA-1 N900TH no E18S -9700	N45B N405T	age 1.9.76; t 15.1.90: FS Flying Service, emergency landing after takeo age AK 27.5.90 Turboliner; Run MI 7.91 Connie Kalitta, trigear turbine, stored poor cond r conversion #19; Run MI 7.98 dismantled; Aircraftsman Inc, Oklahoma City OK: CofA issued Graubart Aviation, Valparaiso IN Frank D. Hansen/ Hansen Air Activities, Morris IL Meginnes Enterprises Inc Larry B. Byerly/ By-Air Industries/ Byerly Aviation, Peoria IL (cargo door installed 5.68) Atlas Cargo Airlines JSA Financial Corp, Boston MA Byerly Aviation, Peoria IL dest. by fire ground collision with Cessna 337, Keokuk IA sale reported, Keokuck IA: USCR built Commonwealth Plan Inc, Boston MA Trostel Aviation Co, Milwaukee WI Gweneth C. Landry, East Troy WI Business Aircraft Leasing, East Troy WI Mode Air Enterprises, Delray Beach FL George K. Armagost/ Pro Air Services, Opa Locka FL Pamela E. Shanks, Woodland CA sold to Canada, struck-off USCR	lition, 26.10.55/63 63 4.6.63/65 1.4.65/66 26.2.66/69 10.69 70 19.9.70 29.9.70 72/91 .55 62/64 66 69/72 79 1.82 6.82/83 22.2.83 31.8.83

C-GIFR noted Vancouver 26.6.84 Coval Air;

E18S	N44N	The Norman Larson Co	9.11.55
		McCulloch Motors Corp/ McCulloch Corp,	
		Los Angeles CA	9.11.55/68
			10.6.68
			26.9.68/70
			10.9.70/71
			12.2.71/72
			5.4.74/75
			16.5.75/76
			15.10.76
			10.76/77
			28.2.77
			14.3.77/82
			26.7.82/84
			1.5.84
			25.7.84
			1.1.85
			85
		forced landing in field, Billings MT after struck by lightning	
		and right engine deflected downwards due turbulence	15.8.85
		sold: documentation not completed	
N44N photo	) Long Beach	1959 titles "McCulloch Motors Inc. Los Angeles"	
N++N Holee	Dakershela		
F18S	N384	Currey Sanders Aircraft Co: CofA issued	11.11.55
L100	NOOA		
			12.55/57
			22.1.57/61
			19.6.61/62
			11.62/63
trigear		(Volpar Mk.IV trigear installed 6.63)	
		Atkinson & Co, Indianapolis IN	3.9.63/67
			1.2.67/69
Volpar			
•			
1 di bolinici	N352\/		
	110021		21 4 60/74
Turk alla an I			21.4.69/74
		(further modified 4.73 to Volpar Turboliner II)	
			Fairbanks Flight
irbanks AK	E 2 71/76		
		or installed 23.9.74)	
	& cockpit do	Polar Airways, Anchorage-Merrill Field AK	1.76
		Polar Airways, Anchorage-Merrill Field AK	1.76 25.4.76/78
	& cockpit do	Polar Airways, Anchorage-Merrill Field AK Polar Airways, Anchorage-Merrill Field AK	25.4.76/78
	& cockpit do N115PA	Polar Airways, Anchorage-Merrill Field AK Polar Airways, Anchorage-Merrill Field AK Soonair Lines Inc, Tulsa OK	25.4.76/78 19.4.78
	<sup>-</sup> & cockpit do N115PA N17SL	Polar Airways, Anchorage-Merrill Field AK Polar Airways, Anchorage-Merrill Field AK Soonair Lines Inc, Tulsa OK Soonair Lines Inc, Tulsa OK	25.4.76/78 19.4.78 21.7.78/81
	& cockpit do N115PA	Polar Airways, Anchorage-Merrill Field AK Polar Airways, Anchorage-Merrill Field AK Soonair Lines Inc, Tulsa OK Soonair Lines Inc, Tulsa OK Troy Air Inc, Anchorage AK	25.4.76/78 19.4.78 21.7.78/81 13.5.81/84
	<sup>-</sup> & cockpit do N115PA N17SL	Polar Airways, Anchorage-Merrill Field AK Polar Airways, Anchorage-Merrill Field AK Soonair Lines Inc, Tulsa OK Soonair Lines Inc, Tulsa OK Troy Air Inc, Anchorage AK Connie Kalitta Services, Willow Run MI	25.4.76/78 19.4.78 21.7.78/81 13.5.81/84 10.2.84/90
	<sup>-</sup> & cockpit do N115PA N17SL	Polar Airways, Anchorage-Merrill Field AK Polar Airways, Anchorage-Merrill Field AK Soonair Lines Inc, Tulsa OK Soonair Lines Inc, Tulsa OK Troy Air Inc, Anchorage AK Connie Kalitta Services, Willow Run MI renamed: American International Airways, Willow Run MI	25.4.76/78 19.4.78 21.7.78/81 13.5.81/84 10.2.84/90 10.90/92
	<sup>-</sup> & cockpit do N115PA N17SL	Polar Airways, Anchorage-Merrill Field AK Polar Airways, Anchorage-Merrill Field AK Soonair Lines Inc, Tulsa OK Soonair Lines Inc, Tulsa OK Troy Air Inc, Anchorage AK Connie Kalitta Services, Willow Run MI renamed: American International Airways, Willow Run MI renamed: Kalitta Flying Service, Detroit-Willow Run MI	25.4.76/78 19.4.78 21.7.78/81 13.5.81/84 10.2.84/90 10.90/92 1.1.92/99
	<sup>-</sup> & cockpit do N115PA N17SL	Polar Airways, Anchorage-Merrill Field AK Polar Airways, Anchorage-Merrill Field AK Soonair Lines Inc, Tulsa OK Soonair Lines Inc, Tulsa OK Troy Air Inc, Anchorage AK Connie Kalitta Services, Willow Run MI renamed: American International Airways, Willow Run MI	25.4.76/78 19.4.78 21.7.78/81 13.5.81/84 10.2.84/90 10.90/92
	<sup>-</sup> & cockpit do N115PA N17SL	Polar Airways, Anchorage-Merrill Field AK Polar Airways, Anchorage-Merrill Field AK Soonair Lines Inc, Tulsa OK Soonair Lines Inc, Tulsa OK Troy Air Inc, Anchorage AK Connie Kalitta Services, Willow Run MI renamed: American International Airways, Willow Run MI renamed: Kalitta Flying Service, Detroit-Willow Run MI	25.4.76/78 19.4.78 21.7.78/81 13.5.81/84 10.2.84/90 10.90/92 1.1.92/99
	<sup>-</sup> & cockpit do N115PA N17SL	Polar Airways, Anchorage-Merrill Field AK Polar Airways, Anchorage-Merrill Field AK Soonair Lines Inc, Tulsa OK Soonair Lines Inc, Tulsa OK Troy Air Inc, Anchorage AK Connie Kalitta Services, Willow Run MI renamed: American International Airways, Willow Run MI renamed: Kalitta Flying Service, Detroit-Willow Run MI Kitty Hawk Charters Inc, Morristown TN	25.4.76/78 19.4.78 21.7.78/81 13.5.81/84 10.2.84/90 10.90/92 1.1.92/99 6.5.99/01 29.1.02/20
	N44N photo N44N notec N44N notec E18S trigear Volpar Turboliner I (conv. #011	N44N photo Long Beach N44N noted Long Beach N44N noted Bakersfield E18S N38A trigear Volpar	McCulloch Motors Corp/ McCulloch Corp, Los Angeles CA         Valley Airlines, Phoenix AZ         McCulloch Corp, Los Angeles CA         J. W. Duff Aircraft Co, Denver CO         Leo Pike/ Bakersfield Aviation Service CA         Sierra West Airlines, Oxnard CA         Avenales Aviation Inc, Las Vegas NV         Great Western Airlines, Tulsa OK         Sam Vires/ Mid-South Aircraft Sales, Memphis TN         Deleware Valley Airways         (cargo door installed 2.77)         Jamson Corp, Palmyra NY         Coker Air Freight, Dallas TX         nn: Skyfreighters Corp, Dallas TX         Allen Godwin/ Memphis Recipro         Sam Vires/ Mid-South Aircraft Sales, Memphis TN         op: Skyfreighters Corp, Dallas TX         Allen Godwin/ Memphis Recipro         Sam Vires/ Mid-South Aircraft Sales, Memphis TN         op: Skyfreighters Corp, Dallas TX         Allen Godwin/ Memphis Recipro         Sam Vires/ Mid-South Aircraft Sales, Memphis TN         op: Skyfreighters Corp, Dallas TX         Allen Godwin/ Memphis Recipro         Sam Vires/ Mid-South Aircraft Co: CofA isoued         recon Engineers Inc, Frankfort KY         Capitol Engineering Services, Frankfort KY         Capitol Engineering Services, Frankfort KY         Blue Grass Airmotive Inc

N408TH Willow Run 8.97 Kalitta, noted as Turboliner; N408TH noted Boston-Logan MA 22.8.98 Turboliner Kalitta FS; N408TH noted Willow Run 3.8.99; N408TH noted Ankeky IA 31.7.03 Turboliner trigear, no titles, ex Kalitta scheme, appears in service N408TH noted Ankeny IA 22.7.06 Turboliner, no engines; Ankeny IA 24.7.08, red & gold; N408TH noted Ankeny 24.7.14 Turboliner, white with red & gold trim, operational; same 16.7.15;

BA-111	E18S	N24R	Beech Aircraft Corp: built	8.55
	-9700		Atlantic Aviation Services	12.12.55
		N555CB (1	Cleveland Brothers Equipment Co, Harrisburg PA	.56
			(mods to E18S-9700, 3 bladed props completed 10.59)	
		N575C	Univac Division, Sperry Rand Corp	19.10.62/64
			National Financing Inc, Wilmington DE: USCR	63/64
			Atlantic Aviation Corp, Teterboro NJ	5.64
			sold to Great Britain, struck-off USCR	30.6.64
			(ferry tanks installed Amityville NY, dep. on del. 11.6.64,	
			N575C arr. London-Gatwick 15.6.64)	
		G-ASUG	Survey Flights Ltd, Coleraine, Northern Ireland	7.64/68
			(British CofA issued 31.3.65 after transparent nose cone	
			and other survey mods completed at Stansted)	
	E18S-9700		Loganair Ltd, Glasgow-Abbotsinch: delivered	28.5.68/76
			(mod. to E18S-9700 11.2.69)	
			retired Glasgow-Abbotsinch	12.3.75
			Museum of Flight, East Fortune, Scotland	3.76/20
			(displayed as "G-ASUG Loganair")	

N575C noted London-Gatwick 15.6.64 (plate BA-111), 16.6.64 & 2.8.64; Originally planned to have survey nose and camera gear installed by Air Couriers Ltd at Gatwick, But G-ASUG flown Gatwick-Stansted 12.8.64 for Field Aircraft Services to install perspex nose and survey camera gear, cream & brown; departed Stansted 3.65 on completion of mods by Fields; G-ASUG noted Leeds-Bradford (Yeadon) 28.3.65 owned Survey Flights (Yeadon) Ltd, a subsidiary

of BKS Aerial Surveys

G-ASUG departed Stansted 4.65 after 7 months here with Survey Flights;

G-ASUG noted Newcastle 4.4.65 survey flying, to Yeadon;

G-ASUG noted Dublin 7.4.65 Survey Flights Ltd: first visit of many on survey ops;

G-ASUG visited Lulsgate 27.6.65 on survey flight;

G-ASUG visited Stansted 16.10.65 Survey Flights;

G-ASUG visited Dublin 27.2.66;

G-ASUG arrived Stansted 7.12.65 for overhaul by Fields for Survey Flights, testflown 21.12.65 after overhaul;

G-ASUG arrived Stansted 28.7.66 for overhaul by Fields for Survey Flights;

G-ASUG visited Dublin 6.6.67 Survey Flights;

G-ASUG visited Newcastle 2.11.65 Survey Flights, refuelled while operating in the area;

G-ASUG visited Gatwick 23.4.66;

G-ASUG returned to Yeadon 22.1.67 where based after overhaul and respray at Stansted; G-ASUG visited Exeter 8.2.67, visited Gatwick 12.3.67; G-ASUG arrived Abotsinch on delivery to Loganair 28.5.68; Purchased by Loganair 5.68 and used for passenger services, including a Scandinavian

passenger services, including a Scandinavian passenger service Glasgow-Aberdeen-Stavanger 7.69-11.70, then charter work from Glasgow until grounded 3.75 due cost of regulatory wingspar inspection;

G-ASUG noted Dublin 28.2.70 Loganair; Dublin 4.71, 8.71, 10.71, 3.74, 9.74, all Loganair; G-ASUF visited Cork 30.4.74; Heathrow 17.10.74 Loganair;

retired Abbotsinch 12.3.75 ahead of CofA expiry 23.7.75; G-ASUG noted in museum East Fortune 10.8.02;

BA-112	E18S	N62B	Beech Aircraft, Wichita KS	.55	
			(demonstrator "Super 18" model .55)		
			Warren Teed Products Co, Columbus OH	63	
			Jack Adams Aircraft Sales, Walls MS	64	
			Air Credit Inc, Long Beach CA	66	
			Mobile Aircraft Inc, Mobile AL	69	
			Northern Airlines, St Marys OH	70	
			Jed Air Inc	76	

last Dublin visit 10.3.75 Loganair;

Francisco Cruz, San Juan, Puerto Rico	14.4.77/79
op: Air Caribbean, San Juan, Puerto Rico	79
crashed destroyed in night landing on abandoned strip,	
cocaine on board, San Juan, Puerto Rico	13.7.79

N62B noted San Juan PR 30.4.78;

BA-113	E18S	N81D (1	Youngstown Airways, Youngstown OH	1.12.55
			The Wean Engineering Co	12.55/56
			Lease Air Inc	10.7.56/60
		N8111	Jack Adams Aircraft Sales, Walls MS	10.60/61
			Farrell-Cheek Steel Co of Delaware, Sandusky OH	2.3.61/64
			Crescent City Aviation, Evansville IN	10.64/69
			Lexington Airways, Lexington KY	25.2.69/70
			op: Lexington Air Taxi, Lexington KY	69
			Alliance Aero Enterprises, Jackson OH	22.4.70
			Flint Air	11.8.70/71
			Hamilton Aircraft Co, Tucson AZ	24.6.71/73
			(converted to all-cargo configuration 12.73)	
			Banner Flight Ltd	12.73/75
			Precision Valley Aviation, Springfield VT	1.75/84
			(operated windowless, "Precision Freighter" titles)	
			damaged, hit snowbank landing, Boston-Logan MA	31.1.77
			Rockingham Aviation Corp/ K&K Aircraft, Bridgewater	VA 21.6.84/89
			(converted for aerial application, 350 gallon cabin	
			chemical tank installed 4.85 for gipsy moth and mosqu	uito
			spraying contracts)	
			Bill Walker & Associates, St Simons Island GA	.89
			Center Air Inc, Greenville SC	10.89/90
			Milton B. & Darlene P. Henry, Juno FL	14.2.91
			Westwind Trading Inc, Lake Worth FL	10.12.91
			Jetlease Finance Corp, Fort Lauderdale FL	9.9.93/95
			•	
			op: Caribe Air Cargo	95
	N8111 ac		op: Caribe Air Cargo ditched during landing, Walkers Cay, Bahamas VY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke	95 23.3.95 een NH,
	N8111 ac 8.30pm, p N8111 nc	cident report bilot unhurt; bted Boston-L	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte	23.3.95 een NH,
34-114	N8111 ac 8.30pm, p N8111 nc N8111 nc	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic;	23.3.95 een NH, r", in service;
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service	23.3.95 een NH, r", in service; 8.12.55
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE	23.3.95 een NH, r", in service; 8.12.55 12.55/60
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes,
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74)	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN (cockpit door installed 1.77)	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75 5.6.75/79
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN (cockpit door installed 1.77) AeroServ Inc	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75 5.6.75/79 27.6.79
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN (cockpit door installed 1.77) AeroServ Inc St. Joseph Bank & Trust Co	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75 5.6.75/79 27.6.79 8.9.79/82
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN (cockpit door installed 1.77) AeroServ Inc St. Joseph Bank & Trust Co Bruce & Mark McSwiggan, Fayetteville GA	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75 5.6.75/79 27.6.79 8.9.79/82 9.2.82/97
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN (cockpit door installed 1.77) AeroServ Inc St. Joseph Bank & Trust Co Bruce & Mark McSwiggan, Fayetteville GA gear collapsed taxiing, Anderson SC	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75 5.6.75/79 27.6.79 8.9.79/82 9.2.82/97 25.5.99
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN (cockpit door installed 1.77) AeroServ Inc St. Joseph Bank & Trust Co Bruce & Mark McSwiggan, Fayetteville GA gear collapsed taxiing, Anderson SC Tol-Air Services, San Juan, Puerto Rico	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75 5.6.75/79 27.6.79 8.9.79/82 9.2.82/97 25.5.99 5.2.97/99
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L ted Ft Laude N52A	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN (cockpit door installed 1.77) AeroServ Inc St. Joseph Bank & Trust Co Bruce & Mark McSwiggan, Fayetteville GA gear collapsed taxiing, Anderson SC Tol-Air Services, San Juan, Puerto Rico MBD Corp, San Juan, Puerto Rico	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75 5.6.75/79 27.6.79 8.9.79/82 9.2.82/97 25.5.99 5.2.97/99 8.2.99/01
3A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L bted Ft Laude	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN (cockpit door installed 1.77) AeroServ Inc St. Joseph Bank & Trust Co Bruce & Mark McSwiggan, Fayetteville GA gear collapsed taxiing, Anderson SC Tol-Air Services, San Juan, Puerto Rico MBD Corp, San Juan, Puerto Rico	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75 5.6.75/79 27.6.79 8.9.79/82 9.2.82/97 25.5.99 5.2.97/99
9A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L ted Ft Laude N52A	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN (cockpit door installed 1.77) AeroServ Inc St. Joseph Bank & Trust Co Bruce & Mark McSwiggan, Fayetteville GA gear collapsed taxiing, Anderson SC Tol-Air Services, San Juan, Puerto Rico MBD Corp, San Juan, Puerto Rico (retired, stripped San Juan, Puerto Rico 12/13)	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75 5.6.75/79 27.6.79 8.9.79/82 9.2.82/97 25.5.99 5.2.97/99 8.2.99/01 10.1.01/13
A-114	N8111 ac 8.30pm, p N8111 nc N8111 nc E18S	cident report bilot unhurt; bted Boston-L ted Ft Laude N52A	ditched during landing, Walkers Cay, Bahamas NY 11.8.74; 31.1.77: Precision Valley, groundloop on landing from Ke ogan MA 8.78, tailwheel, windowless "Precision Freighte rdale-Executive FL 10.11.91 all metallic; Atlantic Aviation Service E. I. duPont de Nemours & Co, Wilmington DE Lehigh Portland Cement Co, Allentown PA T. R. Carpenter/ Flight Service Inc/ Empire State Airlin Syracuse NY Tampa Air Centre Inc, Tampa FL William G. Thomas (cargo floor installed 1.73, cargo door 10.74) Stockert Flying Service, South Bend IN (cockpit door installed 1.77) AeroServ Inc St. Joseph Bank & Trust Co Bruce & Mark McSwiggan, Fayetteville GA gear collapsed taxiing, Anderson SC Tol-Air Services, San Juan, Puerto Rico MBD Corp, San Juan, Puerto Rico	23.3.95 een NH, r", in service; 8.12.55 12.55/60 11.60/65 nes, 3.1.66/72 19.5.72 2.1.73/75 5.6.75/79 27.6.79 8.9.79/82 9.2.82/97 25.5.99 5.2.97/99 8.2.99/01

N52A noted Indianapolis IN 28.4.79 titles "Stockert Flying Service/SFS Freightliner"; N52A noted Atlanta GA 8.9.82 SFS Freighter; N52A noted Griffin GA 12.92 all metallic; N52A noted Griffin GA 26.6.96, metallic, in service; N52A noted St Croix USVI 1.97 "Tol Air";

		oted Opa Lock oted Tamiami	ka FL 4.11.04; FL 10.8.05;	
BA-115	E18S trigear	N39A	IBM Corp American Aero Leasing Corp, Elizabeth NJ Leasing Consultants Inc, Forest Hill NY Bonita Airlines, San Juan, Puerto Rico op: South Atlantic Airlines, Hilton Head Island SC	63/66 69 70 71
			op: Caribbean Island Airways, San Juan, Puerto Rico op: Caribbean Executive Airlines Pleasant Financing Co, Lynn MA	.71 71 72
			ditched in Pacific Ocean, 22 miles from Maui HI, on ferry flight Honolulu-Van Nuys CA	12.6.74
			a FL 6.10.68 trigear, plate BA-115; PR 10.12.70 trigear, Caribbean Executive AL;	
BA-116	E18S	N29S (2	J. R. Gray Co, Dallas TX Sun Oil Co/ Sun Pipe Line Co, Philadelphia PA (D18S N29S traded in on E18S 12.55)	12.55 12.55/64

0,1110	E100			12.00
			Sun Oil Co/ Sun Pipe Line Co, Philadelphia PA	12.55/64
			(D18S N29S traded in on E18S 12.55)	
		N290S	Houston Beechcraft Inc, Houston TX	66
			Fort Myers Airways, Fort Myers FL	13.12.67
		N281FM	Miller Aviation	
			crashed destroyed, forced landing due in-flight fire,	
			Salisbury NC	2.3.68

N281FM accident report: Miller Aviation, struck trees during forced landing on cargo flight due fire in cabin and cockpit;

BA-117	E18S	N42D	Southern Airways Co	27.12.55
	-9700		Southern Aircraft Co	29.6.56/57
			Watkins Motor Lines Inc, Miami FL	19.4.57/65
			minor damage, landing Thomasville GA	13.2.60
			Flowers Baking Co, Thomasville GA	11.65/69
			Properties Inc, Jacksonville FL: USCR	66
			Allied Helicopter Service, Tulsa OK	30.6.69/73
			S. S. Airways, Kansas City KS	22.6.73/81
			Methow Aviation, Wenatchee WA & Everett WA	29.5.81/98
			lsd: Airpac Airlines, Seattle WA	81 /84
			Comanche Air, Winthrop WA	25.9.98/06
			op: Methow Aviation, Everett-Paine Field WA	00/06
			Emerald Aircraft LLC, Issaquah WA	22.11.06/11
			Northern Aviation LLC, Palmer AK (bulk fuel carrier)	29.6.56/57 19.4.57/65 13.2.60 11.65/69 66 30.6.69/73 22.6.73/81 29.5.81/98 81 /84 25.9.98/06 00/06 22.11.06/11 r) 12.1.12/18 8.6.18 1.11.18/19 11.3.19/20 0 Methow Aviation, 63/70 72 28.2.75
			struck-off USCR	
		N42D	Raymond A. Evarts, Cedar City UT: rest. to USCR	1.11.18/19
			Michael A. Majerle, Big Lake AL	11.3.19/20
	N42D not N42D not tailwheel, N42D not N42D not N42D not N42D not N42D not	ted Burbank ( ted Arlington "Methow" al ted Moses La ted Arlington ted Seattle-B ted Ephrata V ted Renton W	Sity KS 28.8.79 tailwheel, no titles; CA 4.6.85 "Methow" titles, in service, tailwheel; WA 11.8.98 "Methow titles, tailwheel, in service; arbour WA 21.9.99 on mail run from Paine Field, rep. op Me pove cabin windows; ake WA 5.01 Methow Aviation; WA 3.6.02 "Methow" tailwheel in service; oeing field 27.4.04 "Methow" in service; VA 16.9.04 "Methow", tailwheel, in service; /A 21.10.06 "Methow", tailwheel, in service; 5 fitted with bulk fuel tank in cabin;	ethow Aviation,
BA-118	E18S	N23X	Vernon F. Neuhaus, Mission TX	63/70
		N23XY	Stripling Coleman, El Paso TX	72
			Omar Stoltzfus, Salisbury MD	28.2.75
			crashed destroyed after takeoff, Salisbury MD	15.5.75
	N23XY a	ccident repor	t 15.5.75: destroyed 12.07am, engine failure after takeoff,	

forced landing off airport, 1k 4 hurt, departing on flight to Haiti, 400lb over Gross Weight;

BA-119	E18S	N63B	Beech Aircraft Corp, Wichita KS	11.1.56
			(CofA for experimental research & development)	
			Atlantic Aviation Corp	9.5.56
			Air Associates Inc	10.56/57
			Trade-Ayer Inc, Linden NJ	4.3.57/58
			C. K. McCan, Victoria TX	25.7.58/71
			George A. Constant	7.7.71/72
			Apollo Airways, Detroit MI	17.7.73/79
			(conversion to all-cargo configuration completed 7.73)	
			renamed: Gelco Courier Services, Chicago IL	79
			United Leasing Corp	4.79/83
			Isd: Little Mountain Airport Inc/	
			Mountain Air Cargo, Denver NC	3.5.79/85
			Equipment Leasing Corp, Greenville SC	19.8.83/85
			Coastal States Aviation, Denver NC	2.85
			J. Richard Wixom/ Blackhawk Airways, Janesville WI	20.3.85/86
			Charles J. Vannoy/ K-Airways, Kenosha WI	21.5.86/88
			Northern Airmotive Corp, Kenosha WI	29.8.88/91
			crashed in forced landing, destroyed, Martinsville OH	20.8.91

N63B noted Kenosha WI 7.91, plate BA-119; 20.8.91 crash report: forced landing off airport after takeoff Martinsville OH, operated by Gary Jelinek;

BA-120	E18S	N52C	Ohio Aviation Co, Dayton OH	6.1.56
			Pittsburgh Consolidation Coal, Pittsburgh PA	6.1.56/67
		N152H	George M. Humphrey, Cleveland OH	2.6.67/70
			Morrow Aviation Co, Marion OH	26.5.70/72
			Van Dusen Acceptance Corp, Minneapolis MN	23.6.72/74
			Hamilton Aircraft Co, Tucson AZ	14.8.74
	Hamilton		(cargo conversion and Hamilton extended nose fitted	
	Extended		by Hamilton Aircraft Co at Tucson AZ 9.74)	
	Nose		Chris Crowell & Co Inc	7.10.74/75
			Palm Beach Air Traders	2.4.75
		N171LG (1	Florida Airmotive Inc, Lantana-Palm Beach FL	9.10.75/83
			(Florida Airmotive request N171LG be removed	
			from register: letter to FAA 4.6.83)	
			struck-off USCR	9.83
			(broken-up: cargo door & cockpit entrance door	
			ex BA-120 installed in BA-16/N255D 6.84)	

N152H noted Tucson AZ 20.9.74 inside Hamilton hangar, extended nose just installed, radials; N171LG noted Miami 4.8.78 op a flight for Air Vero, owned Florida Airmotive; N171LG noted Ft Lauderdale FL 16.3.81 reported as Hamilton Westwind;

BA-121	E18S	N45D	Topeka Aircraft Sales & Service, Topeka KS	12.1.56
			Panhandle Eastern Pipe Line Co	12.1.56/62
			S & S Aviation Inc	2.7.62
			Tempo Design Corporation, Miami FL	63
			Continental Aviation Corp, Opa Locka FL	10.63/64
			Charles W. Gering, Miami FL	12.64/69
			Kno-Mac Asphalt Paving Inc	9.10.69/70
		(N1EK)	ntu: Kno-Mac Asphalt Paving Inc	10.69
			(cargo/airstair door installed 11.69)	
		N10EK	Kno-Mac Asphalt Paving Inc	10.69/75
			(FAA report 3.70: aircraft is still painted as N1EK)	
		N11HT	Charles E. Bush/ Bush Aviation, Ft Lauderdale FL	9.5.75/78
			Bill Swipe, Coconut Grove FL:	
			fictitious address, sale documentation not completed	29.3.78
			struck-off USCR	8.82

N45D noted Miami FL 4.10.68;

N10EK noted Ft Lauderdale FL 28.9.70; N11HT noted Ft Lauderdale FL 15.9.76;

BA-122	E18S	N2002A	Aluminum Company of America, Pittsburgh PA	.56
0,1122	2100	N412A	Aluminum Company of America, Pittsburgh PA	63/64
			Hess Manufacturing Co, Quincy PA	66
		N198HA	Henson Aviation, Hagerstown MD	69/70
		N107T	Tobey Inc, Simsbury CT	9.3.71/72
			crashed on takeoff, destroyed by fire, Newark NJ	23.9.72
BA-123	E18S	N700E (2	Atlantic Aviation Corp	19.1.56
	-9700		Esso Shipping Co	23.1.56/58
		N73114	Esso Shipping Co	27.2.58
			Butterworth Systems Inc	16.6.58
		N700CC (1	The Chemstrand Corp	12.58/61
		N563R N370M	The Chemstrand Corp Murphy Oil Corp, El Dorado AR	9.3.61 5.4.61/67
		N378M	Stan Burnstein/ Continental Aviation Co	10.1.67/69
		11070101	John Rourke/ Rourke Aviation, Bartlesville OK	10.4.69
			Caribe Air Sales Inc, Opa Locka FL	11.69/76
			op: Pro Air Services, Opa Locka FL	77
			Davis Horne Flying Service, McAlester OK	26.9.76/79
			(cockpit entrance door installed 3.78)	
			op: Pro Air Services, Opa Locka FL	78
			Marcus B. Butler, Shreveport LA	1.6.79/91
		oted Miami FL oted Miami 25.	3.10.77 in service; 10.78;	
BA-124	E18S	N64B	Young Aviation Corp, Fort Smith AR	63/64
			Bailey Leasing Corp, Fort Wayne IN	66/68
			op: Standard Airways	7.6.66/68
			Eastern Aviation Corp/ Shenandoah Airlines,	
			Baltimore-Friendship MD	68/69
			Coastal Airways, San Juan, Puerto Rico	23.1.70
			crashed landing, San Juan, Puerto Rico	10.2.70
	N64B N01	ted Baitimore w	1D 21.9.68 & 28.9.68, both Shenandoah;	
BA-125	E18S	JA5501	built	30.1.56
			Maritime Safety Board, Tokyo-Haneda	65
			Maritime Safety Agency, Fukuoka	70/81
			retired, struck-off Register	24.3.81
			derelict complete in junk yard, Wakamiya Town,	02
			Fukuoka Prefecture, Japan	03
	JA5501 r	noted Tokyo-Ha noted in junkyar e Coast Guard	rd, Wakamiya Town, Fukuoka Prefecture, 10.03 in faded	
BA-126	E18S	JA5502	built	30.1.56
			Maritime Safety Board, Tokyo-Haneda	65
			Maritime Safety Agency, Sendai	70/80
			Nihon Technology Corp	80
			sold to USA, struck-off Japanese Register	21.7.80
		N8475D	Eugene C. Eversole, Honolulu HI	22.7.80/81 28.5.81/82
			Adrian I. Dalsey, Honolulu HI op: DHL Cargo, Honolulu HI	28.5.81/82 81
			op: Alpha Air, Manila, Philippines	82
			(ferry permit 4.6.82 from Honolulu to Manila)	02
		RP-C707	Commuter Air Philippines, Manila	.82/87
			Air Charter Philippines, Manila	90
			crashed in sea on takeoff, Masbate, Philippines	14.8.91
		, , <b>-</b> ,	4 40 0 07	
	JA5502 r	noted Tokyo-Ha	ineda 13.3.67;	

JA5502 noted Tokyo-Haneda 13.3.67; N8475D noted Honolulu 23.8.81 full DHL scheme, in service; RP-C707 noted Manila 7.5.86 "Commuter Air Philippines" titles, ex DHL orange & white scheme, tailwheel;

RP-C707 noted Manila 10.9.86 "Commuter Air Philippines" titles;

BA-127	E18S	N82D (1 N8211	Youngstown Airways/ Lease Air, Youngstown OH Minneapolis Lakers Basketball Corp, Minneapolis MN Marshfield Airways Inc, Marshfield WI op: Midstate Air Commuter/ MAC Airlines, Marshfield WI landed gear-up Fond du Lac WI Lake Geneva Airways, Lake Geneva WI Stockert Flying Service, South Bend IN nosed over in snowbank landing, Elyria OH	23.4.67 69/73 23.9.74/76 3.12.74
			struck-off USCR derelict in scrapyard, DuPage IL	27.5.76 91
	N8211 no	ted Chicago-(	D'Hare 2.68 Midstate Air Commuter;	
	N8211 no N8211 no	ted O'Hare 18 ted O'Hare 4.	3.5.70 Lake Geneva AW; 71 "Lake Geneva Airways" titles, tailwheel; 3.7.71, 30.4.72 no titles;	
	N8211 ac	cident report :	eva WI 3.8.73, Lake Geneva Airways; 3.12.74: Stockert Aviation: South Bend IN to Elyria, 11.55pr scrapyard DuPage IL 7.91;	n;
BA-128	E18S	N45N (1	Topeka Aircraft Sales & Service	7.2.56
		,	C. E. Brehm Drilling & Producing Co, Mt Vernon IL	5.7.56/79
			Niles Airways	16.3.79/80
		N977RB	op: General Aviation Inc, Greenville TN Niles Airways	80 3.80
			William Jackson	3.6.80/81
			Hector Rocha & Vanessa Rocha Gandara,	
			Brownsville TX	22.1.82/86
			(cockpit door installed 5.86, cargo floor 4.87)	40.0.00/07
			Mario E. Britt & John J. Singer, Brownsville TX Air America Freight Inc, Reno NV	10.6.86/87 17.4.87
		N9187W	Air America Freight Inc, Reno NV	7.6.87/89
			Aerospace Products Inc, North Hollywood CA	3.3.89
			sold to Canada, struck-off USCR	20.3.89
		C-FSAO	Summit Air Charters Ltd, Atlin BC	28.4.89/96
			crashed, landing Atlin BC	28.7.92 7.96
			struck-off Register	7.90
BA-129	E18S	N54C (2	Pittsburgh Consolidation Coal, Pittsburgh PA	63/66
		N5402	Mid Continent Airlines, Morris IL	69/70
			Norbert F. Ogorek, Naperville IL	4.2.74/79
			struck-off USCR stripped hulk stored Pontiac MI	19.12.79 97/00
			Supped fulk stored Fondac Mi	97700
			II 2.97 stripped hulk;	
		ted Pontiac M ted Pontiac M	II 3.3.97; II 2.98 fuselage only;	
			Il 23.7.00 derelict, plate BA-129 built 2.56;	
BA-130	E18S	N28V	J. R. Gray Co, Dallas TX: CofA issued	10.2.56
			J. R. Gray/ Executive Air Transportation, Dallas TX	13.3.56
			Joe Fetchell/ Western Services Inc/	
			Western Hatcheries of Waco/	14 2 56/72
			Western Hatcheries of Waco/ Poultry Improvement Agency Inc, Dallas TX	14.3.56/73 1 3 73
			Western Hatcheries of Waco/	14.3.56/73 1.3.73 24.7.73/75
			Western Hatcheries of Waco/ Poultry Improvement Agency Inc, Dallas TX The Catholic Foundation	1.3.73
			Western Hatcheries of Waco/ Poultry Improvement Agency Inc, Dallas TX The Catholic Foundation Gibbes Lease-Air Inc Berg Aviation Ltd Ronald Ruble	1.3.73 24.7.73/75
			Western Hatcheries of Waco/ Poultry Improvement Agency Inc, Dallas TX The Catholic Foundation Gibbes Lease-Air Inc Berg Aviation Ltd Ronald Ruble (cargo door installed 6.77)	1.3.73 24.7.73/75 13.3.75/76 10.76/77
			Western Hatcheries of Waco/ Poultry Improvement Agency Inc, Dallas TX The Catholic Foundation Gibbes Lease-Air Inc Berg Aviation Ltd Ronald Ruble (cargo door installed 6.77) Aero American Aviation, Chicago IL	1.3.73 24.7.73/75 13.3.75/76 10.76/77 29.8.77/78
			Western Hatcheries of Waco/ Poultry Improvement Agency Inc, Dallas TX The Catholic Foundation Gibbes Lease-Air Inc Berg Aviation Ltd Ronald Ruble (cargo door installed 6.77) Aero American Aviation, Chicago IL Royal Air Freight, Pontiac MI	1.3.73 24.7.73/75 13.3.75/76 10.76/77 29.8.77/78 24.7.78/95
			Western Hatcheries of Waco/ Poultry Improvement Agency Inc, Dallas TX The Catholic Foundation Gibbes Lease-Air Inc Berg Aviation Ltd Ronald Ruble (cargo door installed 6.77) Aero American Aviation, Chicago IL Royal Air Freight, Pontiac MI Tol Air Services, San Juan, Purto Rico	1.3.73 24.7.73/75 13.3.75/76 10.76/77 29.8.77/78
		N728T	Western Hatcheries of Waco/ Poultry Improvement Agency Inc, Dallas TX The Catholic Foundation Gibbes Lease-Air Inc Berg Aviation Ltd Ronald Ruble (cargo door installed 6.77) Aero American Aviation, Chicago IL Royal Air Freight, Pontiac MI	1.3.73 24.7.73/75 13.3.75/76 10.76/77 29.8.77/78 24.7.78/95 18.5.95/99

N28V noted Dallas-Love TX 2.10.71, 1.5.73; N28V noted Pontiac MI 7.91 at Royal Air ramp; N28V noted St Croix USVI 1.98 "Tol Air"; N28V noted San Juan PR 16.6.00 all metallic, op by Tolair; N728T noted Opa Locka FL 4.11.04; N728T noted San Juan PR 24.6.05 all metallic, tailwheel, op by Tolair; N728T noted San Juan PR 26.2.06 all metallic no windows, i/s; N728T noted San Juan PR 2.2.08 all metallic no windows, i/s; N728T photo in service Tol Air at Puerto Rico 5.10, all metallic, windows faired over;

BA-131	E18S	CF-IKM	R. J. McFarland Construction Co, Picton ONT	22.2.56/63
	-9600		Carl Millard Ltd/ Millardair Ltd, Toronto-Malton ONT	3.9.63/67
			Hicks & Lawrence Ltd, St Thomas ONT	27.6.67/72
			Voyageur Airways Ltd, North Bay ONT	6.72
			Bradley Air Services Ltd, Carp ONT	6.73/78
			undercarriage collapsed landing Ottawa ONT	17.12.73
			slid off runway on takeoff, struck snow bank, Carp ONT	30.11.75
			not repaired, struck-off Register	22.9.78
			(CF-IKM wreck stored at Carp ONT 78)	
			(cabin roof from rivet line beneath windows removed and	
			installed in TC-45J Westwind III C-GBLI/6323 by Buckeye	
			for Interflite Aviation Service for increased freight	
			capacity)	

CF-IKM visited Toronto ONT 23.4.64; CF-IKM noted Indianapolis IN 5.68 reported as Hicks & Lawrence, no titles, tailwheel; CF-IKM noted Carp ONT 24.8.74 Voyageur Airways; CF-IKM noted Carp ONT 12.8.78, damaged, derelict, Bradley AS; further details of grafting of cabin: see Beech 18 by Parmerter p. 345;

BA-132	E18S	N3611F	Aircraftsmen Inc, Oklahoma City OK	2.3.56
	-9700		R. H. Fulton & Co	5.3.56/61
			minor damage landing, Helena MT	10.7.60
			Wiles-Holloway Inc, Baton Rouge LA	14.8.61/64
			Louisiana Dept. of Highways	24.1.64
			Louisiana Television Broadcasting Corp,	
			Baton Rouge LA	31.7.64
		N362M	Louisiana Television Broadcasting Corp	23.9.65/70
			Wiles-Holloway Inc, Baton Rouge LA	1.12.70/71
			sold to Iceland: struck-off USCR	3.71
		TF-FHM	Landflug, Reykjavik	4.71.73
		TF-JMB	Nordurflug, Reykjavik	5.73
			Flugfelag Norourlands, Akureyri	.75/76
		TF-EBB	Flugstoedin HF, Reykjavik	8.77/78
			sold to USA: struck-off Icelandic Register	9.11.78
			(TF-EBB delivered Reykjavik-Philadelphia PA 6-8.11.78)	
		N90276	Frank Cannavo/ Aero Taxi, Philadelphia PA	11.78/79
			(US CofA renewed 19.4.79)	
			Robert Avery/ Rancho Perdido, Devine TX	19.6.79/91
			- -	
	TF-JMB n	oted Reykjav	ik 20.5.77;	
	TF-EBB n	oted Reykjav	ik 19.6.78 no titles;	

BA-133	E18S	N42A	built	.56
			E. I. duPont de Nemours & Co, Wilmington DE	59
			Atlantic Aviation Service, Philadelphia PA	63/70
			Sebastino Cannavo/ Aero Taxi, Philadelphia PA	28.9.70/72
			op: Quaker City Airways	72
			left wing failed & folded up in flight, crashed,	
			destroyed by fire, Cleveland OH	22.6.72
	- · · · · · - ·			

crash report 22.6.72 Cleveland OH: operator Aero Taxi;

NTSB report 22.6.72: operator Quaker City Airways, flight Philadelphia to Rockford IL, pilot k;

BA-134	E18S trigear	N99L N699JG N299JD N2993D N1131T	built Travel Leasing Co, San Bernardino CA Juanita Daly, Las Vegas NV Fletcher Aircraft Leasing Corp, Houston TX <i>unconf.</i> Fletcher Aircraft Leasing Corp, Bellaire TX Harry W. Nichoalds, Boulder CO struck-off USCR	.56 63/64 66 69/70 72 21.11.74/75 13.3.75
			A 10.57, "Les Cal" emblem; tailwheel; s CA 19.8.72;	
BA-135	E18S	N43A N2000H (2 N2000R N218A	Chalmers & Barton Construction Co Chalmers & Barton Construction Co rereg Business Counselors Inc, Salina KS Hamilton Airport Inc, Hamilton OH Hamilton Aviation Inc, Hamilton OH struck vehicle during forced landing off runway, Fort Campbell KY struck-off USCR	59 12.2.59 63/64 66/70 16.9.70/76 13.1.76 17.5.76
			Hamilton Aviation, mail flight Louisville KY to Paducah TN, bell air base, landed off runway hit alert truck, 3.50am, pilo	
BA-136	E18S trigear G18S cab	N19X N402FW	Hawthorne Metal Products Co, Royal Oak MI Page Airways, Rochester NY (G18S cabin mod. installed) Page Airways, Rochester NY Rolair Corp/ Wright Air Lines, Cleveland OH Burlington Airways, Burlington WI crashed on landing, gear collapsed, Burlington WI Blackhawk Airways, Janesville WI (damaged) (trucked damaged to Janesville: cabin roof, cargo doors & G18S cab of N402FW fitted .78 to Westwind III C-45H N35136/AF-629 by Blackhawk Airways, Janesville WI)	63/64 66 69/72 15.6.73/75 25.7.75 75/79
	N402FW o N402FW a	ccident repor	r p.334, 339; appears leased fleet to Wright Airlines, Cleveland; t 25.7.75: flight Janesville Wi to Burlington, fuel mismanag bach to Burlington, forced landed on airport,	ement,
BA-137	E18S	N17T	reg Francis Aviation, Lansing MI struck-off USCR	.56 25.5.59/72 21.1.72
BA-138	E18S -9700 trigear	N198B	Butler Co/ Butler Airplane Sales Structo Manufacturing Co International Steel Co, Evansville IN (Volpar Mk.IV trigear & two-piece windshield installed 3.64)	17.3.56 10.56/60 10.8.60/73
			Charles M. Booth/ Goco Inc Lily F. Browne, Melbourne FL Intercontinental Association Inc, Cocoa Beach FL: sale documentation not completed crashed destroyed after takeoff, Orlando FL	16.5.73/76 27.8.76/79 .79 22.12.79
			no operator quoted: passenger flight Orlando-Herndon to er 12.40am, destroyed, pilot & 3 pax k;	
BA-139	E18S	N43D (1	Anderson Air Activities Lake Shore Inc, Iron Mountain MI Nelson M. Robinson, DeKalb IL	23.3.56/61 5.7.56/62 6.2.62
	trigear	N503W (2	Capitol Aviation Inc, Springfield IL (Volpar trigear installed 11.62) S. J. Groves & Sons Co, Minneapolis MN	13.8.62 11.62/68

N563W	Flite Training Center Bayou Transit Inc, St. Louis MO	11.68/69 69
	Williams Patent Crusher & Pulverizer Co, St Louis MO	15.5.70/72
	Malcolm Jacobs Aviation (agents)	15.5.72
	sold to Canada, struck-off USCR	7.72
CF-DCC	Sud Aviation Canada, St Jean Crysostome QUE	2.8.72/74
	J. Wright Enterprises Ltd, Edmonton ALTA	4.4.75/78
	lsd: Newfoundland & Labrador Air Transport,	
	Corner Brook NFLD	18.9.75/76
	Isd: International Forest Fire Systems Ltd, Calgary ALTA (modified with fire spotter window 5.76)	14.5.76/78
	crashed ran off runway landing, Abbotsford BC (ferry permit 2.78 Abbotsford-Vancouver BC)	27.9.77
	William Kostich, Clarkston MI	6.9.78
	(CF-DCC ferry permit 9.78 Vancouver to US)	0.0.70
N563W	Royal Air Freight, Pontiac MI	28.9.78/90
1100077	(stored Pontiac .78/84: Royal planned rest. to fly .84)	20.0.10/30
	crashed & burned on takeoff, Greenwood SC	9.8.90
	clashed & burned on takeon, Greenwood SC	3.0.30

N503W noted Washington-DCA 8.5.64 Groves; N563W noted Pontiac MI 9.80 trigear; N563W reported entered service with Royal Air Freight late 84;

BA-140	E18S	N65B	Beech Aircraft Corp, Wichita KS: CofA issued	11.4.56
			Elliot Flying Service	27.8.56
			Gardner-Denver Co, Quincy IL	27.8.56/59
			(mods to E18S-9700 by Remmert-Werner Inc,	
	-9700		St Louis MO .56)	
		N165GD	Gardner-Denver Co, Quincy IL	12.59/65
			Topeka Aircraft Sales & Service, Topeka KS	12.65/66
		N165G	Topeka Aircraft Sales & Service, Topeka KS	5.5.66
	trigear		(Volpar Mk.IV trigear & G18S type two-piece	
			windshield installed 12.66)	
			Atlas Tool and Manufacturing Co, St Louis MO	12.66/69
			James O. Holton/ L & H Co, Jackson Hole WY	8.11.69/71
			Air Travel Inc	11.71/72
			L & H Co, St Louis MO	72
		N611CW	Air Travel Inc	21.3.72/76
			Southernaire Inc, Chattanooga TN	22.5.76/77
			National Aviation Underwriters, Atlanta GA	.77
			Odesa Inc: sale documentation not completed	.78
3A-141	E18S	N72SF	J. P. Stevens & Co, New York NY	56/61
			Mele Manufacturing Co, Richmond Hill NY	63/70
			Utica Mutual Insurance Co, Utica NY	72/78
			Robert F. Dorsey, Athens TX	78
			Fredrico L. Cantu, Brownsville TX	3.10.78/82
			struck-off USCR	23.8.82
	photo sho	ows N72SF. N	73SF, N74SF, N75SF & N176SF in row at Wallace NC	4.61. all
			Stevens & Co;	- ) -
			lle TX 8.5.79 in service;	
	-		-	
BA-142	E18S	N83D (1	Youngstown Airways/ Lease Air, Youngstown OH	
		N8311	Capitol Aviation, Springfield IL	63
			Weston Paper & Manufacturing Co, Dayton OH	64/72
			Gifford Aviation, Anchorage AK	23.1.75/76
			ditched in sea after takeoff, sank, Kodiak AK	22.5.76
		ccident report: n water, 2 unh	Gifford Aviation: flight Kodiak to Anchorage, engine faile urt;	ed on takeoff, force
34-143	F185	N31M	Ishell Construction Co. Phoenix A7	63

BA-143	E18S	N31M	Isbell Construction Co, Phoenix AZ	63	
	-9700		Union Rock & Materials Corp, Phoenix AZ	64	
			Arizona Highway Patrol, Phoenix AZ	66/69	
			Cutter Beechcraft Inc, El Paso TX	70	

	reg. pending, Albuquerque NM	72
	K & K Aircraft, Bridgewater VA	79
	Morey Wyman/ Wyman Pilot Service, Pontiac MI	2.86
	Majestic Airlines, Salt Lake City UT	10.8.87/95
	sold to Canada, struck-off USCR	5.10.95
C-FCLO	Enterprise Air Inc, Oshawa ONT	25.1.96/17

C-FCLO noted Oshawa ONT 9.96 & 6.98, 17.8.03, 17.4.04: all Enterprise Air: 4.04 report states that the company uses DC-3s and CLO on freight work for car industry; C-FCLO noted Toronto-Downsview 17.4.04 in service with Enterprise Air Inc; C-FCLO noted Oshawa ONT 15.5.05, 24.6.05, 24.6.06 no titles, tailwheel, in service;

BA-144	E18S	N65V	Texas Gulf Producing Co, Houston TX	63/64
			Michigan Bank Association, Detroit MI	66/69
	trigear		reg. pending: USCR	70
			Kingery Drilling Co, Saint Jo TX	72
			Tampa Air Centre Inc, Tampa FL	28.3.78/80
			struck towers, forced landing off-airport, crashed	
			destroyed by fire, Gainesville FL	24.10.80

N65V noted Tampa FL 11.4.79 trigear;

N65V accident report 24.10.80: Tampa Air Centre: pax flight Bartow FL to Lake City FL, 1 engine mechanical failure, forced landing in fog 9.47am, pilot & 2 pax k;

BA-145	E18S	N575Q	J. D. Reed Co, Houston TX: CofA issued	23.4.56
	trigear		Quintana Petroleum Corp	25.4.56/58
			Southern Airways Co	12.58/60
		N1906L	Special Services Corp	29.3.60
			Martha White Mills Inc, Nashville TN	4.6.60/64
		N233MW	Martha White Mills Inc, Nashville TN	29.1.64/68
		N263MW	Martha White Mills Inc, Nashville TN	7.68
			Cousins Properties Inc, Atlanta GA	12.68/69
			Omni Investment Corp, Washington DC	15.9.69
			Sherman Aircraft Sales, West Palm Beach FL	17.9.69/70
			Continental Aero Space Corp, Ft Lauderdale FL	28.4.70/71
			Sherman Aircraft Sales, West Palm Beach FL	1.9.71
		N263VG	Tamboo Aviation, Palm Beach FL	11.71/72
			Lucille Quattlebaum/ L. G. Equipment Co	11.72/73
			BTR Enterprises Inc/ Johnny Bolton Aircraft	7.9.73/74
			L T D Development Inc	22.4.74/75
			Rich Ice Cream Co	17.3.75
		(N263JF)	ntu: Jerry Fairbanks Productions	5.12.75
		N263VG	Jerry Fairbanks Productions, Hollywood CA	5.12.75/77
			John L. Moore, Sarasota FL	11.5.77
			R. A. Johnson: documentation not completed	.77
			•	

N263MW noted Ft Lauderdale FL 28.9.70 trigear;

	E400	NAOT	Atlantia Aviatian Orma OrfA issued	04.4.50
	XB-ZEE I	noted Mexico C	City 25.4.66 trigear;	
			struck-off USCR	9.7.13
			G. R. Lowe, Clinton MO	14.1.78/13
			Aamtax Corp	18.3.77/78
			Herbert E. Guynn, St. Petersburg FL	18.3.77
			Tampa Air Centre, Tampa FL	23.8.73/77
			Patrick J. Horrington/ Horrington Bonding Co	18.3.72/73
			Silver Enterprises Inc, Charleston WV	14.8.70/72
			District Equipment Co, Decatur GA	6.3.68/70
		N14610	Southern Airways Co, Orlando FL	10.10.67
	trigear	XB-ZEE (2	The Coca Cola Export Corp	.65/67
		N606S	Coca Cola Co/ Minute Maid Co	64/65
		N404C	Trippeer Organizations Inc, Memphis TN	63
3A-146	E18S	N40DC (1	built	.56

BA-147	E18S	N19T	Atlantic Aviation Corp: CofA issued	24.4.56
	-9700		Wayfarer Ketch Corp	1.5.56/60

Nelson A. & David Rockefeller, New York NY Cornell University, Ithica NY Colgan Airways Corp, Manassas VA Aero Leasing Inc	6.60/67 10.3.67/70 21.3.70/73 28.9.73/78
Midwest Air Charter, Elyria OH: leased	5.10.73/78
(Hamilton cockpit door installed 11.77)	70
op: Airborne Express	78
Youngstown Executive Beechcraft Inc, Jackson OH	14.4.78
Executive Air Express	4.79/80
Wolverine Air Charter	3.12.80/81
Ajax Aircraft Leasing Inc, Dover DE	11.81/82
Raul Mireless, McAllen TX	8.6.82/83
SmithAir Inc, Sharpsburg GA	26.3.83/85
op: Airborne Express, Wilmington OH	85
destroyed, struck on runway by landing USAF F-4,	
Birmingham AL	20.6.85

N19T noted Washington-DCA 30.9.70; N19T noted Willow Run MI 14.7.81; accident report 20.6.85: op SmithAir Inc on a Airborne Express cargo flight, lined up on runway then overlooked by Tower controller who cleared F-4 to land, Beech destroyed;

BA-148	E18S	N98B	Piedmont Aviation, Winston Salem NC	12.7.56
	-9700		Hennis Freight Lines	12.7.56/63
		N751H	Hennis Freight Lines	15.4.63
			Piedmont Aviation, Winston Salem NC	7.5.63
			Joseph I. O'Neill, Midland TX	10.63/65
			M. W. Branum, Midland TX	11.65/74
			Farmington Airmotive, Farmington MO	10.74/82
			(pilot cockpit door installed 7.78)	
			Festus Flying Service, Festus MO	17.9.82/84
			HoganAir Inc, Hamilton OH	8.2.84
		N95HA	HoganAir Inc, Hamilton OH	8.5.84/85
			crashed destroyed on takeoff, Huntington WV	31.1.85
			struck-off USCR	9.85
			South West Aero Exchange, Owasso OK	00
			(wreck dismantled in salvage yard, Owasso OK 00)	

N751H noted Sr Louis MO 2.6.76; N95HA fuselage and detached tailplane noted in SW Aero Exchange yard Owasso OK 10.8.00;

BA-149	E18S	N82B	Narmid Inc, Lubbock TX	63
			Jack Adams Aircraft Sales, Walls MS	64
	Volpar		Volitan Aviation, Pacoima CA	66
	Super		(converted c65 to the 2nd Volpar Super Turbo 18,	
	Turbo 18		with AiResearch TPE-331-25 turbines)	
			Imperial Commuter Airlines, Imperial CA	29.11.67/68
			crashed destroyed on takeoff, San Diego CA	8.1.68

further details, see Beech 18 by Robert Parmerter p.386; N82B noted San Diego CA 14.9.67 Imperial Commuter AL, turbine trigear; crash 8.1.68 3 k; Visco Flying Co operated third level service Imperial CA to Blythe CA 68, renamed

Imperi	al Commuter Airlines by 69;		
1	· · · · · · · · · · · · · · · · · · ·		

BA-150	E18S	N32M	Gerald C. Francis/ Francis Aviation, Lansing MI	30.4.56
	-9600		Howard Sober Inc	30.4.56/60
			Francis Aviation, Lansing MI	11.4.60/70
			MacGillivray Buick Co, Swartz Creek MI	13.4.70/73
			Donald A. Paolucci, Cleveland OH	28.9.73/94
			(cargo door installed 5.74)	
			op: Mohican Air Service, Cleveland OH	79/84
			Piedmont Air Cargo, Gastonia NC	17.3.94/95
			Kestrel Inc, Waukee IA	31.3.98/16
			reg. expired 30.11.16, struck-off USCR	13.3.18

Mohican Air Service was owned by Don Paolucci, who purchased the airfield at Wakeman OH in 1981, still there 2007. Mohican had 2 DC-3s, 2 Convairs and Beech 18s including a turbine version.

N32M noted Oskaloosa IA 24.7.98 in service, freighter owned Kestrel Inc, old titles Piedmont Air Cargo readable through paint, plate: BA-150 built 4.56; another plate: Aerospace Products spar kit 156 to 9600 lbs 18.12.61; N32M noted Oskaloosa IA 25.7.99 parked in same position, props & flaps removed: owned Bill Chase of Kestrel Inc: paperwork in aircraft gave CofR issued 1.8.56, ownership change 22.6.94 to Piedmont;

BA-151	E18S	N23T	Alamo Aviation, San Antonio TX: CofA issued	27.4.56
			B. L. McFarland Inc, Midland TX	1.5.56/63
			Rich-Air Co, Midland TX	4.10.63/64
			E. C. Johnston, Longview TX	17.1.64/75
			(two-piece G18S type windshield installed 8.65,	
			picture windows installed 10.65)	
			Rich-Air Co	27.2.75/76
			San Angelo Flight Service Inc	5.4.76/77
			Albert W. Long/Long Construction Co/	
				2.78/81
			D'Arlee Inc. McAllen TX	22.5.81
			(FAA report 5.81: ficticious address)	
			picture windows installed 10.65) Rich-Air Co San Angelo Flight Service Inc Albert W. Long/Long Construction Co/ Kanga Exporting Inc, Cocoa FL D'Arlee Inc, McAllen TX	5.4.76/77 2.78/81

N23T noted St Thomas USVI 30.4.78;

BA-152	E18S	(N32R)	ntu: J. D. Reed Co, Houston TX	3.56
	-9700	N33JD (1	J. D. Reed Co, Houston TX	11.5.56
		N330LL	J. D. Reed Co, Houston TX	11.56/57
			Northern Electric Co, Chicago IL	28.5.57
		N330N	Northern Electric Co, Chicago IL	12.9.57/65
	trigear		(Volpar tricycle gear installed 4.65,	
			picture windows installed 5.65)	
			Wells Stewart, Houston TX	22.9.65/68
			Fiber Controls Corp	26.1.69
			Carolina Fleets Inc, Anderson SC	21.2.69/71
		N116FC	Carolina Fleets Inc, Anderson SC	27.1.71/72
			damaged, struck trees, Tocca GA	29.1.72
			Malcolm Jacobs Aviation	12.8.72
			sold to Canada, struck-off USCR	10.72
		CF-FSB	Commuter Air Services Ltd, Quebec QUE	10.72/
			(ferry permit St Louis MO to Montreal 10.72, CofA 30.1	1.72)
			Sud Aviation Canada Ltd, St Jean Crysostome QUE	4.73
			J. Wright Enterprises Ltd, Edmonton ALTA	4.75
			International Forest Fire Systems Ltd, Calgary ALTA	4.76
			Patricia Air Transport Ltd, Sioux Lookout ONT	11.77
			Skycraft Air Transport Ltd, Oshawa ONT	4.78
			Pacific Coastal Airines Ltd, Nanaimo BC	5.78
			Labrador Airways, Goose Bay LAB	7.78
			sold to USA, struck-off Canadian Register	20.10.78
		N9013Y	Tobey Inc, Simsbury CT	10.78/80
			(aircraft in full cargo configuration by 11.78)	
			Lawrence E. Dietrich/ Gateway Associates	18.1.80/81
		N75BC	op: Bahamas Caribbean Airlines	81
		N9013Y	Astro Airways Corp, Pine Bluff AR	11.81/82
			Goodner Bros Aircraft Inc, Mena AR	1.82
			Mid-South Aircraft Sales, Memphis TN	4.1.82/84
			Allen Godwin, Memphis TN	.84
			Schindler Energy Inc, Columbus TX	11.7.84/13
			struck-off USCR	12.9.13

N9013Y noted Hartford CT 21.6.79;

N75BC noted Mena AR 14.3.81 trigear, "Bahamas Caribbean Airlines" titles, good condition;

BA-153	E18S	N47A	Andre J. Andreoli, Akron OH	63/64
	trigear		Ohio University, Athens OH	66

Southwestern Skyways Inc, Albuquerque NM	69
Distribute Aire Inc, Albuquerque NM	70
Florida Communities Sales Inc, Beachwood OH	23.12.70/71
crashed, destroyed landing in fog, Columbia SC	26.2.71

accident report 26.2.71: Volpar E18S: hit ground during missed approach in poor weather, 8k;

BA-154	E18S	N48W (1	Tulsair Distributors Inc, Tulsa OK	16.5.56
	-9700		Norango Inc	16.5.56/57
			Flight Service Inc	30.1.57/58
			The Ridge Tool Co	26.1.59/60
			(modified 5.59 to E18S-9700)	
			Hanover Shoe Farms Inc, Hanover PA	6.5.60/64
	PacAero		Pacific Airmotive Corp, Burbank CA	28.9.64
	Turbo	N6651R (2	Pacific Airmotive Corp, Burbank CA	11.64/67
	Tradewind		(converted by PacAero to Turbo Tradewind with	
			PT-6A-6s, Volpar trigear, single fin: flight testing 10.65,	
			completed 25.7.66)	
			Continental Air Services, Laos	66
			Boun Oum Airways, Laos	
			Ken Air Inc	4.10.67
		B-1530	China Airlines, Taipei	4.10.67/73
		N40AP	Sizer Airways, Rochester MN	18.6.73
			Aveneles Aviation, Las Vegas NV	28.6.74/76
			(cargo floor & cabin cargo door installed 9.75,	
			cockpit door installed 1.76)	
		N25SM	Aveneles Aviation, Las Vegas NV	27.2.76/78
			Oliver Smith/ Umiat Enterprises, Van Nuys CA	10.78/79
			(op. as Alaska Umiat Enterprises)	
			Union Flights, Sacramento CA	2.4.79/91
			Ministic Air Ltd, Winnipeg MAN	29.4.91
			sold to Canada, struck-off USCR	1.5.91
		C-FRGT	Ministic Air Ltd, Winnipeg MAN	14.5.91/00
			undershot on landing approach, crashed on frozen lake,	
			Little Grand Rapids MAN	5.2.92
			K & K Aircraft Inc, Bridgewater VA	.92/98
			(salvaged ex lake crash site by K&K, stored at	
			Bridgewater for spares use)	

This aircraft? or possibly Tradewind AF-831/N9981Z/HS-SKA?

- In early 1967, CIA was preparing a programme of surveillance of the Ho Chi Minh Trail: Air America planned to use its Volpar Turbo 18s, also bidding for the contract was Boun Oum Airways (BOA) owned by Laotian prince Boun Oum: since 1965 BOA had expanded when Continental Air Service (CASI) loaned it 2 PA18s, 2 C-47s, a second Dornier Do28 and a Beech Tradewind conversion: none of BOA's aircraft carried any airline logo and aircraft and their

Thai pilots were integrated with CASI by early 1967;

- As part of the overall shift of CIA paramilitary programmes to the US Dept of Defense, covert operations in Vietnam were turned over to a new Saigon-based Special Operations Group (SOG) controlled by the Pentagon from January 1964. Under SOG, infiltratiion missions into North Vietnam were to continue, using Chinese Air Force C-123Bs with ECM gear flown by Chinese and SVNAF crews, plus C-46s. From 1966 two unmarked China Airlines aircraft, a C-47 & Beech C-45 plus crews, were contracted by SOG for flights within South Vietnam. The C-45 was used primarily by

the SOG commander and other senior personnel. The following year the C-45 was found to be unairworthy and was replaced by a modified PAC Tradewind effective 1.9.67;

- In June 1971 the Tradewind had been replaced by a C-46, which was used for SOG passenger flights. The C-46 hit a mountain 5.6.72 in Central Highlands, killing 11 Americans,1 South Vietnamese and 6 Chinese. After this, the remaining CAL crew returned to Taiwan, bringing to an

end this secret chapter of Republic of China participation in the Vietnam War;

- Parmerter p.375: "The prototype Tradewind N9981Z was operating in SE Asia in late 1966 for Continental Air Services Inc, then with Boun Oum Airways (owned by Laotian Prince Boun Oum)

then then for Sahakol Air in Thailand as HS-SKA. Its fate is unknown".

- photo of B-1530 in Taiwan: Tradewind single tail, trigear, E18S type fuselage, 4 square cabin windows: by 1979 N25SM had middle two windows extended to one long vista window + 2 standard windows;

N6651R noted Burbank 6.5.66, N6651R noted Burbank CA 6.8.66 Turbo Tradewind, plate BA-154; N25SM noted Bakersfield Air Park CA 8.76 Trigear Turbo Tradewind, plate BA-154; N25SM noted Mojave CA 8.76 Turbo Tradewind; N25SM noted Van Nuys CA 18.10.78 Tradewind; N25SM photo (no date) in Alaska (looks like Fairbanks:GG) Turbo Tradewind trigear "Umiat Alaska - Umiat Enterprises" titles above windows; N25SM photo with titles "Alaska Umiat Enterprises";

BA-155	E18S	N48M	Ohio Aviation Co, Dayton OH	9.5.56
			Ohio Oil Co, Findlay OH	25.5.56/62
			Marathon Oil Co	23.8.62/63
			Ohio Aviation Co, Dayton Airport OH	63
			Broughton Plant & Equipment Co	11.63/66
			Ohio Aviation Co, Dayton Airport OH	7.66/72
			Van Dusen Acceptance Corp, Minneapolis MN	12.6.72/74
			Woods-Tucker Leasing Corp	15.7.74/75
		NASA948	NASA: leased	.74/75
			(NASA sensors, extended nose, cargo floor &	
			cockpit door installed 9.74)	
	Hamilton	N48M	Gordon B. Hamilton/ Hamilton Aircraft Co, Tucson AZ	10.75/76
	extended		Edward West/ American Turbine Aircraft Corp	.76/77
	nose		Hamilton Aviation Co, Tucson AZ	.77/80
			NASA, Space Technology Laboratories	19.5.80/81
			State of Louisiana, Dept. of Natural Resources,	
			Baton Rouge LA	12.3.81/88
			Hilderbrand Aero Service	2.2.88/89
			Thomas W. May/ May Air Xpress, New Boston TX	22.8.89/95
			crashed De Witt AR	27.9.96
			Springdale Air Services, Springdale AR	13.7.98/99
			Paul F. Amidon, Avondale AZ, later Lakespur CO	26.2.01/13
			Bill L. Rogers, Mukilteo WA	10.5.13/16
			William E. Garrison, Nickerson KS	7.9.16/20

NASA948: see Beech 18 by Robert Parmerter p.372; NASA943 noted Tucson AZ 20.11.75: probably mislogging of this aircraft? photo no date or place: NASA 948 & N48M painted on, NASA scheme, long nose, "Earth Resources Labortatory" above windows; N48M noted Texarkana TX 7.97, 8.97 May Air Xpress: plate BA-155 built 5.56: long nose; N48M Springdale AR 16.8.99 long nose "Springdale Air Service" & "May Air Xpress" titles;

N48M noted Phoenix-Goodyear Municiple AZ 24.12.00, tatty, tailwheel, fitted with nose section from a different aircraft;

BA-156	E18S	N39GB	Southern Airways Co: CofA issued	17.5.56
	-9700		Greene Brothers Lumber Co	21.5.56/62
		N11827 (3	Southern Natural Gas Co, Birmingham AL	12.62/66
		N1182T	Southern Natural Gas Co, Birmingham AL	11.66/67
		N4980V	Kieran Construction Co, Birmingham AL	12.1.67/72
			E L A Corp	20.6.72/73
			Tampa Air Center Inc, Tampa FL	21.2.73/78
			Air Continental Flying Association Inc	21.7.78/82
			(Aerospace Products cargo door installed 9.78)	
			Robert W. Metz, Sacramento CA	12.6.82/86
			engine fire during parachuting flight, Davis CA,	
			landed safely without airframe damage	16.4.83
			Aerospace Products Inc, North Hollywood CA	20.1.86
			Springdale Air Service, Springdale AR	2.86/99
			ground collision with Springdale AS E18S N2069C	
			on taxiway at UPS cargo ramp, Dalls-FTW TX	29.12.97
			Bush Air Inc, Wilmington DE	12.2.01/13

reg expired 30.9.13, struck-off USCR

N4980V noted California City CA 9.83 plate BA-156; N4980V noted Springdale AR 8.97 Springdale Air Service: plate BA-156 built 5.56, another plate: converted to E18S-9700 2.63; N4980V noted Springdale AR 13.10.97; N4980V noted Texarkana AR 6.8.98 Springdale AS, departed on freight flight to Shreveport-Dallas-Springdale AR; N4980V noted Springdale AR 16.8.99 Springdale AS; N4980V noted Ft Lauderdale Exec FL 4.4.01;

BA-157	E18S	N26T	Baggett Transportation Co, Birmingham AL	.56/69
	ATE		(converted to American Turbine Engine Co ATE Westw	ind I:
	Westwind I		PT6A turbines, trigear, completed 4.69)	
	trigear	N2699	Thunderbolt Land & Cattle Co, Houston TX	.69/72
	U U	N111EL	Air Transport Corp/ E&L Truck Rental, Dearborn MI	14.6.74/77
	Hamilton		(rebuilt as Hamilton Westwind III with tail gear,	
	Westwind II	I	extended nose by Hamilton Aviation at Tucson AZ)	
	tailwheel		exported to Colombia, struck-off USCR	2.77
		HK-1111 (1	Aerolineas Especiales de Colombia Ltda-	
			AE Colombia, Bogota-Eldorado	.76/78

HK-1111 noted Opa Locka FL 1.77 "A E Colombia" titles, Westwind III tailwheel (photo confirms no "G" suffix") HK-1111G noted Opa Locka FL 30.3.77 AEC, Turbo Westwind; HK-1111 noted Tucson AZ 4.6.80 rep as BA-77 trigear turbine, AE Colombia scheme but no titles; HK-1111 noted Tucson AZ 28.10.80 reported as BA-77 Hamilton HA-1 Aerolineas Especiales freighter, converted from E18S in 4.80; HK-1111 noted Tucson 5.11.81 rep as BA-77 Aerolineas Especiales; HK-1111 noted Tucson 9.11.81 (GG) trigear "AE";

N111EL BA-157 on USCR 1991 printout (with many other long deleted BE18s): Air Transport Corp

Above is Parmerter's version (12/06) but HK-1111 was a trigear by 1980!!!!!!!! Probably HK-1111(2 was BA-77;

	E18S	N38M	Andrew Schwartz, Chicago IL	63/64			
	-9700		(converted 8.59 by Graubart Aviation: various mods,				
	Graubart		enlarged cabin windows; trigear installed 63)				
	Aviation		(displ. at Paris Air Show 6.63 as Graubart Trigear)				
	Trigear	D-IBEV	Battenfeld Maschinenfabrik, Meinershagen	.63/75			
			dam. landing Meinershagen, West Germany (delivered to USA via Prestwick 12.9.75 as N70DG)	2.12.64			
		N70DG	reg	12.75			
			gear collapsed landing, Chicago-DuPage IL	26.10.76			
			M. A. Ammerman, Fort Sumner NM	8.7.77/82			
			struck-off USCR	21.5.82			
	<ul> <li>D-IBEV flew Meinershagen-Southend-Heathrow 20.1.64, Battenfield, plate BA-158;</li> <li>D-IBEV visited London-Heathrow 20.1.64 Battenfeld, visited Heathrow 4.2.64;</li> <li>D-IBEV visited Schiphol 25.2.64;</li> <li>D-IBEV arrived Sydney-Mascot 31.8.64 delivering a heavy industrial compression moulding press for a Sydney company, built by Battenfeld Machinery Co of Cologne, flown by Battenfeld pilot Captain J. H. Blumschein: white &amp; blue, trigear,</li> <li>"Battenfeld" above windows, enlarged cabin windows, airstair door: plate: BA-158 built 5.56. modified to trigear 8.59;</li> <li>100 hourly inspection at Flight Facilities, Mascot, departed Mascot 11.9.64 for Germany;</li> <li>D-IBEV noted Heathrow 11.2.66, 11.3.66, 22.6.66, 23.6.66, 30.6.66, 23.7.66, 31.7.66,</li> <li>4.8.66, 19.8.66, 3.9.66, 30.9.66, 19.10.66, 17.12.66, 18.5.67: all Battenfield;</li> <li>D-IBEV visited Yeadon 18.5.67 Battenfield;</li> </ul>						

E18S -9700 trigear	N46A (1	Atlantic Aviation Service: CofA issued E. I. duPont de Nemours & Co, Wilmington DE (Volpar tricycle gear, picture windows & G18S type two-piece windshield installed by Capital Aviation 4.65)	21.5.56 20.7.56/65
	N299Z	Dow Jones & Co/ The Wall Street Journal, Princeton NJ	24.5.65/67
		gear retracted during landing, Linden NJ	23.6.66
		J. J. Crosetti Co, Watsonville CA	27.7.67/73
		Sam L. Manatt	4.5.73/74
		S. R. Chaney	12.74/76
		Bryce Wisener, Garland TX	18.2.77/88
		William H. Wisner, Dallas TX	1.7.88/99
		J. D. Daniel, San Angelo TX	17.3.99
		Ray Johnson, Bridgeport TX	22.5.00/12
		Great Gulf Corp, Dallas TX	24.1.13
		sold to Canada, struck-off USCR	10.7.13
		(N299Z parked Brantford ONT 17/18 parts removed)	
	N299Z	Dakota Express LLC, Wilmington DE	9.7.19/20

N299Z noted Watsonville CA 23.4.72 trigear;

N299Z at Beech FlyIn, Tullahoma TN 18.10.00;

N299Z noted Mineola TX 2.8.02 rep has been based here past 20 years, reportedly recently sold; N299Z at Beech flyin Tullahoma TN 14.10.07;

N299Z nited Bratford ONT 8.17 trigear, props and panels removed, red and white; same 6.18;

BA-160	E18S	N40K	Southwest Forest Industries, Phoenix AZ	64	
			National Commerce Bank, Tulsa OK	66	
			damaged landing, cargo flight, Cheyenne WY	22.4.68	
			Ross Aviation, Tulsa-Riverside OK	68/69	
			Great Western Airlines, Tulsa-Riverside OK	28.7.69/74	
			crashed destroyed landing in snow, Cheyenne WY	12.4.74	

N40K accident report 12.4.74: Great Western, flight Riverton WY to Cheyenne to Denver CO, hit trees & pole on go-around in blowing snow, 11.46pm, pilot unhurt;

BA-161	E18S	N36V (1	J. R. Gray Co Inc, Dallas TX	29.5.56
	-9700	N3000S	J. R. Gray Co Inc, Dallas TX	11.7.56
			Roselie Shumaker	2.8.56/58
			The Hardy Corp	21.1.58/59
		N432U	The Hardy Corp	21.8.59/60
			Minne-Tex Inc	9.11.60/62
	trigear		(Volitan Aviation installed Volpar trigear 30.6.62)	
			Indiana-Michigan Corp, Chicago IL	10.5.63/65
			Jones & Lamson Machine Co: leased	10.5.63
			landed with nosewheel locked up, Boston-Logan MA	23.11.64
			Jones & Lamson Machine Co	26.7.65
			Chester County Aviation	2.8.65/66
			(G18S type two-piece windshield installed 9.65)	
			Federal Airlines/ Air North, Burlington VT	5.3.66/67
	ATE		(converted to American Turbine Engine ATE Westwind I	
	Westwind I		by American Turbine Aircraft Corp, completed 1.67:	
	trigear		type quoted in FAA file as "American Turbine 600R":	
	conv. #22		trigear, PT6A-20 turbines)	
			Varis Leasing Corp, Burlington VT	7.3.67/70
			landed gear-up, Nassau, Bahamas	12.3.69
			McCollum Aviation, Danville IL	18.3.70/71
			Connell Chevrolet Co, Killeen TX	18.2.71/72
			Dee Howard Aircraft Sales, San Antonio TX	22.6.72
			Apollo Airways, Pine Bluff AR	26.6.72/77
	Hamilton		(rebuilt as Hamilton Westwind III 3.77: tricycle gear	
	Westwind I	11	replaced by conventional tailwheel, cargo floor,	
	tailgear		Hamilton extended cargo nose, cockpit door)	
	-		Tilman E. Rosenblatt/ Baltimore Airways/	
			Baltair Cargo, Baltimore MD	25.3.77/83
			op: Pronto Aviation Services, El Paso TX	81
			-	

gear retracted on landing roll, Albuquerque NM Methow Aviation, Wenatchee WA, later Everett WA Comanche Air, Winthrop WA op: Cascade Air, Ephrata WA (stripped for parts, Ephrata WA 00	23.1.81 4.8.83/98 28.9.98/05 00
op: Jim Baron, St Charles IL for skydiving	04
ran off runway on takeoff, gear collapsed,	
skydiving ops., Tullahoma TN (10 pax unhurt)	6.9.04
(stripped fuselage on belly in trees, Tullahoma TN 06/1	4)
Jim E. Baron, St Charles IL	7.4.09/14
Bill Stuart, Tullahoma TN	.17/20

N432U noted Reading PA 6.67 as American Turbine 600R trigear; N432U noted visiting Montreal-Dorval QUE 10.67, turbines; N432U noted Millville NJ 2.9.74 Westwind trigear; N432U noted Burlington VT 12.79 "Baltimore Airways" titles, tailwheel; turbine in service; N432U accident report 23.1.81: Pronto Aviation, cargo flight from Denver CO, 7.17am, pilot inadvertantly retracted gear, minor dam; N432U noted Seattle-Boeing Field WA 16.3.85 turbines Methow Aviation "Pinocchio"; N432U noted Everett WA 24.5.90 Methow Aviation;

BA-162	E18S	N32W	Alamo Aviation, San Antonio TX: new	.2.7.56/57
			sold to Mexico, struck-off USCR	23.1.57
		XB-YOT	reg Aviones se Sonora, Hermosillo	- 77
			Guillermo S. Lopez	93

XB-YOT noted Phoenix AZ 10.8.71;

BA-163	E18S	N42E	Piedmont Aviation, Winston Salem NC: CofA issued	31.5.56
	-9700		Food Fair Stores Inc, Miami FL	11.56/67
		N4288	William C. Whitesell/ Continental Aircraft Sales/	
			Longhorn Airways, Medford NJ	6.3.67/69
			Carolina Aircraft Corp, Ft Lauderdale FL	69
	ATE		American Turbine Aircraft Corp, Long Beach CA	25.4.69/72
	Westwind I		(converted at Long Beach CA to ATE Westwind I:	
	trigear		Volpar trigear, PT-6A turbines, cargo door,	
	-		picture window, two-piece windshield, completed 9.69)	
			Hamilton Aircraft Co, Tucson AZ	16.2.72
	Hamilton Westwind III		(rebuilt as Hamilton Westwind III: trigear replaced by	
			tailwheel gear, cockpit door, Hamilton extended cargo nose	
	tailgear		completed by Hamilton 6.72)	
	-		SMB Stage Line Inc, Des Moines IA	29.6.72/78
			Blackhawk Airways, Janesville WI	5.9.78/79
		N4288T	Blackhawk Airways, Janesville WI	15.2.79/80
		N924J	Earl L. Christ, Racine WI	2.80
			The Beta Corp	20.2.80/84
			op: Check-Air Inc, Milwaukee WI	81
			Coastal States Aviation, Denver NC	18.9.84/85
			op: Mountain Air Cargo, Denver NC	84
			American Federal Bank, Equipment Leasing Division,	
			Greenville SC	1.2.85/89
			lsd: Mountain Air Cargo, Denver NC	1.2.85/89
			Methow Aviation, Everett WA & Wenatchee WA	1.3.89/91
			Jim & Louise A. Baron, St Charles IL	11.3.93/13
			(retired engineless Aurora IL 99/02)	
			struck-off USCR	28.10.13
		N924J	Dash Flying Service, Chilton WI: rest. to USCR	26.11.17/20
			CA 15.11.69 Westwind Mk.1 trigear turbine;	
			ach CA 8.6.71 Westwind trigear, "Westwind I" titles;	
			Z 3.4.72 at Hamilton Aircraft ramp, Westwind;	
	N/4000			

N4288 noted Columbus OH 10.72 Westwind III tailwheel, "SMB Stage Line" titles;

N924J noted Coeur d'Alene ID17.10.91 "Methow" tailwheel turbine Westwind;

N924J noted Seattle-Boeing Field 24.5.90, 10.8.90: both "Methow" titles, in service, Westwind III; N924J noted Aurora IL 8.97 as Westwind III;

N924J noted Aurora IL 7.99, tailwheel, long nose, no titles, engineless; N924J noted Aurora IL 2.8.99 "The Bear", plate BA-163 built 5.56, conv. -9700 mods 10.59; report 2000: parachute jump plane at Xenia OH; N924J noted Aurora IL 30.12.01 engineless; unchanged 9.6.02; N924J noted Aurora IL 24.7.03 Westwind III engineless, not titles;

BA-164 •	E18S	N49A (1	Anderson Air Activities: CofA issued	31.5.56			
	-9700	N510G (2	Gisholt Machine Co	25.7.56/61			
		N510Q	Gisholt Machine Co	7.2.61			
			Western Mutual Insurance Co, Des Moines IA	10.61/67			
			(picture windows, extra window, and G18S type				
			two-piece windshield installed 3.62)				
			Air Travel Inc, Des Moines IA	18.7.67/70			
			Barton Manufacturing Inc, Campbellsport WI	9.12.70/71			
			Thomas L. Waller & Mark D. Goforth	14.6.72/73			
			Circle S Farms Inc	13.7.73/77			
			A. L. Sutton, Fort Davis TX	2.9.77/78			
			Thomas Bussard	14.3.79/86			
			US Customs Service: aircraft forfeited	6.1.86			
			Jim Hankins Air Service, Jackson MS	13.8.86			
			Tora Express Inc, Monroe LA	11.86/88			
			Aircraft Technical Support Inc, Galena OH	20.1.89/96			
			John S. Rux, Chicago IL	2.7.96/13			
			op: Skytrain Inc, Wakeman OH	99			
			struck-off USCR	25.3.13			
	N510Q no	ted Van Nuys	: CA 13.11.76;				
	N510Q no	ted Oshkosh	WI 27.7.89, plate BA-164;				
		ted Wakemar					
	N510Q no	N510Q noted Wakeman OH 9.8.99 "Sky Train" placard in window, plate: BA-164 built 6.56,					
		to -9700 10.5		,			
	N510Q no	ted Cleveland	I-Hopkins OH 8.99 flying;				
	N510Q no	ted Tulsa OK	11.17 open storage complete, brown and cream, vusta	windows;			
BA-165	E18S	N48A	Aircraftsmen Inc, Oklahoma City OK: CofA issued	5.6.56/57			
		N225H	Halliburton Oil Well Cementing Co, Duncan OK	25.3.57/68			
			Princeton Mining Co, Terre Haute IN	22.2.68/69			
			SMB Stage Line Inc, Des Moines IA	5.8.69/78			
			gear collapsed landing, Muskogee OK	20.1.71			
			(cargo door installed 9.77)				
			Ralph Quinlan/ Mountain Air Cargo, Denver NC	18.9.78/82			
			(cockpit pilot door installed 10.78)				
			op: General Aviation Inc, Greenville TN	80			
			ABC Flying Inc, Cedarville OH	29.3.82/83			
			Carlos Rosario: sale documentation not completed	.83			
			(noted retired derelict Beef Island Airport, BVI 85)				
	N225H no	ted Kansas C	ity MO 30.10.69;				
BA-166	E18S	N27T	Page Airways, Rochester NY: CofA issued	5.6.56/57			
			Webb & Knapp Inc	8.5.57/58			
			The Allan Corp, Morristown NJ	10.7.58/59			
			Clayton Irwin	10.59/60			
			Allan P. Kirby/ Allan Corp, Morristown NJ	8.4.60/64			
			Tri-State Aviation, Washington PA	17.1.64/67			
	trigear		(Volpar Mk.IV tricycle gear installed 6.64 by				
			Capitol Aviation, Springfield IL)				
		N405FW	Rolair Corp/ Wright Air Lines, Cleveland OH	19.5.67/70			
			Metro Commuter, Denver CO: leased	69			
			Frank E. Bachner	2.10.70/72			
			US Bureau of Customs: aircraft forfeited	22.5.72			
		N2395M	US Bureau of Customs	5.7.72/78			
			Michael K. Knight	1.3.78			

Franklin B. Davis, Coral Springs FL

(FAA report 78: false address)

31.3.78/80

N405FW owned Rolair, appears leased fleet to Wright Airlines, Cleveland; N405FW noted Ft Lauderdale FL 13.6.71; N2395M noted NAS Corpus Christi TX 10.5.73 "US Bureau of Customs", trigear; N2395M noted Opa Locka FL 2.10.77 trigear;

BA-167	E18S	N32R	J. D. Reed Co, Houston TX	2.56
		N4321D	Beech Aircraft Corp, Wichita KS	.56
			(delivered to India via Prestwick 28.6.56)	
			sold to India, struck-off USCR	2.7.56
		VT-DIR	Hind Provincial Flying Club, Lucknow	7.56/79
			Indamer Co, Bombay-Juhu	.89/92
			(noted Juhu 13.7.92, dismanted stored under sheets	
			outside Indamer hangar, with D18S VT-CJV)	
			broken-up for scrap, Bombay-Juhu	.96

VT-DIR noted Juhu 13.7.92, dism. under sheets outside Indamer hangar, with VT-CJV; VT-DIR noted Bombay-Juhu 1.93 "being rebuilt";

	E18S	N34W	Combs Aircraft Inc: CofA issued	11.6.56
			Midwest Oil Corp, Fort Worth TX	9.7.56/64
		N234W (2	Combs Aircraft Inc	12.64/65
			Mark Warinner, Boulder CO	9.11.65/67
			(smoke spotters hatch behind door fitted 5.66)	
		N904BC	Birko Chemical Corp	24.4.67/68
			Sentinel Airways Systems Inc	20.9.68
			Wallace R. Sitton, Tarzana CA	2.4.70
		N555WS	Wallace R. Sitton, Tarzana CA	11.70/71
	Hamilton		Circle S Farms Inc, Ashland OR	17.2.71/76
	Little Liner		Schaefer Air Service, Los Angeles CA	1.8.76/84
			Telcom Communications Inc, Fresno CA	16.5.84/86
			Paul A. Broussard/ Classic Aeroplane Leasing,	
			Madera CA	11.6.86/05
			Jack Shepard, Columbia MS	29.7.05/18
			reg pending, Rolling Fork MS	20
100	E400		Veeder Deet Inc. Hetferd CT	00/04
BA-169	E18S	N45E	Veeder Root Inc, Hartford CT	63/64
A-169	E18S trigear	N45E	American National Bank, Jacksonville FL	66
A-169		N45E	American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL	66 68
A-169		N45E	American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL Leasing Consultants Inc, Forest Hills NY	66 68 69
A-169		N45E	American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL Leasing Consultants Inc, Forest Hills NY Burnside Ott Aviation Training Centre, Opa Locka FL	66 68 69 4.5.70/71
A-169		N45E	American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL Leasing Consultants Inc, Forest Hills NY Burnside Ott Aviation Training Centre, Opa Locka FL op: South Atlantic Airlines, Hilton Head Island SC	66 68 69 4.5.70/71 71
A-169			American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL Leasing Consultants Inc, Forest Hills NY Burnside Ott Aviation Training Centre, Opa Locka FL op: South Atlantic Airlines, Hilton Head Island SC sold to Colombia, struck-off USCR	66 68 69 4.5.70/71 71 10.8.71
A-169		N45E HK-1248P	American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL Leasing Consultants Inc, Forest Hills NY Burnside Ott Aviation Training Centre, Opa Locka FL op: South Atlantic Airlines, Hilton Head Island SC sold to Colombia, struck-off USCR reg	66 68 69 4.5.70/71 71 10.8.71 8.71
A-169		HK-1248P	American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL Leasing Consultants Inc, Forest Hills NY Burnside Ott Aviation Training Centre, Opa Locka FL op: South Atlantic Airlines, Hilton Head Island SC sold to Colombia, struck-off USCR reg Jairo P. Forero	66 68 69 4.5.70/71 71 10.8.71 8.71 26.4.72
A-169			American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL Leasing Consultants Inc, Forest Hills NY Burnside Ott Aviation Training Centre, Opa Locka FL op: South Atlantic Airlines, Hilton Head Island SC sold to Colombia, struck-off USCR reg Jairo P. Forero Aerotor	66 68 69 4.5.70/71 71 10.8.71 8.71
A-169		HK-1248P	American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL Leasing Consultants Inc, Forest Hills NY Burnside Ott Aviation Training Centre, Opa Locka FL op: South Atlantic Airlines, Hilton Head Island SC sold to Colombia, struck-off USCR reg Jairo P. Forero Aerotor Aerotabo	66 68 69 4.5.70/71 71 10.8.71 8.71 26.4.72 72
A-169		HK-1248P	American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL Leasing Consultants Inc, Forest Hills NY Burnside Ott Aviation Training Centre, Opa Locka FL op: South Atlantic Airlines, Hilton Head Island SC sold to Colombia, struck-off USCR reg Jairo P. Forero Aerotor Aerotabo Aerolineas Medellin, Medellin	66 68 69 4.5.70/71 71 10.8.71 8.71 26.4.72 72 76
3A-169		HK-1248P	American National Bank, Jacksonville FL op: Florida Atlantic Airlines, Fort Lauderdale FL Leasing Consultants Inc, Forest Hills NY Burnside Ott Aviation Training Centre, Opa Locka FL op: South Atlantic Airlines, Hilton Head Island SC sold to Colombia, struck-off USCR reg Jairo P. Forero Aerotor Aerotabo	66 68 69 4.5.70/71 71 10.8.71 8.71 26.4.72 72

HK-1248 noted Bucaramanga, Colombia 30.9.72 Aertor;

BA-170	E18S	N51K (1	Gopher Aviation, Rochester Airport MN: CofA issued Rockford Screw Products Inc	18.6.56 26.6.56/62
	-9700		(mods. to E18S-9700 4.59)	

		N251K	Rockford Screw Products Inc	21.8.62
			Beloit Corp, Beloit WI	6.9.62/70
			Griffing-Sandusky Airport Inc, Sandusky OH	8.7.70/72
			Blackhawk Airways, Janesville WI	23.4.72/73
			North Continent Airlines, Long Beach CA	23.2.73/84
			op: Blackhawk Airways, Janesville WI	73
			struck baggage carts taxying, Chicago-O'Hare IL	1.11.73
			Richard Wixom/ Blackhawk Airways, Janesville WI	78/84
			Aero Taxi-Rockford Inc, Rockford IL	30.7.84/95
			Earl V. Long, Wichita KS	31.7.95/96
			Kestrel Inc, Waukee IA	12.96/99
			Methow Aviation, Everett WA	12.9.00/05
			Kestrel Inc, Waukee IA	25.5.05/06
			Neenah Classic Aircraft LLC, Menasha WI	21.8.07/20
	N251K no	ted Chicago-	O'Hare 1.10.72 Blackhawk Airways;	
			O'Hare 17.11.76 Blackhawk Airways;	
			1.11.73: Blackhawk Airways, flight Waterloo IA to O'Har	e, taxying after
	landing, 9	.50pm;		
	N251K no	ted Chicago-	O'Hare 117.11.76 Blackhawk Airways;	
	N251K no	ted Long Bea	ach CA 7.9.83 North Continent Airlines;	
	N251K no	ted Rock Fall	ls IL 12.88 arr on freighter charter, op Aero Taxi, tailwhe	el;
	N251K no	ted Tucson A	XZ 30.4.92;	
	N251K no	ted Ankenky	IA 24.7.98 freighter Kestrel Inc, plate: BA-170 built 6.56	
	plate: con	v. 4.59 to E18	8S-9700;	
	N251K no	ted Moses La	ake WA 22.3.00 "Methow" titles;	
			6.8.03 "Methow" titles;	
	N251K no	ted Neenah V	<i>NI</i> 22.7.17 "Methow" titles, having maintenance in hanga	ar;
BA-171	E18S	N73V	Topeka Aircraft Sales & Service, Topeka KS	13.7.56
	-9700		Wilcox Electric Co	17.7.56/61
			Seaboard Allied Milling Corp, Kansas City MO	11.61/63
			Wylie-Stewart Machinery Co, Oklahoma City OK	25.4.64/68
	trigear		(tricycle gear, picture windows, G18S type	
			two-piece windshield installed 6.65)	
			Webster B. Todd/ Princeton Aviation Corp	8.67/69
			damaged gear collapsed landing, Newark NJ	5.10.67
		N4303Y	Princeton Aviation Corp	27.4.68/69
			Bernard L. Warner/ Spectrum Leasing Corp,	40.00/=4
			Van Nuys CA	10.69/71
			op: Hawaii Pacific Airlines, Honolulu HI	70
			Panorama Air Tour Inc, Honolulu HI	1.2.71/75
			Ray Berney, Warren Bailey, Berney Thompson/	
			B&B Enterprises Inc/ Panorama Air Tour Inc,	20.075/00
			Honolulu HI (fleet #53)	30.9.75/82
			AirTour Acquisition Corp, Honolulu HI	26.7.82/85 71/84
			op: Panorama Air Tour, Honolulu HI	
			Kemavia Inc, Honolulu HI Unicomp International Inc, Cape Canaveral FL	12.85/87 3.2.87/89
			Pleasure Flying Airways, Fort Lauderdale FL	10.5.89/91
			accident Bimini, Bahamas	15.8.91
			struck-off USCR	28.10.91
				20.10.01
	N73V acc	ident report 5	10.67 Princeton Aviation, gear collapsed due maintena	nce:
			gton-DCA 2.10.68 trigear;	
			u 9.9.70 & 5.10.70 both "Hawaii Pacific" trigear;	
			u 8.9.71 & 1.76 trigear "Panorama AT";	
			HI 27.7.76 Panorama AT:	
		noted Honoli		
			8.81 "Panorama AT" #53, in Beech 18 tour formation;	
			leet list as at 15.11.83: BA-171 tt 14,860 hrs, fleet #53;	
			ys CA 25.8.85 "Panorama Air" titles #53;, trigear;	
			ys CA 15.10.85 "Panorama Air" titles #53 trigear;	
		-	erdale FL 20.9.90;	
			Votaile in NTSB listing, on guated on Blacoura Elving Air	

accident 28.10.91: no details in NTSB listing, op quoted as Pleasure Flying Airways;

BA-172	E18S -9800	N42RJ	The Norman Larson Co: CofA issued Robert O. Cummings/ Cummings Research	25.6.56 9.7.56		
			Hughes Aircraft Co: leased	12.7.56/61		
			Ten Sixty Corp, Beverly Hills CA	63		
		N139HH	Hastings Harcourt/ Santa Barbara Aviaton CA	11.63/65		
			(PacAero installed two-piece windshield 1.64)			
		N1399H	Hastings Harcourt/ Santa Barbara Aviation CA	12.65/66		
			Wholesale Aircraft Inc	11.5.66		
		N797S	Aircraft Owners Inc, Miami FL	11.66/67		
			(picture windows installed 12.66)			
			Čalhoun Aviation, Battle Creek MI	2.8.68/71		
			Michigan Air Activities, Battle Creek-Kellog MI	15.2.71/76		
		N797SB	Security National Bank	6.76/77		
			G E M Interstate Development Co, Hickory Corners WI	12.77/83		
			SmithAir Inc, Sharpsburg GA	7.8.83/94		
			Piedmont Air Cargo, Gastonia GA	6.7.94		
			Aero Express Inc, Dearborn Heights MI	6.6.95/96		
			Jim Hankins Air Service, Jackson MS	7.3.96/99		
			Jim Ryan/ Brazoria County Mosquito Control District,			
			Angelton TX	21.10.99/09		
			(under-wing spray bars fitted .99)			
			forced landing, struck two cows and wood pile, after			
			wing hit a correctional facility tower during a turn followin			
			a mosquito spray run, Jones Creek TX	3.10.09		
			· Data Ourserie en affan anna an difacture dia bia TV ataura			
	N42RJ flown by TV star Bob Cummings, often appeared featured in his TV shows;					
			GA 20.8.98 in service, freight, Hankins Air Service, plate: B	A-172 DUIIL 0.30,		
	•		d to E18S-9800 9.64; Is Air Service fleet Status Report 10.8.98, TT9323 hrs;			
		noted Angleto				
			rcos TX 18.7.03 good condition, "Brazoria County Mosquite	Control District"		
		ay-bars under				
			milys, n TX 0.8.03 flving nilot lim Rvan owner plate RA-172			

N797SB noted Angleton TX 9.8.03 flying, pilot Jim Ryan owner, plate BA-172;

BA-173	E18S	N46W	built	.56
Breno	2100	N456T	Transwestern Pipeline Co. Houston TX	63/66
			Fletcher Aircraft Leasing Corp, Bellaire TX	69
			Coastal Airways, San Juan, Puerto Rico	25.8.69/71
			crashed destroyed on takeoff, hit Beachcomber Hotel,	
			St. Thomas-Truman USVI (8k)	21.4.71

N456T accident report 21.4.71: Coastal Airways: engine failed on takeoff;	

BA-174	E18S	N23W	Beech Aircraft Corp, Wichita KS: CofA issued	29.6.56
	-9700		Ohio Aviation Co, Dayton OH	17.8.56
			Perfect Circle Corp, Hagerstown IN	11.56/65
			Dana Corp	15.3.65/66
		N423W	Dana Corp	5.7.66/67
			National Flight Service, Toledo OH	6.9.66/67
			Van C. Parriot	7.4.67
			Louis W. Mack	10.67/68
			Aircraftsmen Inc, Oklahoma City OK	9.2.68/70
			(Beech cargo door installed 6.68)	
			Stuart E. Aegler/ Great Lakes Aviation Corp	13.1.71
		N20GL	Great Lakes Airlines, Chicago IL	11.71/74
			Semo Aviation Inc, Malden MO	17.5.74/79
			Word Science Corp	15.3.79
			Glades County Sheriffs Department FL: seized	4.10.79
			Knight Aircraft Corp	11.79/80
			Carl Morriss	12.80/82
		(N174CM)	ntu: Carl Morriss	30.5.81
		N20GL	Karl Knight/ Global Aircraft Inc, Miami FL	28.5.82/84
			Mark Olson, Humboldt IA	8.82
			Brian Clark, Miami FL	9.84/85
			US Marshal: seized at Sylvania GA by	
			, , , , , , , , , , , , , , , , , , ,	

Drug Enforcement Administration:	23.9.85/91
Hubert J. Dwyer, Clear Lake IA	19.4.91/13
struck-off USCR	22.5.13

N423W noted Ft Lauderdale FL 24.8.71; N20GL noted Mason City IA 8.97, open storage poor condition: plate BA-174 built 6.56; N20GL noted Mason City IA 25.7.98 unchanged; N5600D & N20GL auction at Mason City IA 6.17: N20GL stripped hulk in very high grass;

BA-175	E18S	N46D	Cutter Carr Flying Service, Cutter Carr Airport,	
	2100	NTOD	Albuquerque NM: CofA issued	10.7.56/57
			Galles Motor Co	28.2.57/60
			Continental Oil Co, Houston TX	3.1.60/66
			Dunham-Price Inc	10.66/69
			Wiles-Holloway Inc, Baton Rouge LA	20.1.69/70
			Southern Fleet Leasing Corp, Baton Rouge LA	5.70/72
			Transcontinental Air Service	6.1.73/75
			Robert Robinson/ National Aviation	8.75/76
			op: National Air Freight	75
			Aerospace Products Inc, North Hollywood CA	28.2.76
			Patrick W. Lawing	12.76/77
			Fess E. Parker	15.9.77/78
			Aerospace Products Inc, North Hollywood CA	11.78
			Leon & Velma Wheeler	11.78/80
			Landwealth Inc, Houston TX	10.81/82
			P. W. Burtis, Dallas TX	21.5.82/83
			Charles R. Warren, Dallas TX	5.83
		N599DC	Charles R. & Dorothy J. Warren, Dallas TX	16.5.83/90
		N818TW	Tom J. Wakefield/ Devils Lake Aviation, Devils Lake ND	3.90/94
			Robert H. Powell, Wayzata MN	17.6.94/96
		N818RP	Robert H. Powell, Wayzata MN	22.7.96/97
			Powell Air Inc, Wayzata MN	3.3.97/16
			Island City Seaplanes Inc, Cordova AK	17.2.16/19
		N54CX	Island City Seaplanes Inc, Cordova AK	2.5.19
	N46D note	ed Havward (	CA 19.9.75 "National Air Freight" titles, tailwheel;	
			uff AR 2.95, tailwheel;	
			// 8.97 plate BA-175 built 7.56;	
			98 owned Powell Air;	
			County MN 13.7.03 tailwheel;	
BA-176	E18S	N50K	Continental Oil Co, Houston TX	63/64
	2.00		Great Western Investment Corp, Corpus Christi TX	66
			Davis Airlines, Bryan TX	68/70
			MS & C Realty, Killeen TX	71/72
		N50JR	Bromley Corp, Dallas TX	26.1.72/73
			op: Robert Airways	73
			crashed destroyed on takeoff, Natchitoches LA	20.9.73
			(6k including singer Jim Croce)	
	NEOK not	d Callaga St	ation TV 7.70 "Davia Airlines" titles toilukaal in samilaat	
			ation TX 7.70 "Davis Airlines" titles, tailwheel, in service; obert Airways: 10.45pm, slow climb after takeoff from Natcl	hitoches Municiple
			of tree and aircraft crashed to ground. Pilot incapacitation,	

20.9.73 crash report: Robert Airways: 10.45pm, slow climb after takeoff from Natchitoches Municipi Airport, wing struck top of tree and aircraft crashed to ground. Pilot incapacitation, had coronary artery disease, had just run 3 miles from motel to airport; singer Jim Croce had just completed a performance at Northwest State University;

E18S	N70A	Protective Insurance Underwriters, Omaha NE	63/66
-9700	N2070A	SMB Stage Line Inc, Des Moines IA	69/79
Hamilton		op: Little Mountain Alr Cargo, Denver NC	78
Westwind		Southern National Leasing Corp, Charlotte NC	30.6.78/81
		minor damaged in gear-up landing, Blountville TN	5.9.78
		op: General Aviation Inc, Greenville TN	80
		op: Mountain Air Cargo, Denver NC	80/81
		crashed forced landing off-airport at night, struck poles	
		while avoiding buildings, Glen Burnie MD	15.12.81
	-9700 Hamilton	-9700 N2070A Hamilton	-9700N2070ASMB Stage Line Inc, Des Moines IAHamiltonop: Little Mountain Alr Cargo, Denver NCWestwindSouthern National Leasing Corp, Charlotte NCminor damaged in gear-up landing, Blountville TNop: General Aviation Inc, Greenville TNop: Mountain Air Cargo, Denver NCcrashed forced landing off-airport at night, struck poles

N2070A noted Chicago-O'Hare IL 3.2.69 SMB Stage Line; N2070A noted Harrison AR 13.7.73 SMB Stage Line; N2070A accident report 5.9.78: Little Mountain Air Cargo, cargo flight Greenville TN to Blountville, 5.48pm, pilot unhurt; N2070A accident report 15.12.81: Mountain Air Cargo, cargo flight from Glen Burnie MD to Columbus OH, carb icing, right engine failed, left running rough, 11.07pm, pilot unhurt;

BA-178	E18S	N41R N141Z	US Department of Agriculture, US Forest Service: CofA USDA /US Forest Service, Ogden UT	25.7.56 5.3.59/78
	Aerojet		(Aerojet rocket engines installed 17.6.59)	
	rockets		struck trees during low pass, Taos NM	15.11.65
			unairworthy: struck-off USCR US Dept. of Agriculture,	12.4.78
			Animal & Plant Health Inspection Service (APHIS)	25.1.79/80
		N141ZA	USDA/ APHIS: restored to USCR	15.1.80/85
		111712/1	(converted for fruit fly spraying 1.81)	10.1.00/00
			USAF Museum Foundation	20.7.85/86
			struck-off USCR	11.85
			Hawkins & Powers Aviation, Greybull WY	11.2.86/00
			D & G Inc, Greybull WY	24.8.00/02
			Advanced Air Inc, Council Bluffs IA	16.11.04/07
			struck-off USCR as "sold to New Zealand" (not del.)	4.10.07
			Taigh Ramey, Stockton CA	10/15
		N141ZA	Taigh Ramey/ Vintage Aircraft Inc, Stockton CA	11.12.15/19
			Airventures LLC, Englewood CO	6.2.20
BA-179	USFS insig N141ZA n N141ZA n N141ZA n N141ZA n Further de N141ZA n	gnia, JATO ec oted Greybull oted Greybull oted Sheridan oted Sheridan tails on USFS oted at Stockt	base Illinois Valley OR 5.9.66, tailwheel, cream & red, guipped; 2.8.89 metallic, in service; 26.6.90, 12.10.92, H&P in service; wWY 8.8.95 in Big Horn Airways hangar (H&P subsidiary) WY 3.8.00 H&P, stored in hangar, plate BA-178 built 7.56 Suse: see Beech 18 by Robert Parmerter p.291; fon CA 14.9.10 parked outside in civil paint scheme; CA 29.6.17 reported in excellent condition; built Texas Gas Transmission Corp, Owensboro KY Indianapolis Transit Service, Indianapolis IN	5; .56 63/64 66
			Wisconsin Airways, Milwaukee WI	69
			Horizon Aviation Enterprises, Chicago IL	70
			SS Airways Inc, Mission KS	6.11.75
			crashed destroyed by fire, landing Kansas City MO	24.12.75
3A-180	E18S	N48D	built	.56
		N83CP (2	Chas Pfizer & Co, Maywood NJ	63/64
			American Aero Leasing Corp, Elizabeth NJ	66
			Jack Adams Aircraft Sales, Walls MS	69
			Leasing Consultants Inc, Forest Hills NY	70
			Burnside Ott Aviation Training Centre, Opa Locka FL	70
			Jordan Klein Inc, Miami FL	72
			International Airmotive Corp, Fort Lauderdale FL	8.11.72
		CC-CLJ	sold to Chile, struck-off USCR reg	8.11.72 .72
	N83CP no	ted Miami FL	27.5.70.	
			dale FL 13.6.71; rdale FL 1.10.72;	
BA-181	E18S	N60K	Beech Aircraft Corp, Wichita KS: CofA issued Gerald C. Francis/ Francis Aviation, Lansing MI Galion Iron Works & Manufacturing Co Bailey Leasing Corp/ George H. Bailey Co, Ft Wayne IN Aircraftsmen Inc, Oklahoma City OK Texas Aviation Investments Inc, Amarillo TX Shulton Inc, Clifton NJ	10.7.56 12.56/57 12.2.57/60 16.9.60/62 5.5.62/63 63 21.8.63/69

trigear		(Volpar Mk.IV trigear & two-piece G18S type windscreen installed 1.64)	
		Mercury Aircraft Inc, Hazard KY	10.5.69/73
		op: Catawba Air Transport	72
		gear collapsed landing, Hickory NC	20.3.72
		Jimsair Aviation Services, San Diego CA	6.6.73
		Santiago F. Braccamonte	6.6.73
	N407JB	Santiago F. Braccamonte	.74/77
	XA-GOX	Servicos Aeronauticos de Baja California S.A.	10.1.77/83
		struck-off Register	6.83
		G. L. Gaylor Construction Co, Thermal CA (stored Thermal CA 83/84)	16.7.83/84
	N18LG	G. L. Gaylor Construction Co, Thermal CA George L. Gayler, Thermal CA	18.1.84/14 6.1.14/20

N60K noted Toronto 1.4.64;

N60K accident report 20.3.72: Catawba Air Transport, gear failed due mechanical fault; XA-GOX noted San Diego-Lindberg Field CA 12.78 landing, trigear "Servicios Aeronauticos de Baja California" titles: rep. used by Governor of Baja California; N18LG noted Thermal CA 12.8.08;

BA-182	E18S	N43T	Tulsair Distributors Inc, Tulsa OK: CofA issued	19.7.56
			Texas Natural Gasoline Corp	10.8.56/60
			Union Texas Petroleum	10.60/62
			Madden & Smith Aircraft Corp, Miami FL	5.6.62
			John T. Oxley, Tulsa OK	6.6.62/74
			Great Western Airlines, Tulsa OK	13.3.74/76
			(cabin cargo door installed 4.74)	
			minor damage on takeoff, Erie PA	30.1.76
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	12.76/77
			Carlisle Air Transport, Carlisle AR	22.2.77/78
			Larry Blatt & Robert Mascaro/ Lake County Aviation	10.78/83
			Richard A. Healey & Jose Masrtinez-Alegria, Miami FL (Aerospace Products cargo door installed 5.83)	18.3.83/85
			Andres Suarez, Miami FL	1.12.85/86
			damaged ran off runway on takeoff, Opa Locka FL	13.12.85
			Guidi Luis Felipe Gonzalez, Miami FL	2.86
			Rafael A. Medrano: sale documention not completed	31.3.86
			Intermarketing Air Corp, Miami FL	21.4.86/91
			(noted parked at Paitilla, Panama 12.86)	
	struck rig N43T noi N43T noi	ht wing on ru ted Ft Laude ted Miami FL	30.1.76: Great Western, takeoff on flight to Pittsburgh PA, s inway, landed again, 9.50pm, pilot unhurt; rdale FL 31.10.81 Carlisle Air Transport titles on roof, appea 25.10.84; 85: no owner quoted, tailwheel;	
BA-183	E18S	N47E	Gerald C. Francis/ Francis Aviation, Lansing MI	20.8.56
			Hydro Manufacturing Co, Detroit MI	12.9.56/73
			Blackhawk Airways, Janesville WI	19.5.73/81
			(cargo door installed 6.73, cockpit door 10.76)	
			Sky Train Inc	13.3.81
			Kevin P. Donnelly & Gary D. Douris/ Big Iron Airways,	
			Culver City CA	14.7.81/82

Coast Air Freight Inc, Long Beach CA

Centre Airlines Inc, Reedville PA

N47E noted Chicago-O'Hare 17.11.76 Blackhawk Airways titles; N47E noted Chino CA 31.1.81 no titles, ex Blackhawk AW;

N47E noted LAX 3.85 no titles, all metal finish, tailwheel, flying;

N47E noted Philadelphia PA 20.10.90, all metallic no titles;

N47E noted Long Beach CA 9.83 no engines; N47E noted LAX 11.1.84 Coast Air Freight;

N47E noted Van Nuys CA 12.6.90;

Aerospace Products Inc, North Hollywood CA

crashed Mount Nittany near State College PA

11.5.82/87

18.7.90/93

12.87/90

23.2.93

BA-184	E18S	F-OAXQ	Gouvernement du Niger, Niamey (delivered via Prestwick 7.8.56)	5.9.56/65
		5U-MAW	Niger Air Force	.65/73
		(F-BUOP)	ntu	.73
		( )	noted Cannes Airport, as "F-BCCI Chambre de Comme	
			et d'Industrie de Cannes"	8.74
			Cannes-Mandelieu, France: displayed on pole at airport	t
			entrance as "F-BCCI Aeroport Cannes Mandelieu",	
			later repainted various colours, and "Breitling" titles	76/14
			leetaways via Prestwick 7.8.56;	
			n-Croydon ex Prestwick 9.8.56;	
			6.73 left engine removed; Cannes 6.74;	
			8.74 "Chambre de Commerce et d'Industrie de Cannes"	
	,		a Do.27 in 12.74)	
			as gate guard 6.76, 8.8.79, 8.86; aite with green cheat line "Aeroport Cannos Mandelieu" tii	los
			nite with green cheat line "Aeroport Cannes Mandelieu" tit with no reg, white with grey/blue cheatlines (no reg) and t	
			delieu Chambre de Commerce et d'Industrie Nice Cote d'	
			ed 22.2.03; unchanged 17.8.05; same 9.07, 1.5.08; on po	
				·• · • · • · · · · · · · · · · · · · ·
BA-185	E18S	N84D (1	Youngstown Airways/ Lease Air, Youngstown OH	56
		N820	Youngstown Airways, Youngstown OH	11.56
			Studebaker Corp, Minneapolis MN	63/64
			Tulakes Aviation, Bethany OK	66
			tail gear collapsed landing, Albuquerque NM	22.12.66
			Wat Henry Car Leasing Co, Tulsa OK	12.12.67/68
			ditched, sank Gulf of Mexico, Marco Island FL	5.9.68
	N820 acc	cident report 22	2.12.66: Tulakes Aviation, swung on landing tail wheel col	lapsed;
BA-186	E18S	N18Y	Alamo Aviation, San Antonio TX	56
			O. L. Longoria	12.56
		XB-ZEO	O. L. Longoria/Empresas Longoria S. A.	57/72
		N38219	Sam Vires/ Mid-South Aircraft Sales, Memphis TN	11.72
			(US CofA renewed18.12.72)	
			Century Granite Co	12.72/76
			California Western University, Santa Ana CA	11.76/81
			Chipola Oil Corp, Brighton CO	20.5.81/82
			Antilles Air Charters	5.10.82/83
			Jorge Castro, Rio Pedras, Puerto Rico	1.11.83/85
			US Marshal, District of Pueto Rico:	40.0.05/00
			seized by Drug Enforcement Agency	16.9.85/88
			Atlanta Air Salvage	22.8.88
			Don J. Oglesby, Fayetteville GA	19.9.88/90
		N18SE	Don J. Oglesby, Fayetteville GA Eastport Enterprises Inc, Wilmington DE	14.1.90 23.8.90/95
			Shores Ag Air Inc, Robstown TX	23.8.90/95
				12.30/13
			Гиllahoma TN 10.93, Vichita KS 11.10.97;	
DA 407		-		
3A-187	E18S	N55H	built From Corp. Foot Providence DI	.56
			Fram Corp, East Providence RI	63/72
			struck off LISCP	27 11 72

		struck-off USCR	27.11.72
E18S	N18R (1	built	
	N4X È	rereg	17.12.56
		Mathieson Olin Chemical Corp, New York NY	63
	N650M	forced landing gear-up off airport after engine broke	
		away in flight, Columbia LA	21.4.66
	N139K	Modern Aero Sales, Dallas-Redbird TX	66/69
		Georgia Air Inc, Atlanta GA	26.1.70
		crashed destroyed during forced landing off-airport,	
		due in-flight fire, Sioux City IA	19.5.70
	E18S	N4X N650M	E18S       N18R (1 N4X       built rereg Mathieson Olin Chemical Corp, New York NY         N650M       forced landing gear-up off airport after engine broke away in flight, Columbia LA         N139K       Modern Aero Sales, Dallas-Redbird TX Georgia Air Inc, Atlanta GA crashed destroyed during forced landing off-airport,

BA-189	E18S	N48E	J. R. Gray & Co/ Executive Air Transportation Service,	14.9 56/50
			Dallas TX	14.8.56/59
			Tecon Corp	2.1.59
			Jeffries & Betts Gravel Co	11.9.59/60
			Trishman Equipment Leasing Inc	18.3.60/62
		NCOOOF	Wesco Leasing Corp, Addison TX	19.9.62/67
		N6039F	Wesco Leasing Corp, Addison TX	
		N165X	Aerodyne Engineering Corp	5.10.67/68
			Transamerica Commercial Corp, New York NY	14.6.68/69
			Marvin Hambrick/ Hambrick Aircraft, Lafayette CA	11.69/79
			George C & Janet L. Holberton	10.79/81
			Christopher J. & Christine A. Petrikas,	0.04/00
			Lake Havasu City AZ	6.81/88
			(Aerospace Products wrap-around windshield	
			installed 9.87)	20 1 00/04
			Cal Corp, Oakdale CA	28.1.88/94
			F1 Systems Inc, Bandon OR	9.11.94/95
			Hardin Optical Co, Bandon OR	20.3.95
			FIL Systems, Bandon OR	11.97
			Thomas E. Duzan, Kennewick WA	23.4.98/15
			Redhead LLC, Wilmington DE	10.3.15/17
			J & M Aviation Enterprises. Greendale WI	30.1.18
	NIGEV no	tod Von Nuu		
		oted Van Nuys oted Van Nuys		
			(S 4.8.96 warbird flyin, in military scheme;	
	INTOON VIS		S 4.6.90 Warbird Hylli, III Hillitary Scheme,	
BA-190	E18S	N49E	Atlantic Aviation Corp	22.8.56/58
			D.A. Financial Service Co	5.6.58/61
			Dayco Corp, Dayton OH	1.6.61/67
		N722K	Skyways Inc	26.6.67
			John Palmer/Metro Air Service, Detroit MI	26.9.67/71
			(cargo door installed 2.69)	
			Ed Bowlin Associates Inc, Memphis TN	16.6.71/72
			Vero Aero Inc	7.4.72/74
		N300JH	Sedalia-Marshall-Boonville Stage Line, Des Moines IA	24.1.74/76
		N380JH	Precision Valley Aviation, Springfield VT	12.8.76/81
			(pilot cockpit door installed 3.77)	
			P B Leasing Inc, Naperville IL	24.3.81
			leased: Viking Express Inc, Minneapolis MN	81
		N101VE	P B Leasing Inc, Naperville IL	13.7.81/84
			leased: Viking Express Inc, Chicago-Midway IL	81/84
			op: Titan Air	86
			crashed residential area on takeoff Chicago IL	29.9.86
			C C	
BA-191	E18S	N4346D	Beech Aircraft Corp, Wichita KS	8.56
			sold to India, struck-off USCR	23.8.56
			(delivered to India via Prestwick 22.9.56)	
	trigear	VT-DIS	The Tata Iron & Steel Co Ltd, Jamshedpur	9.56/77
			Goldensun Aviation, Bombay-Juhu Urvashi	77/85
			retired Bombay-Juhu, reported as derelict	82
			rep. crashed	.85
			burnt-out wreck, Bombay-Juhu	85/86
			CofA expired 10.6.86: struck-off Register	28.3.06
			ugural service 20.12.77 from Bombay-Juhu, scheduled pa	
			o Surat & Bhavnagar with VT-DIS & -DCW, later other pol	7S;
			i, India 12.77 trigear "Goldensun Aviation";	
		oted Bombay-		
			1.84 trigear, retired but complete, engine & cockpit covers,	
			Juhu 9.85 burnt-out wreck dumped in Bombay Flying Club	nangar;
	vi-DIS n	olea Junu 3.8	6 " burnt out wreck";	

N139K accident report 19.5.70: Georgia Air, cargo flight;

BA-192	E18S	N25X (1	Butler Airplane Sales	14.9.56/57
		N125X	Butler Airplane Sales	16.1.57
			Ridge Associates	17.6.57/60
			W. B. Osborne	4.1.60/62
			(Airline Training one-piece windshield fitted 1.62)	
			H. L. Brown, Fort Worth TX	11.62/63
			R. B. Montcreif, Fort Worth TX	12.63/65
			The Texstar Corp, San Antonio TX	2.4.65/67
			Sherwood Van Lines	20.7.67/68
			B & B Construction Co, Youngstown OH	11.68/73
			Dade Leasing Inc/ Dade Air Charter, Miami FL	27.7.73/74
			Great Western Airlines, Tulsa OK	10.74/80
			Aircraft Leasing & Pilot Services Inc, Brownsville TX	1.80/87
		(N8PZ)	ntu: Aircraft Leasing & Pilot Services Inc TX	2.83
		N125X	William R. Sandlin, Evant TX	18.4.87/91
		XB-CRK	reg	c.91
			Luis J. P. Rangel	93
		N125X	Jim Hankins Air Service, Jackson MS	6.93/95
			sold to Canada: struck-off USCR	2.96
		C-FXKG	Gold Belt Air Transport, Pickle Lake ONT	1.3.96/00
			G. Andrew Swartman	01
			sold to USA, struck-off Canadian Register	31.8.01
		N125X	Denis G. Lison, Mason NH	7.9.01/20

N125X noted Dallas-Love TX 21.4.66; N125X noted McAllen TX 10.87;

BA-193	E18S	N37V	Transcontinental Gas Pipe Line Corp, Houston TX	63/66
			Pocoflite Inc, Lakville PA	69
			Cherry Ridge Flying Service, Honesdale PA	70/72
			Export Airmotive Inc, Miami FL	29.8.72
			sold to Colombia, struck-off USCR	3.10.72
		HK-1382	reg	c72
			Transportes Aereos Nacionales - TANA, Bogota	74/76
			Aerolineas Especiales de Colombia Ltda - AE Colombia,	
			Florencia	76/77
		HK-1382P	J. F. Pulido	82

HK-1382 noted Opa Locka FL 3.10.72; HK-1382 noted Opa Locka FL 3.10.72; HK-1382 photo at Bogota c76 "AE Colombia" tailwheel; HK-1382 noted Tucson AZ 11.1.83; HK- ???? fuselage E18S "AE Colombia" titles on roof noted Bridgewater VA 11.8.99 in K&K Aircraft storage compound with other dismantled E18S: probably this acft;

BA-194	E18S	XB-XEO	built	9.56
	trigear		Manuel J. Galvan, Mexicali	93
	XB-XEO	noted Wichita	KS 18.10.72 trigear;	
BA-195	E18S	N70V	Nevada Plane Rentals, Las Vegas NV	63/70
			J. W. Duff/ Duffy's Aircraft Parts, Denver CO	71/08
			(stored dismantled in Duff's salvage yard, Denver 71/00)	
			struck-off USCR	20.2.08
	N70V not	ted in Duffys y	ard, Denver 9.8.00 fuselage only seen;	
BA-196	E18S	N37N	Ohio Aviation Co, Dayton OH: CofA issued	10.9.56
			McDowell-Wellman Engineering Co, Cleveland OH	9.9.56/63
			Corey Custom Airtravel Inc, Detroit MI	5.11.63/67
			Miducators Airlings Datrait City Airport MI	04 7 07/70
			Midwestern Airlines, Detroit-City Airport MI	21.7.67/70
			Aircraft Painting Inc	11.70/71
		N333EH	Aircraft Painting Inc Air Journeys Inc, Little Rock AR	11.70/71 6.10.71/72
		N333EH	Aircraft Painting Inc	11.70/71

	nosed over landing, Kirksville MO	25.3.75
	(Aerospace Products cargo door fitted 3.78)	
	Aero Craft Leasing Inc, Plymouth MI	20.4.78/79
	Hoffman Flying Service, Cheboygon MI	7.3.79/02
	(Aerospace Products wrap-around windshield	
	installed 3.88)	
	sold to Canada, struck-off USCR	18.6.04
C-FBKD	Parachutisme Nouvel Air Inc, Farnham QUE	21.6.04/17
	sold to USA, struck-off Canadian reg	24.4.17
N3717S	Thomas Setter, Burnsville MN	3.5.17/20

N333EH noted Muskogee OK 2.3.73 SMB at SMB maintenance base; USCR72 still N37N Air Journeys Inc; N333EH accident report 25.3.75: SMB Stage Line, mail flight Columbia MO to Kirksville, 4.15am, swerved off runway into soft ground; N333EH noted Willow Run MI 4.78 "SMB Stage Line" titles, standard E18S tailwheel; JP78 quotes N333EH as Westwind III: incorrect!! N333EH noted Cheboygan MI 10.96 Hoffman FS; C-FBKD noted St Mathias QUE 20.3.05 Parachutisme Nouvel Air, delivered to them .04; C-FBKD noted Farnham QUE 11.9.05 Parachutisme Nouvel Air, flying parachute drops, tailwheel;

BA-197	E18S	N45L	Pacific Aircraft Sales	18.10.56
			Ivar Akselsen	22.1.57
			KPF Electric Co, Stockton CA	7.6.57/69
			Richard E. Keith, San Anselmo CA	30.4.69/73
			Air Courier Inc	12.73/76
			(cabin cargo door installed 3.74)	
			op: Eureka Aero	74
			Cargo Air Transport Inc	25.2.76
			Peninsular Air Delivery/ Adelphic Cargo Enterprises	1.8.76/77
			Mat Mattson/ Rio Dusters, San Benito TX	10.77/79
			Dorlaine Romain	9.2.79
			(owner report 7.85: aircraft destroyed/scrapped)	
			struck-off USCR	12.85

## N45L noted Novato CA 22.8.72; N45L noted Gnoss Field, San Francisco CA 10.9.72; N45L noted Bakersfield-Meadows Field CA 10.6.74 "Eureka Aero", tailwheel;

BA-198	E18S	N48N (2	Spartan Mills, Spartanburg SC	63/64
		N75SA	Spartan Mills, Spartanburg SC	66
			Transit Homes Inc	69
		N5034F	Dee Howard Sales Inc, San Antonio TX	10.3.69
			David Rogers, Baytown TX	70/72
			SMB Stage Line Inc, Des Moines IA	6.2.74/80
			struck-off USCR	12.11.80

N5034F noted La Porte TX 7.5.73;

BA-199	E18S	N49A (2	Anderson Air Activities	.56
		N123H CF-LPC	International Harvester Co, Chicago IL W. Norman Smith/	57/59
			International Harvester Co of Canada Ltd, Hamilton ONT (ferry permit 6.59 Dayton OH to Hamilton ONT)	4.5.59/64
			International Harvester Co of Canada Ltd, Hamilton ONT	23.12.64/66
			Carl Millard Ltd, Toronto-Malton ONT	4.11.66/74
			Millardair Ltd, Toronto-Malton ONT	16.5.68
			dam by fire in left engine on start-up, London ONT	19.1.74
		N81GA	Gilley Airways Corp, Fulton NY (purchased damaged London ONT "as is/where is", repaired, ferried London-Syracuse NY 6.3.74 pilot William C. Gilley, Pesident of Gilley Airways)	29.1.74
			K & K Aircraft Inc, Bridgewater VA struck-off USCR (CofA not renewed after return to US .74)	22.10.74/11 4.8.11

CF-LPC noted Toronto-Malton ONT 17.4.68 tailwheel, not titles, at Millardair hangar;

BA-200	E18S	N59K	Crosby Forest Products Co, Picayune MS	63/64			
			Wiles-Holloway Inc, Baton Rouge LA	66			
			Combs Aircraft Inc, Denver CO	6.3.67			
			sold to Philippines, struck-off USCR	2.6.67			
		PI-C798	Lianga Bay Logging Co Inc, Manila	.67/70			
		RP-C798	Lianga Bay Logging Co Inc, Manila	78			
			Swiftair Inc, Zamboanga	79/84			
			Commuter Air Manila, Manila	90/98			
			Charles R. Miller/ CM Aero, Manila	03			
	RP-C798 RP-C798 RP-C798	noted Manila noted Manila noted Manila	7.5.86 tailwheel, no titles, yellow, red & white; 7.92 tailwheel i/s, 2.1.94 white with red trim, tailwheel; 4.2.98 red/white, no titles, tailwheel, in service; 5.03 tailwheel, at CM Aero ramp, in service, white with re	d;			
3A-201	E18S	N16U (1	Beech Aircraft Corp, Wichita KS	26.9.56			
			sold to Argentina, struck-off USCR	6.1.58			
		LV-IKA	M. J. Ordonez	5.8.58/61			
			Serv S Aereos Santa Isabel, Cap Fed	27.3.61/64			
		LQ-IGN	Gob Pcia de Santa Cruz	28.2.64			
			crashed on takeoff, Largo Argentino	4.11.65			
3A-202	E18S	N48K	Atlantic Aviation Corp: CofA issued	17.9.56			
			Time Inc, New York NY	21.9.56/65			
			landed with gear locked up, Boston-Logan MA	5,8,64			
			(repairs completed 9.64)				
			Louis McCollum/ McCollum Aviation, Danville IL	1.10.65/66			
			Lindley Johnson/ John Gard Development Service,				
			Richmond IN	20.8.66/72			
			Herbert E. Guynn, St Petersburg FL	6.72			
			McMillen Co Inc	12.9.72/73			
			Blackhawk Airways, Janesville WI	7.2.73/84			
			(cargo floor & cockpit door installed 3.73;				
			cabin cargo door fitted 7.81;				
			G18S type windshield installed 11.81)				
			J. Richard Wixom/ Blackhawk Airways, Janesville WI	7.7.84/94			
			damaged landed short of runway, Oak Creek WI	25.1.90			
			Cascade Air Inc, Seattle WA	17.3.94/95			
			Comanche Air Inc, Winthrop WA	28.2.95/07			
			op: Methow Aviation, Everett-Paine Field WA	00			
			crashed off end of runway on takeoff, Burlington WA	4.2.03			
			(stripped of parts, Burlington WA 04)	11 4 07			
			struck-off USCR	11.4.07			
			'Hare 20.3.73 Blackhawk;				
	N48K noted Chicago-O'Hare 13.9.76;						
			Blackhawk Airways;				
	N48K noted Seattle-Paine Field WA 8.94;						
		oted Burlingto	n WA 7.04 less engines & other components;				
	BA-202 n						
3A-203	BA-202 n E18S		FA Brasileira as U45 FAB 2876	,56			
3A-203		PT-KXN		,56 6.78/83			
3A-203	E18S		FA Brasileira as U45 FAB 2876 Miguel F.P.Chaves, Sao Paulo				
3A-203	E18S U45	PT-KXN					
	E18S U45 FAB 287	PT-KXN	Miguel F.P.Chaves, Sao Paulo				
	E18S U45 <i>FAB 287</i> E18S	PT-KXN 6 noted Rio-Sa	Miguel F.P.Chaves, Sao Paulo antos Dumont 20.10.72; FA Brasileira as U45 FAB 2877	6.78/83			
3A-203 3A-204	E18S U45 FAB 287	PT-KXN	Miguel F.P.Chaves, Sao Paulo antos Dumont 20.10.72;	6.78/83			
3A-204	E18S U45 <i>FAB 287</i> E18S U45	PT-KXN 6 noted Rio-Sa	Miguel F.P.Chaves, Sao Paulo antos Dumont 20.10.72; FA Brasileira as U45 FAB 2877 Jose A. Simioni Escola de Aviacan Elite Ltda, Golana	6.78/83 .56 6.77 83			
8A-204	E18S U45 <i>FAB 287</i> E18S U45 E18S	PT-KXN 6 noted Rio-Sa	Miguel F.P.Chaves, Sao Paulo antos Dumont 20.10.72; FA Brasileira as U45 FAB 2877 Jose A. Simioni Escola de Aviacan Elite Ltda, Golana FA Brasileira as U45 FAB 2878	6.78/83 .56 6.77 83 .56			
3A-204	E18S U45 <i>FAB 287</i> E18S U45	PT-KXN 6 noted Rio-Sa PT-KVQ	Miguel F.P.Chaves, Sao Paulo antos Dumont 20.10.72; FA Brasileira as U45 FAB 2877 Jose A. Simioni Escola de Aviacan Elite Ltda, Golana FA Brasileira as U45 FAB 2878 crashed in FAB service, Campo Grande AB (rebuilt)	6.78/83 .56 6.77 83 .56 5.12.67			
	E18S U45 <i>FAB 287</i> E18S U45 E18S	PT-KXN 6 noted Rio-Sa	Miguel F.P.Chaves, Sao Paulo antos Dumont 20.10.72; FA Brasileira as U45 FAB 2877 Jose A. Simioni Escola de Aviacan Elite Ltda, Golana FA Brasileira as U45 FAB 2878	6.78/83 .56 6.77 83 .56			

FAB 2878 noted Rio-Santos Dumont 30.7.67, 8.9.67; PT-KXO noted Barbados 5.79 derelict, 30.12.83 derelict, dismantled;

BA-206	E18S	N59E	Beech Aircraft Corp, Wichita KS (retained for development work, CofA issued 14.3.57)	1.10.56/57
			Gerald C. Francis/ Francis Aviation, Lansing MI	11.5.57/73
			Executive Air Sales	11.73/76
			Mohican Air Service, Cleveland OH	9.6.76/91
			Skytrain Inc, Wakeman OH	4.2.94/99
			Jack L. Harmon, Jenks OK	18.5.01/06
			Daniel S. Jones, Panama City Beach FL	13.4.10/20
	N59E not N59E not N59E not another p N59E not	ted Wakeman ted Wakeman ted Middletow blate Aerospac ted Middletow	City 3.11.81 in freight service Mohican Air Service, metallic OH 8.96; OH 9.8.99 Sky Train, plate BA-206 built 10.56; n OH 20.7.02: frieght interior, all metallic, stored: plate BA-2 ce Products spar kit 1509 s/n 169 22.4.75; n OH 1.8.05 all silver in storage; n OH 17.6.06 all silver in storage;	
BA-207	E18S	N844KN	built	
			Hope Natural Gas Co, Clarksburg WV crashed destroyed on takeoff, struck terrain in snow,	28.5.63/65
			Bridgeport WV	10.3.65
			iotes reg "N844K": struck rising terrain 1.5 miles beyond ru	
BA-208	crash rep destroyed E18S			
BA-208 BA-209	destroyed	d, 4k; N46L (1	otes reg "N844K": struck rising terrain 1.5 miles beyond run built	nway, .56
	destroyed E18S	d, 4k; N46L (1 PP-ECT	otes reg "N844K": struck rising terrain 1.5 miles beyond run built Govt. Est de Minas Gerais	nway, .56 65
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI	nway, .56 65 23.10.56
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66)	.56 65 23.10.56 1.12.56/64 10.64/71
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI	.56 65 23.10.56 1.12.56/64 10.64/71 21.6.71
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN	.56 65 23.10.56 1.12.56/64 10.64/71
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while	.56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while taxying, Rockford IL	nway, .56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75 1.5.75
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while taxying, Rockford IL Aircraft Maintenance Specialists Inc	.56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while taxying, Rockford IL Aircraft Maintenance Specialists Inc (cargo floor & cabin door installed 10.75)	.56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75 1.5.75 3.6.75
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while taxying, Rockford IL Aircraft Maintenance Specialists Inc (cargo floor & cabin door installed 10.75) American Lease Plans Inc, Charlotte NC	nway, .56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75 1.5.75 3.6.75 3.11.75/80
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while taxying, Rockford IL Aircraft Maintenance Specialists Inc (cargo floor & cabin door installed 10.75) American Lease Plans Inc, Charlotte NC Isd: Thomas J. Wood & Ralph Quinlan	nway, .56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75 1.5.75 3.6.75 3.11.75/80 4.11.75/80
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while taxying, Rockford IL Aircraft Maintenance Specialists Inc (cargo floor & cabin door installed 10.75) American Lease Plans Inc, Charlotte NC Isd: Thomas J. Wood & Ralph Quinlan minor damage landed gear locked-up, Asheville NC	nway, .56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75 1.5.75 3.6.75 3.11.75/80 4.11.75/80 4.3.76
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while taxying, Rockford IL Aircraft Maintenance Specialists Inc (cargo floor & cabin door installed 10.75) American Lease Plans Inc, Charlotte NC Isd: Thomas J. Wood & Ralph Quinlan minor damage landed gear locked-up, Asheville NC op: General Aviation Inc, Greenville TN	nway, .56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75 1.5.75 3.6.75 3.11.75/80 4.11.75/80 4.3.76 79/80
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while taxying, Rockford IL Aircraft Maintenance Specialists Inc (cargo floor & cabin door installed 10.75) American Lease Plans Inc, Charlotte NC Isd: Thomas J. Wood & Ralph Quinlan minor damage landed gear locked-up, Asheville NC op: General Aviation Inc, Greenville TN Ralph Quinlan/ Mountain Air Cargo, Denver NC	nway, .56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75 1.5.75 3.6.75 3.11.75/80 4.11.75/80 4.3.76 79/80 4.9.80/81
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while taxying, Rockford IL Aircraft Maintenance Specialists Inc (cargo floor & cabin door installed 10.75) American Lease Plans Inc, Charlotte NC Isd: Thomas J. Wood & Ralph Quinlan minor damage landed gear locked-up, Asheville NC op: General Aviation Inc, Greenville TN Ralph Quinlan/ Mountain Air Cargo, Denver NC Equipment Leasing Corp, Greenville SC	nway, .56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75 1.5.75 3.6.75 3.11.75/80 4.11.75/80 4.3.76 79/80 4.9.80/81 11.2.81/85
	destroyed E18S E18S	d, 4k; N46L (1 PP-ECT N34747 N474L	built Govt. Est de Minas Gerais Anderson Air Activities: CofA issued Ladish Malting Co, Milwaukee WI Ladish Malting Co, Milwaukee WI (G18S two-piece windshield installed 8.66) Ladish Malting Co, Milwaukee WI G. C. Landry/ Beechcraft Sales & Charter, East Troy WI The Polk Corp, Indianapolis IN minor damage when struck Beech A36 N3116W while taxying, Rockford IL Aircraft Maintenance Specialists Inc (cargo floor & cabin door installed 10.75) American Lease Plans Inc, Charlotte NC Isd: Thomas J. Wood & Ralph Quinlan minor damage landed gear locked-up, Asheville NC op: General Aviation Inc, Greenville TN Ralph Quinlan/ Mountain Air Cargo, Denver NC	nway, .56 65 23.10.56 1.12.56/64 10.64/71 21.6.71 18.6.71 29.6.71/75 1.5.75 3.6.75 3.11.75/80 4.11.75/80 4.3.76 79/80 4.9.80/81

N474E accident report 1.5.75: The Polk Corp, taxying for flight to Milwaukee WI, 4 on Beech unhurt;
N474E accident report 4.3.76: op "Little Mountain Air Cargo", gear mechanical failure to extend,
flight from Tricity TN, 7.45pm, pilot unhurt;
N474E noted Miami FL 28.12.81, arrived, Mountain Air Cargo;

BA-210	E18S	N52E	J. R. Gray Co, Dallas TX: CofA issued	17.10.56/58
			Hunsaker Trucking Contractor, Carrollton TX	2.2.58/69
			James A. Pope	9.6.69/70
			ran off runway on takeoff, struck ditches, Jasper TX	2.1.70
		Universal Box & Packaging, Shreveport LA	7.5.70/71	
			Dan Futrell	11.71/72
			Rodney F. McLean	15.6.72/74
			William G. Thomas	4.1.74/75

			(cargo kit installed 2.74)	
			Robert Robinson/ National Aviation	22.8.75
			Pinal County Sheriff, Tucson AZ: seized due	
			use in transportation of narcotic drugs	26.7.76/78
			Wilfred & Mary I. Dailey	15.7.78/79
			Aerospace Products Inc, North Hollywood CA	30.3.79
			Phoenix Charter Airways, St Croix USVI	7.11.79/82
			Francis J. McCarthy, St Thomas USVI	20.8.82/86
			op: Four Star Air Cargo, St Thomas USVI	84/85
			Jank Inc, Kotzebue AK	28.4.86/90
			Wade O. Kane, North Pole AK	10.90/96
			op: Alaska Airships Nicholas E. Mesmer, Baraboo WI	- 8.1.96/14
			struck-off USCR	27.10.14
	N52E notea	Dallas-Love	e TX 21.4.66;	
	N52E arrive	d Miami FL	5.5.79 operator Donaldson, no titles;	
			SVI 11.10.79 "Phoenix Charter AW",	
	N52E notea	l San Juan F	PR 17.11.79 "Phoenix Charter AW"	
	N52E notea	l San Juan F	PR 5.11.80 "Phoenix Charter AW"	
			AK 26.5.90 "Alaska Air Ships", tailwheel;	
			3 "Alaska Airships" titles, plate BA-210 built 10.56;	
	N52E at Os			
			05 open storage "Alaska Airships";	
	N52E at Os	hkosh 7.06	"Alaska Airships"; Oshkosh 7.08;	
BA-211	E18S	N54E	General Electric Co, White Plains NY	63/66
	ATE		Northern Airways Inc, Burlington VT	68/69
	Westwind II		(rebuilt by American Turbine Engine Co, Long Beach CA	50,00
	trigear		as the only ATE Westwind II, 2.08m fuselage stretch of	
			ATE Westwind I trigear, completed 23.6.68)	
		N14NA	Northern Airways Inc, Burlington VT	
		N51AN (1	renamed: Air North Inc, South Burlington VT	.69/70
		N51CS	Air North Inc, South Burlington VT	21.5.70/71
			Chicago & Southern Airlines, Chicago IL: leased	27.11.70/71
			crashed destroyed landing, Peoria IL (16 k)	21.10.71
			see Beech 18 by Robert Parmerter p.334; I only ATECO Westwind II, completed 23.6.68 for Northern	
			SA1721WE. Modifications included a 9 feet fuselage	
			27 turboprop engines, Volpar tricycle landing gear and spar	
			pax seats & crew 2, maximum gross weight 11,500lb.	
	The engine	ering for the	fuselage extension was under licence from Volpar	
			par Turboliner).	
		Long Beacl	h CA 18.9.67 trigear turbine;	
	N54E noted	d Chinar 1	laigo Eiald 6 71 "Chiange & Cautharm Airlinger" titles -turtet	od
	N51CS note	ed Chiago-M	leigs Field 6.71 "Chicago & Southern Airlines" titles, stretch	ed
	N51CS note trigear turbi	ed Chiago-M nes;		ed
	N51CS note trigear turbi crash report	ed Chiago-M nes; t 21.10.71 P	eoria IL: type ATECO Westwind II, Chicago & Southern	ed
	N51CS note trigear turbin crash report Airlines Inc,	ed Chiago-M nes; t 21.10.71 P landing in r		ed
34-212	N51CS note trigear turbin crash report Airlines Inc, struck wires	ed Chiago-M nes; t 21.10.71 P landing in r s, 14 pax, 2 c	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed;	
BA-212	N51CS note trigear turbin crash report Airlines Inc,	ed Chiago-M nes; t 21.10.71 P landing in r c, 14 pax, 2 c N39M	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built	.56
BA-212	N51CS note trigear turbin crash report Airlines Inc, struck wires	ed Chiago-M nes; t 21.10.71 P landing in r s, 14 pax, 2 c	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built Rudd Melikian Inc, Hatboro PA	.56 63
BA-212	N51CS note trigear turbin crash report Airlines Inc, struck wires	ed Chiago-M nes; t 21.10.71 P landing in r c, 14 pax, 2 c N39M	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built Rudd Melikian Inc, Hatboro PA Carl Johnstone, Longview TX	.56 63 64
BA-212	N51CS note trigear turbin crash report Airlines Inc, struck wires	ed Chiago-M nes; t 21.10.71 P landing in r c, 14 pax, 2 c N39M	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built Rudd Melikian Inc, Hatboro PA Carl Johnstone, Longview TX Plane Co, Houston TX	.56 63 64 66
BA-212	N51CS note trigear turbin crash report Airlines Inc, struck wires	ed Chiago-M nes; t 21.10.71 P landing in r c, 14 pax, 2 c N39M	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built Rudd Melikian Inc, Hatboro PA Carl Johnstone, Longview TX Plane Co, Houston TX Black Hills Glass & Mirror Co, Rapid City SD	.56 63 64 66 67/68
BA-212	N51CS note trigear turbin crash report Airlines Inc, struck wires	ed Chiago-M nes; t 21.10.71 P landing in r c, 14 pax, 2 c N39M	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built Rudd Melikian Inc, Hatboro PA Carl Johnstone, Longview TX Plane Co, Houston TX	.56 63 64 66
	N51CS note trigear turbin crash report Airlines Inc, struck wires E18S	ed Chiago-M nes; t 21.10.71 P landing in r s, 14 pax, 2 c N39M N3400 (2	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built Rudd Melikian Inc, Hatboro PA Carl Johnstone, Longview TX Plane Co, Houston TX Black Hills Glass & Mirror Co, Rapid City SD forced landing, Rapid City SD crashed destroyed landing, Rapid City SD	.56 63 64 66 67/68 11.9.67 17.3.68
BA-212 BA-213	N51CS note trigear turbin crash report Airlines Inc, struck wires	ed Chiago-M nes; t 21.10.71 P landing in r c, 14 pax, 2 c N39M	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built Rudd Melikian Inc, Hatboro PA Carl Johnstone, Longview TX Plane Co, Houston TX Black Hills Glass & Mirror Co, Rapid City SD forced landing, Rapid City SD crashed destroyed landing, Rapid City SD Anderson Air Activities: CofA issued (CofA issued 17.10.56)	.56 63 64 66 67/68 11.9.67
	N51CS note trigear turbin crash report Airlines Inc, struck wires E18S	ed Chiago-M nes; t 21.10.71 P landing in r s, 14 pax, 2 c N39M N3400 (2	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built Rudd Melikian Inc, Hatboro PA Carl Johnstone, Longview TX Plane Co, Houston TX Black Hills Glass & Mirror Co, Rapid City SD forced landing, Rapid City SD crashed destroyed landing, Rapid City SD Anderson Air Activities: CofA issued (CofA issued 17.10.56) Allis-Chalmers Manufacturing Co, West Allis WI	.56 63 64 66 67/68 11.9.67 17.3.68
	N51CS note trigear turbin crash report Airlines Inc, struck wires E18S	ed Chiago-M nes; t 21.10.71 P landing in r s, 14 pax, 2 c N39M N3400 (2	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built Rudd Melikian Inc, Hatboro PA Carl Johnstone, Longview TX Plane Co, Houston TX Black Hills Glass & Mirror Co, Rapid City SD forced landing, Rapid City SD crashed destroyed landing, Rapid City SD Anderson Air Activities: CofA issued (CofA issued 17.10.56) Allis-Chalmers Manufacturing Co, West Allis WI Gordon K. Newstrom/ Mesaba Aviation,	.56 63 64 66 67/68 11.9.67 17.3.68 17.10.56
	N51CS note trigear turbin crash report Airlines Inc, struck wires E18S	ed Chiago-M nes; t 21.10.71 P landing in r s, 14 pax, 2 c N39M N3400 (2	eoria IL: type ATECO Westwind II, Chicago & Southern ain & low cloud, descended below MDA on approach, crew all killed; built Rudd Melikian Inc, Hatboro PA Carl Johnstone, Longview TX Plane Co, Houston TX Black Hills Glass & Mirror Co, Rapid City SD forced landing, Rapid City SD crashed destroyed landing, Rapid City SD Anderson Air Activities: CofA issued (CofA issued 17.10.56) Allis-Chalmers Manufacturing Co, West Allis WI	.56 63 64 66 67/68 11.9.67 17.3.68 17.10.56

(cargo cabin door & floor installed 1.73)	
Vannoy Airfreight, Oskaloosa IA	4.75
Malcolm C. Thurmond, Georgetown TX	4.9.75/79
Starship Leasing Service, Austin TX	79
Corley M. Tedder/CMT Leasing, Texarkana TX	13.3.79/81
Isd: ABC Airlines	79/80
Clark Thurmond, Georgetown TX: skydiving ops	79/80
tailwheel collapsed landing, Dallas-Ft Worth TX	2.10.80
James L. Hudson, Mesquite TX	24.4.81/83
lsd: ABC Airlines, Dallas TX	1.12.81/82
Robert A. Nelson, Sulphur Bluff TX	24.12.83/85
James L. Hudson, Dallas-Mesquite TX	18.3.85/93
Howard Y. Sigler	4.1.93
sale rep., Dallas TX: USCR	98/05
(derelict in car wreckers yard, Mesquite TX 98/03,	
advertised for sale complete in hangar by 3.04 TT 10,403	5)
Velvet A. Carroll, Heath TX	19.4.05/13
struck-off USCR	29.4.13

N64A noted Chicago-O'Hare 21.7.73 BJ Aero Freight; Clark Thurmond recalls N64A was purchased from BJ Aero Freight in 75, he used it for skydiving at Georgetown TX for 4 years with "BJ Aero Freight" titles still on it, then sold it to Corley Tedder. Starship Leasing was an attempt to set up a freight company to use it while he retained ownership,

but never started operations (he understood that BJ Aero Freight shut down when another Beech 18 crashed c74 killing a company partner) N64A noted Oklahoma City OK 5.9.79 all white, no titles; N64A noted Dallas-Ft Worth TX 1.12.79 ABC Airlines; Letter to Beech 18 SIte from Clark Thurmond: N64A was his first 18, photo of N64A skydiving over Georgetown TX in 1979 "ABC Airlines" titles, sold it for freight in 1980; N64A accident report 2.10.80: ABC airlines, cargo flight from Abeline TX, 7.50pm; N64A noted in car breakers yard, Dallas-Mesquite TX 10.4.98 with 5 other Beech 18s; N64A noted unchanged 6.8.98 Lawson Road near Scyene Road, Mesquite; N64A noted Mesquite 9.5.03 in scrapyard near airport with other Beech 18 hulks;

BA-214	E18S U45	PT-KXP	Brasileira as U45 FAB 2879 Jose Angelo Simioni, L Paulista	.56 13.7.78/83
BA-215	E18S -9700	N67V HK-1418P	built Wichita KS J. M. McDonald, Hastings NE W. K. Enterprises Inc, Memphis TN Hernando Sequera H. Segura	10.56 63/70 72 30.12.71/72 82

## HK-1418P noted Barranquilla 28.4.82 reported as ex TANA scheme;

BA-216	E18S	ZS-CFC	Stewarts & Lloyds of South Africa Ltd, Vereeniging	1.57			
			Letaba Airways, Johannesburg-Jan Smuts	.75/77			
			Transport & Equipment Engineering Co, Baragwanath	80/81			
			Wonderair Pty Ltd, Wonderboom	85			
			minor damage, wheels-up landing, Lanseria	22.1.85			
			(ferried to Wonderboom, repaired .85)				
			Wonderair Pty Ltd, Wonderboom	5.7.85			
			Johan S. Schoeman, Tzaneen	26.2.93/10			
	ZS-CFC noted Johannesburg-Rand 27.1.68, ZS-CFC noted Wonderboom 10.75 "Letaba Lugdiens" titles, tailwheel;						
BA-217	E18S	N67A	Atlantic Aviation Services: CofA issued	31,10,56/60			
DA-211	-9700	NUTA	National Financing Inc	11.5.60/61			
	-3700		Sullivan Trail Coal Inc. Pittston PA	11.61/77			
			American Lease Plans Inc, Charlotte NC	19.7.77/81			
			Isd: Ralph Quinlan/ Little Mountain Airport Inc/	13.1.1101			
			Mountain Air Cargo, Denver NC	19.7.77/85			

(cargo cabin door & floor installed 8.77)	
op: General Aviation Inc, Greenville TN	80
Equipment Leasing Corp, Greenville SC	10.2.81/85
Mountain Air Cargo, Denver NC: leased	.81/85
Coastal States Aviation, Denver NC	1.2.85/86
forced landing in field, came to rest on road,	
Fisherville VA	25.4.85
Jim Hankins Air Service, Jackson MS	12.86/87
Triple C Aviation, Louisville MS	12.87
Eglund Air Inc, St Elmo AL:	
sale documentation not completed	c90

N67A noted Miami FL 26.5.81 arrived, Mountain Air Cargo;

accident report 25.4.85: op Mountain Air Cargo: forced landing in field due fuel expiry, came to rest on VA Route 608: no indication of extent of damage; rep. standing next to a road in Alabama in 2007;

BA-218	E18S	N73SF	J. P. Stevens & Co, New York NY	57/64
			Topeka Aircraft Sales, Topeka KS	66
			Kings Skyline Inc, Olathe KS	69
		N73JB	Jean M. Brannon, Greenville SC	70
			SMB Stage Line, Des Moines IA	17.12.71/73
			crashed destroyed landing, Tyler TX	31.5.73

photo shows N72SF, N73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.61, all tailwheel, all owned J.P.Stevens & Co; N73JB noted Muskogee OK 2.3.73 SMB Stage Line, at SMB maintenance base, N73JB noted Dallas-Love 19.5.73 SMB; N73JB accident report 31.5.73: SMB Stage Line, struck trees on final approach 2am, flight Dallas-Tyler-Longview TX, pilot fatigue a factor, 1k;

BA-219	E18S	N700M (1	Roscoe Turner Aeronautical Corp: CofA issued	7.11.56
			Inland Container Corp	9.11.56/62
		N703M	Roscoe Turner Aeronautical Corp	29.10.62
			Basler Flight Service, Oshkosh WI	2.11.62/64
			(cabin cargo tie-downs installed 12.62)	
			Johnston Container Corp, Indianapolis IN	22.1.64/68
			Arkansas Aviation Sales, Little Rock AR	10.2.69/70
			ground-loop landing, gear collapsed, Big Spring TX	24.4.69
			Golden Eagle Aviation	16.9.70
			Pioneer Bank & Trust Co	12.70/71
			Combs Airways, Billings MT	21.6.71/72
			Van Dusen Acceptance Corp, Minneapolis MN	5.6.72/76
			National Leasing Corp, Charlotte NC	30.9.76/81
			lsd: Ralph Quinlan/Mountain Air Cargo, Denver NC	9.76/86
			(cargo door & floor, cockpit pilot door installed 11.76)	
			op: General Aviation Inc, Greenville TN	79
			Equipment Leasing Corp, Greenville SC	11.2.81/85
			Coastal States Aviation, Denver NC	1.2.85/86
			P. B. Leasing Co, Naperville IL	1.7.86/90
			lsd: Viking Express, Cleveland OH	90
			crashed landing, Minneapolis MN	5.10.90

N703M accident report 24.4.69: Arkansas Aviation, Big Spring-Howard County, 30 knot winds; N703M noted Miami FL 25.8.83: Mountain Air Cargo, no titles, arrived; accident report 5.10.90: ran off runway landing, undercarriage collapsed, tailwheel;

BA-220	E18S	N2601	Mobil Oil Corp, New York NY	.56
			Socony Mobil Oil Co, New York NY	63/64
		N2621	rereg	
		N2630	Mobil Oil Corp, New York NY	66
		N2630K	damaged gear-up landing, Boston MA	19.12.68
			William Hathaway, Somerset MA	69
			Midwest Airlines, Louisville KY	70/73
			W. A. Mims Inc, Jacksonville FL	29.10.73/91

3A-221	E18S	N19R	Red Owl Stores, Minneapolis MN	63/64
	2.00	N198N	William J. Blohm, Omaha NE	66/69
		i i i i i i i i i i i i i i i i i i i	International Business Aircraft Inc, Reno NV	70
			(visited Europe 7-11.70)	
			registration pending: USCR	72
		N16572	crashed on takeoff, Reno NV	31.5.72
	London-H N16572 I	leathrow 15.1 not listed on 72	19.7.70, London-Gatwick 4.8.70 tailwheel; Glasgow 19.8.1 1.70; Glasgow 16.11.70; 2 USCR; : E18S stalled from 20 feet, 4 unhurt;	70;
3A-222	E18S	N49W	Warren Petroleum Corp, Tulsa OK	63/64
			Colonial Pipeline Co, Atlanta GA	66
			Admiral Equipment Corp, Akron OH	69/72
			Zephyr Aviation, Zephyr Hills FL	1.12.75/8
			struck-off USCR	10.81
3A-223	E18S	N38L (1	Tulsair Distributors Inc, Tulsa OK	11.56/57
			Loffland Brothers Co	19.3.57/59
			Mid-Continent Supply Co	3.11.59/6 <sup>-</sup>
			Loffland Brothers Co of Venezuela	21.3.61/62
			J. C. Scott	18.1.62
			Sunny South Aircraft Service	17.9.62/63
			J & M Transportation Co, Americus GA	16.2.63
			St Louis-San Francisco Railway, St Louis MO	10.63/64
			Gulf-Virola Corp	24.1.65
			Ortner Air Service, Wakeman OH	12.65/75
			damaged struck snowbank of takeoff, Wakeman OH	3.2.66
			Sunnyside Enterprises Inc Active Air Inc, Wakeman OH	17.1.75 12.8.75/77
			(stored Wakeman OH as a wreck 76)	12.0.75/7
			K & K Aircraft Inc, Bridgewater VA	9.4.77/89
			(owner report 7.84: aircraft destroyed/scrapped)	0.1111/00
			struck-off USCR: owner request	14.8.89
			(reg. tfd to K&K rebuild of Westwind c/n 6323)	
	N38L not	ed Wakeman-	Ortner Field OH 25.5.76 as wreck;	
3A-224	E18S	N56H	Tulsair Distributors Inc, Tulsa OK: CofA issued	29.11.56
	-9700		Flint Steel Corp	11.56/59
		NACARY	Butler Airplane Sales	29.7.59/60
		N962BH	Butler Airplane Sales	29.1.60
			Gwen C. Landry, East Troy WI	4.3.60/62
		NIGOV	Campbell Sixty-Six Express, Springfield MO	5.5.62/65
		N166X	Campbell Sixty-Six Express, Springfield MO	15.3.65/7
			Semo Aviation Inc/Semo Airways, Malden MO (cockpit emergency hatch installed 4.77)	12.71/84
			Air Machine & Services Inc, St James OH	2.2.84/86
			Hoganair Inc, Hamilton OH	19.2.86
		N76HA	Hoganair Inc, Hamilton OH	11.7.86
		N766X (2	Hoganair Inc, Hamilton OH	10.86
			The Eagle & The Hawks Inc, Middletown OH	1.11.86/94
			Miami Valley Aviation, Middletown OH	18.3.94/98
			The Eagle & The Hawks Inc, Middletown OH	29.5.98/0
			(retired, spares source for MVA at Middletown 98/07)	
			Kurt M. Yearout, Middletown OH	30.7.08/10
			struck-off USCR	26.5.10
			Columbus Zoo & Aquarium, Columbus OH: arr. by road	19.2.14/1
			(displ. in lion enclosure, all metal finish)	

N2630K noted Chicago-O'Hare 10.1.71 Midwest Airlines; N6230K noted Chicago-O'Hare 10.6.71 Midwest Airlines;

	N766X note source for N plate: conve N766X note N766X note N766X note	ed Middletov Aiami Valley erted to -970 ed Middletov ed Middletov ed Middletov	vn OH 22.7.98 stored away from Miami Valley ramp; vn OH 6.8.99 & 22.7.00: both all metallic poor condition, in v Aviation, previous reg N166X visible, plate BA-224 built 1 00 5.60; vn OH 20.7.02 still stored; vn OH 1.8.05 in hangar, spares ship for MVA who have no vn OH 17.6.06 wfu; vn OH 8.07 out on grass retired;	1.56, another
BA-225	E18S	N45M	Memphis Aero Corp, Memphis TN: CofA issued Dealers Transport Co John Morrell & Co, Chicago IL (PacAero two-piece windshield fitted 6.64) Vercoa Air Service/ Allegheny Commuter, Danville IL (cargo door installed 1.68) Golden Eagle Aviation Great Plains Realty & Development Co Southern Aviation, Lawton OK Apollo Airways, Detroit MI (cargo tie-downs fitted 3.73) renamed: Gelco Courier Services, Chicago IL	27.11.56/57 24.5.57/63 12.2.63/67 9.11.67/70 2.9.70 12.70/71 72 7.72/79 79
	N45M photo N45M noted	o c72 "Apoll d Fort Wayn	Carl W. Drebing Bob Alexander Aircraft Sales FAA file report: seized by Mexican authorities ity MO 25.7.71; o Airways" titles, tailwheel; he IN 27.5.76 Apollo Airways; style two-piece windshield;	5.4.79/80 20.6.80
BA-226	E18S	N38D	Great Lakes Pipe Line Co, Kansas City MO	63/64
		N352WB N319NF	Williams Bros Pipe Line Co, Kansas City MO damaged struck snowbank landing, Minneapolis MN rereg	66 7.1.67
	Turbo-Mod 18	N148JM	United Engines Inc, Shreveport LA Robert A. Emmett/ Turbo-Mod Co, Birmingham MI ( <i>Turbo-Mod 18</i> conversion commenced by 6.80, fitted with Lycoming TIGO-541-D turbines: not completed)	69/72 18.4.77/81
			struck-off USCR	12.3.81
BA-227	E18S	N26X N1400E	Ohio Aviation Corp, Dayton OH: CofA issued Armco Steel Corp Atwood Vacuum Machine Co, Rockford IL Aerodynamics Inc, Pontiac MI Cryderman Air Service, Pontiac MI Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc, Bridgewater VA (cargo door installed 6.79; aerial spraying system 350 gallon tank in cabin installed 7.80 for gipsy moth & mosquito spraying contracts) (retired, stored in open Bridgewater VA 3.98,	4.12.56 12.56/59 10.59/67 3.7.67/71 13.4.71 10.71/06
		ted Bridgew	stored dismantled in shed on airfield by 8.99) nn: Dynamic Avlease Inc, Bridgewater VA (completing airworthy rest. at Bridgewater Air Park 6.19) rater Air Park VA 3.98 tailwheel, wfu in open, nose remove rater VA 11.8.99 all metallic, wfu by K&K stored in "chicker	d;
	further deta	ils K&K spra ted Bridgwa	ayers: see Beech 18 by Robert Parmerter p.292;\ ter Air Park VA 6.19 almost finished long-term rest, polish	ed metallic,
BA-228	E18S	N43L	Atlantic Aviation Corp: CofA issued	13.12.56/58

Continental Pipe Line Co, Ponca City OK J. R. Hatton, Alice TX	26.2.60/66 31.8.66/72
(G18S type windshield installed 11.66) Valko T. E. DeMint, Pine Bluff AR	5.7.72/76 13.5.76/80
(cargo door installed 1.80) International Aero Sales Inc, Miami FL	5.9.80
groundlooped on takeoff, struck parked Goose N33S and 3 other parked aircraft N9423G, N203L & N9473D,	
destroyed by fire, Gainesville FL	9.9.80

N43L accident report 9.9.80: no operator quoted, pilot unknown, pax hurt, takeoff at 11.22pm for unknown destination, 132lbs over gross weight;

BA-229	E18S	N68A	Moffat Coal Co, Scranton PA	63/64
			Corporate Air Transport, Chicago IL	66/70
			Southern Aviation, Lawton OK	71/72
			Leone I. Van Torne, Van Dalia OH	25.8.76/77
			crashed destroyed by fire landing, Springfield OH	3.6.77

N68A noted Kansas City MO 12.72;

BA-230	E18S	N84D (2	Youngstown Airways, Youngstown OH	12.56/57				
			Harbison-Walker Refractories Co	2.1.57/60				
			Forrest Beckett/Beckett Aviation/					
			Youngstown Airways/ Lease Air, Youngstown OH	25.5.60/62				
		N8411	Jack Adams Aircraft Sales, Walls MS	28.7.62				
			Jack Richards Aircraft Sales	24.8.62				
			Graubart Aviation, Valparaiso IN	2.10.62/63				
	trigear		(Volpar Mk.IV trigear installed 11.62)					
	•		National Equipment Sales Inc, Elmont NY	7.2.63/66				
			Rolair Corp/ Wright Air Lnes, Cleveland OH	29.6.66/70				
			(window & windshield mods installed 8.66)					
		N404FW	Wright Air Lines, Cleveland OH	2.8.66/70				
			P. M. Bachner	2.2.71/72				
	-9700		(modified 3.71 to E18S-9700)					
			Bureau of Customs: seized South Bend IN	5.72				
		N2132M	P. M. Bachner	5.7.72/77				
		-	Northrop University, Inglewood CA	28.4.77/84				
			(retired: ground instructional airframe)					
			struck-off USCR	8.88				
			Aerospace Products Inc, North Hollywood CA	97				
		N2132M	Cameron & Stahl Inc, North Hollywood CA	6.97				
			Empire Airways Corp, Jacksonville FL & Maplewood NJ	11.8.97/99				
		(N18KG)	rereg. res: Empire Airways Corp	8.97				
		N18LK	Empire Airways Corp, Montville NJ	11.1.99				
			George J. Kaminskyj, Montville NJ	14.2.00/05				
			OTW Farms LLC, Wilmington DE	2.11.05/06				
			Holli Aero Leasing Inc, Wilmington DE	17.8.10/16				
			Gerald D. Quitney, Ennis MT	22.9.16/20				
			(moved by road dism. to Stockton CA 9.19)					
	N404FW owned Rolair, leased to Wright Airlines, Cleveland;							
	N404FW noted Ft Lauderdale FL 13.6.71 trigear;							
	"N2132" trigear advertised for sale 4.97: out of licence, ferriable, Aerospace Products; N2132M noted Chino CA 10.98 trigear; N18LK noted Chino 4.99 at Aero Trader hangar;							
	N18LK noted Chino 4.99 at Aero Trader hangar, N18LK noted Chino CA 18.8.99 trigear in Aero Trader hangar, plate BA-230 built 12.56, another plate converted to -9700 3.71; N18LK noted Chino CA 16.8.00, N18LK noted Chino CA 17.9.01 trigear;							
			27.10.18 trigeart parked flat tyres;					
BA-231	E18S	N61E	Burlington Industries Inc, Greensboro NC	63/64				
			Carolina Fleets Inc, Anderson SC	66/72				
			National Air Freight	75				
			<u> </u>					

			Santa Nella Parachute Center, Gustine CA forced landing off-airport, near Santa Nella CA struck-off USCR	6.5.76/81 20.8.77 10.81
BA-232	E18S	N75A	S. D. Warren Co, Boston MA	63/64
		N7580	Jack Adams Aircraft Sales, Walls MS	66
			op: Ambassador Airlines, Las Vegas-McCarran NV	67/68
	ATE		(conv. to ATE Westwind I trigear .68)	
	Westwind I		Carco Air Service of Nevada, Las Vegas NV	69
	trigear		Nevada National Bank, Las Vegas NV	70
	C C	N80GP	Georgia Pacific Corp, Portland OR	.71/72
			Great Western Airlines, Tulsa OK	9.74
		N201GW	Great Western Airlines, Tulsa OK	10.6.77/79
	Hamilton Westwind III		(rebuilt as Hamilton Westwind III with tail gear,	
			by Hamilton Aircraft at Tucson AZ)	
	tailgear		crashed destroyed on takeoff, Cedar Rapids IA	23.3.79

N758D noted LAX 18.8.67 Ambassador Airlines, rep. as Volpar Super Turbo: probably this acft GG; N201GW accident report 23.2.79: Great Western: stalled on takeoff on slushy runway, ice on airframe, flight to Springfield IL, pilot had high blood alcohol, 8.53pm, 2 crew k;

BA-233	E18S	N49K (1	Flightcraft Inc	7.1.57/58
			Walston Aircraft Sales & Service	1.7.58/61
		N249K	Walston Aircraft Sales & Service	6.6.61/62
			Graubart Aviation, Valparaiso IN	27.3.62/63
			Frank D. Hansen/ Hansen Air Activities, Morris IL	4.6.63/65
			James E. Kelley, Fort Wayne IN	18.2.65/67
			Glen T. Albrecht/ Air Trader, Fairfax VA	30.3.67/71
			Gilley Airways Corp, Fulton NY	6.4.71/74
			damaged, struck snowbank landing, Syracuse NY Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc,	22.12.73
			Bridgewater VA	26.1.74/11
			struck-off USCR	27.5.11

N249K accident report 22.12.73: Gilley Airways, pilot unhurt;

BA-234	E18S	N5Y (2	Southern Airways Co	7.1.57
	-9700	·	Turner-Halsey Co, New York NY	7.1.57/65
		N245RM	Riverside Manufacturing Co, Moultrie GA	12.3.65/69
		N11RM	Riverside Manufacturing Co, Moultrie GA	17.4.69/76
		N11RX	Nayak Aviation Corp	26.5.76
			Ross-Hulett International Insurors	17.8.76/78
			A. L. Sutton, Fort Davis TX	31.1.78
			Larry Murphy, Florida City FL	5.10.78/82
			(last FAA contact with owner 1982: struck-off USCR (note: BA-234 also quoted as CU-T106)	28.8.14

N11RM noted Atlanta GA 24.9.70;

BA-235	E18S	N54K	Currey Sanders Aircraft Co	11.1.57
	-9700		Interstate Oil Pipe Line Co	14.3.57/61
			Humble Pipe Line Co, Houston TX	31.7.61/66
			Miami Aviation Corp, Opa Locka FL	5.8.66/72
			landed with gear retracted, Tampa FL	8.8.67
			Gilley Airways Corp, Fulton NY	15.9.72/73
			Charles E. Rockwell/ Rockwell Farm	1.11.73/74
			George P. Tobler/ Henry Ford Plantation	15.5.74/76
			Jerry A. Lindahl, Chardon OH	4.2.76/79
			KCR Airplane Co	11.79/84
			Daniel L. Brodsky-Chenfeld, Columbus OH	5.84/86
			William S. Jones, Clewiston FL	11.86/87
			William B. Lumley, Villa Park IL, later Delray Beach FL	21.8.87/20

N54K noted Opa Locka FL 23.8.71;

BA-236       E18S       N33JD (2)       J. D. Reed Co, Houston TX       11.2.57/62         -9700       N514J       J. S. Abercrombie, Houston TX       211.62/63         N514J       L.S. Abercrombie, Houston TX       211.62/63         Aerojet       Capitol Inc, Cincinatitu, Lunken OH       82.63/65         rockets       (Capitol Avation G185 type two-picee windshield, trigger filted 1.64)       7.11.66         N5651       Southern Ohio Avation Sales, West Caroliton OH       7.11.67         Aircraft Owners Inc, Miami FL       3.467       7.11.66         Vestwind I       at Long Beach CA 3.67. PT6A-20 turbines: type also       referred to as ATE Turbine 600R         Harry H. Bassett, Miami FL       25.8.67/68       50.000 Feast Properties Financial Carriers Inc, Miami FL       2.6.37/4         Hamilton       referred to as ATE Turbine 600R       Harry H. Bassett, Miami FL       2.7.67       2.5.37/7         Hamilton       referred to as ATE Turbine 600R       Harry H. Bassett, Miami FL       2.7.67       2.5.37/7         Hamilton       referred to as ATE Turbine 600R       Harry H. Bassett, Miami FL       2.7.67       2.5.37/7         Hamilton       referred to as ATE Turbine 600R       Harry H. Bassett, Miami FL       2.7.67       2.5.37/7         Hamilton       reburbine Aveant Co, Turbine Aveant Co ton 2.							
N514.J     J. S. Abercombie, Houston TX     2.1122/63       Aerojet     CAerojet rockets fitted 4.63)     62.63/65       rockets     rockets     rockets       N56S     Americal Avaiton G18S type two-piece windshield.     164       N56S     Southern Ohio Aviation Sales, West Caroliton OH     7.15       N56S     American Management Association inc, Hamilton NY     22.765       N56S     Arcraft Owners Inc, Miami FL     3.467       ATE     (rebuilt by American Turbine Arcraft Co to ATE Westwind J     at Long Beach CA 3.67: PT6A-20 turbines: type also       referred to as ATE Turbine 600R)     11.66/67     3.4.67       Westwind I     at Long Beach CA 3.67: PT6A-20 turbines: type also     12.6.7374       Hamilton     (rebuilt by American Co, Orlando FL     2.7.0       N909CP     Georgia Pacific Corp, Portland OR     25.3.7073       Hamilton     (rebuilt as <i>Hamilton Westwind III</i> trigear replaced with     conventional landing gear, cargolaristari door,       Cockpit door, Hamilton extended cargo nose:     completed by Hamilton 5.74     15.5.74/79       Check-Air Inc, Milwaukee WI     20.8.74     FFC Inc     4.10.74/86       Isd: Mountain Air Cargo, Denver NC     4.10.74/86     3.80       Isd: Mountain Air Cargo, Denver NC     5.86/89     4.79       Mountain Air Cargo, Denver NC     5.86/89 <t< td=""><td>BA-236</td><td>E18S</td><td>N33JD (2</td><td>J. D. Reed Co, Houston TX</td><td>11.2.57</td></t<>	BA-236	E18S	N33JD (2	J. D. Reed Co, Houston TX	11.2.57		
N514.JH Executair Inc. Cincinatti-Lunken OH 8.2.63/65 Aerojet (Capitol Aviation G185 type two-piece windshield, trigear windows, Volpar Mk/ V trigear filted 1.64) N565 N5681 Southern Ohio Aviation Sales, West Carollton OH 7.11.66 Aircraft Owners Inc, Miami FL 11.66/67 Aircraft Owners Inc, Miami FL 11.66/67 Aircraft Owners Inc, Miami FL 22.7.65 Aircraft Owners Inc, Miami FL 25.8.67/68 Southern Sinc, Miami FL 25.8.67/68 N909CP Georgia Pacific Corp. Optimum Corp. 25.8.67/68 Southern Airways Co, Orfando FL 27.70 N909CP Georgia Pacific Corp. Optimum Corp. 25.8.70/73 Harry H. Basett, Miami FL 25.8.67/68 Southern Airways Co, Orfando FL 27.70 N909CP Georgia Pacific Corp. Optimum Corp. 25.8.70/73 Hamilton (rebuilt as <i>Hamilton Westwind II</i> trigger replaced with conventional landing gear, cargo/airstair door, cockpit door, Hamilton S.74) Tobey Inc. Belgrade Lakes ME 15.5.74/79 Check-Air Inc, Milwaukee WI 20.8.77 Check-Air Inc, Milwaukee WI 20.8.79 Mountain Air Cargo, Denver NC 4.10.74/89 Isd: Mountain Air Cargo, Denver NC 4.10.74/89 Isd: Mountain Air Cargo, Denver NC 5.86/89 Karl D & Kenneth A. Stolutzu's K & Aircraft Inc, Bridgewater VA 26.9.89/06 (rebuilt by K&K 11.91, cabin windows skinned over, ag. & pest control category, ColA renewed 29.4.94) Brazona County Mosquito Control, Angleton TX 21.4.10/16 County Mosquito Control, Angleton TX 21.4.10/16 Southers VA 28.74 turbine Tobey' titles; N909CP noted Cinton County NY 22.8.74 turbine Tobey' titles; N909CP noted Cinton County NY 22.8.74 turbine Tobey' titles; N909CP noted Cis Alamitos CA 17.8.9 Westwind III tailgear; N909CP noted Los Alamitos CA 17.8.9 Westwind III tailgear; N909CP noted Cis Alamitos CA 17.8.9 Westwind III tailgear; N909CP noted Los Alamitos CA 17.8.9 Westwind III tailgear; N909CP noted Cis Alamitos CA 17.8.9 Westwind III tailgear; N909CP		-9700	N514T	Tennessee Gas & Transmission Co, Houston TX	18.4.57/62		
Aerojet       (Aerojet rockets fitted 4.63)         rockets       (Capitol Aviation G185 type two-piece windshield, picture windows, Volpar Mk.IV trigear fitted 1.64)         N5681       Southern Ohio Aviation Sales, West Carollton OH       71.166         N7875       Aircraft Owners Inc, Miami FL       34.67         N7875       Aircraft Owners Inc, Miami FL       34.67         ATE       (rebuilt by American Turbine Aircraft Co to ATE Westwind 1       at Long Beach CA 3.67: PT6A-20 turbines: type also referred to as ATE Turbine 600R)       25.07         Westwind 1       at Long Beach CA 3.67: PT6A-20 turbines: type also       26.07       27.00         Southern Aircraft Co, Tucson AZ       23.70/73       12.6.73/74         Hamilton Aircraft Co, Tucson AZ       12.6.73/74       12.6.73/74         Hamilton Aircraft Co, Tucson AZ       12.6.73/74       12.6.73/74         Hamilton Aircraft Co, Tucson AZ       12.6.73/74       15.5.74/79         Westwind III       conventional landing gear, cargo/airstair door,       20.8.74         HFC Inc       4.10.74/88       15.5.74/79         Check-Air Inc, Milwaukee WI       20.8.74         FFC Inc       4.10.74/88       5.79         Isd: Mountain Air Cargo, Denver NC       3.80       26.9.89/90         Coastal States Aviation, Denver NC       5.86/89			N514J	J. S. Abercrombie, Houston TX	2.11.62/63		
rockeis (Capitol Aviation G18S type two-piece windshield, trigear picture windows, Volgar MkU Virgear fitted 1.64) N56S Southern Ohio Aviation Sales, West Carollton OH 7,11.66 N578T Aircraft Owners Inc, Miami FL 3,4.67 ATE (rebuilt by American Turbine Aircraft O to ATE Westwind / at Long Beach CA 3, 67: P16A-20 turbines: type also referred to as ATE Turbine 600P) Harry H, Bassett, Miami FL 25.8,67/68 Southern Airways Co. Oriando FL 22,70 N909GP Georgia Pacific Corp. Portland OR 25.3,70/73 Harrilton (rebuilt by American Turbine store) trigear 12,67374 Hamilton (rebuilt as Hamilton Westwind II: trigear replaced with conventional landing gear, cargolaistair door, cockpit door, Hamilton Szies, Westwind II: trigear replaced with Cockpit door, Hamilton Szies, Westwind II: trigear replaced with cockpit door, Hamilton Szies, Westwind III: trigear replaced With Cocket Air Inc, Milwaukee WI 20, 57, HFC Inc 4, 10, 74/89 Isd: Check-Air Inc, Milwaukee WI 78/79 Check-Air Inc, Milwaukee WI 78/79 Check-Air Inc, Milwaukee WI 78/79 Check-Air Inc, Milwaukee WI 78/79 Nountain Air Cargo, Denver NC 5,86/99 Karl D, & Kenneth A. Stolzfusir K & Kaircraft Inc, Bridgewater VA 26,9,89/06 Create Salar States Aviation, Denver NC 5,86/99 Karl D, Z & Kenneth A. Stolzfusir K & KAircraft, sprayer, "K& Kaircraft" titles, plate: BA-236 built 157; N909GP noted Cinton County NY 22,8,74 turbine "Tobey" titles; N909GP noted Des Moines IA 7,18,90 Westwind III tailgear; N909GP noted Des Moines IA 7,18,90 Westwind III tailgear; N909GP noted Des Moines IA 7,18,90 Westwind III tailgear; N909GP noted Des Moines IA 7,18,90 Westwin			N514JH	Executair Inc, Cincinatti-Lunken OH	8.2.63/65		
trigear       picture windows, Volpar Mk. IV trigear fitted 1.64)         NS65       American Management Association Inc, Hamilton NY       22.7.65         N787S       Aircraft Owners Inc, Miami FL       3.4.67         ATE       (rebuilt by American Turbine Aircraft Co to ATE Westwind 1       at Long Beach CA 3.67: PTGA-20 turbines: type also         trigear       referred to as ATE Turbine 600R)       12.5.8.67/68         Southeast Properties/ Financial Carriers Inc, Miami FL       12.68/70         N905GP       Georgia Pacific Corp, Portland OR       25.3.70/73         Hamilton       corpt Hing Gear, cargo/airstair door, cockpit door, Hamilton extended cargo nose:       completed by Hamilton 5/41         Vestwind III       cockpit door, Hamilton extended cargo nose:       completed by Hamilton 5/41       10.74/89         Isd: Check-Air Inc, Milwaukee WI       20.8.74       70.74/89       16.5.74/79         Check-Air Inc, Milwaukee WI       78/79       Check-Air Inc, Milwaukee WI       78/79         Check-Air Inc, Milwaukee WI       78/79       56/89       53.0         Coastal States Aviation, Denver NC		Aerojet		(Aerojet rockets fitted 4.63)			
NS65       American Management Association Inc, Hamilton NY       22.7.65         NS681       Southern Ohio Aviation Sales, West Caroliton OH       7.11.66         N787S       Aircraft Owners Inc, Miami FL       34.67         ATE       (rebuilt by American Turbine Aircraft Co to ATE Westwind I       at Long Beach CA 367: PTGA-20 turbines: type also         triggear       referred to as ATE Turbine 600P)       25.8.67/68         Harry H. Bassett, Miami FL       25.8.67/68         Southers Alrways Co, Orlando FL       25.8.37/74         Hamilton Aircraft Co, Tucson AZ       12.6.73/74         Hamilton Aircraft Co, Tucson AZ       12.6.74/77 <tr< td=""><td></td><td>rockets</td><td></td><td>(Capitol Aviation G18S type two-piece windshield,</td><td></td></tr<>		rockets		(Capitol Aviation G18S type two-piece windshield,			
NS681       Southern Ohio Áviation Sales, West Carollton OH       11.66/67         N787S       Aircraft Owners Inc, Miami FL       34.67         ATE       (rebuilt by American Turbine Aircraft Co to ATE Westwind I       at Long Beach CA 3.67: PT6A-20 turbines: type also         Irigear       referred to as ATE Turbine 400R)       Lang Beach CA 3.67: PT6A-20 turbines: type also         N809GP       Context, Miami FL       25.8.67/68         Southeast Properties/ Financial Carriers Inc, Miami FL       26.8.77/63         N809GP       Georgia Pacific Corp, Portland OR       25.3.70/73         Hamilton       (rebuilt as Hamilton Vestwind III: trigear replaced with       Check-Air Inc, Milwauke         Westwind III       conventional landing gear, cargo/airstair door,       cockpit door, Hamilton extended cargo nose:         completed by Hamilton 5.74       Tobey Inc, Belgrade Lakes ME       15.5.74/79         Check-Air Inc, Milwaukee WI       20.8.74       6.79         Kountain Air Cargo, Denver NC       4.10.74/88       1.074/88         Isd: Check-Air Inc, Milwaukee WI       8.79       6.86/69         Kart D. & Kemeich A.S tolztus K & Aircraft Inc,       8.60       6.20.89/06         Groby Droted Clinton Country NY 22.8.74 turbine "Tobey" titles;       N909GP noted Clinton Country NY 22.8.74 turbine "Tobey" titles;       N909GP noted Los Alamitos CA 13.8.02 with other K&K		trigear		picture windows, Volpar Mk.IV trigear fitted 1.64)			
Aircraft Owners Inc, Miami FL       34.67         ATE       34.67         (rebuilt by American Turbine Aircraft Co to ATE Westwind I       at Long Beach CA 3 67: PTGA-20 turbines: type also         trigear       referred to as ATE Turbine 600R)         Harry H. Bassett, Miami FL       25.8.57/68         Southeast Properties Financial Carriers Inc, Miami FL       12.68/70         N909GP       Georgia Pacific Corp, Portland OR       25.3.70/73         Hamilton (rebuilt as Hamilton Westwind II): trigear replaced with conventional landing gear, cargo/airstair door, tailing even cargo pince Begrande Lakes ME       15.5.74/79         Vestwind III       cockpil door, Hamilton extended cargo nose: completed by Hamilton 5.74)       70 begv Inc. Begrande Lakes ME       15.5.74/79         Check-Air Inc, Milwaukee WI       20.8.74       87/9       70/74/88         Isd: Mountain Air Cargo, Denver NC       4.10.74/88       13.6/89         Isd: Mountain Air Cargo, Denver NC       5.86/99       8.87         Kart D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc.       Bridgewater VA       26.9.89/06         (rebuilt by Kaki 11.91, cabin windows skinned over, ag. & pest control category. Coff. renewed 29.49.49       19.16/20         N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles;       N909GP noted Des Moines U.5.79" Check Air" titles;       14.10.16         N909GP noted Des Moines U.5.79" Ch			N56S	American Management Association Inc, Hamilton NY	22.7.65		
N787S       Aircraft Owners Inc. Miami FL       3.4.67         ATE       (rebuil by American Turbine Aircraft Co to ATE Westwind I         at Long Beach CA 3.67: PT6A-20 turbines: type also       referred to as ATE Turbine 600R)         Harry H. Bassett, Miami FL       25.8.67/68         Southeast Properties/ Financial Carriers Inc, Miami FL.       12.6870         N909GP       Georgia Pacific Corp. Portland OR       25.3.70/73         Hamilton       (rebuilt as Hamilton Westwind III: trigger replaced with       25.3.70/73         Hamilton       (rebuilt as Hamilton Westwind III: trigger replaced with       26.7.74         Westwind III       cockpit door, Hamilton extended cargo nose:       20.8.74         completed by Hamilton 5.74)       Tobey Inc, Beigrade Lakes ME       15.5.74/79         Check-Air Inc, Milwaukee WI       20.8.74       10.74/86         Isd: Mountain Air Cargo, Denver NC       4.10.74/86       15.6         Isd: Mountain Air Cargo, Denver NC       3.80       26.9.89/06         Coastal States Aviation, Denver NC       5.86/69       26.9.89/06         Karl D, & Kenneth A. Stoltztus/ K & K Aircraft Inc,       Bridgewater VA       26.9.89/06         V909GP noted Clinton County NY 22.8.74 furbine "Tobey" titles;       N909GP noted Los Alamitos CA 11.8.92 Westwind III tailgear;       N909GP noted Clinton County NY 22.8.74 furbine "Tobey" t			N5681	Southern Ohio Aviation Sales, West Carollton OH	7.11.66		
ATE       (rebuilt by American Turbine Aircraft Co to ATE Westwind I         Westwind I       at Long Beach CA 3.67; PT6A-20 turbines: type also         trigear       referred to as ATE Turbine 600R)         Harry H. Bassett, Miami FL       12.68/70         Southeast Properties/ Financial Carriers Inc, Miami FL       12.67/74         N909GP       Georgia Pacific Corp, Portland OR       25.3.07/3         Hamilton       (rebuilt as Hamilton Vestwind III: trigear replaced with         vestwind II       conventional landing gear, cargo/aistair door.       12.6.73/74         Hamilton       (rebuilt as Hamilton extended cargo nose:       20.8.74         completed by Hamilton Part Mill II: trigear replaced with       20.8.74       74/79         Vestwind II       conventional landing gear, cargo/aistair door.       15.5.74/79         Tobey Inc. Belgrade Lakes ME       15.5.74/79       20.8.74         Tobey Inc. Belgrade Lakes ME       15.5.74/79         Check Air Inc, Milwaukee WI       70/79         Sci Check Air Inc, Milwaukee WI       8.79         Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/99         Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc,       Brazonia County Mesquito Control, Angleton TX       21.4.10/16         Countryside Aviation, Chitto				Aircraft Owners Inc, Miami FL	11.66/67		
Westwind I       at Long Beach CA 3.67: PT6A-20 turbines: type also trigear       referred to as ATE Turbine 600R) Harry H. Bassett, Miami FL       25.8.67/68         N909GP       Georgia Pacific Corp, Portland OR       2.70         N909GP       Georgia Pacific Corp, Portland OR       2.70         Hamilton Aircraft Co, Tucson AZ       12.68/70         Westwind II       coventional landing gear, cargo/airstair door, cockpit door, Hamilton Setwind III: trigear replaced with Westwind III       25.3.70/73         Hamilton       cockpit door, Hamilton Extended cargo nose: completed by Hamilton 5.74/79       20.8.74         Tobey Inc, Belgrade Lakes ME       15.5.74/79         Check-Air Inc, Milwaukee WI       20.8.74         FFC Inc       4.10.74/86         Isd: Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/89         Kari D, & Kenneth A. Stoltzfus/ K & K Aircraft Inc, Bridgewater VA       26.9.89/06         (rebuil by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94)       21.4.10/16         Brazonia County Mosquito Control, Angleton TX       6.9.89/06         WordsGP noted Clinton County NY 22.8.74 turbine "Tobey" titles: N900GP noted Des Moines L6 3.78 "Orcheck-Air" titles: N900GP noted Los Alamitos CA 17.8 99 Westwind III tailgear; N900GP noted Los Alamitos CA 17.8 99 Westw			N787S	Aircraft Owners Inc, Miami FL	3.4.67		
trigear       referred to as ATE Turbine 600R)       25.8.67/68         Harry H. Bassett, Miami FL       25.8.67/68         Southeast Properties/ Financial Carriers Inc, Miami FL       12.68/70         N909GP       Gergia Pacific Corp, Portland OR       25.3.7073         Hamilton       (rebuilt as Hamilton Vestwind III: trigear replaced with conventional landing gear, cargo/airstair door.       12.6.7374         Hamilton       (rebuilt as Hamilton vestwind III: trigear replaced with conventional landing gear, cargo/airstair door.       15.5.74/79         Ialigear       conventional landing gear, cargo/airstair door.       4.10.74/88         Isd: Mountain Air Cargo, Denver NC       4.10.74/89         Isd: Mountain Air Cargo, Denver NC       5.86/89         Karl D. & Kerneth A. Stolztus/ K & K Aircraft Inc, Bridgewater VA       26.9.89/06         Varidge Aviation, Denver NC       5.86/89         Karl D. & Kerneth A. Stolztus/ K & K Aircraft Inc, Bridgewater VA       26.9.89/06         Varidge Aviation, Chilton Wi       6.9.16/20         N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP noted Minwakee WI 1.9.78 "Check Air" titles; N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear; N909GP noted Los Alamitos CA 13.8.02 with other K& K grayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;         BA-237       E18S -9700 <td< td=""><td></td><td>ATE</td><td></td><td>(rebuilt by American Turbine Aircraft Co to ATE Westwind</td><td>dl</td></td<>		ATE		(rebuilt by American Turbine Aircraft Co to ATE Westwind	dl		
Harry H. Bassett, Miami FL       25.8 67/68         Southeast Properties/ Financial Carriers Inc, Miami FL       27.0         N909GP       Georgia Pacific Corp, Portland OR       27.0         Hamilton Aircraft Co, Tucson AZ       12.6.7374         Hamilton Micraft Co, Tucson AZ       12.6.7374         Hamilton Aircraft Co, Tucson AZ       15.5.74/79         Check Air Inc, Milwaukee WI       20.8.74         FCC Inc       4.10.74/86         Isd: Check Air Inc, Milwaukee WI       8.79         Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/89         Karl D. & Kenneth A. Stolzfus/ K & Aircraft Inc,       8.79         Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Chilton WI       6.9.16/20         N909GP noted Clinton County NV 22.8.74 turbine "Tobey" titles;       N909GP noted Milwaukee WI 19.78 "Check Air" titles, Westwind III taitgear:         N909GP n		Westwind I					
Southera Kirvays Co, Orlando FL       12.68/70         N909GP       Georgia Pacific Corp, Portland OR       25.3.70/73         Hamilton       (rebuilt as Hamilton Vestwind III: trigear replaced with conventional landing gear, cargo/airstair door, tailgear       12.6.73/74         Hamilton       (rebuilt as Hamilton Vestwind III: trigear replaced with conventional landing gear, cargo/airstair door, toople Inc, Belgrade Lakes ME       15.5.74/79         Tobey Inc, Belgrade Lakes ME       15.5.74/79         Check-Air Inc, Milwaukee WI       20.8.74         FFC Inc       4.10.74/88         Isd: Mountain Air Cargo, Denver NC       4.10.74/88         Isd: Mountain Air Cargo, Denver NC       5.86/89         Karl D & Kenneth A. Stoltzfus/ K & K Aircraft Inc, Bridgewater VA       26.9.89/06         Criebuil by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94)       Brazoria Countly Mosquito Control, Angleton TX       21.4.10/16         N909GP noted Clinton Countly MY 22.8.74 turbine "Tobey" titles; N909GP noted Milwaukee WI 1.9.76 "Check-Air" titles; N909GP noted Los Alamitos CA 17.8.99 Westwind III to service with K&K Aircraft, sprayer, "K&K Aircraft" titles, Jotate AJ. 3.09 Westwind III to service with K&K Aircraft, sprayer, "K&K Aircraft" titles, Jotate AJ. 3.79 "Check-Air" titles; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;         BA-237       E18S       N57H       built		trigear		referred to as ATE Turbine 600R)			
Southern Airways Co, Orlando FL         2.70           N909GP         Georgia Pacific Corp, Portland OR         25.3.70/73           Hamilton Aircraft Co, Tucson AZ         12.6.73/74           Hamilton Aircraft Co, Tucson AZ         15.5.74/79           Conck Air Inc, Milwaukee WI         20.8.74           Har Cargo, Denver NC         4.10.74/88           Isd: Check-Air Inc, Milwaukee WI         8.79           Mountain Air Cargo, Denver NC         3.80           Coastal States Aviation, Denver NC         5.86/89           Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc,         Brazoria County Mosquito Control, Angleton TX           J. Hardgewater VA         26.9.89/06           (rebuil by K&K 11.91, cabin windows skinned over,         3.80           J. Sountry MY 22.8.74 turbine "Tobey" titles; <t< td=""><td></td><td></td><td></td><td></td><td>25.8.67/68</td></t<>					25.8.67/68		
N909GP     Georgia Pacific Corp, Portland OR     25.3.70/73       Hamilton     (rebuilt as Hamilton Aircraft Co, Tucson AZ     12.6.73/74       Hamilton     (rebuilt as Hamilton Westwind III: triggear replaced with     12.6.73/74       tailgear     cocxpit door, Hamilton extended cargo nose:     completed by Hamilton 5.74)       Tobey Inc, Belgrade Lakes ME     15.5.74/79       Check-Air Inc, Milwaukee WI     20.8.74       Linc, Milwaukee WI     20.8.74       Bist: Mountain Air Cargo, Denver NC     4.10.74/86       Ist: Mountain Air Cargo, Denver NC     3.80       Coestal Ator, Milwaukee WI     8.79       Mountain Air Cargo, Denver NC     3.80       Coastal States Aviation, Denver NC     5.66/89       Karl D. & Kenneth A. Stottzys K & K Aircraft Inc,     Bridgewater VA       Check Air Inc, Milwaukee WI     29.9.89/06       (rebuilt by K&K 11.91, cabin windows skinned over,     ag. & pest control category, CoAr enewed 29.4.94)       Brazoria County My S2.8.74 turbine "Tobey" titles;     N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles;       N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles;     N909GP noted Los Alamitos CA 17.8.99 Westwind III aligear;       N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft ittles, Slas quotes N568M for BA-236, RP says was typo for N5681;       BA-237     E18S     N57H     built							
Hamilton       Itentiton       (rebuilt as Hamilton Westwind III: trigear replaced with conventional landing gear, cargo/airstair door, cockpit door, Hamilton extended cargo nose: completed by Hamilton 5.74)       15.5.74/79         Tobey Inc, Belgrade Lakes ME       15.5.74/79         Check-Air Inc, Milwaukee WI       208.74         FFC Inc       4.10.74/86         Isd: Mountain Air Cargo, Denver NC       4.10.74/86         Isd: Check-Air Inc, Milwaukee WI       78/79         Check Air Inc, Milwaukee WI       78/79         Check Air Inc, Milwaukee WI       78/79         Check Air Inc, Milwaukee WI       78/79         Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/89         Karl D, & Kenneth A. Stoltzfus/ K & Kaircraft Inc,       Bridgewater VA         (rebuilt by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94)       21.4.10/16         Countryside Aviation, Chilton WI       6.9.16/20         N909GP noted Clinton Country NY 22.8.74 turbine "Tobey" titles; N909GP noted Des Moines 14.5.79 "Check-Air" titles; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft ittles, plete: BA-236 built 1.57; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft ittles, plete: BA-236 built 1.57; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N566M for BA-236, R							
Hamilton       (rebuilt as Hamilton Westwind III: trigear replaced with Westwind III         tallgear       cockpit door, Hamilton extended cargo nose: completed by Hamilton 5.74)         Tobey Inc, Belgrade Lakes ME       15.5.74/79         Check-Air Inc, Milwaukee WI       20.8.74         FFC Inc       4.10.74/86         Isd: Mountain Air Cargo, Denver NC       4.10.74/86         Isd: Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/89         Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc, Bridgewater VA       26.9.89/06         Coastal States Aviation, Denver NC       5.86/89         Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc, Bridgewater VA       26.9.89/06         Wountain Air Cargo, Denver NC       1.0.1/16         Brazoria County Mosquito Control, Angleton TX       21.4.10/16         Brazoria County Mosquito Control, Angleton TX       21.4.10/16         N909GP noted Dis A swestwind III:       11 tailgear:         N909GP noted Jibwawkee WI 19.78 "Check Air" titles;       N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear:         N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft ittles, Jale Alamitos CA 13.8.02 with other K&K sprayers;         Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;         BA-237 <td< td=""><td></td><td></td><td>N909GP</td><td></td><td></td></td<>			N909GP				
Westwind III       conventional landing gear, cargo/airstair door, cockpil door, Hamilton extended cargo nose: completed by Hamilton 5.74)         Tobey Inc, Belgrade Lakes ME       15.5.74/79         Check-Air Inc, Milwaukee WI       20.8.74         FFC Inc       4.10.74/86         Isd: Check-Air Inc, Milwaukee WI       78/79         Check-Air Inc, Milwaukee WI       8.79         Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/89         Karl D. & Kenneth A. Stoltzfus/K & K Aircraft Inc, Bridgewater VA       26.9.89/06         Grebult by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94)       Brazoria County Mosquito Control, Angleton TX       21.4.10/16         Sountryside Aviation, Chilton WI       6.9.16/20       N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.09 Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.00 with other K&K sprayers; Beech 18 by Parmeter index also quotes N568M for BA-236, RP says was typo for N5681;         BA-237       E18S       N57H       built       .57 <td></td> <td></td> <td></td> <td></td> <td>12.6.73/74</td>					12.6.73/74		
tailgear       cockpit door, Hamilton extended cargo nose: completed by Hamilton 5.74)         Tobey Inc, Beigrade Lakes ME       15.5.74/79         Check-Air Inc, Milwaukee WI       20.8.74         FFC Inc       4.10.74/86         Isd: Mountain Air Cargo, Denver NC       4.10.74/86         Isd: Mountain Air Cargo, Denver NC       3.80         Check Air Inc, Milwaukee WI       8.79         Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/89         Karl D. & Kenneth A. Stoltzfus/K & K Aircraft Inc,         Bridgewater VA       26.9.89/06         (rebuilt by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94)         Brazoria County NY 22.8.74 turbine "Tobey" titles;         N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles;         N909GP noted Des Moines IA 5.79         N909GP noted Los Alamitos CA 17.8.99 Westwind III ailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III ailgear;         N909GP noted Los Alamitos CA 17.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;         BA-237       E18S       N57H       built       .57         .9700       CF-TAB       Timmins Aviatio Ltd, Montreal QUE       .57         .9700       CF-TAB       Timmins Aviatio CAT, B.20 Lok							
completed by Hamilton 5.74)Tobey Inc, Belgrade Lakes ME15.5.74/79Check-Air Inc, Milwaukee WI20.8.74FFC Inc4.10.74/86Isd: Mountain Air Cargo, Denver NC4.10.74/86Isd: Mountain Air Cargo, Denver NC4.10.74/86Isd: Check-Air Inc, Milwaukee WI8.79Mountain Air Cargo, Denver NC3.80Coekt Air Inc, Silwaukee WI8.79Mountain Air Cargo, Denver NC5.86/89Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc,Bridgewater VA26.9.89/06(rebuilt by K&K 11.91, cabin windows skinned over,ag, & pest control category, CofA renewed 29.4.94)Brazoria County Mosquito Control, Angleton TX21.4.10/16Countryside Aviation, Chilton WI6.9.16/20N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles;N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer,"K&K Aircraft" titles, plate: BA-236 built 1.57;N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer,"K&K Aircraft" titles, plate: BA-236 built 1.57;N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer,"K&K Aircraft" titles, plate: BA-236 built 1.57;N909GP noted Los Alamitos CA 17.8.90 Westwind III in service with K&K Aircraft, sprayer,"K&K Aircraft" titles, plate: BA-236 built 1.57;N909GP noted Los Alamitos CA 17.8.02 with other K&K sprayers;Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;BA-237E18SN57Hbuilt			11				
Tobey Inc, Belgrade Lakes ME       15.5.74/79         Check-Air Inc, Milwaukee WI       20.8.74         HFC Inc       4.10.74/86         Isd: Mountain Air Cargo, Denver NC       4.10.74/86         Isd: Check-Air Inc, Milwaukee WI       8.79         Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/89         Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc, Bridgewater VA       26.9.89/06         (rebuilt by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94)       21.4.10/16         Brazoria County Mosquito Control, Angleton TX       21.4.10/16         Countryside Aviation, Chilton WI       6.9.16/20         N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP noted Des Moines IA 5.79       Check Air" titles;         N909GP noted Des Moines IA 5.79       Check Air" titles;       N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57;       N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;         BA-237       E18S       N57H       built       .57         -9700       CF-TAB       Timmins Aviatio Ltd, Montreal QUE       .57         -9700       CF-TAB		tailgear					
Check-Air Inc, Milwaukee WI       20.8 74         FFC Inc       4.10.74/86         Isd: Mountain Air Cargo, Denver NC       4.10.74/86         Isd: Check-Air Inc, Milwaukee WI       8.79         Mountain Air Cargo, Denver NC       3.80         Coestal States Aviation, Denver NC       5.86/89         Karl D. & Kenneth A. StoltZfus/ K & K Aircraft Inc,       Bridgewater VA				, ,			
FFC Inc       4.10.74/86         Isd: Mountain Air Cargo, Denver NC       4.10.74/89         Isd: Check-Air Inc, Milwaukee WI       78/79         Check Air Inc, Milwaukee WI       8.79         Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/89         Bridgewater VA       26.9.89/06         (rebuilt by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94)         Brazoria County Mosquito Control, Angleton TX       21.4.10/16         Countryside Aviation, Chilton WI       6.9.16/20         N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles;       N909GP noted Milwaukee WI 19.78 "Check Air" titles;         N909GP noted Des Moines IA 5.79 "Check Air" titles;       N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear;         N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57;       N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers;         Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;       57         BA-237       E18S       N57H         9700       CF-TAB       Timmins Aviatio Ltd, Montreal QUE       .57         -9700       CF-TAB       Transair Ltd, St James MAN       Steep Rock Iron Mines Ltd, Atikokan ONT       .65/66							
Isd: Mountain Air Cargo, Denver NC       4.10.74/89         Isd: Check-Air Inc, Milwaukee WI       78/79         Check Air Inc, Milwaukee WI       8.79         Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/89         Karl D. & Kenneth A. Stoltztus/ K & K Aircraft Inc, Bridgewater VA       26.9.89/06         (rebuilt by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94)       Brazoria County Mosquito Control, Angleton TX       21.4.10/16         N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP noted Des Moines IA 5.79 "Check Air" titles;       N909GP noted Des Moines IA 5.79 "Check Air" titles;       N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.90 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;         BA-237       E18S       N57H       built       .57         -9700       CF-TAB       Timmins Aviation Ltd, Montreal QUE       .57         Transair Ltd, St James MAN       Steep Rock Iron Mines Ltd, Atlikokan ONT       .66         N12421       Miami Aviation Corp, Opa Locka FL       47.66         N380MA       Miami Aviation Corp, Opa Locka FL       12.66/68         Dee Howard Co, San Antonin TX							
Isd: Check-Air Inc, Miiwaukee WI       78/79         Check Air Inc, Miiwaukee WI       8.79         Mountain Air Cargo, Denver NC       3.80         Coastal States Aviation, Denver NC       5.86/89         Karl D. & Kenneth A. Stolizfus/ K & K Aircraft Inc,       Bridgewater VA         Bridgewater VA       26.9.89/06         (rebuilt by K&K 11.91, cabin windows skinned over,       ag. & pest control category, CofA renewed 29.4.94)         Brazoria County Mosquite Control, Angleton TX       21.4.10/16         Brazoria County Mosquite Control, Angleton TX       21.4.10/16         N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles;       N909GP noted Dimes IA 5.79 "Check Air" titles;         N909GP noted Dimes IA 5.79 "Check Air" titles;       N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear;         N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57;       N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57;         N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57;       Steep Rock Iron Mines Ltd, Montreal QUE       .57         -9700       CF-TAB       Timmins Aviation Corp, Opa Locka FL       4.7.66         N12421       Miami Aviation Corp, Opa Locka FL       12.66/68							
BA-237       E18S       N57H       built       .57         CF-TAB       Timmins Aviation Corp. Opa Locka FL       .57       .57         Tansair Ltd, St James Ltd, Atikokan ONT       .65       .66         N12421       Miami Aviation Corp. Opa Locka FL       .57       .73         BA-237       E18S       N57H       built       .57         -9700       CF-TAB       Timmins Aviation Corp. Opa Locka FL       .57         Castal Aviation       .73.73/840       .22.4.66/68         Dee Howard Co, San Antonio TX       .21.4.76       .26.9/76         De Howard Co, San Antonio TX       .27.3.73/840       .27.3.73/840         De Howard Co, San Antonio TX       .21.5.68/69       .21.66/68         De Howard Co, San Antonio TX       .21.66/68       .22.4.69/76							
Mountain Air Cargo, Denver NC3.80Coastal States Aviation, Denver NC5.86/89Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc, Bridgewater VA26.9.89/06(rebuilt by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94) Brazoria County Mosquito Control, Angleton TX21.4.10/16 6.9.16/20N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP noted Milwaukee W1 19.78 "Check Air" titles; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, IA-236 built 1.57; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, BA-236 built 1.57; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;BA-237E18SN57H Timmins Aviatio Ltd, Montreal QUE Commander Aviation Ltd.57 .57 .57 .57 .57 .57 .57 .5700BA-237E18SN57H Timmins Aviatio Crop, Opa Locka FL N380MA4.7.66 .66 .56 .57 .57 .57 .57 .5380MA.56 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57<							
Coastal States Aviation, Denver NC5.86/89Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc, Bridgewater VA26.9.89/06(rebuilt by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94) Brazoria County Mosquito Control, Angleton TX21.4.10/16N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP noted Des Moines IA 5.79 "Check-Air" titles; N909GP noted Des Moines IA 5.79 "Check-Air" titles; N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;BA-237E18S N57H -9700Duilt.57 Timmins Aviation Ltd, Montreal QUE Transair Ltd, St James MAN Steep Rock Iron Mines Ltd, Atikokan ONT Commander Aviation Corp, Opa Locka FL N380MA Miami Aviation Corp, Opa Locka FL Dee Howard Co, San Antonio TX Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO 27.4.77/78 Coastal Aviation Coastal Aviation Compander Co, Pensacola FL Missouri Aviation29.1.80/82 27.3.78/80BA-237Fitness Marketing Associates Inc, Manhasett NY A 14.4.82 crashed destroyed landing, parachute ops, Lakewood NJ 13.8.82							
Karl D. & Kenneth A. Stoltzfus/ K & K Aircraft Inc, Bridgewater VA26.9.89/06 (rebuilt by K& K1.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94) Brazoria County Mosquito Control, Angleton TX21.4.10/16 6.9.16/20N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP noted Des Moines IA 5.79 "Check Air" titles, N909GP noted Des Moines IA 5.79 "Check-Air" titles, Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;BA-237E18SN57H built57 Transair Ltd, St James MAN Steep Rock Iron Mines Ltd, Attikokan ONT 66/66 Commander Aviation Ltd65/66 commander Aviation Corp, Opa Locka FL 1.2.66/68 Dee Howard Co, San Antonio TX 31.5.68/69 Jim Hankins Air Service/ Hankins Airways, Jackson MS 2.2.4.69/76 Cape Central Alivays, Cape Girardeau MO 2.7.3.78/80 Op: The Airplane Co, Pensacola FL Missouri Aviation73.378/80Viet Alivation Coastal Aviation Coastal Aviation Coastal Aviation Coastal Aviation Coastal Aviation Coastal Aviation Coastal Aviation Coastal Aviation 21.3.78/8079 Missouri Aviation Missouri Aviation Missouri Aviation Missouri Aviation Missouri Aviation Missouri Aviation Coastal Aviation 29.1.80/82 Fitness Marketing Associates Inc, Manhasett NY Missouri Aviation Missouri Aviation Miss							
Bridgewater VA       26.9.89/06         (rebuilt by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94)       Brazoria County Mosquito Control, Angleton TX       21.4.10/16         Brazoria County NY 22.8.74 turbine "Tobey" titles;       N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles;       N909GP noted Milwaukee WI 1.9.78 "Check Air" titles;       N909GP noted Milwaukee WI 1.9.78 "Check Air" titles;       N909GP noted Los Alamitos CA 17.8.99 Westwind III tailgear;       N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57;       N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers;         Bech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;       57         BA-237       E18S       N57H       built       .57         -9700       CF-TAB       Timmins Aviatio Ltd, Montreal QUE       .57         Transair Ltd, St James MAN       Steep Rock Iron Mines Ltd, Atikokan ONT       65/66         N12421       Miami Aviation Corp, Opa Locka FL       12.66/68         Dee Howard Co, San Antonio TX       31.5.68/69         Jim Hankins Air Service/ Hankins Airways, Jackson MS       22.4.69/76         Cape Central Airways, Cape Girardeau MO       27.4.77/78         Coastal Aviation       27.3.78/80       09.7.76/77         Charles H. Southerland       27.4.77/78       Coas					5.00/09		
(rebuilt by K&K 11.91, cabin windows skinned over, ag. & pest control category, CofA renewed 29.4.94) Brazoria County Mosquito Control, Angleton TX Countryside Aviation, Chilton WI21.4.10/16 6.9.16/20N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP noted Milwaukee WI 1.9.78 "Check Air" titles; N909GP noted Des Moines IA 5.79 "Check-Air" titles, Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III is service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;BA-237E18S -9700N57H CF-TAB Timmins Aviatio Ltd, Montreal QUE Transair Ltd, St James MAN Steep Rock Iron Mines Ltd, Atikokan ONT Commander Aviation Corp, Opa Locka FL Use Howard Co, San Antonio TX Use Howard Co, San Antonio TX Use Howard Co, San Antonio TX Cape Central Airways, Cape Girardeau MO Cape Station Comatel Aviation Cape Central Airways, Cape Girardeau MO Cape 12.76/77 Charles H.Southerland Coastal Aviation Cape Central Airways, Cape Girardeau MO Cape 12.76/77 Charles H.Southerland Cape Central Airways, Cape Girardeau MO Cape Central Airways, Cape Girardeau MO Cape 12.76/77 Charles H.Southerland Coastal Aviation Cape Central Airways, Cape Girardeau MO Cape 12.76/77 Charles H.Southerland Cape Central Airways, Cape Girardeau MO Cape 12.76/77 Charles H.Southerland Cape Central Airways, Cape Girardeau MO Cape 12.76/77 Charles H.Southerland Cape Central Airways, Cape Girardeau MO Cape 12.76/77 Charles H.Southerlan					26.0.80/06		
ag. & pest control category, CofA renewed 29.4.94) Brazoria County Mosquito Control, Angleton TX 21.4.10/16 Countryside Aviation, Chilton WI 6.9.16/20 N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP noted Des Moines IA 5.79 "Check Air" titles; N909GP noted Des Moines IA 5.79 "Check Air" titles, Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681; BA-237 E18S N57H built .57 -9700 CF-TAB Timmins Aviatio Ltd, Montreal QUE .57 Transair Ltd, St James MAN Steep Rock Iron Mines Ltd, Atikokan ONT 65/66 Commander Aviation Corp, Opa Locka FL 4.7.66 N380MA Miami Aviation Corp, Opa Locka FL 4.7.66 N380MA Miami Aviation Corp, Opa Locka FL 12.66/68 Dee Howard Co, San Antonio TX 315.568/69 Jim Hankins Air Service/ Hankins Airways, Jackson MS 22.4.69/76 Cape Central Airways, Cape Girardeau MO 12.76/77 Charles H.Southerland 27.4.777/78 Coastal Aviation 29.1.80/82 Fitness Marketing Associates Inc, Manhasett NY 14.4.82 crashed destroyed landing, parachute ops, Lakewood NJ 13.8.82					20.9.09/00		
Brazoria County Mosquito Control, Angleton TX21.4.10/16 6.9.16/20N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP photo 9.76 as Westwind III; N909GP noted Milwaukee WI 1.9.78 "Check Air" titles; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;BA-237E18S -9700N57H CF-TABbuilt Timmins Aviatio Ltd, Montreal QUE Commander Aviation Ltd.57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 .57 							
Countryside Aviation, Chilton WI       6.9.16/20         N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP photo 9.76 as Westwind III; N909GP noted Milwaukee WI 1.9.78 "Check Air" titles; N909GP noted Des Moines IA 5.79 "Check-Air" titles; Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;         BA-237       E18S       N57H       built       .57         -9700       CF-TAB       Timmins Aviatio Ltd, Montreal QUE       .57         Transair Ltd, St James MAN       Steep Rock Iron Mines Ltd, Atikokan ONT       65/66         N12421       Miami Aviation Corp, Opa Locka FL       4.7.66         N380MA       Miami Aviation Corp, Opa Locka FL       12.66/68         Dee Howard Co, San Antonio TX       31.5.68/69         Jim Hankins Air Service/ Hankins Airways, Jackson MS       22.4.69/76         Cape Central Airways, Cape Girardeau MO       12.74/77/78         Coastal Aviation       27.3.78/80         op: The Airplane Co, Pensacola FL       79         Missouri Aviation       29.1.80/82         Fitness Marketing Associates Inc, Manhasett NY       14.4.82         crashed destroyed landing, parachute ops, Lakewood NJ 13.8.82					21 4 10/16		
N909GP noted Clinton County NY 22.8.74 turbine "Tobey" titles; N909GP photo 9.76 as Westwind III; N909GP noted Milwaukee WI 1.9.78 "Check Air" titles; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57; N909GP noted Los Alamitos CA 13.8.02 with other K&K sprayers; Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;         BA-237       E18S       N57H       built       .57         -9700       CF-TAB       Timmins Aviatio Ltd, Montreal QUE       .57         rransair Ltd, St James MAN       Steep Rock Iron Mines Ltd, Atikokan ONT       65/66         N12421       Miami Aviation Corp, Opa Locka FL       4.7.66         N380MA       Miami Aviation Corp, Opa Locka FL       12.66/68         Dee Howard Co, San Antonio TX       31.5.68/69         Jim Hankins Air Service/ Hankins Airways, Jackson MS       22.4.69/76         Cape Central Aliways, Cape Girardeau MO       12.76/77         Charles H.Southerland       27.4.77/78         Coastal Aviation       27.3.78/80         op: The Airplane Co, Pensacola FL       79         Missouri Aviation       29.1.80/82         Fitness Marketing Associates Inc, Manhasett NY       14.4.82         crashed destroyed landing, parachute ops, Lakewood NJ 13.8.82							
Beech 18 by Parmerter index also quotes N568M for BA-236, RP says was typo for N5681;BA-237E18SN57Hbuilt.57-9700CF-TABTimmins Aviatio Ltd, Montreal QUE.57Transair Ltd, St James MANSteep Rock Iron Mines Ltd, Atikokan ONT65/66N12421Miami Aviation Corp, Opa Locka FL4.7.66N380MAMiami Aviation Corp, Opa Locka FL12.66/68Dee Howard Co, San Antonio TX31.5.68/69Jim Hankins Air Service/ Hankins Airways, Jackson MS22.4.69/76Cape Central Airways, Cape Girardeau MO12.76/77Charles H.Southerland27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82		N909GP photo 9.76 as Westwind III; N909GP noted Milwaukee WI 1.9.78 "Check Air" titles; N909GP noted Des Moines IA 5.79 "Check-Air" titles, Westwind III tailgear; N909GP noted Los Alamitos CA 17.8.99 Westwind III in service with K&K Aircraft, sprayer, "K&K Aircraft" titles, plate: BA-236 built 1.57;					
BA-237E18S -9700N57H CF-TABbuilt.57 Timmins Aviatio Ltd, Montreal QUE Transair Ltd, St James MAN Steep Rock Iron Mines Ltd, Atikokan ONT Commander Aviation Ltd.57 .57 .57 .566 .666 M12421N12421Miami Aviation Corp, Opa Locka FL N380MA4.7.66 Miami Aviation Corp, Opa Locka FL Dee Howard Co, San Antonio TX .050 Jim Hankins Air Service/ Hankins Airways, Jackson MS .22.4.69/76 Cape Central Airways, Cape Girardeau MO .27.3.78/80 .0p: The Airplane Co, Pensacola FL .99 Missouri Aviation29.1.80/82 .29.1.80/82 .29.1.80/82 .20.1.80/82					NECO1		
-9700CF-TABTimmins Aviatio Ltd, Montreal QUE Transair Ltd, St James MAN Steep Rock Iron Mines Ltd, Atikokan ONT Commander Aviation Ltd.57N12421Miami Aviation Corp, Opa Locka FL N380MA4.7.66N12421Miami Aviation Corp, Opa Locka FL Dee Howard Co, San Antonio TX Jim Hankins Air Service/ Hankins Airways, Jackson MS Cape Central Airways, Cape Girardeau MO Coastal Aviation Op: The Airplane Co, Pensacola FL Missouri Aviation27.4.77/78 29.1.80/82Fitness Marketing Associates Inc, Manhasett NY crashed destroyed landing, parachute ops, Lakewood NJ13.8.82		Deech 18 D	y Farmener	inuex also quoles ivooolvi ior BA-230, RP says was lypo to	N NOODI;		
-9700CF-TABTimmins Aviatio Ltd, Montreal QUE Transair Ltd, St James MAN Steep Rock Iron Mines Ltd, Atikokan ONT Commander Aviation Ltd.57N12421Miami Aviation Corp, Opa Locka FL N380MA4.7.66N12421Miami Aviation Corp, Opa Locka FL Dee Howard Co, San Antonio TX Jim Hankins Air Service/ Hankins Airways, Jackson MS Cape Central Airways, Cape Girardeau MO Coastal Aviation Op: The Airplane Co, Pensacola FL Missouri Aviation27.4.77/78 29.1.80/82Fitness Marketing Associates Inc, Manhasett NY crashed destroyed landing, parachute ops, Lakewood NJ13.8.82	BV 002	E199	N57U	built	57		
Transair Ltd, St James MANSteep Rock Iron Mines Ltd, Atikokan ONT65/66Commander Aviation Ltd.66N12421Miami Aviation Corp, Opa Locka FL4.7.66N380MAMiami Aviation Corp, Opa Locka FL12.66/68Dee Howard Co, San Antonio TX31.5.68/69Jim Hankins Air Service/ Hankins Airways, Jackson MS22.4.69/76Cape Central Airways, Cape Girardeau MO12.76/77Charles H.Southerland27.4.77/78Coastal Aviation27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82	DA-231						
Steep Rock Iron Mines Ltd, Atikokan ONT65/66Commander Aviation Ltd.66N12421Miami Aviation Corp, Opa Locka FL4.7.66N380MAMiami Aviation Corp, Opa Locka FL12.66/68Dee Howard Co, San Antonio TX31.5.68/69Jim Hankins Air Service/ Hankins Airways, Jackson MS22.4.69/76Cape Central Airways, Cape Girardeau MO12.76/77Charles H.Southerland27.4.77/78Coastal Aviation27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82		-3100			.51		
Commander Aviation Ltd.66N12421Miami Aviation Corp, Opa Locka FL4.7.66N380MAMiami Aviation Corp, Opa Locka FL12.66/68Dee Howard Co, San Antonio TX31.5.68/69Jim Hankins Air Service/ Hankins Airways, Jackson MS22.4.69/76Cape Central Airways, Cape Girardeau MO12.76/77Charles H.Southerland27.4.77/78Coastal Aviation27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82					65/66		
N12421Miami Aviation Corp, Opa Locka FL4.7.66N380MAMiami Aviation Corp, Opa Locka FL12.66/68Dee Howard Co, San Antonio TX31.5.68/69Jim Hankins Air Service/ Hankins Airways, Jackson MS22.4.69/76Cape Central Airways, Cape Girardeau MO12.76/77Charles H.Southerland27.4.77/78Coastal Aviation27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82							
N380MAMiami Aviation Corp, Opa Locka FL12.66/68Dee Howard Co, San Antonio TX31.5.68/69Jim Hankins Air Service/ Hankins Airways, Jackson MS22.4.69/76Cape Central Airways, Cape Girardeau MO12.76/77Charles H.Southerland27.4.77/78Coastal Aviation27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82			N12421				
Dee Howard Co, San Antonio TX31.5.68/69Jim Hankins Air Service/ Hankins Airways, Jackson MS22.4.69/76Cape Central Airways, Cape Girardeau MO12.76/77Charles H.Southerland27.4.77/78Coastal Aviation27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82							
Jim Hankins Air Service/ Hankins Airways, Jackson MS22.4.69/76Cape Central Airways, Cape Girardeau MO12.76/77Charles H.Southerland27.4.77/78Coastal Aviation27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82							
Cape Central Airways, Cape Girardeau MO12.76/77Charles H.Southerland27.4.77/78Coastal Aviation27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82							
Charles H.Southerland27.4.77/78Coastal Aviation27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82							
Coastal Aviation27.3.78/80op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82							
op: The Airplane Co, Pensacola FL79Missouri Aviation29.1.80/82Fitness Marketing Associates Inc, Manhasett NY14.4.82crashed destroyed landing, parachute ops, Lakewood NJ13.8.82							
Missouri Aviation 29.1.80/82 Fitness Marketing Associates Inc, Manhasett NY 14.4.82 crashed destroyed landing, parachute ops, Lakewood NJ 13.8.82							
Fitness Marketing Associates Inc, Manhasett NY 14.4.82 crashed destroyed landing, parachute ops, Lakewood NJ 13.8.82							
crashed destroyed landing, parachute ops, Lakewood NJ 13.8.82				Fitness Marketing Associates Inc, Manhasett NY			
OF TAD visited Terrarda ONT 02.4 64					13.8.82		
			ite el Te f				

CF-TAB visited Toronto ONT 23.4.64;

BA-238	E18S	N49M	Ohio Oil Co, Findlay OH	
			American Brake Shoe Co, Akron OH	63/70
			emergency exit inadvertantly released in flight by	
			a passenger, over Lake Erie OH	25.3.64
			ABEX Corp, Athens OH	72
		N49MA	rereg	11.76
			Tobey Inc, Belgrade Lakes ME, later Simsbury CT	78
			Brennan & Hargreaves Inc, Bradford CT	79/80
			minor damage landed gear-up, Newburgh-Stewart NY	15.9.79
			Francis J. McCarthy, St Thomas USVI	8.82
			op: Four Star Air Cargo, St Thomas USVI	84/85
			groundlooped, crashed on takeoff St Thomas USVI	20.3.85
			struck-off USCR	12.85

N49MA accident report 15.9.79: Brennan & Hargreaves, pilot forgot to extend landing gear, he was

No.1 in a sequence of 3 inbound acft, No.2 was DC-9 with cargo for the others, 5.10am, pilot unhurt; N49MA noted Burlington VT 1.80 in service, tailwheel, "BH" on tail;

BA-239	E18S	N51M	built	.56
			Ohio Oil Co, Findlay OH	<u></u>
			Marathon Oil Co, Findlay OH	63
			Ohio Aviation, Dayton OH Page Airways, Rochester NY	64 66
			HAT Inc, Flint MI	69/70
			Eagle Aviation, Flint MI	71/79
			Green Aero Inc, Flint MI	2.2.79/82
			struck-off USCR	1.12.82
	N51M no	ted Flint-Bisho	p MI 8.80 "Green Aero" titles, tailwheel;	
BA-240	E18S	N41G	Gopher Aviation, Rochester Airport MN	29.1.57
		-	Gerald H. Galbreath	21.5.57/61
			John J. Shea, Memphis TN	11.61/63
			Memphis Air Taxi	24.7.63
			Leeward & Hart Aeronautical Corp, Miami FL	11.63/65
			Harry W. Hosford, Shaker Heights OH	2.2.65/75
			Morris L. Henderson	22.3.75
			Bernard L. Stella	12.75/76
			Jack R. Tarry, Elyria OH	12.76/77
			William R. Sandlin & Aubrey Buzan, Harlingen TX	12.77/78
			Lorena Sanchez	5.9.78/81
			William R. Sandlin, Harlingen TX	16.1.81/98
			struck off USCR	28.7.98
	N41G no	ted Pittsburg F	PA 30.8.69;	
BA-241	E18S	N42T	McGean Chemical Co, Cleveland OH	63/70
			Chemetron Corp, Cleveland OH	71/72
			John R. Tarry, Elyria OH	21.4.78/82
			sold to owner, Texas	82
			(electrical goods smuggling operations into Mexico,	
			undercarriage failed landing Mexico: TVs unloaded	
			then aircraft set on fire)	
			struck-off USCR	8.82
BA-242	E18S	N3333 (3	Beech Aircraft Corp, Wichita KS: CofA issued	31.1.57
			Southern Airways Co, Atlanta GA	12.2.57
			Swiflite Aircraft Corp, New York NY	12.2.57/67
			landed with tailwheel retracted, Des Moines IA	23.2.66
			Landy Taylor & Associates, Lansing MI	22.9.67/70
			Dexter D. Coffin	11.70/71
			Florida Airmotive Inc, Lantana-Palm Beach FL	30.4.71
			Riggers & Erectors of Florida Inc, St Croix USVI	10.71/77
			Eastern Caribbean Airways, St Croix USVI	10.77/79
			Thomas L. Hughes	31.3.79/82

op: General Aviation Inc, Greenville TN International Airsalvage Co sale rep., Atlanta GA 80 5.9.82 91

Swiftlite Aircraft Corp also traded as Cities Service Co; N3333 noted Ft Worth TX 6.57, "Cities Service" titles & emblem; N3333 noted Ft Lauderdale FL 28.9.70; N3333 noted Opa Locka FL 4.10.77; N3333 noted St Thomas USVI 30.4.78; N3333 noted St Croix USVI 2.5.78 ECA;

BA-243	E18S	N4372D	Beech Aircraft Corp, Wichita KS: CofA issued	10.1.57/58
		N21U (1	J. D. Reed Co, Houston TX	7.8.58
			Ceramic Engineers Inc, Houston TX	7.8.58/65
			Keystone Valve Corp, Houston TX	10.4.65/67
			damaged landing with gear locked-up, Chicago IL	14.3.67
		N2107	Keystone Valve Corp	5.9.67/68
			Robert M. Flagler	18.1.68
			Alberto Nayor, Santure, Puerto Rico	16.9.68/71
			op: Coastal Airways, San Juan, Puerto Rico	70/71
			Coastal Airways, San Juan, Puerto Rico	10.71/72
			Henry R. Collazo	20.4.72/73
		N6898	Belvon Aircraft Leasing Inc	6.73/76
			Jed Air	29.6.76/77
			(Aerospace Products cargo door installed 6.76)	
			Burl-Air Freight Inc, Burlington WI	23.5.77/82
			James R. Beardsley/ Crystal Lake School of Aviation,	
			Crystal Lake IL	11.82/84
			sale rep., USCR	10.5.84/91
			K & K Aviation, Bridgewater VA: broken-up for parts	.83
			South West Aero Exchange, Owasso OK (damaged fuselage in salvage yard, Owasso OK 00)	00

N2107 noted San Juan PR 12.12.70 Coastal AW; N6898 fuselage only in Southwest Aero Exchange yard, Owasso OK 10.8.00;

BA-244	E18S	N650R (1	Atlantic Aviation Corp: CofA issued	5.2.57
	trigear		International Business Machines Corp	6.2.57/59
	U	N770C (2	The Chemstrand Corp	10.59/62
		N400S	Monsanto Chemical Co, St Louis MO	24.4.62/63
			Capitol Aviation, Springfield IL	29.4.63
		N7N	Capitol Aviation, Springfield IL	9.9.63/64
			(Volpar Mk.IV trigear, picture windows & G18S type	
			windshield installed 11.63)	
			S & W Construction Co	14.1.64/66
			Downtowner Corp, Memphis TN	25.7.66/69
			Commercial Leasing & Financing, Lafayette LA	21.8.69/72
			Isd: Marvin Pool & Associates	21.8.69/72
			Super 18 Inc	2.10.72/74
			Business Aircraft Corp	11.1.75/76
			landed gear locked-up on foamed runway,	
			Niagara Falls NY	29.5.75
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	27.2.76/91
			sale rep: USCR 91/12, struck-off USCR	15.10.12

N7N accident report 29.5.75: flight Bridgeport CT to Buffalo NY, pilot unhurt; (FAA file: Sam Vies advises 7.90: although N7N still reg. to him, he no longer owns it!)

BA-245	E18S	N73A	built	57
			Airlease Corp, San Francisco CA	63/64
			Fairchild Hiller Corp, St Augustine FL	66/72
			Gilley Airways Corp, Fulton-Oswego County NY	9.2.78/82
			struck-off USCR	8.82
BA-246	E18S	CF-JMV	Field Aviation Co Ltd, Oshawa ONT: dealer	2.57
			(del. to Oshawa 15.2.57 ex Wichita)	

TG-EXM	Canadian Nickel Alr Services Ltd, Copper Cliff ONT nn: International Nickel Co of Canada Ltd, Toronto ONT Exploraciones y Explotaciones Mineras Izabal SA struck-off Canadian Register Exmibal SA, La Aurora, Guatemala (CofA expired 31.4.75)	24.4.57/71 12.71/74 27.2.74 21.3.74 3.74/75
	(TG-EXM arrived Toronto ONT 19.11.76 on delivery,	
	noted parked at Maple ONT 9.4.77)	
C-FJMV	Floyd Carson	77
	Strout Aviation Inc	21.9.77
N70766	Ralph Quinlan/ Mountain Air Cargo, Denver NC	22.9.77
	(Aerospace Products cargo door, cargo floor,	
	Hamilton pilot cockpit door installed 31.10.77)	
N700M (3	Ralph Quinlan, Lincolnton NC/ Mountain Air Cargo,	
	Denver NC	12.77/83
	op: General Aviation, Greenville TN	80
	crashed, ran off runway into trees on takeoff,	
	Denver-Little Mountain Airport NC	3.10.83

N700M noted JFK NY 23.8.83 Mountain Air Cargo, no titles;

3A-247	E18S	N25X (2	Butler Airplane Sales: CofA issued	14.2.57
	-9700	· <b>`</b>	Thor Power Tool Co, Chicago IL	19.2.57/59
			Electric Auto-Lite Co	16.7.59/60
			O. C. Field, Palos Verdes CA	18.3.60/71
			op: Personnel Air	68
			struck runway lights landing, Los Angeles CA	20.12.68
			Crescent E. Clark, Sepulveda CA	4.5.71/75
			Theta Enterprises	15.1.75/77
			Trademark Aviation Corp, Van Nuys CA	2.77
			Aerospace Products Inc, North Hollywood CA	11.8.77/82
			Eugene A. O'Brien, Denver CO	12.82/87
			Leasing Equipment Services Inc, Penndel PA	17.2.87/88
			Audley Maduro, Pomona NY	25.5.88/13
			struck-off USCR	23.10.13
	N25X vis N25X ph N25X no N25X no	ited Dublin, Ire oto at London ted San Ferna ted San Ferna	Scotland 10.9.57 Thor Silver Line/ Thor Power Tools titles, land .57 Thor Silver Line, a power tool company; c57 Thor Tools titles; ndo Valley CA 22.11.62; ndo Valley CA 7.68; 0.12.68: Personnel Air, struck runway lights landing LAX;	
	N125X 20			
		ted Van Nuys		
A-248			CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA	5.3.57
3A-248	N25X not E18S -9700	ted Van Nuys	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows,	5.3.57 7.3.57/65
A-248	N25X no. E18S -9700 JATO	ted Van Nuys	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62)	7.3.57/65
A-248	N25X not E18S -9700	ted Van Nuys	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX	7.3.57/65
A-248	N25X no. E18S -9700 JATO	ted Van Nuys	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO	7.3.57/65
3A-248	N25X no. E18S -9700 JATO	ted Van Nuys	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74)	7.3.57/65 12.9.65/69 3.6.69/75
A-248	N25X no. E18S -9700 JATO	ted Van Nuys	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc	7.3.57/65 12.9.65/69 3.6.69/75 11.75
3A-248	N25X no. E18S -9700 JATO	ted Van Nuys	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74)	7.3.57/65 12.9.65/69 3.6.69/75
3A-248 3A-249	N25X no. E18S -9700 JATO	ted Van Nuys	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc sale reported: USCR Southern Airways Co, Atlanta GA: CofA issued	7.3.57/65 12.9.65/69 3.6.69/75 11.75 77/91 25.2.57
-	N25X no E18S -9700 JATO jets	N49N N2000 (3	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc sale reported: USCR Southern Airways Co, Atlanta GA: CofA issued Swiflite Aircraft Corp, New York NY	7.3.57/65 12.9.65/69 3.6.69/75 11.75 77/91 25.2.57 6.3.57/66
-	N25X no E18S -9700 JATO jets	ted Van Nuys N49N N2000 (3 N2000C	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc sale reported: USCR Southern Airways Co, Atlanta GA: CofA issued Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY	7.3.57/65 12.9.65/69 3.6.69/75 11.75 77/91 25.2.57 6.3.57/66 21.1.66
	N25X no E18S -9700 JATO jets	N49N N2000 (3	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc sale reported: USCR Southern Airways Co, Atlanta GA: CofA issued Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY	7.3.57/65 12.9.65/69 3.6.69/75 11.75 77/91 25.2.57 6.3.57/66 21.1.66 4.5.66
-	N25X no E18S -9700 JATO jets	ted Van Nuys N49N N2000 (3 N2000C	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc sale reported: USCR Southern Airways Co, Atlanta GA: CofA issued Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Southern Airways Co	7.3.57/65 12.9.65/69 3.6.69/75 11.75 77/91 25.2.57 6.3.57/66 21.1.66 4.5.66 30.9.66/68
	N25X no E18S -9700 JATO jets	ted Van Nuys N49N N2000 (3 N2000C	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc sale reported: USCR Southern Airways Co, Atlanta GA: CofA issued Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Southern Airways Co Franklin Development Co, Newnan GA	7.3.57/65 12.9.65/69 3.6.69/75 11.75 77/91 25.2.57 6.3.57/66 21.1.66 4.5.66 30.9.66/68 10.4.68/71
-	N25X no E18S -9700 JATO jets	ted Van Nuys N49N N2000 (3 N2000C	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc sale reported: USCR Southern Airways Co, Atlanta GA: CofA issued Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Southern Airways Co Franklin Development Co, Newnan GA Georgia Sheriff's Boys Ranch	7.3.57/65 12.9.65/69 3.6.69/75 11.75 77/91 25.2.57 6.3.57/66 21.1.66 4.5.66 30.9.66/68 10.4.68/71 1.4.71
	N25X no E18S -9700 JATO jets	ted Van Nuys N49N N2000 (3 N2000C	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc sale reported: USCR Southern Airways Co, Atlanta GA: CofA issued Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Southern Airways Co Franklin Development Co, Newnan GA Georgia Sheriff's Boys Ranch David L. Zuck/ Tigre Aircraft Maintenance & Repair Inc	7.3.57/65 12.9.65/69 3.6.69/75 11.75 77/91 25.2.57 6.3.57/66 21.1.66 4.5.66 30.9.66/68 10.4.68/71 1.4.71 7.8.71
-	N25X no E18S -9700 JATO jets	ted Van Nuys N49N N2000 (3 N2000C	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc sale reported: USCR Southern Airways Co, Atlanta GA: CofA issued Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Southern Airways Co Franklin Development Co, Newnan GA Georgia Sheriff's Boys Ranch David L. Zuck/ Tigre Aircraft Maintenance & Repair Inc Aircraft Unlimited Inc	7.3.57/65 12.9.65/69 3.6.69/75 11.75 77/91 25.2.57 6.3.57/66 21.1.66 4.5.66 30.9.66/68 10.4.68/71 1.4.71 7.8.71 11.71/72
	N25X no E18S -9700 JATO jets	ted Van Nuys N49N N2000 (3 N2000C	CA 17.4.72; Topeka Aircraft Sales & Service, Topeka KS: CofA Panhandle Eastern Pipe Line Co, Kansas City MO (G18S type windshield, picture windows, JATO jet-assisted takeoff kit installed 2.62) Anadarko Production Corp, Fort Worth TX American Jet Leasing Inc, St Louis MO (Aerospace Products cargo door installed 7.74) William Crowley/ East Central Lines Inc sale reported: USCR Southern Airways Co, Atlanta GA: CofA issued Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Swiflite Aircraft Corp, New York NY Southern Airways Co Franklin Development Co, Newnan GA Georgia Sheriff's Boys Ranch David L. Zuck/ Tigre Aircraft Maintenance & Repair Inc	7.3.57/65 12.9.65/69 3.6.69/75 11.75 77/91 25.2.57 6.3.57/66 21.1.66 4.5.66 30.9.66/68 10.4.68/71 1.4.71 7.8.71

N238K	struck fuel tanker taxiing, St Louis-Lambert MO Springdale Air Service, Springdale AR struck Metro taxying at night, Oklahoma City OK Julio M. Contrera, Miami FL Richard F. Kelley, Fort Lauderdale FL Charles M. Howell, Lake Worth FL Roy A. Hall, West Palm Beach FL William B. Lumley, Chattanooga TN Carol J. Lumley, Desplaines IL (noted at Lonoke AR 4.10 derelict) reg expired 31.12.12, struck-off USCR	29.2.80 10.83/87 23.6.86 5.7.87 11.87/88 11.1.88 25.2.88/89 4.8.89/97 28.10.97/12 20.7.17
-------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------

N2001C accident report 29.2.80: Semo Aviation, cargo flight St Louis to Chattanooga TN, 11.01pm, pilot unhurt;

N2001C accident report 23.6.86: Springdale Air Service, taxiway collision at night;

BA-250	E18S	N58H	Kay Kimbell, Fort Worth TX	63/64
			Kimbell Milling Co, Fort Worth TX	66/69
			Schero & Waldren Inc, Houston TX	70
			Jess P. Kimball/ Spa Flying Service Hot Springs AR	8.7.71/78
	Hamilton		op: Tobey Inc, Simsbury CT	78
	Extended		op: Brennan & Hargreaves, Bradford CT	78
	Nose		crashed dest., night forced landing Latham NY	1.9.78

N58H accident report 1.9.78: Brennan & Hargreaves, cargo flight Albany NY to Windsor Locks CT, power failure initial climb, forced landing off airport, fire after impact, 8.46pm, pilot unhurt;

BA-251	E18S	N1111 (2	Southern Airways Co, Atlanta GA: CofA issued	1.3.57
	-9800		Swiflite Aircraft Corp, New York NY	4.4.57/66
		N1000C	Swiflite Aircraft Corp, New York NY	1.66
		N1002C	Swiflite Aircraft Corp, New York NY	5.5.66
			Atlantic Aviation Corp	24.6.66
			Ortner Air Service, Wakeman OH	24.8.66/74
			wing damaged during emergency landing after takeoff,	
			St. Louis MO	29.8.73
			Fred F. Ortner/ Rural Leasing Inc	30.8.74/75
			Active Air Inc, Wakeman OH	12.75/78
			K & K Aircraft, Bridgewater VA	7.9.78/96
			(cabin cargo floor installed 2.79, converted for	
			aerial application 350 gallon chemical tank 2.82 for	
			gipsy moth & mosquito spraying contracts)	
	floats		Glenn Goodman, Venice FL	10.96/01
			Eagle Point Inc, Venice FL	19.11.01/02
			crashed on takeoff, destroyed by fire, Venice FL	26.6.02
	N1002C   plate: -98 N1002C	noted Venice I 300 conv. 12.6 noted Sarasota	a FL 8.4.97 floats;	
	N1002C   plate: -98 N1002C	noted Venice I 300 conv. 12.6 noted Sarasota	FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.5 1;	
BA-252	N1002C   plate: -98 N1002C	noted Venice I 300 conv. 12.6 noted Sarasota	FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8 1; a FL 8.4.97 floats; rmerter book index lists N1002 for BA-251: RP confirms built	is error; .57
BA-252	N1002C   plate: -98 N1002C   Beech 18	noted Venice F 800 conv. 12.6 noted Sarasota 8 by Robert Pa	FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8 1; a FL 8.4.97 floats; rmerter book index lists N1002 for BA-251: RP confirms built Gov East de Minas Gerais, Belo Horizante	is error; .57 65/83
3A-252	N1002C   plate: -98 N1002C   Beech 18	noted Venice F 800 conv. 12.6 noted Sarasota 8 by Robert Pa	FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8 1; a FL 8.4.97 floats; rmerter book index lists N1002 for BA-251: RP confirms built	is error; .57
	N1002C   plate: -98 N1002C   Beech 18	noted Venice F 800 conv. 12.6 noted Sarasota 8 by Robert Pa	FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8 1; a FL 8.4.97 floats; rmerter book index lists N1002 for BA-251: RP confirms built Gov East de Minas Gerais, Belo Horizante	is error; .57 65/83
	N1002C / plate: -98 N1002C / Beech 18 E18S	noted Venice I 800 conv. 12.6 noted Sarasota 8 by Robert Pa PP-ECW	<ul> <li>FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8</li> <li>1; a FL 8.4.97 floats; rmerter book index lists N1002 for BA-251: RP confirms built Gov East de Minas Gerais, Belo Horizante crashed</li> <li>Ohio Aviation Co, Dayton OH: CofA issued</li> </ul>	is error; .57 65/83 1.8.68
	N1002C / plate: -98 N1002C / Beech 18 E18S E18S	noted Venice I 800 conv. 12.6 noted Sarasota 8 by Robert Pa PP-ECW	EL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8 1; a FL 8.4.97 floats; rmerter book index lists N1002 for BA-251: RP confirms built Gov East de Minas Gerais, Belo Horizante crashed	<i>is error;</i> .57 65/83 1.8.68 21.3.57 3.57/66
	N1002C / plate: -98 N1002C / Beech 18 E18S E18S	noted Venice I 800 conv. 12.6 noted Sarasota 8 by Robert Pa PP-ECW	<ul> <li>FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8</li> <li>1; a FL 8.4.97 floats; rmerter book index lists N1002 for BA-251: RP confirms built Gov East de Minas Gerais, Belo Horizante crashed</li> <li>Ohio Aviation Co, Dayton OH: CofA issued M. A. Hanna Co/ Hanna Mining Co, Cleveland OH (miscellaneous improvements, Chemberlain radome 3.</li> </ul>	<i>is error;</i> .57 65/83 1.8.68 21.3.57 3.57/66
	N1002C / plate: -98 N1002C / Beech 18 E18S E18S	noted Venice I 800 conv. 12.6 noted Sarasota 8 by Robert Pa PP-ECW	<ul> <li>FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8 1; a FL 8.4.97 floats; rmerter book index lists N1002 for BA-251: RP confirms built Gov East de Minas Gerais, Belo Horizante crashed</li> <li>Ohio Aviation Co, Dayton OH: CofA issued M. A. Hanna Co/ Hanna Mining Co, Cleveland OH</li> </ul>	<i>is error;</i> .57 65/83 1.8.68 21.3.57 3.57/66 .60)
	N1002C / plate: -98 N1002C / Beech 18 E18S E18S	noted Venice I 800 conv. 12.6 noted Sarasota 8 by Robert Pa PP-ECW	<ul> <li>FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8</li> <li>a FL 8.4.97 floats;</li> <li>rmerter book index lists N1002 for BA-251: RP confirms</li> <li>built</li> <li>Gov East de Minas Gerais, Belo Horizante</li> <li>crashed</li> <li>Ohio Aviation Co, Dayton OH: CofA issued</li> <li>M. A. Hanna Co/ Hanna Mining Co, Cleveland OH</li> <li>(miscellaneous improvements, Chemberlain radome 3.</li> <li>George H. Bailey Leasing Corp, Fort Wayne IN</li> <li>Life Insurance Co of Kentucky</li> </ul>	<i>is error;</i> .57 65/83 1.8.68 21.3.57 3.57/66 .60) 14.3.66/67
	N1002C / plate: -98 N1002C / Beech 18 E18S E18S	noted Venice I 800 conv. 12.6 noted Sarasota 8 by Robert Pa PP-ECW	<ul> <li>FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8</li> <li>a FL 8.4.97 floats;</li> <li>rmerter book index lists N1002 for BA-251: RP confirms</li> <li>built</li> <li>Gov East de Minas Gerais, Belo Horizante</li> <li>crashed</li> <li>Ohio Aviation Co, Dayton OH: CofA issued</li> <li>M. A. Hanna Co/ Hanna Mining Co, Cleveland OH</li> <li>(miscellaneous improvements, Chemberlain radome 3.</li> <li>George H. Bailey Leasing Corp, Fort Wayne IN</li> <li>Life Insurance Co of Kentucky</li> <li>SMB Stage Line Inc, Des Moines IA</li> </ul>	<i>is error;</i> .57 65/83 1.8.68 21.3.57 3.57/66 .60) 14.3.66/67 25.5.67/68
	N1002C / plate: -98 N1002C / Beech 18 E18S E18S	noted Venice I 800 conv. 12.6 noted Sarasota 8 by Robert Pa PP-ECW	<ul> <li>FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8</li> <li>a FL 8.4.97 floats;</li> <li>rmerter book index lists N1002 for BA-251: RP confirms</li> <li>built</li> <li>Gov East de Minas Gerais, Belo Horizante</li> <li>crashed</li> <li>Ohio Aviation Co, Dayton OH: CofA issued</li> <li>M. A. Hanna Co/ Hanna Mining Co, Cleveland OH</li> <li>(miscellaneous improvements, Chemberlain radome 3.</li> <li>George H. Bailey Leasing Corp, Fort Wayne IN</li> <li>Life Insurance Co of Kentucky</li> <li>SMB Stage Line Inc, Des Moines IA</li> <li>ran off runway on takeoff, struck ditches,</li> </ul>	<i>is error;</i> .57 65/83 1.8.68 21.3.57 3.57/66 .60) 14.3.66/67 25.5.67/68
	N1002C / plate: -98 N1002C / Beech 18 E18S E18S	noted Venice I 800 conv. 12.6 noted Sarasota 8 by Robert Pa PP-ECW	<ul> <li>FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8</li> <li>a FL 8.4.97 floats;</li> <li>rmerter book index lists N1002 for BA-251: RP confirms</li> <li>built</li> <li>Gov East de Minas Gerais, Belo Horizante</li> <li>crashed</li> <li>Ohio Aviation Co, Dayton OH: CofA issued</li> <li>M. A. Hanna Co/ Hanna Mining Co, Cleveland OH</li> <li>(miscellaneous improvements, Chemberlain radome 3.</li> <li>George H. Bailey Leasing Corp, Fort Wayne IN</li> <li>Life Insurance Co of Kentucky</li> <li>SMB Stage Line Inc, Des Moines IA</li> </ul>	<i>is error;</i> .57 65/83 1.8.68 21.3.57 3.57/66 .60) 14.3.66/67 25.5.67/68 10.68/79
BA-252 BA-253	N1002C / plate: -98 N1002C / Beech 18 E18S E18S	noted Venice I 800 conv. 12.6 noted Sarasota 8 by Robert Pa PP-ECW	<ul> <li>FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8</li> <li>1; a FL 8.4.97 floats; rmerter book index lists N1002 for BA-251: RP confirms</li> <li>built Gov East de Minas Gerais, Belo Horizante crashed</li> <li>Ohio Aviation Co, Dayton OH: CofA issued</li> <li>M. A. Hanna Co/ Hanna Mining Co, Cleveland OH (miscellaneous improvements, Chemberlain radome 3. George H. Bailey Leasing Corp, Fort Wayne IN Life Insurance Co of Kentucky</li> <li>SMB Stage Line Inc, Des Moines IA ran off runway on takeoff, struck ditches, gear collapsed, Cleveland-Hopkins OH</li> </ul>	<i>is error;</i> .57 65/83 1.8.68 21.3.57 3.57/66 .60) 14.3.66/67 25.5.67/68 10.68/79 27.2.70
	N1002C / plate: -98 N1002C / Beech 18 E18S E18S	noted Venice I 800 conv. 12.6 noted Sarasota 8 by Robert Pa PP-ECW	<ul> <li>FL 15.8.98 under overhaul, no reg: plate: BA-251 built 3.8</li> <li>1;</li> <li>a FL 8.4.97 floats;</li> <li>rmerter book index lists N1002 for BA-251: RP confirms</li> <li>built</li> <li>Gov East de Minas Gerais, Belo Horizante</li> <li>crashed</li> <li>Ohio Aviation Co, Dayton OH: CofA issued</li> <li>M. A. Hanna Co/ Hanna Mining Co, Cleveland OH</li> <li>(miscellaneous improvements, Chemberlain radome 3.</li> <li>George H. Bailey Leasing Corp, Fort Wayne IN</li> <li>Life Insurance Co of Kentucky</li> <li>SMB Stage Line Inc, Des Moines IA</li> <li>ran off runway on takeoff, struck ditches,</li> <li>gear collapsed, Cleveland-Hopkins OH</li> <li>Crawford Aviation</li> </ul>	<i>is error;</i> .57 65/83 1.8.68 21.3.57 3.57/66 .60) 14.3.66/67 25.5.67/68 10.68/79 27.2.70 .79

	G18S cab		Midwest Aviation Corp Pablo Gutierrez Richard Wixom/ Blackhawk Airways, Janesville WI (G18S cab mod. removed from N5696D/BA-422 and fitted to N166H by Blackhawk Airways)	7.4.81/85 19.2.85 1.5.85/91
			Blackhawk Airways, Janesville WI Gail Force Corp/ Gail Force Express, Beloit WI Falcon Field LLC, Sun Prairie WI Catalina Flying Boats Inc, Long Beach CA Hans W. Munich, Yakutak AK dam. accident Yakutak AK reg expired 31.12.13, struck-off USCR	1.94/95 10.1.97/00 2.3.01 24.8.01/06 20.2.08/ 15.9.08 11.1.18
	N166H not N166H not another pla Report 1.0 including N N166H not N166H not N166H not N166H not	ted Rock Cou ted Rock Cou ate -9700 cor 0: Gail Force V166H rotatin ted Rockford ted Long Bea ted Phoenix / ted Long Bea	Express operating Beech 18s on US Mail run Albany NY t og between maintenance at Blackhawk Alrways, Janesville IL 30.7.00 parked outside Aero Taxi hangar, plate BA-253; ach CA 29.4.01 at Catalina Flying Boat hangar, tailwheel; AZ 27.5.01 with "Catalina Flying Boats" titles; AZ 7.01 in service; ach 8.01 in service Catalina FB, flying;	o Williamsport PA WI;
BA-254	E18S -9700 Hamilton extended	N1019B	Gerald C. Francis/ Francis Aviation, Lansing MI: CofA Herschel H. Decker/ Airtravel Service Matilda R. Wilson/ Meadow Brook Farms, Rochester MI Sargent Engineering Corp, Fort Dodge TX Warner & Swasey Co, Cleveland OH Ohio Aviation Co, Dayton OH Van Dusen Acceptance Corp, Minneapolis MN Maxson Aviation, Kotzebue AK (cargo door, floor, cockpit entrance door, and extended cargo nose installed 6.74)	21.3.57 23.4.57 23.4.57/66 8.3.66/67 11.67/69 25.7.69/72 8.6.72/74 4.6.74/76
	nose		Conrad Kalitta, Willow Run MI Tobey Inc, Belgrade Lake ME op: Brennan & Hargreaves Inc, Hartford CT Jimmie L. Billingsley, Fort Worth TX Del Caribbean Corp, San Juan, Puerto Rico op: Borinquen Air, San Juan, Puerto Rico Antilian Puerto Rico Inc, San Juan, Puerto Rico struck-off USCR	10.8.76 12.76/82 79 8.3.82/89 17.11.89/06 00 24.7.06/18 2.1.18

N1019B noted Waco TX 10.87, radials, Hamilton extended nose; N1019B noted San Juan PR 16.6.00 in service, operated Borinquen Air;

BA-255	E18S	YV-P-EPA	reg	1.57
		N74825	reg	
		YV-P-AEA	reg	
		YV-P-GPX	rereg	10.61
		YV-E-BPV	rereg	5.62
			Technica Cartografica	72
		YV-14CP	rereg	

## YV-E-BPV noted Caracas-Maiquetia 1.3.72 Technica Cartografica;

BA-256	E18S	N5000 (2	Swiflite Aircraft Corp, New York NY	.56/66
		N5000J	Swiflite Aircraft Corp, New York NY	5.66
			Southern Airways Beechcraft Inc, Orlando FL	66
			Five Smiths Inc, Atlanta GA	69/70
			Goldways Inc, Winter Park FL	8.10.70/73
			crashed destroyed during landing Treasure Cay, Ba	hamas 26.3.73

N5000J noted Atlanta GA 3.10.68, plate BA-256;

N5000J noted Atlanta GA 24.9.70 "Falcons";

BA-257	E18S	N73H	Piedmont Aviation, Winston Salem NC	22.3.57
			Hanes Hosiery Mills Co, Winston Salem NC	22.3.57/63
	-9700		(mods to E18S-9700 installed .57 by Piedmont Aviation,	
			Winston-Salem NC)	
			Bailey Leasing Corp, Fort Wayne IN	31.5.63
			Northwestern Engineering Co, Rapid City SD	6.11.63/71
			Snedigar Flying Service, Rapid City SD	1.7.71/77
			(cabin cargo floor installed 2.72)	
			Bard Air Freight, Detroit MI	12.77/78
		N80CB	Bard Air Freight, Detroit MI	20.5.78/79
			(cockpit hatch entrance installed 9.78)	
			Bard Air Corp/ Bard Air Freight, Detroit MI	84/92
			Viking Group Inc, Detroit MI	10.5.92
			Robert B. Burwell, West Chicago IL	25.9.92/93
			lsd: Viking Express, Chicago-Midway IL	93
			crashed, struck trees during emergency landing,	
			Lone Rock WI	4.5.93
BA-258	E18S	N74SF	J. P. Stevens & Co, New York NY	.57/64
			Deltona Corp, Miami FL	66
			S. W. Sisk/ Orion Airways, St. Louis MO	68/69
			Maplewood Bank & Trust Co: repossessed	3.11.69/70
			Sisk Aviation Activities, St. Louis MO	14.1.70
			Harry B. Combs, Billings-Logan MT	71/72
			Merdel Inc	75
			Air International Inc, Houston TX	4.1.78/82
			struck-off USCR	24.9.82

photo shows N72SF, N73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.61, all tailwheel, all owned J.P.Stevens & Co;

A-259	E18S	N39L	Norman Larson Co, Van Nuys CA	19.4.57/58
			Charles A. Krause Milling Co, Milwaukee WI	12.58/65
			Wiles-Holloway Inc, Baton Rouge LA	23.3.66/67
			Volpar Inc, Van Nuys CA	13.3.67/68
	Volpar Turbo 18		(Volpar trigear installed, conversion to <i>Volpar Turbo 18</i> completed 17.7.67)	
			op: Ransome Air/ Allegheny Commuter, Philadelphia PA minor damage, elevator tab separated in flight near	67
			Baltimore-Friendship MD	20.8.67
	Volpar		(further converted 9.68 to Volpar Turboliner:	
	Turboliner		81.5" fuse. stretch, ventral fin)	
		N1031B (2	Mack Trucks Inc, Allentown PA	26.9.68/74
		N139PM	Pilgrim Airlines, New London CT: delivered	27.3.74/78
			Perkiomen Airways, Reading PA	22.4.78
			Supreme Aviation, Belleville MI	11.78/84
			op: Connie Kalitta Services, Willow Run MI	79
			Supreme Machine Products Inc, Rockford IL	7.84
			Supreme Aviation, Belleville MI Atorie Air, El Paso TX:	9.85/91
			sale documentation not completed	.85
			struck-off USCR	9.12.93
		XA-SMC	Aero Juarez SA de CV, Chihuahua	12.93
			sold to USA, struck-off Mexican Register	13.7.98
		N122GS	Dixie Aviation Enterprises LLC, Troy MI, Gallatin TN	28.8.98/20

N39L accident report 20.8.67 Ransome AIr;

N1031B noted Washington-DCA 30.9.70;

N139PM noted Detroit-Willow Run MI 23.9.79 turbine trigear, in Butler hangar;

N139PM noted Columbus IN 27.3.80 Volpar Turboliner, Supreme Aviation, still in Pilgrim Airlines scheme but no titles;

N139PM noted Tucson AZ 9.11.81;

N139PM noted Indianapolis IN 7.9.84 Supreme Aviation, Willow Run, Volpar freighter;

	N122GS		TX 29.10.05 Dixie Aviation, active; TX 10.8.08, in service, all white, freighter, "BTZA630C" on TX 4.8.15;	fuselage;
BA-260	E18S	N38W (1	Ohio Aviation Co, Dayton OH: CofA issued	26.3.57/60
			H. B. Layne Contractor Inc, Springfield OH	30.9.60/63
			Graubart Aviation, Valparaiso IN	10.63/66
		N616T (2	Duncan Beechcraft Inc, Omaha NE	21.7.66/67
			Iseman Corp, Sioux Falls SD	2.3.67/69
			Victor E. Katt, Chester IL	12.69/70
			Maples Aviation Co, Vichy MO	12.8.71/78
			William R. Sandlin/ Sandlin Flying Service, Harlingen TX	12.78/88
			William R. Sandlin, Harlingen TX	10.88/05
		N5001T (2	William R. Sandlin, Harlingen TX	3.11.05/14
		,	struck-off USCR	29.10.14

N122GS noted El Paso TX 23.2.01 all white, not titles, in service;

N616T noted Wichita KS 27.7.71; N616T noted Kansas City-Fairfax MO 3.6.76;

3A-261	E18S	N69A	Atlantic Aviation Corp: CofA issued	1.4.57
	-9700		E. I. duPont de Nemours & Co, Wilmington DE	3.7.57/65
			Beverly Agency Inc, Chicago IL	29.1.66/70
			lsd: Modern Welding Co	28.2.66/70
		N69AB	Omni Investment Corp	6.2.70
			Fidelity Properties Inc, Northbrook IL	70
			Fred L. Irwin	10.9.70/75
			(high density pax seating installed 9.70)	
			op: Chicago & Southern Airlines, Chicago IL	71
			(cargo floor installed 4.74)	
			Semo Aviation Inc, Malden MO	25.3.75/78
			(cockpit emergency hatch installed 4.77,	
			G18S cab and G18S windshield fitted)	
			J. D. Enterprises, Harlingen TX	20.9.78/82
			crashed during Mexican electrical goods smuggling ops.,	
			reportedly shot down by ground fire	c81
			no owner contact with FAA since 1982: struck-off USCR	13.11.14

Further details: see Beech 18 by Robert Parmerter p.338;

N69AB noted Chicago-O'Hare 13.6.71 Chicago & Southern (no titles): freighter: G18S style windshield & skylight;

BA-262	E18S	N76A	Atlantic Aviation Corp: CofA issued	8.4.57
	-9700		L. G. deFelice & Sons Inc, North Haven CT	10.4.57/63
			Ridge Associates Inc, Flint MI	4.11.63/65
			Carrier Service Corp, Flint MI	11.65/74
			Frederick B. Annas/ Annas Airways	10.74/83
			Voight Implement Co Inc, Houston TX: USCR	13.3.83/90
			impounded Haiti due carrying marijuana	c83
			(to FA Haiti as 1279)	
			(retired, parked at Port-au-Prince, Haiti 92/94)	
		HH-DWM	Haiti Aviation, Port-au-Prince	94/98
			(restored at Port-au-Prince, flown 95-97,	
			ferried to Miami FL c98 for resale, parked Opa Locka 99)	
		N76A	Llisel M. Espego, Miami FL	13.4.00
			Lauren C. Dates, Red Creek NY Twin Bitch	29.8.01/05
			reg pending, Newnan GA: USCR	10/11
			Dynamic Avlease Inc, Bridgewater VA	6.6.13/20

N76A noted Pontiac MI 9.80, plate BA-262;

HH-DWM noted Santo Domingo-Hererra DR 20.5.94, plate BA-262: ex FA Haiti markings;

HH-DWM noted Port-au-Prince, Haiti 16.11.96 in service, civil scheme, "..i Aviation"; HH-DWM noted Opa Locka FL 17.4.99 civil scheme no titles; Opa Locka 4.8.99 N76A at Oshkosh 23.7.02 plate BA-262 built 4.57, plate -9700 mods, name "Twin Bitch";

BA-263	E18S	N110WB	built	.57
			Williams Bros Co, Tulsa OK	63
			Fabick Machinery Co, Marion IL	64
			crashed, destroyed by fire, near Knoxville TN	21.3.64
3A-264	E18S	N1525H	built	.57
	trigear		J. L. Gidwitz/ Analco Services Inc, Eagle River WI	63/64
		N417R	Modern Aero Sales, Dallas-Red Bird TX op: Command Airways, Dutchess Country Airport,	.66
			Wappinger Falls NY	67/68
			emergency landing New York-JFK, no damage	26.12.67
			KGM Leasing Corp, Wappingers Falls NY	69/70
			Gilley Airways, Hartsville SC	18.2.71
			crashed destroyed during forced landing, Milford NY	29.7.71
	N417R a	ccident report	Command Airways titles, trigear; 29.7.71: Gilley Airways; forced landing off airport during rd-Westville on night mail flight, struck trees, 2 hurt;	
3A-265	E18S	N52N	built	.57
			Ball Bros Co Inc, Muncie IN	63/66
		N1052N	Andrew C. Ortner, Wakeman OH	20.2.68/76
			op: Ortner Air Services, Wakeman OH	75/76
			tailgear collapsed landing, Columbus OH	26.4.75
			crashed destroyed near Covington TN	1.9.76
	N1052N i N1052N a	noited Waken accident repo	', tailwheel failed,12.37am; nan-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem illed, total destruction, 10.40pm, reason undetermined;	phis TN
<b>DA 000</b>	N1052N i N1052N a crashed o	noited Waken accident repo	nan-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem illed, total destruction, 10.40pm, reason undetermined;	- -
BA-266	N1052N 1 N1052N a crashed c E18S	noited Waken accident repo	nan-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem	pphis TN .57
3A-266	N1052N i N1052N a crashed o	noited Waken accident repo	nan-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem illed, total destruction, 10.40pm, reason undetermined;	- -
	N1052N 1 N1052N a crashed c E18S	noited Waken accident repo	nan-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem illed, total destruction, 10.40pm, reason undetermined; FA Brasileira as U45 FAB 2880 Youngstown Airways/ Lease Air, Youngstown OH	.57
	N1052N I N1052N a crashed o E18S U45	noited Waken accident repo dest, 2 crew k N85D	nan-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem illed, total destruction, 10.40pm, reason undetermined; FA Brasileira as U45 FAB 2880 Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS	.57 .57 63/64
	N1052N I N1052N a crashed o E18S U45	noited Waken accident repo dest, 2 crew k	nan-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem illed, total destruction, 10.40pm, reason undetermined; FA Brasileira as U45 FAB 2880 Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX	.57 .57 63/64 66
	N1052N I N1052N a crashed o E18S U45	noited Waken accident repo dest, 2 crew k N85D	han-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem- illed, total destruction, 10.40pm, reason undetermined; FA Brasileira as U45 FAB 2880 Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX	.57 .57 63/64 66 69
	N1052N I N1052N a crashed o E18S U45	noited Waken accident repo dest, 2 crew k N85D	han-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem- illed, total destruction, 10.40pm, reason undetermined; FA Brasileira as U45 FAB 2880 Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX	.57 .57 63/64 66 69 70/72
	N1052N I N1052N a crashed o E18S U45	noited Waken accident repo dest, 2 crew k N85D	han-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem- illed, total destruction, 10.40pm, reason undetermined; FA Brasileira as U45 FAB 2880 Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX Wilfredo E. Otero, Guaynabo, Puerto Rico	.57 63/64 66 69 70/72 15.11.72/75
	N1052N I N1052N a crashed o E18S U45	noited Waken accident repo dest, 2 crew k N85D	han-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem- illed, total destruction, 10.40pm, reason undetermined; FA Brasileira as U45 FAB 2880 Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX	.57 .57 63/64 66 69 70/72
BA-267	N1052N I N1052N a crashed o E18S U45	noited Waken accident repo dest, 2 crew k N85D	nan-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem illed, total destruction, 10.40pm, reason undetermined; FA Brasileira as U45 FAB 2880 Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico	.57 63/64 66 69 70/72 15.11.72/75
BA-267	N1052N f N1052N a crashed o E18S U45 E18S	noited Waken accident repo dest, 2 crew k N85D N8511	nan-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem illed, total destruction, 10.40pm, reason undetermined; FA Brasileira as U45 FAB 2880 Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico SA Aerotechnique, Alger (delivered via Prestwick 4.5.57)	.57 .57 63/64 66 69 70/72 15.11.72/75 15.10.75 30.9.57/64
BA-266 BA-267 BA-268	N1052N n N1052N a crashed d E18S U45 E18S E18S	noited Waken accident repo dest, 2 crew k N85D N8511 F-OAXI	<ul> <li>han-Ortner Field OH 25.5.76, no titles;</li> <li>ht 1.9.76: Ortner Air Services, flight Wakeman OH to Memilled, total destruction, 10.40pm, reason undetermined;</li> <li>FA Brasileira as U45 FAB 2880</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX</li> <li>Fultz Oil Co, Graham TX</li> <li>Maurice Ray Smith, Midland TX</li> <li>Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico</li> <li>SA Aerotechnique, Alger</li> <li>(delivered via Prestwick 4.5.57)</li> <li>struck-off Reguisert as destroyed</li> </ul>	.57 63/64 66 69 70/72 15.11.72/75 15.10.75
3A-267	N1052N n N1052N a crashed d E18S U45 E18S E18S	noited Waken accident repo dest, 2 crew k N85D N8511 F-OAXI	nan-Ortner Field OH 25.5.76, no titles; rt 1.9.76: Ortner Air Services, flight Wakeman OH to Mem illed, total destruction, 10.40pm, reason undetermined; FA Brasileira as U45 FAB 2880 Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico SA Aerotechnique, Alger (delivered via Prestwick 4.5.57)	.57 .57 63/64 66 69 70/72 15.11.72/75 15.10.75 30.9.57/64
BA-267 BA-268	N1052N n N1052N a crashed d E18S U45 E18S E18S	noited Waken accident repo dest, 2 crew k N85D N8511 F-OAXI	<ul> <li>han-Ortner Field OH 25.5.76, no titles;</li> <li>ht 1.9.76: Ortner Air Services, flight Wakeman OH to Memilled, total destruction, 10.40pm, reason undetermined;</li> <li>FA Brasileira as U45 FAB 2880</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX</li> <li>Fultz Oil Co, Graham TX</li> <li>Maurice Ray Smith, Midland TX</li> <li>Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico</li> <li>SA Aerotechnique, Alger</li> <li>(delivered via Prestwick 4.5.57)</li> <li>struck-off Reguisert as destroyed</li> <li>k 4.5.57 reported on delivery to Aerotec;</li> <li>Piedmont Aviation, Winston Salem NC</li> </ul>	.57 .57 63/64 66 69 70/72 15.11.72/75 15.10.75 30.9.57/64 6.1.64
3A-267 3A-268	N1052N I N1052N a crashed o E18S E18S E18S F-OAXI n	noited Waken accident repo dest, 2 crew k N85D N8511 F-OAXI	<ul> <li>han-Ortner Field OH 25.5.76, no titles;</li> <li>ht 1.9.76: Ortner Air Services, flight Wakeman OH to Memilled, total destruction, 10.40pm, reason undetermined;</li> <li>FA Brasileira as U45 FAB 2880</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX</li> <li>Fultz Oil Co, Graham TX</li> <li>Maurice Ray Smith, Midland TX</li> <li>Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico</li> <li>SA Aerotechnique, Alger (delivered via Prestwick 4.5.57) struck-off Reguisert as destroyed</li> <li>k 4.5.57 reported on delivery to Aerotec;</li> <li>Piedmont Aviation, Winston Salem NC Titmus Optical Co, Petersburg VA</li> </ul>	.57 63/64 66 69 70/72 15.11.72/75 15.10.75 30.9.57/64 6.1.64
3A-267 3A-268	N1052N I N1052N a crashed o E18S E18S E18S F-OAXI n	noited Waken accident repo dest, 2 crew k N85D N8511 F-OAXI	<ul> <li>han-Ortner Field OH 25.5.76, no titles;</li> <li>rt 1.9.76: Ortner Air Services, flight Wakeman OH to Memilled, total destruction, 10.40pm, reason undetermined;</li> <li>FA Brasileira as U45 FAB 2880</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico</li> <li>SA Aerotechnique, Alger (delivered via Prestwick 4.5.57) struck-off Reguisert as destroyed</li> <li><i>ck 4.5.57 reported on delivery to Aerotec;</i></li> <li>Piedmont Aviation, Winston Salem NC Titmus Optical Co, Petersburg VA Arlington Real Estate &amp; Equipment Leasing,</li> </ul>	.57 .57 63/64 66 69 70/72 15.11.72/75 15.10.75 30.9.57/64 6.1.64 63 64/66
3A-267 3A-268	N1052N I N1052N a crashed o E18S E18S E18S F-OAXI n	noited Waken accident repo dest, 2 crew k N85D N8511 F-OAXI	<ul> <li>han-Ortner Field OH 25.5.76, no titles;</li> <li>ht 1.9.76: Ortner Air Services, flight Wakeman OH to Memilled, total destruction, 10.40pm, reason undetermined;</li> <li>FA Brasileira as U45 FAB 2880</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico</li> <li>SA Aerotechnique, Alger (delivered via Prestwick 4.5.57) struck-off Reguisert as destroyed</li> <li>k 4.5.57 reported on delivery to Aerotec;</li> <li>Piedmont Aviation, Winston Salem NC Titmus Optical Co, Petersburg VA Arlington Real Estate &amp; Equipment Leasing, Arlington TX</li> </ul>	.57 .57 63/64 66 69 70/72 15.11.72/75 15.10.75 30.9.57/64 6.1.64 63 64/66 69/72
BA-267	N1052N I N1052N a crashed o E18S E18S E18S F-OAXI n	noited Waken accident repo dest, 2 crew k N85D N8511 F-OAXI	<ul> <li>han-Ortner Field OH 25.5.76, no titles;</li> <li>rt 1.9.76: Ortner Air Services, flight Wakeman OH to Memilled, total destruction, 10.40pm, reason undetermined;</li> <li>FA Brasileira as U45 FAB 2880</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico</li> <li>SA Aerotechnique, Alger (delivered via Prestwick 4.5.57) struck-off Reguisert as destroyed</li> <li><i>ek 4.5.57 reported on delivery to Aerotec;</i></li> <li>Piedmont Aviation, Winston Salem NC Titmus Optical Co, Petersburg VA Arlington Real Estate &amp; Equipment Leasing, Arlington TX Apollo Airways, Detroit-City Airport MI</li> </ul>	.57 .57 63/64 66 69 70/72 15.11.72/75 15.10.75 30.9.57/64 6.1.64 63 64/66 69/72 17.4.75/81
3A-267 3A-268	N1052N I N1052N a crashed o E18S E18S E18S F-OAXI n	noited Waken accident repo dest, 2 crew k N85D N8511 F-OAXI	<ul> <li>han-Ortner Field OH 25.5.76, no titles;</li> <li>rt 1.9.76: Ortner Air Services, flight Wakeman OH to Memilled, total destruction, 10.40pm, reason undetermined;</li> <li>FA Brasileira as U45 FAB 2880</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico</li> <li>SA Aerotechnique, Alger (delivered via Prestwick 4.5.57) struck-off Reguisert as destroyed</li> <li><i>ek 4.5.57 reported on delivery to Aerotec;</i></li> <li>Piedmont Aviation, Winston Salem NC Titmus Optical Co, Petersburg VA Arlington Real Estate &amp; Equipment Leasing, Arlington TX Apollo Airways, Detroit-City Airport MI op: Gelco Courier Services, Chicago IL</li> </ul>	.57 .57 63/64 66 69 70/72 15.11.72/75 15.10.75 30.9.57/64 6.1.64 63 64/66 69/72 17.4.75/81 79/81
3A-267 3A-268	N1052N I N1052N a crashed o E18S E18S E18S F-OAXI n	noited Waken accident repo dest, 2 crew k N85D N8511 F-OAXI	<ul> <li>han-Ortner Field OH 25.5.76, no titles;</li> <li>rt 1.9.76: Ortner Air Services, flight Wakeman OH to Memilled, total destruction, 10.40pm, reason undetermined;</li> <li>FA Brasileira as U45 FAB 2880</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico</li> <li>SA Aerotechnique, Alger (delivered via Prestwick 4.5.57) struck-off Reguisert as destroyed</li> <li><i>ek 4.5.57 reported on delivery to Aerotec;</i></li> <li>Piedmont Aviation, Winston Salem NC Titmus Optical Co, Petersburg VA Arlington Real Estate &amp; Equipment Leasing, Arlington TX Apollo Airways, Detroit-City Airport MI</li> </ul>	.57 .57 63/64 66 69 70/72 15.11.72/75 15.10.75 30.9.57/64 6.1.64 63 64/66 69/72 17.4.75/81
BA-267 BA-268	N1052N I N1052N a crashed d E18S E18S E18S F-OAXI n E18S	noited Wakem accident repo dest, 2 crew k N85D N8511 F-OAXI	<ul> <li>han-Ortner Field OH 25.5.76, no titles;</li> <li>rt 1.9.76: Ortner Air Services, flight Wakeman OH to Memilled, total destruction, 10.40pm, reason undetermined;</li> <li>FA Brasileira as U45 FAB 2880</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Adams Aircraft Sales, Walls MS John H. Hill, Dallas TX Fultz Oil Co, Graham TX Maurice Ray Smith, Midland TX Wilfredo E. Otero, Guaynabo, Puerto Rico crashed Nevis, Puerto Rico</li> <li>SA Aerotechnique, Alger (delivered via Prestwick 4.5.57) struck-off Reguisert as destroyed</li> <li><i>ek 4.5.57 reported on delivery to Aerotec;</i></li> <li>Piedmont Aviation, Winston Salem NC Titmus Optical Co, Petersburg VA Arlington Real Estate &amp; Equipment Leasing, Arlington TX Apollo Airways, Detroit-City Airport MI op: Gelco Courier Services, Chicago IL</li> </ul>	.57 .57 63/64 66 69 70/72 15.11.72/75 15.10.75 30.9.57/64 6.1.64 63 64/66 69/72 17.4.75/81 79/81

BA-270	E18S	N19Y (1	built	.57
		N219Y	Robert C. Watson, Lewistown PA	63/66
			landed gear-up after takeoff with frost on wings,	
			Reedsville PA	27.10.66
			George Sisk/ Orion Airways, St. Louis MO	68/69
			Maplewood Bank & Trust Co: repossessed	3.11.69/70
			Sisk Aviation Activities, St Louis MO	14.1.70

			Golden Eagle Aviation Skyway Aviation, Fort Leonardwood MO Karl Knight, Miami FL struck-off USCR	.70 71/72 18.5.77/81 10.81
BA-271	E18S	N39T N3971	Currey Sanders Aircraft Co: CofA issued Texas Eastern Transmission Corp, Shreveport LA Clayton Specialties Inc, Corpus Christi TX S. W. Sisk/ Orion Airways, St Louis MO Maplewood Bank & Trust Co: repossessed Sisk Aviation Activities, St Louis MO McGhee Aviation Skyway Aviation/ Skyway Airlines, Ft Leonard Wood MO Nevada Aircraft Leasing Corp, Carson City NV struck-off USCR	24.4.57 29.4.57/66 3.6.66/68 24.6.68/69 3.11.69/70 14.1.70 10.70/71 4.71/80 4.4.80/12 14.11.12
BA-272	E18S	N234AP	APCO Oil Co, Oklahoma City OK Smyer Aircraft Co/ Smyer Commuter Airlines, Arkansas City KS crashed destroyed, engine fire in flight, wing broke away, Winfield KS	63/66 69/72 3.6.72
	N234AP a	ccident repor	t 3.6.72: Smyer Aircraft, flight Arkansas City to White Plains	s NY 9.30am, 2k;
BA-273	E18S	N53N	Beech Aircraft Corp, Wichita KS Ohio Aviation Co, Dayton OH (CofA issued 19.2.59) Ohio Oil Co/ Marathon Oil Co, Findlay OH	9.5.57/59 19.2.59 23.2.59/65
		N825YC	Youngstown Cartage Co, Youngstown OH Youngstown Cartage Co, Youngstown OH Reeder Flying Service, Twin Falls ID (smoke spotters hatch behind door fitted 6.66; converted to smoke-jumping configuration for USFS H. M. Newhall & Co (cabin cargo floor installed 11.72) Vanpac Carriers Inc, Richmond CA D. L. McEwen & Harold Smith, Las Vegas NV Louis W. Stallings Southwind Inc: documentation not completed Bob Wood/ Wood Flying Service, Laredo TX sale reported: USCR	22.4.65 12.8.65/66 24.6.66/71 6.67 6.11.71/73 27.2.74/76 12.76/79 20.2.79/81 4.6.81 82 23.3.88/91
	N825YC n N825YC n N825YC n	oted Oakland oted Oakland oted Tulsa O	ield-Meadows Field 20.4.72; I CA 5.74 "Vanpac Carriers Inc" titles, tailwheel; I CA 19.9.75; K 6.80, tailwheel, i/s Ied into sea, South Caicos Island 5.11.79: but not in NTSB	list;
BA-274	E18S	F-OAXJ F-BLLN	Ste Aerotechnique, Alger (deivered via Prestwick 12.5.57) Escadrille Mercure, Paris-Le Bourget fate unknown, struck-off Register in clean-up	30.9.57 14.6.63/71 8.9.83
			dge 2.5.63, carrying the Aga Khan; Bourget 71, reported based there;	
BA-275	E18S -9700	N227 N2279 (2 N10FM	Tulsair Distributors Inc, Tulsa OK: CofA issued Petrolite Corp, St Louis MO Capitol Aviation, Springfield IL tailgear failed during landing, Muskogee OK Sunco Manufacturing Co, Muskogee OK Stevenson Aviation Oklahoma Aircraft Corp, Yukon OK Thomas M. Hajecate Charles H. Midkiff, San Antonio TX Foy P. Midkiff, San Antonio TX	9.5.57 29.5.57/70 12.70/71 30.4.71 11.71/80 24.9.80 .81 2.81/84 17.9.84/85 1.2.85/90

	Thomas Migel, St Cloud FL	11.90/91
N233T	M Thomas Migel, St Cloud FL	12.3.91/96
	Discovery Air, San Jose CA	20.5.96
	Michael T. Warn, Milwaukie OR	8.4.98
N63M\	N Michael T. Warn, Milwaukie OR	10.98/99
	Management West LLC, Aurora OR	20.3.99/00
N18BY	18BY LLC, Hood River OR	8.6.00/20
	Western Antique Aeroplane and Automobile Museum,	
	Hood River OR: displ. as "NC18BY"	14/18

N2279 noted Toronto ONT 3.5.79 Sunco Manufacturing ; N18BY at Beech Fly-In, Tullahoma TN 18.10.00;

BA-276	E18S	N31XL	J. R. Gray Co, Dallas TX	14.5.57
	-9700		TXL Oil Corp	7.6.57/62
			Texaco Oil Corp, New York NY	19.4.62
		N1626	Texaco Oil Corp/Texaco Inc, New York NY	6.8.62/63
		N1626B	Penn-Aire Aviation	28.5.63
		N1626D	Ferro Stamping Co/ Ferro Manufacturing Corp, Detroit	
	trigear	IN TOZE	(Volpar trigear installed 1.64)	11 23.1.04/73
	trigear		gear collapsed landing, Detroit-City MI	0 10 69
				9.10.68
			Kingston Aero Lake Airport	13.3.73/74
			A. P. St. Philip Inc, Tampa FL	11.75/76
		N162SP	A. P. St. Philip Inc, Tampa FL	25.5.76/78
			Panorama Air Tour, Honolulu HI (fleet #63)	30.5.78/83
			Ray Berney/ AirTour Acquisition Corp, Honolulu HI	26.7.82/83
			minor damage runway collision on takeoff with	
			N888M in a flight of 5 scenic Beech 18s, Kahalui HI	23.7.83
			Robert A. Justman/ Hawaiian Sky Tour, Honolulu HI	12.83/84
		N692T	Hawaiian Sky Tour, Honolulu HI Tasha	5.84/85
			Big Island Air, Kailua-Kona HI	5.4.85/86
			Lani Bird Inc/ Scenic Air Tour, Honolulu HI	13.8.86/88
			(owner report 2.88: aircraft has been scrapped)	
			struck-off USCR	28.11.88
				20.11.00
	N162SP I N162SP I N162SP I "Lani 10" N162SP I N162SP I N692T nc	noted Honolul noted Hilo 26. accident repor on inter-island noted Honolul in Panorama A oted Honolulu	u 9.80 "Panorama Air Tour" fleet #63; u 23.8.81 "Panorama Air Tour #63"; 8.81 "Panorama AT" in Beech 18 tourist formation; t 23.7.83: Panorama Airtour: flight of 5 Beech 18s with ca d tour, collided on takeoff, 1 minor injury & 19 uninjured in u 9.83 "Panorama Air Tour, trigear, fleet #62, plate BA-27 Air fleet list as at 15.11.83: BA-276 TT 10,610 hrs, fleet #6 22.10.88 derelict, Scenic Air Tour; 6.10.91 derelict, Scenic Air Tour ramp, stripped for parts;	both aircraft; 6; 33;
BA-277	E18S	N41LZ (2	Lubrizol Corp, Wickliffe OH	.57/64
		N418Z	Northern Bank & Trust, Little Rock AR	66/69
			First Arkansas Leasing Corp, Little Rock AR	70/72
			Catlin Aviation Co, Oklahoma City OK	8.8.72
			sold to Canada, struck-off USCR	8.8.72
		CF-STA	St Andrews Airways Ltd, Winnipeg MAN	8.72/74
		01-01A	dest. forced landing near Cantin Lake MAN	9.1.74
			dest. forced landing field Cantin Lake MAN	9.1.74
DA 270	E100		Gutta Percha & Rubber Ltd, Toronto ONT	<b>F</b> 7
BA-278	E18S	CF-CEL	Stuart Brothers Co Ltd	.57 62
	-9700			
		N9438H	Compass Exploration Inc, Denver CO	12.62/63
		(N64CE)	ntu: Compass Exploration Inc, Denver CO	3.63
			Compass Exploration Inc, Denver CO	3.63
		N130L	The Lewis Grocer Co, Indianola MS	9.12.63/68
			Cibbo Elving Conviso/Cibbo Lesso Air Inc	
			Gibbs Flying Service/ Gibbs Lease Air Inc,	
			San Diego-Montgomery Field CA	28.5.68/76
			San Diego-Montgomery Field CA op: Bank Air, San Diego CA	28.5.68/76 68/70
			San Diego-Montgomery Field CA	

Pope Valley Parachute Ranch	7.77/78
George C. Holberton, Medford OR	23.1.78
M. Corley Tedder/ CMT Leasing Co, Texarkana TX	18.8.78/81
(cargo floor, cargo door & crew door fitted 12.78)	
Isd: ABC Airlines Inc, Dallas-DFW TX	79/82
James L. Hudson, Mesquite TX	24.4.81/93
op: ABC Airlines, Dallas-DFW TX	.81/84
damaged night taxying collision with D18S N80017,	
Dallas-Fort Worth TX	17.3.83
Howard Y. Sigler	4.1.93
sale reported, Dallas TX	95/05
(hulk in car wreckers yard, Mesquite TX 98/03)	
Velvet A. Carroll, Heath TX	19.4.05/12
struck-off USCR	21.6.12

N130L noted Visalia CA 21.4.72; N130L noted Fort Worth TX 1.12.79 ABC Airlines; noted Dallas-FTW 7.11.81 at freight terminal "ABC Airlines" titles, freight door; N130L accident report 17.3.83: ABC Airlines: just landed at night from Lubbock TX, struck ABC Airlines Beech 18 N130L stopped on taxiway just landed from Amarillo TX; N130L noted in car breakers yard, Dallas-Mesquite TX 10.4.98 with 5 other Beech 18s; N130L noted 6.8.98 in contractors yard Lawson Road near Scyene Road, Mesquite; N130L noted 3.8.02 on property 106 Lawson Road near Sceyene Road, Mesquite with other Beech18 hulks, reported that all Jim Hudson aircraft will shortly be sold by his estate; N130L noted Mesquite 9.5.03 in scrapyard near airport with other Twin beech hulks;

BA-279	E18S	N62V	built	.57
			Mitchell Aero Inc, Milwaukee WI	63/64
			Great Plains Water Co, Austin TX	66
			S. W. Sisk/ Orion Airways, St. Louis MO	68/69
			Sisk Aviation Activities, St Louis MO	70
			James E. Boyett, East Point GA	72
			Precision Valley Aviation, Springfield VT	75/82
			damaged groundloop landing, Springfield VT	9.12.75
			Air Cargo Inc, McAllen TX	22.10.82/83
			sold to Mexico, struck-off USCR	25.1.83

N62V noted Dallas-Love TX 21.4.66;

N62V accident report 9.12.75: Precision Valley Aviation, flight to Boston MA, groundloop when returned due brake mechanical problem on takeoff, struck object, pilot unhurt, 7pm; N62V noted Boston MA 9.80 "Precision"; N62V noted McAllen TX 7.10.82;

BA-280	E18S	N43G	built	.57
		XB-REP	Roberto M. Lopez, Mexicali	93
BA-281	E18S	N23Y	Atlantic Aviation Corp: CofA issued	24.5.57
	-9700		Food Fair Stores Inc, Philadelphia PA	18.7.57/66
		N231H	National Financing Inc, Wilmington DE	16.8.66/67
			Sebastaino Cannavo, Lester PA	8.12.67/71
			Call Air Transport, Goshen NY	30.3.71/72
			Belvon Aircraft Leasing Inc	14.3.72/76
			(Beech cargo door installed 3.72)	
			North American Publishing Co	5.8.76/77
			O. M. Richter	14.6.77
			I. D. Hill Co: sale documentation not completed	.77
			US Customs Service: seized	.78/80
			Commodities Recovery Corp	11.12.80
			K & K Aircraft Inc, Bridgewater VA	12.80/81
			Jorge L. Ibern, Guaynabo, Puerto Rico	23.4.81
			Raul Morales, Guaynabo, Puerto Rico	24.7.81
			Ramon Juan Alvarez, Miami FL	6.10.81/82
			Sergio B. Pantosa, Dania FL	29.6.82/84
			Aircraft Rebuilders, Opa Locka FL	12.84/86
			Harmer Inc, Miami FL	1.10.86/89
			Santee Aircraft, Manning SC	15.3.89/90

James P. Ewing/ High Tech Classics, Fresno CA	16.2.90/93
Matthew R. Barnet, Haleiwa HI	24.2.93/95
Jerry H. Jackson, Mililani HI	11.95
Kamaka Air Inc, Honolulu HI	6.3.98/19
reg expired 31.10.19, struck-off USCR	31.1.20

N231H noted Tamiami FL 5.12.78 N231H noted Tamiami FL 11.87; N231H noted Honolulu HI 26.2.01 all metallic, in service; N231H noted Honolulu HI 26.8.01 fully painted "Kamaka Air" titles, tailwheel; N231H noted Honolulu 13.11.05 being painted for TV series "Lost" to be used in flying scene representing a Beech 18 wreck found in a tree, owned Kamaka Air; N231H noted Honolulu 5.2.06 civil scheme no titles, at Kamaka Air hangar, with Tradewind & DC-3;

BA-282	E18S	N68V	Tulsair Distributors Inc, Tulsa OK	29.5.57
	-9700		Oklahoma Mississippi River Products Line Inc	17.6.57/59
			Sunray Mid-Continent Oil Co/ Sun Oil Co	19.2.59/61
			Lion Trailer Corp, La Crosse WI	7.11.61/68
			Gateway Aviation, La Crosse WI	10.68/70
	G18S cab		landed gear locked-up, La Crosse WI	5.2.69
			International Manufacturers & Representatives/ IMR Inc	15.5.70/75
			Bennett C. Pollard/ Midnight Air Express	4.12.75/76
			(cargo door & floor installed 1.76)	
			Blackhawk Airways, Janesville WI	1.7.76/84
			Richard J. Wixom, Janesville WI	11.10.84/91
			damaged by engine fire taxying, Janesville WI	20.4.85
			broken-up for parts: Beech cockpit cab installed in	
			N404T, wings to N929DV, tail to N103AF)	
			(owner report 1.91: aircraft destroyed or scrapped)	
			struck-off USCR	28.1.91

N68V accident report 5.2.69: Gateway Aviation, mechanical failure jammed gear; USCR70: reg pending, USCR72: not listed; N68V photo mid 70s: bronze & white, windows, G18S cab, tailwheel, "Midnight" titles; N68V noted Cincinatti OH 3.84 "Blackhawk Airways" titles, tailwheel, G18S cab;

BA-283	E18S	N23R	Butler Airplane Sales	5.6.57/58			
			Butler Co, Chicago IL	10.9.58/64			
	-9700		(mods to E18S-9700 installed 7.59)				
			Theodore H. McNabb	10.5.64/65			
			Chandler W. Drummond, Phoenix AZ	11.6.65/68			
			Harry H. Webb, Shelburne VT	24.9.68/71			
			Woodruff H. Griffin	11.2.72/73			
			Hamilton Aviation, Hamilton OH	7.5.73/77			
			Air Service Center Inc	15.4.77/79			
			HoganAir Inc, Hamilton OH	1.7.79/86			
		N86HA	HoganAir Inc, Hamilton OH	12.8.80/86			
		N8627A (2	HoganAir Inc, Hamilton OH	29.10.86			
			The Eagle and the Hawks Inc, Middletown OH	1.11.86/94			
			(cockpit exit hatch installed 4.87)				
			Miami Valley Aviation, Middletown OH	5.4.94/98			
			The Eagle and the Hawks Inc, Middletown OH	29.5.98/06			
			op: Miami Valley Aviation, Middletown OH	98/02			
			Michael J. Hogan, Fruitland Park FL	11.7.06/20			
			lsd: Stan Brock/ Remote Aera Medical Volunteer Corp,				
			Knoxville TN	.06/15			
	N8627A N8627A N8627A BA-283 b N8627A N8627A	noted Middletov noted Middletov noted Bessema puilt 6.57, anoth noted Middletov noted Middletov	wn OH 2.92 no titles, tailwheel; wn OH 30.8.97 no titles; wn OH 22.7.98 no titles; wr AL 12.8.98 Miami Valley Aviation, Middletown OH, plate er plate: -9700 conv. 7.59; wn OH 6.8.99 Miami Valley Aviation; wn OH 6.8.99 MVA, plate BA-283 built 6.57, -9700 conv 7				
	N8627A noted Middletown OH 20.7.02 operated by Miami Valley Aviation;						

N8627A noted Middletown OH 12.10.02 no titles;

N8627A noted Island Home TN 4.8.05 still in Miami Valley scheme but titles "Remote Area Medical"

titles, pilot Stan Brock; N8627A leased to Remote Aera Medical Volunteer Corp for \$1 per year for 15 years: takes medical assistance across USA and overseas offering medical help after disasters;

ooard, 3 k; N28X N501W N221H N221H	crashed on takeoff, destroyed, St.Thomas USVI ort 6.12.68 Conquest Airways, stalled on takeoff St Thomas built L. E. Dixon Co, Cleveland OH Frank Sinatra, Palm Springs CA S. J. Groves & Sons Co, Minneapolis MN crashed destroyed, Johnson City NY built Beaumont Car Leasing Corp, Beaumont TX Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	6.12.68 S-Harry S.Truman, .57 63 64 66/67 8.5.67 .57 63/64 66 69/70 1.6.70 79 22.8.79/82 8.11.82
ooard, 3 k; N28X N501W N221H N221H	built L. E. Dixon Co, Cleveland OH Frank Sinatra, Palm Springs CA S. J. Groves & Sons Co, Minneapolis MN crashed destroyed, Johnson City NY built Beaumont Car Leasing Corp, Beaumont TX Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	.57 63 64 66/67 8.5.67 .57 63/64 66 69/70 1.6.70 79 22.8.79/82
N28X N501W N221H nt report 1.6.70: 72: not listed;	L. E. Dixon Co, Cleveland OH Frank Sinatra, Palm Springs CA S. J. Groves & Sons Co, Minneapolis MN crashed destroyed, Johnson City NY built Beaumont Car Leasing Corp, Beaumont TX Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	63 64 66/67 8.5.67 .57 63/64 66 69/70 1.6.70 79 22.8.79/82
N501W N221H nt report 1.6.70: 72: not listed;	L. E. Dixon Co, Cleveland OH Frank Sinatra, Palm Springs CA S. J. Groves & Sons Co, Minneapolis MN crashed destroyed, Johnson City NY built Beaumont Car Leasing Corp, Beaumont TX Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	63 64 66/67 8.5.67 .57 63/64 66 69/70 1.6.70 79 22.8.79/82
N221H nt report 1.6.70: 72: not listed;	Frank Sinatra, Palm Springs CA S. J. Groves & Sons Co, Minneapolis MN crashed destroyed, Johnson City NY built Beaumont Car Leasing Corp, Beaumont TX Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	64 66/67 8.5.67 .57 63/64 66 69/70 1.6.70 79 22.8.79/82
N221H nt report 1.6.70: 72: not listed;	S. J. Groves & Sons Co, Minneapolis MN crashed destroyed, Johnson City NY built Beaumont Car Leasing Corp, Beaumont TX Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	66/67 8.5.67 .57 63/64 66 69/70 1.6.70 79 22.8.79/82
N221H nt report 1.6.70: 72: not listed;	crashed destroyed, Johnson City NY built Beaumont Car Leasing Corp, Beaumont TX Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	8.5.67 .57 63/64 66 69/70 1.6.70 79 22.8.79/82
nt report 1.6.70: 72: not listed;	built Beaumont Car Leasing Corp, Beaumont TX Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	.57 63/64 66 69/70 1.6.70 79 22.8.79/82
nt report 1.6.70: 72: not listed;	Beaumont Car Leasing Corp, Beaumont TX Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	63/64 66 69/70 1.6.70 79 22.8.79/82
72: not listed;	Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	66 69/70 1.6.70 79 22.8.79/82
72: not listed;	Air Lease Inc, Chicago-O'Hare IL Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	69/70 1.6.70 79 22.8.79/82
72: not listed;	Grand Forks Airmotive, Grand Forks ND forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	1.6.70 79 22.8.79/82
72: not listed;	forced landing gear-up off airport, due engine failure after takeoff, Detroit Lake MN Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	79 22.8.79/82
72: not listed;	Harold E. Roberts, Ivanhoe TX Herbert A. Hartley, Brownsville TX struck-off USCR	79 22.8.79/82
72: not listed;	Herbert A. Hartley, Brownsville TX struck-off USCR	22.8.79/82
72: not listed;	struck-off USCR	
72: not listed;		8.11.82
72: not listed;	anaratar Grand Farka Airmativa	
yard Denver C		
N51W	Ohio Aviation Co, Dayton OH	15.7.57
	Anchor Hocking Glass Corp Reading Aviation Service, Reading PA	24.9.57/62 1.10.62/73
	op: Suburban Airlines, Reading PA	72
	James T. Knight	13.4.73/76
	(cargo floor installed 5.73)	10.1.10/10
	Morey Wyman/ Wyman Pilot Service, Pontiac MI	10.1.76/98
	op: Lafayette Aviation	85
	crashed on takeoff, Youngstown OH	18.7.85
	struck-off USCR, owner's request	8.10.98
noted Pontiac N	/I 9.80 plate BA-287;	
N45G	built	.57
N448	R. Morgan, Corpus Christi TX	61/64
	H & F Ranch, Corpus Christi TX	66/70
N4061L	H. C. Marks	71
	Biscayne Suffolk Associates, Miami FL	71/72
		22.11.72/73
FT 4		10 0 70 77
EI-AFE		10.9.73/75
		17.5.75/87
		75/87
	CIASHEU WUHUU TIKA AWASSA FAIMI	8.4.87
	cka FL 23 8 71:	
	noted Pontiac N nt report 18.7.8 N45G N448 N4061L ET-AFE	crashed on takeoff, Youngstown OH struck-off USCR, owner's request         noted Reading PA 29.5.72 Suburban Airlines; noted Pontiac MI 9.80 plate BA-287; nt report 18.7.85: operated by Lafayette Aviation;         N45G       built         N448       R. Morgan, Corpus Christi TX H & F Ranch, Corpus Christi TX         N4061L       H. C. Marks         Biscayne Suffolk Associates, Miami FL International leasing Corp, Miami FL (del. to Ethiopia via Keflavik-Prestwick-Luton 4.10.73)

BA-289	E18S	N47G	Pacific Aircraft Sales Co: CofA issued Georgia-Pacific Corp	21.6.57 28.6.57/59
			L. A. Johnson/ Rialto Co	6.11.59/60
			Pope & Talbot Inc, San Francisco CA	3.3.60/69
			George A. Pope, San Francisco CA	70/79
		XB-BPH	false registration: operated by drug dealer	c79
		confiscated	, owner arrested, San Jose de Cabo,	
			Southern Baja California, Mexico	c80
		(open stora	ge, Cabo San Lucas 80/92)	
			Hacienda Publico Federal	17.3.89/91
			Francisco Jose Chavez Macias	91
			Banco Mercantil Del Norte: sales agent	91
		N47G	Westernair Inc, Albuquerque NM	1.10.91/92
			(ferried Cabo San Lucas to Van Nuys 29.3.92, as XB-BPH, rebuilt at Van Nuys CA 92)	
			Brian L. Launder, Tulsa OK	9.10.92/20

(note: N47G shown as N47D in 1961 USCR then reverted to N47G: no mention in FAA file) "The Beech Eagle" article 3.92: N47G based Oakland CA as executive aircraft first 20 years, plush 4 leather seat cabin, sold c78 to drug runner who used it as personal transport with false reg XB-BPH; engines overhaulled and interior retained, flew 120 hours with new owner until he took a vacation at Cabo San Lucas, Mexico where he was arrested and aircraft confiscated by Mexican authorities, parked in open at Cabo San Lucas airport near sea 80/91 when Dick Durand of Westernair obtained title from Mexican Government, advertised "as is" in Trade-A-Plane; prepared

for ferry 3.92 by Matt Jackson/Airworks, Van Nuys CA who flew to Cabo in a Bonanza with a team from Van Nuys to Cabo 24.3.92, Lee Cameron provided metallised control surfaces already in Mexico to replace the rotted fabric surfaces, ferried 29.3.92 to Van Nuys as XB-BPH for complete restoration by Matt Jackson's Airworks ; N47G notd Madera CA 23.4.72; N47G visited Beech Fly-In Tullahoma TN 13.10.95, plate BA-289; N47G at Beech Fly-In Tullahoma TN 10.10.99 owned by Brian Launder OK; N47G at Beech FlyIn Wichita KS 11.10.97, plate BA-289; N47G noted Tucson AZ 9.02 executive scheme, in service, tailwheel; N47G at Beech flyin Tullahoma TN 16.10.03;

BA-290	E18S	N37T	Ohio Aviation Co, Dayton OH: CofA issued	28.6.57
			Thompson Products Inc/	
			Thompson Ramo Wooldridge Foundation/	
			Space Technology Laboratories/ TRW Inc,	
			Redondo Beach CA, later Cleveland OH	28.6.57/74
		N37TC	Harry H. Delno/ Mission Airlines, Mojave CA	2.3.73/75
			Burke Matthews, Austin TX:	
			sale documentation not completed	30.1.75

N37T noted LAX 2.11.69, 19.5.70;

BA-291	E18S	N2100	Butler Airplane Sales	3.7.57
	-9700		Danly Machine Specialties Inc	3.7.57/58
		N210Q	Sollitt Construction Co, South Bend IN	11.4.58/70
			Skystream Inc, Plymouth IN	20.1.70/71
			Coachmen Industries Inc. Middlebury IN	27.7.71/72
			John Crawford/ Airline Air Conditioning Co	2.11.72/73
			S. S. Airways Inc, Kansas City KS	8.2.74/82
			George D. Gandy, Lenaxa TX	4.5.82
			Verl Thompson, Springdale AR	11.82
			Verl Thompson, Springdale AR: restored to USCR	3.93
			Springdale Air Service, Springdale AR	15.6.95
			SCS Group Ltd, Springdale AR	13.9.95
			op: Springdale Air Service, Springdale AR	97
			Springdale Air Service, Springdale AR	13.7.98/99
			crashed Fort Smith AR	6.8.99
			Mosquito Bel Air, Greenville MS	9.11.00/01
			(conv. for spraying 10.00 by Crowley's Ridge Aviation, Helena AR)	
			Vector Disease Control Inc, Waltham MA	5.3.02/06

(mosquito spraying: subsidiary of Mosquito Bel Air)	
Paul H. Bartlett, Marion NC	17.9.08/13
Byron Rovey, La Grande OR	20.8.13/16
Cascade Airways, Corvallis OR	23.8.17/20

N210Q noted Kansas City-Fairfax 3.6.76; N210Q noted Memphis TN 8.97 Springdale Air Service; N210Q noted at Rockford IL 24.7.08, for sale at Courtesy Aircraft hangar; further details spraying: see Beech 18 by Robert Parmerter p.292;

	-9700	N21011	Danly Machine Specialties Inc	
	-9700	N21011		16.7.57/58
	-9700		Missouri State Highway Dept., Jefferson City MO	12.6.58/78
			(mods to E18S-9700 installed 6.61,	
			G18S type cockpit cab installed 10.61)	10 70/00
			Welco Leasing Co	10.78/80
			(cabin cargo floor installed 11.78)	44.00/00
			Louis W. Stallings	11.80/83
			op: Southwest Air Transport	83
			Delco Delp Corp	2.11.83
			Bahamas Customs Department: seized (found at Cistern Bay with a cocaine cargo 23.4.84)	26.4.84
			Aviation One Inc, Cincinatti OH	20.8.64/65
			Nihon Kaisha Design Group	12.6.85
			J. M. DuFriend/ D & D Airepair, Perris CA	10.85/86
			Paralift Inc, Pasadena CA	8.6.86/88
			Auburn Flying Service, Auburn CA	1.88/93
			Native Village of Mekoryuk/	
			Bering Sea Reindeer Products, Mekoryuk AK	10.2.93/95
			Charles C. Bramel, Xenia OH	4.11.97/99
			op: Carolina Skysports, Louisburg NC	99
			Vee Jay Enterprises, Eaton OH	15.6.00/02
			Airplane Services Inc, Jay FL	4.2.03
			Frances T. Hess, Fayetteville GA K.R.Oddy Associates Inc, Orange Park FL	19.3.04/11 13/20
	N21011a N21011 a N21011 a N21011 a	t Beech flyin at fly-in Lakela at fly-in Oshko	iana stickers inside cabin; Tullahoma TN 16.10.03; and FL 15.4.05 tailwheel; osh 7.05 plate BA-292; anta-Peachtree GA 10.05, allover metallic, flying; osh 7.06,	
	N21011 a	at fly-in Lakela	and FL 21.4.07;	
3A-293	E18S	N53S	Combs Aircraft Inc: CofA issued	12.7.57
	-9700		Mid-Continent Leasing Co	6.12.57/59
			Rockford Newspapers Inc, Rockford IL Frontier Ford Inc	4.12.59/70
				31.7.70/72 21.6.72/76
			Viking International Airlines, Minneapolis MN (cargo door installed 12.72)	
			Eugene Pikovsky & William H. Ramsey, Minneapolis MN Isd: Viking International Airfreight, Minneapolis MN	29.9.76/81 5.10.76/79
			(cockpit door installed 2.77)	0.10.10.10
				31.8.81/84
			(cockpit door installed 2.77) Robert J. Belmar/ Blue Star Aviation, Brownsville TX	
			(cockpit door installed 2.77)	31.8.81/84

N53S noted Indianapolis IN 5.68 "Remarkable Rockford Illinois" titles, tailwheel, curtains in windows; USCR72: not listed; N53S noted Brownsville TX 10.87 tailwheel;

BA-294	E18S	N54S	Beechcraft Aircraft Corp, Wichita KS: CofA issued	15.7.57

	Currey Sanders Aircraft Co, Shreveport LA	19.7.57
	Wheless Drilling Co, Shreveport LA	6.11.57/77
(N24S)	ntu: Wheless Drilling Co, Shreveport LA	2.5.77
N54S	John R. Webster, Shreveport LA	6.7.77/78
	Richard L. Burger	20.9.78/81
	found abandoned damaged in a ditch, Cox's Air Strip SC	
	loaded with 1,840lb marijuana. painted as "N70B"	8.3.81
	South Carolina Aeronautics Commission, Columbia SC	4.81
	North American Aviation Institute, Conway SC: donated	
	(inst airframe, painted as "N5606NA" with "392" on tail)	
	purchased by restorer, moved to Lake City SC, by	13
	in use by fire service near Florence SC by	16

"N5606NA" noted Marion County Airport,Lake City SC 9.10.95 complete, looks good condition, red & white; same location 6.13 with outer wings removed, fabric tattered, red and white; noted near Mytle Beach FL 2.16

BA-295	E18S	N26Y	Tulsair Distributors Inc	22.7.57/58
			Pan American Petroleum Corp, Tulsa OK	21.8.58/65
			Standard Oil Co/ 910 Michigan Ave, Chicago IL	
		N910U	Nine-Ten Corp, Chicago IL	1.6.65
		N910R	Jack Adams Aircraft Sales, Walls MS	11.65/68
		N152JB	Jamison Bedding Inc, Nashville TN	12.65/68
			S. W. Sisk/ Orion Airways, St. Louis MO	7.68/69
			nosed over landing, Fayetteville AR	23.10.68
			George Sisk/ Orion Airways, St. Louis MO	68/69
			Maplewood Bank & Trust Co: repossessed	3.11.69/70
			Robert E. Staples, St Louis MO	12.69/71
			Isd: Sisk Aviation Activities, St Louis MO	70
			Apollo Airways, Kansas City MO	4.71/77
			(cargo floor & door installed prior to 73)	1.7 1777
			gear collapsed landing, Detroit-City MI	25.3.77
			Royal Air Freight/ Great Lakes Air Freight, Pontiac MI	14.6.77/91
			Jeffrey K. Gutow, San Carlos CA	3.12.91/94
			sold to Belize, struck-off USCR	30.3.94
				00.0.34
	due mech N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngsi noted Pontiac	t 25.3.77: Apollo Airways, cargo flight Ft Wayne IN to Deti pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no own OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air;	
	due mech N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngsi noted Pontiac	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no own OH 16.9.82 Royal Air Freight, Pontiac MI;	
3A-296	due mech N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngsi noted Pontiac	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no iown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; iown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued	
3A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin	props or tailwhe
3A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways	props or tailwhe 18.7.57
3A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways Mar Dora Inc, West Palm Beach FL: USCR	props or tailwhe 18.7.57 18.7.57/68
3A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways	props or tailwhe 18.7.57 18.7.57/68 6.68/70
8A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways Mar Dora Inc, West Palm Beach FL: USCR	props or tailwhe 18.7.57 18.7.57/68 6.68/70 69
8A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways Mar Dora Inc, West Palm Beach FL: USCR Aviation Sales Inc Jim Hankins Air Service, Jackson MS (cargo floor installed 4.72)	props or tailwhe 18.7.57 18.7.57/68 6.68/70 69 8.7.70/72
3A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways Mar Dora Inc, West Palm Beach FL: USCR Aviation Sales Inc Jim Hankins Air Service, Jackson MS (cargo floor installed 4.72) Morey L. Wyman/ Wyman Pilot Service, Pontiac MI	props or tailwhe 18.7.57 18.7.57/68 6.68/70 69 8.7.70/72
3A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways Mar Dora Inc, West Palm Beach FL: USCR Aviation Sales Inc Jim Hankins Air Service, Jackson MS (cargo floor installed 4.72) Morey L. Wyman/ Wyman Pilot Service, Pontiac MI Hubert J. Dwyer/ Dwyer Air Cargo, Mason City IA	props or tailwhe 18.7.57 18.7.57/68 6.68/70 69 8.7.70/72 24.3.72/74
3A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways Mar Dora Inc, West Palm Beach FL: USCR Aviation Sales Inc Jim Hankins Air Service, Jackson MS (cargo floor installed 4.72) Morey L. Wyman/ Wyman Pilot Service, Pontiac MI	props or tailwhe 18.7.57 18.7.57/68 6.68/70 69 8.7.70/72 24.3.72/74 30.3.74/83
8A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways Mar Dora Inc, West Palm Beach FL: USCR Aviation Sales Inc Jim Hankins Air Service, Jackson MS (cargo floor installed 4.72) Morey L. Wyman/ Wyman Pilot Service, Pontiac MI Hubert J. Dwyer/ Dwyer Air Cargo, Mason City IA	props or tailwhe 18.7.57 18.7.57/68 6.68/70 69 8.7.70/72 24.3.72/74 30.3.74/83 5.5.83/15
3A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways Mar Dora Inc, West Palm Beach FL: USCR Aviation Sales Inc Jim Hankins Air Service, Jackson MS (cargo floor installed 4.72) Morey L. Wyman/ Wyman Pilot Service, Pontiac MI Hubert J. Dwyer/ Dwyer Air Cargo, Mason City IA tailwheel collapsed on landing, Cedar Rapids IA	props or tailwhe 18.7.57 18.7.57/68 6.68/70 69 8.7.70/72 24.3.72/74 30.3.74/83 5.5.83/15
3A-296	due mech N152JB r N152JB r N152JB r N152JB r	nanical failure, noted Detroit ( noted Youngs noted Pontiac noted Youngs	pilot unhurt, 12.45am; City MI 26.5.77, "Apollo Airways" titiles, minor damage, no fown OH 16.9.82 Royal Air Freight, Pontiac MI; MI 7.91 Royal Air; fown OH 16.9.82 Royal Air Freight; Butler Airplane Sales: CofA issued Walker Manufacturing Co of Wisconsin Lexington Air Taxi/ Lexington Airways Mar Dora Inc, West Palm Beach FL: USCR Aviation Sales Inc Jim Hankins Air Service, Jackson MS (cargo floor installed 4.72) Morey L. Wyman/ Wyman Pilot Service, Pontiac MI Hubert J. Dwyer/ Dwyer Air Cargo, Mason City IA tailwheel collapsed on landing, Cedar Rapids IA (retired Mason City IA, for ssle by auction 6.17)	props or tailwhe

N5600D & N20GL auction at Mason City IA 6.17: N5600D complete, metallic, parked in high grass;

BA-297	E18S	N5601D	built	7.57
			Coastal Rental Corp, Monroe LA	63/70
			Lyle Adams, Rayvville LA	72
			SMB Stage Line Inc, Des Moines IA	76/77
			Blackhawk Airways, Janesville WI	12.1.77/84
			prop blade failed, engine torn away,	
			crashed destroyed in forced landing near Plymouth IN	1.10.77
			(wreck stored Janesville WI 82)	
			struck-off USCR	12.7.84

accident report 1.10.77: Blackhawk Airways, cargo flight Dayton OH to Chicago, right propeller failed, right engine torn away, forced landing 4.56am, destroyed, pilot hurt; N5601D noted Janesville WI 10.5.82, derelict, "Blackhawk" titles;

BA-298	E18S	N36N	Beech Aircraft Corp	8.57/58
			Alamo Aviation, San Antonio TX	22.5.58
			Rodney DeLange	20.6.58/60
			SC State Development Board, Columbia SC	22.8.60/67
			SC Aeronautics Commission, Columbia SC	1.11.67/71
			(picture windows, 2 piece windshield installed	
	-9700		and mods to E18S-9700 completed 8.68)	
			Midlands Aviation Corp	1.7.71
			Rod M. Love, Columbia SC	11.9.71/81
			Barron Thomas Aviation, Dallas TX	16.4.81/82
			sold to Canada: struck-off USCR	6.82
		C-GPAV	Keewatin Air Ltd, Winnipeg MAN	7.82/83
			op: Icarus Flying Service	85
			National Business Funding Inc	29.3.85
			David Quinn, Entry Island, Magdalen Islands QUE	85
			sold to USA: struck-off Canadian Register	4.85
		N900WP	National Business Funding Inc: reg candidate	3.85
			Lafayette Aviation	25.3.85/88
			(cabin cargo floor fitted 2.87)	
			crashed into houses on takeoff, destroyed, Detroit MI	10.3.88

accident report 10.3.88: Warren MI, Lafayette Aviation: crashed into houses after takeoff Detroit, cargo misloaded, shifted on takeoff;

BA-299	E18S	N5603D	Parker Pen Co, Janesville WI	6.57
		N61A	Parker Pen Co, Janesville WI	57/61
		N613A	Wyandotte Chemicals Corp, Wyandotte MI	16.2.61
		N387W	Wyandotte Chemicals Corp, Wyandotte MI	62/64
			Unitec Corp, Timonium MO	66
			Metro Air Service Co, Detroit-Metropolitan Airport MI	5.6.70/71
			wrecked in forced landing gear-up due engine failure,	
			Lyndon Station WI	15.9.70
			struck-off USCR	25.2.71

accident report 15.9.70 N387W: Metro Air Service, intentional wheels-up forced landing due right engine failed, unable to maintain altitude, 1 unhurt;

BA-300	E18S -9700	N49R	Krispy Kreme Doughnut Co, Winston Salem NC (mods to E18S-9700 by Piedmont Aviation, Winston-Salem NC .57)	.57/64
		N911H N12TF	Piedmont Aviation, Winston Salem NC American Lease Plans Inc, Anderson SC	66/72 27.3.72/91
BA-301	E18S -9700	N24Y	Atlantic Aviation Corp: CofA issued Correale Construction Co, Hazleton PA Muratone Co, Philadelphia PA Semo Aviation, Malden MO Baron Aviation Services, Vichy MO sale reported, Weiner AR Henry B. Ponder, Heber Springs AR	7.8.57 27.9.57/68 12.9.68/72 14.4.72/80 9.5.80/99 01/02 21.10.04/13

Russ Amos, Batesville AR

BA-302	E18S	N5604D	Alamo Aviation, San Antonio TX: CofA issued	12.8.57
			Centex-Zachary/Centex Construction Co, Dallas TX	24.9.57/63
			Corporate Air Industries Inc, Anaheim CA	7.11.63/64
			Murietta Farms Co, Madera CA	12.64/68
	trigear		(Volpar Mk.IV trigear installed 1.65)	
	-	N979ST	Murietta Farms Co, Madera CA	15.7.68/75
			(G18S type two-piece windshield, and picture	
			windows kit installed 7.68)	
			William H. MillerSilver State Airlines	3.4.75/76
			(high-density pax seating installed 7.75)	
			Aviation Parts Inc, Las Vegas NV	15.3.76
		N979SB	Aviation Parts Inc, Las Vegas NV	11.76/77
			Land-Air Sales & Leasing Inc	1.6.77
			Aviation Parts Inc, Las Vegas NV	15.8.77
			op: Air Fast Freight	77
			crashed destroyed on takeoff, Catalina Island CA	22.8.77
			-	

N24Y noted St Louis MO 3.76 "Semo Airways: tailwheel; St Louis MO 2.6.76 retired;

accident report 22.8.77: Air Fast Freight, flight to Long Beach, 2 crew affected by carbon monoxide poisoning from exhaust, both killed - photo shows brown & white scheme;

BA-303	E18S	N54N	built	,57
			Farm & Home Savings Association, Nevada MO	63/64
			MFA Security Service, Columbia MO	66/69
			reg. pending, Harrisonville MO	70
			William S. Schwab, Joplin MO	72
			Bob Kilpatrick Aircraft Inc, West Memphis AR crashed destroyed on takeoff in snow & fog,	9.11.73/75
			struck building, Wheeling-Pal Waukee IL	6.3.75

3A-304	E18S	N29N	built	,57		
			Digiorgio Fruit Corp, San Francisco CA	63/70		
			Eureka Aero Industries, Eureka CA	74/75		
			Air Courier Inc, Eureka CA	25.2.74/75		
			crashed destroyed in violent weather, near Claude TX	28.5.75		
	USCR72	: not listed				
	N29N photo 8.74, tailwheel, "Eureka Aero" titles;					
	N29N DN	0to 8.74. tain	Nneel, "Eureka Aero" titles:			
				t Worth TX.		
	N29N ac	cident report	vneei, "Eureka Aero" titles; 28.5.75: Eureka Aero Industries, mail flight Amarillo TX to F d in extreme thunderstorms & hail, 10.22pm, pilot k;	t Worth TX,		
	N29N ac descende	cident report ed into groun	28.5.75: Eureka Aero Industries, mail flight Amarillo TX to F d in extreme thunderstorms & hail, 10.22pm, pilot k;			
3A-305	N29N ac	cident report	28.5.75: Eureka Aero Industries, mail flight Amarillo TX to F	t Worth TX,		
3A-305	N29N ac descende	cident report ed into groun	28.5.75: Eureka Aero Industries, mail flight Amarillo TX to F d in extreme thunderstorms & hail, 10.22pm, pilot k;			
3A-305	N29N ac descende	cident report ed into groun	28.5.75: Eureka Aero Industries, mail flight Amarillo TX to F d in extreme thunderstorms & hail, 10.22pm, pilot k; Piedmont Aviation, Winston Salem NC: CofA issued	29.8.57		
3A-305	N29N ac descende	cident report ed into groun N27R	28.5.75: Eureka Aero Industries, mail flight Amarillo TX to F d in extreme thunderstorms & hail, 10.22pm, pilot k; Piedmont Aviation, Winston Salem NC: CofA issued R. J. Reynolds Tobacco Co	29.8.57 30.8.57/59 11.5.59/60		
3A-305	N29N ac descende	cident report ed into groun N27R	28.5.75: Eureka Aero Industries, mail flight Amarillo TX to F d in extreme thunderstorms & hail, 10.22pm, pilot k; Piedmont Aviation, Winston Salem NC: CofA issued R. J. Reynolds Tobacco Co R. J. Reynolds Tobacco Co	29.8.57 30.8.57/59 11.5.59/60 20.5.60/72		
3A-305	N29N ac descende	cident report ed into groun N27R	<ul> <li>28.5.75: Eureka Aero Industries, mail flight Amarillo TX to F d in extreme thunderstorms &amp; hail, 10.22pm, pilot k;</li> <li>Piedmont Aviation, Winston Salem NC: CofA issued R. J. Reynolds Tobacco Co R. J. Reynolds Tobacco Co DeVlieg Machine Co, Royal Oak MI</li> </ul>	29.8.57 30.8.57/59		
A-305	N29N ac descende	cident report ed into groun N27R	<ul> <li>28.5.75: Eureka Aero Industries, mail flight Amarillo TX to F d in extreme thunderstorms &amp; hail, 10.22pm, pilot k;</li> <li>Piedmont Aviation, Winston Salem NC: CofA issued R. J. Reynolds Tobacco Co R. J. Reynolds Tobacco Co DeVlieg Machine Co, Royal Oak MI Semo Aviation/ Semo Airways, Malden MO</li> </ul>	29.8.57 30.8.57/59 11.5.59/60 20.5.60/72 22.4.72/81		

N59U noted St Louis MO 29.9.72 Semo Airways;

BA-306	E18S	N75Z	built	.57
			Hughes Supply Inc, Orlando FL	63/70
		N829K	Executive Air Leasing Inc, Orlando FL	71/74
			South Florida Aircraft Sales & Leasing Inc, Miami FL	13.3.74
			sold to Chile, struck-off USCR	23.7.74
		CC-CAK	reg.	.74

Transporte Aereo de Magallanes Ltda - TAMA,	
Punta Arenas	80
accident at Punta Arenas	2.8.80
Aerodromo Luis Fuentes Martinez, Porvenir, Chile:	
gate guard on plinth, painted as "CCHV"	07/20

N829K noted Miami FL 7.74 Executive AIr Leasing;

BA-307	E18S	N100W (2	built	.57
	-9700		Landis Carr Aviation, Los Angeles Airport CA	3.6.63
			sold to Mexico, struck-off USCR (same day)	3.6.63
		XB-YOO	reg.	.63
			Banco Regional Del Norte S.A.	68
			sold to US, struck-off Mexican Register	19.11.68
		N2510C	Industrial Nucleonics Corp	11.68/69
			Ross Aviation, Tulsa-Riverside OK	18.1.69
			(US CofA renewed 15.1.69)	
			Great Western Airlines, Tulsa-Riverside OK	2.6.69/76
			(cargo floor installed 4.72)	
			forced landing at night in crop field, hit fence,	
			near Kalamazoo MI	30.4.76
			M & K Aviation	13.8.76
			Cardinal Aviation	11.76/77
			Harry H. Delno, Mojave CA, later Sanford FL	24.8.77/91
	with fuel pu	imps, hit crop	30.4.76: en route Kalamazoo-Detroit, fuel starvation due n os, fence and a hog, 2.13am, pilot unhurt; oo MI 10.76 "Great Western Airlines", tailwheel, tatty;	nechanical fault
		ted Mojave C		
			s CA 29.11.79 derelict, ex Great Western;	
			after 30.4.76 accident probably for parts only;	
	J. J			
A-308	E18S	(N5602D)	ntu: Beech Aircraft Corp, Wichita KS	21.8.57
		N200HR	J. D. Reed Co, Houston TX: CofA issued	21.8.57
			Hampton C. Robinson, Houston TX	23.8.57/65
			American Aero Leasing Corp	19.3.65
			Gilley Airways Corp, Myrtle Beach SC	9.12.65/66
		N342E	Gilley Airways Corp, Myrtle Beach SC	18.2.66/68
	trigear		(Volpar trigear, G18S type windshield, picture	
	0		windows kit installed 2.66)	
			Fiber Controls Corp, Gastonia NC	12.68/70
			Vercoa Air Service, Danville IL	22.9.70/74
			Royale Airlines	28.1.74/75
			Tul-Aero Inc	14.2.75
			Joseph T. Mackey	25.9.75/77
			op: Baja Airlines	76
			gear collapsed landing, Bahia de Los Angeles, Mexico	20.2.76
			landed gear-up on foamed runway, San Diego CA	26.5.76
			Aero Wasp, Redondo Beach CA	14.6.77
			Aircraft Associates	12.77/79
			Aerospace Products Inc, North Hollywood CA	22.1.79/81
			op: Silver State Airlines, Las Vegas NV	81
	Hamilton		(mods for <i>Hamilton Little Liner</i> by Hamilton Aviation,	
	Little Liner		Tucson AZ 6.81)	
			Lani Bird Inc/ Scenic Air Tour, Honolulu HI	10.81/92
			(fleet #24)	
			Tomy International Inc dba Scenic Air Tours, Honolulu HI	1.3.91/92
			crashed into Mount Kaleakala, Kahului, Maui HI (9 k)	22.4.92
	N342E note	ed Chicago-C	D'Hare 14.7.71 Vercoa AS;	
			20.2.76: Baja Airlines: flight Mexicali-Bahia LA, 9 unhurt;	
			26.5.76: Baja Airlines: mechanical failure in gear, 8 unhurt;	
			CA 12.7.81 "for Silver State Airlines";	
			9.83 "Lani Bird/Scenic Air Tour" Fleet #24, plate BA-308;	

N342E noted Honolulu 9.83 "Lani Bird/Scenic Air Tour" Fleet #24, plate BA-308; N342E noted Kahului HI 2.88 allover green "Scenic Air Tours" trigear;

N342E noted Honolulu 7.89 "Scenic Air Tour" fleet #24, trigear; crash report 22.4.92: struck Mount Kaleakala, operated by Tomy International dba Scenic Air Tours;

Steve Darke quotes this N477GM accident repor engine failed after taked frost on wings, insufficie E18S CN-TTC TR-LQG CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D	ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield; Journal Publishing Co, Albuquerque NM W. C. Spain, Santa Fe NM Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to d and burned, 2k;	to Selawik AK, eaking through ic 12.57/73 3.73/78 5.75 63/64 66 26.5.69/71 22.6.71
N477GM reported as tu Steve Darke quotes this N477GM accident repor engine failed after taked frost on wings, insufficie E18S CN-TTC TR-LQG CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	Bernard Florcke, Anchorage AK op: Gifford Aviation, Anchorage AK op: Aurora Air Service, Fairbanks AK gear-up forced landing on frozen lake, after takeoff Kotzebue AK <i>inbine when crashed 10.79: but see report below re engines</i> <i>is an unknown turbine conversion;</i> <i>rt 25.10.79: Aurora Air Service, cargo flight Kotzebue AK to</i> <i>off, pilot landed gear-up on frozen lake to prevent gear bre-</i> <i>ent engine warm up, pilot unhurt;</i> Omnium Nord Africain, Casablanca & Rabat (CN-TTC delivered via Prestwick 27.9.57) Ste Nideco SA/Air Inter Gabon, Port Gentil CofA expired, struck-off Register <i>Prestwick 27.9.57 Omnium Nord Africain;</i> <i>Senegal 24.7.62 Ardic;</i> <i>ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield;</i> Journal Publishing Co, Albuquerque NM W. C. Spain, Santa Fe NM Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to a d and burned, 2k;	16.5.78/79 79 79 25.10.79 e warmup; to Selawik AK, eaking through ic 12.57/73 3.73/78 5.75 63/64 66 26.5.69/71 22.6.71
Steve Darke quotes this N477GM accident repor engine failed after taked frost on wings, insufficie E18S CN-TTC TR-LQG CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	op: Gifford Aviation, Anchorage AK op: Aurora Air Service, Fairbanks AK gear-up forced landing on frozen lake, after takeoff Kotzebue AK urbine when crashed 10.79: but see report below re engines is an unknown turbine conversion; rt 25.10.79: Aurora Air Service, cargo flight Kotzebue AK off, pilot landed gear-up on frozen lake to prevent gear bree ent engine warm up, pilot unhurt; Omnium Nord Africain, Casablanca & Rabat (CN-TTC delivered via Prestwick 27.9.57) Ste Nideco SA/Air Inter Gabon, Port Gentil CofA expired, struck-off Register Prestwick 27.9.57 Omnium Nord Africain; Senegal 24.7.62 Ardic; ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield; Journal Publishing Co, Albuquerque NM W. C. Spain, Santa Fe NM Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to the d and burned, 2k;	79 79 25.10.79 e warmup; to Selawik AK, eaking through ic 12.57/73 3.73/78 5.75 63/64 66 26.5.69/71 22.6.71
Steve Darke quotes this N477GM accident repor engine failed after taked frost on wings, insufficie E18S CN-TTC TR-LQG CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	op: Aurora Air Service, Fairbanks AK gear-up forced landing on frozen lake, after takeoff Kotzebue AK Inbine when crashed 10.79: but see report below re engines is an unknown turbine conversion; rt 25.10.79: Aurora Air Service, cargo flight Kotzebue AK is off, pilot landed gear-up on frozen lake to prevent gear bree ent engine warm up, pilot unhurt; Omnium Nord Africain, Casablanca & Rabat (CN-TTC delivered via Prestwick 27.9.57) Ste Nideco SA/Air Inter Gabon, Port Gentil CofA expired, struck-off Register Prestwick 27.9.57 Omnium Nord Africain; Senegal 24.7.62 Ardic; ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield; Journal Publishing Co, Albuquerque NM W. C. Spain, Santa Fe NM Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to the d and burned, 2k;	79 25.10.79 e warmup; to Selawik AK, eaking through ic 12.57/73 3.73/78 5.75 63/64 66 26.5.69/71 22.6.71
Steve Darke quotes this N477GM accident repor engine failed after taked frost on wings, insufficie E18S CN-TTC TR-LQG CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	gear-up forced landing on frozen lake, after takeoff Kotzebue AK Inbine when crashed 10.79: but see report below re engines is an unknown turbine conversion; rt 25.10.79: Aurora Air Service, cargo flight Kotzebue AK to off, pilot landed gear-up on frozen lake to prevent gear bree ent engine warm up, pilot unhurt; Omnium Nord Africain, Casablanca & Rabat (CN-TTC delivered via Prestwick 27.9.57) Ste Nideco SA/Air Inter Gabon, Port Gentil CofA expired, struck-off Register Prestwick 27.9.57 Omnium Nord Africain; Senegal 24.7.62 Ardic; ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield; Journal Publishing Co, Albuquerque NM W. C. Spain, Santa Fe NM Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to the d and burned, 2k;	25.10.79 e warmup; to Selawik AK, eaking through ic 12.57/73 3.73/78 5.75 63/64 66 26.5.69/71 22.6.71
Steve Darke quotes this N477GM accident repor engine failed after taked frost on wings, insufficie E18S CN-TTC TR-LQG CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	after takeoff Kotzebue AK Information of the set of th	e warmup; to Selawik AK, eaking through ic 12.57/73 3.73/78 5.75 63/64 66 26.5.69/71 22.6.71
Steve Darke quotes this N477GM accident repor engine failed after taked frost on wings, insufficie E18S CN-TTC TR-LQG CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	<ul> <li>Irbine when crashed 10.79: but see report below re engines is an unknown turbine conversion;</li> <li>Int 25.10.79: Aurora Air Service, cargo flight Kotzebue AK at off, pilot landed gear-up on frozen lake to prevent gear breat engine warm up, pilot unhurt;</li> <li>Omnium Nord Africain, Casablanca &amp; Rabat (CN-TTC delivered via Prestwick 27.9.57)</li> <li>Ste Nideco SA/Air Inter Gabon, Port Gentil CofA expired, struck-off Register</li> <li>Prestwick 27.9.57 Omnium Nord Africain;</li> <li>Senegal 24.7.62 Ardic;</li> <li>ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield;</li> <li>Journal Publishing Co, Albuquerque NM</li> <li>W. C. Spain, Santa Fe NM</li> <li>Hankins Airways, Jackson MS</li> <li>crashed destroyed after takeoff, Birmingham AL</li> <li>Hankins Airways, cargo improperly tied down, shifted to a and burned, 2k;</li> </ul>	e warmup; to Selawik AK, eaking through ic 12.57/73 3.73/78 5.75 63/64 66 26.5.69/71 22.6.71
Steve Darke quotes this N477GM accident repor engine failed after taked frost on wings, insufficie E18S CN-TTC TR-LQG CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	s is an unknown turbine conversion; rt 25.10.79: Aurora Air Service, cargo flight Kotzebue AK to off, pilot landed gear-up on frozen lake to prevent gear bre- ent engine warm up, pilot unhurt; Omnium Nord Africain, Casablanca & Rabat (CN-TTC delivered via Prestwick 27.9.57) Ste Nideco SA/Air Inter Gabon, Port Gentil CofA expired, struck-off Register Prestwick 27.9.57 Omnium Nord Africain; Senegal 24.7.62 Ardic; ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield; Journal Publishing Co, Albuquerque NM W. C. Spain, Santa Fe NM Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to a d and burned, 2k;	to Selawik AK, eaking through ic 12.57/73 3.73/78 5.75 63/64 66 26.5.69/71 22.6.71
TR-LQG CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	<ul> <li>(CN-TTC delivered via Prestwick 27.9.57)</li> <li>Ste Nideco SA/Air Inter Gabon, Port Gentil CofA expired, struck-off Register</li> <li>Prestwick 27.9.57 Omnium Nord Africain;</li> <li>Senegal 24.7.62 Ardic;</li> <li>ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield;</li> <li>Journal Publishing Co, Albuquerque NM</li> <li>W. C. Spain, Santa Fe NM</li> <li>Hankins Airways, Jackson MS</li> <li>crashed destroyed after takeoff, Birmingham AL</li> <li>Hankins Airways, cargo improperly tied down, shifted to a d and burned, 2k;</li> </ul>	3.73/78 5.75 63/64 66 26.5.69/71 22.6.71
CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	<ul> <li>(CN-TTC delivered via Prestwick 27.9.57)</li> <li>Ste Nideco SA/Air Inter Gabon, Port Gentil CofA expired, struck-off Register</li> <li>Prestwick 27.9.57 Omnium Nord Africain;</li> <li>Senegal 24.7.62 Ardic;</li> <li>ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield;</li> <li>Journal Publishing Co, Albuquerque NM</li> <li>W. C. Spain, Santa Fe NM</li> <li>Hankins Airways, Jackson MS</li> <li>crashed destroyed after takeoff, Birmingham AL</li> <li>Hankins Airways, cargo improperly tied down, shifted to a d and burned, 2k;</li> </ul>	5.75 63/64 66 26.5.69/71 22.6.71
CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	Ste Nideco SA/Air Inter Gabon, Port Gentil CofA expired, struck-off Register Prestwick 27.9.57 Omnium Nord Africain; Senegal 24.7.62 Ardic; ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield; Journal Publishing Co, Albuquerque NM W. C. Spain, Santa Fe NM Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to a d and burned, 2k;	5.75 63/64 66 26.5.69/71 22.6.71
CN-TTC delivered via F CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	CofA expired, struck-off Register Prestwick 27.9.57 Omnium Nord Africain; Senegal 24.7.62 Ardic; ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield; Journal Publishing Co, Albuquerque NM W. C. Spain, Santa Fe NM Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to a d and burned, 2k;	5.75 63/64 66 26.5.69/71 22.6.71
CN-TTC visited Dakar, CN-TTC noted Columbi E18S N5605D accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	Senegal 24.7.62 Ardic; ier Neu Chatel, Switzerland 31.5.67 at ski resort airfield; Journal Publishing Co, Albuquerque NM W. C. Spain, Santa Fe NM Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to d and burned, 2k;	66 26.5.69/71 22.6.71
accident report 22.6.71: takeoff, stalled, crashed E18S N18R (2	W. C. Spain, Santa Fe NM Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to d and burned, 2k;	66 26.5.69/71 22.6.71
takeoff, stalled, crashed E18S N18R (2	Hankins Airways, Jackson MS crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to d and burned, 2k;	26.5.69/71 22.6.71
takeoff, stalled, crashed E18S N18R (2	crashed destroyed after takeoff, Birmingham AL : Hankins Airways, cargo improperly tied down, shifted to d and burned, 2k;	22.6.71
takeoff, stalled, crashed E18S N18R (2	: Hankins Airways, cargo improperly tied down, shifted to d and burned, 2k;	
takeoff, stalled, crashed E18S N18R (2	and burned, 2k;	rear of cabin dur
	J. D. Reed Co, Houston TX: CofA issued Rowan Oil Co	28.8.57 4.9.57/61
0,00	Champlin Oil & Refining Co	12.61/62
	L. F. Peterson, Fort Worth TX	10.62/70
	Texas A & M Research Foundation	1.12.70/71
		7.7.71/72
		11.72/75
		10.6.75/78 11.78/79
		8.2.79/84
		0.2.19/04
		21.9.84/85
		21.9.04/05 6.85/86
	· · ·	12.6.86/89
		17.4.89/99
	(converted to all-cargo configuration 2.90)	11.7.03/33
	op: Catalina Flying Boats, Long Beach CÁ	90/99
	Catalina Flying Boats, Long Beach CA	28.6.99/06
	op: Phoenix Airtransport, Phoenix AZ	02/03
	Harry Traufer/ Aircap Management Co, Opa Locka FL	12.4.06/11
	Opa Locka FL (repaired)	6.11.07
	crashed into house after takeoff, destroyed by fire,	
	Opa Locka FL (Traufer k)	2.5.11
		op: Catalina Flying Boats, Long Beach CA Catalina Flying Boats, Long Beach CA op: Phoenix Airtransport, Phoenix AZ Harry Traufer/ Aircap Management Co, Opa Locka FL damaged in collision on taxiway with Cessna 208, Opa Locka FL (repaired) crashed into house after takeoff, destroyed by fire,

N18R noted Chino CA 13.11.83, right rudder damaged; Note: In 1989 the owners of Aeronautical Services Inc, Friday Harbour WA purchased Long Beach

based Catalina Flying Boats Inc and used this company to service Catalina Island: sold two Geese and used Beech 18s N18R, N911E, N9375Y; N18R noted Long Beach CA 9.9.90; N18R noted Long Beach CA 7.91 at Catalina Flying Boats ramp, plate BA-312; N18R noted Long Beach CA 4.92, 2.4.93 in service, 4.95; N18R noted Long Beach CA 5.10.98 no windows, no titles, op Catalina Flying Boats, tailwheel; N18R noted Long Beach CA 17.8.99 no titles, op Catalina Flying Boats; N18R noted Long Beach CA 18.9.01 op Catalina Flying Boats, i/s; N18R noted Phoenix AZ 22.12.02 "Phoenix Airtransport" titles; N18R noted Phoenix AZ 6.03 op by Phoenix Air Transport, all metallic, tailwheel; N18R noted Opa Locka FL 4.06 "Phoenix Air Transport", all metallic, windows faired over;

BA-313E18SCN-TTD<br/>6V-AABOmnium Nord Africain, Rabat12.57/636V-AABAir Senegal<br/>crashed5.63.63

CN-TTD visited London-Gatwick 26.9.60; CN-TTD visited Dakar, Senegal 24.7.62 Ardic;

BA-314	E18S	N5608D	Butler Airplane Sales: CofA issued	9.9.57
	-9700		Allegheny Ludlum Steel Corp, Pittsburgh PA	11.9.57/67 16.3.67/70
			Elmira Aeronautical Corp, Horseheads NY	
			Bobbie J. Johnson/ Paris Airways, Paris TN	12.70/73
			International Sales & Leasing Inc	23.8.73/76
			(cargo door installed 9.75)	
			James Spector/ Great Western Associates	2.9.76/78
			John W. Albert/ Almore Aircraft, Miami FL	31.1.78/79
			William Blake: documentation not completed	16.1.79
<u></u>	= 100			
BA-315	E18S	N5609D	Southern Airways Co: CofA issued	5.9.57/58
			Albany Air Service, Albany GA	9.8.58
	0700		A. C. Samford Inc	9.8.58/62
	-9700		(mods to E18S-9700 installed 4.59)	0 40 00/05
	Triner		Albany Air Service, Albany GA	9.10.62/65
	Trigear		(Volpar trigear, picture windows, G18S type windscreen	
			installed 3.65 by Capitol Aviation, Springfield IL) Carenco Inc, Albany GA	12.65/80
			Calton Co	20.2.80/89
			University of the South, Sewanee TN	8.6.89/91
			Isd: Centre Airlines, Reedsville PA	1.9.90/91
			Centre Airlines, Reedsville PA	1.8.91
			David Nutt & Associates, Jackson MS	12.93/95
			Burt Faibisoff, Lake Havasu City AZ	16.5.95/96
			Hugh M. Eaton, Dublin NH	2.96/06
			Input/Output Technology Inc, Valencia CA	8.1.08/20

N5609D at Oshkosh 31.7.04;

BA-316	E18S	N5611D	built 8.57, CofA issued	24.9.57
			Flightcraft Inc	25.9.57
			Weyerhaeuser Timber Co, Tacoma WA	25.9.57/67
	Junior		(test aircraft fitted Aerojet-General Junior JATO in rear	
	JATO		of engine nacelles 19.1.58, testflown with JATO at	
			Beech plant, Wichitra KS 58)	
			Atlantic Aviation Service	18.12.67/68
			Vercoa Air Service, Danville IL	29.2.68
			Sam Vires/ Mid South Aircraft Sales, Memphis TN	12.10.68
			(mods for MAUW 9800lb installed 13.10.68)	
			S. W. Sisk/ Orion Airways, St. Louis MO	16.10.68/69
			struck trees, landed safely Iron Mountain MI	6.2.69
			Maplewood Bank & Trust Co MO: repossessed	3.11.69/70
			Sisk Aviation Activities, St Louis MO	14.1.70
			Skyway Aviation/ Skyway Airlines, Ft Leonardwood MO	12.2.70/78
			(mods. for MAUW 10,100lb installed 19.2.74)	
			taxied over steep embankment, Lexington KY	17.11.75
	Hamilton		(Hamilton extended nose installed 1.7.76 by	

Extended NoseHouston Aviation)<br/>Pacific Missionary Aviation, Agana, Guam<br/>(cargo airstair door & cockpit entry door installed 5.10.78)<br/>Jonathon Rosenberg & Russell D. Large,<br/>Fort Lee NJ & Philippines18.12.03/07<br/>17.9.07/17<br/>Michael M.Large, Angeles City, Philippines<br/>3.8.17/20<br/>reg expired 31.8.20, struck-off USCR8.12.20accident report 6.2.69: Orion Airways, 7.20am, night mail flight, pilots drowsy due inadequate rest,10.100<br/>10.100

allowed aircraft to descend, continued on to airfield;
N5611D noted St Louis MO 29.9.72 "Skyway Airlines";
N5611D accident report 17.11.75: taxy for takeoff for flight to Jefferson City MO, pilot misjudged speed while taxying 1.17pm, 11 minor injuries;
N5611D noted Tucson AZ 15.10.78;
N5611D long nose flew San Francisco-Honolulu-Majuro-Yap .79, based Yap;
Photo 89: bare metal with sharks mouth on extended nose;
N5611D noted Yap 23.3.95 all silver, red & white band, spread wings logo & cross;
N5611D photo at Clark, Philippines 2004;
N5611D noted Clark, Philippines 6.05 on rebuild, owned by Jonathon Rosenberg & Russel Large;
N5611D noted Clark Ti.1.07 complete, tailwheel, extended nose, departed several days later;
N5611D noted Clark Field 7.07 no props, otherwise complete;
N5611D noted Clark Field 29.12.16;

BA-317	E18S	N29X (1	built	9.57
		N711L (2	rereg	24.1.58
			landing gear retracted on landing, Rochester NY	10.7.59
		N7117	Maine & New Hampshire Granite Corp, Manchester NH	63/70
		N711TL	Gilley Airways, Hartsfield SC	71/73
			landed gear locked-up, Watertown NY	30.5.73
			Burlington Airways/ Burl Air Freight, Burlington WI crashed destroyed on takeoff, due wake turbulence	77/79
			from preceeding Boeing 727, Indianapolis IN	27.2.79
			Charles E. Bush/ Bush Aviation, Fort Lauderdale FL	79
			Bush Aviation, Dania FL: restored to USCR	31.1.85
			struck-off USCR	13.11.85

N711L BA-317 photo 1.59 by Larry Smiley; N7117 noted Washington-DCA 6.4.66; N7117L accident report 30.5.73: Gilley Airways, gear mechanical failure, 2.19am;

BA-318	E18S	N76S	Anderson Air Activities: CofA issued	17.9.57
			Air-Craft Leasing Corp	19.9.57/60
	-9700		(mods to E18S-9700 installed 4.59)	
			Sundstrand Corp, Rockford IL	10.60/65
			Hartzog-Schneck Aviation, Rockford IL	24.9.65/66
			DC Aircraft Inc, Detroit-City Airport MI	1.4.66/68
			(cargo door installed 11.66)	
			Hartzog Aviation, Rockford IL	1.3.68/72
			Air Central Airlines	11.72/73
			Lima Aviation Corp	12.73/76
			(cargo floor, cockpit door installed 8.75)	
			Kenneth D. Burden & Gerald Grismore	16.8.76/77
			Allen County Air Services, Pandora OH	13.5.77/80
		N136JR	Jack L. Rhoades/ Rhoades International, Seymour IN	3.80/87
			Rhoades Aviation Inc, Columbus IN	9.87/89
			ran into ditch on takeoff, Elyria OH	19.7.88
		N136JJ	Centre Airlines, Centre Hill PA	15.3.89/93
			(wrap-around windshield installed 9.89)	
			Southern Air Freight, St Joseph LA	11.93/95
			SCS Group Ltd, Springdale AR	12.95
			Springdale Air Service, Springdale AR	13.7.98/99
			Kestrel Inc, Waukee IA	13.3.01/02
			Dash Flying Service, Chilton WI	19.11.04/06
			Mark M. Neal, Kensington MD	27.12.07/18
			-	

N76S noted Chicago-O'Hare 30.9.71; N76S noted Columbus IN 29.9.79 Rhoades International; N76S noted Columbus IN 26.8.80 Rhoades International; N136JJ noted Springdale AR 8.97 in service, Springdale Air Service: plate BA-318 built 9.57, another plate: converted to E18S-9700 4.59; N136JJ noted Springdale 13.10.97 "Springdale Air Services"; N136JJ at fly-in Oshkosh 26.7.06 plate E18S-9700 BA-318 built 9.57; N136JJ noted at Janesville WI 25.7.08, still has Springdale Air Services titles; N136JJ visited Oshkosh flyin 7.16, 7.17;

BA-319	E18S	N5612D	Pacific Aircraft Sales Co: CofA issued	26.9.57/58
	-9700		Frederickson Equipment Co, Truckee CA	11.2.58/67
			Qualitron Aero Inc	6.10.67/68
			Ross Aviation, Tulsa-Riverside OK	3.7.68/69
			(cargo floor installed 11.69)	
		damaged when struck snowbank landing, Chicago IL2Sam Vires/ Mid-South Aircraft Sales, Memphis TN1Semo Aviation Inc, Malden MO7(cockpit emergency hatch installed 5.77)7Coker Airfreight Inc, Dallas TX1	70/76	
			27.12.73	
			10.76/77	
			7.2.77/80	
			11.80/81	
			damaged in ground-loop landing, Lubbock TX	18.2.81
		N90CA	Coker Airfreight Inc, Dallas TX	5.9.81/83
			Mountain Air Cargo, Denver NC	13.9.83/87
			Reggie S. Hopwood/ Cape Central Airways, Malden MO	2.87/92
			Cape Central Airways, Cape Girardeau MO	6.92/94
			damaged, struck by vehicle, Kansas City MO	14.3.94
		N582MS	Cape Central Airways, Cape Girardeau MO	30.6.94/95
			Earl V. Long, Wichita KS	14.7.95
			Professional Aviation, Alcoa TN	12.95
			Kestrel Inc, Waukee IA	7.97
			Comanche Air, Winthrop WA	18.7.98/99
		N33HH	Comanche Air, Winthrop WA	6.1.99/15
			op: Cascade Air, Ephrata WA	00
			Brian D. Fleming, Longview WA	27.8.15/20

N5612D accident report 27.12.73: Great Western Airlines, swerved on landing into snowbank, pilot unhurt, 6.08am;

N5612D accident report 18.2.81: Coker Airfreight: cargo flight from Grand Prairie TX; N90CA noted Cincinatti-Lunken OH 9.11.93 metallic "Cape Central Airways" titles; N90CA 14.3.94: struck by airport police car on ramp while taxying Kansas City, on freight flight for Cape Central AW; N582MS noted Wichita-Westport Airport KS 6.8.95 "Cape Central Airways";

N33HH noted Ephrata WA 15.10.14 polished metal, in service, no titles;

BA-320	E18S	N86D	Youngstown Airways/ Lease Air, Youngstown OH: CofA	26.9.57/63
		N8611	Air Orlando Inc, Orlando FL	2.5.63
			Richard R. Freeman, Orlando FL	2.12.63/64
			Robert Wray	10.64/65
		N1431T	Charles M. Stephenson	14.5.65
			landed gear-up, Opa Locka FL	22.5.65
			J. S. Showalter/ Showalter Co, Orlando FL	12.65/68
			S. W. Sisk/ Orion Airways, St. Louis MO	23.9.68/70
			Maplewood Bank & Trust Co: repossessed	3.11.69
			Sisk Aviation Activities, St. Louis MO	14.1.70
			Golden Eagle Aviation	9.70
			Skyway Aviation/ Skyway Airlines, Ft Leonardwood MO	26.3.71/80
	Hamilton		(Hamilton extended nose installed 4.75)	
	long nose		struck tug while taxying, St. Louis MO	8.3.79
	-		Nevada Aircraft Leasing Corp, Carson City NV	4.4.80/12
			struck-off USCR	6.7.12

N1431T noted St Louis MO 29.9.72 "Skyway AL";

N1431T accident report 8.3.79: Skyways Aviation, flight Ft Leonardwood to St Louis;

	E18S	N63E	Francis Aviation, Lansing MI Miller Industries Inc, Reed City MI	8.10.57 8.10.57/67
	-9700		(mods to E18S-9700 installed 8.59)	0.10.07/07
			Miller Airmotive Inc/ Miller Airlines, Osceola MI	19.5.67/69
			McCollum Aviation, Danville IL	4.4.69/70
			Runway 5 Aviation Inc, West Mifflin PA	7.70/74 7.74
	Hamilton		Nanuet National Bank, Nanuet NY: repossessed (rebuilt as <i>Hamilton Westwind III</i> with PT6A-20 turbines	1.14
	Westwind III		by Hamilton Aircraft Co at Tucson AZ 12.74)	
			Great Western Airlines, Tulsa-Riverside OK	28.5.75
		N202GW	Great Western Airlines, Tulsa-Riverside OK	2.76/81
			ground collision with tug, Chicago-O'Hare IL	22.12.77
			minor structural damage in flight, Tulsa OK Viking International Airlines, Minneapolis MN	26.11.80 4.3.81
			Ajax Aircraft Leasing Inc, Dover DE	5.11.85
			Active Aero Charter, Willow Run MI: leased	8.88/89
			Ken & Karl Stoltzfus/K & K Aircraft Inc, Bridgewater VA	3.91/07
			(agricultural mods CofA 19.4.91,	
			rebuilt by K&K 12.95 with G18S cockpit, fitted for	
			agricultural & pest control spraying operations)	
			Brazoria County Mosquito Control, Angleton TX	18.12.08/16
			struck-off USCR	18.10.16
	NOODOLA		March Street III.	
		photo 4.77 as	westwind III; t 22.12.77: Great Western, taxying after landing from Kan	sas City 12 51am
			ig did not give way;	Sas Cily, 12.51aiii,
			Run MI 3.8.89 "Active Aero Charter, Willow Run MI", West	wind:
			sboro VA 19.7.98 K&K Aircraft, turbine tailwheel, refuelled	
			ater Air Park VA 30.7.98, tailwheel turbines, in service;	',
			mitos CA 17.8.99 Westwind III K&K Aircraft, sprayer, "K&ł	Aircraft" titles.
			, another plate: converted to E18S-9700 8.59;	.,
			mitos CA 13.8.02 with other K&K sprayers;	
	11202600	noted Los Ald		
	11202000	noted 200 Ald		
BA-322	E18S	N617M	McLean Trucking Co, Winston Salem NC	63/66
BA-322			McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later	
BA-322			McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC	69/72
BA-322			McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI	69/72 21.10.74/79
BA-322			McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC	69/72
BA-322	E18S	N617M	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH	69/72 21.10.74/79
BA-322	E18S N617M no	N617M oted Washingto	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI	69/72 21.10.74/79 10.4.79
BA-322	E18S N617M no N617M ao	N617M oted Washingto	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322;	69/72 21.10.74/79 10.4.79 (son-
	E18S N617M no N617M ao Youngstor	N617M oted Washingto ccident report wn Exec OH, h	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot	69/72 21.10.74/79 10.4.79 (son- unhurt;
BA-322 BA-323	E18S N617M no N617M ao	N617M oted Washingto ccident report wn Exec OH, f N5615D	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report wn Exec OH, h	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp	69/72 21.10.74/79 10.4.79 (son- unhurt;
	E18S N617M no N617M ao Youngstor	N617M oted Washingto ccident report wn Exec OH, f N5615D	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60)	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report wn Exec OH, f N5615D	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report wn Exec OH, f N5615D	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report wn Exec OH, f N5615D	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL Zinke-Smith Inc, Pompano Beach FL	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service K. C. Benbow Co	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67 2.8.67/69
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service K. C. Benbow Co Piedmont Aviation, Winston Salem NC	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67 2.8.67/69 13.1.69
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service K. C. Benbow Co Piedmont Aviation, Winston Salem NC Chattahoochee Air Service	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67 2.8.67/69 13.1.69 14.8.69
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service K. C. Benbow Co Piedmont Aviation, Winston Salem NC Chattahoochee Air Service Richard J. Kavanaugh, Tifton GA	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67 2.8.67/69 13.1.69 14.8.69 1.12.69/73
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service K. C. Benbow Co Piedmont Aviation, Winston Salem NC Chattahoochee Air Service Richard J. Kavanaugh, Tifton GA Semo Aviation, Malden MO	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67 2.8.67/69 13.1.69 14.8.69
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service K. C. Benbow Co Piedmont Aviation, Winston Salem NC Chattahoochee Air Service Richard J. Kavanaugh, Tifton GA Semo Aviation, Malden MO (pilot cockpit emegency hatch fitted 6.77)	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67 2.8.67/69 13.1.69 14.8.69 1.12.69/73 30.1.73/79
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service K. C. Benbow Co Piedmont Aviation, Winston Salem NC Chattahoochee Air Service Richard J. Kavanaugh, Tifton GA Semo Aviation, Malden MO (pilot cockpit emegency hatch fitted 6.77) H & R Leasing Co/ Hunt Pan Am Distributors	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67 2.8.67/69 13.1.69 14.8.69 1.12.69/73 30.1.73/79 31.5.79
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service K. C. Benbow Co Piedmont Aviation, Winston Salem NC Chattahoochee Air Service Richard J. Kavanaugh, Tifton GA Semo Aviation, Malden MO (pilot cockpit emegency hatch fitted 6.77) H & R Leasing Co/ Hunt Pan Am Distributors Aircraft Leasing & Pilot Services Inc, Brownsville TX	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67 2.8.67/69 13.1.69 14.8.69 1.12.69/73 30.1.73/79
BA-323	E18S N617M no N617M ac Youngston E18S -9700	N617M oted Washingto ccident report - wn Exec OH, H N5615D N75200 (2 N216ZS	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service K. C. Benbow Co Piedmont Aviation, Winston Salem NC Chattahoochee Air Service Richard J. Kavanaugh, Tifton GA Semo Aviation, Malden MO (pilot cockpit emegency hatch fitted 6.77) H & R Leasing Co/ Hunt Pan Am Distributors Aircraft Leasing & Pilot Services Inc, Brownsville TX (last FAA communication from owner in 1983)	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67 2.8.67/69 13.1.69 14.8.69 1.12.69/73 30.1.73/79 31.5.79 11.79/91
	E18S N617M nd N617M ad Youngstor E18S	N617M oted Washingto ccident report - wn Exec OH, h N5615D N75200 (2	McLean Trucking Co, Winston Salem NC Prompt Air Delivery Inc, Vero Beach FL, later Washington-National DC Robert L. Green/ Green Aero, Clarkston MI crashed destroyed landing, Youngstown-Execuive OH on-DCA 2.10.68, plate BA-322; 10.4.79: Green Aero Inc: cargo flight Flint MI to North Jack hard landing, attempted go-around, crashed, 2.42pm, pilot Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp: CofA issued Atlantic Aviation Corp (mos to E18S-9700 installed 1.60) Miniature Precision Bearing Inc Treesdale Laboratories Inc Zinke-Smith Inc, Pompano Beach FL engine torn out on takeoff due prop failure, landed safely Ft Lauderdale FL: still painted as N75200 Sunny South Aircraft Service K. C. Benbow Co Piedmont Aviation, Winston Salem NC Chattahoochee Air Service Richard J. Kavanaugh, Tifton GA Semo Aviation, Malden MO (pilot cockpit emegency hatch fitted 6.77) H & R Leasing Co/ Hunt Pan Am Distributors Aircraft Leasing & Pilot Services Inc, Brownsville TX	69/72 21.10.74/79 10.4.79 (son- unhurt; 10.10.57/58 1.58/59 6.6.60/61 15.9.61/63 9.1.63 10.63/67 16.9.64 23.3.67 2.8.67/69 13.1.69 14.8.69 1.12.69/73 30.1.73/79 31.5.79

		Sacramento CA	11.57/72
		(fish dropping hopper installed in belly 4.58,	
		extensive dropping of fingerlings in lakes)	
	N10FG	California Department of Fish & Game, Sacramento CA	19.5.72/74
Hamilton		(rebuilt Tucson AZ 5.72 by Hamilton Aircraft Co as	
Westwind I		Hamilton Westwind I: PT6A-27 turbines, Hamilton cargo	,
trigear		picture windows, Volpar Mk.IV trigear, G18S type windsh	ield)
	N21FG	California Department of Fish & Game, Sacramento CA	6.3.74/84
	N51FG	California Department of Fish & Game, Sacramento CA	7.3.84
		Smithair Inc, Sharpsburg GA	8.8.84/90
		Ajax Aircraft Leasing Inc, Dover DE	4.1.90/91
		op: Active Aero Charter, Willow Run MI	23.5.90/93
	(N983AA)	ntu: Ajax Aircraft Leasing Inc, Belleville MI	3.3.93
	N51FG	crashed dest. on takeoff, Detroit-Willow Run MI	8.6.93

N5614D noted Tucson AZ 3.4.72 at Hailton Aircraft ramp, Westwind trigear; N21FG noted Arcata CA 7.81 trigear turbines; further datails on fish dranning; see Reach 18 by Robert Permetter p 201;

further details on fish dropping: see Beech 18 by Robert Parmerter p.291;

BA-325	E18S	N5617D	Roscoe Turner Aeronautical Corp: CofA issued	21.10.57/58
			William H. Ball	27.1.58/60
			Bell Intercontinental Corp, Mishawaka IN	29.7.60/63
			Howard Aero Service/ Alamo Aviation/	
			Business Aircraft Corp, San Antonio TX	31.7.63
		N765FT	Professional Pilot Service Inc	7.9.63/64
		N965FT	Professional Pilot Service Inc	24.4.64
			Florida Tile Industries Inc	20.7.64/65
			Conequip Corp, Evansville IN	29.6.65/71
	-9900		(mods for E18S-9900 installed 12.66)	
			damaged landing with gear locked-up, Evansville IN	28.5.67
		N677RR	Leon F. Roberts	2.2.71/72
		N962H	Catlin Aviation Co	10.8.72/73
			Gary R. Levitz/ Western Aircraft Leasing Co	20.4.73/74
		N26BB	Robert J. Binkley, Shawnee OK	18.4.74/79
			Southland Flyers Inc	15.5.79/82
			(cargo door & floor, cockpit hatch installed 7.79)	
			Robert A. Younkin, Springdale AR	29.1.82/85
		N18RY	Robert A. Younkin, Lowell AR	12.85/91
			(fitted c90 with nose-cockpit section from G18S	
			N5724M/BA-593)	
			Doak Boreing, Magnolia AR	9.3.91/93
			Robert A. Younkin/ Younkin Air Service, Lowell AR	17.2.93/99
			Musick Aircraft Co, Brownfield TX Beech House	21.8.99/02
			Leprechaun Air Service, Syracuse KS	26.2.04/20
			· · · · · · · · · · ·	

N962H noted Addison TX 29.4.73;

N18RY at Oshkosh 8.99, "Beach House" & "Younkin Air Services, Springdale AR" titles, plate BA-325 built 10.57, another plate: conv. to E18S-9900 12.66; N18RY at Oshkosh 23.7.02 "Beech House";

Parmerter says USCR 7.71 & 1.73 list BA-325 as N977R but the FAA Index Card quotes only N677R as do most other sources. In his Index corrections list (AB-IX 25/6/06) he corrects BA-325 N977RA to N977RR;

BA-326	E18S	N33JD (3	J. D. Reed Co, Houston TX	.57
		XB-DAC	reg	
	Volpar	N88002	reg	
	Centennial	N76MC	Volpar Inc, Van Nuys CA: USCR	7.75/76
			(prototype Volpar Centennial, conversion begun 8.75,	
			longer fuselage than Turboliner & PT6A turboprops:	
			project sold by Volpar 5.76 to Aerocom Inc)	
	Aerocom		Aerocom Inc, Reno-Stead NV	5.76/77
	Skyliner		(conversion continued at Reno .76/77 as prototype	
			Aerocom Skyliner, extra fuselage stretch for	
			19 pax, single fin, new wing & undercarriage:	
			construction not completed)	

Volpar Inc, Van Nuys CA: USCR	79/82
stripped fuselage dumped at Volpar, Van Nuys CA, by	1.79

Aerocom, Reno NV was formed 5.76 as subsidiary of S&G Construction/ Northslope Enterprises, Anchorage AK to acquire design and production rights to the proposed Volpar Centennial development of the Turboliner. Took over Lear Avia plant at Reno-Stead to commence production. Included in the purchase was the uncompleted "Centennial" prototype, which was trucked to Reno to be used as the "Skyliner" prototype: stretched fuselage, all metallic outside a hangar near Volpar's at Van Nuys 1.79; see Beech 18 by Robert Parmerter pp.319, 393;

BA-327	E18S	N5618D (1	reg	.57
			Coleman Co, Wichita KS	63/64
		N334V	Mississippi Federal Cooperative, Jackson MS	66
			Orion Airways, St Louis MO	69/70
			Sisk Aviation Activities, St Louis MO	70/72
			Northwood Institute, Midland MI	79
			Combs Airways: USCR	91
			J. W. Duff/ Duffy's Aircraft Parts, Denver CO (stored in Duff's salvage yard, Denver 00)	00/15
			Reg expired 31.10.15, struck-off USCR	13.2.18

N334V noted Duffy's yard, Denver CO 7.8.00 standing on wheels, wings removed;

BA-328	E18S	N5619D	Atlantic Aviation Corp	11.57/58
D/( 020	trigear	NOOTOD	Doubleday & Co, Garden City NY	2.2.58/72
	ingea	N5618D (2		27.6.72/73
		1450100 (2	Flite Time Inc	10.72/73
			Norwood Institute Corp, Midland MI	4.8.73/81
			•	
			John A. Daniels	26.1.81/82
			K & B Aircraft Broker Corp, Miami FL	16.3.82/83
		N729KB	Robert Bennett/ K & B Aircraft Broker Corp, Miami FL	18.9.83/86
			Arrowhead Airways, Blaine MN	12.7.86
		N621AA	Ernie Joyner/ Arrowhead Airways, Blaine MN	10.86/91
			Milton E. Glass, Anoka MN	17.5.91
			Farm Air Flying Service, Sacramento CA	7.12.91/93
		N328N	Wilbert R. Porter, Sacramento CA	20.1.93
			Norman E. Hibbard, Carson City NV	21.4.95/97
			sold to Switzerland: struck-off USCR	12.97
	tailwheel	HB-GJG	Adventure Flight AG, Zurich	22.12.97/01
	taininoon	112 000	(based Buochs, Switzerland 01/03, flying in	22.12.07701
			US Navy red/white scheme "328", name Rosmarie)	
		D-IROM	Helmuth Beyerlein, Straubing	03/17
		D-IKOW	Teiniuti beyenein, Straubing	03/17
			dia NY 31.3.72 trigear;	
		-	tans-Buochs 25.4.01 & 2.7.01 red nose;	
	HB-GJG li	sted with aircr	aft of members of Antique Airplane Association of Switze	rland 01;

HB-GJG noted Buochs, Switzerland 26.10.01, 1.7.02: both USN scheme, tailwheel, i/s; HB-GJG noted Buochs 20.12.01 US Navy red & white scheme, tailwheel; D-IROM noted Buochs 22.3.03 US Navy red/white scheme, no titles; D-IROM noted Oberschleissheim, Germany 9.7.05 flying, tailwheel, USN red/white;

D-IROM noted Oberschleissheim 22.7.06, tailwheel, USN red/white scheme;

BA-329	E18S	N398B	Lang Aircraft: CofA issued	7.11.57/58
	-9700		Robert L. Graf	26.2.58/59
			Bankers Life Insurance of Nebraska	16.2.59/60
			Delhi-Taylor Oil Corp	7.6.60/63
			Florida Gas Transmission Co, Miami FL	19.4.63/68
			collided with automobile while taxying for departure,	
			Fort Lauderdale FL	27.1.65
			Ross Aviation, Tulsa-Riverside OK	12.68/69
			Great Western Airlines, Tulsa-Riverside OK	70/76
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	10.76/77
			American Lease Plan Inc, Charlotte NC	15.3.77/81
			Ralph Quinlan/ Mountain Air Cargo, Denver NC: Isd	16.3.77/86
			(Aerospace Products cargo door & cockpit door installed 5.77)	

	op: General Aviation Inc, Greenville TN	80
	Equipment Leasing Corp, Greenville SC	11.2.81/84
	Coastal States Aviation, Denver NC	1.2.85/86
	Union Flights, Sacramento CA	9.6.86/92
	Del Caribbean Corp, San Juan, Puerto Rico	21.7.92/97
	Tol Air Services, San Juan, Puerto Rico	27.6.97/99
	MBD Corp, San Juan, Puerto Rico	8.2.99/00
N748T	MBD Corp, San Juan, Puerto Rico	14.3.01/13
	op: Tol Air Services, San Juan, Puerto Rico	99/10
	reg expired 30.9.13, struck-off USCR	26.1.18

N398B noted SFO 6.59 "Bankers Life Insurance of Nebraska" titles; N398B noted LAX 6.11.87;

N398B noted St Croix USVI 1.98 "Tolair";

N748T noted San Juan PR 27.3.05 all metallic, windows faired over, no titles, tailwheel, in service; N748T photo in service Tol Air at Puerto Rico 5.10, all metallic, windows faired over;

BA-330	E18S	N78A	Beech Aircraft Corp, Wichita KS: CofA issued	18.11.57/58
			Flightcraft Inc	7.8.58
		N2424 (2	Cheney Forest Products, Central Point OR	10.58/74
	trigear		(Volpar Mk.IV trigear installed 3.64)	
			Frederick W. & Mary Jo Lawless	25.4.74
			Hollywood Flying Service	15.8.74/77
			Smithville Flying Service	17.1.77
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	22.8.77/78
			International Transfer Corp	22.9.78/80
			op: Pro Air Services, Opa Locka FL	79
			Harold E.Valley, Glenwood Springs CO: USCR	79
			Billy W. Mahaffey	1.8.80
			seized at Belize Airport with 1500lb marijuana:	
			Mahaffey & J. R. Sirmons arrested	30.8.80
			Government of Belize: impounded	1.9.80/81
			Raymond Weir, Belize	19.1.81
		N24JE	James Eakes & Robert L. Ross	22.1.81/83
			T. E. De Mint/ Astro Airways Corp, Pine Bluff AR	18.3.83/89
			(cabin cargo floor installed 1.86)	
			minor damage in midair collision with Beech 18 N492DM	
			both landed safely, Natchez MS	, 9.12.87
		N446DM	T. E. De Mint/ Astro Airways Corp, Pine Bluff AR	28.4.89/91
		NT TODM	Thomas M. Rawlins, Newcastle CA	11.1.91/95
			Alma D. Mallard, Idaho Falls ID	17.8.98/13
			struck-off USCR	7.6.13
				1.0.10

N2424 noted Miami FL 3.10.78 trigear;

accident report 9.12.87: midair collision while cruising on positioning flight, both aircraft had same owner Aerovation Inc; N446DM noted Flores, Guatemala 11.11.94 at airfield near Tikal Ate ruins; Stripped E18S trigear hulk derelict at Flores, Guatemala 1.18, assumed this aircraft;

BA-331	E18S	N200UP	Upjohn Co	.58/61
		N208UP	Upjohn Co	22.5.61
		N208UB	Upjohn Co	16.6.61
			Francis Aviation, Lansing MI	63
			Louis F. Dow Co, St Paul MN	64/65
			prop failed, left engine separated from airframe,	
			crashed into water, destroyed by fire, Henderson KY	3.1.65

N208UB crash report: left propeller blade failure in flight over Henderson KY and left engine separated from airframe, came to rest in water, post-impact fire, 4k;

BA-332	E18S	N5621D	built	.58
		N724A	Anaconda Aluminum Co, Louisville KY	63/64
		N724AA	Poulan Beaird Inc, Shreveport LA	66/72
			Emerson Electric, Shreveport LA	78
			John R. Webster, Shreveport LA	12.1.79/82
			sold to Cayman Islands, struck-off USCR	23.7.82

BA-333	E18S	N19M	built	.58
571000	-9700		(mods to E18S-9700 completed 14.5.59)	
	0.00		Mellon National Bank, Pittsburgh PA	63/64
		N190X	Mellon National Bank, Pittsburgh PA	66
		11100/1	Equitable Leasing Corp, Rochester NY	69/70
			op: Del Airways	70
		CF-ANA	Port Colburne Flying Service t/a Air Niagara,	10
			St Catharines ONT	2.70/73
			tail blown into fence by windstorm while parked,	
			St Catharines ONT	14.8.72
			Collingwood Air Services	.73
			Laurentian Air Services Ltd, Ottawa ONT	76/78
			Skycraft Air Transport, Oshawa ONT	78/83
		C-FANA	Skycraft Air Transport, Oshawa ONT	84/93
			sold to USA, struck-off Canadian Register	9.93
		N5847	One Way Ride Inc, Portersville PA	9.93
		N5867	One Way Ride Inc, Portersville PA	16.9.93/99
			Jay D. Swarthout, Windsor CA	24.4.00/02
			(flew as "USAF WZ-333 Tuff" &	
			"US Marines WZ333 Air FMF PAC")	
			Jimmy Rollison, Nut Tree Airport, Vacaville CA	03/05
			Michele E. Yarbrough, Vacaville CA	17.8.05/20
	CF-ANA CF-ANA C-FANA N5867 nc N5867 at PAC", pla N5867 at	noted Toronto noted Youngs noted Oshawa oted Vacaville- t fly-in Oshkos ate BA-333 bu	al-Dorval 27.2.71 Air Niagara; -Malton ONT 26.3.71 Air Niagara title, tailwheel; town OH 17.6.81 Skycraft; a ONT 8.84 "Skycraft" titles, tailwheel; -Nut Tree CA 7.6.02 "WZ-333" plate BA-333; h 30.7.03 owned Jim Rollison, Vacaville CA, "US Marines ilt 12.57, another plate -9700 conversion 14.5.59,; CA 4.6.04 "333"; fly-in 7.15;	WZ333 Air FMF
BA-334	E18S	N5622D	built	.58
DA-00 <del>4</del>	L100	N140J	Continental Oil Co, Houston TX	63/66
		N I TOO	Hankins Airways, Jackson MS	69/72
			PBF Enterprises Inc, North Canton OH	75
			op: Burlington Airways, Burlington WI	75
			crashed destroyed, Argos IN, forced landing in woods	10
			due cargo fire in flight	1.4.75

N140J accident report 1.4.75: Burlington Airways, flight Indianapolis IN to
South Bend IN, fire in cabin & cockpit, struck trees, destroyed by fire 1.30am, pilot k;

BA-335	E18S	N5624D	Anderson Air Activities: CofA issued	13.12.57/58
	-9700		Twin Disc Clutch Co, Racine WI	25.8.58/64
			Marshall & Isley Bank, Milwaukee WI	10.64/68
	trigear		(Volpar Mk.IV trigear & Beech kit for Skywide G18S	
			panoramic window replacing two middle cabin windows	
			on both sides installed 10.64)	
			Air Journeys Inc, Little Rock AR	10.68/69
		N111EH	Air Journeys Inc, Little Rock AR	3.10.69/71
			James R. Laird & Associates Inc, Appleton WI	15.3.71/72
			Corporate Air Inc	29.6.72/74
			minor damage landed with nose gear down,	
			main gear locked-up, Windsor Locks-Bradley CT	19.12.73
			Frederick W. & Mary Jo Lawless	1.8.74/75
			Sam Vires/ Mid-South Aircraft Sales, Memphis TN	7.3.75
			Colonial Airlines	29.7.75/76
			Troy J. Sandifer	10.76/77
			North American Publishing Co, Houston TX	1.2.77/87
			Diamond Bar C	11.87/90
			Tom Neal, Pasadena CA	23.1.90/91
		N111TN	Tom Neal, Long Beach CA	8.8.91/93

	Patrick J. Foley, Middletown DE	22.5.93/94
N57PF	Patrick J. Foley, Middletown DE Class of '57	2.94/02
	Charles W. Schooley, West Palm Beach FL	23.1.04/06
	H. Anthony Miller Jnr LLC, Warsaw IN	30.10.07
N90TT	H. Anthony Miller Jnr LLC, Warsaw IN	8.1.08
	Monroe Motors Inc, Colorado Springs CO	11.12.09/12
	Beech Eighteen Aviation, Birmingham AL	25.4.12/14
	Michael Blackstone/ Skythrills LLC, Fullerton CA	10.9.14/20
	(flew as "Blackstone Airlines", executive cabin)	

accident report 19.12.73: Corporate Air, flight Windsor Locks to New York, returned to Bradley due gear problem, minor dam., 6 unhurt; N111TN noted Chino CA 7.91 trigear; N57PF at Oshkosh WI 7.97 trigear, allover red scheme, plate BA-335 built 12.57;

N57PF at Oshkosh W17.97 Ingeal, anover red scheme, plate DA-335 built 12.57, N57PF owned Pat Foley up for sale 1.00 at Dutchess County Airport NY; N57PF noted Danbury CT 2.9.00 allover red scheme, retired but looks flyable; N90TT at Oshkosh 7.08, Tony Miller, Warsaw IN, plate BA-335 built 12.57;

BA-336	E18S	N5625D	built	.58
			left gear collapsed landing, Sandston VA	4.62
			(repaired at Sandston-Byrd Field VA)	
			Silas King, Portland OR	63/64
			Nevadair Co, Boulder City NV	66
			Lease Air Inc, San Diego-Montomery Field CA	69/72
			Virginia Financial Corp, Lathrp Wells NV	6.7.76/77
			struck-off USCR	8.7.77

N5625D noted Oakland CA 11.9.71;

BA-337	E18S	N5626D	Alamo Aviation, San Antonio TX	16.1.58
	-9700		H. E. Butt Grocery Co, Corpus Christi TX	5.5.58/71
			(two piece G18S type windshield fitted 6.67)	
			A. G. Wise Trucking, Grapevine TX	13.2.71/72
			Precision Flight Navigation Co	7.2.72/76
			Adcock Farms, Mer Rouge LA	11.76/78
			James R. Latta/ Latco Inc	28.8.78/82
			Robert A. Younkin, Springdale AR	10.82/83
			Todd Orlando Ham, Opdyke IL	25.2.83/86
			Dennis Chadala, Mississauga ONT	.86
			sold to Canada: struck-off USCR	11.86
		C-GEVR	Air 500 Ltd, Toronto ONT	1.87/92
			sold to USA: struck-off Canadian Register	11.92
		N916TM	May Air Xpress Inc, New Boston TX	11.92/95
			(US CofA issued 2.2.93: fitted with cargo door)	
			Scott R. Michels, New Boston TX	5.12.95/01
			op: May Air Xpress, New Boston TX	95/97
			struck ground during aborted takeoff, Lake Elmo MN	2.10.97
			John W. Westling, Princeton MN	11.7.02/05
			struck-off USCR	6.10.05
				0.10.00

C-GEVR noted Toronto ONT 4.8.89 "Air 500" tailwheel;

BA-338	E18S	N5627D	Currey Sanders Aircraft Co	16.1.58
	-9700		Canam Co	4.2.58/61
			Northern Natural Gas Co, Omaha NE	11.1.61
		N503N (2	Northern Natural Gas Co, Omaha NE	27.2.61/64
	trigear		(Volpar trigear installed 8.62)	
	-		Aeronaut Air Service, Birmingham AL	4.4.64/67
			David A. McCoy/ Aircraft Leasing Co	25.5.67/68
			John R. Tarry & Theodore C. Walker/ T-W Enterprises,	
			Elyria OH	2.3.68/69
			Sundorph Aeronautical Corp, Cleveland OH	10.1.69/70
			(Beech cargo door installed 4.70)	
			Fred W. Johnson Funeral Home, St Paul MN	12.70/73
			Midwest Air Service, Fenton MO	2.7.73/92
			(copilot exit door installed 1.78)	

			George R. Kabeller, Zephyrhills FL Hanair International Inc, Miami FL Carib Air Cargo, Lantana FL overturned by windstorm, Miami FL Hartford Holding Corp, Wilmington DE struck-off USCR: scrapped	26.7.92/94 31.3.94/95 26.5.95 2.2.98 10.2.98 14.4.98
			t'I TX 21.3.63, trigear; a 95: trigear, all metallic "Hanair" titles;	
BA-339	E18S	N5628D	Lopez-Grace Aviation: CofA issued R. D. Keene, Winter Garden FL Wesley Y. Bragg & Kenneth W. Andrews, Edgewater NJ Sam Vires/ Mid-South Aircraft Sales, Memphis TN	8.1.58 9.1.58/68 24.4.68/77 28.1.77
		N71SV	Sam Vires/ Mid-South Aircraft Sales, Memphis TN Sting Stables, Santa Rosa CA Fred Ayres: sale documentation not completed sale reported, Oakland CA: USCR	1.9.77 8.10.77/83 21.11.83 20.5.85/91
	N5628D	noted Sky King	IN 30.5.76;	
BA-340	E18S	N72V	built Tulsair Distributors Inc, Tulsa OK Executive Air Transport, Muskegon MI Aero American Aviation, Chicago-Du Page IL groundlooped landing, struck ditches, Atlanta GA (stolen aircraft, 2000lb over gross weight)	.58 63/64 66/72 22.2.77 23.9.77
	N72V not	ted Chicago-Me	igs Field 23.9.70;	
BA-341	E18S		reg -2 Min. de Hacienda de Venezuala rereg Aeractividades Venezolanas SA - AVSA	3.58 9.66 12.67 .72
BA-342	E18S	N5633D	Ohio Aviation Co, Dayton OH sold to West Germany, struck-off USCR	.58 13.8.58
		D-IEHL D-IEHU	Diehl Metalwerke, Nurnberg Travelair GmbH & Co, Bremen sold to France	.58/60 4.61 7.62
		F-BHOG	Ste France Entretien et Reparation Materiel Aeronautique S.F.E.R.M.A., Bordeaux Ste de'Achats Reparations et Ventes Automoibiles Aerospatiale Societe Nationale Indiustrielle, Paris op: Sud Aviation, Toulouse Air Continent, Cannes Aviasud, Nice Nantes Aviation, Chateau-Bougon accident	
	D-IEHU & D-IEHU v F-BHOG F-BHOG F-BHOG F-BHOG F-BHOG F-BHOG F-BHOG F-BHOG F-BHOG F-BHOG	visited Gatwick noted Le Bourg noted Dublin 1. noted Hurn 4.5 noted Gatwick noted Filton 16 noted Gatwick noted Le Bourg noted Filton 3.7 noted London-I noted Filton 3.7 noted Le Bourg	I 16.12.61 from Birmingham, Travelair GmbH; 1.2.62; get 9.6.63; 8.63 from/to Le Bourget SFERMA; .66 from Filton to Le Bourget; 20.8.66, 28.8.66; .8.66; 5.9.66; get 1.6.67 Sud Avtn; 7.67; Heathrow 21.5.68; 7.68 Sud Avtn;	

	F-BHOG noted Paris-Le Bourget 2.1.73 Air Continent; F-BHOG noted Toussus-le-Noble 11.73 "Air Continent" titles, tailwheel, in service; F-BHOG noted Toussus-le-Noble 15.6.74 "Aviasud" titles, tailwheel, in service; F-BHOG noted Nice 30.6.74;						
BA-343	E18S	4R-AAR	Ceylon Dept. of Survey, Colombo (fitted for photographic survey prior to delivery, delivered ex Wichita KS by Flightways Inc)	1.58			
			crashed on delivery flight, near Naples, Italy	4.4.58			
			ch 18 by Robert Parmerter p.281; f Naples, on delivery flight: see BA-376, BA-433;				
BA-344	E18S	N23Z	Page Airways Inc, Rochester NY	.58			
		CF-PQA	Timmins Aviation Ltd, Montreal QUE	25.4.58			
			Department of Colonizatrion, Quebec City QUE Department of Transport & Communications,	28.4.58			
			Quebec City QUE	24.2.60/70			
			dam. ran off runway on takeoff Quebec Airport QUE	22.3.60			
			Helisolair Ltd, Montreal QUE	16.12.70			
			Aviation Sales International, Montreal QUE	25.3.71			
			Desjardins Sauriol & Associates, Laval QUE	5.4.72			
		N100AE	Eli Graubart/ Air Exchange Inc, Wheeling IL (ferry permit 10.73 Montreal to Chicago)	1.10.73			
		CF-PQA	Floyd Carson, Burlingon ONT (Canadian recertification 11.73 at Brantford ONT)	16.11.73			
			J. C. Turcan, Calgary ALTA	6.12.73			
			Eli Graubart/ Air Exchange Inc, Wheeling IL	12.11.74			
			Dixie Flight Centre Inc, Memphis TN	22.11.74			
		N62411	Thomas L. Stinson, Lake City FL	3.75			
			crashed near Cartagena, Colombia (crew injured but not found)	31.3.75			

CF-PQA noted Montreal-Dorval QUE 3.9.71; C-FPQA noted Mt Hope ONT 5.74, tailwheel, no titles;

BA-345	E18S	N5637D	built	.58			
	trigear		Wyatt C. Hedrick, Fort Worth TX	63/64			
			Wallace-Tiernan Inc, Bellevue NJ	66			
			Volpar trigear collapsed while taxying after landing,				
			Hatteras-Mitchell NC	15.6.66			
			Television Communications Corp, New York NY	69			
		N610TV	Television Communications Corp, New York NY	70/72			
		N76AL	rereg				
		N76LA	Colorado Seafood Supply, Denver CO	78			
			Cargo Air Inc, Houston TX	79			
			midair collision with Baron N12WF near				
			Fort Lauderdale FL: both landed safely	3.1.79			
			crashed landing near Homestead FL, marijuana on bo	ard,			
			struck earthbank and parked Cessna 182 N7187E	23.6.79			
			(aircraft reported stolen, 2 arrested)				
			Hanger Two Inc, Miami FL	7.5.81/84			
			struck-off USCR	29.10.84			
			(wreck stored at fire service, Texarkana TX 03)				
	N610TV noted Teterboro NJ 20.7.71;						
	N76LA no	oted Greater V	Vilmington DE 2.9.74 trigear;				
	N76LA noted Miami FL 28.10.78 no titles;						
	N76LA noted Miami FL 12.78 Cargo Air;						
	N76LA accident report 23.6.79: stolen aircraft crashed on landing Goldstein strip near						
		ad FL, pilot &	1 pax unhurt, arrested for possession of marijuana;				
	Homestea		1 pax unhurt, arrested for possession of marijuana; (a FL 18.7.81;				
	Homestea N76LA no	oted Opa Lock					
BA-346	Homestea N76LA no	oted Opa Lock	ka FL 18.7.81;	10.2.58			

Lamar T. Zimmerman, Pottstown PA	11.63/65
landed gear-up, Reading PA	29.8.64
Corporate Air Transport, Chicago IL	23.6.65/70
accident, Negaune MI	6.2.66
Northern Iowa Express, Des Moines IA	19.5.70
SMB Stage Line, Des Moines IA	10.70/71
Thomas Brickley, Festus MO	8.4.71/72
Festus Flying Service, Festus MO	12.72/75
(Aerospace Products cargo door installed 1.73) damaged struck poles landing, Urbana-Mad River OH Charles E. Bush/ Bush Aviation, Ft Lauderdale FL Avair Inc, Orlando FL Thomas W. May, New Boston TX (cargo floor & crew door installed 1.79)	30.8.73 2.2.75/76 24.9.76/78 12.78/80
Cathryn E. Tedder/ CMT Leasing, Texarkana TX	15.5.80
op: ABC Airlines Inc, Dallas-DFW TX	81
James L. Hudson, Mesquite TX	24.4.81/91
ABC Airlines Inc, Dallas-DFW TX: leased	12.81/86
Texas State Technology Institute: inst. airframe	-

N5632D noted Ft Lauderdale FL 15.9.76;

BA-347	E18S U45	PP-FMN	ferry reg FA Brasileira as U45 FAB 2883	.58
BA-348	E18S	N5634D	built Chotin Transportation Inc, New Orleans LA	.58 63
		N14V (2 N14VH	Permian Mud Service Inc, Odessa TX Hamilton Aviation, Hamilton OH crashed after takeoff, Fort Wayne IN	64/72 73/75 24.11.75

N14VH accident report 24.11.75: Hamilton Aviation, takeoff for mail flight to Indianapolis IN, mushed in on takeoff, ice on airframe, 9.53pm, pilot unhurt;

BA-349	E18S -9700	N5635D (D-IDIM) N5635D N872L	Currey Sanders Aircraft Co: CofA issued ntu Dayton Steel Foundry Co Rish Equipment Co, Bluefield WV (various mods installed 3.66: picture window, additional cabin window, G18S type windshield) gear collapsed during landing, Columbus OH Jasper Aviation Southeastern Beechcraft Inc, Knoxville TN UC Leasing Inc, Memphis TN UC Leasing Inc, Memphis TN Regalair Inc	26.2.58/59 .59 19.1.59/62 28.2.62/70 26.4.67 21.3.70 30.7.70 11.70/72 12.72/74 4.3.74/75
			Safe Wings Inc/ Lake Norman Aviation AM Air Corp, Southern Pines NC sale rep., Huntington NY destroyed in accident in Mexico	25.2.75/76 23.2.76/77 77 6.77
BA-350	E18S	N21Z N711L (3 N177X (1 N1770 N877GP	built Lockport Felt Company, Newfane NY rereg Harper Sibley, Rochester NY rereg Georgia Pacific Corp, Portland OR struck-off USCR	.58 63 63/64 65/66 67/68 2.7.68/71 23.2.71

N877GP noted Portland OR 5.9.75;

	E400	NECOOD	L	58
BA-351	E18S	N5638D	built	.58
		N330D	Precision Scientific Co, Chicago IL	63/64
			Executive Airlines, Chicago IL	66
		N330DW	Horizons Aviation Enterprises, Chicago IL	69/70
			Galt Flying Service, Ringwood IL	25.5.71/74

crashed destroyed in forced landing, Lansing IL 13.7.74

N330DW noted Chicago-O'Hare 23.9.70;

		j		
BA-352	E18S	N87D (1 N4F (3 N4845	Youngstown Airways/ Lease Air, Youngstown OH: CofA Latrobe Construction Co, Latrobe PA Montgomery Aviation Corp, Montgomery AL Semo Aviation Inc, Malden MO	12.3.58 63/69 70/72 78/81
			Trans Air Cargo Inc, Ottumwa IA derelict hulk at Monterrey, Mexico	10.3.81/91 01
	photo: all	l metallic stripp	IA 19.8.81 tailwheel, all metallic; hed hulk, large freight doors, no engines, tailwheel, hal Airport, Mexico c01, photo of plate shows E18S BA-352	).
BA-353	E18S	N5639D	Beech Aircraft Corp, Wichita KS: CofA issued	17.3.58
			Flight Service Inc, Syracuse-Hancock Field NY Niagara Mohawk Power Corp, Syracuse NJ	63/64 66/72
		N705M	minor damage, struck taxiway sign, Newark NJ American Lease Plans, Charlotte NC op: Mountain Air Cargo, Denver NC	20.6.75 6.78/79 79
			op: General Aviation Inc, Greenville TN crashed destroyed on takeoff, Bradley CT	79 19.9.79
	N5639D	noted Syracus	e NY 27.8.74;	
BA-354	E18S	N5648D	built	.58
		N212LM	L. M. Berry & Co, Dayton OH Capitol City Underwriters, Indianapolis IN Granville Leasing Co, Chicago IL	63/64 66 69/70
		CF-STJ	Norman Aircraft Ron Michaluk/St. Andrews Airways, Winnipeg MAN dam. gear-up landing St Teresa Point MAN struck cargo on ramp taxying Island Point MAN	71 10.71/77 5.1.74 25.8.75
			main gear collapaed landing Island Lake MAN (ferry permit Winnipeg to USA 4.77)	25.5.76
		N46952	Burlington Airways, Burlington WI (US CofA issued 4.8.77) struck fence in forced landing off-airport in fog,	23.4.77/80
			Indianapolis IN	7.12.78
			Aero Systems Inc, Kallispell MT struck-off USCR by FAA	30.8.83/12 11.12.12
	N46952 a	accident report	ka FL 13.10.79; t 7.12.78: Burlington Airways, cargo flight Chicago to Indiar n, pilot unhurt;	napolis,
BA-355	E18S -9700	N5640D	Beech Aircraft Corp, Wichita KS: CofA issued Californian Oil Co, Denver CO	24.3.58 63/64
			Chevron Oil Co, Denver CO	66
			Allegheny Leasing Corp, Baltimore MD Saint Aircraft Inc, St Petersburg FL	69 70
			Herbert E. Guynn, St Petersburg FL	71/72
			op: Sun Airline Inc	72
			swung landing, gear collapsed, Tallahassee FL Leo Overturf, Mena AR	27.4.72 79
			sale reported, American Fork UT: USCR J. W. Duff/ Duffy's Aircraft Parts, Denver CO (stored in Duff's salvage yard, Denver 00)	27.12.80/91 00
	N5640D		FL 25.9.70; t 27.4.72: Sun Airline Inc, swerved landing, 6 unhurt; Denver CO 7.8.00 fuse only seen;	
BA-356	E18S	PP-FMO	ferry reg	.58

		PT-KUU	Rico Taxi Aereo Ltda, Manaus Taxi Aereo Rondonia Ltda, Santarem	11.76/83 6.77/79
BA-357	E18S	N5643D	built Harcon Aircraft Inc, Miami FL South State Service Co, Tallahassie FL ANS Corp, Milburn NJ Gilley Airways Corp, Fulton-Oswego County NY	.58 63/64 66/72 79 29.1.79/91
	N5643D I	noted Schene	ctady NY 12.8.74;	
BA-358	E18S	N5645D	built damaged, struck eagle at 8500 feet, Lamont WY Corporate Air Industries Inc, Long Beach CA Indianapolis Morris Plan Corp, Indianapolis IN crashed destroyed in forced landing, near Delta UT	.58 16.3.60 63 1.7.63/64 5.3.64
BA-359	E18S	N23J F-BTCS F-AZEJ	built Kentucky Dept. of Aeronautics, Frankfort KY reg. pending Turb Air Inc, Miami FL (based in France 71/73 as N23J) Fernand Gaspe/ Pyrenair Gaspe, Pau-Idron Amicale Jean-Baptiste Salis, La Ferte-Alais (flew as Luftwaffe "BT+CS", later RAF "436904", later USAAC "22425/V")	.58 63/69 70 71/72 22.11.73/83 26.8.83/15
	F-BTCS I F-AZEJ fi F-AZEJ fi F-AZEJ n F-AZEJ n F-AZEJ n F-AZEJ n F-AZEJ n F-AZEJ n	noted La Ferté loted La Ferte lying at airsho loted La Ferte loted La Ferte loted La Ferte loted La Ferte loted Ca Ferte loted Crleans- loted Lyons-B	bellier 72-74 owned F. Gaspe; Alais 5.6.83; Alais 18.6.91 "436904"; w La Ferte-Alais 6.95, barrel rolls; Alais 6.7.96; irrquet 21.9.02 allover dark colour USAAC "22425"; Aais 18.11.03 "22425"; Alais 15.5.05, flying USAAC "22429/V"; Alais 4.6.06 flying "22425/V"; Bricy 10.6.06, ron 17.6.06 USAAC "V", tailwheel; issus-le-Noble 15.9.07;	
BA-360	E18S -9700	N5644D	Raytheon Manufacturing, Bedford MA North American Aviation Inc, Columbus OH North American Rockwell Corp, El Segundo CA G. J. Douglas, Azle TX Semo Aviation Inc/Semo Airways, Malden MO damaged ran off taxiway, Birmingham AL Air Machines & Services Inc, St James MO Coast Air Freight Inc, Long Beach CA Gold Coast Air Inc, Hawthorne CA sale reported, Salt Lake City UT David C. Smith, Brewster WA Clifton A. Parkhill, Oxnard CA	.58 63/66 69/70 71/72 78/84 26.6.78 5.84 6.85/86 1.87 91/99 18.5.00/06 14.10.09/20
	N5644D i	noted Van Nu	.6.85 Coast Air Freight, no titles; ys CA 7.4.87, 10.87; ys 9.11.87 "Coast Air Freight, Long Beach CA";	
BA-361	E18S	N4369D N458X N48X N458X	built Jervis B. Webb Co, Detroit MI Jervis B. Webb Co, Detroit MI Jervis B. Webb Co, Detroit MI Northern Airlines, St Marys OH Great Western Airlines, Tulsa-Riverside OK struck-off USCR	.58 63/64 66 69/70 74/77 8.7.77

BA-362	E18S	N24J	built Packaging Corp of America, Grand Rapids MI J. W. Woodward, Little Rock AR George Summers, Parowan UT	.58 63/66 69/70 18.6.73/91
BA-363	E18S	N4331D	Beech Aircraft Corp, Wichita KS: CofA issued Fred G. Reed, Chicago IL Addison Products Co, Addison MI	10.6.58 63 64
		N18T (2 N1890	Addison Products Co, Addison MI Department of Defense, Atlanta GA Department of Air Transportation, Atlanta GA sale reported, Washington DC	11.64/66 69 70/72 82/91

N1890 noted Atlanta GA 3.10.68;

"N189" noted at Mesa AZ 1.4.72 rep. as US Dept of Interior – probably this aircraft;

BA-364	E18S	N5647D	Beech Aircraft Corp, Wichita KS: CofA issued	26.6.58
			Leonard Refineries Inc, Alma MI	63/64
			Aircraft Owners Inc, Miami FL	66
			Gee & Jensen Consulting Engineers,	
			West Palm Beach FL	69/72
			Tampa Air Center, Tampa FL	79/84
			Leon B. Canady, Starke FL	6.85
			Span Tech Inc, Glasgow KY	3.88/91
			James L. Nolton, Marco Island FL	2.92
			op: Marco Aviation, Marco Island FL	94
			Cape Central Airways, Cape Girardeau MO	10.94
			crashed landing, Kansas City MO	8.12.94
			Dodson Aviation, Rantoul KS: wreck for parts	98/02

N5647D noted Dodson Aviation parts yard, Rantoul KS 7.97, crashed condition, plate BA-364 built 6.58;

N5647D noted Dodson Aviation parts yard, Rantoul KS 23.7.98 faded titles "Marco Aviation"; noted unmoved in yard 24.7.99 & 11.8.00 & 6.8.02;

BA-365	E18S	N46G	built	.58		
			Mid Continent Leasing Co, Amarillo TX	63		
		CF-FLC	reg	.63		
			Hudson Bay Air Transport Ltd, Flin Flon MAN	65/82		
	Hudson Bay		(fitted with survey noise coil, tail mounted movable boom			
	Ore Hunter		& trailing magnetometer bomb by Field Aviation, Toronto:			
			referred to as Hudson Bay Ore Hunter 67/76)			
		C-FFLC	Skycraft Air Transport, Oshawa ONT	.82/85		
			lsd: Soundair	82		
			crashed into Lake Erie, near Cleveland OH	5.6.85		
	CF-FLC not	ted Toronto	7.67 with magentometer survey gear;			
	CF-FLC not	ted Toronto	3.76 with magentometer survey gear: gear removed by 78;			
			ONT 26.8.80 Hudson Bay Air Transport;			
	CF-FLC noted Toronto ONT 25.8.81 Hudson Bay Air Transport;					
	CF-FLC not	tea i oronto	ONT 25.8.81 HUOSON BAY AIR TRANSPORT;			
			own OH 8.6.82 Soundair Isd ex Skycraft;			
	C-FFLC not					
BA-366				4.8.58		
3A-366	C-FFLC not	ted Youngst	own OH 8.6.82 Soundair Isd ex Skycraft;	4.8.58 63/64		
3A-366	C-FFLC not	ted Youngst	own OH 8.6.82 Soundair Isd ex Skycraft; Beech Aircraft Corp, Wichita KS: CofA issued			
3A-366	C-FFLC not	ted Youngst N28J	own OH 8.6.82 Soundair Isd ex Skycraft; Beech Aircraft Corp, Wichita KS: CofA issued A F L C Inc, Birmingham AL	63/64		
3A-366	C-FFLC not E18S ATE	ted Youngst N28J	own OH 8.6.82 Soundair Isd ex Skycraft; Beech Aircraft Corp, Wichita KS: CofA issued A F L C Inc, Birmingham AL A F L C Inc/ Vulcan Materials Co, Birmingham AL	63/64		
3A-366	C-FFLC not E18S ATE Westwind I	ted Youngst N28J	own OH 8.6.82 Soundair Isd ex Skycraft; Beech Aircraft Corp, Wichita KS: CofA issued A F L C Inc, Birmingham AL A F L C Inc/ Vulcan Materials Co, Birmingham AL (converted .66 to trigear <i>Westwind I</i> by ATE at	63/64		
3A-366	C-FFLC not E18S ATE Westwind I	ted Youngst N28J N271VM	own OH 8.6.82 Soundair Isd ex Skycraft; Beech Aircraft Corp, Wichita KS: CofA issued A F L C Inc, Birmingham AL A F L C Inc/ Vulcan Materials Co, Birmingham AL (converted .66 to trigear <i>Westwind I</i> by ATE at Long Beach CA)	63/64 66/71		
3A-366	C-FFLC not E18S ATE Westwind I trigear	N28J N271VM N49AB	own OH 8.6.82 Soundair Isd ex Skycraft; Beech Aircraft Corp, Wichita KS: CofA issued A F L C Inc, Birmingham AL A F L C Inc/ Vulcan Materials Co, Birmingham AL (converted .66 to trigear <i>Westwind I</i> by ATE at Long Beach CA) A F L C Inc, Alton IL	63/64 66/71		
3A-366	C-FFLC not E18S ATE Westwind I trigear Hamilton	N28J N271VM N49AB	bown OH 8.6.82 Soundair Isd ex Skycraft; Beech Aircraft Corp, Wichita KS: CofA issued A F L C Inc, Birmingham AL A F L C Inc/ Vulcan Materials Co, Birmingham AL (converted .66 to trigear <i>Westwind I</i> by ATE at Long Beach CA) A F L C Inc, Alton IL (rebuilt as <i>Hamilton Westwind III</i> with tail gear by	63/64 66/71		
3A-366	C-FFLC not E18S ATE Westwind I trigear Hamilton Westwind II	N28J N271VM N49AB	Beech Aircraft Corp, Wichita KS: CofA issued A F L C Inc, Birmingham AL A F L C Inc/ Vulcan Materials Co, Birmingham AL (converted .66 to trigear <i>Westwind I</i> by ATE at Long Beach CA) A F L C Inc, Alton IL (rebuilt as <i>Hamilton Westwind III</i> with tail gear by Hamilton Aircraft, at Tucson AZ)	63/64 66/71 72		
3A-366	C-FFLC not E18S ATE Westwind I trigear Hamilton Westwind II	N28J N271VM N49AB	Beech Aircraft Corp, Wichita KS: CofA issued A F L C Inc, Birmingham AL A F L C Inc/ Vulcan Materials Co, Birmingham AL (converted .66 to trigear <i>Westwind I</i> by ATE at Long Beach CA) A F L C Inc, Alton IL (rebuilt as <i>Hamilton Westwind III</i> with tail gear by Hamilton Aircraft, at Tucson AZ) rereg Great Western Airlines, Tulsa-Riverside OK	63/64 66/71 72 2.74		
3A-366	C-FFLC not E18S ATE Westwind I trigear Hamilton Westwind II	N28J N271VM N49AB	Beech Aircraft Corp, Wichita KS: CofA issued A F L C Inc, Birmingham AL A F L C Inc/ Vulcan Materials Co, Birmingham AL (converted .66 to trigear <i>Westwind I</i> by ATE at Long Beach CA) A F L C Inc, Alton IL (rebuilt as <i>Hamilton Westwind III</i> with tail gear by Hamilton Aircraft, at Tucson AZ) rereg Great Western Airlines, Tulsa-Riverside OK gear collapsed landing, Covington KY	63/64 66/71 72 2.74 77/82		
3A-366	C-FFLC not E18S ATE Westwind I trigear Hamilton Westwind II	N28J N271VM N49AB	Beech Aircraft Corp, Wichita KS: CofA issued A F L C Inc, Birmingham AL A F L C Inc/ Vulcan Materials Co, Birmingham AL (converted .66 to trigear <i>Westwind I</i> by ATE at Long Beach CA) A F L C Inc, Alton IL (rebuilt as <i>Hamilton Westwind III</i> with tail gear by Hamilton Aircraft, at Tucson AZ) rereg Great Western Airlines, Tulsa-Riverside OK	63/64 66/71 72 2.74 77/82 20.12.77		

Aero Systems Inc, Erie CO	11.84
Connie Kalitta Services Inc, Willow Run MI	5.87
op: Active Aero Charter, Willow Run MI	89
Ajax Aircraft Leasing Inc, Dover DE	2.90/91
K & K Aircraft Inc, Bridgewater VA	24.3.92/04
(broken-up for parts, Bridgewater VA)	
South West Aero Exchange, Owasso OK	03
scrapped, struck-off USCR	27.9.04

N342T accident report 20.12.77: Great Western, cargo flight from Dayton OH, heavy landing, 10.30pm, 2 crew unhurt;

N342T noted Willow Run MI 3.8.89 "Active Aero Charter, Willow Run MI", rep. as Turboliner; N342T noted Willow Run MI 7.91, stored minus engines & tail; N342T fuselage noted Bridgewater VA 11.8.99 in K&K storage shed on far side of airfield;

BA-367	E18S	N19J	built	.58
			M & R Dietetic Labs Inc, Columbus OH	63/64
			Ross Laboratories, Columbus OH	66
		N1809	Skyways Inc, Dayton Municiple OH	69/73
			Hamilton Aviation, Hamilton OH	5.6.73
			gear collapsed during forced landing due engine failure	
			on takeoff, Dayton-Municiple OH	20.7.73

N1809 accident report: location quoted as Vandalia-Dayton Municiple: ferry permit with gear down and no starter, lost engine after takeoff due water in fuel, pilot unhurt;

E18S	N5641D	built	.58
	N153T	Texas Eastern Transmission Corp, Shreveport LA	62/63
	N153J	Texas Eastern Transmission Corp, Shreveport LA	8.63
		gear collapsed landing Columbia MS	8.4.64
	N515J		66
	N415GP		67/72
ATE		•	
Westwind I		PT6A-27 turbines, trigear, completed .67)	
trigear		North Eastern Airlines	73
-		Hamilton Aircraft Co, Tucson AZ	11.4.73
		sold to Kenya, struck-off USCR	6.9.73
	5Y-ASF	Caspair Ltd, Nairobi-Wilson	11.73/78
Hamilton		(rebuilt as Hamilton Westwind III with tail gear)	
Westwind I tailgear	II	crashed 400 miles west of Khartoum, Sudan	3.5.78
	ATE Westwind I trigear Hamilton Westwind I	N153T N153J N515J N415GP ATE Westwind I trigear 5Y-ASF Hamilton Westwind III	N153TTexas Eastern Transmission Corp, Shreveport LA N153JN153JTexas Eastern Transmission Corp, Shreveport LA gear collapsed landing Columbia MSN515JGeorgia Pacific Corp, Crossett AR N415GPATE(rebuilt as American Turbine Engine Co ATE Westwind I PT6A-27 turbines, trigear, completed .67)Westwind IPT6A-27 turbines, trigear, completed .67)trigearNorth Eastern Airlines Hamilton Aircraft Co, Tucson AZ sold to Kenya, struck-off USCR Caspair Ltd, Nairobi-WilsonHamilton(rebuilt as Hamilton Westwind III with tail gear) crashed 400 miles west of Khartoum, Sudan

N415GP noted Tucson AZ 24.5.73 at Hamilton Aircraft ramp, Westwind trigear; N415GP noted Nairobi-Wilson 5.9.73 Westwind III "North Eastern AL"; 5Y-ASF noted Nairobi-Wilson 12.76 owned Caspair, in Caspair hangar on maintenance;

BA-369	E18S	N21J	built	.58
			Roger W. Stribling, Jackson MS	63
			Alamo Aircraft Inc, Evansville IN	64
			B & P Motor Express Inc, Pittsburgh PA	66/69
			Jack D. Wall, Memphis TN	70
		N21DD	Robert H. Ford, Muscle Shoals AL	.72
			crashed destroyed on takeoff, Sumter SC	17.9.72

N21DD accident report 17.9.72: flight Sumter to Muscle Shoals AL, 300lb above gross weight, engine failed on takeoff, 4 k;

BA-370	E18S	N5646D	built	.58
		N262AA	Moore Brush Newspaper Inc, Canton OH	63/66
			WHBC Inc, Canton OH	69/70
			SMB Stage Line, Des Moines IA	71/73
			crashed destroyed by fire, landing Muscatine IA	27.11.73
	N26244	crash report 2	7 11 73: SMR Stage Line, flight Des Moines IA to Chica	ao

N262AA crash report 27.11.73: SMB Stage Line, flight Des Moines IA to Chicago, 3 attempts to land in freezing rain, flew into ground 10pm,

BA-371	E18S -9700	N753C	built Polaris Corp, Milkwaukee WI	4.58 63/64				
	-9700		Fred J. Banducci, Bakersfield CA	66/70				
		N753CW	Leo Pike, Bakersfield CA	.70/72				
			Bakersfield Aviation Services/ Air Rovers Inc,					
			Bakersfield CA	79				
			minor damage, midair collision Santa Ynez CA with					
			Beech E18S N8711 during ferry flight	7.4.84				
			Gold Coast Air Inc, Hawthorne CA	4.85/86				
			James B. Wilkins, Downey CA	9.87				
			Aerospace Products Inc, North Hollywood CA	7.91				
			Glenn A. Bagley, Honolulu HI	24.10.91/92 24.7.92				
		V6-CAA	sold to Micronesia, struck-off USCR Caroline Pacific Air, Pohnei	.96				
		N753CW	Bob Keys, Palau, Micronesia & Noosa QLD	97/00				
		11100011	(delivered Palau to Caboolture QLD via Cairns 26.10.97,					
			Edtended overhaul at Bundaberg QLD .98/00)					
		VH-CII	Robert H. Keys, Noosa Qld	16.6.00/15				
			(ferried via Cairns to Honiara 4.09, based Honiara)					
			Solomon Islands Seaplanes. Honiara: leased	7.09/10				
			(commenced tourist ops. Honiara 5.7.09,					
			back at Caboolture QLD 2015)	47 44 45/00				
			Brenton Hurt/ Territory Air Hire Pty Ltd, Darwin NT undercarriage retracted early on takeoff, aircraft settled	17.11.15/20				
			on to ground on belly during test flight Caboolture QLD	18.3.16				
			(repaired at Caboolture, ff 28.8.19, del. to Darwin)	10.0.10				
	N753CW r	noted Bakerst	field CA 4.11.79;					
			both being ferried from Santa Maria to Hawthorne CA & Lo					
			minor damage, N8711 badly damaged, both diverted to Sa	nta Ynez,				
		off runway o						
			side CA 27.11.87 retired, no titles;	214/ housed in circle d				
			26.10.97 "C Pacific AIr" titles, V6-CAA painted over, N7530 boolture Qld.;	Jvv nano-painteo				
			ture Qld 11.97 in hangar;					
	N753CW noted Caboolture 4.1.98 outside; BA-371 noted Bundaberg Qld 20.9.98 in hangar on overhaul no reg;							
	BA-371 noted Bundaberg 15.10.98 no reg: plate BA-371 built 4.58 conv to 9700lbs 30.1.64;							
	BA-371 noted Bundaberg 30.1.99 new blue/white colour scheme, no reg, under overhaul;							
	RA-371 noted Bundaberg 11 2 99							
	BA-371 noted Bundaberg 11.2.99 N753CW not on USCR 98/00							
	N753CW not on USCR 98/00; VH-CII noted Archerfield 10.00 new blue white paint scheme;							
	VH-CII noted Archemela 10.00 new blue white paint scheme; VH-CII noted Caloundra QLD 10.8.01, 29.8.01 blue & white good condition;							
	VH-CII noted Caloundra QED 10.8.01, 29.8.01 blue & white good condition, VH-CII noted Bundaberg 9.02 blue & white, outside, no props;							
	VI-CII noted Bundaberg 7.03 blue & white, outside; VH-CII noted Bundaberg 7.03 blue & white, outside;							
	VH-CII noted Bundaberg 28.1.04 blue & white, outside, plate BA-371;							
	VH-CII noted Bundaberg 16.7.05 blue & white;							
	VH-CII based Caboolture 06/07, lived in hangar but hangar cleared out c7.07 and then parked on							
	grass, blue & white; VH CII flow into Rundahara airshow 3.8.07:							
		VH-CII flew into Bundaberg airshow 3.8.07; Solomon Islands Seaplanes commanced 5.7.09. Founded by Cantain Bob Keys, a veteran of 45						
		Solomon Islands Seaplanes commenced 5.7.09. Founded by Captain Bob Keys, a veteran of 45 years in the aviation industry. Operators Certificate granted 11.08 and have an office at the						
		international terminal at Henderson, 9 pax E18S is in service with Goose due approx 9.09, Chief						
			n and Chief Pilot Andy Wade;					
	Damaged	during test flig	ght Caboolture Qld 17.3.16 in preparation for delivery to Da	arwin. Pilot				
attempted			, ,,, ,. ,. ,					
			he grass strip, became airborne, retracted gear but aircraft	settled back on to				
			) hangar the same day for repair. I major rebuild at Caboolture 6.17;					
	vi i-Gii ullo	iei iepail allu	i major repullo al Capoollure 0.17,					
BA-372	E18S	N142LM	Beech Aircraft Corp, Wichita KS: CofA issued	6.5.58				
5.012	2100	N301V	Money Investment Co, Phoenix AZ	63/66				
			ground collision on taxiway with light aircraft N8316J,					
			Phoenix-Sky Harbour AZ	1.8.67				
			Upper Valley Aviation, McAllen TX	69/70				
			G. G. Snediker/ Snedigar Flying Service/ Pro Air Lines,					

	Rapid City SD	72/77
	Bard Air Freight Inc, Detroit MI	78
N70CB	Bard Air Freight Inc, Detroit MI	20.5.78/84
	Bard Air Corp, Detroit MI	86/91
	Viking Group Inc, Detroit MI	6.92
	Skydive Greene County, Xenia OH	1.93
	Sky Charter Inc, Miami FL	22.11.93/13
	struck-off USCR	16.9.13

N70CB noted Detroit-Downtown MI 9.80 "Bard Air"; N70CB noted Toronto ONT 8.10.85 Bard Air, on a car parts charter;

BA-373	E18S	PP-FCN	built	.58
BA-374	E18S	N3030C	Beech Aircraft Corp, Wichita KS: CofA issued	7.7.58
			Charles P. McGaha, Wichita Falls TX	63/64
		N3038C	Austin White Lime Co, Austin TX	66/72
			Air Express Inc, Greensborough NC	79
			Southland Flyers, Memphis TN	79
			op: Air Cargo America Inc, Miami FL	83/86
	Hamilton		Sarah E. Orme, Homestead FL	9.83
	extended	l nose	Southern Aircraft Inc, Lantana FL	7.89/91
			Air Cargo Inc, Fort Lauderdale FL	1.94
			May Air Xpress, New Boston TX	4.5.94/95
			Scott R. Michels, Stillwater MN	29.1.98/99
			Beech Transportation Inc, Eden Prairie MN	23.6.99/00
			Navair Inc, Eden Prairie MN	2.2.00/06
			Ram Control, Osceola WI	8.09
			crashed, destroyed Flying Cloud Airport MN	12.8.09
	N3030C	noted Houstor	n Int'l TX 10.9.62, tailwheel, "M" on engine cowls;	
			L 3.83 landed, tailwheel, rep Air Cargo America;	
		noted Miami F		
	N3038C	noted Ft Laud	erdale Executive FL 10.11.91 Hamilton extended nose;	
			erdale Executive FL 12.91 all metallic, Hamilton extended	nose:
			Noud MN 7.02, Hamilton long nose, excellent condition;	,
			Noud MN 8.04 long nose, freighter;	
			rairie-Flying Cloud MN 30.7.05 polished metal, long nose, t	ailwheel:
			Cloud MN 29.7.06 long nose, stored outside left engine rem	
BA-375	E18S	N266AA	Beech Aircraft Corp, Wichita KS: CofA issued	24.7.58
BA-375	E103	N200AA	Buckeye Pipeline Co, New York NY	63/64
		N995BP	Buckeye Pipeline Co, New York NY	66
				69/72
		N995H	American Aero Leasing Corp, Elizabeth NJ	73/74
			Davis & Horne Flying Service	
			damaged right tyre blew out, landing El Paso TX engine torn away due propeller blade failure on takeoff,	27.10.73
			Topeka KS	7.10.74
			W. W. Dailey, Coolidge AZ	79
			Morey Wyman/ Wyman Pilot Service, Pontiac MI	83/84
			SITUCK ITEES ON IANDING. SKIDDED ON DEILV ACTOSS HEID.	
			struck trees on landing, skidded on belly across field, Youngstown OH	19.6.83
			Youngstown OH	19.6.83 31 12 90/06
			Youngstown OH Gary F. Annas, Brighton MI, later Minden NV	31.12.90/06
			Youngstown OH Gary F. Annas, Brighton MI, later Minden NV retired, stripped hulk, Pontiac MI	
		oted San Dieg	Youngstown OH Gary F. Annas, Brighton MI, later Minden NV retired, stripped hulk, Pontiac MI o CA 7.4.72;	31.12.90/06 97
	N995H a	ccident report	Youngstown OH Gary F. Annas, Brighton MI, later Minden NV retired, stripped hulk, Pontiac MI o CA 7.4.72; 27.10.73 Davis & Horne, flight Albuquerque NM to El Paso	31.12.90/06 97 , 8 unhurt;
	N995H a N995H a	ccident report ccident report	Youngstown OH Gary F. Annas, Brighton MI, later Minden NV retired, stripped hulk, Pontiac MI o CA 7.4.72; 27.10.73 Davis & Horne, flight Albuquerque NM to El Paso 7.10.74 Davis-Horne Flying Service, flight Topeka to McAl	31.12.90/06 97 9, 8 unhurt;
	N995H a N995H a N995H n	ccident report ccident report oted Pontiac N	Youngstown OH Gary F. Annas, Brighton MI, later Minden NV retired, stripped hulk, Pontiac MI o CA 7.4.72; 27.10.73 Davis & Horne, flight Albuquerque NM to El Paso 7.10.74 Davis-Horne Flying Service, flight Topeka to McAl Al 17.9.78;	31.12.90/06 97 9, 8 unhurt;
	N995H a N995H a N995H n N995H n	ccident report ccident report oted Pontiac N oted Pontiac N	Youngstown OH Gary F. Annas, Brighton MI, later Minden NV retired, stripped hulk, Pontiac MI o CA 7.4.72; 27.10.73 Davis & Horne, flight Albuquerque NM to El Paso 7.10.74 Davis-Horne Flying Service, flight Topeka to McAl Al 17.9.78; Al 9.80 plate BA-375;	31.12.90/06 97 9, 8 unhurt; ester OK, 4 unhurt
	N995H a N995H a N995H n N995H n N995H a	ccident report ccident report oted Pontiac N oted Pontiac N	Youngstown OH Gary F. Annas, Brighton MI, later Minden NV retired, stripped hulk, Pontiac MI o CA 7.4.72; 27.10.73 Davis & Horne, flight Albuquerque NM to El Paso 7.10.74 Davis-Horne Flying Service, flight Topeka to McAl Al 17.9.78;	31.12.90/06 97 9, 8 unhurt; ester OK, 4 unhurt
	N995H a N995H a N995H n N995H n N995H a unhurt;	ccident report ccident report oted Pontiac N oted Pontiac N ccident report	Youngstown OH Gary F. Annas, Brighton MI, later Minden NV retired, stripped hulk, Pontiac MI o CA 7.4.72; 27.10.73 Davis & Horne, flight Albuquerque NM to El Paso 7.10.74 Davis-Horne Flying Service, flight Topeka to McAl Al 17.9.78; Al 9.80 plate BA-375;	31.12.90/06 97 9, 8 unhurt; ester OK, 4 unhurt

BA-376	E18S	4R-AAS	Ceylon Dept. of Survey, Colombo-Ratmalana	20
			(fitted for photographic survey prior to delivery)	

20.8.58

			crashed during training flight, Lunawa, Ceylon (wreck stored in hangar Ratmalana 58/59)	25.8.58
BA-377	E18S	N5652D	Beech Aircraft Corp, Wichita KS: CofA issued	13.8.58
			Murphy Oil Corp, El Dorado AR	61
		N360M	Murphy Oil Corp, El Dorado AR	27.4.61/66
		N860M	Ross Aviation, Tulsa-Riverside OK	69
			Great Western Airlines, Tulsa-Riverside OK	70/77
			Bobbie J. Johnson, Camden TN	29.11.77/91
	N860M p	hoto c71 "Gre	at Western Airlines" titles, passenger cabin, tailwheel;	
BA-378	E18S	N17Z	built	.58
		N415A	Aluminum Company of America, Dravosburg PA	63/66
			Geo Update Inc, Salt Lake City UT	69/70
			Palm Beach Air Traders, Lantana FL	15.4.74/75
			struck-off USCR	9.5.75
BA-379	E18S	N46L (2	Beech Aircraft Corp, Wichita KS: CofA issued	26.8.58
			Lincoln National Life Insurance, Fort Wayne IN	63/64
			Excel Corp, Elkhart IN	66
			Continental Bus Interiors Inc, Elkhart IN	69/70
			Phillips Realty Co, Greensboro NC	71/72
			Eagle Aviation, Flint MI	79/82
			Robert L. Green, Clarkston MI	8.83
			Mark H. Thompson, Marietta GA	11.83
			Daniel J. Wetli, Antwerp OH	4.85
			damaged engine fire on start-up, Fort Wayne IN	24.11.85
			retired derelict, Pontiac MI	89
			Wyman Pilot Service, Pontiac MI	91
			David L. Schulze, Flint MI	3.12.93/05
			Donald R. Adamson, Lonoke AR	4.4.05
		N92WA	Donald R. Adamson, Lonoke AR	3.8.05/20
		ted Youngstow		
BA-380		ted Youngstow	Donald R. Adamson, Lonoke AR <i>yn OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built	.58
BA-380	N46L not	ted Youngstow ted Pontiac MI	Donald R. Adamson, Lonoke AR yn OH 12.3.82 Eagle Aviation; ' 4.8.89 retired, derelict;	3.8.05/20 .58 59
BA-380	N46L not	ted Youngstow ted Pontiac MI	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed	.58
BA-380	N46L not	ted Youngstow ted Pontiac MI	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel,	3.8.05/20 .58 59
BA-380	N46L not	ted Youngstow ted Pontiac MI	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed	3.8.05/20 .58 59
	N46L not	ted Youngstow ted Pontiac MI	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G	3.8.05/20 .58 .59 .59
	N46L not	ted Youngstow ted Pontiac MI N19U N5649D N516T	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX	3.8.05/20 .58 .59 .59 .59
	N46L not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie	3.8.05/20 .58 .59 .59 .59
	N46L not	ted Youngstow ted Pontiac MI N19U N5649D N516T	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX	3.8.05/20 .58 59 .59 .59 .59
	N46L not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA	3.8.05/20 .58 59 .59 .59 .59
	N46L not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA	3.8.05/20 .58 59 .59 .59 .59 .59
	N46L not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX	3.8.05/20 .58 59 .59 .59 .59 .59 .59
	N46L not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX James Price, Freeport, Bahamas	3.8.05/20 .58 59 .59 .59 .59 .59 .59 .59 .59 .59 .59
	N46L not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX	3.8.05/20 .58 59 .59 .59 .59 .59 .59
	N46L not E18S E18S N516K at	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J N516K	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX James Price, Freeport, Bahamas	3.8.05/20 .58 59 .59 .59 .59 .59 .59 .59 .59 .59 .59
BA-381	N46L not E18S E18S N516K at N516K not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J N516K	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX James Price, Freeport, Bahamas sale reported, McAllen TX: USCR 19.5.69: Pan Air Corp, struck fire plug taxying at night; ka FL 3.10.78; Beech Aircraft Corp, Wichita KS: CofA issued	3.8.05/20 .58 59 .59 .59 .59 .59 .58 62 11.62 63 66/72 19.5.69 1.82 79 91
BA-381	N46L not E18S E18S N516K at N516K n	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J N516K ccident report oted Opa Lock	Donald R. Adamson, Lonoke AR <i>In OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX James Price, Freeport, Bahamas sale reported, McAllen TX: USCR <i>19.5.69: Pan Air Corp, struck fire plug taxying at night;</i> <i>ka FL 3.10.78;</i> Beech Aircraft Corp, Wichita KS: CofA issued Batesville Casket Co, Batesville IN	3.8.05/20 .58 59 .59 .59 .59 .59 .58 62 11.62 63 66/72 19.5.69 1.82 79 91
BA-381	N46L not E18S E18S N516K at N516K not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J N516K ccident report oted Opa Lock	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX James Price, Freeport, Bahamas sale reported, McAllen TX: USCR 19.5.69: Pan Air Corp, struck fire plug taxying at night; ka FL 3.10.78; Beech Aircraft Corp, Wichita KS: CofA issued	3.8.05/20 .58 59 .59 .59 .59 .59 .58 62 11.62 63 66/72 19.5.69 1.82 79 91
BA-380 BA-381 BA-382	N46L not E18S E18S N516K at N516K not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J N516K ccident report oted Opa Lock	Donald R. Adamson, Lonoke AR <i>In OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX James Price, Freeport, Bahamas sale reported, McAllen TX: USCR <i>19.5.69: Pan Air Corp, struck fire plug taxying at night;</i> <i>ka FL 3.10.78;</i> Beech Aircraft Corp, Wichita KS: CofA issued Batesville Casket Co, Batesville IN	3.8.05/20 .58 59 .59 .59 .59 .59 .58 62 11.62 63 66/72 19.5.69 1.82 79 91
BA-381	N46L not E18S E18S N516K at N516K not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J N516K ccident report oted Opa Lock N5651D N534H	Donald R. Adamson, Lonoke AR <i>In OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX James Price, Freeport, Bahamas sale reported, McAllen TX: USCR <i>19.5.69: Pan Air Corp, struck fire plug taxying at night;</i> <i>ka FL 3.10.78;</i> Beech Aircraft Corp, Wichita KS: CofA issued Batesville Casket Co, Batesville IN Hillenbrand Industries, Batesville IN	3.8.05/20 .58 59 .59 .59 .59 .59 .58 62 11.62 63 66/72 19.5.69 1.82 79 91 .58 63/64 66
BA-381	N46L not E18S E18S N516K at N516K not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J N516K ccident report oted Opa Lock N5651D N534H	Donald R. Adamson, Lonoke AR <i>In OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX James Price, Freeport, Bahamas sale reported, McAllen TX: USCR <i>19.5.69: Pan Air Corp, struck fire plug taxying at night;</i> <i>ka FL 3.10.78;</i> Beech Aircraft Corp, Wichita KS: CofA issued Batesville Casket Co, Batesville IN Hillenbrand Industries, Batesville IN Ohio Aviation Corp, Dayton OH	3.8.05/20 .58 59 .59 .59 .59 .58 62 11.62 63 66/72 19.5.69 1.82 79 91 .58 63/64 66 69
BA-381	N46L not E18S E18S N516K at N516K not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J N516K ccident report oted Opa Lock N5651D N534H	Donald R. Adamson, Lonoke AR <i>In OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX James Price, Freeport, Bahamas sale reported, McAllen TX: USCR <i>19.5.69: Pan Air Corp, struck fire plug taxying at night;</i> <i>ka FL 3.10.78;</i> Beech Aircraft Corp, Wichita KS: CofA issued Batesville Casket Co, Batesville IN Hillenbrand Industries, Batesville IN Ohio Aviation Corp, Dayton OH Belmont Charter Service, Detroit MI	3.8.05/20 .58 59 .59 .59 .59 .59 .58 62 11.62 63 66/72 19.5.69 1.82 79 91 .58 63/64 66 69 70
BA-381	N46L not E18S E18S N516K at N516K not	ted Youngstow ted Pontiac MI N19U N5649D N516T N516J N516K ccident report oted Opa Lock N5651D N534H	Donald R. Adamson, Lonoke AR <i>in OH 12.3.82 Eagle Aviation;</i> <i>4.8.89 retired, derelict;</i> built Cochran Aviation Inc, Oakland Airport CA crashed (nose, cowlings, gear doors, extended tailwheel, cabin windows and other components fitted to C-45G N234JC/AF-317 of Golden Gate Aviation, Oakland .59) built Tennessee Gas & Transmission Co, Houston TX J. S. Abercrombie Kilroy Co of Texas Inc, Houston TX Pan Air Corp, New Orleans LA struck post taxying, New Orleans-Lake Front LA Cathryn E. Tedder, Texarkana TX James Price, Freeport, Bahamas sale reported, McAllen TX: USCR <i>19.5.69: Pan Air Corp, struck fire plug taxying at night;</i> <i>ka FL 3.10.78;</i> Beech Aircraft Corp, Wichita KS: CofA issued Batesville Casket Co, Batesville IN Hillenbrand Industries, Batesville IN Ohio Aviation Corp, Dayton OH Belmont Charter Service, Detroit MI Combs Airways Inc, Billings-Logan MT	3.8.05/20 .58 59 .59 .59 .59 .59 .58 62 11.62 63 66/72 19.5.69 1.82 79 91 .58 63/64 66 69 70 71/72

N9669N	HoganAir Inc, Hamilton OH	10.86
	The Eagle and the Hawks Inc, Middletown OH	91/94
	Miami Valley Aviation, Middletown OH	18.3.94/98
	The Eagle and the Hawks Inc, Middletown OH	29.5.98/14
	op: Miami Valley Aviation, Middletown OH	98/05
	George Loudakis, Stuart FL	1.12.15/20

N538H noted Port Arkansas-Mustang TX 8.6.76 bare metal; N96HA noted Hamilton OH 13.8.85 all metallic no titles; N9669N noted Middletown OH 6.94 no titles, reported HoganAir, tailwheel, freighter; N9669N noted Middletown OH 5.97, 22.7.98 & 9.98, 7.8.99, 22.7.00, 20.7.02: all Miami Valley Aviation, no titles, plate E18S-9700 BA-382 built 9.58; N9669N noted Middletown OH 12.10.02 no titles;

N9669N noted Middletown OH 1.8.05, offered for sale with N8711H, Miami Valley Aviation has ceased ops;

N9669N noted Middletown 17.6.06 retired; N9669N noted Hamilton OH 6.11.10 complete;

BA-383	E18S	N18Z	built	.58
	-9700		Collins Radio Co, Cedar Rapids IA	63/72
		N77CR	Collins Radio Co, Cedar Rapids IA	
			Rockwell International, Cedar Rapids IA	79
		N18E	Philip W. Schultz, Lancaster CA	1.11.84/20

N18E noted Lancaster-Fox Field CA 27.3.93;

N18E at Oshkosh 7.08, plates BA-383 built 9.59, -9700 mod 16.9.60;

BA-384	E18S	N87D (2	Youngstown Airways/ Lease Air, Youngstown OH: CofA	26.9.58
	-9700		(mods. For E18S-9700 installed 4.59)	
		N8711	Jack Adams Aircraft Sales Inc, Walls MS	63
			Beach Air Service, Fort Lauderdale FL	64
			Bear Manufacturing Corp, Rock Island IL	66/72
	trigear		C & L Inc, Homer AK	79
			Aurora Air Service, Fairbanks AK	80/81
			Coast Air Freight, Long Beach CA	11.81/85
			ran off runway landing Santa Ynez CA, landing after	
			midair collision with Beech E18S N753CW	7.4.84
			TELCO, Naperville IL	1.85
			Englund Aviation, Mobile AL	11.87
			Robert B. Burwell, West Chicago IL	3.12.90/14
		(N890P)	ntu: Robert B. Burwell, West Chicago IL	4.91
		N8711	(N8711 retired engineless, nose damaged, Aurora IL 99/	02)
			struck-off USCR by FAA	4.5.15

N8711 noted Indianapolis IN 29.5.76 trigear "Bear Manufacturing Co" titles; N8711 noted LAX 19.7.83 Airborne Express scheme leased from Coastal AW LGB; N8711 noted LAX 1.9.83 Airborne Express scheme & titles, op. by Coast Air Freight, trigear; midair collision 7.4.84: both being ferried from Santa Maria to Long Beach CA & Hawthorne respectively: N753CW minor damage N8711 badly damagd both diverted to Santa Ynez, N8711 ran off runway on landing; N8711 noted Aurora IL 2.8.99 trigear, props removed and nose damaged, plate BA-384 built 9.58, another plate: converted to E18S-9700 4.59;

N8711 noted Aurora IL 30.12.01 engineless;

BA-385	E18S	N5653D	Atlantic Aviation Corp, Hackensack NJ	11.58
			Dorado Beach Hotel & Golf Club, New York NY	11.58/61
			Dorado Beach Hotel Corp, Dorado, Puerto Rico	11.61/64
			Penn Aire Aviation, Franklin PA	5.64
			Continental Aircraft Sales, Medford NJ	12.65
			Thunderbird Airways Inc, Medford NJ	12.65/66
			(modified 2.66 to operate without door, approved by	
			FAA for "emergency delivery of food after blizzard")	
			Longhorn Airways, Medford NJ	4.66
			American Turbine Sales Corp/	
			American Turbine Engine Co, Long Beach CA	9.66
	ATE		(rebuild as prototype ATE Westwind I completed 9.66:	

	Westwind I trigear	Volpar trigear, PT6A-20 turbines, picture windows, airconditioning etc, retained twin tailplanes) Jack Adams Aircraft Sales, Walls MS American Turbine Sales Corp, Long Beach CA Ambassador Airlines, Las Vegas-McCarran NV Carco Air Service of Nevada Inc, Las Vegas NV (Beech cargo door installed 3.69) hard landing, gear collapsed, Bettles AK (turbine props reversed prematurely during short field	3.67 4.67 8.67/68 7.68 25.8.69
	Hamilton Westwind III	landing demonstration: repaired by Field Aviation Co, Calgary ALTA) Nevada National Bank, Las Vegas NV (Beech cargo door removed 2.72) Hamilton Aircraft Co, Tucson AZ (rebuilt as <i>Hamilton Westwind III</i> : Volpar trigear replaced by tailwheel landing gear, crew door & Hamilton long nos	
	tailgear	max AUW 11230 lb kit, completed by Hamilton 3.72) SMB Stage Line Inc, Des Moines IA Jarex Corp, Columbus IN Jet Way Enterprises Inc, Willow Run MI Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter, Willow Run MI: Isd Ken & Karl Stoltzfus/K & K Aircraft Inc, Bridgewater VA (CofA renewed 19.4.91 after fitted for agricultural & pest	23.3.72/85 9.85 11.85 6.87/89 6.87/89 3.91/04
	N8975	control sprayer operations) Brazoria County Mosquito Control, Angleton TX	17.6.04/05 3.05/16 14.10.16/17 121.7.17/20
	Further info: see B N5653D noted LAX N5653D accident r N5653D noted Tuc N5653D noted Tuc N5653D noted Col N5653D noted St I N5653D noted St I N5653D noted Por N5653D noted Des N5653D noted Dal N5653D noted Dal N5653D noted Will N5653D noted Los	do Beach Hotel 11.58 signed by Lawrence S. Rockefeller, owne eech 18 by Robert Parmerter p.332; < 18.3.67 Ambassador Airlines, Turbo Volpar eport 25.8.69: demo flight of Westwind Mk.1, soft surface; son AZ 11.8.71 at Hamilton Aircraft ramp, Westwind turbine con son AZ 3.4.72 at Hamilton ramp, Westwind turbine; umbus OH 5.72 "SMB" titles, PT6As, tailwheel, extended nose; ouis MO 29.9.72 turbine tailwheel "SMB Stage Line", ouis MO 3.76 "SMB Stage Line", tailwheel turbine; t Columbus OH 26.5.76 Westwind III "SMB Stage Line" titles; s Moines IA 21.12.78; las-FTW 7.11.81 "SMB" insignia, Hamilton Westind turbines, tai low Run MI 3.8.89 "Active Aero Charter, Willow Run", Westwind Alamitos CA 17.8.99 K&K Aircraft, sprayer, plate BA-385 built Alamitos CA 13.8.02 with other K&K sprayers;	nversion; ilwheel; I III;
BA-386	E18S N5654 -9700 CF-AN	<ul> <li>Beech Aircraft Corp, Wichita KS sold to Canada, struck-off USCR</li> <li>Anthes-Imperial Co Ltd, St Catherines ONT (replaced D18S CF-ANT A-352 rereg CF-LLF 4.59) Perimeter Flying Associates Ltd, Winnipeg MAN Perimeter Aviation Ltd, Winnipeg MAN op: Air Niagara, St Catharines ONT gear collapsed landing St Therese Point MAN B. F. Klassen Construction Ltd, Winnioeg MAN left gear collapsed landing on snow, Gods Narrows MAN landed gear-up Thompson MAN Lac du Bonnet Air Park, Lac Bonnet MAN Slate Falls Airways Ltd, Sioux Lookout ONT wrecked, ran off runway on takeoff Round Lake ONT (wreck buried at Round Lake Airport)</li> </ul>	8.12.58 19.5.59 23.4.59/67 6.6.67 28.2.69/72 3.69/71 24.6.70 12.8.71/74 13.12.71 22.8.72 24.4.74 26.7.76 25.11.76
	CF-ANT noted Tor	onto-Malton ONT 1.1.71, tailwheel;	

BA-387	E18S	N5655D	Beech Aircraft Corp, Wichita KS: CofA issued	21.10.58
		N500W	S. J. Groves & Sons Co, Ann Arbor MI	63/66

\_

		N762SP	John C. Mosby, Ladue MO Highland Management Co, St Louis MO gear collapsed landing, Festus MO sale reported: USCR	69 70/72 3.11.74 74/91
BA-388	E18S -9700	N27Y	Beech Aircraft Corp, Wichita KS: CofA issued Basic Products Corp, Milwaukee WI Gopher Aviation, Rochester Airport MN Eclipse Fuel Engineering Co, Rockford IL Bakersfield Aviation Services/ Air Rovers Inc, Bakersfield CA A. A. Portanova & Sons, Agoura CA Robert A. Youkin, Springdale AR Wal-Mart Stores Inc, Bentonville AR crashed forced landing in field after takeoff, Terrell TX (carrying photographs developed for Wal-Mart stores) sale reported, Springdale AR: USCR South West Aero Exchange, Owasso OK (dismantled in salvage yard, Owasso OK 97/00)	21.11.58 63 64 66/72 79 8.81 4.84 2.85 2.1.86 91/06 97/00
	N27Y note N27Y note N27Y note	ed Bakersfield ed Bakersfield ed Owasso Ol	A 1.59, tailwheel, no titles; I CA 20.9.77 tailwheel, I CA 4.11.79; K 13.10.97 stripped hulk; W Aero Exchange Owasso OK 10.8.00;	
BA-389	E18S trigear	N691T RP-C690	built Crose-Perrault Equipment Corp, Houston TX Walker Developments Inc, Columbia SC op: Gold Coast Airways, Palm Beach FL Hill Aircraft & Leasing Corp, Atlanta GA Southeast Commuter Airlines, Mobile AL op: Island Air Tours, Honolulu HI Robert A. Justman/ Justman Enterprises Inc/ Hawaiian Sky Tour, Honolulu HI op: Circle Rainbow Air, Honolulu HI <i>Lara</i> op: Hawaiian Sky Tour, Honolulu HI <i>Lara</i> sold to Philippines: struck-off USCR Charles R. Miller/ Commuter Air Philippines, Manila CofA expired 1.3.04, struck-off Register	.58 63/64 66 68 69/70 71/72 76 79 .80/84 2.7.87 87/03 .08
	N691T no N691T no N691T no N691T no N691T no RP-C690 RP-C690	ted Kahului H ted Honolulu ted Honolulu ted Honolulu ted Honolulu noted Manila noted Manila	1.76 trigear, "Island Air Tours"; Il 27.7.76 reported as Panorama AT; 5.9.79 "Lara"; 12.11.79; 3.12.79 Circle Rainbow Air; 1.11.80 trigear "Hawaiian Sky Tour" titles; 9.83 trigear "Hawaiian Sky Tour" & "Lara", plate BA-389; 8.10.87 Commuter Air Philippines; 2.1.94 trigear,white with blue trim no titles, at Charlie Mill 4.2.98 in service white & blue trigear;	er's ramp;
BA-390	E18S	XB-DAX XB-TUN	built rereg	.58
		XA-SIN	rereg	.67/72
	XB-DAX r	noted Mexico	City 25.4.66;	
BA-391	E18S	N185AA N45WT N45TB	built Vinnell Corp, Alhambra CA rereg Bartlite Inc, San Antonio TX Holborn Investments Inc, Woodbury NJ gear collapsed landing, Williston FL struck-off USCR	.58 63/70 71/73 26.11.73/74 9.1.74 1.4.74

N45TB noted San Antonio TX 16.5.73

BA-392	E18S	N5659D	built	.58
			Winthrop Rockefeller, Little Rock AR	63/64
			Central Flying Service, Little Rock AR	16.4.66/70
			crashed destroyed landing, Kansas City MO	14.2.70
		report 14.2.70 in snow & fre	: Central Flying Service, mail flight, time 0108 Local, flew ezing drizzle;	into ground during
BA-393	E18S	N5657D (1	built	.58
		N679T	Concord Mobile Homes Inc, Elkhart IN	63/64
			Lasalle & Deitch Inc, Elkhart IN	66
			Montgomery Aviation Corp/ Huntsville Aviation,	
			Montgomery AL	69/72
			hit trees during night landing, Montgomery AL	10.12.69
			Norman C. Mayes, Powell TN	79
			Semo Aviation, Malden MO	80
			op: General Aviation Inc, Greenville TN	80
			Coker Airfreight Inc, Dallas TX	.80/81
		N91CA	Coker Airfreight Inc, Dallas TX	9.81/84
			ran off runway landing, struck drainage channel,	
			nosed over, Lubbock TX	30.6.82
			nn: Skyfreighters Corp, Dallas TX	84/85
			struck-off USCR	4.85
	during lar	nding at 0310	10.12.69: Montgomery Aviation, pilot vision obscured by v local, 30.6.82: Coker Airfreight Inc: tailwheel;	windscreen alcohol
BA-394	E18S	N5660D	Beech Aircraft Corp, Wichita KS: CofA issued	16.12.58
		N16U (2	Pure Oil Co, Chicago IL	63/64
		\	Union Oil Co of California, Palatine IL	66/70
			Don J. Wangalin, Palatine IL	71/72
			Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA	71/72 74/81
			Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI	71/72 74/81 .81
			Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK	71/72 74/81 .81 7.89/94
			Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK	71/72 74/81 .81 7.89/94 12.7.94/99
			Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00
			Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06
			Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16
			Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06
	N16U not N16U not N16U not	ted Flying Clou ted Flying Clou ted Flying Clou	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20
BA-395	N16U not N16U not N16U not	ted Flying Clou ted Flying Clou ted Flying Clou	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico and MN 7.02, excellent condition, tailwheel; and 25.7.04 tailwheel, owned Navair, extended nose (not H at 8.04; Flying Cloud 30.7.05 tailwheel; and 29.7.06 under maintenance: plate BA-394 built 12.58, d to 9799AUW 26.3.59; Beech Aircraft Corp, Wichita KS: CofA issued	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20
BA-395	N16U not N16U not N16U not another p	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico and MN 7.02, excellent condition, tailwheel; and 25.7.04 tailwheel, owned Navair, extended nose (not H at 8.04; Flying Cloud 30.7.05 tailwheel; and 29.7.06 under maintenance: plate BA-394 built 12.58, d to 9799AUW 26.3.59; Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 damilton long nose
3A-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico and MN 7.02, excellent condition, tailwheel; and 25.7.04 tailwheel, owned Navair, extended nose (not F and 8.04; Flying Cloud 30.7.05 tailwheel; and 29.7.06 under maintenance: plate BA-394 built 12.58, d to 9799AUW 26.3.59; Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 damilton long nose
3A-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P N94PB	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico and MN 7.02, excellent condition, tailwheel; and 25.7.04 tailwheel, owned Navair, extended nose (not F and 8.04; Flying Cloud 30.7.05 tailwheel; and 29.7.06 under maintenance: plate BA-394 built 12.58, d to 9799AUW 26.3.59; Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Perry Enterprises Inc, Fresno CA	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 damilton long nose 7.1.59 63 66/70 71
3A-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico <i>ud MN 7.02, excellent condition, tailwheel;</i> <i>ud 25.7.04 tailwheel, owned Navair, extended nose (not Fud 8.04; Flying Cloud 30.7.05 tailwheel;</i> <i>ud 29.7.06 under maintenance: plate BA-394 built 12.58,</i> <i>d to 9799AUW 26.3.59;</i> Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Perry Enterprises Inc, Fresno CA Federated Leasing Associates, Miami FL	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 Hamilton long nose 63 66/70 71 79
3A-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P N94PB	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico <i>ud MN 7.02, excellent condition, tailwheel;</i> <i>ud 25.7.04 tailwheel, owned Navair, extended nose (not F</i> <i>ud 8.04; Flying Cloud 30.7.05 tailwheel;</i> <i>ud 29.7.06 under maintenance: plate BA-394 built 12.58,</i> <i>d to 9799AUW 26.3.59;</i> Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Perry Enterprises Inc, Fresno CA Federated Leasing Associates, Miami FL George K. Armagost/ Pro Air Services, Opa Locka FL	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 Hamilton long nose 63 66/70 71 79 82/84
BA-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P N94PB	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico <i>ud MN 7.02, excellent condition, tailwheel;</i> <i>ud 25.7.04 tailwheel, owned Navair, extended nose (not Fud 8.04; Flying Cloud 30.7.05 tailwheel;</i> <i>ud 29.7.06 under maintenance: plate BA-394 built 12.58,</i> <i>d to 9799AUW 26.3.59;</i> Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Perry Enterprises Inc, Fresno CA Federated Leasing Associates, Miami FL George K. Armagost/ Pro Air Services, Opa Locka FL damaged wheels-up landing, Opa Locka FL	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 Hamilton long nose 63 66/70 71 79 82/84 22.9.83
BA-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P N94PB	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico <i>ud MN 7.02, excellent condition, tailwheel;</i> <i>ud 25.7.04 tailwheel, owned Navair, extended nose (not Fud 8.04; Flying Cloud 30.7.05 tailwheel;</i> <i>ud 29.7.06 under maintenance: plate BA-394 built 12.58,</i> <i>d to 9799AUW 26.3.59;</i> Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Pedrated Leasing Associates, Miami FL George K. Armagost/ Pro Air Services, Opa Locka FL Julac Export Corp, Boynton Beach FL	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 Hamilton long nose 63 66/70 71 79 82/84
BA-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P N94PB	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico <i>ud MN 7.02, excellent condition, tailwheel;</i> <i>ud 25.7.04 tailwheel, owned Navair, extended nose (not Fud 8.04; Flying Cloud 30.7.05 tailwheel;</i> <i>ud 29.7.06 under maintenance: plate BA-394 built 12.58,</i> <i>d to 9799AUW 26.3.59;</i> Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Perry Enterprises Inc, Fresno CA Federated Leasing Associates, Miami FL George K. Armagost/ Pro Air Services, Opa Locka FL damaged wheels-up landing, Opa Locka FL	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 Hamilton long nose 63 66/70 71 79 82/84 22.9.83
BA-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P N94PB	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico <i>ud MN 7.02, excellent condition, tailwheel;</i> <i>ud 25.7.04 tailwheel, owned Navair, extended nose (not Fud 8.04; Flying Cloud 30.7.05 tailwheel;</i> <i>ud 29.7.06 under maintenance: plate BA-394 built 12.58,</i> <i>d to 9799AUW 26.3.59;</i> Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Pedrated Leasing Associates, Miami FL George K. Armagost/ Pro Air Services, Opa Locka FL Julac Export Corp, Boynton Beach FL	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 Hamilton long nose 63 66/70 71 79 82/84 22.9.83 4.84
BA-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P N94PB	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico <i>ud MN 7.02, excellent condition, tailwheel;</i> <i>ud 25.7.04 tailwheel, owned Navair, extended nose (not Fud 8.04; Flying Cloud 30.7.05 tailwheel;</i> <i>ud 29.7.06 under maintenance: plate BA-394 built 12.58,</i> <i>d to 9799AUW 26.3.59;</i> Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Federated Leasing Associates, Miami FL George K. Armagost/ Pro Air Services, Opa Locka FL Julac Export Corp, Boynton Beach FL Union Flights, Sacramento CA	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 Hamilton long nose 63 66/70 71 79 82/84 22.9.83 4.84 2.85/95
BA-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P N94PB	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico <i>ud MN 7.02, excellent condition, tailwheel;</i> <i>ud 25.7.04 tailwheel, owned Navair, extended nose (not Fud 8.04; Flying Cloud 30.7.05 tailwheel;</i> <i>ud 29.7.06 under maintenance: plate BA-394 built 12.58,</i> <i>d to 9799AUW 26.3.59;</i> Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Federated Leasing Associates, Miami FL George K. Armagost/ Pro Air Services, Opa Locka FL Julac Export Corp, Boynton Beach FL Union Flights, Sacramento CA Jim Hankins Air Service, Jackson MS	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 familton long nose 63 66/70 71 79 82/84 22.9.83 4.84 2.85/95 12.5.95/96
BA-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P N94PB	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico <i>ud MN 7.02, excellent condition, tailwheel;</i> <i>ud 25.7.04 tailwheel, owned Navair, extended nose (not Fud 8.04; Flying Cloud 30.7.05 tailwheel;</i> <i>ud 29.7.06 under maintenance: plate BA-394 built 12.58,</i> <i>d to 9799AUW 26.3.59;</i> Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Perry Enterprises Inc, Frenso CA Federated Leasing Associates, Miami FL George K. Armagost/ Pro Air Services, Opa Locka FL Julac Export Corp, Boynton Beach FL Union Flights, Sacramento CA Jim Hankins Air Service, Jackson MS Sky Charter Inc, Opa Locka FL	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 Hamilton long nose 7.1.59 63 66/70 71 79 82/84 22.9.83 4.84 2.85/95 12.5.95/96 11.96/99
BA-395	N16U not N16U not N16U not another p E18S	ted Flying Clou ted Flying Clou ted Flying Clou late: converte N97N N94P N94PB	Don J. Wangalin, Palatine IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI Gussic Ventures Inc, Unalakleet AK Hageland Aviation Services, Anchorage AK Beech Transportation, Eden Prairie MN Navair Inc, Eden Prairie MN Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Group, Carolina, Puerto Rico <i>ud MN 7.02, excellent condition, tailwheel;</i> <i>ud 25.7.04 tailwheel, owned Navair, extended nose (not Fud 8.04; Flying Cloud 30.7.05 tailwheel;</i> <i>ud 29.7.06 under maintenance: plate BA-394 built 12.58,</i> <i>d to 9799AUW 26.3.59;</i> Beech Aircraft Corp, Wichita KS: CofA issued Martin Marietta Corp, Baltimore MD Perry Enterprises Inc, Frenso CA Federated Leasing Associates, Miami FL George K. Armagost/ Pro Air Services, Opa Locka FL Julac Export Corp, Boynton Beach FL Union Flights, Sacramento CA Jim Hankins Air Service, Jackson MS Sky Charter Inc, Opa Locka FL South Florida Aircraft Leasing, Opa Locka FL	71/72 74/81 .81 7.89/94 12.7.94/99 11.10.99/00 7.2.00/06 7.6.10/16 20.3.17 7.6.17/20 Hamilton long nose, 63 66/70 71 79 82/84 22.9.83 4.84 2.85/95 12.5.95/96 11.96/99 22.4.99/00

N967 noted Tallahassie Municiple FL 28.10.77, trigear; N967 noted Sacramento-Executive CA 4.82 trigear, no titles; accident report 22.9.83: landed wheels-up, Pro Air Services; N967 noted Sacramento-Executive CA 17.8.87 trigear "Union Flights"; N967 noted Bakersfield CA 7.91 trigear "Union Flights"; N967 noted Santa Barabara CA 10.93 "Union Flights" titles, trigear; N967 noted Opa Locka FL 1.96, 21.1.97 trigear, Union Flights scheme, rep op Florida Air Cargo; N967 noted Opa Locka FL 1.4.97 trigear, 9.97 trigear; N967 noted Opa Locka FL 2.4.00 "Florida Air Cargo" titles, blue & metallic; N967 noted Opa Locka FL 27.11.00, 4.4.01 plate BA-395; N967 noted Opa Locka FL 5.01 trigear;

	E18S	N100NH	National Homes Corp, Lafayette IN crashed	27.3.59/62 4.11.62
BA-397	E18S	N383B	built	.58
	-9700		(mods to E18S-9700 installed 24.7.59)	
			Carpenter Paper Co, Omaha NE	63
			Ohio Aviation Co, Vandalia-Dayton Municiple OH	64
			McDonough Co, Parkersburg WV	66
			Rambar Aviation, Parkersburg WV	69/72
			op: Little Mountain Air Cargo, Denver NC	78
			damaged on takeoff, Columbia SC	14.3.78
			Southern National Leasing Corp, Charlotte NC	79
			Equipment Leasing Corp, Greenville SC	81/84
			Mountain Air Cargo, Denver NC: Isd	81/84
			ran off runway landing, down embankment,	
			Franklin-Chess Lambertson PA	8.11.83
			Coastal States Aviation, Denver NC	3.85
			Springdale Air Service, Springdale AR	24.3.86/95
			struck-off USCR	30.3.95
			(retired dismantled Springdale AR: parts source 97)	00.0.00
			South West Aero Exchange, Owasso OK	00
			(stored in salvage yard, Owasso OK 00)	00
			le AR 8.97 & 10.97 fuselage stacked against Springdale	AS hangar wall:
	N383B n	397 built 12.5 oted SW Aero	8; Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed;	-
BA-398	N383B n	397 built 12.5 oted SW Aero	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58	-
BA-398	N383B no another p	397 built 12.5 oted SW Aero plate: conv to -	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed;	3,
BA-398	N383B no another p	397 built 12.5 oted SW Aero blate: conv to - N510E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued	3,
BA-398	N383B no another p	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH	23.1.59
BA-398	N383B no another p	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA	3, 23.1.59 63/69
BA-398	N383B no another p	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA	3, 23.1.59 63/69 70
BA-398	N383B no another p	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA Western Suburban Airways, Chicago IL	3, 23.1.59 63/69 70 71/72
BA-398	N383B nd another p E18S N513E nd	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E N513E N513E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA Western Suburban Airways, Chicago IL Caribbean Aviation Services, Miami FL	3, 23.1.59 63/69 70 71/72 4.76/79
	N383B no another p E18S N513E no N513E no	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E N513E N513E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA Western Suburban Airways, Chicago IL Caribbean Aviation Services, Miami FL sale reported, Miami FL: USCR rdale FL 1.10.72; . 14.8.77 Caribbean Avtn;	3, 23.1.59 63/69 70 71/72 4.76/79 80/91
BA-398 BA-399	N383B nd another p E18S N513E nd	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E N513E N513E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA Western Suburban Airways, Chicago IL Caribbean Aviation Services, Miami FL sale reported, Miami FL: USCR rdale FL 1.10.72; . 14.8.77 Caribbean Avtn; built	3, 23.1.59 63/69 70 71/72 4.76/79 80/91 .58
	N383B no another p E18S N513E no N513E no	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E N513E N513E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.56 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA Western Suburban Airways, Chicago IL Caribbean Aviation Services, Miami FL sale reported, Miami FL: USCR rdale FL 1.10.72; . 14.8.77 Caribbean Avtn; built Goad Motor Co, San Antonio TX	3, 23.1.59 63/69 70 71/72 4.76/79 80/91 .58 63/64
	N383B no another p E18S N513E no N513E no	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E N513E N513E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.58 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA Western Suburban Airways, Chicago IL Caribbean Aviation Services, Miami FL sale reported, Miami FL: USCR rdale FL 1.10.72; . 14.8.77 Caribbean Avtn; built Goad Motor Co, San Antonio TX Blankenship Developments Inc, Lubbock TX	3, 23.1.59 63/69 70 71/72 4.76/79 80/91 .58 63/64 66/70
	N383B no another p E18S N513E no N513E no	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E N513E N513E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.56 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA Western Suburban Airways, Chicago IL Caribbean Aviation Services, Miami FL sale reported, Miami FL: USCR rdale FL 1.10.72; . 14.8.77 Caribbean Avtn; built Goad Motor Co, San Antonio TX Blankenship Developments Inc, Lubbock TX Land Marketing Inc, Lubbock TX	3, 23.1.59 63/69 70 71/72 4.76/79 80/91 .58 63/64 66/70 71/72
	N383B no another p E18S N513E no N513E no	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E N513E N513E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.56 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA Western Suburban Airways, Chicago IL Caribbean Aviation Services, Miami FL sale reported, Miami FL: USCR rdale FL 1.10.72; . 14.8.77 Caribbean Avtn; built Goad Motor Co, San Antonio TX Blankenship Developments Inc, Lubbock TX Land Marketing Inc, Lubbock TX Dorlaine A. Romain, Big Fork MT	3, 23.1.59 63/69 70 71/72 4.76/79 80/91 .58 63/64 66/70 71/72 8.5.78
	N383B no another p E18S N513E no N513E no	397 built 12.5 oted SW Aero blate: conv to - N510E N80D (2 N510E N513E N513E	Exchange Owasso OK 10.8.00 plate BA-397, built 12.56 9700 24.7.59, standing on wheels wings removed; Beech Aircraft Corp, Wichita KS: CofA issued Youngstown Airways/ Lease Air, Youngstown OH G. C. Murphy Co, McKeesport PA G. C. Murphy Co, McKeesport PA Western Suburban Airways, Chicago IL Caribbean Aviation Services, Miami FL sale reported, Miami FL: USCR rdale FL 1.10.72; . 14.8.77 Caribbean Avtn; built Goad Motor Co, San Antonio TX Blankenship Developments Inc, Lubbock TX Land Marketing Inc, Lubbock TX	3, 23.1.59 63/69 70 71/72 4.76/79 80/91 .58 63/64 66/70 71/72

BA-400	E18S	N686Q	H. L. Coble Construction Co, Greensboro NC Two 8 Co, Corpus Christi TX Johnson Flying Service, Missoula MT	.58/64 66/70 72/73
			Blackhawk Airways, Janesville WI Charles T. Madsen, Dutch Harbour AK	79 7.82
			Aleutian Air Ltd, Dutch Harbor AK & Juneau AK crashed destroyed after takeoff, Juneau AK	13.6.83/02 10.4.02

"Flying" 5.59 report: 400th Super 18 purchased by H.L.Coble Construction Co of Greensborough NC who already operated a Twin Bonanza. Delivery ex Beech factory by H.L.Coble, president of the industrial building company, also K.V.Brough Vice President of Greensboro-High Point Air Service (Beech dealers), Coble's chief pilot Roscoe E. Harris & company pilot James C. Lawson;

N686Q noted Missoula MT 21.7.73 JFS, red scheme; crash report 10.4.02: struck shallow water on tidal mud flats a half.

crash report 10.4.02: struck shallow water on tidal mud flats a half mile from Juneau Airport, sole occupant pilot killed: he was on a second trip carrying a full load of wooden roofing for a friend's remote lodge, aircraft was described by loaders as "completely full". Nose pitched up when airborne RWY 08 at about 200 ft and fell into mud flats;

BA-401	E18S	N5661D	built	.58
		N151G	Georgia Pacific Corp, Portland OR	63/70
			sold to Brazil	.68
		PT-DHI	CIA Amazonas Madeiras & Laminados	8.68
			Taxi Aereo Rondonia Ltda, Santarem	79
			Rico Taxi Aereo Ltda, Manaus	83
			Carlos Edo/ Extreme Demonstracoes Aereas Ltda,	
			Campinas-Amarais	99/16
			op: Esquadrilha Oi: formation team #4	02/16

PT-DHI noted Campinas-Amarais, Brazil 15.7.99 all red, in service with other aircraft of Extreme Demonstracoes Aereas, all in same red scheme; PT-DHI at airshow Itirapina Brazil 22.5.05 pseudo military scheme #4; PT-DHI at airshow Araras, Brazil 7.10.06 display scheme #4, flying, tailwheel; PT-DHI noted Amarais, Brazil .16 in hangar with display team T-6s;

BA-402	E18S -9700	N888X	Beech Aircraft Corp, Wichita KS: CofA issued (mods to E18S-9700 installed 1.5.59)	11.2.59
		N388W	Wyandotte Chemicals Corp, Wyandotte MI	63/64
		N737SW	Joseph E. Seagram & Sons Distillery Inc, New York NY	66/70
			James Barbitta & Associates, Akron OH	71/72
			Southernair Inc, Chattanooga TN	79
			Karl J. Wagner, Wichita KS	4.84
			Springdale Air Service, Springdale AR	10.85/86
			Robert A. Younkin, Lowell AR	5.91
			William P. Eckles, Oklahoma City OK	27.7.93/06
			(flew 02 in USAF markings)	
			TDP Inc, Wilmington DE	19.6.09/16
			forced landing on highway FL, no dam., flown out	2.4.13
			Aztec Worldwide Airlines Inc, Fort Lauderdale FL	18.7.16/19

N737SW noted Westchester County NY 6.70, tailwheel, no titles, owned Seagrams Whiskey; N737SW noted McAlester OK 5.8.02 plate BA-402 built 2.59, plate -9700 mods 1.5.59, painted in USAF scheme;

BA-403	E18S	N569BV	built	.59
	-9700		Besser Co, Alpena MI	63/66
			Buffalo Aeronautical Corp, Buffalo NY	69/83
			Crown Star Inc, Los Angeles CA	12.83
			Estel M. Blevins, Palm Harbour FL	10.85
			DCI Inc, Lutz FL	7.86
			sold to Canada: struck-off USCR	17.10.86
	C-GDRJ	Dean River Air Services Ltd, Nimpo Lake BC	17.11.89/91	
			White Bark Enterprises Ltd, Williams Lake BC	27.2.91
			Carson Air Ltd, Williams Lake BC	12.91/93
			Summit Air Charters Ltd, Atlin BC	3.93/95
			Enterprise Air Inc, Oshawa ONT	13.2.95/98

			sold to USA, struck-off Canadian Register	20.11.98		
		N1939K	Gus McLeod/ McLeod Kendall Inc, Dagsboro NE	11.98/03		
			(US CofA renewed 26.11.98)			
			James E. Slocum, Moscow TN	21.8.04/11		
			Crazy Woiman LLC, Tupelo MS	26.9.11/20		
	N569BV I	noted Muskoka	Y 27.8.74 bare metal; ONT 1.11.86; ONT 9.96 Enterprise Air;			
			ONT 6.98 Enterprise Air;			
			sh 8.99 titles "McLeod-Kendall Polar Expedition" & "G			
			DRJ" readable on port fin, "C-FDRJ" readable on starb	oard fin,		
	•	S-9700 BA-403				
		( at fly-in Oshko ( at fly-in Oshko	sh 30.7.03, sh 24.7.06 Jim & Val Slocum, up for sale;			
		at fly-in Lakelan				
			<i>Fullahoma TN 14.10.07;</i>			
			WI fly-in 28.7.14; 7.15, 7.16;			
BA-404	E18S	N187AA	built	.59		
		N157SC	Carmen Diorio, Philadelphia PA	63/67		
			crashed destroyed during landing, Millville NJ	7.6.67		
BA-405	E18S	N651Q	built	2.59		
57-400	L103		E. & J. Gallo Winery, Modesto CA	2.59 63/72		
			sale reported: USCR	79		
			Mountain Skyways Inc, Kalispell MT	2.84		
			Southwest Airlift Inc, El Paso TX	4.85		
			Robert A. Younkin, Lowell AR	10.86		
			sold to Canada: struck-off USCR	1.10.86		
		C-GJEO	Leuenberger Air Services Ltd, Nakina ONT	5.11.86/88		
			Air 500 Ltd, Toronto ONT	8.88/92		
			sold to USA: struck-off Canadian Register	25.8.92		
		N651Q	Express Air Inc, Greenville SC	14.9.92/94		
			Earl V. Long, Wichita KS Blue Ridge Aviation	.94/95 3.1.95		
			sold to Canada, struck-off USCR	17.4.95		
		C-GJEO	936430 Ontario Ltd, Woodstock ONT	3.5.95/96		
		0 0020	Samaritan Air Service Ltd, Toronto ONT	6.3.96/01		
			struck-off Register	3.6.01		
			Stevenson Aviation, Portage MAN	18		
			(outer wings removed, instructional airframe, titles			
			"Stevenson Aviation & Aerospace Training Centre")			
	C-GJEO noted Toronto 20.11.91 "Air 500" titles, tailwheel;					
		noted Toronto 2 noted Toronto 6				
	Reg canc	elled by DoT 3.	6.01 due mail returned as undeliverable address;			
		uthport Airport, 105 built 2.59;	Portage MAN 8.18: C-GJEO inst airframe, outer wings	removed;		
		-	bu ili	FO		
BA-406	E18S	N188AA N2700S (1	built rereg	.59		
		N149AA (2	•	63/70		
		(-	Joseph Fontana, Kingsford MI	71/72		
			Astro Airways, Pine Bluff AR	74		
			damaged when landed gear-up, Laredo TX	30.4.74		
			Semo Aviation/ Semo Airways, Malden MO	79/85		
			Semo Aviation/ Semo Airways, Malden MO Springdale Air Service, Springdale AR	10.85/86		
			Semo Aviation/ Semo Airways, Malden MO			

N149AA accident report 30.4.74: Astro Airways, pilot failed to extend gear, flight to Laredo from Torreon, Mexico, 2 crew unhurt, 3pm;

BA-407	E18S	N5657D (2	built Airlease Corp, San Francisco CA Cooper Tire & Rubber Co, Findlay OH Lee R. Griffith, Lake Dallas TX missing after departure Dallas TX: not found	.59 63/70 71/72 15.10.75 28.10.75
BA-408	E18S -9700	N5663D(1 N952 (1 N952F N405JB N405JR	built Colorado Interstate Gas Co, Colorado Springs CO damaged landing, San Lucas-Hotel Carbo, Mexico S. F. Bracamonte, San Diego CA S. F. Bracamonte, San Diego CA National Air Freight Herbert A. Garms, Smith NV Bob Andrews, Fort Lauderdale FL	.59 63/64 24.2.65 66 69/72 75 78 24.1.79/91

N405JB noted San Diego CA 9.4.72, no titles

N405JR noted Hayward CA 19.9.75 "National Air Freight" titles, tailwheel;

BA-409	E18S	CF-LFT	built	.59
		CF-PER	Majestic Contractors Ltd, Toronto ONT	63
			Northern Telephone Ltd, New Liskeard ONT	65/70
			Air Niagara Ltd, St Catharines ONT	72/74
			White River Air Services	.74
		C-FPER	Air Niagara Ltd, Toronto-Malton ONT	79/83
			damaged accident, Ottawa ONT (repaired)	13.2.79
			struck-off Register	8.83
			Centennial College, Scarborough ONT: inst. airframe	02
			National Air Force Museum of Canada, Trenton AB ONT	18/19

CF-PER photo 10.63, tailwheel;

CF-PER noted Toronto-Malton 8.10.81 in service, no titles, tailwheel;

CF-PER noted 3.02 inside Centennial College hangar at Scarborough ONT, cockpit

complete with all instrumentation;

BA-410	E18S	N387B	built	.59
			Waukesha Motor Co, Waukesha WI	63/66
			Hartzog-Schneck Aviation, Rockford IL	69
			Batvin Aviation Corp, Genoa City WI	70
			Air Charter Inc, Janesville WI	71/72
			Morey Wyman/ Wyman Pilot Service, Pontiac MI	8.3.73
			crashed destroyed on takeoff, Corapolis PA	7.12.73

N387B accident report 7.12.73: Morey L. Wyman, flight Corapolis-Pontiac MI, pilot took intersection departure, stalled after takeoff 3.33am, fire after impact, 2 k;

BA-411	E18S	N197A N197AA	Beech Aircraft Corp, Wichita KS: CofA issued rereg	26.3.59
		N197AA N197G	Automatic Air Service, Camden NJ COAD Inc, Woodcrest NJ Delta Casualty Co, Chicago IL P. Brooks Construction Co, Ruskin FL (noted Barranquilla Colombia 4.82 in compound of impounded drug running aircraft) (to FA Colombiana as FAC 564)	63/64 66 69/72 20.4.78

N197G noted Chicago-O'Hare 30.9.71;

noted Barranquilla Čolombia 4.82 in compound of impounded drug running aircraft: registration obscured, "N1.7G" readable": almost certainly this aircraft;

BA-412	E18S	N5000T (1	reg	.59
		N5000U	Kinzua Corp, Kinzua OR	63/66
			Flightcraft Inc, Portland OR	69/70
			Lewis Enterprises Inc, Portland OR	71/72
			State Forestry Department, Salem OR	78

CF-PER noted Montreal-Droval 10.67 visitor, private;

Providence Air Charter, Providence RI	10.78/79
James A. Dole, Coventry RI	21.8.78/79
op: Providence Air Charter, Providence RI	79
crashed destroyed landing, Stewart AFB NY	4.4.79
	James A. Dole, Coventry RI op: Providence Air Charter, Providence RI

N5000U noted Portland OR 27.4.72; N149PA accident report 4.4.79: Providence Air Charter, cargo flight Boston to Stewart AFB, Newburg NY, stalled in go-around, ice on airframe, 11.15pm, pilot serious injuries;

DA 440	E100		Booch Aircraft Corp. Michite KS: CafA issued	0 1 50
BA-413	E18S -9700	N5001T (2	Beech Aircraft Corp, Wichita KS: CofA issued Thiokol Chemical Corp, Brigham City UT	9.4.59 31.8.61
	-3700		Compax Corp, San Antonio TX	66/79
			Larry Johnson	80
			William R. Sandlin/ Sandlin Flying Service, Harlingen TX	
		XB-CFQ		20.3.00
		N5001T	Allen J. K. Devine, Tijuana	-
			William R. Sandlin/ Sandlin Flying Service, Harlingen TX	
		(N616T)	ntu: William R. Sandlin, Harlingen TX	10.88
		N5001T	William R. Sandlin, Harlingen TX	10.88
		N7765N	William R.Sandlin, Evant TX	12.88/95
			May Air Xpress, New Boston TX	31.3.95/02
			Scott Glover, Mt Pleasant TX	.02/03
			Thro Aviation, Bohemia NY	7.03
			(departed Mt Pleasant TX on delivery to NY 31.7.03)	
			North American Leasing LLC, Fort Myers FL	12.7.04/19
			reg expired, struck-off USCR	9.1.19
		noto at Housto states: aircrat	n TX 12.83; t logbook makes no mention of XB-CFQ but there is a gap	in the records
	he assume	s that was the	8.80 until 10.84 when a number of STCs were carried out o period reregistered in Mexico;	
	Mexican re	gister 93 quot	es XB-CFQ Allen Devine, Tijuana - presumed not yet dele	ted;
	N7765N no			
	N7765N no N7765N no to passeng N7765N at	oted Texarkan oted Texarkan er interior; fly-in Oshkosi	a AR 16.8.99 parked outside May Air Xpress hangar engin a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59;	
	N7765N no N7765N no to passeng N7765N at	oted Texarkan oted Texarkan er interior; fly-in Oshkosi	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s	
BA-414	N7765N no N7765N no to passeng N7765N at	oted Texarkan oted Texarkan er interior; fly-in Oshkosi	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59;	
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built	ilver and restored
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN	.59
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN	.59 63/64 66
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN	.59 63/64
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA	.59 63/64 66 69/72
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S N149R	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as Hamilton Westwind III tailgear 10.72)	.59 63/64 66 69/72 72/85
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S N149R	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as Hamilton Westwind III tailgear 10.72) North Continent Airlines, Long Beach CA: Isd.	.59 63/64 66 69/72 72/85 85/86
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S N149R	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as Hamilton Westwind III tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE	.59 63/64 66 69/72 72/85 85/86 8.86
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S N149R	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd	.59 63/64 66 69/72 72/85 85/86 8.86 87
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S N149R	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as Hamilton Westwind III tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE	.59 63/64 66 69/72 72/85 85/86 8.86
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I	oted Texarkan oted Texarkan er interior; fly-in Oshkos oted Naples Fl N149S N149R II	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd	.59 63/64 66 69/72 72/85 85/86 8.86 87
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note	eted Texarkan oted Texarkan er interior; fly-in Oshkos oted Naples Fl N149S N149R II II tes N149R as ed Burbank C	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III;	.59 63/64 66 69/72 72/85 85/86 8.86 87
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note N149R note	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149R N149R II II etes N149R as ed Burbank C ed Tucson AZ	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind;	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I Westwind I USCR quot N149R note N149R note "N148R" not	ated Texarkan beted Texarkan er interior; fly-in Oshkos beted Naples Fl N149S N149R II II tes N149R as ed Burbank C. ed Tucson AZ beted Muskoge	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; - 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind; 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines;	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note N149R note N149R note N149R note	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S N149R II II II et S N149R as ed Burbank C, ed Tucson AZ oted Muskoge ed Columbus	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind; ' 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines; e OK 2.3.73 at SMB maintenance base, turbines: must be OH 10.8.74 PT6As tailwheel, "SMB Stage Lines";	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87
BA-414	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note N149R note N149R note N149R note N149R note	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S N149R II II II II II tes N149R as ed Burbank C ed Tucson AZ oted Muskoge ed Columbus ed Phoenix AZ	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind; ' 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines; e OK 2.3.73 at SMB maintenance base, turbines: must be	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87
	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note N149R note N149R note N149R note accident re	eted Texarkan oted Texarkan er interior; fly-in Oshkos oted Naples Fl N149S N149R II II II II tes N149R as ed Burbank C. ed Tucson AZ oted Muskoge ed Columbus ed Phoenix AZ port 18.2.87: /	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind; 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines; e OK 2.3.73 at SMB maintenance base, turbines: must be OH 10.8.74 PT6As tailwheel, "SMB Stage Lines"; Z 23.8.85 turbines, radio callsign "North Continent 500"; Active Aero Charter;	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87 <i>N149R;</i>
BA-414 BA-415	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note N149R note N149R note A149R note accident re E18S	oted Texarkan oted Texarkan er interior; fly-in Oshkosi oted Naples Fl N149S N149R II II II II II tes N149R as ed Burbank C ed Tucson AZ oted Muskoge ed Columbus ed Phoenix AZ	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind; 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines; e OK 2.3.73 at SMB maintenance base, turbines: must be OH 10.8.74 PT6As tailwheel, "SMB Stage Lines"; Z 23.8.85 turbines, radio callsign "North Continent 500"; Active Aero Charter; Beech Aircraft Corp, Wichita KS: CofA issued	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87 <i>N149R</i> ; 9.4.59
	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note N149R note N149R note N149R note accident re	eted Texarkan oted Texarkan er interior; fly-in Oshkos oted Naples Fl N149S N149R II II II II tes N149R as ed Burbank C. ed Tucson AZ oted Muskoge ed Columbus ed Phoenix AZ port 18.2.87: /	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind; 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines; e OK 2.3.73 at SMB maintenance base, turbines: must be OH 10.8.74 PT6As tailwheel, "SMB Stage Lines"; Z 23.8.85 turbines, radio callsign "North Continent 500"; Active Aero Charter; Beech Aircraft Corp, Wichita KS: CofA issued Kerr McGee Oil Industries, Oklahoma City OK	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87 <i>N149R</i> ; 9.4.59 63/64
	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note N149R note N149R note A149R note accident re E18S	oted Texarkan oted Texarkan er interior; fly-in Oshkoso oted Naples Fl N149S N149R II II II tes N149R as ed Burbank C. ed Tucson AZ oted Muskoge ed Columbus ed Phoenix AZ port 18.2.87: /	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind; 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines; e OK 2.3.73 at SMB maintenance base, turbines: must be OH 10.8.74 PT6As tailwheel, "SMB Stage Lines"; Z 23.8.85 turbines, radio callsign "North Continent 500"; Active Aero Charter; Beech Aircraft Corp, Wichita KS: CofA issued Kerr McGee Oil Industries, Oklahoma City OK Equitable Leasing Corp, Ashville NC	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87 <i>N149R;</i> 9.4.59 63/64 66
	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note N149R note N149R note A149R note accident re E18S	eted Texarkan oted Texarkan er interior; fly-in Oshkos oted Naples Fl N149S N149R II II II II tes N149R as ed Burbank C. ed Tucson AZ oted Muskoge ed Columbus ed Phoenix AZ port 18.2.87: /	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind; 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines; e OK 2.3.73 at SMB maintenance base, turbines: must be OH 10.8.74 PT6As tailwheel, "SMB Stage Lines"; Z 23.8.85 turbines, radio callsign "North Continent 500"; Active Aero Charter; Beech Aircraft Corp, Wichita KS: CofA issued Kerr McGee Oil Industries, Oklahoma City OK Equitable Leasing Corp, Ashville NC	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87 <i>N149R;</i> 9.4.59 63/64 66 68/70
	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note N149R note N149R note A149R note accident re E18S	oted Texarkan oted Texarkan er interior; fly-in Oshkoso oted Naples Fl N149S N149R II II tes N149R as ed Burbank C. ed Tucson AZ oted Muskoge ed Columbus ed Phoenix AZ port 18.2.87: / N1700 N1707H	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind; 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines; e OK 2.3.73 at SMB maintenance base, turbines: must be OH 10.8.74 PT6As tailwheel, "SMB Stage Lines"; Z 23.8.85 turbines, radio callsign "North Continent 500"; Active Aero Charter; Beech Aircraft Corp, Wichita KS: CofA issued Kerr McGee Oil Industries, Oklahoma City OK Equitable Leasing Corp, Ashville NC Equitable Leasing Corp, Ashville NC equitable Leasing Corp, Ashville NC	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87 <i>N149R;</i> 9.4.59 63/64 66 68/70 68/69
	N7765N no N7765N no to passeng N7765N at N7765N no E18S Hamilton Westwind I USCR quot N149R note N149R note N149R note A149R note accident re E18S	oted Texarkan oted Texarkan er interior; fly-in Oshkoso oted Naples Fl N149S N149R II II II tes N149R as ed Burbank C. ed Tucson AZ oted Muskoge ed Columbus ed Phoenix AZ port 18.2.87: /	a AR 2.8.02 plate BA-413 3.59, May Air Express, now all s h 7.05, plate BA-413 built 3.59; L 17.9.06 civil scheme, tailwheel in service; built Northwestern Refining Co, St Paul MN Admiral Merchants Motor Freight Inc, St Paul MN Gopher Aviation, Flying Cloud Airport MN SMB Stage Line Inc, Des Moines IA (rebuilt as <i>Hamilton Westwind III</i> tailgear 10.72) North Continent Airlines, Long Beach CA: Isd. Ajax Aircraft Leasing Inc, Dover DE Active Aero Charter: Isd crashed destroyed after takeoff, Quincy IL first reg; FAA file confirms mod to Westwind III; A 2.11.72 Westwind; 3.4.72 at Hamilton Aircdraft ramp, Westwind III turbines; e OK 2.3.73 at SMB maintenance base, turbines: must be OH 10.8.74 PT6As tailwheel, "SMB Stage Lines"; Z 23.8.85 turbines, radio callsign "North Continent 500"; Active Aero Charter; Beech Aircraft Corp, Wichita KS: CofA issued Kerr McGee Oil Industries, Oklahoma City OK Equitable Leasing Corp, Ashville NC	.59 63/64 66 69/72 72/85 85/86 8.86 87 18.2.87 <i>N149R;</i> 9.4.59 63/64 66 68/70

			Isd: Dolphin Airways Leon B. Canady, Starke FL R. D. McSwiggan, Griffin GA Tol Air Inc, San Juan, Puerto Rico sale reported, San Juan, Puerto Rico: USCR (noted retired at Tolair ramp, San Juan PR 6.00) struck-off USCR	82 6.85 17.7.86/99 00 01/12 19.7.12
	N1707H r N30TD nc N30TD nc	noted Opa Loc oted Griffin GA oted Griffin GA	- 8.10.68 trigear "Gold Coast Airlines", ka FL 28.9.70 trigear; 26.6.96 trigear freighter; 12.96 op Academy Airlines; PR 16.6.00 at Tolair ramp, not operational;	
BA-416	E18S -9700	N5668D	Beech Aircraft Corp, Wichita KS: CofA issued Owensboro Aviation, Owensboro KY George H. Bailey Leasing Corp, Fort Wayne IN Finn Industries Division, Chicago IL ran off runway landing, hit two parked aircraft, Anchorage-Merrill Field AK Dale Jackson, Anchorage AK Gordon Aviation/ Gordon Air Express, Anchorage AK Billy A. Robbins, Calabasas CA op: Jordan Air Express California Associates Ltd, Oakdale CA Tom Neal, Rancho Mirage CA Fred J. Willert, Chula Vista CA	16.4.59 63 64/69 70/72 14.6.77 79 12.81/84 7.86/99 93 7.5.99 28.2.00/02 23.12.03/20
	N5668D r N5668D r N5668D r painted ov N5668D r plate BA-4	noted Anchora noted Lancaste noted San Dieg ver, operates r noted San Dieg 416;	Meigs Field OH 23.7.71; ge-Merrill Field 15.9.79 windowless freighter, in service; er-Fox CA 22.9.85; go-Montgomery Field CA 3.93, tailwheel, "Gordon Air Expre night freight flights; go-Montgomery Field CA 12.93, retired outside, Jordan Air A 16.8.00 under maintenance, cargo door being removed;	
BA-417	E18S	N5675D N675D	built Anderson Bros Manufacturing Co, Rockford IL Anderson Bros Manufacturing Co, Rockford IL Brennan Cattle Co, Kirkland IL Hamilton Aviation, Hamilton OH Bentley Flight Service, Detroit MI John J. Murphy, Pontiac-Oakland MI struck-off USCR	.59 63/64 66/70 71/72 73 79 17.7.79/87 1.87
	N675D nc	oted Rockford	IL 23.7.71;	
BA-418	E18S -9700	N666X	built Braymont Inc, Syracuse NY S & B Flite Inc, Baldwinsville NY Merrimack Airlines Corp, Bedford MA D&C Leasing Corp, Lawrence MA Providence Air Charter, Providence RI damaged ground-loop taxying for takeoff, Columbus IN Rhoades International, Seymour IN Roy D. Hartley, Parma Heights OH struck-off USCR	19.2.59 63/69 70/72 78 79 80 30.8.80 80 21.10.81/95 17.4.95
	N666X nc	oted Syracuse	NY 27.8.74;	
BA-419	E18S	N5663D (2	Beech Aircraft Corp, Wichita KS: CofA issued	29.4.59

BA-419	E18S	N5663D (2	Beech Aircraft Corp, Wichita KS: CofA issued	29.4.59
	-9700	N390V	Victor Adding Machine Co, Chicago IL	64
			Cherokee Village Development Co, Cherokee Village AR	66
			SMB Stage Line Inc, Des Moines IA	69/77
			Precision Valley Aviation, Springfield VT	78/84

	N390V no N390V no N390V no N390V ba N390V no N390V no (not sighte	oted Dallas-Lov oted Springfield oted Memophis osed Memphis oted Olive Bran oted Olive Bran	Rockingham Aviation Corp/ K&K Aircraft, Bridgewater V (converted for aerial application, 350 gallon cabin chemical tank installed for gipsy moth and mosquito spraying contracts) Darlene Gilding, Memphis TN Beech of Dreams Inc, Wilmington DE Skyranch Aviation, Alma AR Gryder Netyworks LLC, Griffin GA Pinion Air Service, Great Falls MT O'Hare 24.2.69 SMB Stage Lines; re TX 10.4.73 SMB Stage Lines; IVT 7.10.80, tailwheel, in service; TN 2.95, no titles, tailwheel; TN 8.98 as locally based freighter; ch MS 31.7.02 plate BA-419 built 4.59, plate -9600 mods; ch MS 5.8.03, freighter, for sale; nch MS 8.05 by GR but told it was still on the field) 1.8.08;	24.1.86/05 16.11.05/07 13.11.08/17 9.5.17/18 7.10.19/20
BA-420	E18S	N112L	built	.59
	-9700		Southland Paper Mills Inc, Lufkin TX	63/69 70/72
		HH-PRO	registration pending: USCR reg	70/72
		N112L	reg	
			Roy E. Amos, Fort Myers Beach FL	7.82
			David Fernandez Alvarado, St Croix USVI	9.83
			Luis E. Hernandez, Rio Piedras, Puerto Rico Abigail F. Lopez, Rio Pedras, Puerto Rico	2.85 3.88/92
			US Customs: impounded, stored Homestead AFB FL	92
			destroyed Homestead AFB FL by Hurricane Andrew	9.92
<b>DA</b> 404	N112L noi N112L noi	ted Miami FL 4 ted Ft Lauderc	lale International FL 2.90;	50
BA-421	E18S -9700	N665Q N665M	built Alamo Aviation, San Antonio TX	.59 63/64
	-3700	NOOSIM	H. B. Zachry Corp, San Antonio TX	66/69
			Midwest Airways, Milwaukee WI	70/72
			Semo Aviation, Malden MO	79
			Marian E. Riner, Mullsboro DE	0 0 0 / 0 1
				8.83/91
			Jim West/ Skydive Greene County Inc, Xenia OH	27.1.92/13
			Jim West/ Skydive Greene County Inc, Xenia OH crashed after takeoff Xenia OH	27.1.92/13
	N665M nc N665M nc N665M nc	oted Green Co oted Xenia OH	Jim West/ Skydive Greene County Inc, Xenia OH crashed after takeoff Xenia OH (stored at owner's farm, Xenia OH 05) struck-off USCR	27.1.92/13 1.5.93 6.5.13 Iwheel; E18S-9700;
BA-422	N665M nc N665M nc N665M nc	oted Xenia-Gre oted Green Co oted Xenia OH	Jim West/ Skydive Greene County Inc, Xenia OH crashed after takeoff Xenia OH (stored at owner's farm, Xenia OH 05) struck-off USCR 40 2.6.75; ten County OH 3.92, Skydive Greene County, no titles, tai unty OH 6.8.99 Skydive, engines removed, plate: BA-421 1.8.05 stored outside at Jim West's farm near airfield, win	27.1.92/13 1.5.93 6.5.13 Iwheel; E18S-9700;
BA-422	N665M nd N665M nd N665M nd titles "Sky	oted Xenia-Gre oted Green Co oted Xenia OH dive Greene C N5696D	Jim West/ Skydive Greene County Inc, Xenia OH crashed after takeoff Xenia OH (stored at owner's farm, Xenia OH 05) struck-off USCR 40 2.6.75; ten County OH 3.92, Skydive Greene County, no titles, tai unty OH 6.8.99 Skydive, engines removed, plate: BA-421 1.8.05 stored outside at Jim West's farm near airfield, win county", being used for spares, plate E18S-9700; built North American Van Lines Inc, Fort Wayne IN	27.1.92/13 1.5.93 6.5.13 Iwheel; E18S-9700; gs removed 5.59 63/68
BA-422	N665M nc N665M nc N665M nc titles "Sky	oted Xenia-Gre oted Green Co oted Xenia OH dive Greene C N5696D	Jim West/ Skydive Greene County Inc, Xenia OH crashed after takeoff Xenia OH (stored at owner's farm, Xenia OH 05) struck-off USCR 40 2.6.75; sen County OH 3.92, Skydive Greene County, no titles, tai unty OH 6.8.99 Skydive, engines removed, plate: BA-421 1.8.05 stored outside at Jim West's farm near airfield, win county", being used for spares, plate E18S-9700; built North American Van Lines Inc, Fort Wayne IN Mid Continent Airlines, Morris IL	27.1.92/13 1.5.93 6.5.13 Iwheel; E18S-9700; gs removed 5.59 63/68 69/70
BA-422	N665M nd N665M nd N665M nd titles "Sky	oted Xenia-Gre oted Green Co oted Xenia OH dive Greene C N5696D	Jim West/ Skydive Greene County Inc, Xenia OH crashed after takeoff Xenia OH (stored at owner's farm, Xenia OH 05) struck-off USCR 40 2.6.75; ten County OH 3.92, Skydive Greene County, no titles, tai unty OH 6.8.99 Skydive, engines removed, plate: BA-421 1.8.05 stored outside at Jim West's farm near airfield, win county", being used for spares, plate E18S-9700; built North American Van Lines Inc, Fort Wayne IN Mid Continent Airlines, Morris IL Blackhawk Airways, Janesville WI	27.1.92/13 1.5.93 6.5.13 Iwheel; E18S-9700; gs removed 5.59 63/68
BA-422	N665M nd N665M nd N665M nd titles "Sky	oted Xenia-Gre oted Green Co oted Xenia OH dive Greene C N5696D	Jim West/ Skydive Greene County Inc, Xenia OH crashed after takeoff Xenia OH (stored at owner's farm, Xenia OH 05) struck-off USCR 40 2.6.75; een County OH 3.92, Skydive Greene County, no titles, tai unty OH 6.8.99 Skydive, engines removed, plate: BA-421 1.8.05 stored outside at Jim West's farm near airfield, win county", being used for spares, plate E18S-9700; built North American Van Lines Inc, Fort Wayne IN Mid Continent Airlines, Morris IL Blackhawk Airways, Janesville WI (purchased in damaged condition, G18S cab removed	27.1.92/13 1.5.93 6.5.13 Iwheel; E18S-9700; gs removed 5.59 63/68 69/70
BA-422	N665M nd N665M nd N665M nd titles "Sky	oted Xenia-Gre oted Green Co oted Xenia OH dive Greene C N5696D	Jim West/ Skydive Greene County Inc, Xenia OH crashed after takeoff Xenia OH (stored at owner's farm, Xenia OH 05) struck-off USCR 40 2.6.75; ten County OH 3.92, Skydive Greene County, no titles, tai unty OH 6.8.99 Skydive, engines removed, plate: BA-421 1.8.05 stored outside at Jim West's farm near airfield, win county", being used for spares, plate E18S-9700; built North American Van Lines Inc, Fort Wayne IN Mid Continent Airlines, Morris IL Blackhawk Airways, Janesville WI	27.1.92/13 1.5.93 6.5.13 Iwheel; E18S-9700; gs removed 5.59 63/68 69/70
BA-422	N665M nd N665M nd N665M nd titles "Sky	oted Xenia-Gre oted Green Co oted Xenia OH dive Greene C N5696D	Jim West/ Skydive Greene County Inc, Xenia OH crashed after takeoff Xenia OH (stored at owner's farm, Xenia OH 05) struck-off USCR 40 2.6.75; ten County OH 3.92, Skydive Greene County, no titles, tai unty OH 6.8.99 Skydive, engines removed, plate: BA-421 1.8.05 stored outside at Jim West's farm near airfield, win county", being used for spares, plate E18S-9700; built North American Van Lines Inc, Fort Wayne IN Mid Continent Airlines, Morris IL Blackhawk Airways, Janesville WI (purchased in damaged condition, G18S cab removed and installed in Blackhawk's N166H)	27.1.92/13 1.5.93 6.5.13 <i>lwheel;</i> E18S-9700; rgs removed 5.59 63/68 69/70 26.9.77/79

BA-423	E18S	N954 (1 N954F	Colorado Interstate Gas Co, Colorado Springs CO rereg	.59/64
		N1814	National Finance Inc, Wilmington DE	66
			Rambar Aviation, Parkersburg WV	69/70
			struck ILS antennae landing, Detroit-City MI	17.6.70
			Dobbelaere Aviation, Oakwood OH	4.1.71/74
			struck-off USCR	25.7.74

N1814 accident report 17.6.70: Rambar Aviation, windshift during landing in thunderstorm on wet runway, ran off runway, 5 unhurt;

BA-424	E18S	N2067C	Beech Aircraft Corp, Wichita KS: CofA issued	13.5.59
			nacelle fire after JATO firing, landed safely, St Paul MN	5.12.60
			Waldorf Paper Products Co, St Paul MN	63/64
			Lease Air Inc, San Diego-Montgomery Field CA	69/72
			located damaged abandoned, stolen, California	4.4.78
			Aerospace Products Inc, North Hollywood CA	79
			Wyman Pilot Service, Pontiac MI	82/84
			Northern Airmotive Corp, Kenosha WI, later Hillsboro OH	
			crashed destroyed on takeoff, Fayette County OH	10.10.00
		noted Oakland noted Oakland		
			MI 9.80, plate BA-424;	
			own OH 16.6.82 Wyman Pilot Service;	
			gton Court House-Fayette County OH 8.99 with Northern Ai	
			p Northern Airmotive Corp, crashed immediately after taked	
	Washingto	on Court Hous	e-Fayette County OH on positioning flight to Airborne Airpa	rk, Wilmington
OH,	-		off and exploded, P&W R985s pilot was owner of company,	killed:
	he had 17	,000 hours on	Beech 18s;	
BA-425	E18S	N75SF	J. P. Stevens & Co, New York NY	.59/64
		N75S	rereg	
		N1157S	rereg	
		N7581	First Federal Savings & Loan, Raleigh NC	69/70
			B J Aero Freight Inc, Oskaloosa IA	7.1.74/75
			crashed destroyed landing, Rockford IL	2.1.75
	tailwheel, Published N7581 no	all owned J.P. USCR66: not ted Houston-H	73SF, N74SF, N75SF & N176SF in row at Wallace NC 4.61 Stevens & Co; listed under any of the regs; lobby TX 6.5.73; 3J Aero Freight, mail flight Ottumwa IA to Rockford, airframe	
	tailwheel, Published N7581 no accident r	all owned J.P. USCR66: not ted Houston-H	Stevens & Co; listed under any of the regs;	
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built	e ice, .59
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; 3J Aero Freight, mail flight Ottumwa IA to Rockford, airframe	e ice,
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg	e ice, .59 63/64
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL	e ice, .59 63/64 66/72
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY	e ice, .59 63/64 66/72 28.2.75
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K N932R	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR	e ice, .59 63/64 66/72 28.2.75 28.3.75
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR Aero Sur Ltda, Cochabamba	e ice, .59 63/64 66/72 28.2.75 28.3.75 .75/78
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K N932R	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR	e ice, .59 63/64 66/72 28.2.75 28.3.75
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K N932R	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR Aero Sur Ltda, Cochabamba	e ice, .59 63/64 66/72 28.2.75 28.3.75 .75/78
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K N932R	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR Aero Sur Ltda, Cochabamba op: Taxi Aerosur, Cochabamba	e ice, .59 63/64 66/72 28.2.75 28.3.75 .75/78 76/78
BA-426	tailwheel, Published N7581 no accident r stalled in t	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K N932R	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR Aero Sur Ltda, Cochabamba op: Taxi Aerosur, Cochabamba Aerovias Balcazar - AEROBAL, Cochabamba	e ice, .59 63/64 66/72 28.2.75 28.3.75 .75/78 76/78
BA-426	tailwheel, Published N7581 no accident r stalled in t E18S -9700	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K N932R CP-1197	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR Aero Sur Ltda, Cochabamba op: Taxi Aerosur, Cochabamba Aerovias Balcazar - AEROBAL, Cochabamba Aerobal Machanics School, Cochabamba:	e ice, .59 63/64 66/72 28.2.75 28.3.75 .75/78 76/78 85/86
BA-426	tailwheel, Published N7581 no accident r stalled in t E18S -9700 N932R no CP-1197 n	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K N932R CP-1197 CP-1197	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; BJ Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR Aero Sur Ltda, Cochabamba op: Taxi Aerosur, Cochabamba Aerovias Balcazar - AEROBAL, Cochabamba Aerobal Machanics School, Cochabamba: ground instructional airframe	.59 63/64 66/72 28.2.75 28.3.75 .75/78 76/78 85/86 85
BA-426	tailwheel, Published N7581 no accident r stalled in t E18S -9700 N932R no CP-1197 n CP-1197 n	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K N932R CP-1197 oted San Antor noted Cochaba noted Cochaba	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; 3J Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR Aero Sur Ltda, Cochabamba op: Taxi Aerosur, Cochabamba Aerovias Balcazar - AEROBAL, Cochabamba Aerobal Machanics School, Cochabamba: ground instructional airframe nio TX 16.5.73; amba 26.9.78 "Taxi Aerosur" titles; amba 1.5.85 in use as instructional airframe at Aerobal medi	e ice, .59 63/64 66/72 28.2.75 28.3.75 .75/78 76/78 85/86 85
	tailwheel, Published N7581 no accident r stalled in t E18S -9700 N932R no CP-1197 n CP-1197 n E18S	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K N932R CP-1197 CP-1197	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; 3J Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR Aero Sur Ltda, Cochabamba op: Taxi Aerosur, Cochabamba Aerovias Balcazar - AEROBAL, Cochabamba Aerobal Machanics School, Cochabamba: ground instructional airframe hio TX 16.5.73; amba 26.9.78 "Taxi Aerosur" titles; amba 1.5.85 in use as instructional airframe at Aerobal medic built	e ice, .59 63/64 66/72 28.2.75 28.3.75 .75/78 76/78 85/86 85 85 echanics school; .59
BA-426 BA-427	tailwheel, Published N7581 no accident r stalled in t E18S -9700 N932R no CP-1197 n CP-1197 n	all owned J.P. USCR66: not ted Houston-H eport 2.1.75: E the circuit; N1905L N1905K N932R CP-1197 oted San Antor noted Cochaba noted Cochaba	Stevens & Co; listed under any of the regs; lobby TX 6.5.73; 3J Aero Freight, mail flight Ottumwa IA to Rockford, airframe built Special Services Corp, Greenville SC rereg Rust Engineering Corp, Birmingham AL Compass Aviation Ltd, Farmingdale NY sold to Bolivia, struck-off USCR Aero Sur Ltda, Cochabamba op: Taxi Aerosur, Cochabamba Aerovias Balcazar - AEROBAL, Cochabamba Aerobal Machanics School, Cochabamba: ground instructional airframe nio TX 16.5.73; amba 26.9.78 "Taxi Aerosur" titles; amba 1.5.85 in use as instructional airframe at Aerobal medi	e ice, .59 63/64 66/72 28.2.75 28.3.75 .75/78 76/78 85/86 85

	N9000M	Skagit Corp, Sedro Woolley WA	68/70
		(US CofA renewed 13.6.68)	
		CSC Leasing Co, Seattle WA	71/72
		Stockert Flying Service, South Bend IN	79/81
		(operated as STS Freightliner 79)	
Hamilton		Florida Airmotive Inc, Lantana-Palm Beach FL	4.81/84
Extended	N171LG (2	Florida Airmotive Inc, Lantana-Palm Beach FL	2.84/86
Nose		Florida Caribair Inc, Boynton Beach FL	91
		US Dept of Justice, Arlington VA	5.93
		Caribbean Leasing Corp, Orlando FL	14.9.93/95
		op: Avmac Air	95
		ditched in sea due in-flight fire, en route Orlando FL to	
		Freeport, Bahamas	28.8.95

N9000M noted Seattle-Boeing Field WA 29.4.72 "Pacific Land Associates" titles; N9000M noted Oshawa ONT 20.4.79 "Stockert FS Freightliner"; N9000M noted Detroit Metropolitan-Wayne County 4.79 tailwheel "STS Freightliner"; N9000M noted Lantana FL 16.3.81 "SFS Freightliner";

BA-428	E18S	N379B	built	.59
0/1-420	-9700	1107 30	Kawneer Co, Niles MI	.59 63
	-9700		American Metal Climax Inc, Niles MI	64/66
			Patrick Plywood Enterprises Inc, Elkhart IN	69
			Patrick Industries Inc, Elkhart IN	72
		CF-WDV	Millardair Ltd. Toronto-Malton ONT	7.73/78
			Millardair Ltd, Toronto-Malton ONT	78/93
		C-FWDV		
		NIZOCOLI	sold to USA: struck-off Canadian Register	5.93
		N7058U	Casablanca Air Transport, New York NY	20.5.93
			Classic Air Transport Inc, Ridgewood NJ	1.94
			Ronald P. Wayner, White River, South Africa	2.3.94/95
	Hamilton		(dep. Lanseria for relief work in Rwanda 6.94)	
	extended		op: Mercy Air South Africa	94/10
	nose		exported to South Africa, struck-off USCR	17.4.95
		ZS-OIJ	Nelair Pty Ltd, White River	10.98
			Bateleur Air, Namibia	.10
			Filippie Vermeulen/ Springbok Classic Air	15/18
			(stranded at Soussusvlei, flown out .13 by Verneulen)	
			(flies 16 polished metal, Hamilton extended nose kit)	
	C-FWDV n N7058U fle N7058U nc N7058U nc	oted Toronto oted Toronto w Quelimane oted Witrivier, oted airshow I	ONT 25.8.74 "Millardair"; ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; -Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96;	
	C-FWDV n N7058U fle N7058U nc N7058U nc ZS-OIJ not	oted Toronto oted Toronto w Quelimane oted Witrivier, oted airshow I ed Johannes	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428;	l nose;
BA-429	C-FWDV n N7058U fle N7058U nc N7058U nc ZS-OIJ not	oted Toronto oted Toronto w Quelimane oted Witrivier, oted airshow I ed Johannes	ONT 15.9.79 "Millardair <sup>"</sup> titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended	l nose; .59
BA-429	C-FWDV n N7058U fle N7058U nc N7058U nc ZS-OIJ not ZS-OIJ land E18S	oted Toronto oted Toronto w Quelimane ted Witrivier, oted airshow I ed Johannes ded at Monge	ONT 15.9.79 "Millardair <sup>"</sup> titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ana Game Lodge, near Pretoria 11.10.15;	
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18	oted Toronto oted Toronto w Quelimane ted Witrivier, oted airshow I ed Johannes ded at Monge	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued	.59
	C-FWDV n N7058U fle N7058U nc ZS-OIJ not ZS-OIJ land E18S photo: E18	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; -Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in	.59
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; -Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59)	.59
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18 E18S -9700	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; -Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59) Central Flying Service, Little Rock AR	.59
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18 E18S -9700	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; -Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59)	.59 10.6.59/64
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18 E18S -9700	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; -Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59) Central Flying Service, Little Rock AR	.59 10.6.59/64 69/79
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18 E18S -9700	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59) Central Flying Service, Little Rock AR Paul W. Milam, Fayetteville AR Mid South Operations Inc, Fayetteville AR	.59 10.6.59/64 69/79 1.82
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18 E18S -9700	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59) Central Flying Service, Little Rock AR Paul W. Milam, Fayetteville AR Mid South Operations Inc, Fayetteville AR Richards Aviation, Memphis TN	.59 10.6.59/64 69/79 1.82 7.83
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18 E18S -9700	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59) Central Flying Service, Little Rock AR Paul W. Milam, Fayetteville AR Mid South Operations Inc, Fayetteville AR Richards Aviation, Memphis TN Springdale Air Service, Springdale AR	.59 10.6.59/64 69/79 1.82 7.83 84
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18 E18S -9700	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59) Central Flying Service, Little Rock AR Paul W. Milam, Fayetteville AR Mid South Operations Inc, Fayetteville AR Richards Aviation, Memphis TN Springdale Air Service, Springdale AR ground collision with Cessna 310 on UPS ramp,	.59 10.6.59/64 69/79 1.82 7.83 84 20.3.87/99
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18 E18S -9700	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59) Central Flying Service, Little Rock AR Paul W. Milam, Fayetteville AR Mid South Operations Inc, Fayetteville AR Richards Aviation, Memphis TN Springdale Air Service, Springdale AR ground collision with Cessna 310 on UPS ramp, Memphis TN	.59 10.6.59/64 69/79 1.82 7.83 84
	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18 E18S -9700	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59) Central Flying Service, Little Rock AR Paul W. Milam, Fayetteville AR Mid South Operations Inc, Fayetteville AR Richards Aviation, Memphis TN Springdale Air Service, Springdale AR ground collision with Cessna 310 on UPS ramp, Memphis TN ground collision with Springdale E18S N4980V	.59 10.6.59/64 69/79 1.82 7.83 84 20.3.87/99 27.1.94
BA-429 BA-430	C-FWDV n N7058U fle N7058U nd ZS-OIJ not ZS-OIJ land E18S photo: E18 E18S -9700	oted Toronto oted Toronto w Quelimane ted Witrivier, ted airshow I ed Johannes ded at Monge S Turkish AF N2069C	ONT 15.9.79 "Millardair" titles, tailwheel; ONT 5.8.89 "Millardair" titles, tailwheel; e-Nelspruit, South Africa 9.4.95; South Africa 29.1.96, resident, plate BA-428; Margate, Natal 1.5.96; burg-Rand 17.8.14 flying; also 21.4.16 all metallic extended ena Game Lodge, near Pretoria 11.10.15; Turkish Air Force as 6938 6938 at Prestwick on delivery (no date), military scheme; Arkansas Power & Light Co, Little Rock AR: CofA issued (Aerojet-General Junior JATO kit installed in rear of nacelles 59) Central Flying Service, Little Rock AR Paul W. Milam, Fayetteville AR Mid South Operations Inc, Fayetteville AR Richards Aviation, Memphis TN Springdale Air Service, Springdale AR ground collision with Cessna 310 on UPS ramp, Memphis TN	.59 10.6.59/64 69/79 1.82 7.83 84 20.3.87/99

			Aztec Worldwide Airlines Inc, Wilmington DE	14.12.11/20
	N2069C no N2069C no N2069C no N2069C no	ted Texarkar ted Mesa AZ ted Mesa AZ ted Mesa AZ	s TN 9.85 in service, no windows, tailwheel, no titles; na AR 8.97 Springdale Air Service: in service, plate BA-430, [ 6.01, tailwheel; Mesa 1.8.02, 28.6.03 tailwheel; [ 10.10.04 tailwheel in service, rough paintwork, reportedly c [ 3.06 "Harley Davidson" nose art; [ 18.7.08 freighter, "Air West";	
3A-431	E18S	N452C	built	.59
	-9700		Peter Kiewit & Sons Inc, Omaha NE	63/64
			Ruby Co, Boise ID	66/69
		N452CC	Johnson Flying Service, Missoula MT	70/72
			Dickinson Air Service, Dickinson ND	79
			Frank E. Fairchild	81
			confiscated at West Palm Beach FL: due use in illegal	
			drug smuggling operations	2.81
			Crown Air Services, Fort Lauderdale FL	6.81
			Smithair Inc, Sharpsburg GA	9.82/85
			ran off runway, nosed over, Jonesboro GA	20.9.83
			Robert G. Stanford, Kodiak AK	12.3.90/93
			struck-off USCR	30.4.93
3A-432	E18S	N670Q	Beech Aircraft Corp, Wichita KS	6.59
	-9700		Beech demonstrator, <i>Aerojet-General Junior JATO</i> installed in rear of engine nacelles)	
		ΝΛΟΛΤ	<b>u</b>	62/60
		N404T	Trostel Aviation Co, Milwaukee WI	63/69 70/79
		N404T	Trostel Aviation Co, Milwaukee WI Par Aviation, Hales Corners WI	70/79
		N404T	Trostel Aviation Co, Milwaukee WI Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL	
		N404T	Trostel Aviation Co, Milwaukee WI Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour,	70/79
	G18S cab	N404T	Trostel Aviation Co, Milwaukee WI Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97)	70/79
	G18S cab	N404T	Trostel Aviation Co, Milwaukee WI Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed	70/79
	G18S cab	N404T	Trostel Aviation Co, Milwaukee WI Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282)	70/79 2.12.83/06
	G18S cab	N404T	Trostel Aviation Co, Milwaukee WI Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA	70/79 2.12.83/06 25.8.10/12
	G18S cab	N404T	Trostel Aviation Co, Milwaukee WI Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA Greatest Generation Naval Museum, San Diego CA, later	70/79 2.12.83/06 25.8.10/12
	G18S cab	N404T	Trostel Aviation Co, Milwaukee WI Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA	70/79 2.12.83/06 25.8.10/12
		N404T	Trostel Aviation Co, Milwaukee Wi Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA Greatest Generation Naval Museum, San Diego CA, later Colorado Sporings CO	70/79 2.12.83/06 25.8.10/12
	N404T note		Trostel Aviation Co, Milwaukee Wi Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA Greatest Generation Naval Museum, San Diego CA, later Colorado Sporings CO	70/79 2.12.83/06 25.8.10/12
	N404T note N404T at fl	ed Reno NV y-in Oshkosh	Trostel Aviation Co, Milwaukee Wi Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA Greatest Generation Naval Museum, San Diego CA, later Colorado Sporings CO	70/79 2.12.83/06 25.8.10/12
	N404T note N404T at fl N404T at B N404T at B	ed Reno NV y-in Oshkosh eech fly-in T eech fly-in W	Trostel Aviation Co, Milwaukee Wi Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA Greatest Generation Naval Museum, San Diego CA, later Colorado Sporings CO 12.9.75; WI 1.8.91; ullahoma TN 10.93 & 16.10.94; /ichita KS 9.10.97, plate BA-432;	70/79 2.12.83/06 25.8.10/12 11.1.13/20
	N404T note N404T at fl N404T at B N404T at B N404T note	ed Reno NV y-in Oshkosh eech fly-in T eech fly-in W ed Janesville	Trostel Aviation Co, Milwaukee Wi Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA Greatest Generation Naval Museum, San Diego CA, later Colorado Sporings CO 12.9.75; WI 1.8.91; ullahoma TN 10.93 & 16.10.94; /ichita KS 9.10.97, plate BA-432; WI 26.7.99 visiting for maintenance, owned Richard Hansel	70/79 2.12.83/06 25.8.10/12 11.1.13/20 n IL,
	N404T note N404T at fl N404T at B N404T at B N404T note plate BA-43	ed Reno NV y-in Oshkosh eech fly-in Ti eech fly-in W ad Janesville 32 E18S-970	Trostel Aviation Co, Milwaukee Wi Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA Greatest Generation Naval Museum, San Diego CA, later Colorado Sporings CO 12.9.75; WI 1.8.91; ullahoma TN 10.93 & 16.10.94; /ichita KS 9.10.97, plate BA-432; WI 26.7.99 visiting for maintenance, owned Richard Hanser 0 built 6.59, still carried markings for Chicago-Europe flight	70/79 2.12.83/06 25.8.10/12 11.1.13/20 n IL,
	N404T note N404T at fl N404T at B N404T at B N404T note plate BA-43 N404T at fl	ed Reno NV y-in Oshkosh leech fly-in Ti leech fly-in W ad Janesville 32 E18S-9700 y-in Lakeland	Trostel Aviation Co, Milwaukee Wi Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA Greatest Generation Naval Museum, San Diego CA, later Colorado Sporings CO 12.9.75; WI 1.8.91; ullahoma TN 10.93 & 16.10.94; /ichita KS 9.10.97, plate BA-432; WI 26.7.99 visiting for maintenance, owned Richard Hanser 0 built 6.59, still carried markings for Chicago-Europe flight of FL 10.4.01;	70/79 2.12.83/06 25.8.10/12 11.1.13/20 n IL,
	N404T note N404T at fl N404T at B N404T at B N404T note plate BA-43 N404T at fl N404T at B	ed Reno NV y-in Oshkosh eech fly-in Ti eech fly-in W ad Janesville 32 E18S-9700 y-in Lakeland eech fly-in Ti	Trostel Aviation Co, Milwaukee Wi Par Aviation, Hales Corners WI Richard W. Hansen, Batavia IL (departed Chicago 19.6.97 to Europe for tour, returned to Chicago 11.7.97) (fitted c86 with Beech G18S cockpit cab mod. removed from N68V BA-282) Pissed Away N404T LLC, Bellevue WA Greatest Generation Naval Museum, San Diego CA, later Colorado Sporings CO 12.9.75; WI 1.8.91; ullahoma TN 10.93 & 16.10.94; /ichita KS 9.10.97, plate BA-432; WI 26.7.99 visiting for maintenance, owned Richard Hanser 0 built 6.59, still carried markings for Chicago-Europe flight	70/79 2.12.83/06 25.8.10/12 11.1.13/20 n IL,

N404T at fly-in Oshkosh 7.03 Richard Hansen, won award; N404T at Beech fly-in Tullahoma TN 16.10.03; N404T at fly-in Oshkosh 30.7.10;

BA-433	E18S	4R-AAU	Ceylon Survey Department, Colombo	28.7.59/82
			(fitted for photographic survey prior to delivery)	
			retired Colombo-Ratmalana 80/81)	
			to Sri Lanka AF as CS450	.82
			op: Sri Lanka Government Survey Department	82/89
			op: No.2 Training Wing, Ratmalana AB	
			Sri Lanka Air Force Museum, Ratmalana AB	94/17
	4R-AAU	noted Ratmala	na 13.4.63 "Ceylon Survey Dept" titles, tailwheel;	
			ed. Colombo-Ratmalana 3.80:	
			ct at Ratmalana 81;	
		ill in service 89		

CS450 noted in SLAFM Ratmalana 3.97, 2.11; 2.16;

BA-434	(E18S)		E18S-9700 BA-444 modified at Beech factory to	
	G18S		become prototype for the Super G18S model,	
			FAA type certification 8.10.59)	
		N2072C	Beech Aircraft Corp, Wichita KS	.60
		N866A	Tidewater Construction Corp, Norfolk VA	63/64
		N8668	Piedmont Aviation, Winston Salem NC	66
		N8668V	Business Aircraft Leasing, Gainesville FL	69
			Virginia Equipment Corp, Suffolk VA	70/72
			Heilig Meyers Co, Suffolk VA	79
		(N106TD)	ntu: Fayette Aviation NC	2.80
		N8668V	rereg	80
		N101RG	GALCO Leasing Co, Houston TX	11.80
			Bentley International Trading, Santa Monica CA	6.82
			struck-off USCR	7.82
			e Beech 18 by Robert Parmerter p.294; a City OK 16.6.81 "Annie" under cockpit, tailwheel, exce	llent condition;
3A-435	E18S	N1250 (2	Iowa Engineering Co, Cedar Rapids IA	4.59/66
JI+00	-9700	N1258	Altorfer Machinery Corp, Cedar Rapids IA	4.59/00 69/70
	5700	11/200	ran off runway into snow and mud,	00//0
			gear collapsed, landing Kansas City MO	16.12.70
			S. W. Sisk, St Louis MO	71/72
			Madison National Airways Inc, Madison IN	29.5.73/74
			crashed destroyed by fire on takeoff, Madison IN	11.9.74
			perator Madison Nation- (full name obscured), hit trees a ton KY, 2 crew k;	after airborne
3A-436	E18S	N10J	Beech Aircraft Corp, Wichita KS: CofA issued	6.7.59
	-9700	N540MC (2	Interstate Life Insurance Co, Chattanooga TN	63/67
		N549MC	Interstate Life Insurance Co, Chattanooga TN	11.67
			Seymour Rose, Glencoe IL	30.1.68/70
			Impex Corp, Camp Hill PA	70
		N3131W	Southland Oil Co, Yazoo City MS	71/72
			S. S. Airways Inc, Kansas City KS	74/81
			ground collision with van, Chicago-O'Hare IL	17.12.77
			Frank Taylor, Drexell Hill PA	7.81
			US Customs Service, Washington DC	4.84
			Lansing Community College, Lansing MI	5.1.90/14
			(instructional airframe at College 99)	
			struck-off USCR	17.2.14
	N549MC r	noted La Guard	lia NY 3.6.70 Implex Corp;	
	N3131W n	oted Kansas (	City-Fairfax MO 3.6.76;	
	N3131W a 2 crew uni	•	17.12.77: SS Airways, taxying for departure to Kansas (	City at 4.05am,
3A-437	E18S	N156H	Beech Aircraft Corp, Wichita KS: CofA issued	9.7.59
107-701	-9700	NIJUI	Flint Steel Corp, Tulsa OK	63
	5700		Cherokee Village Development Corp,	00
			Cherokee Village AR	64
			Greensboro High Point Air Service, Greensboro NC	66/72
			Professional Air Charter, San Francisco CA	.80
			Cocker Air Freight, Dallas TX	.ou 1.83/84
				7.84
			renamed: Skyfreighters Corp, Dallas TX	7.84 9.84
			Onyx Aviation, Oklahoma City OK Telford Aviation, Waterville ME	9.84 8.85
				8.85
			Barron Thomas Aviation, Dallas TX	12.87 27.1.88/08
			Royal Air Freight, Pontiac MI (retired derelict, Pontiac MI 91/00)	21.1.00/00
			struck-off USCR	1.12.08
				1.12.00

N156H noted Detroit-City MI 24.5.76;

	N156H note N156H note N156H note	ed Pontiac Mi ed Pontiac 3. ed Pontiac 7.	· · · · · · · · · · · · · · · · · · ·	
BA-438	E18S -9700	N930R	Beech Aircraft Corp, Wichita KS: CofA issued Rust Engineering Co, Pittsburgh PA Saunders Leasing System, Birmingham AL Osborne & Co, Birmingham AL James J. Thompson, Birmingham AL Twin Beech Aviation, Birmingham AL Doug Armstrong/ A & M Aviation Inc, Matthews NC David B. Garrett, Polson MT	17.7.59 63/66 69/70 71/79 7.82 1.84/95 1.10.97/14 27.8.14/20
	no titles, alv N930R note N930R visit N930R visit N930R at fi N930R at B N930R at a N930R at fi N930R at B	vays had bee ed Pell City A ed Beech fly- ed Beech fly- y-in Oshkosh bshkosh 8.98 eech fly-in Ta irshow Lakela y-in Oshkosh eech fly-in Ta	m AL 5.93, tailwheel, just completed interior refurbishment, en an executive aircraft never a freighter; L 5.93, tailwheel, in service; -in Tullahoma TN 16.10.94 -in 13.10.95 plate BA-438; o WI 8.97 plate BA-438 E18S-9700 built 7.59; civil scheme, award winner: owner Doug Armstrong NC; ullahoma TN 16.10.98 flown Doug Armstrong; and FL 4.99; o 8.99 Doug Armstrong; ullahoma TN 16.10.02 Doug Armstrong; ullahoma TN 18.10.14; Oshkosh 7.15, 7.16;	
BA-439	E18S	N2094C	Skyways Aircraft Ferry Service Inc, Van Nuys CA exploded mid-air near Wake Island, Pacific on delivery flight to Japan	.59 1.9.59
	further deta	ils, see Beec	h 18 by Parmerter p.289;	
BA-440	E18S G18S Cab	N324B N317MH	Beech Aircraft Corp, Wichita KS: CofA issued A. C. Houston Lumber Co, Boise ID Medusa Equipment Co, Oildale/Bakersfield CA Tye Sales Co, Lockney TX Lawrence T. Biedenharn, San Antonio TX Ronald R. Hyde, Kenedy TX Cheryl H. Walton, Indianapolis IN	24.7.59 63/64 66/72 79 5.91 22.12.93/06 9.4.07/20
	N317MH at N317MH at	Beech fly-in Beech fly-in fly-in Oshkos fly-in Oshkos Beech fly-in Oshkosh 8.5 Beech fly-in fly-in Oshkos Beech fly-in fly-in Oshkos Beech fly-in fly-in Oshkos Beech fly-in fly-in Oshkos Beech fly-in fly-in Oshkos	Tullahoma TN 16.10.02 Ron Hyde; sh 30.7.03 Ron Hyde; Tullahoma TN 16.10.03;	ilt 7.59;
BA-441	E18S -9700	N246AA N1230S	Beech Aircraft Corp, Wichita KS: CofA issued United States Rubber Co, New York NY Bowes Seal Fast Corp, Indianapolis IN Marion Brick Corp, Marion OH William L. Hart, Arlington VA	6.8.59 63 64 66/69 70

		Air Chicago Freight Airlines, Chicago IL	71/72
Hamilton	N102SA	Shorter Airlines, Miami FL	.72/73
extended		Ridder Air Enterprises, Whiteman MA	79
nose		Universal Action Corp, Middleburg Heights OH	4.84
		Robert B. Burwell, West Chicago IL	11.90/98
		op: Viking Express, Chicago-Midway IL	97
		Kestrel Inc, Waukee IA	30.4.98/20
		op: Turks Air Cargo, Opa Locka FL	13

N1230S noted Washington-DCA 30.9.70,

N1230S Chicago-O'Hare 28.8.71 Air Chicago;

N102SA noted Detroit-City Airport MI 5.72 "Shorter Airlines" titles, standard nose, tailwheel, polished metal scheme;

N102SA noted San Antonio TX 1.9.73 & 28.9.73, Hamilton conversion, Shorter AL; N102SA photo 8.78 with Hamilton long nose;

N102SA noted Aurora IL 8.97 Viking;

N102SA noted Oskaloosa IA 24.7.98 in service, freighter, Kestrel Inc, lengthened nose, plate: BA-441 built 7.59 as E18S-9700, AUW increased to 10,100 lb by Hamilton Aircraft; N102SA retired Opa Locka FL late 2013, ferried to FLL Executive .15 parked 15-16;

BA-442	E18S	N137X	Beech Aircraft Corp, Wichita KS: CofA issued	31.7.59
			Collins Radio Co, Richardson TX	63/66
			(Collins flying avionics showcase)	
	-9700		(mods to E18S-9700 installed 4.67)	
576		N901NC	Belton Bagging Co, Belton SC	69/72
			United Leasing Corp, Richmond VA	79
			Equipment Leasing Corp, Greenville SC	7.81/84
			op: General Aviation Inc, Greenville TN	80
			Isd: Mountain Air Cargo, Denver NC	.80/84
			Coastal States Aviation, Denver NC	3.85
			Mountain Air Cargo, Denver NC	86
			P B Leasing Company, Naperville IL	5.87
			Milton Glass, Anoka MN	2.88
		N962AA	Milton Glass/ Arrowhead Airways Anoka MN	3.88
			S D Air Express, Jackson WI	2.89
			op: Ernie Joyner/ Arrowhead Airways, Blaine MN	90
			Trans Gulf Airways, Slidell LA	31.8.92/99
			Taylor Energy Co, New Orleans LA	8.6.99
		N992PT	Taylor Energy Co, New Orleans LA	14.7.99/06
			insurance write-off New Orleans, probably due	
				9 8 06
			Hurricane Katrina 10.05) struck-off USCR	9.8.06

N962AA noted Slidell LA 9.8.98, plate: BA-442 built 7.59; plate -9700 conv. 4.67; N962AA at airshow Lakeland FL 4.99 Trans Gulf AW, Slidell LA, no titles;

BA-443	E18S	N326W	Beech Aircraft Corp, Wichita KS: CofA issued	28.7.59
			White Motor Co, Lansing MI	63/66
			SMB Stage Line Inc, Des Moines IA	69/80
			Crawford Aviation	.80
			Aurora Air Service, Fairbanks AK	81/91
			ran into ditch landing, Tobin Creek AK	30.7.81
			Roger W. Brooks/ Brooks Fuel Inc, Fairbanks AK	28.10.92/13
			(stored stripped, derelict, Fairbanks AK 96/11)	
			reg expired, struck-off USCR	30.7.13
	N326W r N326W r N326W r N326W r N326W r	noted Fairbanh noted Fairbanh noted Fairbanh noted Fairbanh noted Fairbanh	nks AK 26.5.90; (s 4.96, derelict with N114V: both stored by Brooks for f (s AK 15.8.00, wreck used for spares only; (s AK 18.4.04 at Brooks fuel junk area, (s AK 8.9.04 at Brooks fuel junk area, engineless; (s 26.9.05 at Brooks fuel, parts & engines removed, san (s 8.7.11 stored;	
BA-444	E18S	N352B	Beech Aircraft Corp, Wichita KS: CofA issued	18.8.59
			Electric Autolite Co, Toledo OH	63

			Eltra Corp, Toledo OH National Flight Service, Toledo OH Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Isd: International Aviation Corp, Minneapolis-Crystal MN Crawford Aviation Midwest Aviation Corp, Davenport IA forced landing in ploughed field, Pharr TX	64 66 69 70/80 80 .80 20.7.81/85 10.3.85
BA-445	E18S -9700	N89D N6911	Youngstown Airways/ Lease Air, Youngstown OH Lease Air Inc, Youngstown OH SMB Stage Line Inc, Des Moines IA op; Island Airlines Hawaii, Honolulu HI First Venture Corp, Bartlesville OK crashed, destroyed by fire, Hakalau HI	.59/64 66 69/79 .79/80 5.12.79/82 28.4.82
	N6911 note N6911 note N6911 note	d Chicago-O d Muskogee d Dallas-Lov	'Hare 8.9.71 SMB Stage Lines; 'Hare 30.9.71 SMB Stage Lines; OK 2.3.73 at SMB Stage Line maintenance base; e TX 12.7.73; plulu 9.10.80 Island Airlines Hawaii, no titles;	
BA-446	E18S -9700	N2083C	built Hartzell Industries Inc, Piqua OH Orville E. Horten, Indianapolis IN Indianapolis Air Charter Services, Indianapolis IN Indianaero Inc, Bloomington IN David B. Norcutt, Mount Airy MD Aero Express Inc, Dearborn Heights MI op: Blackhawk Airways, Rock County WI Kenneth R. Phillips/ Phillips Air Service, Del Rio TX crashed on takeoff, Del Rio TX struck-off USCR (stored dism. Brackettville TX, bare metallic 00/10) William E. Signs, Addison TX: for parts	8.59 63/72 79 3.83/86 4.89/91 8.93 8.9.94/95 97 22.1.98 8.4.98 5.11.98 .10
	N2083C not N2083C not N2083C not plate BA-44	ted Blooming ted Grosse Is ted Rock Cou 6 built 8.59;	rne IN 28.5.76; iton IN 10.91, tailwheel, no titles; sle MI 2.97 "Aero Express" titles; unty WI 7.97 "Aero Express" titles painted over, rep. op. Bla r parts 5.10 by Bill Signs to restore his E18S N666AK;	ackhawk Airways,
BA-447	E18S -9700	N2079C XB-ADS	Beech Aircraft Corp, Wichita KS: CofA issued Southern Alrways Co, Altlanta Airport GA Dickerson Inc, Monroe NC sale reported, Elberton GA struck-off USCR Rogelio R. Perez, Mexicali	19.8.59 63/64 69/72 77 18.10.77 93
BA-448	E18S trigear	N680Q N190CM	Beech Aircraft Corp, Wichita KS: CofA issued Sewart Seacraft Inc, Berwick LA Crosby Forest Products Co, Picayune MS Delmar L. Phillips, Converse TX Stillwater Publishing Co, Stillwater OK PWA Aircraft Inc, Ponca City OK La Tour Air, New Baltimore MI La Tour Air, New Baltimore M	4.8.60 63/64 66/70 71/72 79/91 11.93/96 14.5.96 10.96 10.9 08/01
		N7MB	Mike Strong Resources Inc, Birmingham AL Barrels of Fun Inc, Lebanon MO B & B Leasing Co, Lebanon MO Markley C. Brown, Santa Ynez CA Markley C. Brown, Santa Ynez CA TDH Investments LLC, Dewey AZ Beechit LLC, Precott AZ	10.8.98/01 25.5.01 19.7.02 29.7.03 6.10.03/05 8.3.06 11.8.09/12

N680Q noted Oklahoma City OK 25.6.81 trigear, no titles; N190CM noted Pontiac MI 12.96; N190CM noted Pontiac 7.97 trigear; N190CM visited Beech fly-in Tullahoma TN 16.10.98 trigear owned Michael & Catherine Strong, Birmingham AL; N190CM at Beech fly-In Tullahoma TN 10.10.99 Michael Strong, Alabama; N190CM at Beech flyIn, Tullahoma TN 18.10.00; N190CM BA-448 advertised for sale T-A-P 5.01: trigear TT5650hrs: always corporate executive airplane, Dee Howard spar strap, meticulously maintained, \$225K: Strong Resources;

BA-449	E18S	N161DP	Beech Aircraft Corp, Wichita KS: CofA issued	.59	
			Detroiter Mobile Homes Inc, St Louis MI	63/64	
			Continental Independent Telephone, St Louis MO	66	
		N5000M	Continental Telephone Service Corp, Wentzville MO	69/72	
			sale reported, Azusa CA	6.76/91	

N5000M noted Topeka KS 24.8.70; N5000M noted Bakersfield-Meadows Field CA 20.4.72;

BA-450	E18S	N509B	built	.59
			Conley Lott Nichols Machinery Co, Dallas TX	63/72
			Modern Aero Inc, Dallas-Redbird TX	19.12.73/77
			struck-off USCR	22.8.77
BA-451	E18S	N2095C	built	.59
			Lodi Drilling & Service Co, Longview TX	63/72
			Robert L. Burns, Shawnee Mission KS	17.3.77/91
BA-452	E18S	N438A	Armco Steel Corp, Topeka KS	.59
			Shakespeare Co, Kalamazoo MI	63/66
			Jack Adams Aircraft Sales, Walls MS	69
			Jim Hankins Air Service/ Hankins Airways, Jackson MS	70/74
			landed gear locked-up, Albany NY	18.1.74
			Wyman Pilot Service, Pontiac MI	16.3.78/79
			crashed destroyed during a 3 aircraft formation flypast	
			at night over a relative's house, Burton OH	9.5.79

N438A accident report 18.1.74: Hankins Airways, flight from Lebanon NH, temperature 12 degrees below zero, mechanical fault in gear extention, 1am, 2 unhurt;

N438A accident report 9.5.79: Wyman Pilot Service: flight Youngstown OH to Pontiac MI, 3 aircraft formation low flypast over leader's mother's house, 12.05am, N438A struck trees & burned, pilot k;

BA-453	E18S	N435A	Armco Steel Corp, Topeka KS: CofA issued	18.9.59/66
	-9700	N4351	Wedekind Aircraft Inc, Middletown OH	69/70
			Crosco Inc, Canton OH	71/79
			John Schweller, Wilmington DE	3.86
		N712JS	John Schweller, Wilmington DE	4.86
	G18S Cab		Classic Aircraft Inc, St Louis MO	7.89/91
			Alton E. "Chuck" Cianchette, Palmyra ME	8.12.91/02
			Chuck's Classic Aircraft LLC, Palmyra ME	6.3.02/20

N4351 noted Chicago-O'Hare IL 23.7.71;

N712JS at Oshkosh WI 1.8.89, plate BA-453;

N712JS at Beech fly-in Wichita KS 10.92;

N712JS at Beech flyins Tullahoma TN 10.93,16.10.94 & 13.10.95, plate BA-453;

N712JS at Oshkosh WI 8.97 "Miss Maine" plate BA-453 E18S-9700 built 9.59;

N712JS at Beech FlyIn Wichita KS 11.10.97 plate BA-453 "Miss Maine";

N712JS at Beech fly-in Tullahoma TN 4.98 "Miss Maine", owned Chuck Cianchette, Newport ME;

N712JS at Beech flyin Tullahoma TN 16.10.98 tailwheel, Chuck Cianchette, Palmyra ME;

N712JS at Oshkosh 8.99 Chuck Cianchette "Miss Maine";

N712JS at Beech Fly-In Tullahoma TN 10.10.99 Chuck Cianchette ME;

(Chuck Cianchette killed 15.1.00 in crash of his Cessna 190 195 in KY)

N712JS at Beech flyin Tullahoma TN 16.10.02 owned Chuck Cianchette, Newport ME,

name "Miss Maine" on nose; N712JS noted Tullahoma TN 1.3.03 exec scheme, parked outside Staggerwing museum; N712JS noted Tullahoma TN 16.10.03 at Staggerwing museum; N712JS noted Tullahoma TN 14.10.07 at Beech fly-in, civil scheme "Miss Maine"; same 18.10.14;

BA-454	E18S	N436A	Armco Steel Corp, Topeka KS	.59/64			
-			Millie Carlisle, Jackson WY	66			
			Gopher Aviation, Rochester Airport MN	69/70			
	Hamilton		SMB Stage Line Inc, Des Moines IA	76/85			
	Westwind II		(rebuilt .72 as Hamilton Westwind III)				
			op: North Continent Airlines, Long Beach CA	85/86			
			SMB Stage Line, Dallas-Ft Worth TX	10.86			
			sold to Philippines: struck-off USCR	18.9.89			
		RP-C1126		.89/92			
			Territory Airlines, Goroka PNG t/a Metroair	.91/92			
			retired Manila, stripped airframe sold	.92			
			Charles R. Miller/ CM Air, Manila: parts use	94/97			
			(rep. re-engined with P&W R-985s)	0 1101			
	<ul> <li>N436A noted Pittsburg PA 18.3.78 Westwind III tailwheel, "SMB Stage Line" titles;</li> <li>N436A noted Des Moines IA 26.8.80 Westwind III "SMB Stage Lines" titles;</li> <li>N436A noted Tucson AZ 16.3.84, Hamilton Westwind, no engines;</li> <li>N436A noted Phoenix AZ 7.2.85 North Continent (no titles);</li> <li>N436A noted LAX 6.8.85 in freight service, turbines, North Continent (no titles);</li> <li>N436A noted Dallas-Ft Worth TX 10.87, tailwheel Tradewind, "SMB Stage Lines";</li> <li>RP-C1126 noted Manila 1.91 Westwind III tailwheel, long nose, "Metro Manila Airways International" titles;</li> <li>Metro Manila Airways purchased by Territory Airlines PNG c91 to acquire charter licence and hangar facilities at Manila Domestic Airport, renamed Metroair: Talair Twin Otters replaced the 2 Westwinds; the 2 Hamilton Westwinds wewre included in purchase but not required. Paul Howard recalls closing down Metroair 2.92, the PT-6A-20 turbines &amp; props from Westwinds were removed and sent to Goroka PNG for resale and Beech 18 airframes offered for sale without turbines; sold in Manila</li> </ul>						
	presumeably for parts; RP-C1126 noted Manila 2.1.94;						
	RF-011201	ioleu Manila	2.1.94,				
BA-455	E18S -9700	N439A	Armco Steel Corp, Topeka KS & Houston TX: CofA SMB Stage Line Inc, Des Moines IA B & B Aircraft Service, Fort Lauderdale FL	15.10.59/66 69/81 9.81			

-9700		SMB Stage Line Inc, Des Moines IA	69/81
		B & B Aircraft Service, Fort Lauderdale FL	9.81
	N50BP	B & B Aircraft Service, Fort Lauderdale FL	11.81/82
		D & D Airfreight Service, Fort Myers FL	11.86
		Wauchula Flying Service, Wauchula FL	8.88/91
		damaged when nosed over on landing, Wauchula FL	12.1.90
		exported, struck-off USCR	11.2.92
		Lee Cameron & Larry Stahl/ C & S Inc,	
		North Hollywood CA	96
	N95AP	C & S Inc, North Hollywood CA	5.97/98
AT-11		(composite rebuild using fuselage & perspex nose of	
nose		AT-11 N241X, ferried to Whiteman Air Park CA 3.6.97)	
H18	N241X (2	C & S Inc, North Hollywood CA	5.98/04
mods		(rebuild continued at Whiteman Air Park CA 98,	
		H18 raised cabin roof, windows & windshield,	
		mods to MAUW 10,100 lb, CofA 12.11.98)	
		Bogie Bros LLC, Oklahoma City OK	6.6.06/18
		ran off runway landing, struck fence, Guyon KS	1.6.08
		reg expired 30.4.18, struck-off USCR	13.9.18

further details on composite rebuild see Beech 18 by Robert Parmerter p.381;

N439A noted Topeka KS 4.6.76 "SMB Stage Line" titles; N439A noted Toronto ONT 13.5.79 SMB Stage Line;

N241X noted Whiteman Air Park CA 15.8.00, rebuild by Lee Cameron of Aerospace Products almost complete, using nose section ex AT-11 N241X from Clearwater FL, and H18 forward fuselage from a H18 involved in a midair collision, E18S tail, rear fuse and wings, planned to fly 10.00, plate BA-455 built 6.5.56;

Advertised 318 gallons baggage do possibilities N241X note	for sale in T-A fuel, HS prop por LH, photo s, \$660K: appl ed in hangar V	A-P 5.01: "Beech AT-11/E18/H18" only one in the world,10, ps, metal controls, relicensed, Hamilton strap, cabin configu door inward opening R-side, new H18 windshield, magneto ly Aerospace Products; Whiteman Airpark 6.9.01 & 13.8.02;	ired
E18S	N311D	built Dow Chemical Co, Tulsa OK Miller Container Corp, Milan IL SMB Stage Line, Des Moines IA crashed destroyed after takeoff in fog, Dodge City KS	.59 63/64 66 69/75 3.3.75
E18S	N307B	Beech Aircraft Corp, Wichita KS: CofA issued Corey Custom Airtravel Inc, Detroit MI Midwestern Airlines, Detroit MI Southeastern Airways Corp, Double Springs AL Mohican Air Service Inc, Cleveland OH Northern Airmotive Corp, Kenosha WI, later Hillsboro OH KJL Aviation, Wilmington DE	14.1.59 63/66 67/70 71/72 79/91 26.5.93/00 29.11.00/20
E18S -9700	N40DC (2 N240DC N2405C	Daniel Construction Co, Greenville SC Daniel Construction Co, Greenville SC Belmont Charter Service, Detoit MI Van Dusen Acceptance Corp, Minneapolis MN Frank C. Benanzinga, Jepaga, San Salvadar	.59/63 64/66 69/72 72
Hamilton long nose	YS-133P	(Hamilton long cargo nose installed at Tucson AZ by Hamilton Aircraft 73)	6.73
	N133PA	(based llopango, San Salvador 72/76) Frank C. Bonansinga, Desert Hot Springs CA Lee Morris, Galveston TX Skytram Aviation, Laredo TX struck-off USCR	6.73/76 12.76 77 9.2.79/82 18.9.82
Frank Bona Hamilton Al cargo door: more aft Co Flew severa with sick US Brownsville flying it for t	nsinga (ex Ai ircraft in Tucs bfG. Based it a al medivacs n S Embassy pe TX which wa the few years	ir America pilot), purchased E18S in 6.73, had Hamilton mo on. Hamilton long cargo nose, spar strap, metal cabin liner long nose added 10 knots and made it more stable and eas at ilopango, San Salvador on cargo & pax work. on-stop to New Orleans & Miami, and one to Tampa then B erson. Brought back full loads of used clothing from New O as sold in op stores in San Salvador. "I was a poor business I was in Central America." Aircraft was painted pale green	pilot hatch and sier to land with Boston rleans and man but I loved . He repainted it
E18S -9700	N440DC N449DC N4490C CF-QCG	Daniel Construction Co, Greenville SC Daniel Construction Co, Greenville SC Belmont Air Charter Service, Detroit MI sold to Canada, struck-off USCR Bale Comeau Air Service, Hauterive QUE Golfe Air Quebec Ltee, Hauterive QUE Air Caravane, Montreal-Dorval QUE Robert W. McCreadie, Winnipeg MAN (stored at CFB Trenton with unid. Beech 18 airframe 96)	.59/66 3.66 15.11.68/72 1.2.72 2.72 74 76/78 9.4.79/01
	Advertised 318 gallons baggage do possibilities N241X note Still being a E18S N311D acc. took off in s E18S N307B note N307B note N307B pho E18S -9700 Hamilton long nose N2405C no Frank Bona Hamilton Al cargo door: more aft Co Flew severa with sick US Brownsville flying it for t white when E18S	Advertised for sale in T-A 318 gallons fuel, HS prop baggage door LH, photo possibilities, \$660K: app N241X noted in hangar M Still being advertised in TE18SN311DN311D accident report 3 took off in snow and fogE18SN307BN307B noted Washingto N307B photo 01: all polisE18SN40DC (2 -9700-9700N2405CHamilton long noseN2405C noted Tucson A Frank Bonansinga (ex AL Hamilton Aircraft in Tucs cargo door: he says the a more aft CofG. Based it a Flew several medivacs in with sick US Embassy pe Brownsville TX which wa flying it for the few years white when he brought itE18SN440DC -9700Advertised TX which wa flying it for the few years white when he brought it	Dow Chemical Co, Tulsa OK Miller Container Corp, Milan IL SMB Stage Line, Des Moines IA crashed destroyed after takeoff in fog, Dodge City KS         N311D accident report 3.3.75: SMB Stage Line, mail flight Dodge City to Hays KS, took off in snow and fog 9.47pm, destroyed, pilot k;         E18S       N307B       Beech Aircraft Corp, Wichita KS: CofA issued Corey Custom Airtravel Inc, Detroit MI Midwestern Airlines, Detroit MI Southeastern Airways Corp, Double Springs AL Mohican Air Service Inc, Cleveland OH Northern Airmotive Corp, Kenosha WI, later Hillsboro OH KJL Aviation, Wilmington DE         N307B noted Washington Court House OH 6.8.99 op Northern Airmotive; N307B photo 01: all polished metallic, tailwheel, in service;         E18S       N40DC (2         -9700       N240DC         Daniel Construction Co, Greenville SC         -9700       N240DC         Daniel Construction Co, Greenville SC         -9700       N240DC         Daniel Construction Co, Greenville SC         -9701       N240DC         Daniel Construction Co, Greenville SC         -9700       N240DC         Daniel Construction Co, Greenville SC         -9701       N240DC         Hamilton       Uharniton Aircraft 73)         YS-133P       Frank C. Bonansinga, Ilopango, San Salvador (based llopango, San Salvador 72/76)         N133PA       Frank C. Bonansinga, Desert Hot Springs CA Lee Morris, Galveston TX Skytram Aviation, Laredo TX struck-off USCR </td

(complete airframe offered for sale 2017)

CF-QCG noted Montreal 21.10.73 reported as Golfair; CF-QCG noted CFB Trenton 6.96 with an unid Beech 18 hulk;

BA-460	E18S	N90D	Youngstown Airways/ Lease Air, Youngstown OH	.59/64
	-9700		Beckett Aviation Corp, Youngstown OH	66
		N9001	SMB Stage Line, Des Moines IA	69/78
			Southern National Leasing Corp, Charlotte NC	79
			op: General Aviation Inc, Greenville TN	80
			Equipment Leasing Corp, Greenville SC	7.81/84
			lsd: Mountain Air Cargo, Denver NC	81/84
			Coastal States Aviation, Denver NC	3.85
			Pelican transport Inc, Lake Worth FL	4.86
			Aubrey Aviation, Ocala FL	6.87
			Guy Pere, Fairbanks AK	5.90/91
			Methow Aviation, Everett WA	19.2.92/98
			Comanche Air, Winthrop WA	28.9.98/06
			op: Methow Aviation, Everett-Paine Field WA	00/05
			Aero Equipment LLC, Kenai AK	14.7.07/11
			op: Air Supply Alaska, Kenai AK	09/11
			crashed destroyed, New Stuyahok AK	3.1.11
	N9001 no N9001 no	ted Seattle-Boo ted Ephrata W	Beach Executive FL 2.90, exec scheme, extended nose; eing Field 6.6.01; A 4.8.02 "Methow" titles, tailwheel, in service; e WA 18.10.02 "Methow";	
BA-461	N9001 no N9001 no	ted Ephrata W. ted Ephrata W.	A 11.02 yellow & black; A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 6.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg	
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg	.59 63/64
	N9001 no N9001 no N9001 no	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built	.59 63/64 .59
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM	.59 63/64 .59 63
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA	.59 63/64 .59 63 63 64
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS	.59 63/64 .59 63 63 64 66
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS SMB Stage Line Inc, Des Moines IA	.59 63/64 .59 63 63 64
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS SMB Stage Line Inc, Des Moines IA Perkiomen Airways Ltd, Reading PA trading as	.59 63/64 .59 63 64 66 69/72
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS SMB Stage Line Inc, Des Moines IA Perkiomen Airways Ltd, Reading PA trading as Sun International Airways, San Juan, Puerto Rico	.59 63/64 .59 63 64 66 69/72 9.76/97
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS SMB Stage Line Inc, Des Moines IA Perkiomen Airways Ltd, Reading PA trading as Sun International Airways, San Juan, Puerto Rico op: Air Pensylvania	.59 63/64 .59 63 64 66 69/72 9.76/97 80
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS SMB Stage Line Inc, Des Moines IA Perkiomen Airways Ltd, Reading PA trading as Sun International Airways, San Juan, Puerto Rico op: Air Pensylvania op: Sun International Airways, San Juan, Puerto Rico	.59 63/64 .59 63 64 66 69/72 9.76/97 80 80
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS SMB Stage Line Inc, Des Moines IA Perkiomen Airways Ltd, Reading PA trading as Sun International Airways, San Juan, Puerto Rico op: Air Pensylvania op: Sun International Airways, San Juan, Puerto Rico Christopher E. Poindexter, Lone Wolf OK	vice; .59 63/64 .59 63 64 66 69/72 9.76/97 80 80 80 6.97/11
	N9001 no N9001 no N9001 no G18S	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS SMB Stage Line Inc, Des Moines IA Perkiomen Airways Ltd, Reading PA trading as Sun International Airways, San Juan, Puerto Rico op: Air Pensylvania op: Sun International Airways, San Juan, Puerto Rico	.59 63/64 .59 63 64 66 69/72 9.76/97 80 80
3A-461 3A-462	N9001 no N9001 no G18S G18S N9590R r	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1 N9590R	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS SMB Stage Line Inc, Des Moines IA Perkiomen Airways Ltd, Reading PA trading as Sun International Airways, San Juan, Puerto Rico op: Air Pensylvania op: Sun International Airways, San Juan, Puerto Rico Christopher E. Poindexter, Lone Wolf OK struck-off USCR	vice; .59 63/64 .59 63 64 66 69/72 9.76/97 80 80 80 6.97/11
3A-462	N9001 no N9001 no G18S G18S N9590R r N9590R r	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1 N9590R N9590R	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS SMB Stage Line Inc, Des Moines IA Perkiomen Airways Ltd, Reading PA trading as Sun International Airways, San Juan, Puerto Rico op: Air Pensylvania op: Sun International Airways, San Juan, Puerto Rico Christopher E. Poindexter, Lone Wolf OK struck-off USCR	vice; .59 63/64 .59 63 64 66 69/72 9.76/97 80 80 6.97/11 4.1.11
	N9001 no N9001 no G18S G18S N9590R r	ted Ephrata W. ted Ephrata W. ted Kenai AK 6 N766A N511W (1 N9590R	A 5.4.03 "Methow" yellow scheme, tailwheel in service; A 8.5.05 "Methow" titles, "Bumble Beech" name, tailwhee 5.08, 8.09 "Air Supply Alaska" titles, yellow & black, in ser built National Financing Inc, Wilmington DE rereg built C & C Contractors Inc, Albuquerque NM Huston Peanut Co, Columbus GA Jack Adams Aircraft Sales, Walls MS SMB Stage Line Inc, Des Moines IA Perkiomen Airways Ltd, Reading PA trading as Sun International Airways, San Juan, Puerto Rico op: Air Pensylvania op: Sun International Airways, San Juan, Puerto Rico Christopher E. Poindexter, Lone Wolf OK struck-off USCR	vice; .59 63/64 .59 63 64 66 69/72 9.76/97 80 80 80 6.97/11

	Volpar Turboliner II	N600WA	Executive Flight Services Inc, Portland OR Bullhead Air Transport Corp, Bullhead City AZ (rebuilt by Volpar .73 as <i>Turboliner II</i> for Winship) Winship Air Service, Anchorage AK crashed dest. landing, Dutch Harbour AK	64/69 70/72 2.11.73/76 22.7.76
BA-464	G18S	N9604R	Beech Aircraft Corp, Wichita KS: CofA issued Buckeye Union Casualty Co, Columbus OH Hill Brothers Aviation, Pekin IL McNeely Air Charter Service, Earle AR Jim Ratiff Air Service, Columbus MS gear collapsed landing, Jackson MS Doak Boreing, Magnolia AR	21.10.59 63/72 79 4.85/86 9.89 12.9.89 11.90/91

Robert A. Youkin, Springdale AR	1.93
Robert W. Sagers, Fallbrook CA, later Toledo WA,	
later Kearneysville WV	23.2.93/06
Howard M. Bohl, Temecula CA	21.12.10/20

accident report 12.9.89: Jim Ratiff Air Service, gear collapsed on landing; N9604R noted Chino CA 12.93, hangared good condition; N960R noted Madera CA 10.96 "Wayward Wind" in service: plate BA-464 built 10.59; N9604R at Beech fly-In Tullahoma TN 10.10.99 Bob Sager; N9604R at fly-in Lakeland FL 10.4.01; N9604R at Beech fly-in Tullahoma TN 16.10.02; N9604R at Beech fly-in Tullahoma TN 16.10.03;

BA-465	G18S	N123L	built	.59
			Holley Carburettor Co, Warren MI	63/64
		N123A	W. R. Boles, Monroe LA	66
			Herlin Inc, Shreveport LA	69/70
			Ross Aviation, Tulsa-Riverside OK	16.11.70/74
			op: Great Western Airlines, Tulsa OK	70/74
			crashed destroyed by fire, forced landing off airport	
			at night, Fort Scott KS	1.3.74

N123A accident report: Great Western: flight Tulsa to Kansas City MO, engine shut down, low fuel, power loss, struck trees, 2.20am, pilot serious injuries;

BA-466	G18S	N9606R	built	11.59
			Southern Airways of Florida Inc, Orlando FL	63/64
			Business Mens Assurance Co, Kansas City MO	66
		N788MW	Pegasus Transport Inc, Cincinatti OH	69/70
			Thomas E. Nentwick, Leetonia OH	71/72
			Semo Aviation/ Semo Airways, Malden MO	76/84
			Northwest Air Cargo Inc, Springdale AR	4.84
			Younkin Air Service, Springdale AR	1.88
			Cape Central Airways, Cape Girardeau MO	7.88/91
			Jim Hankins Air Service, Jackson MS	3.93
			sold to Canada: struck-off USCR	7.93
		C-GJKA	Central Pacific Outfitters Ltd/ Bottenfields Winisk Air,	
			Pickle Lake ONT	10.1.94/96
			Land-Sea-Air Transport Ltd, Cochenour ONT	29.1.96/97
			Gold Belt Air Transport, Pickle Lake ONT	5.6.97/99
			Parachtisme Nouvel Air, Farnham QUE	16.5.00/06
		N45CF	Aircraft Guaranty Corp, Houston TX: trustee: USCR	27.5.08/20
			Carlo Ferrari, Grenchen, Switzerland	.08/20
			(flew 19 as olive drab USAAF "436784")	
	C-GJKA no C-GJKA no C-GJKA no C-GJKA no N45CF at fi N45CF note N45CF visit	ted St Mathia ted St Mathia ted Farnham ted Rockcliffe ly-in Tannheir ed Hahnweid ted Fairford L	MO 15.9.76 Semo AW; as QUE 10.8.00 op Parachutisme Nouvel Air, tailwheel; as QUE 20.3.05, Parachutisme Nouvel Air, parachute ops; QUE 11.9.05, tailwheel in service; e ONT 26.8.06 for Classic Air Rallye, tailwheel in service; m, Gernany 28.8.10 all metallic, owned Carlo Ferrari; e, Germany 3.9.11 bare metal; JK 14.7.14, Mulhouse-Habsheim 27.6.15 polished metal; JK 17.7.17 polished metal;	
BA-467	G18S	N5555X	Beech Aircraft Corp, Wichita KS: CofA issued	5.11.59
			Clifford M. Farmer, Atherton CA	63/64
			T. R. Carpenter/ / Empire State Airlines/ Flight Service Ir	IC,
			Syracuse-Hancock Field NY	66/73
			Joseph S. Sneden/ Pro-Pilots Inc, Syracuse NY	.73/79
			Stockert Flying Service, South Bend IN	79/81
			P B Leasing Co, West Chicago IL	2.3.81
		N100VE	P B Leasing Co, West Chicago IL	7.81/86
			lsd: Viking Express, Chicago-Midway IL	.81/86
			damaged ran off runway landing, struck snow bank,	
			Minneapolis MN	28.12.85

crashed into houses, destroyed Chicago IL (stored dismantled, fire damaged, in salvage yard, Owasso OK 00)

Joseph S. Sneden Jr was Chief Pilot for Empire State Airlines, and after scheduled Services were discontinued, continued with associate company Flight Service Inc. He purchased N5555X in 1973 when Flight Service's owner moved to Florida. Sneden's own company Pro-Pilots Inc flew it on charter and night freight; for passenger charters the dark brown all-leather interior was re-installed; During 1973-78 Snedden/Pro-Pilots Inc provided pilots and maintenance for BA-141 for Utica Mutual Insurance Co; N5555X noted Syracuse NY 27.8.74; accident reports 28.12.85 & 28.9.86: both op. Viking Express;

N100VE fuselage noted in SW Aero Exchange yard, Owasso OK 10.8.00, plate BA-467;

BA-468	G18S	N697Q	Beech Aircraft Corp, Wichita KS: CofA issued	6.11.59
			Ruan Inc, Des Moines IA	63/66
			SMB Stage Line Inc, Des Moines IA Betty IV	69/79
			gear collapsed during landing, Tulsa OK	5.5.69
			Ajax Aircraft Leasing, Dover DE	1.83
			ACE Air Cargo Express Inc, Cleveland OH	8.84/86
			Robert A. Younkin, Lowell AR	6.87
			Younkin Air Service, Springdale AR	6.88
			Tamboo Trading Co, Palm Beach FL	7.88/97
			Missionary Flights & Services Inc, West Palm Beach FL	2.97
			Hartford Holing Corp, Wilmington DE	21.8.97/99
			Carib-Air Cargo Inc, Lantana FL	7.12.99/01
			struck while parked at Key West FL by DC-3 N79MA	1.12.00/01
			which suffered brake failure while taxying after landing	21.8.00
			Randell Stevenson, Wildwood MO	02/06
			Barron Aviation, Perry MO	26.8.10/12
			rolled inverted at 11,000 feet, crashed in residential stree	
			dest., Taylorville IL (12 parachutists jumped, pilot k)	11.8.12
	N697Q na N697Q ph N697Q na	oted West Palr noto Ft Lauder oted Lantana-V	II 9.80 plate BA-468; n Beach FL 10.5.92; dale FL early 00: tailwheel, "Carib Air Cargo" titles; West Palm Beach County FL 5.4.01; MO 18.8.03 all metaalic freighter, plate BA-468 built 11.59;	
BA-469	G18S	N9615R	Beech Aircraft Corp, Wichita KS: CofA issued	6.11.59
		N565BA	Hawthorne Metal Products Co, Royal Oak MI	63/64
			William F. Lomasney, Harper Woods AL	66
		N565US	US Equipment Corp, Detroit MI	69/79
			Juan Rodriguez, Clinton MO	9.84
			Five of Us Inc, Clinton MD	7.89/91
			Robert E. Haydon, Hartwood VA	8.92
			Gerald A. Stevens, Boca Raton FL	12.94/96
			Avlite Aviation, Paso Robles CA	9.96
			Thomas Leatherwood, Paso Robles CA	.96
			John G. Wood, Winter Haven FL	9.7.98/99
			Rasmus Nielson, Des Moines WA, later Seattle WA (departed Tacoma WA 27.5.07 on flight to Denmark by Ras Nielson, via Reykjavik 6.6.07, arrived back at Tacoma-Narrows WA 23.6.07)	14.4.00/14
			William R. Nolte, Murray NE	27.6.14/18
			Dynamic Avlease Inc, Bridgewater VA	20.8.19
		N18G	Dynamic Avlease Inc, Bridgewater VA	16.3.20
		NICO		10.0.20

N565US noted Detroit-City 24.5.76;

N565US noted Paso Robles CA 10.96, owned Leatherwood: plate BA-469 built 10.59;

N565US at fly-in Oshkosh 8.98 owner John Wood, Winterhaven FL, plate BA-469 built 10.59;

28.9.86

N565US at Beech fly-in Tullahoma TN 16.10.98 tailwheel, John & Tom Wood, Winter Haven FL; N565US at fly-in Oshkosh 30.7.00 Ras Neilson, Tacoma WA, plate BA-469 built 10.59; N565US at Beech fly-in, Tullahoma TN 18.10.00; N565US at fly-in Arlington WA 13.7.02, tailwheel, excellent condition; N565US at Beech fly-in Tullahoma TN 16.10.02; N565US at Beech fly-in Tullahoma TN 16.10.03; N565US at Beech fly-in Tullahoma TN 16.10.03; N565US at fly-in Arlington WA 7.02, 7.7.05 & 7.7.06 civil scheme, tailwheel; departed Tacoma-Narrows Airport 27.5.07 on flight to Denmark, pilot Ras Nielson, planned to attend airshows in Denmark; N565US at Beech fly-in Tullahoma TN 14.10.07; Oshkosh 7.08; N565US visited Oshkosh 7.17 brown & white;

BA-470	G18S	N118W	built	.59
			Midwest Oil Co, Fort Worth TX	63/64
			Bryant Chucking Grinder Co, Springfield VT	66/70
			Carson Helicopters Inc, Perkasie PA crashed destroyed by fire after takeoff in snow,	25.2.72/73
			Ann Arbor MI	29.12.73

N118W accident report: flight Ann Arbor to Allentown PA return, encrusted snow on wings and tail surfaces, 5 minor injuries;

BA-471	G18S	N9621R	built	.59		
	trigear		M & R Dietetic Laboratories Inc, Columbus OH	63/64		
	C C		Ross Laboratories, Columbus OH	66		
			Jack Adams Aircraft Sales, Walls MS	69		
			D-W Corp, Des Moines IA	70/79		
			Frank Cannavo, Lester PA	4.84		
			Aero Taxi Inc, New Castle DE	12.88/99		
			Cannavo Inc, New Castle DE	3.2.95		
			Aero Taxi Inc, New Castle DE	3.2.95/99		
			Randys Olde Towne Service Inc, Traverse City MI	4.10.00/20		
	N9621R n	oted Detoit Cit	y MI 7.4.65;			
			g PA 3.79 trigear in service;			
			oort DE 7.91 trigear;			
3A-472	G18S	N92D	Lease Air Inc, Youngstown OH: CofA issued	14.11.59		
···· <b>-</b>	0.00		Harbison Walker Refractories Co, Pittsburgh PA	63		
			Beckett Aviation, Youngstown OH	63		
			Lease Air Inc, Youngstown OH	64/66		
		N9210	SMB Stage Line Inc, Des Moines IA	69/72		
			Blackhawk Airways, Janesville WI	79		
			Methow Aviation Inc, Wenatchee WA	7.2.83/95		
			Isd: Airpac Airlines, Seattle WA	84		
			Comanche Air, Winthrop WA	28.9.98/06		
			op: Methow Aviation, Everett-Paine Field WA	00/04		
			Aero Equipment LLC, Kenai AK	3.9.08/13		
			Michael W. Renfro, Bethel AK	30.9.13/19		
			reg expired 30.9.19, struck-off USCR	6.1.20		
	NQ2D nha	to Vounastow	n OH 63 on Beckett Aviation, tailwheel:			
	N92D photo Youngstown OH 63 op Beckett Aviation, tailwheel; N9210 noted Everett WA 24.5.90 "Methow" titles;					
	N9210 noted Coeur d'Alene ID 17.10.91 "Methow" in service; N9210 noted Moses Lake WA 8.95 "Methow";					
			A 16.9.04 "Methow", tailwheel, in service;			
3A-473	G18S	N561B	built	.59		
	0100	NJOTD		.39 63/72		
JA-475			Rex Rutter Manufacturing Co, New Orleans LA	78		
54-415						
JA-410			Richard Theriault, Rumford ME	-		
л- <del>-</del> то		(C-GQWX)	ntu: Toronto Piper Sales & Service, Toronto Airport ONT	-		
JA-473		(C-GQWX) C-GOPI	ntu: Toronto Piper Sales & Service, Toronto Airport ONT (inspection at Toronto-Malton 1.79)	-		
JA-473		. ,	ntu: Toronto Piper Sales & Service, Toronto Airport ONT	6.11.78		

	North Cariboo Flying Service, Fort St John BC	8.9.81/82
N32809	Rick Lytjes/ Air America Inc, Avoca PA	25.8.82
	Michael Malone, Fort Pierce FL	9.83
	Indian River Helicopter Service, Fort Pierce FL	3.84
	Florida Airmotive Inc, Lantana-Palm Beach FL	9.84
	Piper East Inc, Concord NH	10.84
	op: Wiggins Airways, Manchester NH	84
	crashed dest. after takeoff, Laconia NH	1.11.84

N32809 accident report 1.11.84: Wiggins Airways;

BA-474	G18S	N377H	International Telephone & Telegraph Corp (IT&T),	
			New York NY	.59/60
			Hamilton Management Corp, Denver CO	63/66
			International Telephone & Telegraph Corp (IT&T),	
			New York NY	69/79
	Hamilton		Africa Inland Mission International, Pearl River NY	.88
	Extended		(delivered from US to Africa via Azors 5.88)	
	Nose	N344EA	Africa Inland Mission International/ AIM Air,	
			Pearl River NY & Nairobi, Kenya	18.7.88/97
			(delivered from Nairobi-Wilson to Lanseria 12.97)	
		ZS-OEP	Luis Rebelo/ Mid-Dav Pty Ltd, Lanseria	19.12.97
			Saxon Wings	
			damaged in emergency landing	14.3.01
			(stored Lanseria 04, stored dismantled Rand 05/06)	

ZS-OEP noted Lanseria 10.2.98, 12.4.99;

ZS-OEP noted Lanseria 9.5.03 stored without engines, damage to belly;

ZS-OEP noted Lanseria 5.10.03 stored engineless, Hamilton long nose, tailwheel;

ZS-OEP noted Lanseria 18.4.04 stored in Foster Aero hangar;

Further details African ops: see Beech 18 by Robert Parmerter p.299;

ZS-OEP noted Johannesburg-Rand 21.11.05;

ZS-OEP noted Rand 9.5.06 damaged dismantled in SFS hangar, was previously stored Lanseria; ZS-OEP noted Rand 10.06;

BA-475	G18S	N316MU N316Q	Mutual Benefit Health & Accident, Omaha NE rereg	.59/64
		N319A	Duncan Corp, Tarkio MO	66
			SMB Stage Line Inc, Des Moines IA	69/79
			Castle Air, Los Angeles CA	11.81/82
			sale reported, Los Angeles CA	29.7.83/91
BA-476	G18S	N648B	Beech Aircraft Corp, Wichita KS: CofA issued	24.11.59
			Chicago Steel Service Co, Chicago IL	63/64
		N151E	Peter Eckrich & Sons Inc, Fort Wayne IN	66
		N15111	Executive Aircraft Corp, Indianapolis IN	69
			Johnson Flying Service, Indianapolis IN	70/72
		N151H	rereg	12.77
			D. Graves, Brownsburg IN	79
			Indianapolis Air Charter Services, Indianapolis IN	82/86
			Indianaero Inc, Bloomington IN	4.89/91
			Crouch Ag Aviation, Cameron MO	12.94/95
			Ryan Air Service, Anchorage AK	6.4.95
			Arctic Transportation Service, Anchorage AK	9.5.95/99
			damaged in accident, Kotzebue AK	12.9.96
			James M. Johnston, Nome AK	29.11.99/06
		N985S	Thomas Johnston, Wasilla AK	21.10.09/20

N15111 noted Brownsburg IN 29.5.76 enlarged windows;

N151H noted Youngstown OH 17.6.82 Indianapolis Air Charter Services;

YV-717P		78
YV-316C		
YV-668P		83
YV-122CP	Aeroejecutivos C.A., Miranda	.83

YV-717P noted Opa Locka FL 3.10.78, tailwheel;

BA-478	G18S	N180P	built Pilot Freight Carriers Inc, Winston Salem NC Wyman Pilot Service, Pontiac MI	.59 63/72 2.78	
			crashed destroyed on takeoff, Rockingham NC	2.3.78	

N180P noted San Francisco CA 10.69, tailwheel, "Pilot Freight Carriers" titles; N180P accident report 2.3.78: Wyman Pilot Service, cargo flight Rockingham to Pontiac MI, snow on airframe, snow on runway, hit wires after takeoff 8.20pm, pilot hurt;

BA-479	G18S	N9633R	built	.59
			Rent Car Inc, Boise ID	63/64
			Southeastern Beechcraft Inc, Knoxville TN	66/69
			Jim Hankins Air Service, Jackson MS	70/72
			Morey L. Wyman/ Wyman Pilot Service, Pontiac MI	76/81
			damaged, groundlooped on takeoff, Youngstown OH	20.1.77
			struck-off USCR	5.1.81

N9633R accident report 20.1.77: Wyman, flight Youngstown to Pontiac MI, 2.47am, 2 crew unhurt: "pilot had limited use of legs due a prior loss of control in same type of aircraft";

BA-480 (	G18S	N1127M	built	.59
			Miles Laboratories Inc, Elkhart IN	63/64
	N1129M	Miles Laboratories Inc, Elkhart IN	66	
			Ross Aviation, Tulsa-Riverside OK	69
			Great Western Airlines, Tulsa-Riverside OK	70/74
		N112GW	Great Western Airlines, Tulsa-Riverside OK	.74/77
		N146PA	Providence Air Charter, Providence RI	1.4.78/80
		Kurt Fleter	.80	
			Roy Musgrove/ Alaska Express, Anchorage AK	5.81
		crashed destroyed after takeoff, Anvik AK	4.6.81	
			struck-off USCR	10.87

Has been quoted as a turbine conversion but crash photographs show radial engines; N146PA accident report 4.6.81: Alaska Express, stalled on initial climb, cargo flight to Anchorage AK, 188 lbs over max gross weight, destroyed by fire after impact, pilot k.

BA-481	G18S	N233HC	Hooker Chemical Corp, Niagara Falls NY: CofA	16.12.59/64
			Malcolm Jacobs Co, St Louis MO	66
			Frederick H. Beach, Wilmington DE	69/72
			Yankee Aviation, Beloit WI	76/79
			Indianapolis Air Charter Services, Indianapolis IN	12.82/86
			Indianaero Inc, Bloomington IN	6.89/91
			Chris Spatz, Conway AR	2.94
		N584MS	Chris Spatz, Conway AR	7.94/95
		N233H	rereg	
			Bill Ingram/ Quick Air Freight Inc, Danville IL	8.9.97/06
			Michael W. Renfro, Bethel AK	12.2.10/19
			reg expired, struck-off USCR	1.11.19

N233HC noted New York-La Guardia NY 2.61, tailwheel; N233H noted Danville IL 7.10.97 "Quick Air"; N233H at fly-in Oshkosh 1.8.98 polished metallic "Quick Air" titles, owned Bill Ingram, Danville IL and flown by Robert Auman, plate: BA-481 built 12.59; N233H at fly-in Oshkosh 8.99 metallic "Quick Air" titles, Bill Ingram/Quick Air Freight Inc, Danville IL; N233H at fly-in Oshkosh 26.7.01 "Quick Air Freight", tailwheel; N233H noted Springdale AR 12.01 all metallic, tailwheel, op by Quick Air Freight; N233H at fly-in Oshkosh 26.7.02 Quick Air; N233H noted St Louis MO 25.1.03, tailwheel, cargo run; N233H at fly-in Oshkosh WI 30.7.03 Quick Air; N233H at fly-in Oshkosh 7.05 "Quick Alr"; N233H at fly-in Oshkosh 7.06 "Quick Air"; Oshkosh 7.08 "Quick Air" further details: see Beech 18 by Robert Parmerter p. 301-302;

BA-482	G18S	N9696R	Beech Aircraft Corp, Wichita KS: CofA issued	22.12.59
			Duncan Corp, Tarkio MO	63/64
		N138Z	Intermountain Aviation, Marana AZ	66/69
			USDA Forest Service, Albuquerque NM	69/70
	N138ZL	N138ZL	USDA Forest Service, Atlanta GA	71/72
			Federal Extension Service, Stillwater OK	79
			Triangle Aircraft Air Charter, Baldwin KS	3.86/91
			Southwest Assets Inc	94
	N450TA		Aerospace Products Inc, North Hollywood CA	12.4.94/95
			Mid America Transport International Inc, Gibraltar MI	29.6.95/99
			Tellico Air Services, Madisonville TN	22.3.99
		N450TA	Tellico Air Services, Madisonville TN	12.8.99/00
			Professional Air Charter Inc, Nashville TN	16.11.00/02
			Kenneth R. Phillips, Brackettville TX	17.3.04/07
			Kestrel Inc, Waukee IA	30.1.09/20

N138ZL noted Grosse Isle MI 1.98; N450TA at Beech flyin Tullahoma TN 16.10.02;

3A-483	G18S	N9644R	built	.60			
			Texas Power & Light Co, Dallas TX	63/66			
			Richard P. Scaling, Stamford TX	69/79			
			Hammonds Commuter Air Service, Houma LA	81			
			Crow Inc, Millbury OH	9.83/85			
			Olson Air Service, Nome AK	7.91/95			
			John A. Marden, Concord MA	11.95/96			
		AW-01	Tonga Defence Services Air Wing as AW-01	.96/06			
			(fitted maritime surveillance gear Seattle WA,				
			delivered Honolulu-Christmas Island-Pago Pago 2.5.96,				
			Pago Pago-Tonga 4.5.96: for maritime patrols)				
			sold to Tonga, struck-off USCR	19.11.96			
			renamed: Tonga Air Service Air Wing,				
			Nuku'Alofa-Tongatapu, Tonga	94/06			
		atad Cinainat	i OH 17 5 95 Crow Air Freight:				
			i OH 17.5.85 Crow Air Freight;				
	N9644R noted Ottawa ONT 28.7.85 "Crow Air Freight" titles;						
	report 6.96 Seattle with	: purchased l	e: See Beech 18 by Robert Parmerter p.195, 302-303 by Tonga Defence Force from a freight company in Alaska, unveillance and communications equipment; arrived Tonga				
	report 6.96 Seattle with 4.5.96: photo AW- AW-01 not AW-01 not AW-01 not	: purchased l h \$250,000 si 01"Tonga De ed Tonga-Fu ed Auckland- ed Tongatapi	by Tonga Defence Force from a freight company in Alaska,	on delivery flight			
3A-484	report 6.96 Seattle with 4.5.96: photo AW- AW-01 not AW-01 not AW-01 not	: purchased l h \$250,000 si 01"Tonga De ed Tonga-Fu ed Auckland- ed Tongatapi	by Tonga Defence Force from a freight company in Alaska, urveillance and communications equipment; arrived Tonga o fence Services" flying Tonga 96; a'amotu 2.97; Ardmore NZ 8.97 completed after repairs to hurricane dama u, Tonga 16.2.00;	on delivery flight			
3A-484	report 6.96 Seattle with 4.5.96: photo AW- AW-01 not AW-01 not AW-01 not	2: purchased I h \$250,000 si o1"Tonga De ed Tonga-Fu ed Auckland- ed Tongatapu ed Nuku'Alofa	by Tonga Defence Force from a freight company in Alaska, urveillance and communications equipment; arrived Tonga of fence Services" flying Tonga 96; a'amotu 2.97; Ardmore NZ 8.97 completed after repairs to hurricane dama u, Tonga 16.2.00; a-Tongatapu 26.7.06 (AW-02 Bellanca 7GCBC also there) Beech Aircraft Corp, Wichita KS: CofA issued Container Corp of America, Chicago IL	on delivery flight age;			
3A-484	report 6.96 Seattle with 4.5.96: photo AW- AW-01 not AW-01 not AW-01 not	2: purchased I h \$250,000 si o1"Tonga De ed Tonga-Fu ed Auckland- ed Tongatapi ed Nuku'Alofa N228AA	by Tonga Defence Force from a freight company in Alaska, urveillance and communications equipment; arrived Tonga of fence Services" flying Tonga 96; a'amotu 2.97; Ardmore NZ 8.97 completed after repairs to hurricane dama u, Tonga 16.2.00; a-Tongatapu 26.7.06 (AW-02 Bellanca 7GCBC also there) Beech Aircraft Corp, Wichita KS: CofA issued Container Corp of America, Chicago IL Howard A. Weiss, Chicago IL	on delivery flight age; 17.3.60 63/66 69			
3A-484	report 6.96 Seattle with 4.5.96: photo AW- AW-01 not AW-01 not AW-01 not	2: purchased I h \$250,000 si o1"Tonga De ed Tonga-Fu ed Auckland- ed Tongatapi ed Nuku'Alofa N228AA	by Tonga Defence Force from a freight company in Alaska, urveillance and communications equipment; arrived Tonga of fence Services" flying Tonga 96; a'amotu 2.97; Ardmore NZ 8.97 completed after repairs to hurricane dama u, Tonga 16.2.00; a-Tongatapu 26.7.06 (AW-02 Bellanca 7GCBC also there) Beech Aircraft Corp, Wichita KS: CofA issued Container Corp of America, Chicago IL Howard A. Weiss, Chicago IL SMB Stage Line Inc, Des Moines IA	on delivery flight age; 17.3.60 63/66 69 .69/81			
3A-484	report 6.96 Seattle with 4.5.96: photo AW- AW-01 not AW-01 not AW-01 not	2: purchased I h \$250,000 si o1"Tonga De ed Tonga-Fu ed Auckland- ed Tongatapi ed Nuku'Alofa N228AA	by Tonga Defence Force from a freight company in Alaska, urveillance and communications equipment; arrived Tonga of fence Services" flying Tonga 96; a'amotu 2.97; Ardmore NZ 8.97 completed after repairs to hurricane dama u, Tonga 16.2.00; a-Tongatapu 26.7.06 (AW-02 Bellanca 7GCBC also there) Beech Aircraft Corp, Wichita KS: CofA issued Container Corp of America, Chicago IL Howard A. Weiss, Chicago IL	on delivery flight age; 17.3.60 63/66 69 .69/81			
3A-484	report 6.96 Seattle with 4.5.96: photo AW- AW-01 not AW-01 not AW-01 not	2: purchased I h \$250,000 si o1"Tonga De ed Tonga-Fu ed Auckland- ed Tongatapi ed Nuku'Alofa N228AA	by Tonga Defence Force from a freight company in Alaska, urveillance and communications equipment; arrived Tonga of fence Services" flying Tonga 96; a'amotu 2.97; Ardmore NZ 8.97 completed after repairs to hurricane dama u, Tonga 16.2.00; a-Tongatapu 26.7.06 (AW-02 Bellanca 7GCBC also there) Beech Aircraft Corp, Wichita KS: CofA issued Container Corp of America, Chicago IL Howard A. Weiss, Chicago IL SMB Stage Line Inc, Des Moines IA	on delivery flight age; 17.3.60 63/66 69 .69/81			
3A-484	report 6.96 Seattle with 4.5.96: photo AW- AW-01 not AW-01 not AW-01 not	2: purchased I h \$250,000 si o1"Tonga De ed Tonga-Fu ed Auckland- ed Tongatapi ed Nuku'Alofa N228AA	by Tonga Defence Force from a freight company in Alaska, urveillance and communications equipment; arrived Tonga of fence Services" flying Tonga 96; a'amotu 2.97; Ardmore NZ 8.97 completed after repairs to hurricane dama u, Tonga 16.2.00; a-Tongatapu 26.7.06 (AW-02 Bellanca 7GCBC also there) Beech Aircraft Corp, Wichita KS: CofA issued Container Corp of America, Chicago IL Howard A. Weiss, Chicago IL SMB Stage Line Inc, Des Moines IA Universal Aircraft Sales & Leasing Inc, Detroit MI: USCR	on delivery flight age; 17.3.60 63/66 69 .69/81 17.6.81/12			

BA-485	G18S	N9660R N517T	built Tennessee Gas Transmission Co. Houston TX	.60 63/64
			Tenneco Inc. Houston TX	66
		N517E	rereg	10.67
			Jess Hall, Houston TX, later Weatherford TX	69/79
			Bohlke International Airways, St Croix, US Virgin Islands	12.84/86
			Tol Air Services, San Juan, Puerto Rico	19.4.91
		N353T	Tol Air Inc, San Juan, Puerto Rico	8.91/96
			ditched in sea off NAS Roosevelt Roads, Puerto Rico	11.12.96

N353T based Antigua 94;

accident report 11.12.96: ditched en route San Juan-St Vincent, diverted due engine problems, aircraft located but pilot not found, accident report quotes owner as MBD Corp;

BA-486	G18S	N542B	Beech Aircraft Corp, Wichita KS: CofA issued	7.1.60
			Welbilt Vulcan Co, Memphis TN	63/64
		National Bank of Commerce, Memphis TN	66	
		Ralph A. Miller, Norfolk VA	69/72	
			Dole Aviation	74
		N145PA	wing struck truck, taxying Boston-Logan MA	6.6.74
			Providence Air Charter, Providence RI	1.4.78/79
			damaged on takeoff, Newburgh NY	5.4.79
			Don Kipp, Palm Beach FL: rest. to USCR	7.81
			Robin Tjader Lechnir, Boston MA	3.82
			Charles Green, Miami FL	28.12.83/14
			last FAA contact with owner 1989: struck-off USCR	5.9.14

Steve Darke quotes this is an unknown turbine conversion;

N542B noted Providence RI 14.8.74;

N542B accident report 6.6.74: Dole Aviation, left wing struck truck crossing taxiway while taxying for takeoff 11.03pm, flight to New York;

BA-487	G18S	N9658R	built	.60
		N965DC	rereg	00/04
		N686E	H. L. Coble Construction Co, Greensboro NC	63/64
		N661JB N6614B	CC Leasing Corp, Baltimore MD	66 69/72
		N0014B	Priority Air Despatch Inc, Washington-National DC	
			right gear collapsed landing, Griffiss AFB NY	2.12.69
			Semo Aviation, Malden MO	8.6.73/75 6.3.75
			crashed destroyed near Troy AL	0.3.75
			quotes "N4416B": Priority Air Despatch: right gear fatigu	
			6.3.75: Semo Aviation, mail flight Montgomery AI to Troy	v, struck trees on
	approach	in fog, destroy	ved, pilot k, 3.50am;	
BA-488	G18S	N9659R	Beech Aircraft Corp, Wichita KS: CofA issued	14.1.60
		N119T	Texas Eastern Transmission Corp, Shreveport LA	63/66
			Johnson Flying Service, Missoula MT	69/73
			Evergreen Air of Montana, Missoula MT	10.75/77
			Clyde Frederickson, Polson MT	79
			sale reported, Jonesboro GA: USCR	91
	N119T nc	oted Missoula I	MT 21.7.73 JFS, red scheme;	
DA 190	C199	ND74AA	E I duDont do Nomoure ( 'o Inc. )////minaton LIE	60/61
BA-489	G18S	N274AA	E. I. duPont de Nemours Co Inc, Wilmington DE	.60/64
BA-489	G18S	N573D	E. I. duPont de Nemours Co Inc, Wilmington DE	.60/64 66
BA-489	G18S		E. I. duPont de Nemours Co Inc, Wilmington DE Jack R. Peck/ Alaska Aeronautical Industries,	66
BA-489	G18S	N573D	E. I. duPont de Nemours Co Inc, Wilmington DE Jack R. Peck/ Alaska Aeronautical Industries, Anchorage AK	66 12.1.68
BA-489	G18S	N573D	E. I. duPont de Nemours Co Inc, Wilmington DE Jack R. Peck/ Alaska Aeronautical Industries,	66
	G18S G18S	N573D	E. I. duPont de Nemours Co Inc, Wilmington DE Jack R. Peck/ Alaska Aeronautical Industries, Anchorage AK crashed destroyed landing, Sanak Island, Kenai AK Beech Aircraft Corp, Wichita KS: CofA issued	66 12.1.68
		N573D N5730U	E. I. duPont de Nemours Co Inc, Wilmington DE Jack R. Peck/ Alaska Aeronautical Industries, Anchorage AK crashed destroyed landing, Sanak Island, Kenai AK Beech Aircraft Corp, Wichita KS: CofA issued Jones & Loughlin Steel Corp, Pittsburgh PA	66 12.1.68 18.12.68
		N573D N5730U	E. I. duPont de Nemours Co Inc, Wilmington DE Jack R. Peck/ Alaska Aeronautical Industries, Anchorage AK crashed destroyed landing, Sanak Island, Kenai AK Beech Aircraft Corp, Wichita KS: CofA issued	66 12.1.68 18.12.68 19.1.60
BA-489 BA-490		N573D N5730U	E. I. duPont de Nemours Co Inc, Wilmington DE Jack R. Peck/ Alaska Aeronautical Industries, Anchorage AK crashed destroyed landing, Sanak Island, Kenai AK Beech Aircraft Corp, Wichita KS: CofA issued Jones & Loughlin Steel Corp, Pittsburgh PA	66 12.1.68 18.12.68 19.1.60 63/66

		XB-DHM Oscar K. B	reg alderrama, Hermosillo	c91 93		
BA-491	G18S	N9681R XB-MAH	Alamo Aviation Inc, San Antonio TX sold to Mexico, struck-off USCR reg. R. F. Corona, Guadalajara	12.2.60/62 9.3.62 .62 77		
BA-492	G18S	N9662R	built	.60		
		N104KC	Pioneer Aircraft Leasing Corp, Burbank CA Kern County Land Co, San Francisco CA M. R. Clarke Co, San Leandro CA Union Flights, Sacramento CA crashed destroyed on takeoff, Sacramento-Executive C	63/64 66 69/79 29.6.78/79 CA 4.1.79		
	N104KC r	noted Hayward	ncisco CA 4.8.66 (rep as "N9626R" assumed this acft) I CA 3.8.71; t 4.1.79: Union Flights: stalled after takeoff, 5.38pm, 2 cre	w k;		
BA-493	G18S	HZ-IBN	Mohammed bin Ladin/ Bin Ladin Corp crashed near Abha, Saudi Arabia	4.60/67 3.9.67		
	HZ-IBN fu	irther details: s	ee Beech 18 by Robert Parmerter p.300;			
BA-494	G18S	N9690R	Beech Aircraft Corp, Wichita KS: CofA issued Poole Motors Inc, Raleigh NC Federal Resources Corp, Salt Lake City UT Cape Air Leasing, Hyannis MA Gull Air, Hyannis MA & West Palm Beach FL Aviation One Inc Lake Clark Air Inc, Port Alsworth AK Jet Air Express Inc, Wilmington DE Aerolease of America Inc, Carson City NV Tropic Air Cargo, Sebastian FL Dove Enterprises LLC, Wilmington DE op: Aztec Worldwide Airlines Inc, Fort Lauderdale FL	27.1.60 63/64 66/72 79 77/86 7.87 7.88/96 6.2.96/99 13.10.99/02 20.3.03/05 27.12.05/19 06/19		
	N9690R noted Hyannis MA 3.4.78 "Gull Air" titles, tailwheel in service; N9690R noted Hyannis MA 27.9.80 "Gull Air", tailwheel, plate BA-494; N9690R photo 4.85 "Gull Air" tailwheel; N9690R noted Anchiorage-Merrill Field 27.5.90; N9690R noted Houston-Hobby TX 19.11.98, op Jet Air Express Inc (no titles), tailwheel; N9690R noted Fort Laudwerdale Executive FL 2.11.04; N9690R noted North Perry FL 3.4.06 "Aztec Airways" titles, freighter no windows, tailwheel; N9690R noted Nassau, Bahamas 22.11.06 "Aztec Airways" titles, tailwheel, in service;					
BA-495	G18S	N9669R	Beech Aircraft Corp, Wichita KS: CofA issued Custom Finance Co, Vicksburg MS Clark Equipment Co, Buchanan MI	4.2.60 63/64 66/69		
		CF-IGD	Niles Airways, Niles MI Koenena Air Service Ltd, Yellowknife NWT Aviair Aviation Ltd, Kamloops BC sold to USA: struck off Canadian Register	70/72 11.73/76 .82/87 4.87		
		N9669R	Richard Wixom/ Blackhawk Airways, Janesville WI Blackhawk Airways, Janesville WI Flight Training Centre, Janesville WI Gail Force Corp, Janesville WI William B. Baum, Seattle WA Rogers Racing & Restorations Inc, Mukilteo WA Matt Engram, Branson MO	4.87 8.4.87/91 1.94/96 11.96 18.9.98/99 14.5.01/11 8.12.11/16 20.4.16/20		
	N9669R n N9669R n N9669R n	noted Willow R noted Janesvill noted Janesvill	e-Rock County WI 7.91 "Blackhawk AW", plate BA-495; Jun MI 11.11.97 Blackhawk; e-Rock County WI 2.8.98 Gail Force Express, e WI 26.7.99 Gail Force, plate: BA-495 built 1.60; I IL 31.7.00 at Courtesy Aircraft for resale;			

N9669R noted Bellingham WA 6.03 "Aire Marjorie" titles, civil scheme, tailwheel, i/s; N9669R noted Arlington WA flyin 12.7.03, tailwheel, "US Army 04771 82<sup>ND</sup> AIRBORNE DIVISION"; N969R at flyin Arlington WA 7.7.05; Adv for sale 11.15 Courtesy Aircraft: TT 13,454 hrs, same Army paint scheme

BA-496	G18S	N9675R	built	.60
			Sunnyland Packing Co, Thomasville GA	63/64
	N675SP	Sunnyland Packing Co, Thomasville GA	66	
	N6750P	Domestic Aviation, Millersburg OH	69/70	
		Ross Aviation, Tulsa-Riverside OK	71/72	
		Great Western Airlines, Tulsa-Riverside OK	77/79	
			Aero Transit Inc, Danvers MA	.80
			ACE Air Cargo Express Inc, Cleveland OH	1.83/86
			Royal Air Freight, Pontiac MI	20.1.89/91
			sold to Venezuala, struck-off USCR	4.2.91
		YV-757C	Aviogenex Cargo	95
			retired on airport dump, Caracas	99

N6750P noted Terre Haute IN 14.12.85 Ace Air Cargo; YV-757C noted Caracas 24.9.99 on dump;

BA-497	E18S		(E18S model from G18S production line)	3.60
		N901T (1	Skyways Aircraft Ferrying Service Inc, Los Angeles CA	31.3.60
			sold to Japan, struck-off USCR	26.5.60
		JA5060	Japan Civil Aviation Bureau, Civil Aviation College	4.60
			Ministry of Transportation, Miyazaki	65
			Civil Aviation College, Sendai	70
			retired, broken-up: struck-off Register	18.6.74

Produced by Beech with E18S style cockpit windows, 5 cabin seats plus jumpseat: see Beech 18 by Robert Parmerter p.286;

BA-498	G18S	N161M	built	.60
			General Development Air Service, Miami FL	63
			Beach Air Service, Fort Lauderdale FL	64
			Big Dutchman Inc, Zeeland MI	66
			US Industries Inc, Zeeland MI	69/70
			Joseph Fontana, Kingsford MI	71/72
		N75FA	Flight Express Cargo, Essington PA	24.2.77
			crashed after takeoff, Pittsburgh PA	17.8.77

N75FA accident report: flight Pittsburgh to Cleveland OH, engine failed after takeoff, crashed during forced landing back on airport, stalled in, 5.41am, 2 hurt;

BA-499	G18S	PT-BFX	built	.60	
			Central Electrica de Furnas SA, Rio de Janeiro	65	
			Taxi Aereo Rio Ltda, Rio de Janeiro	83	

PT-BFX noted Rio-Santos Dumont 8.1.68; PT-BFX noted Rio-Santos Dumont 10.3.72 Taxi Aereo Rio;

BA-500	G18S	N9684R	built	.60	
			Koss Construction Co, Des Moines IA	63/69	
			Streamline Pastics Inc, Knoxville TN	70/72	
			Great Western Airlines, Tulsa-Riverside OK	74/80	
			Deral D. Browning, Roanoke AL	28.4.80	
			crashed on takeoff, Atlanta-Charlie Brown GA	13.12.80	
	N9684R noted Chicago-O'Hare 18.5.74 Great Western Airlines; N9684R noted Dayton OH 27.5.76 Great Western Airlines; N9684R accident report 13.12.80: operator not quoted, aborted takeoff, ran off runway and struck trees, fire after impact, 6.01am; 1700 lbs over gross weight, CofG 7.6 inches beyond aft limit, pilot had 22 hrs flight time since last layoff, frost on airframe;				

N704GP	Georgia Pacific Corp, Portland OR	69/72
CF-BUS	Pacific Coastal Airlines	11.72
	Northern Thunderbird Air, Prince George BC	74
	Central BC Air Services, Kamloops BC	76/77
	North Cariboo Flying Service, Fort Saint John BC named <i>White Tornado</i>	80
	crashed into mountain slope, 80M north of Saint John BC	.80
	struck-off Register	4.81
	(wreck in situ at 3,000 feet elevation, seen 8.16)	

CF-BUS noted Kamloops BC 27.9.77, in service, blue & white, no titles; CF-BUS wreck in situ on mountain slope at 3,000 ft AMSL, fuselage intact;

	G18S	N9683R N100X (2	Beech Aircraft Corp, Wichita KS: CofA issued American Snuff Co, Memphis TN	15.2.60 63/64
		N189X	rereg	
		N188X	Rowan Drilling Co, Fort Worth TX	66
			M. L. Mulcher Co, Virden IL	69/70
			struck truck taxying after landing, Springfield IL	29.8.0
			St Germaine Aviation, Hinsdale IL	71/72
			damaged when hit snowbank landing, Oshkosh WI	4.3.75
			Eugene Pikowsky, Minneapolis MN	76/79
			op: Viking International Air Freight, Minneapolis MN	76/79
			Dave Davis, League City TX	3.3.82/12
			struck-off Register	14.8.12
BA-503	G18S	N269A	built	.60
			John T. Dorrance, Gladwyne PA	63/64
		N375S	International Salt Co, Flemington NJ	66/70
			Elk Mountain Flying Service, Kinston NC	71/72
			Jack Hudson, Gallup NM	79
			Ronald W. Smith/ Smithair, Atlanta GA	15.9.78/91
			badly damaged by windstorm, Atlanta GA	19.11.81
			struck-off USCR	21.6.91
BA-504	G18S	N1847R	built	.60
			Rahr Malting Co, Manitowoc WI	63/70
		N74FA	Fontana Aviation, Iron Mountain MI	71/72
			K-Airways Inc, Kenosha WI	79/86
			crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta,	22.2.86
	Pilot calls descende	to ATC non-st	crashed on mountain, destroyed, Copperhill TN	22.2.86
BA-505	Pilot calls descende	to ATC non-st d without clear	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued	22.2.86
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN	22.2.86 18.2.60 63/66
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC	22.2.86 18.2.60 63/66 69
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS	22.2.86 18.2.60 63/66 69 70/72
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI	22.2.86 18.2.60 63/66 69 70/72 79/84
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR	22.2.86 18.2.60 63/66 69 70/72 79/84
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts (stripped hulk in compound Texarkana TX 97/08)	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88 16.6.89/97 97/03
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts (stripped hulk in compound Texarkana TX 97/08) Tom May/ May Air Xpress, New Boston TX: for parts	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88 16.6.89/97 97/03 03
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts (stripped hulk in compound Texarkana TX 97/08) Tom May/ May Air Xpress, New Boston TX: for parts struck-off USCR	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88 16.6.89/97 97/03
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts (stripped hulk in compound Texarkana TX 97/08) Tom May/ May Air Xpress, New Boston TX: for parts struck-off USCR Steve Dean/ Flight of the Phoenix Aviation Museum,	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88 16.6.89/97 97/03 03 1.7.13
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts (stripped hulk in compound Texarkana TX 97/08) Tom May/ May Air Xpress, New Boston TX: for parts struck-off USCR Steve Dean/ Flight of the Phoenix Aviation Museum, Gilmer TX	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88 16.6.89/97 97/03 03
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts (stripped hulk in compound Texarkana TX 97/08) Tom May/ May Air Xpress, New Boston TX: for parts struck-off USCR Steve Dean/ Flight of the Phoenix Aviation Museum, Gilmer TX (awaiting collection from Texarkana 03/08, planned to	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88 16.6.89/97 97/03 03 1.7.13
BA-505	Pilot calls descende operator k	to ATC non-st d without clear <-Airways Inc;	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts (stripped hulk in compound Texarkana TX 97/08) Tom May/ May Air Xpress, New Boston TX: for parts struck-off USCR Steve Dean/ Flight of the Phoenix Aviation Museum, Gilmer TX	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88 16.6.89/97 97/03 03 1.7.13
BA-505	Pilot calls descende operator k G18S N9682R n	to ATC non-st d without clear <-Airways Inc; N9682R	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts (stripped hulk in compound Texarkana TX 97/08) Tom May/ May Air Xpress, New Boston TX: for parts struck-off USCR Steve Dean/ Flight of the Phoenix Aviation Museum, Gilmer TX (awaiting collection from Texarkana 03/08, planned to be restored for static display)	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88 16.6.89/97 97/03 03 1.7.13 .03
BA-505	Pilot calls descende operator k G18S N9682R n N9682R n	to ATC non-st d without clear <-Airways Inc; N9682R N9682R noted Dallas-FT noted Texarkan	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts (stripped hulk in compound Texarkana TX 97/08) Tom May/ May Air Xpress, New Boston TX: for parts struck-off USCR Steve Dean/ Flight of the Phoenix Aviation Museum, Gilmer TX (awaiting collection from Texarkana 03/08, planned to be restored for static display) TW TX 12.93, all metallic, in service; the AR 8.97 & 6.8.98 & 16.8.99: all metallic, dismantled in the	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88 16.6.89/97 97/03 03 1.7.13 .03
BA-505	Pilot calls descende operator k G18S N9682R n N9682R n N9682R n	to ATC non-st d without clear <-Airways Inc; N9682R N9682R noted Dallas-FT noted Texarkan	crashed on mountain, destroyed, Copperhill TN night freight flight Kenosha WI to Milwaukee then Atlanta, andard then no replies, acft cruising 11,000 feet until rance, struck trees on a moiuntain, crashed and burned, Beech Aircraft Corp, Wichita KS: CofA issued Bailey Leasing Corp, Fort Wayne IN Howard A. Weiss, Washington DC Jim Hankins Air Service, Jackson MS Morey Wyman/ Wyman Pilot Service, Pontiac MI Aaron T. Hale, Cleveland OH Hale Aviation, Romulus MI: USCR M. Corley Tedder, Texarkana TX: for parts (stripped hulk in compound Texarkana TX 97/08) Tom May/ May Air Xpress, New Boston TX: for parts struck-off USCR Steve Dean/ Flight of the Phoenix Aviation Museum, Gilmer TX (awaiting collection from Texarkana 03/08, planned to be restored for static display)	22.2.86 18.2.60 63/66 69 70/72 79/84 7.88 16.6.89/97 97/03 03 1.7.13 .03 compound;

not beenbcollected by 8.03, unmovedTexarkana 22.7.08 dismantled;

BA-506	G18S	N9649R	Beech Aircraft Corp, Wichita KS: CofA issued International Milling Co, Minneapolis MN Titus Manufacturing Co, Waterloo IA	23.2.60 63/64 66		
		N735EB	E. T. Barwick Industries, Chamblee GA	69		
		N732EB	E. T. Barwick Industries, Chamblee GA	70/72		
			Southland Flyers Inc, Memphis TN	29.12.77/14		
			last owner contact with FAA 1984, struck-off USCR	17.11.14		
		N732EB	Kris A. Nace, Glendale OR: rest. to USCR	22.9.17/20		
	N9649R noted Atlanta GA 3.10.68; N732EB noted Oklahoma City OK 6.9.79 no titles, tailwheel; N732EB noted Memphis TN 5.80;					
BA-507	G18S	N941S	built	.60		
			Stokely Van Camp Inc, Indianapolis IN	63/66		
		N9415	Diehl Machines Inc, Wabash IN	69		
			Champion Pneumatic Machinery Co, Princeton IL	70/72		
			Gilley Airways Corp, Hartsville SC	30.3.76/77		
			struck-off USCR	11.11.77		
BA-508	G18S	N9689R	built	.60		
			Dorsey Trailers, Elba AL	63/69		
		N844C	PA Glass Sand Co, Wilmington DE	70/79		
		N843C	Pennsylvania Glass Sand Corp, Wilmington DE	5.80		
			struck-off USCR	8.12.86		
BA-509	G18S	XC-CEO	Mexican Government	.60		
		XC-CNI	Mexican Government			
		N36F	Johnson Flying Service, Missoula MT	69/75		
			Evergreen Air of Montana, Missoula MT	10.75/77		
	Volpar Turboliner II		(converted to <i>Volpar Turboliner II</i> 16.8.77, conv. No.21: special long range version <i>Asterix VLR</i> )			
	Asterix VLR		sold to France, struck-off USCR	30.9.77		
		F-ODHJ	SA Interthon, Abidjan, Ivory Coast	13.6.78/91		
			op: Ste Interthon, Mahe	90		
			op: Saipex Aero	91		
			sold to USA, struck-off French Register	22.4.91		
		N81CK	American International Airways, Detroit MI	17.4.91		
			Kalitta Flying Service, Detroit-Willow Run MI	11.92/99		
			Kitty Hawk Charters Inc, Morristown TN	6.5.99/02		
			Jim Hankins Air Service, Jackson MS	7.1.02/14		
			(purchased 10.01 at Kitty Hawk auction \$78.5K, TT 20.9076 hrs)			
		N320GB	GB Airlink Inc, Fort Lauderdale FL	18.9.14/19		
		NJZUGD	Airsquid Aviation, Las Vegas NV	3.1.20		

Asterix VLR was a special long range reconnaissance model for intertion at Abidjan: standard additional 757 litres in 2 cabin tanks extending range to 2200NM: used for fish spotting: see Beech 18 by Robert Parmerter p.392;

N36F noted Missoula MT 21.7.73 JFS, blue scheme;

N81CK noted Willow Run 7.91 at Kalitta ramp, Turboliner, retired stored, F-ODHJ visible;

N81CK noted Willow Run 8.96 Kalitta, as Turboliner;

N81CK noted Willow Run MI 2.3.97, 5.97;

N81CK noted Willow Run 23.7.00, Kitty Hawk Charters, Volpar Turboliner, plate BA-509 built 3.60; N81CK noted Jackson MS 1.8.02 plate G18S BA-509 built 3.60, Turboliner serial 021 date 8.77; N81CK noted Jackson-Hawkins Field MS 5.8.03 Volpar, "JHAS" titles;

N81CK noted Panama City FL 13.8.05 turbine Trigear Hankins Air Service;

N81CK noted Jackson-Hawkins Field MS 5.8.08 Turboliner;

Connie Kalitta had an auction of retired turbine Beech 18s at Willow Run 7.02:

- N231LJ (Bu23835) sold to Nick Quint/Blackhawk Airways for \$2500, towed by road to Janesvill 7.02;

- Jim Hankins purchased N231SK, N4209V, N81CK, N404CK

- 10 others broken up for scrap - 5 cockpit & nose sections purchased by Dave Warren, Tulsa OK;

BA-510	G18S	N9916R	built	.60
			R. H. Fulton, Lubbock TX	63/66
			C. W. Zumbiel Corp, Cincinatti OH	69/70
		N11BZ	C. W. Zumbiel Corp, Cincinatti OH	
		N11ZB	C. W. Zumbiel Corp, Cincinatti OH	71/72
			Wyman Pilot Service, Pontiac MI	10.78
			crashed destroyed landing, Cleveland-Hopkins OH	11.10.78
			18S: Wyman Pilot Service, cargo flight Bowling Green KY t d, crashed wheels-up, cargo shifted, dest: pilot hurt, first flig	
BA-511	G18S	N605V	Beech Aircraft Corp, Wichita KS: CofA issued Kirsch Company, Sturgus MI	11.3.60 63/64
		N605L	rereg	00/01
		N7711S (2		7.8.65
			Travco Inc, Wilmington DE	66/70
			Aircraft Finance Co, Memphis TN	71/72
			op: Great Western Airlines, Tulsa OK	77
			Seymour Canter, Murrieta CA	79
			sale reported	8.81/91
BA-512	G18S	N9680R	built	.60
			Louisiana State Police, Baton Rouge LA	63
			State of Louisiana Public Safety, Baton Rouge LA	64/66
			J. B. McDuff, Burnet TX	69/70
			Tidwell Industries, Haleyville TN	71/72
			Howard G. Schlick, Central Point OR	79
			Air Cortez, Ontario CA	79
			Lucky Seven Airways	80
			(departed Chino CA 9.8.80 on deivery to new owner FL)	
			Wayne Sturtman Aircraft Sales, Merritt Island FL	91/98
			scrapped, struck-off USCR	21.1.98
	N9680R n N9680R n	oted Chino CA	a KS 5.6.76; \ 5.4.80 "Lucky Seven Airways" titles; \ 7.80 "Lucky Seven Airways" titles, tailwheel; departed on delivery to new owner Orlando FL;	
BA-513	G18S	N9900R	built	.60
			Howard Sober Inc, Lansing MI	63/70
			Jerry Moore Inc, Canton OH	71/72
			Frank J. Cannavo/ Aero Taxi, Lester PA	15.4.77/85
			ran off runway on takeoff, struck ditch, gear collapsed,	
			Allentown-Wilkes Barre PA struck-off USCR	2.2.83 20.2.85
	N9900R a	ccident report	2.2.83: Air Taxi Inc, main gear collapsed;	20.2.03
	G18S	N772AA	Atlantic Aviation: CofA issued	19.3.60
RΔ_514	0.00			63/64
BA-514			National Financing Inc. Wilmington LIF	
BA-514			National Financing Inc, Wilmington DE	
BA-514		N610G	IT&T Corp, New York NY	64
BA-514		N610G N710G	IT&T Corp, New York NY IT&T Corp, New York NY	64
BA-514		N610G N710G	IT&T Corp, New York NY IT&T Corp, New York NY IT&T Corp, New York NY	
BA-514			IT&T Corp, New York NY IT&T Corp, New York NY IT&T Corp, New York NY Ford & Ivester Associates, Waltham MA	64 66/76 79
BA-514			IT&T Corp, New York NY IT&T Corp, New York NY IT&T Corp, New York NY Ford & Ivester Associates, Waltham MA GM Airlines, Opa Locka FL	64 66/76 79 6.82
BA-514			IT&T Corp, New York NY IT&T Corp, New York NY IT&T Corp, New York NY Ford & Ivester Associates, Waltham MA GM Airlines, Opa Locka FL Anton J. Koprivnik, Miami FL	64 66/76 79 6.82 3.87/89
BA-514		N710G	IT&T Corp, New York NY IT&T Corp, New York NY IT&T Corp, New York NY Ford & Ivester Associates, Waltham MA GM Airlines, Opa Locka FL Anton J. Koprivnik, Miami FL Reynaldo A. Blanco, Miami FL	64 66/76 79 6.82 3.87/89 4.89/91
BA-514		N710G	IT&T Corp, New York NY IT&T Corp, New York NY IT&T Corp, New York NY Ford & Ivester Associates, Waltham MA GM Airlines, Opa Locka FL Anton J. Koprivnik, Miami FL Reynaldo A. Blanco, Miami FL dam. accident San Andros, Bahamas	64 66/76 79 6.82 3.87/89 4.89/91 20.10.89
BA-514		N710G	IT&T Corp, New York NY IT&T Corp, New York NY IT&T Corp, New York NY Ford & Ivester Associates, Waltham MA GM Airlines, Opa Locka FL Anton J. Koprivnik, Miami FL Reynaldo A. Blanco, Miami FL	64 66/76 79 6.82 3.87/89 4.89/91
BA-514	N772AA c	N710G N610RB	IT&T Corp, New York NY IT&T Corp, New York NY IT&T Corp, New York NY Ford & Ivester Associates, Waltham MA GM Airlines, Opa Locka FL Anton J. Koprivnik, Miami FL Reynaldo A. Blanco, Miami FL dam. accident San Andros, Bahamas Manuel Alen, Miami FL struck-off USCR	64 66/76 79 6.82 3.87/89 4.89/91 20.10.89 18.1.92/14
BA-514		N710G N610RB ohoto La Guarc	IT&T Corp, New York NY IT&T Corp, New York NY IT&T Corp, New York NY Ford & Ivester Associates, Waltham MA GM Airlines, Opa Locka FL Anton J. Koprivnik, Miami FL Reynaldo A. Blanco, Miami FL dam. accident San Andros, Bahamas Manuel Alen, Miami FL struck-off USCR	64 66/76 79 6.82 3.87/89 4.89/91 20.10.89 18.1.92/14
3A-514	N710G nc	N710G N610RB shoto La Guard sted Opa Locká	IT&T Corp, New York NY IT&T Corp, New York NY IT&T Corp, New York NY Ford & Ivester Associates, Waltham MA GM Airlines, Opa Locka FL Anton J. Koprivnik, Miami FL Reynaldo A. Blanco, Miami FL dam. accident San Andros, Bahamas Manuel Alen, Miami FL struck-off USCR	64 66/76 79 6.82 3.87/89 4.89/91 20.10.89 18.1.92/14

BA-515	G18S	N333X N334X	built George Hall Corp, Ogdensburg NY Millers Aviation, Mooresville NC	.60 63/66 20.11.68/91
BA-516	G18S trigear	N9907R N5000T (3	built Thiokol Chemical Corp, Brigham City UT struck-off USCR	.60 31.8.61/72 16.11.72
	N5000T no	oted Deer Valle	ey AZ 7.11.69 trigear;	
BA-517	G18S	N529M N729M	Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued Ohio Aviation Co, Dayton OH	26.3.60/64 70/72
		N300MF (2 N729M	Knight Aircraft Corp, Miami FL Missionary Flights International, West Palm Beach FL Missionary Flights International, West Palm Beach FL Coast Air Freight Inc, Long Beach CA Union Flights, Sacramento CA Jim Jankins Air Service, Jackson MS John C. Hooper, Carriere MS	79 5.80/82 4.82 6.85 1.86/95 27.7.95/97 15.5.97/01
		(N37FC) N729M	Frank U. Cain, Katy-Sugerland TX Frank U. Cain, Katy TX: ntu Classic Flights LLC, Wilmington DE Peanut Butter Investments LLC, Conroe TX	8.7.02/05 7.02 15.6.05/13 1.8.13/20
	N729M no N729M no N729M no N729M no N729M no N729M no titles "Tran	ted Toledo-Exp ted LAX 24.7.8 ted Ontario CA ted Santa Mari ted Sugarland ted West Hous ps Pearl River A	ia CA 11.6.90 Union Flights;	8.60;
BA-518	G18S	N93D	built	.60
BA-519	G18S	N9912R N49K (2	built rereg Walston Aircraft Sales & Service, Alton IL Alton Box Board Co, Alton IL Midwest Piper Sales Inc, Wichita KS Semo Aviation Inc, Malden MO Levitz Aviation Service, Fort Lauderdale FL Aviation One Inc, Cincinatti OH Florida Fresh Seafood, Miami FL H & G Import & Export Corp, Fort Lauderdale FL crashed destroyed by fire, Fort Lauderdale FL K & K Aircraft Inc, Bridgewater VA (for parts) struck-off USCR	.60 6.6.61 63/64 66/70 71/72 76/79 12.83 12.85 10.88/91 94/95 16.2.94 23.2.95 5.6.95
		ed Ft Lauderda ed Tulsa OK 30		

N49K noted Tulsa OK 30.9.71; N49K noted Ft Lauderdale-Exec FL 21.11.83 tailwheel, Levitz Aviation Service, no titles, in service; N49K noted Ft Lauderdale FL 4.11.87;

BA-520	G18S	N9913R	Beech Aircraft Corp, Wichita KS: CofA issued	11.4.60
		N512T	Tennessee Gas Transmission Co, Houston TX	63/64
			Tenneco Inc, Houston TX	66
		N512E	Hickory Springs Manufacturing Co, Hickory NC	69/70
			Tailwinds Inc, Old Brookville NY	79
			Springdale Air Service, Springdale AR	16.6.86/00
			damaged by fire during landing, Springdale AR	2.4.95
			South West Aero Exchange, Owasso OK	00
			(stored dism. fire damaged in salvage vard,	
			Owasso OK 00)	

N512E noted MacArthur NY 8.8.74 Tailwinds Inc; N512E noted Springdale AR 8.97, spares source, fuselage stacked against Springdale Air Service hangar, badly burnt cockpit area on starboard side: plate BA-520 built 3.60; N512E noted Springdale AR 13.10.97 fire damaged; N512E fuselage noted in SW Aero Exchange yard, Owasso OK 10.8.00, plate BA-520 built 3.60, spar kit #178 22.4.75;

BA-521	G18S	N9918R	Beech Aircraft Corp, Wichita KS: CofA issued	12.4.60
			Airfleet Leasing Corp, Gainsville FL	63/64
			George H. Bailey Co, Fort Wayne IN	66
			Cleveland Aero Inc, Cleveland OH	69
			Henry O. Moffett, Centreport NY	70
			op: Eastern Caribbean Airlines	70
			Miami Aviation Corp, Opa Locka FL	71/72
			Lee Maples/ Maples Aviation Co Inc, Rolla MO	11.72/02
			op: Baron Air Services, Rolla MO	98
			John G. Wood, Winter Haven FL	4.2.03/15
			Andrew Hochhaus, Norfolk VA	31.12.15/20
	N9918R r	noted Bridgetov	wn, Barbados 31.5.70 Eastern Caribbean Airlines;	
	N9918R r	noted Opa Loci	ka FL 23.8.71;	
	N9918R á	at fly-in Oshkos	sh WI 30.7.94 owner Lee Maples, won Classic Grand (	Champion;
			tional MO 26.8.98 owned Baron AS, plate: BA-521 buil	
		at fly-in Oshkos		-
			hy MO 7.8.02, plate BA-521;	
			Tullahoma TN 16.10.03;	
		at fly-in Oshkos		
		at fly-in Oshkos		
			Fullahoma TN 14.10.07; same 18.10.14;	
	N9918R 2	at Reech flvin T		
	N9918R a	at Beech flyin T		
3A-522	N9918R a	N9920R	built	.60
BA-522		N9920R	built	.60 63/64
BA-522		-	built Socony Mobil Oil Co, New York NY	
BA-522		N9920R	built	63/64
_	G18S	N9920R N2634 (2 N2634E	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY	63/64 66 69/70
BA-522 BA-523		N9920R N2634 (2	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built	63/64 66 69/70 .60
_	G18S	N9920R N2634 (2 N2634E	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built Burford Toothaker Tractor Co, Montgomery AL	63/64 66 69/70 .60 63
_	G18S	N9920R N2634 (2 N2634E N572B	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built Burford Toothaker Tractor Co, Montgomery AL Burford Equipment Co, Montgomery AL	63/64 66 69/70 .60 63 64/72
_	G18S	N9920R N2634 (2 N2634E N572B N1WF	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built Burford Toothaker Tractor Co, Montgomery AL Burford Equipment Co, Montgomery AL Signal Airmotive Corp, Chatanooga TN	63/64 66 69/70 .60 63 64/72 79
_	G18S	N9920R N2634 (2 N2634E N572B	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built Burford Toothaker Tractor Co, Montgomery AL Burford Equipment Co, Montgomery AL Signal Airmotive Corp, Chatanooga TN rereg	63/64 66 69/70 .60 63 64/72 79 1.79
_	G18S	N9920R N2634 (2 N2634E N572B N1WF	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built Burford Toothaker Tractor Co, Montgomery AL Burford Equipment Co, Montgomery AL Signal Airmotive Corp, Chatanooga TN rereg Sky Train Inc, McAllen TX	63/64 66 69/70 .60 63 64/72 79 1.79 4.82
_	G18S	N9920R N2634 (2 N2634E N572B N1WF	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built Burford Toothaker Tractor Co, Montgomery AL Burford Equipment Co, Montgomery AL Signal Airmotive Corp, Chatanooga TN rereg	63/64 66 69/70 .60 63 64/72 79 1.79
_	G18S	N9920R N2634 (2 N2634E N572B N1WF	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built Burford Toothaker Tractor Co, Montgomery AL Burford Equipment Co, Montgomery AL Signal Airmotive Corp, Chatanooga TN rereg Sky Train Inc, McAllen TX sale reported Beech Aircraft Corp, Wichita KS: CofA issued	63/64 66 69/70 .60 63 64/72 79 1.79 4.82
BA-523	G18S G18S	N9920R N2634 (2 N2634E N572B N1WF N400R	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built Burford Toothaker Tractor Co, Montgomery AL Burford Equipment Co, Montgomery AL Signal Airmotive Corp, Chatanooga TN rereg Sky Train Inc, McAllen TX sale reported	63/64 66 69/70 .60 63 64/72 79 1.79 4.82 14.10.82/97
BA-523	G18S G18S	N9920R N2634 (2 N2634E N572B N1WF N400R	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built Burford Toothaker Tractor Co, Montgomery AL Burford Equipment Co, Montgomery AL Signal Airmotive Corp, Chatanooga TN rereg Sky Train Inc, McAllen TX sale reported Beech Aircraft Corp, Wichita KS: CofA issued Winn Dixie Inc, Greenville SC	63/64 66 69/70 .60 63 64/72 79 1.79 4.82 14.10.82/97 27.4.60
BA-523	G18S G18S	N9920R N2634 (2 N2634E N572B N1WF N400R N9699R	built         Socony Mobil Oil Co, New York NY         Mobile Oil Corp, New York NY         Irving Industries Inc, Lexington KY         built         Burford Toothaker Tractor Co, Montgomery AL         Burford Equipment Co, Montgomery AL         Signal Airmotive Corp, Chatanooga TN         rereg         Sky Train Inc, McAllen TX         sale reported         Beech Aircraft Corp, Wichita KS: CofA issued         Winn Dixie Inc, Greenville SC         Winn Dixie Inc, Greenville SC	63/64 66 69/70 .60 63 64/72 79 1.79 4.82 14.10.82/9 <sup>-</sup> 27.4.60 63/64
BA-523	G18S G18S	N9920R N2634 (2 N2634E N572B N1WF N400R N9699R	built         Socony Mobil Oil Co, New York NY         Mobile Oil Corp, New York NY         Irving Industries Inc, Lexington KY         built         Burford Toothaker Tractor Co, Montgomery AL         Burford Equipment Co, Montgomery AL         Signal Airmotive Corp, Chatanooga TN         rereg         Sky Train Inc, McAllen TX         sale reported         Beech Aircraft Corp, Wichita KS: CofA issued         Winn Dixie Inc, Greenville SC         Winn Dixie Inc, Greenville SC         sale reported: USCR	63/64 66 69/70 .60 63 64/72 79 1.79 4.82 14.10.82/9 <sup>-1</sup> 27.4.60 63/64 66/72 79
BA-523	G18S G18S	N9920R N2634 (2 N2634E N572B N1WF N400R N9699R	built Socony Mobil Oil Co, New York NY Mobile Oil Corp, New York NY Irving Industries Inc, Lexington KY built Burford Toothaker Tractor Co, Montgomery AL Burford Equipment Co, Montgomery AL Signal Airmotive Corp, Chatanooga TN rereg Sky Train Inc, McAllen TX sale reported Beech Aircraft Corp, Wichita KS: CofA issued Winn Dixie Inc, Greenville SC Winn Dixie Inc, Greenville SC sale reported: USCR M. Corley Tedder, Texarkana TX	63/64 66 69/70 .60 63 64/72 79 1.79 4.82 14.10.82/97 27.4.60 63/64 66/72 79 10.82/87
BA-523	G18S G18S	N9920R N2634 (2 N2634E N572B N1WF N400R N9699R	built         Socony Mobil Oil Co, New York NY         Mobile Oil Corp, New York NY         Irving Industries Inc, Lexington KY         built         Burford Toothaker Tractor Co, Montgomery AL         Burford Equipment Co, Montgomery AL         Signal Airmotive Corp, Chatanooga TN         rereg         Sky Train Inc, McAllen TX         sale reported         Beech Aircraft Corp, Wichita KS: CofA issued         Winn Dixie Inc, Greenville SC         Winn Dixie Inc, Greenville SC         sale reported: USCR         M. Corley Tedder, Texarkana TX         Jan E. Goodson, Texarkana TX	63/64 66 69/70 .60 63 64/72 79 1.79 4.82 14.10.82/9 <sup>-1</sup> 27.4.60 63/64 66/72 79 10.82/87 7.87
BA-523	G18S G18S	N9920R N2634 (2 N2634E N572B N1WF N400R N9699R	built         Socony Mobil Oil Co, New York NY         Mobile Oil Corp, New York NY         Irving Industries Inc, Lexington KY         built         Burford Toothaker Tractor Co, Montgomery AL         Burford Equipment Co, Montgomery AL         Signal Airmotive Corp, Chatanooga TN         rereg         Sky Train Inc, McAllen TX         sale reported         Beech Aircraft Corp, Wichita KS: CofA issued         Winn Dixie Inc, Greenville SC         Winn Dixie Inc, Greenville SC         sale reported: USCR         M. Corley Tedder, Texarkana TX         Jan E. Goodson, Texarkana TX         M. Corley Tedder, Texarkana TX	63/64 66 69/70 .60 63 64/72 79 1.79 4.82 14.10.82/9 27.4.60 63/64 66/72 79 10.82/87 7.87 91
BA-523	G18S G18S	N9920R N2634 (2 N2634E N572B N1WF N400R N9699R	built         Socony Mobil Oil Co, New York NY         Mobile Oil Corp, New York NY         Irving Industries Inc, Lexington KY         built         Burford Toothaker Tractor Co, Montgomery AL         Burford Equipment Co, Montgomery AL         Signal Airmotive Corp, Chatanooga TN         rereg         Sky Train Inc, McAllen TX         sale reported         Beech Aircraft Corp, Wichita KS: CofA issued         Winn Dixie Inc, Greenville SC         Winn Dixie Inc, Greenville SC         sale reported: USCR         M. Corley Tedder, Texarkana TX         Jan E. Goodson, Texarkana TX         M. Corley Tedder, Texarkana TX         May Air Xpress, New Boston TX	63/64 66 69/70 .60 63 64/72 79 1.79 4.82 14.10.82/9 <sup>-1</sup> 27.4.60 63/64 66/72 79 10.82/87 7.87 91 12.92/97
BA-523	G18S G18S	N9920R N2634 (2 N2634E N572B N1WF N400R N9699R	built         Socony Mobil Oil Co, New York NY         Mobile Oil Corp, New York NY         Irving Industries Inc, Lexington KY         built         Burford Toothaker Tractor Co, Montgomery AL         Burford Equipment Co, Montgomery AL         Signal Airmotive Corp, Chatanooga TN         rereg         Sky Train Inc, McAllen TX         sale reported         Beech Aircraft Corp, Wichita KS: CofA issued         Winn Dixie Inc, Greenville SC         Winn Dixie Inc, Greenville SC         sale reported: USCR         M. Corley Tedder, Texarkana TX         Jan E. Goodson, Texarkana TX         M. Corley Tedder, Texarkana TX	63/64 66 69/70 .60 63 64/72 79 1.79 4.82 14.10.82/9 27.4.60 63/64 66/72 79 10.82/87 7.87 91

N219W noted Atlanta TX 8.97, plate BA-524 ; N219W noted Atlanta TX 6.8.98 & 16.8.99: both owned Corley M. Tedder, plate: BA-524 built 4.60; N219W noted Atlanta TX 2.8.02 & 6.8.03 both stored inside Corley Tedder hangar;

BA-525	G18S	N9941R	built	.60
			Wiles Holloway Inc, Baton Rouge LA	63
			Goldrus Drilling Co, Houston TX	64
		N941R	Goldrus Drilling Co, Houston TX	66/70
		CF-ZYT	D. C. Plaunt, Sudbury ONT	3.71/72
		N741GB	A. Newton Ball, Anchorage AK	8.77
			forced landing after takeoff, Anchorage AK	17.8.77

			Air Parts Inc, Anchorage AK	78/79
			(stored in Air Parts Inc yard, Anchorage 78/79) struck-off USCR	10.3.81
BA-526	G18S	N277S	Beech Aircraft Corp, Wichita KS: CofA issued	6.6.60
			Hardware Mutual Casualty, Stevens Point WI	63/66 69/72
		N103AF	Airlie Foundation, Warrenton VA Wilmington Flying Service, Troy MI	79
		NIUSAI	Earth Resourced Conservation Society, Atlanta GA	5.82
			Richard J. Wixom/ Blackhawk Airways, Janesville WI (fitted with wings removed from N68V BA-282 c86)	7.86/91
			Blackhawk Airways, Janesville WI	1.94/95
			Gail Force Corp/ Gail Force Express, Beloit WI	10.1.97/00
			Catalina Flying Boats Inc, Long Beach CA	24.11.00/11
			op: Phoenix Airtransport, Phoenix AZ	01/02
			N103AF LLC, Englewood CO	21.1.12/14
			Point to Point LLC, Arlington WA	26.6.14/17
			emergency landing Ketchikan AK due power loss,	
			ditched in sea, sank near Ketchikan AK	3.3.17
	including N Report 6.0 for resale; N103AF no N103AF no N103AF no N103AF no N103AF no	I103AF rotatii 0: Gail Force oted Phoenix oted Long Bea oted Long Bea oted Phoenix oted Deer Val	Express operating Beech 18s on US Mail run Albany NY in ang between maintenance at Blackhawk Airways, Janesville have ceased operations, all their Beech 18s have been flo AZ 3.3.01 no titles; ach CA 29.4.01, ach CA 13.5.01 operated by Catalina Flying Boats; AZ 22.12.02 "Phoenix Airtransport" titles; ley AZ 4.03 "Phoenix Airtransport" titles; Deer Valley 22.5 of WA 20.9.15, blue & white, tailwheel, in service with Point	e WI; own to Rockford IL .08 no titles;
BA-527	G18S	N9940R	built	.60
			Commonwealth Plan Inc, Boston MA	63/64
		N340AP	Commonwealth Plan Inc, Boston MA	66/72
		N75LA	Ellsworth G. Keene, East Bridgewater MA	79/81
			Cape Air Leasing/ Air Cape/ Gull Air, Hyannis MA	5.81/81
			crashed destroyed on takeoff, Hyannis MA	23.5.81
	N75LA acc Hamilton I/ limit, 2 crea	ident report 2 AW STC 1998 w k;	/ilmington DE 2.9.74; 23.5.81: Gull Air, cargo flight Hyannis to Nantucket MA 5.5 5: crashed on initial climb, 1551 lbs above mauw, CofG 31	inches behind aft
BA-528	G18S	N606RP	Ralston Purina Co, Chesterfield MO	.60/72
		N528	Cannavo Aviation, Philadelphia PA	79
			Frank Cannavo/ Aero Taxi Rockford Inc, Rockford IL	84/89
			struck-off USCR	8.3.89
			Cascade Air, Ephrata WA	00
			(wfu stored Ephrata 00/01, Methow titles)	
	N528 fuse	lage noted in	gton-National DC 6.4.66; hangar Ephrata WA 22.3.00 plate BA-528; phrata 22.5.01;	
3A-529	G18S	HB-GAS	reg	.60
	trigear		(delivered to Geneva via Prestwick 19.6.60)	
		F-OBTA 5T-TTA	Ste des Mines de Fer de Mauritanie-Miferma, Port Etier Ste des Mines de Fer de Mauritanie-Miferma, Port Etier CofA suspended at Nouakchott	
			k 19.6.60 Super 18 delivery to Geneva;	
	HB-GAS v	isited Gatwick	( 5.7.60;	

			.3.63 Miferma, ex F-OBTA;	
BA-530	G18S	N176SF N1158S	J. P. Stevens & Co, New York NY Henderson Advertising Agency, Greenville SC sold to Canada, struck-off USCR	.60/63 66/72 27.6.74
		C-GOWQ	Wagner Aviation Ltd, Kingston ONT A. V. Flowers, Kingston ONT	.74 8.74/80
			3SF, N74SF, N75SF & N176SF in row at Wallace NC 4. P.Stevens & Co;	61,
BA-531	G18S	N282A	Beech Aircraft Corp, Wichita KS: CofA issued	31.5.60
		N282AA	North American Aviation, Columbus OH	63/66
			North American Rockwell Corp, El Segundo CA	69/72
			Rockwell International, Columbus OH	79
			Central Skyport Inc, Columbus OH	11.86
			sale reported: USCR	91
BA-532	G18S	N9965R	Beech Aircraft Corp, Wichita KS: CofA issued	20.7.60
		N9965L	Frito Lay Inc, Dallas TX	63/69
			James E. Boyett, East Point GA	70/72
			Dale Jackson, Anchorage AK	15.12.76/77
			op: Klondike Line	77
			badly damaged when struck ruts in ice and snowbank	
			during forced landing off airport, Tyonek AK	4.3.77
BA-533			Klondike Line, cargo flight Anchorage to Tyonek, precau on, pilot unhurt; Beech Aircraft Corp, Wichita KS: CofA issued	7.6.60
			Francis Aviation, Lansing MI	63/69
		NOODOM	reg. pending	70/72
		N933GM	Grimes Manufacturing Co, Urbana OH	-
			Ladd Christiansen, Salt Lake City UT	79 70
			Madison Aviation Centre, London OH	79
			op: General Aviation Inc, Greenville TN	80
		(N933GW)	ntu Cons Air Lossing, Lluennis MA	10.01
		N933GM	Cape Air Leasing, Hyannis MA	12.81
			Gull Air, Hyannis MA & West Palm Beach FL	9.83/86
			Aviation One Inc	7.87
			GC & C Inc, Tampa FL Mark Thiom Enterprises Inc. Temps Fl	1.88
			Mark Thiem Enterprises Inc, Tampa FL	7.88 2.89
			Jim Hankins Air Service, Jackson MS	2.89 7.89/91
			Premium Allied Tool Inc, Owensboro KY	11.93
			Jim Hankins Air Service, Jackson MS	11.93

F-OBTA visited Dakar, Senegal 1.10.62 Miferma, Mauritanie;

			JIII HAIKIIIS AII SEIVICE, JACKSOIT WIS	11.95
			Air Plans Inc, Dover DE	30.3.94/99
			Clyde Peters, Crete NE	98
			Carla J. Payne, Fort Worth TX	24.4.01/06
			Glen W. Ernst, Bend OR	31.1.07/15
			struck-off USCR	30.4.15
		N933GM	Glen W.Ernst Estate, Bend OR: rest. to USCR	1.8.17/18
			Mid-Atlantic Aviation, New Castle DE	12.6.18/20
	N933GM	at fly in Oables	sh 26.7.01 tailwheel;	
	N933GM		Slidell TX 9.5.03;	
BA-534	N933GM G18S		Slidell TX 9.5.03;	9.6.60
BA-534		noted at ranch		9.6.60 63/66
BA-534		noted at ranch	Beech Aircraft Corp, Wichita KS: CofA issued	
BA-534		noted at ranch	Beech Aircraft Corp, Wichita KS: CofA issued El Paso National Bank, El Paso TX	63/66
BA-534		noted at ranch	Beech Aircraft Corp, Wichita KS: CofA issued El Paso National Bank, El Paso TX Edward P. Mayer, Frontenac MO	63/66 69
BA-534		noted at ranch	Beech Aircraft Corp, Wichita KS: CofA issued El Paso National Bank, El Paso TX Edward P. Mayer, Frontenac MO Malcolm Jacobs Aviation, Chesterfield MO	63/66 69 70

	Executive Aviation	85
	damaged, ran off runway on takeoff, Newark NJ	28.8.85
	K & K Aircraft Inc, Bridgewater VA	7.86
	KDW Schools Inc, Arlington TX	7.90/94
	L. H. Underwood & Son Aerial Patrol Inc, Guthrie OK	6.12.94
	sale rep.	98
	Douglas Durning, Oklahoma City OK	99
	Michael B. Ohlinger/ Sterling Air Service,	
	Weslaco-Mid Valley TX, later Mission TX	22.6.01/05
N33KM	Michael B. Ohlinger, Mission TX	5.4.05/15
	Eckles Aircraft LLC, Weslaco TX	4.10.17/20

N9990R noted Chicago O'Hare IL 15.9.79 Great Western, retired stored; N9990R accident report 28.8.85: owned Executive Aviation, freight flight; N9990R at airshow Oklahoma City OK 20.6.98; N9990R noted Weslaco TX 5.5.03; N9990R noted Weslaco-Mid Valley Airport (near McAllen) 10.8.03 owned Michael Ohlinger of Sterling Air Service (also 3 freighter Queenairs): plate BA-534 built 6.60; N33KM noted Weslaco TX 7.8.08;

BA-535	G18S	N530M	Marathon Oil Co, Findlay OH	.60/64
		N730M	Broughton Plant & Equipment Co, Parkersburg WV	66/72
			Midwest Air Charter, Elyria OH	74/79
			minor damage, landed gear-up, Philadelphia PA	10.12.74
			op: Airborne Express	79
			David K. Dill, Indianapolis IN	79
			Indianapolis Air Charter Services, Indianapolis IN	17.9.82
			crashed during takeoff, Indianapolis IN	17.9.82

N730M accident report 10.12.74: Midwest Air Charter, failed to extend gear, 12.10pm;
N730M accident report 17.9.82: Indianapolis Air Charter, swerved on takeoff, left wing dug in,
aircraft spun around, pilot unhurt;

3A-536	G18S	N674Q	built	.60
			Jack Adams Aircraft Sales, Walls MS	63
		XB-JEM	reg	
		N67VQ	reg	
		N268AA	Atlantic Aviation Corp, Wilmington DE	66/70
			N268AA Inc, Fort Lauderdale FL	79
			American Flag Airlines Inc, Fort Lauderdale FL	
			Exuma Express	84/86
			sale reported: USCR	91
			Hill Air Co, Fort Lauderdale FL	9.92
			James E. Sheehan, Pompano Beach FL	8.1.93/05
			scrapped, struck-off USCR	22.9.05
	N268AA r N268AA r N268AA r	noted Ft Laude noted Ft Laude	gton-DCA 30.9.70; erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01;	
34 537	N268AA r N268AA r N268AA r N268AA r	noted Ft Laude noted Ft Laude noted Ft Laude noted Ft Laude	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01;	60
3A-537	N268AA r N268AA r N268AA r	noted Ft Laude noted Ft Laude noted Ft Laude	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01; Transair Ltd, St James MAN	.60
3A-537	N268AA r N268AA r N268AA r N268AA r	noted Ft Laude noted Ft Laude noted Ft Laude noted Ft Laude	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01; Transair Ltd, St James MAN Empire Leasing Corp, Montreal QUE	65/66
3A-537	N268AA r N268AA r N268AA r N268AA r	noted Ft Laude noted Ft Laude noted Ft Laude noted Ft Laude CF-TAE	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01; Transair Ltd, St James MAN Empire Leasing Corp, Montreal QUE Bradley Air Services Ltd, Carp ONT	65/66 70/76
3A-537	N268AA r N268AA r N268AA r N268AA r	noted Ft Laude noted Ft Laude noted Ft Laude noted Ft Laude	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01; Transair Ltd, St James MAN Empire Leasing Corp, Montreal QUE Bradley Air Services Ltd, Carp ONT Bradley Air Services Ltd, Carp ONT	65/66 70/76 76/85
BA-537	N268AA r N268AA r N268AA r N268AA r	noted Ft Laude noted Ft Laude noted Ft Laude noted Ft Laude CF-TAE	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01; Transair Ltd, St James MAN Empire Leasing Corp, Montreal QUE Bradley Air Services Ltd, Carp ONT Bradley Air Services Ltd, Carp ONT Air 500, Toronto ONT	65/66 70/76 76/85 87
3A-537	N268AA r N268AA r N268AA r N268AA r	noted Ft Laude noted Ft Laude noted Ft Laude noted Ft Laude CF-TAE	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01; Transair Ltd, St James MAN Empire Leasing Corp, Montreal QUE Bradley Air Services Ltd, Carp ONT Bradley Air Services Ltd, Carp ONT	65/66 70/76 76/85
3A-537	N268AA r N268AA r N268AA r G18S CF-TAE n	noted Ft Laude noted Ft Laude noted Ft Laude CF-TAE C-FTAE	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01; Transair Ltd, St James MAN Empire Leasing Corp, Montreal QUE Bradley Air Services Ltd, Carp ONT Bradley Air Services Ltd, Carp ONT Air 500, Toronto ONT struck-off Register ALTA 12.9.71 Bradley Air Service;	65/66 70/76 76/85 87
3A-537	N268AA r N268AA r N268AA r G18S CF-TAE n C-FTAE n	noted Ft Laude noted Ft Laude noted Ft Laude CF-TAE C-FTAE noted Calgary	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01; Transair Ltd, St James MAN Empire Leasing Corp, Montreal QUE Bradley Air Services Ltd, Carp ONT Bradley Air Services Ltd, Carp ONT Air 500, Toronto ONT struck-off Register ALTA 12.9.71 Bradley Air Service; g MAN 17.4.79 visitor Bradley AS;	65/66 70/76 76/85 87
3A-537	N268AA r N268AA r N268AA r G18S CF-TAE n C-FTAE n C-FTAE n	noted Ft Laude noted Ft Laude noted Ft Laude CF-TAE C-FTAE noted Calgary in noted Calgary in	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01; Transair Ltd, St James MAN Empire Leasing Corp, Montreal QUE Bradley Air Services Ltd, Carp ONT Bradley Air Services Ltd, Carp ONT Air 500, Toronto ONT struck-off Register ALTA 12.9.71 Bradley Air Service; g MAN 17.4.79 visitor Bradley AS; IT 8.80 "Bradley Air Services" titles, tailwheel;	65/66 70/76 76/85 87
3A-537	N268AA r N268AA r N268AA r G18S G18S CF-TAE n C-FTAE n C-FTAE n C-FTAE n	noted Ft Laude noted Ft Laude noted Ft Laude CF-TAE C-FTAE noted Calgary in noted Calgary in noted Carp ON noted Carp ON	erdale FL 25.10.84; 23.8.87; erdale FL 5.92; erdale FL 21.1.98 retired, stored; erdale 4.4.01; Transair Ltd, St James MAN Empire Leasing Corp, Montreal QUE Bradley Air Services Ltd, Carp ONT Bradley Air Services Ltd, Carp ONT Air 500, Toronto ONT struck-off Register ALTA 12.9.71 Bradley Air Service; g MAN 17.4.79 visitor Bradley AS;	65/66 70/76 76/85 87

BA-538	G18S	N319Z	Beech Aircraft Corp, Wichita KS: CofA issued	7.7.60
			Great Lakes Pipe Line Co, Kansas City MO	63/64
		N351WB	rereg Williama Brea Dina Lina Ca, Tulaa OK	66/60
		N351WP	Williams Bros Pipe Line Co, Tulsa OK	66/69 2.6.69
			landed gear-up, Okmulgee OK Kern Pump Co, Bakersfield CA	70/79
			Old River Crop Dusting Inc, Bakersfield CA	3.82
			Robert A. Younkin, Lowell AR	2.86
			John Dowd/ Syracuse Flying Service, Syracuse KS	1.90/92
			James Warren, Castle Rock CO, later Coeur d'Alene ID	13.7.93/14
			Big Sky EDM Inc, Hayden ID	22.10.14/17
			Gary B. Peters, Clarkston WA	27.4.17/18
			Forte Aviation Parts Inc, Fort Lauderdale FL	5.12.19
			sold to Brazil, struck-off USCR	12.2.20
		PR-WBE	CISA Trading SA	2.20
	N351WP no	oted Bakersfi	eld-Meadows Field CA 20.4.72;	
			Miner Field CA 28.4.84;	
			N 16.10.94, tailwheel, Jim Warren, Castle Rock CO;	
			Wichita KS 10.92 John & Sue Ann Dowd;	
			Wichita KS 11.10.97 John & Sue Ann Dowd; le WI 26.7.99 en route Oshkosh, owned Jim Warren, Denvi	er CO <sup>.</sup>
			sh 8.99, plate BA-538 built 6.60, Jim & Georgia Warren of	er CO,
		k CO, tailwhe		
			nd FL 9.4.00;	
			on WA 7.01 tailwheel;	
			Tullahoma TN 16.10.02;	
			on WA 12.7.03; sh 7.06 plate BA-538 built 6.60;	
	NJJIWI al			
BA-539	G18S	N162DP	Beech Aircraft Corp, Wichita KS: CofA issued	15.7.60
		N321	Federal Mogul Bower Bearings Inc, Detroit MI	63/72
			Semo Aviation Inc/ Semo Airways, Malden MO	79/84
			Farmington Airmotive Inc, Farmington MO Interstate Aviation, Farmington MO	10.84 7.88
			Bowman Aviation, Fort Wayne IN	2.91
			Ralph E. Pingel, Farmington MO	10.90
			Graves Aircraft Inc, El Reno OK	5.91
		N555CG	Graves Aircraft Inc, El Reno OK	6.91
			Grant Aviation, Emmonak AK	16.9.94/99
			damaged at Nome AK	21.3.97
			(fire under cockpit, extinguished with corrosive material	
			which caused severe corrosion) Bob Heckman, Anchorage AK	00
			(ferried to Anchorage for restoration by 00)	00
			Turbo North Aviation, Anchorage AK	00
			Angels of Mercy Ministries, Xenia OH	01/03
			Airplane Services Inc, Jay FL	27.2.03
			Lewis Flying & Maintenance Service, Morse LA	18.8.03
			James C. Bramel, Washington Court OH	27.8.04/05
			Lewis Flying & Maintenance Service, Morse LA	24.3.05/20
			reg expired 31.12.19, struck-off USCR	3.4.20
			ge-Merrill Field AK 8.94;	
	N555CG at	Beech fly-in	Tullahoma TN 14.10.07;	
BA-540	G18S	N94D	Youngstown Airways/ Lease Air, Youngstown OH: CofA	18.7.60/66
		N9412	Beckett Aviation Corp, Youngstown OH	66
		110412	rereg SMB Stage Line Inc, Des Moines IA	69/72
			Perkiomen Airways, Reading PA	9.76/97
			Christopher E. Poindexter, Lone Wolf OK	6.97/11
			struck-off USCR	4.1.11

N9412 noted Chicago-O'Hare 2.4.69 SMB Stage Lines;

BA-541	G18S	N127BD N172SG	built Mayco Investments Inc, Wichita KS George H. Bailey Co, Fort Wayne IN D. L. Peterson Trust, Baltimore MD crashed into mountain, destroyed, Weston VT	.60 63 64 66 19.3.68
BA-542	G18S	N5002T N534D	Beech Aircraft Corp, Wichita KS: CofA issued Thiokol Chemical Corp, Bristol PA Wiles Holloway Inc, Baton Rouge LA Currey Sanders Aircraft Co, Shreveport LA Dale Jackson, Anchorage AK Harold W. Tobey, Anchorage AK Gordon Aviation, Anchorage AK	1.8.60 63/64 66 69/72 79 6.81 12.81/85 8.88/91
		N18DM	Douglas R. Moran, Santa Ana CA Douglas R. Moran, Santa Ana CA Theodore W. Hunt, Waldport OR D & D Air Transport, Houston TX	5.91 12.92 24.8.94
		N502DD	D & D Air Transport, Houston TX D & D Air Transport, Houston TX Christopher C. Cecil, Almont MI (flew in USAAC blue & red scheme) Florida Bahama Trading Co, Palm Beach FL Chart Air Inc, Fort Lauderdale FL Southern Cross Aviation, Wilmington DE Seven Stars Air Cargo Corp, Carolina, Puerto Rico	12.94/95 20.8.97/06 19.12.08/12 3.4.12/17 15.3.17 25.10.18/20
	N534D note N502DD no N502DD no	ed Anchorage Ited Lapeer N Ited Pontiac-(	e-Merrill Field AK 9.79 windowless freighter, no titles; e-Merrill Field AK 10.7.85 Gordon Air Express; /I 7.97; Dakland MI 25.8.02 in blue & red USAAC scheme; Fara Field GA 20.9.17, landed, blue & white, tailswheel;	
BA-543	G18S	N331Z	Beech Aircraft Corp, Wichita KS: CofA issued Bovaird Supply Co, Tulksa OK George H. Bailey Co, Fort Wayne IN Kinder Transportation Corp, Elkhart IN Kinder Manufacturing Co, Elkhart IN Donohoh & Sons Inc, Fort Smith AR	15.8.60 63/64 66 69 70 71/72
		N79LA	Brennan & Hargreaves Inc, Bradley CT gear collapsed landing, Burlington VT Air Cape, Hyannis MA damaed in accident Ridder Air Enterprises, Whitman MA Blackhawk Airways, Janesville WI TELCO, Naperville IL M. Corley Tedder, Texarkana TX Thomas W. May, New Boston TX May Air Xpress, New Boston TX (retired, hulk stored Texarkana AR 98/03) Steve Dean/ Flight of the Phoenix Aviation Museum, Gilmer TX: hulk donated (awaiting collection from Texarkana 8.03) struck-off USCR	76/79 12.6.77 80/81 23.5.81 6.81/83 1.84/85 1.85 10.87 8.88/91 30.7.91/03 .03 9.5.13
	N79LA acci groundloop N79LA note N79LA note N79LA note Tommy Ma	dent report 1 at end of run ed Hyannis M ed Texarkana ed Texarkana	4 27.5.76 "BH" titles; 2.6.77: Brennan & Hargreaves, flight from Hartford CT, inte way, main left gear failed, pilot unhurt, 11.49am; A 9.80 "Air Cape" in service, plate BA-543; A R 6.8.98 & 16.8.99: stripped hulk in compound with 2 of A R 2.8.02 still in compound off airport; S 2 E18S hulks at Texarkana to Steve Dean's museum .03, by 8.03;	ther Beech 18s;
BA-544	G18S	N95D N9511 N999WG	Youngstown Airways/ Lease Air, Youngstown OH: CofA LOM Inc, Youngstown OH Apollo Airways, Detroit MI	15.8.60/66 69/72 76/79

			renamed: Gelco Courier Services, Chicago IL Bryan P. Shaw, Signal Mountain TN (noted Barranquilla, Colombia 4.82 stored in compound of impounded drug running aircaft) struck-off USCR	79 10.8.79 1.7.13
	N999WG I	noted Barranqu	City MI 24.5.76; uilla Colombia 4.82 in impounded drug runners compound paint scheme, less engines and parts;	d,
BA-545	G18S	N318M	built R. L. Manning Co, Denver CO Alexander H. Smith, Baltimore MD Beeline Aviation, Colorado Springs CO Scientific Communications Inc, Chicago IL crashed destroyed after takeoff, Grand Canyon AZ	.60 63/66 69 70 12.8.70/71 16.4.71
			6.4.71: flight Grand Canyon to Los Angeles, pilot turned i high density altitude, 5k;	nto nsing terrain,
BA-546	G18S	N9993R	built Bendix Corp, South Bend IN Your Host Inc, Columbus OH	.60 63/64 66
		N966YH	SMB Stage Line Inc, Des Moines IA Perkiomen Airways Ltd, Reading PA op: Sun International Airways, San Juan, Puerto Rico struck by vehicle on ground, San Juan, puerto Rico damaged in ground-loop on landing, San Juan Christopher E. Poindexter, Lone Wolf OK struck-off USCR	69/72 9.76/97 .76/81 11.5.79 28.1.81 6.97/11 4.1.11
	taxying aft N966YH a	er landing 6.11	11.5.79: Perkiomen Airways: flight Aguadilla PR to San J 1am, pilot & 10 pax unhurt; 28.1.81: Sun International, flight St Thomas USVI-San Ju	
BA-547	G18S	N2000H (3	built Russell Stover Candies Inc, Kansas City MO Grimes Manufacturing Co, Urbana OH	.60 63/64 69
		N932GM	Grimes Manufacturing Co, Urbana OH Johnson Welded Products, Urbana OH op: General Aviation Inc, Greenville TN Madison Aviation Centre, London OH WCW Corp, Midland TX Wood Flying Service, Laredo TX Isd: Viking Express, Chicago-Midway IL struck-off USCR	70/72 79 80 80 5.82 9.11.82/13 89 11.9.13
BA-548	G18S	N9991R N711Y (3 N9991R N18C	Beech Aircraft Corp, Wichita KS: CofA issued Southern Ohio Aviation Sales, West Carrollton OH Terminal Transport Co, Indianapolis IN rereg Commercial Motor Freight, Indianapolis IN	2.9.60 63/64 66 .66 69/72
		N18CK	rereg	

N181WB	Wild Blue Yonder Inc, Goldsby OK	4.4.01/11
	sold to Australian syndicate	7.11
VH-NWB	Neville Pringle, Sydney NSW	22.11.11/12
	(due to depart CA on ferry to Australia 15.2.12)	
	dam. when ran off runway on takeoff for testflight,	
	Hollister CA	14.2.12
	(VH-NWB noted dism. in parts yard, Hollister CA 8.14)	

N18C noted San Antonio TX 16.5.73;

N1800L noted William AZ airshow 10.96: plate BA-548 built 8.60; N1800L advertised for sale 4.97 hangared Scottsdale AZ, excellent condition, contact Curtis Clark; 6.7.00 accident report: owned Wild Blue Yonder Inc, Goldsby OK: FAA inspector giving PPL instruction, ran off runway on takeoff Taos NM: lower right tailplane and rudder damaged, wing skin wrinkled and right main tyre blew out; N181WB noted Chickasha OK 6.10.02 tailwheel, in service; N181WB noted Taos NM 7.10.03 in service, tailwheel, brown & white; Windward Aviation list Be18 VH-NWB as a pending ferry to Australia December 2011, planned to be based at Wedderburn airfield near Sydney; VH-NWB noted Hollister CA dism. damaged aircraft compound 17.8.14, brown & cream paint

scheme;

BA-549	G18S	N299AA	reg	.60
	trigear	N37P	Pure Oil Co, Palatine IL	63/64
	-	N376U	rereg	
		N876U	Jim Hankin Air Service, Jackson MS	69/72
			Brennan Air Freight Inc, Clintonville WI City of Wasau	79
			minor structural damage, cargo door opened on	
			approach, Clintonville WI	9.3.79
			Sair Aviation/ Sair Air Freight, Syracuse NY	.80/83
			crashed destroyed on takeoff, Syracuse NY	24.10.83

N876U noted Milwaukee WI 3.7.79 Brennan Air Freight;

accident report 9.3.79: quoted as "N847U": Brennan Air Freight, flight Milwaukee WI to Clintonville WI, aft cargo door opened, 11pm, pilot unhurt: assumed this acft; N876U noted Syracuse NY 9.8.80 "Sair Air Freight" titles;

BA-550	G18S	N9312Y	Beech Aircraft Corp, Wichita KS: CofA issued	15.9.60
			White Motor Co, Cleveland OH	63/66
			SMB Stage Line Inc, Des Moines IA	69/72
			Perkiomen Airways, Reading PA	79
			Sun International, San Juan, Puerto Rico	80
			Air Pennsylvania	80
			Aurora Air Service, Fairbanks AK	9.83/85
			Ed Begley, Glasgow KY	10.85
			McNeely Charter Service, Earle AR	12.87
			Nighthawk Express, Mankato KS	2.89/91
			May Air Xpress, New Boston TX	5.5.94/97
			crashed destroyed, Crosbytown TX	6.10.97
			· · · · ·	

N9312Y photo 80: based San Juan PR on pax services;

N9312Y noted Aguadilla, Puierto Rico 8.80, tailwheel in service, op by Sun International;

BA-551	G18S	N4353Z	built	.60
		N353Z	Air Ferry International, Pacific Palisades CA	28.10.60
			sold to Japan, struck-off USCR	22.11.60
		JA5503	reg	11.60
			Maritime Safety Board, Kagoshima	65
			Maritime Safety Agency, Kagoshima	70/80
			Ken-Ichi Azuma	81
			retired, struck-off Register	11.4.81
	JA5503 r JA5503 r	• •		

BA-552	G18S	N9300Y	Beech Aircraft Corp, Wichita KS: CofA issued (first G18S with Beech Panoramic Window,	3.10.60
	Junior JATO	N9967L N5722T	also <i>Junior JATO</i> units in engine nacelles) Del Corp/ Frito Lay Inc, Dallas TX minor damage, partial prop failure, near Waco TX O. M. Waters, Alexandria LA National Equipment Rental Ltd, Hyde Park NY Air Best de Puerto Rico, San Juan, Puerto Rico Air Limo of Florida Inc, Miami FL Air Limo of Florida Inc, Miami FL Paradise Aircraft Sales, Murrieta CA Larry G. Bentley, Corona CA Chino Aircraft Sales Inc, Chino CA reg expired, struck-off USCR	63/69 1.5.68 70/72 79 79 1.10.80/86 18.4.86/04 29.11.04/05 15.4.05/06 10/18 8.6.18
	N9967L n N5722T n N5722T n N5722T n N5722T n N5722T n	oted Opa Lock oted Opa Lock oted Corona C oted Corona C oted Corona 1 oted Chino CA	a FL 22.3.87; A 19.8.05 plate BA-522 built 9.60 "Trans Islands" for sale	
BA-553	G18S	F-BJLC	Societe Schneider et Compagnie., Paris-Le Bourget op: Escadrille Mercure/ Taxis Aeriens Mercure, Paris Robert Daire, Pottiers crashed	28.10.60/67 .63/65 6.6.67 24.7.67
	F-BJLC vi F-BJLC vi F-BJLC vi F-BJLC vi	sited Dublin 23	et 6.63; Heathrow 30.10.63 & 14.11.63 both op Taxis Aeriens Merc 8.1.65, Escadrille Mercure, charter from Paris for football r 16.11.65 to Castle Donnington;	
BA-554	G18S	N411UM	built	.60
		N56K (2 N753K	Weyerhaeuser Co, Tacoma WA landed gear-up, Chicago-O'Hare IL Weyerhaeuser Co, Gig Harbour WA	9.2.62/66 17.3.66 69/70
		NY SOIL	exported to Philippines, struck-off USCR	22.5.70
		PI-C1975 RP-C1975	reg Philippine Flour Mills, Manila Greenbelt Products Inc, Manila Central Bank of Philippines, Manila	.70 78 80/81 90
BA-555	G18S	N901TC	built	.60
		N901T (2	rereg	
		N901PC	Investment Securities Co, Wilmington DE Preston Ester, St Louis MO Bank of St Louis, St Louis MO Festus Flying Service, Festus MO crashed destroyed by fire landing, Hays KS	63/64 66/70 71/72 23.2.77/78 16.11.78
			16.11.78: Festus Flying Service, cargo flight Wichita KS approach, freezing drizzle, 3am: pilot & 1 pax k;	
BA-556	G18S	N153X	built	10.60
27, 000	0.00	N625W	Stuart Investment Co, Lincoln NE	63/66

BA-556	G18S	N153X	built	10.60
		N625W	Stuart Investment Co, Lincoln NE	63/66
		N625G	rereg	
		N621NU	University of Nebraska, Lincoln NE	69/70
		N621KE	N. E. Isaacson & Associates, Reedsburg WI	71/72
			Viking International Airlines, Minneapolis MN	79
			Burl-Air Freight Inc, Burlington WI	79/82
			James R. Beardsley/ Crystal Lake School of Aviation,	
			Crystal Lake IL	11.82/83

K & K Aviation, Bridgewater VA	.83
rep. op by Alliance Airlines, Kenosha WI	84
TELCO, Naperville IL	1.85
op: Viking Express, Chicago-Midway IL	87
Thomas W. May, New Boston TX	10.87/94
May Air Xpress, New Boston TX	21.3.94/99
Beech Transportation, Eden Prairie MN	27.4.99
crashed on takeoff, Minneapolis-St Paul MN	23.7.99
(wreck stored St Paul-Flying Cloud MN 00)	

N621KE noted Lexington KY 9.79 no titles, tailwheel; N621KE noted DuPage IL 8.87 Viking Express; N621KE noted Atlanta TX 10.87 plate BA-556; N621KE noted Texarkana AR 8.97 in service May Air Xpress: plate BA-556 built 10.60; accident report 23.7.99: May Air Xpress, tailwheel undercarriage, pilot positioned from Flying Cloud to Minneapolis 5.15am for flight to Duluth MN, right engine lost power airborne at MSP at 7.20AM, attempted to return, heavy landing, ran off runway, gear collapsed, skidded to side of runway;

BA-557	G18S	N9308Y	built	.60
		N607RP	Ralston Purina Co, Chesterfield MO	63/69
		N807P	P. R. Insulation Ltd, Houston TX	70/72
	Hamilton		PCD Corp, McAllen TX	24.3.78/89
	extended		struck drainage ditch on takeoff, McAllen TX	5.7.78
	nose	RP-C986	Metro Manila Airways, Manila	.89/91
			Charles R. Miller/ CM Aero, Manila	93/98
			J. G. Gomez, Clark Field	.00
			(in service 03, with Hamilton long-nose mod)	

N807P accident report 5.7.78: flight McAllen to Tampico, Mexico, aborted takeoff due power loss, 5am, "destroyed", 2 unhurt;

*RP-C*986 noted Manila 2.1.94 tailwheel, standard nose, white with red trim; *RP-C*986 noted Manila 4.2.98 tailwheel, Hamilton long cargo nose, at CM Aero ramp; *RP-C*986 noted Manila 5.03 tailwheel, Hamilton long cargo nose, at CM Aero ramp, doors open operational, white with red trim;

BA-558	G18S	N2222X	Beech Aircraft Corp, Wichita KS: CofA issued	2.11.60
	trigear		Robert Graf Inc, Tarkio MO	63
	C C		Thompson Tractor Co, Birmingham AL	64
		N2222K	rereg	
		N1031B (1	Mack Trucks Inc, Somerville NJ	66
		N10313	Jim Hankins Air Service, Jackson MS	69/72
			nose gear collapsed landing, Boulder City NV	25.2.74
			Stephen Wilmans, Las Vegas NV	79
			Aristera Co, Lubbock TX	8.9.78
			sale rep.	91
			•	

N10313 accident report 25.2.74: nose gear did not fully extend due mechanical fault;

BA-559	G18S	N96D	Youngstown Airways/ Lease Air Inc, Youngstown OH	10.60
			Wean Engineering Co, Warren OH	1.61/64
		N9611	Youngstown Airways/ Lease Air Inc, Youngstown OH	4.65/66
			Bailey Leasing Corp, Fort Wayne IN	3.67
	ATE	N961GP	Georgia Pacific Corp, Augusta GA & Portland OR	6.67/71
	Westwind II	l	(converted by American Turbine Engine Co,	
			Long Beach CA 9.68 as the sole ATE Westwind III,	
			PT-6A-20s with conventional tailwheel, TT 4782 hrs)	
			Hamilton Aircraft Co, Tucson AZ	7.71
			SMB Stage Line Inc, Des Moines IA	21.7.71/85
	Hamilton		(rebuilt as Hamilton Westwind III 9.74 with tailwheel,	
	Westwind II	l	Hamilton Extended Nose, 11230 lb AUW kit,	
			and Hamilton cargo door)	
			Jarex Corp, Columbus IN	9.85
			Jet Way Enterprises Inc, Willow Run MI	11.85
			Ajax Aircraft Leasing Inc, Dover DE	6.87
			Isd: Active Aero Charter, Willow Run MI	.87/89

			Ken & Karl Stoltzfus/K & K Aircraft Inc, Bridgewater VA (agricultural & pest sprayer)	3.91/08
			Suncoast Air Cargo LLC, Palm City FL	29.4.08/12
			Skydive Greene County, Xenia OH	6.3.13
		N74GJ	Skydive Greene County, Xenia OH	19.6.13/20
	N96D visit N961GP r N961GP r	ted Toronto ON notyed Port Col noted Des Moin	umbus IN 26.5.76, Westwind III, "SMB Stage Line"; es IA 26.8.80 Westwind III tailwheel, "SMB Stage Line" tii	tles;
			In MI 3.8.89, Active Aero Charter;	
	N961GP r	noted Los Alam	ale 11.90: Westwind III tailwheel; itos CA 17.8.99 Westwind III, plate BA-559 built 10.60,	
		rcraft" titles, spr noted Los Alam	ayer; itos CA 13.8.02 with other K&K sprayers;	
BA-560	G18S	N847B	Beech Aircraft Corp, Wichita KS: CofA issued	22.11.60
			American Republic Insurance Co, Des Moines IA	63/66
			SMB Stage Line Inc, Des Moines IA	69/78
			Blackhawk Airways, Janesville WI	80/84
			J. Richard Wixom/ Blackhawk Airways, Janesville WI	10.84/86
			General Air Service, Valley City MD	6.89/91
			North Atlantic Seafood, New Middletown OH	2.92
			Alvin H. Dill, New Middletown OH	7.93/97
			Charles H. Hainline, Albany OR	6.97/02
			Anthony R. L. Quadrani, Sagola MI	31.3.03/04
		N727AV (2	Anthony R. L. Quadrani, Sagola MI	8.12.04/06
			Sport Truck LLC, Coldwater MI	4.1.10/11
			Aircraft & Aviation Professionals LLC, Coldwater MI	31.1.12/16
			Zulu Forty One Inc, Anchorage AK	17.1.17/20
	plate: BA-	560 built 11.60	e-Herlong FL 19.8.98, "Hail Lines - Slow but Costly" titles, ; Charles Hainline was setting up P-2 tanker business; o NM 28.2.05 "Hain Lines" titles, in service;	
3A-561	G18S	N9321Y	Beech Aircraft Corp, Wichita KS: CofA issued	15.11.60
		N511WP (2	West Point Manufacturing Co, La Grange GA	63
		N511W (2	West Point Manufacturing Co, La Grange GA	64/69
			Abrams Aerial Surveys, Lansing MI	70/79
			Wayne Sturman Aircraft Sales, Merritt Island FL	10.81/06
			struck-off USCR	17.8.06
	N511W no	oted Albany NY	′ 17.11.75 tailwheel;	
3A-562	G18S	N273V	built	.60
			Wilcox Electric Co, Kansas City MO	63
			Cabot Corp, Pampa TX	64/66
			Henry O. Moffett Co, Centreport NY	69/70
		8P-ECA	Eastern Caribbean Airlines, Seawell	6.71/74
		N273V	reg	.74
			William Mitchell	77/77
			crashed destroyed near Aero Oasis Airport FL	20.8.77
	N273V no	oted Bridgetown	, Barbados 8.12.68;	
			FL 27.5.70 panoramic windows;	
		oted Opa Lock		
		oted Opa Lock		
			0.8.77: stalled on climb for parachuting from Aero Oasis, p	planned flight to
	Immokale		er MAUW, CofG beyond after limit, auto gasoline being us	
3A-563	G18S	N470T	Beech Aircraft Corp, Wichita KS	2.12.60
5, 1 000	0.00		sold to Switzerland, struck-off USCR	27.12.60
		F-BERT	Ste Automobiles M.Berliet, Lyon-Bron	26.1.61/68
			Ste des Entereprises H. Courbot, Montrouge	26.3.68
			Ste Avia Taxi. Paris	19.12.68/78
			JIC AVIA 1 AXI, FAIIS	13.12.00//0

Ste Avia Taxi, Paris

19.12.68/78

Struck-off Register 19.10.78 (stored dism. at La Ferte-Alais 00/11) F-BERT arrived Birmingham 9.1.61 ex Prestwick, to Gatwick next day, F-BERT displayed at Paris Air Show, Le Bourget 3.6.61 with E18S N34L; F-BERT visited Gatwick 14.4.61; F-BERT arrived Perpignan ex Lyon 13.12.61 Automobile Berliet; F-BERT visited Gatwick 24.9.62, Manchester 24-26.9.62; Cambridge 24.10.62 Automobile Berliet; F-BERT visited Edinburgh-Turnhouse 8.7.63 Automobile Berliet; F-BERT noted London-Gatwick 17.2.64, 9.9.64, 30.9.64; F-BERT noted Glasgow 10.9.64 Automobiles Berliet, to Woolsington, plate BA-563; F-BERT arrived Elmdon 28.4.65 ex Paris F-BERT visited Southend 1.6.65 Berliet, from Lyons to Barkstone Heath; F-BERT arrived Southend 30.6.65 Berliet, from Lyons to Cambridge; F-BERT noted Palma Majorca 25.8.66; F-BERT noted Gatwick 9.12.66; F-BERT visited Amsterdam 10.1.68; F-BERT visited London-Heathrow 22.2.68; Amsterdam-Schiphol 28.6.68; Reportedly retired 10.2.69; F-BERT major components noted at La Ferte-Alais 3.9.00; BA-564 G18S N9375Y Beech Aircraft Corp. Wichita KS: CofA issued 7.12.60

BA-904	6185	193751	J. R. Gray Co, Dallas TX William H. Ball, Indianapolis IN Bailey Leasing Corp, Fort Wayne IN Ohio Valley Riggers & Erectors Inc, Dayton OH Aero Services Inc HNT Corp, Sherman Oaks CA Air Cortez International, Ontario CA Able Computer, Irvine CA Union Flights, Sacramento CA Aeronautical Services Inc, Friday Harbour WA	7.12.80 63 64 66 69/72 76 79 .79/84 4.84 11.86 20.4.89/99
			op: Catalina Flying Boats, Long Beach CA minor damage on takeoff, Long Beach CA Catalina Flying Boats Inc, Long Beach CA op: Phoenix Airtransport, Phoenix AZ Nord Aviation, Santa Teresa NM	89/99 23.11.98 28.6.99/06 .02 18.9.07/20
	N9375Y r N9375Y r N9375Y r 83 report: N9375Y r N9375Y r	noted Kansas noted Ontario (noted San Dieg N9275Y with noted Las Veg noted Cange (noted Cang Be noted Long Be noted Cong Be noted Phoenix noted Phoenix noted Long Be	Catalina Flying Boats); ach CA 8.89 at Catalina Flying Boats ramp, plate BA-5 ach CA 9.90, ach CA 7.91 at Catalina Flying Boats ramp, also 4.92, ach 9.11.97 "Catalina Flying Boats" small titles, tailwhe t: ran off runway on takeof LGB, came to rest on dirt of r damage to right outer wing, right gear and tailwheel, flight, pilot Thomas W. Glasgow; ach CA 17.8.99 op Catalina Flying Boats; Sky Harbour AZ 4.01 "Catalina Flying Boats Inc" windo AZ 22.12.02 "Phoenix Airtransport" titles; ach CA 18.8.05 at Catalina Flying Boats;	564; 4.95; eel; ff runway facing operator Catalina owless;
BA-565	G18S	N9374Y	built Bailey Leasing Corp, Fort Wayne IN Central Soya Co, Chicago IL	.60 63/66 69

BA-202	G 185	N9374Y	Dulit	.60	
			Bailey Leasing Corp, Fort Wayne IN	63/66	
			Central Soya Co, Chicago IL	69	
			Duncan Aviation, Omaha NE	70/72	
			Hamilton Aviation, Hamilton OH	73	
			Jimmy F. Godwin, Eustis FL	79	

		C-FKEL	Hoffman Flying Service, Saginaw MI sold to Canada: struck-off USCR V. Kelner Airways Ltd, Pickle Lake ONT 846090 Ontario Ltd, Thunder Bay ONT Wildcountry Airways, Red Lake ONT struck-off register	26.11.84/91 10.5.91 31.5.91/93 1.93/96 21.4.93/05 20.1.05
BA-566	G18S	N9400Y	built Security Insurance Co, New Haven CT Sklar Producing Co, Shreveport LA Sklar & Philips Oil Co, Shreveport LA SS Airways, Kansas City KS ground-loop, struck ditches on takeoff, Lansing IL struck-off USCR	.60 63/64 66/70 71/72 79 17.9.80 3.87
BA-567	G18S		built Stewart Equipment Co, Philadelphia PA DBS Transit Co, Harrisburg PA Fischer Bros Aviation/ Fischer Bros Flight Training/ GCS Airlines, Galion OH Metro Air System, Bardstown KY crashed destroyed by fire Elkton KY (11k)	.60 63/64 66 69/71 22.10.71/72 17.11.72
	N2700S no N2700S no nose (not H N2700S ac	oted Manassas oted Mansfield Hamilton long i ccident report n route in icing	S Airlines - Fischer Bros Aviation" titles, tailwheel; s OH 7.71 "GCS Airlines" titles, tailwheel; OH 7.71 "GCS Airlines" titles, op Fischer Bros Aviation, ta nose); 17.11.72: G18S Metro Air System, flight Hopkinsville KY to conditions, 798 lb over gross weight, CofG 2.72 inches rea	Lexington KY,
BA-568	G18S	N579B (2 N5798 N931GM	Beech Aircraft Corp, Wichita KS: CofA issued E. W. Bliss Co, Canton OH Grimes Manufacturing Co, Urbana OH Grimes Manufacturing Co, Urbana OH Projects Unlimited, Dayton OH op: General Aviation, Greenville TN Madison Aviation Centre, London OH Cape Air Leasing, Hyannis MA op: Gull Air, Hyannis MA Gull Air, Hyannis MA & West Palm Beach FL Aviation One Inc Terrell Leasing Co, Terrell TX Thomas W. May, New Boston TX May Air Xpress, New Boston TX (stripped hulk in compound Texarkana AR 97/08) struck-off USCR	5.1.61 63/64 66/69 70/72 79 80 80 7.81 82 9.83/86 7.87 9.88 3.89/91 9.3.94/13 22.5.13
	N931GM n N931GM n N931GM n	oted Texarkar oted Texarkar oted Texarkar	na AR 8.97 stored in compound near airport with two other na 6.8.98 & 16.8.99 unchanged; na AR 2.8.02, 6.8.03 still in compound off airport; na AR 22.7.08 dismantled in compound with N9682R; na AR 9.17 stripped hulk standing on its wheels;	Beech 18s;
BA-569	G18S	N9423Y	built Bankers Leasing Corp, Boston MA crashed destroyed by fire, wing structural failure in flight, near Toadlena NM	.61 63/64 16.7.64
BA-570	G18S	N766X (1 N652TM XC-CIU	built Volpar Inc, Van Nuys CA Mexican Government	.61 14.11.68/69 -
BA-571	G18S	N9449Y	Beech Aircraft Corp, Wichita KS: CofA issued McLaughlin Inc, Great Falls MT Kiekhaefer Corp, Fond du Lac WI	16.1.61 63/64 66/69

N36BC	Brunswick Corp, Fond du Lac WI (merger) Brunswick Corp, Fond du Lac WI	22.4.69/71 28.6.71
	David B. Fields, Midland TX	10.87
	Glen E. Johnson, Fort Worth TX	8.89/94
	RZM Corp, Evansville IN	5.4.94/95
	Scott White/ Scotts Flying Service,	
	Hockessin DE & Castlewood VA	26.7.95/11
	Bancroft Contracting Corp, South Paris ME	13.6.11/20
N36BC at fly-in Oshkosh N36BC at fly-in Oshkosh N36BC noted Tullahoma N36BC at Beech flyin Tu N36BC at airshow Lakel N36BC at Beech fly-in Tu N36BC at Beech fly-in, T	-in Tullahoma TN 13.10.95, plate BA-571; WI 1.8.96; 1.8.98, Scott White, Castlewood VA, plate: BA-57 TN 4.98; Illahoma TN 16.10.98 tailwheel, Scott & Brenda Wi and FL 4.99 tailwheel, Scott White, Castlewood VA ullahoma TN 10.10.99 Scott White VA;	hite, Castlewood VA;

N36BC at Waco fly-in, Waco TX 25.8.01 plate BA-571; N36BC at Beech fly-in Tullahoma TN 16.10.02;

BA-572	G18S	N9448Y (1	Beech Aircraft Corp, Wichita KS: CofA issued	24.1.61
			Atlantic Aviation Corp, Teterboro NJ	63
		N2427	Owens Corning Fibreglass Corp, Toledo OH	64
			Kiekitaefer Corp, Fond du Lac WI	66/69
			escape hatch released in flight, struck tailplane,	
			landed safely Quincy IL	25.3.66
			Brunswick Corp, Fond du Lac WI (merger)	22.4.69/71
		N34BC	Brunswick Corp, Fond du Lac WI	28.6.71
		N100KU (2	University of Kansas, Lawrence KS	76/79
		N400KU	rereg	1.80
			Ronald W. Smith/ Smithair Inc, Atlanta GA	81/95
			badly damaged by windstorm, Atlanta GA	19.11.81
			Ronald W. Smith, Fort Myers Beach FL	19.1.95
			RBS Aviation Group Inc, Dover DE	25.7.95/05
			Brenda Smith, Jonesboro GA	16.11.05/11
			Daniel R. Gudgel, Hillsboro ND, later Lemoore CA	.13/20

N100KU noted Lawrence KS 3.6.76; N400KU reported in service with Smithair 85; N400KU noted Tara Field GA 5.8.05 plate BA-572 built 1.61, op by Smith Air;

BA-573	G18S	N2019C	Beech Aircraft Corp, Wichita KS: CofA issued	2.2.61
			Smiths Transfer Corp, Staunton VA	63/70
			Goldston Transfer Inc, Eden NC	71/72
		Anderson Aviation, Anderson IN	76/86	
			Dragon Air Inc, Tonawanda NY	8.90/97
			Air Čargo Express Inc, Amherst NY	19.2.97/99
			Pro-Freight Cargo Services Inc, Opa Locka FL	29.2.00
			Great American Transportation Co, Nashville TN	24.10.01/05
		N6B	Great American Transportation Co, Nashville TN	.04/12
			Russell W. Berithgeers, Burns TN	5.9.13/15
			dam. gear-up landing at closed airfield, Nashville TN	22.4.12
			struck-off USCR	3.2.15
	N2019C r	noted Andewrs	son IN 28.5.76:	
			own OH 4.2.83 Anderson Aviation;	
		-	ach FL 28.6.02 "Pro Freight Cargo Service" titles, in servi	ce.
			Tullahoma TN 16.10.03;	,
		•	e-Cornelia Fort Airpark TN 8.4.04 all metallic, tailwheel, in	service;
RΔ-574	G18S	N9461Y	built	61

BA-574	G18S	N9461Y	built	.61
			Tecumseh Products Co, Tecumseh MI	63/64
			Kiekhaefer Corp, Fond du Lac WI	66/69
			Brunswick Corp, Fond du Lac WI (merger)	22.4.69/71

N33BC N38BC	Brunswick Corp, Fond du Lac WI rereg	28.6.71/72
N38RM	Robert Z. Blue, Mount Prospect IL	77/79
	op: Georgia Air Freight	78
	gear collapsed landing, West Chicago-Dupage IL	11.1.78
	P B Leasing Co, Naperville IL	81/82
	Isd: Viking Express Inc, Chicago-Midway IL	81/82
	Miami Valley Bank, Quincey OH	2.82
	struck dirt bank on takeoff, Chicago IL	30.8.82
N103VE	P B Leasing Co, Naperville IL	12.82
	Isd: Viking Express Inc, Chicago-Midway IL	82
N38RM	P B Leasing Co, Naperville IL	17.3.82/91
	op: Viking Express Inc, Chicago-Midway IL	82/91
	crashed on takeoff, West Chicago IL	4.12.91
	•	

N38RM accident report 11.1.78: Georgia Air Freight, flight Grand Rapids MI to West Chicago, mechanical gear failure, 9.45pm, 2 crew unhurt;

BA-575	G18S	N1171	built Borg Warner Gear Division, Muncie IN	.61 63/69
			Borg Warner Corp, Birmingham MI	70/72
			Millwood Aviation, New York NY	27.1.76/80
			struck-off USCR	9.5.80
3A-576	G18S	N576M	Beech Aircraft Corp, Wichita KS: CofA issued	14.2.61
			T. J. O'Connor Cattle Co, Victoria TX	63
			Aggregate Plant Product Co, San Antonio TX	66/72
			Larry Johnson, McAllen TX	79
			Raul A. Lopez, McAllen TX	25.5.83/13
			damaged in accident	21.6.83
			last FAA contact with owner 1989, struck-off USCR	23.4.13
3A-577	G18S	N9490Y	Beech Aircraft Corp, Wichita KS: CofA issued	17.5.61
			Sanders Currey Aircraft Co, Shreveport LA	63
			Ohio Aviation Co, Dayton OH	64
			Sohio Petro Co, Oklahoma City OK	66
			SMB Stage Line Inc, Des Moines IA	69/81
			William R. Sandlin, Harlingen TX	.81
			Castle Air, Los Angeles CA	2.82
			Rainbow Islands Cargo Inc, Honolulu HI	6.83/85
			Sun Pacific Airlines, Honolulu HI	4.85/86
			Sun racine Annines, nonolulu m	4.00/00
			Western Venture Capital Corp, Tulsa OK	11.86/13
	N9490Y r	noted Honolulu	Western Venture Capital Corp, Tulsa OK	11.86/13
3A-578	N9490Y r	noted Honolulu	Western Venture Capital Corp, Tulsa OK struck-off USCR 9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo"; Surinaamse Luchtvaart Maatschappij/ Surinam Airways	11.86/13
3A-578	N9490Y r N9490Y r G18S	noted Honolulu noted Honolulu	Western Venture Capital Corp, Tulsa OK struck-off USCR 9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo"; Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger	11.86/13 23.5.13
3A-578	N9490Y r N9490Y r G18S Junior	noted Honolulu noted Honolulu	<ul> <li>Western Venture Capital Corp, Tulsa OK struck-off USCR</li> <li>9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo";</li> <li>Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin &amp; additional baggage capacity,</li> </ul>	11.86/13 23.5.13
3A-578	N9490Y r N9490Y r G18S	noted Honolulu noted Honolulu PZ-TAQ	Western Venture Capital Corp, Tulsa OK struck-off USCR 9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo"; Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, delivered with Junior Jato units in engine nacelles)	11.86/13 23.5.13
3A-578	N9490Y r N9490Y r G18S Junior	noted Honolulu noted Honolulu	Western Venture Capital Corp, Tulsa OK struck-off USCR 9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo"; Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, delivered with Junior Jato units in engine nacelles) reg	11.86/13 23.5.13
3A-578	N9490Y r N9490Y r G18S Junior	noted Honolulu noted Honolulu PZ-TAQ N50CN	Western Venture Capital Corp, Tulsa OK struck-off USCR 9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo"; Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, delivered with Junior Jato units in engine nacelles)	11.86/13 23.5.13 2.61
BA-578	N9490Y r N9490Y r G18S Junior	noted Honolulu noted Honolulu PZ-TAQ N50CN	Western Venture Capital Corp, Tulsa OK struck-off USCR 9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo"; Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, delivered with Junior Jato units in engine nacelles) reg Fred N. Stalder, Harrisonville MO struck-off USCR	11.86/13 23.5.13 2.61 79
3A-578	N9490Y r N9490Y r G18S Junior	noted Honolulu noted Honolulu PZ-TAQ N50CN	Western Venture Capital Corp, Tulsa OK struck-off USCR 9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo"; Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, delivered with Junior Jato units in engine nacelles) reg Fred N. Stalder, Harrisonville MO	11.86/13 23.5.13 2.61 79 4.82
	N9490Y r N9490Y r G18S Junior	noted Honolulu noted Honolulu PZ-TAQ N50CN	Western Venture Capital Corp, Tulsa OK struck-off USCR 9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo"; Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, delivered with Junior Jato units in engine nacelles) reg Fred N. Stalder, Harrisonville MO struck-off USCR Fred N. Stalder, Harrisonville MO: restored to USCR	11.86/13 23.5.13 2.61 79 4.82 3.86
	N9490Y r N9490Y r G18S Junior JATO	noted Honolulu noted Honolulu PZ-TAQ N50CN N100SS	<ul> <li>Western Venture Capital Corp, Tulsa OK struck-off USCR</li> <li>9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo";</li> <li>Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin &amp; additional baggage capacity, delivered with Junior Jato units in engine nacelles) reg Fred N. Stalder, Harrisonville MO struck-off USCR Fred N. Stalder, Harrisonville MO: restored to USCR struck-off USCR</li> </ul>	11.86/13 23.5.13 2.61 79 4.82 3.86 4.86
	N9490Y r N9490Y r G18S Junior JATO	noted Honolulu noted Honolulu PZ-TAQ N50CN N100SS	Western Venture Capital Corp, Tulsa OK struck-off USCR 9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo"; Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, delivered with Junior Jato units in engine nacelles) reg Fred N. Stalder, Harrisonville MO struck-off USCR Fred N. Stalder, Harrisonville MO: restored to USCR struck-off USCR	11.86/13 23.5.13 2.61 79 4.82 3.86 4.86 4.86
	N9490Y r N9490Y r G18S Junior JATO	N9499Y	<ul> <li>Western Venture Capital Corp, Tulsa OK struck-off USCR</li> <li>9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo";</li> <li>Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin &amp; additional baggage capacity, delivered with Junior Jato units in engine nacelles) reg Fred N. Stalder, Harrisonville MO struck-off USCR Fred N. Stalder, Harrisonville MO: restored to USCR struck-off USCR</li> <li>built Aetna Life Insurance Co, Hartford CT</li> </ul>	11.86/13 23.5.13 2.61 79 4.82 3.86 4.86 4.86 .61 63/64
	N9490Y r N9490Y r G18S Junior JATO	N9499Y N16A	<ul> <li>Western Venture Capital Corp, Tulsa OK struck-off USCR</li> <li>9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo";</li> <li>Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin &amp; additional baggage capacity, delivered with Junior Jato units in engine nacelles) reg Fred N. Stalder, Harrisonville MO struck-off USCR Fred N. Stalder, Harrisonville MO: restored to USCR struck-off USCR</li> <li>built Aetna Life Insurance Co, Hartford CT United Properties Inc, Warwick RI</li> </ul>	11.86/13 23.5.13 2.61 2.61 79 4.82 3.86 4.86 4.86 .61 63/64 66/70
	N9490Y r N9490Y r G18S Junior JATO	N9499Y N16A	<ul> <li>Western Venture Capital Corp, Tulsa OK struck-off USCR</li> <li>9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo";</li> <li>Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin &amp; additional baggage capacity, delivered with Junior Jato units in engine nacelles) reg Fred N. Stalder, Harrisonville MO struck-off USCR Fred N. Stalder, Harrisonville MO: restored to USCR struck-off USCR</li> <li>built Aetna Life Insurance Co, Hartford CT United Properties Inc, Warwick RI Tobey Inc, Wethersfield CT</li> </ul>	11.86/13 23.5.13 2.61 2.61 4.82 3.86 4.86 .61 63/64 66/70 71/72
3A-578 3A-579	N9490Y r N9490Y r G18S Junior JATO	N9499Y N16A	<ul> <li>Western Venture Capital Corp, Tulsa OK struck-off USCR</li> <li>9.83 "Rainbow Islands Cargo", plate BA-577; 12.10.83 Rainbow Islands Cargo tailwheel; 6.84 "Rainbow Islands Cargo";</li> <li>Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin &amp; additional baggage capacity, delivered with Junior Jato units in engine nacelles) reg Fred N. Stalder, Harrisonville MO struck-off USCR Fred N. Stalder, Harrisonville MO: restored to USCR struck-off USCR</li> <li>built Aetna Life Insurance Co, Hartford CT United Properties Inc, Warwick RI Tobey Inc, Wethersfield CT Great Western Airlines, Tulsa-Riverside OK</li> </ul>	11.86/13 23.5.13 2.61 2.61 4.82 3.86 4.86 .61 63/64 66/70 71/72 77

N723T noted Chicago-O'Hare IL 23.10.78; accident report 26.2.86: crashed off runway during landing, owned Richard J. Wixom;

BA-580	G18S	N9966R	Beechcraft Aircraft Corp, Wichita KS	.60/63
B/( 000	H18	1000010	(CofA as G18S 6.7.60, modified as prototype H18,	.00/00
			ff as H18 29.8.60: used for test flying 60/63,	
			H18 FAA type certificate issued 11.7.62,	
			N9966R CofA as H18 issued 5.7.63)	
		N616T (1	Duncan Beechcraft Inc, Tarkio MO	64/66
		N38W (2	Duncan Beechcraft Inc, Tarkio MO	7.66/70
			Josam Manufacturing Co, Michigan City IN	71/72
			Caribe Air, Birmingham AL	79
			Clifford A. Marlatt/ Sky Castle Aviation, New Castle IN	7.5.79/11
			Bank of Utah, Salt Lake City UT: trustee	19.10.11/20
	N38W note	ed New York-J	IFK 21.7.71;	
BA-581	G18S	N9933R	Beech Aircraft Corp, Wichita KS	.61
DA-001	0100	113333311	(Beech demonstrator 61)	.01
			Associates Investment Co, South Bend IN	63/64
	Hamilton	N215W	Burton Supply Co, Youngstown OH	66
	Westwind	1421000	SMB Stage Line Inc, Des Moines IA	69/79
	III		struck snowbank landing, turned over on to back,	00110
			Chicago-O'Hare IL	24.1.79
			Blackhawk Airways, Janesville WI	.79/83
			(wreck purchased, temporary repairs to ferry O'Hare to	.19/00
			Janesville WI .79 with nose from another aircraft &	
			aluminium windshield with small pilot vision holes;	
			rebuilt using C-45H cabin roof from N35136/AF-629,	
			G18S cab, used nose, returned to service 79)	
			struck hill destroyed while low flying under cloud poor	
			struck hill destroyed, while low flying under cloud near	30 6 83
	N215W not	ted Muskogee	Keyser WV ch publicity photos of G18S: central elongated panoramic of OK 2.3.73 SMB Stage Line maintenance base;	30.6.83 cabin window;
	N215W noi N215W noi N215W aci	ted Muskogee ted Ft Worth-I cident report 3	Keyser WV ch publicity photos of G18S: central elongated panoramic of	cabin window;
BA-582	N215W noi N215W noi N215W aci	ted Muskogee ted Ft Worth-I cident report 3	Keyser WV ch publicity photos of G18S: central elongated panoramic of OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 80.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX	cabin window; cloud, pilot k; 12.6.61/63
BA-582	N215W not N215W not N215W act Further det	ted Muskogee ted Ft Worth-I cident report 3 tails on the co	Keyser WV ch publicity photos of G18S: central elongated panoramic of OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302;	cabin window; cloud, pilot k;
	N215W not N215W not N215W act Further det G18S	ted Muskogee ted Ft Worth-I cident report 3 ails on the co N234W (1	Keyser WV ch publicity photos of G18S: central elongated panoramic of OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR	cabin window; cloud, pilot k; 12.6.61/63 11.2.63
	N215W not N215W not N215W act Further det	ted Muskogee ted Ft Worth-I cident report 3 tails on the co	Keyser WV ch publicity photos of G18S: central elongated panoramic of OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN	cabin window; cloud, pilot k; 12.6.61/63
	N215W not N215W not N215W act Further det G18S	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S	Keyser WV ch publicity photos of G18S: central elongated panoramic of OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA	<i>cabin window;</i> <i>cloud, pilot k;</i> 12.6.61/63 11.2.63 .61/63 64/66
	N215W not N215W not N215W act Further det G18S	ted Muskogee ted Ft Worth-I cident report 3 ails on the co N234W (1	Keyser WV ch publicity photos of G18S: central elongated panoramic of OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA	<i>cabin window;</i> <i>cloud, pilot k;</i> 12.6.61/63 11.2.63 .61/63 64/66 69
	N215W not N215W not N215W act Further det G18S	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S	Keyser WV ch publicity photos of G18S: central elongated panoramic of OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN	<i>cabin window;</i> <i>cloud, pilot k;</i> 12.6.61/63 11.2.63 .61/63 64/66 69 70
	N215W not N215W not N215W act Further det G18S	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S	Keyser WV ch publicity photos of G18S: central elongated panoramic of a OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK	<i>cabin window;</i> <i>cloud, pilot k;</i> 12.6.61/63 11.2.63 .61/63 64/66 69
	N215W not N215W not N215W act Further det G18S	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S	Keyser WV ch publicity photos of G18S: central elongated panoramic of a OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72
	N215W not N215W not N215W act Further det G18S	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S	Keyser WV ch publicity photos of G18S: central elongated panoramic of a OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80
	N215W not N215W not N215W act Further det G18S G18S	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K	Keyser WV ch publicity photos of G18S: central elongated panoramic of a OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83
BA-583	N215W not N215W not N215W act Further det G18S G18S N192K not	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K N192K	Keyser WV ch publicity photos of G18S: central elongated panoramic of a OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR <i>io-Stinson TX 17.5.73;</i>	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83 8.6.83
BA-583	N215W not N215W not N215W act Further det G18S G18S	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K	Keyser WV ch publicity photos of G18S: central elongated panoramic of e OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR io-Stinson TX 17.5.73; Surinaamse Luchtvaart Maatschappij/ Surinam Airways	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83
BA-583	N215W not N215W not N215W act Further det G18S G18S N192K not G18S	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K N192K	Keyser WV ch publicity photos of G18S: central elongated panoramic of a OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR <i>io-Stinson TX 17.5.73;</i> Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83 8.6.83
BA-583	N215W not N215W not N215W act Further det G18S G18S N192K not G18S Junior	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K N192K	Keyser WV ch publicity photos of G18S: central elongated panoramic of e OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR <i>io-Stinson TX 17.5.73;</i> Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity,	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83 8.6.83
BA-583	N215W not N215W not N215W act Further det G18S G18S N192K not G18S	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K N192K	Keyser WV ch publicity photos of G18S: central elongated panoramic of e OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR io-Stinson TX 17.5.73; Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, del. with Junior Jato units in engine nacelles)	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83 8.6.83 3.61/65
BA-583	N215W not N215W not N215W act Further det G18S G18S N192K not G18S Junior	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K N192K	Keyser WV ch publicity photos of G18S: central elongated panoramic of e OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR <i>io-Stinson TX 17.5.73;</i> Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity,	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83 8.6.83
BA-583 BA-584	N215W not N215W not N215W act Further det G18S G18S M192K not G18S Junior JATO	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K ed San Anton PZ-TAR	Keyser WV ch publicity photos of G18S: central elongated panoramic of e OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR <i>io-Stinson TX 17.5.73;</i> Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, del. with Junior Jato units in engine nacelles) crashed Kabelebo	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83 8.6.83 3.61/65 23.6.65
BA-583 BA-584	N215W not N215W not N215W act Further det G18S G18S N192K not G18S Junior	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K N192K	Keyser WV ch publicity photos of G18S: central elongated panoramic of e OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR <i>io-Stinson TX 17.5.73;</i> Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, del. with Junior Jato units in engine nacelles) crashed Kabelebo Youngstown Airways/ Lease Air, Youngstown OH	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83 8.6.83 3.61/65 23.6.65 .61
BA-583 BA-584	N215W not N215W not N215W act Further det G18S G18S M192K not G18S Junior JATO	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K ed San Anton PZ-TAR	Keyser WV ch publicity photos of G18S: central elongated panoramic of e OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR io-Stinson TX 17.5.73; Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, del. with Junior Jato units in engine nacelles) crashed Kabelebo Youngstown Airways/ Lease Air, Youngstown OH Wheeling Steel Corp, Wheeling WV	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83 8.6.83 3.61/65 23.6.65 .61 63/64
BA-582 BA-583 BA-584 BA-585	N215W not N215W not N215W act Further det G18S G18S M192K not G18S Junior JATO	ted Muskogee ted Ft Worth-I cident report 3 tails on the co N234W (1 N4S N192K ed San Anton PZ-TAR	Keyser WV ch publicity photos of G18S: central elongated panoramic of e OK 2.3.73 SMB Stage Line maintenance base; Meacham TX 7.77 "SMB Stage Line" titles, tailwheel; 30.6.83: Blackhawk Airways: freight flight, struck hill in low mposite 1979 rebuild: aee Beech 18 by Parmerter p.302; Western Gas Service Co, El Paso TX struck-off USCR Rock Island Lumber Co, St Paul MN Weyerhaeuser Co, Tacoma WA Master Jobbers Inc, La Crosse IN Ross Aviation, Tulsa-Riverside OK Great Western Airlines, Tulsa-Riverside OK Herbert A. Hartley, Brownsville TX struck-off USCR <i>io-Stinson TX 17.5.73;</i> Surinaamse Luchtvaart Maatschappij/ Surinam Airways (high capacity seating model by Beech: 9 passenger seats in cabin & additional baggage capacity, del. with Junior Jato units in engine nacelles) crashed Kabelebo Youngstown Airways/ Lease Air, Youngstown OH	cabin window; cloud, pilot k; 12.6.61/63 11.2.63 .61/63 64/66 69 70 71/72 77/80 9.5.80/83 8.6.83 3.61/65 23.6.65 .61

			Alpat Aviation, Bowmansville NY David Warren & Son, Orlando FL Barrow Aircraft Brokerage Ltd, New York NY	69/70 79 11.9.79/91
BA-586	G18S	N1290Z	built	4.61
		N129GP (*		63/64
		N1291N	General Precision Inc, Tarrytown NY	66/69
			Allied Aviation, Columbia SC Sierra West Airlines, Oxnard CA	71/72 74
			damaged landing gear locked-up, Nashville TN	8.4.74
			Frank A. Neuhausen, Santee CA	79
			Morey Wyman/ Wyman Pilot Service, Pontiac MI	84
			McNeely Charter Service, Earle AR	3.88
			Thomas W. May, New Boston TX	8.89/91
			May Air Xpress, New Boston TX	9.3.94/97
			Robert L. Brown, Springdale AR	4.98
			Springdale Air Service, Springdale AR	13.7.98/99
			N1291N Inc, Pembroke Pines FL	20.8.01
			Bush Air Inc, Wilmington DE	22.4.02/05
			wrecked at North Perry FL by Hurricane Wilma	8.05
			struck-off USCR as "destroyed"	14.12.05
		N363NY	reg. candidate	30.9.08/11
			struck-off USCR	27.6.11
	N1291N N1291N N1291N N1291N N1291N N1291N	noted Van Nuy noted Pontiac I noted Dallas-F noted Texarka noted Springda noted Opa Loc	MI 9.80; TW TX 12.93 all metallic, took off; na AR 7.97 May Air Xpress; ale AR 16.8.99 all metallic no reg, plate BA-586 built 4.61;	nes" titles,
BA-587	G18S	N1200Z	Beech Aircraft Corp, Wichita KS: CofA issued	27.7.61
			State of North Carolina, Raleigh NC	63/64
			Commercial Credit Equipment, Rockford IL	66/72
		N120ZZ	op: Flight Express Cargo, Philadelphia PA	77/79
			crashed on takeoff, Cleveland-Hopkins OH	1.11.77
			SSM Inc, Newark DE	78
			Swift Air Charter, Cleveland-Hopkins OH struck-off USCR	2.10.78/13 19.4.13
			1.11.77: Flight Express, cargo flight to Detroit, tailwheel fa lots seat slid back on takeoff, 2 crew unhurt;	ailed, groundlooped
BA-588	G18S	N98D	Youngstown Airways/ Lease Air, Youngstown OH: CofA	4.8.61
	0.00		Crucible Steel Co of America, Ditteburgh DA	62/64

BA-588	G18S	N98D	Youngstown Airways/ Lease Air, Youngstown OH: CofA	4.8.61
			Crucible Steel Co of America, Pittsburgh PA	63/64
			Beckett Aviation Corp, West Mifflin PA	66
		N9800 (2	Bailey Leasing Corp, Fort Wayne IN	66
			Time Airlines, Benton Harbour MI	69/71
			Midwest Commuter Airlines Corp, Indianapolis IN	71/72
			Flight Express Cargo, Philadelphia PA	79
			sale reported, Houston TX	91
			-	

N9800 noted Chicago-O'Hare 18.5.70 Time Airlines; N9800 noted Cleveland-Hopkins IL "Time Air Lines" titles, tailwheel, in service;

BA-589	G18S	N1384Z	Beech Aircraft Corp, Wichita KS	.61
			sold to Argentina, struck-oiff USCR	19.10.61
		LV-PJB	delivery reg.	8.61
		LV-HNH	Ministry Economy Secr Energy & Gas	4.9.62
		LQ-HNH LV-HNH	Argentine Government rereg	64
			Juan Carlos Rodriguez Louro, Buenos Aires	21.11.79

			retired, stored Buenos Aires-Don Torcuato under restoration, all metallic, Don Torcuarto	91/95 97/01
	LV-HNH r LV-HNH r LV-HNH r LV-HNH r LV-HNH r	noted Buenos . noted Don Torr noted Don Torr noted Don Torr noted Don Torr noted Don Torr	Aires-Ezeiza 22.7.64; Aires-Ezeiza 8.76; cuato, Argentina 7.86; cuato 28.5.91 stored; cuato 8.95, derelict in open; cuato 6.12.97 under rebuild in hangar, previously outside prcuato 2.11.01 all metallic, overhaul partially completed,	
BA-590	G18S	N404G	built	.61
		N404H	P. H. Glatfelter Co, Spring Grove PA P. H. Glatfelter Co, Spring Grove PA Burgess Aviation, Holland MI Paul J. Chauvin, Detroit MI Abrams Aerial Survey, Lansing MI PDL Associates Inc, Northridge CA Mid Atlantic Air Museum, Reading PA	63/64 66 69 71/72 72/82 9.82/91 8.1.92/20
	N404H nc N404H nc N404H nc	oted Tampa FL oted Fulton NY oted at MAAM	PA 6.64 owned P.H. Gladfelter Paper Corp, tailwheel; . 9.81, tailwheel, not titles, no external survey gear; ′ 7.93; Reading PA 16.5.01; PA 5.02 civil scheme outside MAAM hangar;	
BA-591	G18S	N1125M	built Schwitzer Corp, Indianapolis IN Wallace Murray Corp, Indianapolis IN Apollo Airways, Chicago IL struck snowbank on takeoff, Boston-Logan MA Northern Air Service, Grand Rapids MI	.61 63/66 69/70 71/77 20.2.72 21.4.78/79
		N400NA	Northern Air Service, Grand Rapids MI damaged in forced landing after takeoff, Evart MI struck-off USCR	2.79/85 11.8.83 25.7.85
	N1125M r "N402NA" N400NA r N400NA r N400NA r accident r	noted Detroiut ' noted Indiana noted London noted Youngst noted Toronto eport 11.8.83:	MA 13.6.73 Apollo Airways; •City MI 24.5.76, 26.5.77 "Apollo Airways", tailwheel; apolis IN 6.6.80 Northern Air Freight – probaby a missigh ONT 3.12.80 Northern Air Freight; own OH 16.9.82 Northern Air Service; ONT 5.8.83 Northern Air Service; Northern Air Service, freight flight, engine failure on take reet near airport;	-
BA-592	G18S	N505X	built Page Airways, Rochester NY midair collision with US Navy F3H Demon Bu145299,	
			N505X crashed into ocean	2.10.62
BA-593	G18S turbine trigear	N414GN N5724M	Gust Newberg Construction Co, Chicago IL Gust K. Newburg, Chicago IL left gear collapsed taxying, Pal-Waukee IL Hartzog Aviation, Rockford IL Squadron of the Quad City, Moline IL Jim Hankins Air Service Inc, Jackson MS Jim Ratliff Air Service, Columbus MS crashed, gear-up landing, Greenwood MS (PT6A-20 turbines, trigear by 89) struck-off USCR	.61/66 71/79 7.3.71 3.82 5.82 9.85/86 12.87/89 15.8.89 31.8.89
		anari 7 0 74-1	wreck sold for parts: nose-cockpit section fitted to N18RY/BA-325)	
	accident r	ероп 7.3.71:1	eft gear broke through ice covering soft ground taxying a	πer landing,

accident report 7.3.71: left gear broke through ice covering soft ground taxying after landing, accident 15.8.89: landed gear up Greenwood MS, pilot attempted go around but hit runway, PT6A-20 engine torn out: cargo ops, Jim Ratliff Flying Service;

BA-594	G18S	N1394Z	Beech Aircraft Corp, Wichita KS: CofA issued	5.9.61
			Chicago & Northwest Railway Co, Chicago IL	63/64
			Hartzog Schneck Aviation, Rockford IL	66/70
			reg. pending: USCR	71
			Thomas Russell, Knoxville TN	22.9.82/13
			last FAA contact with owner 85: struck-off USCR	31.1.13
<b>D</b> 4 <b>B</b> 6 <b>B</b> 6	0.400		1	
BA-595	G18S	N1500Z	built	.61
			Kansas Nebraska Natural Gas Co, Hastings NE	63/69
			Airkaman of Omaha Inc, Omaha NE	70
			prop blade detached on takeoff, Laramie WY	24.10.69
			Summit Aero Leasing, Akron OH	13.7.70/91
			gear collapsed on takeoff, Augusta GA	21.7.73
	accident r	eport 24.10.6	9 propeller blade failed on takeoff Laramie WY;	
BA-596	G18S	N163DP	built	.61
5/1000	0100	NICODI	Francis Aviation, Lansing MI	63
			Borg Warner Corp, Chicago IL	64/66
		N174YC	York Corp, York PA	69
		111710	Central Tool & Die Inc, Hopkinsonville KY	70
			Michael D. McGee: USCR	76
			crashed destroyed landing, Chicago-DuPage County II	_ 31.3.70
			t 31.5.76: flight International Falls MN to West Chicago-D ht in weather below minimums, stalled, dest: 7k;	uPage,
BA-597	G18S	N948Q	Beech Aircraft Corp, Wichita KS: CofA issued	9.10.61
			Ohio Aviation Co, Cleveland OH	63
			Perfect Circle Corp, Hagerstown IN	64
			Dana Corp, Toledo OH	66
			Harrison Security Services, Jackson MS	69/70
			Jim Hankins Air Service, Jackson MS	71/72
			William Catalina, Greenwell LA	78
			ditched in sea at night near Nassau, Bahamas	12.9.78
			John S. Smith, Montgomery AL: USCR	18.12.78/91
	N948Q ac Fort Laud	cident report erdale FL, pov	12.9.78: flight Barangia, Colombia to Great Inagua Bahan ver failure, ditched 10.30pm, 2 on board unhurt;	nas, destination
BA-598	G18S	N1557Z	built	.61
			Montana Power Co, Butte MT	63/64
			Tradewind Airport Corp, Amarillo CA	66
			Dan Futrell, Nashville AR	69/70
		N331E	Ag Air Inc, Belle Glade FL	
		N331SE	Barnett Serio Oil Co, Natchez MS	71/72
			Joseph J. Tucker, Hattiesburg MS	79
			Walkers Cay Air Terminal, Fort Lauderdale FL	2.82
		N444PV	Walkers Cay Air Terminal, Fort Lauderdale FL Walkers Cay Air Terminal, Fort Lauderdale FL	3.82/83
		187791 V	crashed destroyed after takeoff, Fort Lauderdale FL	14.4.83
	pilot was a	able to avoid b	4.4.83: Walkers International Inc: engine failure on takeofl buildings near airport boundary, struck trees and crashed impact fire, pilot minor injuries;	f Ft Lauderdale,
BA-599	G18S	N9334Y	built	.61
511 000	0100	11000-11	E. I. duPont de Nemours & Co, Wilmington DE	63/66
		N577DU	E. I. duPont de Nemours & Co, Wilmington DE	00/00
		N577D0 N547DA		69/70
		NJ4/DA	Deleware Air Freight Co, Wilmington DE	71/79
			Sebastiano Cannavo, Lester PA	1 1/19

N547DA accident report 12.6.81: Aero Taxi: cargo flight New Cumberland to Columbus OH, aborted takeoff, ran off end of runway, struck automobile on road near end of runway 10.22pm, pilot unhurt;

Cannavo Aviation/ Aero Taxi Inc, Claymont DE crashed on takeoff, New Cumberland PA

16.10.80/81 12.6.81

BA-600	G18S	N959T	E. I. duPont de Nemours & Co, Wilmington DE: CofA Spencer Chemical Co, Kansas City KS	21.11.61 63/64
			Gulf Oil Corp, Kansas City MO	66
			Priority Air Transport System, Redwood City CA	69
			struck vehicle taxying, San Francisco CA	30.1.69
			Eureka Aero Industries, Eureka CA	70/72
			Great Western Airlines, Tulsa OK	77/81
			William R. Sandlin, Harlingen TX	24.2.81/91
	N959T no	ted San Franc	Priority Air Transport, night mail flight, 12.30am; sico CA 2.71 "Eureka Aero Industries", tailwheel; ( 9.5.73 "Eureka Aero Industries" titles;	
BA-601	G18S	N1480W	E. I. duPont de Nemours & Co, Wilmington DE: CofA	11.12.61
			Midcontinent Leasing Co, Amarillo TX	63/66
			Public Service Co, Junction City KS	69 70
			Gates Aviation Corp, Denver CO	70
		N1480K	Ross Aviation, Tulsa-Riverside OK op: Great Western Airlines, Tulsa OK	71/80 75/80
			groundloop landing, rolled tail-first into ditch,	10100
			Dallas-Fort Worth Regional TX	15.7.75
			Saber Aviation/ Sabre Cargo Airlines, Charlotte NC	87/88
			crashed on takeoff, Morganton NC	24.2.88
			Piedmont Air Cargo, Gastonia NC	12.90/95
			Midline Air Freight, Cecilia KY	24.8.95/04
			William B. Chase, Des Moines IA	3.1.05/17
			gear collapsed landing, Ft Lauderdale-Executive FL	19.10.16
			Jane A. Theberge, Oakland Park FL	17.10.17/19
			op: Maurice Roundy, Fort Lauderdale FL	17/19
	15.7.75 ad 24.2.88 ad	ccident report: ccident: Sabre	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo o A 22.7.06 freighter conversion, "Miss Magoo";	;)
BA-602	15.7.75 ad 24.2.88 ad	ccident report: ccident: Sabre noted Ankeny I. CC-PRC	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo o	;)
BA-602	15.7.75 ad 24.2.88 ad N1480K n	ccident report: ccident: Sabre ooted Ankeny I.	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo o A 22.7.06 freighter conversion, "Miss Magoo";	i) ops;
BA-602 BA-603	15.7.75 ad 24.2.88 ad N1480K n	ccident report: ccident: Sabre noted Ankeny I. CC-PRC	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo o A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued	i) ops;
	15.7.75 ac 24.2.88 ac N1480K n G18S	ccident report: ccident: Sabre loted Ankeny I. CC-PRC CC-CEM	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA	;) pps; 1.62
	15.7.75 ac 24.2.88 ac N1480K n G18S	ccident report: ccident: Sabre loted Ankeny I. CC-PRC CC-CEM	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo o A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued	) pps; 1.62 2.2.62
	15.7.75 ac 24.2.88 ac N1480K n G18S	ccident report: ccident: Sabre loted Ankeny I. CC-PRC CC-CEM N925G	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA	) pps; 1.62 2.2.62 63/64
	15.7.75 ac 24.2.88 ac N1480K n G18S	ccident report: ccident: Sabre loted Ankeny I CC-PRC CC-CEM N925G N985G	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE	) pps; 1.62 2.2.62 63/64 66 69 70
	15.7.75 ac 24.2.88 ac N1480K n G18S	ccident report: ccident: Sabre loted Ankeny I. CC-PRC CC-CEM N925G	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN	5) pps; 1.62 2.2.62 63/64 66 69 70 76/79
	15.7.75 ac 24.2.88 ac N1480K n G18S	ccident report: ccident: Sabre loted Ankeny I CC-PRC CC-CEM N925G N985G	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN	5) pps; 1.62 2.2.62 63/64 66 69 70 76/79 10.76/82
	15.7.75 ac 24.2.88 ac N1480K n G18S	ccident report: ccident: Sabre loted Ankeny I CC-PRC CC-CEM N925G N985G	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX	5) pps; 1.62 2.2.62 63/64 66 69 70 76/79 10.76/82 1.83
	15.7.75 ac 24.2.88 ac N1480K n G18S	ccident report: ccident: Sabre loted Ankeny I CC-PRC CC-CEM N925G N985G	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH	5) pps; 1.62 2.2.62 63/64 66 69 70 76/79 10.76/82 1.83 10.83/86
	15.7.75 ac 24.2.88 ac N1480K n G18S	ccident report: ccident: Sabre loted Ankeny I CC-PRC CC-CEM N925G N985G	(based Ft Lauderdale-Executive, freight ops to Bahamas aymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI	5) pps; 1.62 2.2.62 63/64 66 69 70 76/79 10.76/82 1.83
	15.7.75 ac 24.2.88 ac N1480K n G18S	ccident report: ccident: Sabre loted Ankeny I CC-PRC CC-CEM N925G N985G	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH	5) pps; 1.62 2.2.62 63/64 66 69 70 76/79 10.76/82 1.83 10.83/86
	15.7.75 ac 24.2.88 ac N1480K n G18S G18S	ccident report: ccident: Sabre toted Ankeny I. CC-PRC CC-CEM N925G N985G N74LA	(based Ft Lauderdale-Executive, freight ops to Bahamas aymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI (retired, poor condition, Pontiac MI 00) struck-off USCR	5) pps; 1.62 2.2.62 63/64 66 69 70 76/79 10.76/82 1.83 10.83/86 20.1.89/14
	15.7.75 ac 24.2.88 ac N1480K n G18S G18S N74LA no N74LA no	ccident report: ccident: Sabre toted Ankeny I. CC-PRC CC-CEM N925G N985G N74LA	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI (retired, poor condition, Pontiac MI 00) struck-off USCR	5) pps; 1.62 2.2.62 63/64 66 69 70 76/79 10.76/82 1.83 10.83/86 20.1.89/14
	15.7.75 ac 24.2.88 ac N1480K n G18S G18S M74LA no N74LA no N74LA no N74LA no	ccident report: ccident: Sabre toted Ankeny I. CC-PRC CC-CEM N925G N985G N74LA N74LA	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI (retired, poor condition, Pontiac MI 00) struck-off USCR X 7.10.82 "VIA" titles; 2.97 Royal; 1 3.3.97,	5) pps; 1.62 2.2.62 63/64 66 69 70 76/79 10.76/82 1.83 10.83/86 20.1.89/14
	15.7.75 ac 24.2.88 ac N1480K n G18S G18S G18S N74LA no N74LA no N74LA no N74LA no	ccident report: ccident: Sabre toted Ankeny I. CC-PRC CC-CEM N925G N985G N74LA N74LA	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI (retired, poor condition, Pontiac MI 00) struck-off USCR X 7.10.82 "VIA" titles; 2.97 Royal; 1 3.3.97,	5) pps; 1.62 2.2.62 63/64 66 69 70 76/79 10.76/82 1.83 10.83/86 20.1.89/14
	15.7.75 ac 24.2.88 ac N1480K n G18S G18S G18S N74LA no N74LA no N74LA no N74LA no	ccident report: ccident: Sabre toted Ankeny I. CC-PRC CC-CEM N925G N985G N74LA N74LA ted Pontiac M ted Pontiac M ted Pontiac M ted Pontiac M ted Pontiac M	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI (retired, poor condition, Pontiac MI 00) struck-off USCR X 7.10.82 "VIA" titles; 2.97 Royal; 3.3.97, 7.98; 23.7.00 parked in long grass, poor condition; Youngstown Airways/ Lease Air, Youngstown OH: CofA	<ul> <li>bps;</li> <li>1.62</li> <li>2.2.62</li> <li>63/64</li> <li>66</li> <li>69</li> <li>70</li> <li>76/79</li> <li>10.76/82</li> <li>1.83</li> <li>10.83/86</li> <li>20.1.89/14</li> <li>18.11.14</li> <li>6.2.62/66</li> </ul>
BA-603	15.7.75 ac 24.2.88 ac N1480K n G18S G18S G18S N74LA no N74LA no N74LA no N74LA no N74LA no	ccident report: ccident: Sabre toted Ankeny I. CC-PRC CC-CEM N925G N985G N985G N74LA N74LA	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI (retired, poor condition, Pontiac MI 00) struck-off USCR X 7.10.82 "VIA" titles; 2.97 Royal; 3.3.97, 7.98; 23.7.00 parked in long grass, poor condition; Youngstown Airways/ Lease Air, Youngstown OH: CofA SMB Stage Line, Des Moines IA	<ul> <li>bps;</li> <li>1.62</li> <li>2.2.62</li> <li>63/64</li> <li>66</li> <li>69</li> <li>70</li> <li>76/79</li> <li>10.76/82</li> <li>1.83</li> <li>10.83/86</li> <li>20.1.89/14</li> <li>18.11.14</li> <li>6.2.62/66</li> <li>68/81</li> </ul>
BA-603	15.7.75 ac 24.2.88 ac N1480K n G18S G18S G18S N74LA no N74LA no N74LA no N74LA no N74LA no	ccident report: ccident: Sabre toted Ankeny I. CC-PRC CC-CEM N925G N985G N74LA N74LA ted Pontiac M ted Pontiac M ted Pontiac M ted Pontiac M ted Pontiac M	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI (retired, poor condition, Pontiac MI 00) struck-off USCR X 7.10.82 "VIA" titles; 2.97 Royal; 3.3.97, 7.98; 2.3.7.00 parked in long grass, poor condition; Youngstown Airways/ Lease Air, Youngstown OH: CofA SMB Stage Line, Des Moines IA struck parked aircraft, taxying Columbia MO	<ul> <li>b)</li> <li>b)</li> <li>b)</li> <li>c)</li> &lt;</ul>
BA-603	15.7.75 ac 24.2.88 ac N1480K n G18S G18S G18S N74LA no N74LA no N74LA no N74LA no N74LA no	ccident report: ccident: Sabre toted Ankeny I. CC-PRC CC-CEM N925G N985G N74LA N74LA ted Pontiac M ted Pontiac M ted Pontiac M ted Pontiac M ted Pontiac M	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI (retired, poor condition, Pontiac MI 00) struck-off USCR X 7.10.82 "VIA" titles; 2.97 Royal; 1 3.3.97, 1 7.98; 1 23.7.00 parked in long grass, poor condition; Youngstown Airways/ Lease Air, Youngstown OH: CofA SMB Stage Line, Des Moines IA struck parked aircraft, taxying Columbia MO struck fence on takeoff, DeKalb IL	<ul> <li>b)</li> <li>b)</li> <li>b)</li> <li>c)</li> &lt;</ul>
BA-603	15.7.75 ac 24.2.88 ac N1480K n G18S G18S G18S N74LA no N74LA no N74LA no N74LA no N74LA no	ccident report: ccident: Sabre toted Ankeny I. CC-PRC CC-CEM N925G N985G N74LA N74LA ted Pontiac M ted Pontiac M ted Pontiac M ted Pontiac M ted Pontiac M	(based Ft Lauderdale-Executive, freight ops to Bahamas eymouth MA 16.8.74; Great Western: 3.02am, flight Tulsa OK to Dallas; Aviation, ran off runway on takeoff Morganton NC, cargo of A 22.7.06 freighter conversion, "Miss Magoo"; built rereg Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator January-August 1962) Pennsalt Chemicals Corp, Philadelphia PA O'Sullivan Rubber Corp, Winchester VA Atlantic Aviation Service, Philadelphia PA Robert E. Moore, Wilmington DE Eugene Pikowsky, Minneapolis MN op: Viking Int'l Air Freight, Minneapolis MN Sam Medley, Dallas TX ACE Air Cargo Express Inc, Cleveland OH Royal Air Freight, Pontiac MI (retired, poor condition, Pontiac MI 00) struck-off USCR X 7.10.82 "VIA" titles; 2.97 Royal; 3.3.97, 7.98; 2.3.7.00 parked in long grass, poor condition; Youngstown Airways/ Lease Air, Youngstown OH: CofA SMB Stage Line, Des Moines IA struck parked aircraft, taxying Columbia MO	<ul> <li>bps;</li> <li>1.62</li> <li>2.2.62</li> <li>63/64</li> <li>66</li> <li>69</li> <li>70</li> <li>76/79</li> <li>10.76/82</li> <li>1.83</li> <li>10.83/86</li> <li>20.1.89/14</li> <li>18.11.14</li> <li>6.2.62/66</li> <li>68/81</li> <li>16.5.74</li> </ul>

N93CA	Cocker Air Freight, Dallas TX	2.82/84
	renamed: Skyfreighters Corp, Dallas TX	11.84/85
	ACE Air Cargo Express Inc, Cleveland OH	11.85/86
	North Coast Aviation, Cleveland OH	4.88
	Bering Air Inc, Nome AK	16.2.90/99
	Hartford Holding Corp, Wilmington DE	7.4.00
	Trans North Aviation, Anchorage AK	.00
	Bellair Inc, Fairbanks AK	31.7.00/01
	Aerolease of America Inc, Carson City NV	9.10.01
	Methow Aviation, Everett WA	7.12.01/05
	Kestrel Inc, Waukee IA	25.5.05/06
	Hans W. Munich, Yakutat AK	30.1.09/13
	ran off runway landing, starboard gear collapsed,	
	Yakutat AK	13.7.09
	Reg expired 30.9.13, struck-off USCR	24.1.18
N8087 noted Chicago-	O'Hare 27.1.69 SMB Stage Line:	
0	e OK 2.3.73 SMB Stage Line maintenance base;	
5	16.5.74: SMB Stage Line: mail flight Kansas City MO to	Columbia MO taxving
•		

after landing struck Piper N3977W, 2.26am; N8087 accident report 23.5.78: SMB Stage Line: flight DeKalb to Rockford IL 6pm, forced landing on airport after takeoff, pilot unhurt; N93CA noted Fairbanks AK 8.01 good condition, long centre window, brown & white; N93CA noted Ephrata WA 18.10.02 "Methow" titles, tailwheel; N93CA noted Ephrata WA 12.8.03 on Methow freight run to Moses Lake then Seattle; N93CA noted Seattle-Boeing field 27.4.04 Methow in service; accident report 13.7.09: Yakutatat AK, cargo flight, tail wheel;

BA-605	G18S	N340K	built	.62
			Panhandle Eastern Pipe Line Co, Kansas City MO	63/69
			reg. pending	70
			Industrial Bearing & Transmission Co, Kansas City MO	71/72
			ran off runway, struck ditches, Beaver Falls PA	16.9.76
			Grace A. Hambel, Lisle IL	79
			Lester H. Hambel, Clarendon Hills CA	10.81
			D & H Flying Service, Kenosha WI	12.82/92
			Bering Air Inc, Nome AK	4.3.92/95
			crashed on takeoff, Nome AK (wreckage was buried)	18.12.95

N340K noted Fort Worth-Oak Grove TX 3.5.73;

BA-606	G18S	N523	Ohio Oil Co/ Marathon Oil Co, Findlay OH: CofA issued	14.2.62/66
		N569AG	Stan Socia Corp, Tyler TX	69
			First National Bank, Carthage TX	70
		N569QA	First National Bank, Carthage TX	71/72
			J & J Aircraft Leasing, Fort Lauderdale FL	79
			Kenneth D. Munn, Hayward CA	11.82
			Julie A. Schwerzmann, Watertown NY	6.83
			Evelio Hernandez, Miami FL	4.84
			op: Air Cargo America, Miami FL	85
			Mark J. Von Mandel, Miami FL	6.9.85/13
			op: Air Cargo America Inc, Miami FL	.85/87
			last FAA contact with owner 1991, struck-off USCR	23.4.13

N569QA noted Hayward CA 7.81; N569QA noted Miami FL 29.7.85 Air Cargo America; N569QA noted Opa Locka FL 22.3.87;

BA-607	G18S	N19Y (2	built	3.62
	trigear	N192Y	Weyerhaeuser Co, Plymouth NC	16.4.62/68
			exported to Philippines, struck-off USCR	29.3.68
		PI-C1932	Weyerhauser Philippines Inc, Manila	.68
		RP-C1932	Balesin Corp, Manila	78/80
			Pacific Airways Corp, Manila	87/90

RP-C1932 noted Manila 21.1.80 Balesin Corp, Manila; RP-C1932 noted Manila 7.5.86 trigear, yellow & white, no titles; RP-C1932 noted Manila 8.10.87 Pacific Airways;

BA-608	G18S	N172M	built	.62
DA-000	G105			
			E. K. Jenkins Inc, Great Falls MT	63/66
			Falcon Airlines	68
			Alvin O. West, Washington DC	69
			Hill Aircraft & Leasing Corp, Atlanta GA	70/72
			Great Western Airlines, Tulsa-Riverside OK	74/77
			damaged on takeoff, Denver-Stapleton CO	12.12.74
			Providence Air Charter, Providence RI	78
		(N147PA)	ntu: Providence Air Charter, Providence RI	4.78
		N172M (	Providence Air Charter, Providence RI	8.78/80
			Aero Marine Surveys Inc, Groton CT	12.6.80/83
			(retired, parts stripped, Groton CT by 11.80)	80
			struck-off USCR	20.7.83
			on-DCA 2.10.68 Falcon Airlines;	
		ed Miami FL		<b></b>
			12.12.74: Great Western, mail flight, groundlooped on taked	off in gusty winds
	1.35am, pilo			
	N172M note	ed Groton C1	<sup>-</sup> 28.11.80 wfu derelict, no titles;	
	0100	NOOOLI		0.00/70
BA-609	G18S	N220H	Halliburton Co, Duncan OK	2.62/72
			SMB Stage Line Inc, Des Moines IA	76/77
			Blackhawk Airways, Janesville WI	78/79
			Buck Maxon, Kotzebue AK	11.82
			James Rood, Kotzebue AK	8.83
			Northwestern Aviation, Kotzebue AK	84
			ACE Air Cargo Express Inc, Cleveland OH	5.85/86
			Bering Air Inc, Nome AK	6.2.89/95
			forced landing on tundra, Brevig Mission AK	23.12.89
				25.12.05
			(wreck abandoned, reportedly buried;	
			stripped fuselage hulk in quarry near Nome AK 08)	
			struck-off USCR	6.4.95
	accident rep recovered b		9: Bering Air, forced landing due engine failure, airframe & e	engines not
BA-610	G18S	N959B	Beech Aircraft Corp, Wichita KS	3.62/64
BA-010	6165			
		N871MP	Mead Corp, Atlanta GA	66
			Ohio University, Athens OH	69
			Rambar Aviation, Parkersburg WV	70
			crashed destroyed landing, Greater Pittsburg PA	12.11.70
			Rambar Aviation, crashed Clinton PA, flew below Glideslo ort of runway, 2 hurt;	pe,
	C100	N17000	built .	1.60
BA-611	G18S	N1709G	built	1.62
			Carey Baxter & Kennedy Inc, New York NY	63/64
		N788G	Cars Unlimited Corp, Allentown PA	66
			First Union National Bank, Charlotte NC	69/72
			hit dirt bank on takeoff, Willmar MN	11.3.73
			Hamilton Aircraft Inc, Tucson AZ	74/79
			(open storage stripped Tucson 74/78 in Hamilton	
			storage compound)	
	Hamilton		(rebuilt as <i>Hamilton Westwind III</i> : PT-6A-20s, tailwheel,	
	Westwind II	1	completed by Hamilton Aviation 1.80)	
	WESIWING II			10.2.80/02
		C-GBST	Condor Aviation Services, Hamilton ONT	19.2.80/82
			(ferry permit 2.80 Tucson AZ to Hamilton ONT)	00 / 00
			ground collision with Cessna 310 CF-ZKK, Toronto ONT	23.4.80
			(repaired Toronto, test flown 6.80)	
			undercarriage collapsed landing Toronto ONT	12.2.81
			Commerce Leasing Ltd, Toronto ONT	15.9.82
			struck-off Canadian Register	21,12.82
			ou doit on oundation register	21,12.02

N788G note BA-611 note reported not accident rep N3281T note crash report BA-612 G18S	ed Tucson A ed Tucson A ted 8.80 as bort 24.10.84 ed Toronto ( t 9.3.89: des N81D (2 (N8101) N81D	<ul> <li>Z 20.9.74 in Hamilton compound, stripped, tailwheel, E18 Z 14.10.78;</li> <li>IZ 7.9.79 "derelict"; Westwind III;</li> <li>4: gear collapsed on takeoff, Ajax Aircraft Leasing Inc; ONT 24.9.85 turbine;</li> <li>st., Action Aero Charter: took off with frost on airframe;</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR</li> <li>alton ONT 3.63 no titles, tailwheel;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding &amp; Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Houston Beechcraft Inc, Houston TX</li> </ul>	.62/63 13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62
crash report BA-612 G18S N81D noted BA-613 G18S	t 9.3.89: des N81D (2 (N8101) N81D I Toronto-Ma N1864T	<ul> <li>Action Aero Charter: took off with frost on airframe;</li> <li>Youngstown Airways/ Lease Air, Youngstown OH Burton Supply Co, Youngstown OH ntu struck-off USCR</li> <li>alton ONT 3.63 no titles, tailwheel;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding &amp; Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued</li> </ul>	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62
N81D noted BA-613 G18S	(N8101) N81D <i>Toronto-Ma</i> N1864T	Burton Supply Co, Youngstown OH ntu struck-off USCR alton ONT 3.63 no titles, tailwheel; Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI Beech Aircraft Corp, Wichita KS: CofA issued	13.6.66/71 70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62
BA-613 G18S	N81D I Toronto-Ma N1864T	ntu struck-off USCR alton ONT 3.63 no titles, tailwheel; Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI Beech Aircraft Corp, Wichita KS: CofA issued	70 12.2.71 14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62
BA-613 G18S	N1864T	alton ONT 3.63 no titles, tailwheel; Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI Beech Aircraft Corp, Wichita KS: CofA issued	14.6.62 63/64 69/70 71/79 23.6.80/91 5.7.62
BA-613 G18S	N1864T	Beech Aircraft Corp, Wichita KS: CofA issued Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI Beech Aircraft Corp, Wichita KS: CofA issued	63/64 69/70 71/79 23.6.80/91 5.7.62
		Travelers Insurance Co, Hartford CT Beck Welding & Manufacturing Inc, Elkhart IN Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI Beech Aircraft Corp, Wichita KS: CofA issued	63/64 69/70 71/79 23.6.80/91 5.7.62
BA-614 G18S	N1780G	Thunander Flying Service, Elkhart IN Scarborough Aviation, Pontiac MI Beech Aircraft Corp, Wichita KS: CofA issued	71/79 23.6.80/91 5.7.62
BA-614 G18S	N1780G	Beech Aircraft Corp, Wichita KS: CofA issued	5.7.62
BA-614 G18S	N1780G		
		Houston Beechcraft Inc, Houston IX	
		Royal Crown Cola Co, Columbus GA	63 64
	N356SW	Royal Crown Cola Co, Columbus GA	04
	N1780G	Royal Crown Cola Co, Columbus GA	66
		Construction Equipment Co, Greenville SC	69
		Yeagin Aviation, Greenville SC	70
	N158YC	Yeagin Aviation, Greenville SC	71/72
		Bo-S-Aire Airlines, Greenville SC	77
	N5BA	Shirley J. Bowman/ Bo-S-Aire Airlines, Anderson SC	9.77/89
		landed gear locked up, Jacksonville FL	12.10.81
		cargo door separated in flight, Huntsville AL tailwheel collapsed landing, ran off runway,	16.11.82
		Jacksonville FL	6.6.83
		Don Haynes Aviation, Anderson SC	8.88
		Jacob C. Bowman, Anderson SC	1.91
		Robert D. McSwiggan, Fayetteville GA	3.92
		Piedmont Air Cargo, Gastonia NC	5.92/95
		Springdale Air Service, Springdale AR	10.95/96
		SCS Group Inc, Springdale AR	7.3.96/98
		op: Springdale Air Service, Springdale AR	97/98
		Springdale Air Service, Springdale AR	13.7.98/99
		Kestrel Inc, Waukee IA	13.3.01
		Gulf Air Taxi, Yakutat AK	7.6.02
		George E. Thomas, Yakutat AK Oleetho-3 Inc, Hemet CA	24.6.03/06 14.9.06/12
			6.6.12/20
		Carlsbad Raceway Corp, Hemet CA	0.0.12/20

N5BA accident report 12.10.81: Bo-S-Aire: cargo flight Atlanta GA to Jacksonville, gear would not extend due mechanical failure 11.15pm, pilot unhurt;

N5BA accident report 16.11.82: Bo-S-Aire: left cargo door installed under Hamilton STC, incorrectly installed, 2 crew uninjured;

N5BA accident report 6.6.83: Bo-S-Aire Airlines Inc, tailwheel collapsed on landing, pilot lost control, ran off runway, pilot unhurt;

N5BA noted Toronto ONT 25.10.85 "Bo-S-Aire" titles;

N5BA noted Springdale AR 8.97 freighter no windows, Springdale Air Service, in service: plate BA-614 built 6.62;

N5BA noted Texarkana AR 5.8.98, windowless freighter, landed on freight run from Springdale AR

owned Springdale Air Service, plate: BA-614 built 6.62; N5BA noted Springdale AR 26.8.99 Springdale Air Service; N5BA noted Hemet CA 14.5.08 blue & white windowlesss freighter, tailwheel 10.8.15, 14.11.15;

BA-615	G18S	N1557S	Beech Aircraft Corp, Wichita KS: CofA issued	8.62
	trigear		National Financing Inc, Wilmington DE	63
	-		Herb Singer Inc, State College PA	64/72
			Harold E. Bahlow, Canton MI	79
			Ajax Aircraft Leasing Inc, Dover DE	1.83
			Kokomo Aviation, Kokomo IN	11.84/91
			Piedmont Air Cargo, Gastonia NC	1.92/97
			US Motorsports Inc, Stateville NC	29.7.97
		N604DK	US Motorsports Inc, Stateville NC	10.97/99
			Air 4CE 1, Chicago IL	26.4.99
		N770DA	Air 4CE 1, Chicago IL	25.8.99/17
			(retired, parked Janesville WI as N604DK .99/16)	
			struck-off USCR	10.3.17
	early 99 fi no window noted at J noted at J	rom Florida an ws "USAV" title Janesville WI 2 Janesville 26.7	le WI 30.7.00, 28.7.02 & 23.7.03 trigear, plate BA-615, ad being prepared for new owner at Du Page IL, ex freig es, previous titles "Piedmont Air Cargo" discernable; 25.7.08 parked outside, not operational, still N604DK; 7.15 parked outside, trigear, tailplane removed; le 30.7.16 outside, outer wings and tailplane removed,	hter
BA-616	G18S	XC-BUX	Mexican Government	.62
DALOIO	0100	XC-CUW	Sria. Rec. Hidraulicos, Mexico City	3.63/77
		X0 0011	Transporte Aereo Federal	86
		N50WA	Westernair Inc, Albuquerque NM	15.9.86
		1001171	Robert L. Wills, Twin Falls ID	2.87
			Kurt A Ledhams Phoenix A/	-
			Kurt A. Tedhams, Phoenix AZ Worldwide Warbirds Inc. Heber City UT	19.5.89/14
			Kurt A. Tedhams, Phoenix AZ Worldwide Warbirds Inc, Heber City UT	-
BA-617	G18S	JA5505	Worldwide Warbirds Inc, Heber City UT	19.5.89/14
BA-617	G18S	JA5505	Worldwide Warbirds Inc, Heber City UT Maritime Safety Board, Kagoshima	19.5.89/14 29.10.14/20 9.62/65
BA-617	G18S	JA5505	Worldwide Warbirds Inc, Heber City UT	19.5.89/14 29.10.14/20
BA-617	G18S	JA5505	Worldwide Warbirds Inc, Heber City UT Maritime Safety Board, Kagoshima Maritime Safety Agency, Kagoshima	19.5.89/14 29.10.14/20 9.62/65 70/78

JA5505 noted at Wichita KS 3.9.62 awaiting delivery; JA5505 noted Kagoshima 28.3.80;

BA-618	H18	N925K	Beech Aircraft Corp, Wichita KS: CofA issued	6.9.62
			(first production H18, company demonstrator from 8.62)	
			Louisiana State Rice Milling Co, Abbeville LA	63/64
		N220T	Trunkline Gas Co, Houston TX	66
			damaged in gear-up landing, Houston-Hobby TX	20.4.67
		N2209	Trunkline Gas Co, Houston TX	69
		N220WH	Wiles-Holloway Inc, Baton Rouge LA	69
			Morris Trading Corp, Sarasota FL	70
			Clifford A. Marlatt/ Sky Castle Aviation, New Castle IN	78/80
		(N220SC)	ntu: Sky Castle Aviation	6.1.79
		N220WH	Aero Services Inc, Union City TN	3.84
			Air Machines & Services Inc, St James MO	3.86
			Hogan Air Inc, Hamilton OH	5.86
		(N74HA)	ntu: Hogan Air Inc, Hamilton OH	7.86
		N220WH	James G. Branam, Gatlinburg TN	6.87
			Tol Air Services, San Juan, Puerto Rico	4.90
		N779T	Tol Air Inc, San Juan Puerto Rico	23.5.90/99
			MBD Corp, San Juan Puerto Rico	8.2.99/13
			op: Tol Air Inc, San Juan, Puerto RIco	99/10
			(retired, stripped, San Juan, Puerto Rico 12/13)	
			reg expired 31.12.13, struck-off USCR	24.1.18

N2209 & N220WH listed separately both as BA-618 in USCR 69 & 70; N779T noted St Croix USVI 1.98 "Tolair"; N779T noted San Juan PR 16.6.00 all metal, op by Tolair; N779T photo in service Tol Air at Puerto Rico 5.10, all metallic, windows faired over; Beech 18 by Robert Parmerter also quotes N2290 for BA-618: RP confirms is misprint;

BA-619	H18	N700M (2	Roscoe Turner Aeronautical Corp: CofA issued	29.10.62
	trigear		Inland Container Corp, Indianapolis IN	12.62/66
		N708M	rereg	
		N502W	S. J. Groves & Sons, Liverpool NY	69/72
		N50225	Banlee Travel, Rehoboth DE	79
			Jerry L. Englund/ Englund Aviation, Mobile AL	2.88/91
			Richard L. Jack, Mount Pleasant MI	3.92/96
			James W. Boyd, Sioux City IA	12.96/99
			FI Systems Inc, Bandon OR	17.7.00/20

N50225 noted Mt Pleasant MI 10.96;

BA-620	H18	N9539Y	built	11.62
			Tecumseh Products Co, Tecumseh MI	63/66
		N955GP	Georgia Pacific Corp, Portland OR	69/72
			Northern Flying Service, Pontiac MI	75/78
			struck-off USCR	10.3.78

N955GP noted Indianapolis IN 30.5.76;

BA-621	H18	N501F	Beech Aircraft Corp, Wichita KS: CofA issued	10.10.62			
			E. I. duPont de Nemours & Co, Wilmington DE	63/69			
		N860H	State of Ohio Highways Dept., Columbus OH	70/79			
		N360H	State of Ohio, Columbus OH	1.85			
			Air Service Centre Inc, Hamilton OH	1.87			
			Mark C. Evans, Memphis TN	7.88			
			Jim Hankins Air Service, Jackson MS	11.89			
			Cape Central Airways, Cape Girardeau MO	5.90/91			
			River City Aviation, Cape Girardeau MO	7.92			
			Jim Hankins Air Service, Jackson MS	1.93			
			Jack C. Fisher, Mayfield KY	10.93/95			
			Susan Dacy/ S. Dacy Enterprises Inc, Harvard IL	3.8.98/20			
		t fly-in Oshkosh					
			Rock County WI 2.8.98;				
	N360H at Beech fly-in Tullahoma TN 10.93;						
	N360H at Beech fly-in Tullahoma TN 16.10.98 tailwheel, owned Susan Dacy;						
	N360H noted Janesville WI 26.7.99,						
	N360H n	oted Janesville	WI 10.8.02 plate BA-621;				
	N360H n N360H n	oted Janesville oted Janesville	WI 10.8.02 plate BA-621; WI 23.7.03				
	N360H n N360H n	oted Janesville oted Janesville	WI 10.8.02 plate BA-621;				
BA-622	N360H n N360H n	oted Janesville oted Janesville	WI 10.8.02 plate BA-621; WI 23.7.03	10.62			
BA-622	N360H n N360H n N360H a	oted Janesville oted Janesville It Beech fly-in Tu	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03;	10.62 63/64			
BA-622	N360H n N360H n N360H a	oted Janesville oted Janesville It Beech fly-in Tu	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built				
BA-622	N360H n N360H n N360H a	oted Janesville oted Janesville t Beech fly-in Tu N51K (2	WI 10.8.02 plate BA-621; WI 23.7.03 Juliahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL	63/64 66/72			
BA-622	N360H n N360H n N360H a	oted Janesville oted Janesville t Beech fly-in Tu N51K (2	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL Greenlee Bros & Co, Rockford IL	63/64			
BA-622 BA-623	N360H n N360H n N360H a	oted Janesville oted Janesville It Beech fly-in Tu N51K (2 N518K	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL Greenlee Bros & Co, Rockford IL Joseph P. Navik, Rochester NY	63/64 66/72 2.12.77/81			
	N360H n N360H n N360H a H18	oted Janesville oted Janesville It Beech fly-in Tu N51K (2 N518K	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL Greenlee Bros & Co, Rockford IL Joseph P. Navik, Rochester NY crashed destroyed by fire landing, Fort Lauderdale FL Cleveland Brothers Equipment Co, Harrisbburg PA rereg	63/64 66/72 2.12.77/81 13.8.81			
	N360H n N360H n N360H a H18	oted Janesville oted Janesville it Beech fly-in Tu N51K (2 N518K N555CB (2	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL Greenlee Bros & Co, Rockford IL Joseph P. Navik, Rochester NY crashed destroyed by fire landing, Fort Lauderdale FL Cleveland Brothers Equipment Co, Harrisbburg PA	63/64 66/72 2.12.77/81 13.8.81			
	N360H n N360H n N360H a H18	oted Janesville oted Janesville t Beech fly-in To N51K (2 N518K N555CB (2 N5559B	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL Greenlee Bros & Co, Rockford IL Joseph P. Navik, Rochester NY crashed destroyed by fire landing, Fort Lauderdale FL Cleveland Brothers Equipment Co, Harrisbburg PA rereg	63/64 66/72 2.12.77/81 13.8.81 9.62/64			
	N360H n N360H n N360H a H18	oted Janesville oted Janesville t Beech fly-in To N51K (2 N518K N555CB (2 N5559B	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL Greenlee Bros & Co, Rockford IL Joseph P. Navik, Rochester NY crashed destroyed by fire landing, Fort Lauderdale FL Cleveland Brothers Equipment Co, Harrisbburg PA rereg Otis Redding Enterprises Inc, Macon GA	63/64 66/72 2.12.77/81 13.8.81 9.62/64 31.10.67			
	N360H n N360H n N360H a H18 H18 N555CB	noted Janesville noted Janesville t Beech fly-in Tu N51K (2 N518K N555CB (2 N5559B N390R	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL Greenlee Bros & Co, Rockford IL Joseph P. Navik, Rochester NY crashed destroyed by fire landing, Fort Lauderdale FL Cleveland Brothers Equipment Co, Harrisbburg PA rereg Otis Redding Enterprises Inc, Macon GA crashed into Lake Monoma, near Madison WI (7 killed, including singer Otis Redding) a KS 3.9.62 just rolled off production line;	63/64 66/72 2.12.77/81 13.8.81 9.62/64 31.10.67			
	N360H n N360H n N360H a H18 H18 N5555CB Publishe	noted Janesville noted Janesville t Beech fly-in Tu N51K (2 N518K N555CB (2 N5559B N390R noted at Wichita d 1966 USCR: r	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL Greenlee Bros & Co, Rockford IL Joseph P. Navik, Rochester NY crashed destroyed by fire landing, Fort Lauderdale FL Cleveland Brothers Equipment Co, Harrisbburg PA rereg Otis Redding Enterprises Inc, Macon GA crashed into Lake Monoma, near Madison WI (7 killed, including singer Otis Redding) a KS 3.9.62 just rolled off production line; not listed any reg;	63/64 66/72 2.12.77/81 13.8.81 9.62/64 31.10.67 10.12.67			
	N360H n N360H n N360H a H18 H18 N5555CB Publishe 10.12.67	noted Janesville noted Janesville t Beech fly-in Tu N51K (2 N518K N555CB (2 N5559B N390R noted at Wichita d 1966 USCR: r accident report	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL Greenlee Bros & Co, Rockford IL Joseph P. Navik, Rochester NY crashed destroyed by fire landing, Fort Lauderdale FL Cleveland Brothers Equipment Co, Harrisbburg PA rereg Otis Redding Enterprises Inc, Macon GA crashed into Lake Monoma, near Madison WI (7 killed, including singer Otis Redding) a KS 3.9.62 just rolled off production line; not listed any reg; : entered spin in fog and crashed into water of Lake Monoma	63/64 66/72 2.12.77/81 13.8.81 9.62/64 31.10.67 10.12.67			
	N360H n N360H n N360H a H18 H18 N5555CB Publishe 10.12.67	noted Janesville noted Janesville t Beech fly-in Tu N51K (2 N518K N555CB (2 N5559B N390R noted at Wichita d 1966 USCR: r accident report	WI 10.8.02 plate BA-621; WI 23.7.03 ullahoma TN 16.10.03; built Rockford Screw Products Co, Rockford IL Greenlee Bros & Co, Rockford IL Joseph P. Navik, Rochester NY crashed destroyed by fire landing, Fort Lauderdale FL Cleveland Brothers Equipment Co, Harrisbburg PA rereg Otis Redding Enterprises Inc, Macon GA crashed into Lake Monoma, near Madison WI (7 killed, including singer Otis Redding) a KS 3.9.62 just rolled off production line; not listed any reg;	63/64 66/72 2.12.77/81 13.8.81 9.62/64 31.10.67 10.12.67			

BA-624	H18	SU-ANH	Eastern Petroleum crashed near Cairo	2.63/66 20.3.66
BA-625	H18	N9614Y	built	11.62
			Atlantic Aviation Corp, Teterboro NJ	63
			National Financing Inc, Wilmington DE	64/66
		N18T (3	Addison Products Co, Addison TX	69/72
		N18TK	Smith Aero Service, Montgomery AL	79
			Springfield Air Service, Springfield MA	79/83
			Bowman Aviation, Anderson SC	8.83
		N29BA	Bo-S-Aire Airlines Inc, Anderson SC	11.83/89
			Don Haynes Aviation, Anderson SC	8.88/89
			struck-off USCR	2.89
			Jacob C. Bowman, Anderson SC: rest. to USCR	1.91
			Hinchinbrook Equipment Co, Palmer AK	4.10.91/99
			Nevada Direct Leasing Corp, Carson City NV	15.9.99/02
			op: New Horizons Telecom Inc, Palmer AK	00
			Matthew J. Ziomek, Kingman AZ	19.5.04/06
			Aero Flite Inc, Kingman AZ	6.6.06/12
			ATC Aero LLC, Kingman AZ	25.7.12/20

N18TK noted Fort Wayne IN 28.5.76; N18TK noted Cleveland OH 16.9.82 Springfield Air Service; N29BA noted Palmer AK 8.94, tailwheel, no windows, in service;

BA-626	H18	N2345Z	built	11.62
			Furrs Realty Co, Lubbock TX	63/64
			Cecil Ruby Co, Austin TX	66
			Executive Air Service, Alexandria VA	69
			Joseph Fontana/ Fontana Aviation, Iron Mountain MI	3.11.69/70
			crashed destroyed landing, Lansing MI	23.12.70

accident report 23.12.70: Fontana Aviation, flight Iron Mountain to Lansing MI, stalled on approach due airframe icing, 1am in fog & freezing rain;

BA-627	H18	N166A	built	9.62
		N517DC	L. C. Cassidy & Son Inc, Clearwater FL	63/64
	trigear		(Volpar Trigear installed early .63 by Volitan Aviation,	
			Pacoima CA: first H18 to have trigear, prior to	
			factory installation which commenced late 63)	
			crashed during forced landing off-airport due	70/79
			engine failure on takeoff, Cincinatti-Lunken OH	9.8.64
		N4746G	James J. Coulas, Chicago IL	66/69
			(flew Keflavik-Prestwick 10.6.67 then Dublin, Gatwick)	
			Weldbend Corp, Chicago IL	70/79
			Oklahoma Aircraft Sales, Yukon OK	9.81
			James E. Dodd, Miami FL	4.82
			Daniel G. Doumis, Fort Myers FL	6.84
			Morgan T. James, Coral Gables FL	4.86
			Daniel G. Doumis, Fort Myers FL	91
			Valerie Balubar, Hayward CA	14.11.91/92
			sold to Philippines, struck-off USCR	14.2.92
		RP-C3737	reg	.92
			CofA expired 22.2.93, struck-off Register	11.11.98

N4746G noted Indianapolis IN 30.5.76;

BA-628	H18	N1481G	Beech Aircraft Corp, Wichita KS: CofA issued	31.10.62	
			Schneck Engine Service & Supply, Rockford IL	63	
			Sealed Power Corp, Muskegon MI	66	

			General Aviation Inc, Lansing MI Aero Taxi-Rockford Inc, Rockford IL Blackstone Rotorcraft Inc, Hartselle AL David Robertson, Cullman AL struck-off USCR	69/78 14.4.84/00 12.3.01/06 26.2.08/15 14.5.15
	N1481G N1481G N1481G N1481G N1481G	noted Rockfol noted Rockfol noted Tucson noted Huntsvi noted Rockfol	alley AZ 7.11.68; rd IL 8.00, tailwheel; rd IL 7.91 at Aero Taxi ramp; AZ 9.95; ille AL 10.98 Aero Taxi Rockford; rd IL 26.7.99 Aero Taxi, usually based Huntsville AL: rd IL 30.7.00 no titles, Aero Taxi, plate BA-628;	
BA-629	N228A no	oted Ephrata	Beech Aircraft Corp, Wichita KS: CofA issued United Airmotive Distributors, Wichita KS Coca Cola Bottling Co, Fort Worth TX Ryan Mortgage Corp, Fort Worth TX Dan Futrell, Nashville AR W. F. Larson Inc, Plainview TX Meridan Aviation, Salt Lake City UT ACE Air Cargo Express Inc, Cleveland OH Johnson Aviation Co, Elyria OH James D. Rowe/ Bering Air, Nome AK crashed, nosed over on to back during landing, White Mountain AK Turbo North Aviation, Anchorage AK Bellair Inc, Fairbanks AK Aerolease of America Inc, Carson City NV Methow Aviation, Burlington WA Engen Farms LLC, Mount Vernon WA James M. Walker, Henderson NV struck-off USCR	12.11.62 63/64 66 69 70 71/72 79 11.85/86 5.88 1.11.88/99 24.8.91 .00 31.7.00 9.10.01 20.3.02/05 10.5.06/07 23.6.09/18 25.8.18

BA-630	H18	N82D (2	Youngstown Airways/ Lease Air, Youngstown OH: CofA	16.11.62			
			Wean Engineering Co, Warren OH	63/64			
			Lease Air Inc, Youngstown OH	66			
		N8217	SMB Stage Line Inc, Des Moines IA	69/80			
			Universal Aircraft Sales, Detroit MI	.80			
			Charles J. Toman, Painesville OH	6.89			
		N368HC	Charles J. Toman, Painesville OH	6.90/91			
			Jim Hankins Air Service, Jackson MS	2.5.95/19			
			(rest. project at Jackson MS 97/05, painted N8217)				
			struck-off USCR	17.1.19			
	10047						
		•	OK 2.3.73 SMB Stage Line maintenance base;				
	N8217 noted Jackson MS 18.7.97 stripped hulk; N8217 noted Jackson MS 11.8.98, fuselage on undercarriage, Hankins AS; N8217 noted Jackson MS 1.8.02 restoration project; N8217 noted Jackson-Hawkins Field MS 5.8.03 JHAS, just fuselage on gear, parked outside; N8217 noted Jackson-Hawkins Field MS 16.8.05 engine tail & outer wings removed;						
	N8217 n	oted Jackson-H	lawkins Field MS 5.8.08, fuselage in storage;				
BA-631	H18	N50L (2	built	10.62			
		,	Transcontinental Gas Pine Line Corn, Houston TX	63/66			

BA-631	H18	N50L (2	built	10.62
			Transcontinental Gas Pipe Line Corp, Houston TX	63/66
		N5012	Transcontinental Gas Pipe Line Corp, Houston TX	69
			Joseph Fontana/ Fontana Aviation, Iron Mountain MI	70/74
		N72FA	crashed dest. landing, Iron Mountain MI	17.10.74
			-	

N72FA accident report 17.10.74: Fontana Aviation: mail flight from Lansing MI, struck terrain on approach 1.51am for landing, pilot k;

BA-632	H18	N989B	built, CofA issued South Lake Farms, Fresno CA John S. Broome, Rancho Guadalasca, Oxnard CA W. T. Burton Industries, Sulphur LA ACE Air Cargo Express Inc, Cleveland OH crashed on landing, destroyed by fire, Kansas City-Downtown MO	25.7.62 63/66 69/72 78 21.11.78/88 1.4.88
		d as always ta oted San Anto	ilgear; nio TX 16.5.73;	
BA-633	H18	N1551S	Atlantic Aviation Corp, Wilmington DE Dentists Supply Co of New York, York PA Dentsply International Inc, York PA	8.63 64/70 71/72
		CF-FTB	Canadian Auto Market, Montreal QUE Provincial Aviation Inc, Montreal-Dorval QUE op: Air Amos	12.72 74 81
		C-FFTB	Air Saguenay, Lake Sebastian QUE Sept-Iles Aero Club, Sept-Iles QUE Aviation Quebec Labrador Ltee, Sept-Iles QUE Aviation Maintenance Ltd, Sault Ste Marie ONT sold to USA, struck-off Canadian Register	81/82 83 12.83/87 88/93 5.93
		N6GJ	Glen Johnson, Fort Worth TX (US CofA renewed 12.5.93)	4.5.93/06
		N62CJ	CJ Aviation Services, Wilmington DE CJ Aviation Services, Wilmington DE Chris J. Price, Catawba NC	5.10.10/12 12/17 2.5.17/20
	N6GJ no N6GJ no N62CJ vi N62CJ a	ted Bangor MI ted Greenville isited Oshkosh t Beech fly-in	nl-Dorval QUE 23.8.74; E 7.02 visitor from Texas; ME 7.9.02; n WI fly-in 28.7.14; Tullahoma TN 18.10.14; n 7.17 blue & white, tailwheel;	
BA-634	H18	N789LN N744G	Liberty National Life Insurance, Birmingham AL Highway Trailer Industries. Edgerton WI groundlooped on takeoff, gear collapsed, Chicago-O'Hare IL struck-off USCR	10.62/66 20.3.67/69 27.10.68 11.2.69
BA-635	H18	N1775G	bil4	4.62
BA-033	пю	N1775G	built Chotin Transportation Inc, New Orleans LA Bodcaw Co, Dallas TX Fontana Aviation, Iron Mountain MI struck-off USCR	4.63 63/64 66/72 11.12.74/77 20.12.77
	N1775G	noted Dallas-L	Love TX 2.10.71;	
BA-636	H18	N1511S	built Galles Motor Co, Albuquerque NM Flexsteel Industries Inc, Dubuque IA Aerospace Products Inc, North Hollywood CA	12.62 63/64 66/72 91
BA-637	H18	N1461G	Southern Airways Co, Atlanta GA Georgia Civil Defense Dept, Atlanta GA Georgia Dept. of Air Transportation, Atlanta GA Starflight Inc, Memphis TN damaged ran off runway on takeoff, Talladega AL crashed destroyed by fire after takeoff, Oklahoma City-Expressway Air Park OK	12.62/63 64/69 70/79 17.7.79/85 11.2.83 5.11.85
	N1461G	noted Atlanta	GA 3.10.68 Pickrick Co;	

N1461G noted Atlanta GA 3.10.68 Pickrick Co; N1461G accident report 11.2.83: Starlight Inc, ran off runway on takeoff, struck a ditch and undercarriage collapsed: confirms tailwheel, 3 unhurt, explosives in cargo continued to explode for more than an hour after the crash;

BA-638	H18	N39V	Beech Aircraft Corp, Wichita KS: CofA issued	4.1.63
	triacar		Piedmont Aviation, Winston Salem NC:	9.63/64
	trigear	N200DH N2009H	Dobbs Houses Inc, Memphis TN Public Leasing Corp, Oklahoma City OK	66 69/72
		11200311	Mercy Flights Inc, Medford OR	78
		N117MF	Mercy Flights Inc, Medford OR	10.78/89
		N117ME	Mercy Flights Inc, Medford OR	3.89
			Doak V. Boreing, Magnolia AR, later Hot Springs AR	8.89/91
			Tom E. Demint/ Astro Airways, Pine Bluff AR	12.93/97
			River City Aviation Inc, Wilmington DE	29.5.97/99
			op: McNeely Charter Service, West Memphis AR	98
			Air Classic Cargo Inc, Spring Hill FL	18.6.99/02
			L J Aviation, Wilmington DE	5.10.04/05
			Monarch Air Group, Palm City FL	9.6.05/12
			nose gear collapsed on landing, Fort Lauderdale FL	4.9.07
			struck-off USCR	7.6.12
	N117ME	noted Pine Blu	d CA 11.11.85 "Mercy Flights Inc" titles, trigear; uff AR 4.96 Astro Airways;	20.
			emphis AR 4.8.98 McNeely Charter Service, plate: BA-63 ssie FL 24.5.04;	0,
			ssie FL 24.5.04, nee FL 12.4.05 & 25.4.05: trigear, in service;	
			100 T L TL.T.00 & 20.T.00. Ingeal, in Service,	
BA-639	H18	N9689Y	Beech Aircraft Corp, Wichita KS: CofA issued	10.1.63
			Topeka Aircraft Sales & Service, Topeka KS	9.63/64
			Southern Airways Beechcraft Inc, Atlanta GA	66
		• • <b>-</b> · ·	Chiminage Corp, Winter Park FL	69/72
		N74JT	White Spot Equipment Co, Huntington Beach CA	79 70
			op: Code Three Air Cargo	79
			Starr Enterprises Inc, Van Nuys CA	10.9.80/82
			op: Western States Express	81
			op: Western States Express crashed on takeoff, Fresno CA	
	N74JT no N74JT no	oted Van Nuys oted LAX 10.81	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo;	81
24.640	N74JT nc N74JT nc crash 18.	oted Van Nuys oted LAX 10.8 6.82: over gro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG;	81 18.6.82
3A-640	N74JT no N74JT no	oted Van Nuys oted LAX 10.81	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL	81 18.6.82 12.63/64
3A-640	N74JT nc N74JT nc crash 18.	oted Van Nuys oted LAX 10.8 6.82: over gro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH	81 18.6.82 12.63/64 66
3A-640	N74JT nc N74JT nc crash 18.	oted Van Nuys oted LAX 10.8 6.82: over gro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH	81 18.6.82 12.63/64 66 69/72
3A-640	N74JT nc N74JT nc crash 18.	oted Van Nuys oted LAX 10.8 6.82: over gro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH	81 18.6.82 12.63/64 66 69/72 79
3A-640	N74JT nc N74JT nc crash 18.	oted Van Nuys oted LAX 10.8 6.82: over gro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines	81 18.6.82 12.63/64 66 69/72 79 c81
3A-640	N74JT nc N74JT nc crash 18.	oted Van Nuys oted LAX 10.8 6.82: over gro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH	81 18.6.82 12.63/64 66 69/72 79
3A-640	N74JT nc N74JT nc crash 18.	oted Van Nuys oted LAX 10.8 6.82: over gro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH william D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA	81 18.6.82 12.63/64 66 69/72 79 c81 10.82
BA-640	N74JT nc N74JT nc crash 18.	oted Van Nuys oted LAX 10.8 6.82: over gro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91
3A-640	N74JT nc N74JT nc crash 18.	oted Van Nuys oted LAX 10.8 6.82: over gro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk (fuselage stored Jackson-Higgins Field MS 98,	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91 27.3.91
BA-640	N74JT nc N74JT nc crash 18.	oted Van Nuys oted LAX 10.8 6.82: over gro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91 27.3.91
BA-640	N74JT nc N74JT nc crash 18. H18 N936S nc N936S nc	oted Van Nuys oted LAX 10.8 6.82: over gro N936S N936S	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk (fuselage stored Jackson-Higgins Field MS 98, to be stripped for interior fittings) Dunty NY 8.71, no titles, tailwheel; Higgins Field MS 11.8.98, fuselage only, recently purchas	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91 27.3.91 .98
BA-640	N74JT nc N74JT nc crash 18. H18 N936S nc N936S nc	oted Van Nuys oted LAX 10.8 6.82: over gro N936S N936S	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk (fuselage stored Jackson-Higgins Field MS 98, to be stripped for interior fittings)	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91 27.3.91 .98
	N74JT nc N74JT nc crash 18. H18 N936S nc N936S nc	oted Van Nuys oted LAX 10.8 6.82: over gro N936S N936S	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk (fuselage stored Jackson-Higgins Field MS 98, to be stripped for interior fittings) Dunty NY 8.71, no titles, tailwheel; Higgins Field MS 11.8.98, fuselage only, recently purchas	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91 27.3.91 .98
BA-640 BA-641	N74JT nc N74JT nc crash 18. H18 N936S nc N936S nc Hankins J	oted Van Nuys oted LAX 10.8 6.82: over gro N936S N936S oted Albany Co oted Jackson-H Air Service fro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk (fuselage stored Jackson-Higgins Field MS 98, to be stripped for interior fittings) Dunty NY 8.71, no titles, tailwheel; Higgins Field MS 11.8.98, fuselage only, recently purchas m owner in Atlanta area, to strip interior fittings;	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91 27.3.91 .98 ed by
	N74JT nc N74JT nc crash 18. H18 N936S nc N936S nc Hankins J	oted Van Nuys oted LAX 10.8 6.82: over gro N936S N936S oted Albany Co oted Jackson-H Air Service fro	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk (fuselage stored Jackson-Higgins Field MS 98, to be stripped for interior fittings) Dunty NY 8.71, no titles, tailwheel; Higgins Field MS 11.8.98, fuselage only, recently purchas m owner in Atlanta area, to strip interior fittings; AFLC Inc, Birmingham AL Savannah Terminal Inc, Savannah GA Aviation Sales International Ltd, Montreal QUE	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91 27.3.91 .98 ed by 2.63/66 69/70 11.72
	N74JT nc N74JT nc crash 18. H18 N936S nc N936S nc Hankins J	oted Van Nuys oted LAX 10.8 6.82: over gro N936S N936S oted Albany Co oted Jackson-H Air Service fro N269VW CF-RQD	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk (fuselage stored Jackson-Higgins Field MS 98, to be stripped for interior fittings) Dunty NY 8.71, no titles, tailwheel; Higgins Field MS 11.8.98, fuselage only, recently purchas m owner in Atlanta area, to strip interior fittings; AFLC Inc, Birmingham AL Savannah Terminal Inc, Savannah GA Aviation Sales International Ltd, Montreal QUE Edward R. Hill, Frobisher Bay, Yukon Territory	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91 27.3.91 .98 ed by 2.63/66 69/70 11.72 74
	N74JT nc N74JT nc crash 18. H18 N936S nc N936S nc Hankins J	oted Van Nuys oted LAX 10.8 6.82: over gro N936S N936S oted Albany Co oted Jackson-H Air Service fro N269VW	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk (fuselage stored Jackson-Higgins Field MS 98, to be stripped for interior fittings) Dunty NY 8.71, no titles, tailwheel; Higgins Field MS 11.8.98, fuselage only, recently purchas m owner in Atlanta area, to strip interior fittings; AFLC Inc, Birmingham AL Savannah Terminal Inc, Savannah GA Aviation Sales International Ltd, Montreal QUE Edward R. Hill, Frobisher Bay, Yukon Territory Air-Dale Ltd, Sault Ste Marie ONT	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91 27.3.91 .98 ed by 2.63/66 69/70 11.72
	N74JT nc N74JT nc crash 18. H18 N936S nc N936S nc Hankins J	oted Van Nuys oted LAX 10.8 6.82: over gro N936S N936S oted Albany Co oted Jackson-H Air Service fro N269VW CF-RQD	op: Western States Express crashed on takeoff, Fresno CA CA 28.8.79 Code Three Air Cargo; 26.7.81; 1 large "WSE" logo, windowless freighter, tailwheel; ss weight, aft CofG; Sundstrand Corp, Rockford IL Crown Steel Products Co, Orrville OH Kenneth A. Little, Canton OH William D. Burrow, Canton OH op: B.A.S. Airlines Superior Contractors & Assoc., Acworth GA Lanier & Lanier Inc, Acworth GA struck-off USCR Hankins Air Service, Jackson MS: hulk (fuselage stored Jackson-Higgins Field MS 98, to be stripped for interior fittings) Dunty NY 8.71, no titles, tailwheel; Higgins Field MS 11.8.98, fuselage only, recently purchas m owner in Atlanta area, to strip interior fittings; AFLC Inc, Birmingham AL Savannah Terminal Inc, Savannah GA Aviation Sales International Ltd, Montreal QUE Edward R. Hill, Frobisher Bay, Yukon Territory	81 18.6.82 12.63/64 66 69/72 79 c81 10.82 19.9.83/91 27.3.91 .98 ed by 2.63/66 69/70 11.72 74

N1461G accident report 5.11.85: right engine lost power soon after airborne, aircraft rolled right and struck power lines before impacting ground, destroyed by post-crash fire, 2k;

CF-RQD noted Montreal-Dorval QUE 23.8.74;

		at fly-in Oshko at fly-in Oshko	sh WI 1.8.89, tailwheel, plate BA-641; sh WI 1.8.91;	
BA-642	H18	N925J	Beech Aircraft Corp, Wichita KS: CofA issued (company demonstrator 63)	25.2.63
			Amerock Corp, Rockford IL	64/70
			Film Corp of America, Jenkintown PA	71/72
			Thomas E. Christ, Racine WI	79
			op: Check-Air Inc, Milwaukee WI	79
			Indianapolis Air Charter Services, Indianapolis IN	11.83/86
			ACE Air Cargo Express, Cleveland OH	8.8.86/90
			right gear collapsed landing, Philadelphia PA	12.11.86
			Mohican Air Services, Cleveland OH: for spares (dismantled, fuselage dumped Wakeman OH 97/07)	97/07
			struck-off USCR	22.5.13
		report 12.11.86 noted Wakema	: owned ACE Air Cargo Express; n OH 7.97;	
			hes Wakeman OH 9.8.99 plate BA-642;	
			n Air Services purchased N8962A, N925J + another from	
	Cleveland	d-Hopkins as s	pares only. He has owned Wakeman OH airfield since 19	981, still does 200
BA-643	H18	N739E	Beech Aircraft Corp, Wichita KS: CofA issued	4.3.63
			Eaton Manufacturing Co, Cleveland OH	63/64
		N739F (1	George H. Bailey Co, Fort Wayne IN	66
			Winn Dixie Inc, Charlotte NC	1.66
		N135W (2	Winn Dixie Stores Inc, Jacksonville FL	2.66/72
			groundloop landing, gear collapsed, Jacksonville FL Winn Dixie Inc, Charlotte NC	3.12.67 78
			gear collapsed landing, Pittsburgh PA	25.1.79
			International Aviation Corp, Minneapolis MN	79
			ACE Air Cargo Express, Cleveland OH	80/86
			struck snowbank taxying, Chicago-O'Hare IL	9.1.81
			minor damage on takeoff, Dayton OH	14.1.85
			Johnson Aviation Co, Elyria OH	5.88
			James D. Rowe/ Bearing Air, Nome AK	1.11.88/99
			damaged ran off runway landing, Deering AK	7.9.90
			Turbo North Aviation, Anchorage AK	22.6.00/05
			Mark W. Bills, Wasilla AK	11.7.05/06 27.4.06
			crashed on landing, Kotzebue AK reg pending, Osceola WI: USCR	10/12
			struck-off USCR	30.8.12
	accident i B747, roli N135W a N135W n	lled into snowba accident report noted Anchorag	struck-off USCR	30.8.12
3A-644	accident i B747, roli N135W a N135W n	report 19.1.81: led into snowba accident report noted Anchorag noted Anchorag N522	struck-off USCR . 25.9.70; H18S N134W (assumed this acft) Ace Air Cargo, struck ank, 7.03am, flight from Detroit; 14.1.85: Ace Air Cargo Express; e AK 12.8.00 retired stored, for sale, rep as Bering Air; e AK 17.4.04, in service; Marathon Oil Co, Findlay OH	30.8.12 by jetblast behind 9.63/66
3A-644	accident   B747, rol N135W a N135W n N135W n	report 19.1.81: led into snowba accident report noted Anchorag noted Anchorag	struck-off USCR . 25.9.70; H18S N134W (assumed this acft) Ace Air Cargo, struck ank, 7.03am, flight from Detroit; 14.1.85: Ace Air Cargo Express; e AK 12.8.00 retired stored, for sale, rep as Bering Air; e AK 17.4.04, in service; Marathon Oil Co, Findlay OH Florida Development Commission, Tallahassie FL	30.8.12 by jetblast behind 9.63/66 69
3A-644	accident   B747, rol N135W a N135W n N135W n	report 19.1.81: led into snowba accident report noted Anchorag noted Anchorag N522 N2130S	struck-off USCR . 25.9.70; H18S N134W (assumed this acft) Ace Air Cargo, struck ank, 7.03am, flight from Detroit; 14.1.85: Ace Air Cargo Express; e AK 12.8.00 retired stored, for sale, rep as Bering Air; e AK 17.4.04, in service; Marathon Oil Co, Findlay OH Florida Development Commission, Tallahassie FL State of Florida, Tallahassie FL	30.8.12 by jetblast behind 9.63/66 69 70/72
3A-644	accident   B747, rol N135W a N135W n N135W n	report 19.1.81: led into snowba accident report noted Anchorag noted Anchorag N522	struck-off USCR . 25.9.70; H18S N134W (assumed this acft) Ace Air Cargo, struck ank, 7.03am, flight from Detroit; 14.1.85: Ace Air Cargo Express; e AK 12.8.00 retired stored, for sale, rep as Bering Air; e AK 17.4.04, in service; Marathon Oil Co, Findlay OH Florida Development Commission, Tallahassie FL State of Florida, Tallahassie FL Bailey Leasing Corp, Fort Wayne IN	30.8.12 by jetblast behind 9.63/66 69 70/72 79
3A-644	accident   B747, rol N135W a N135W n N135W n	report 19.1.81: led into snowba accident report noted Anchorag noted Anchorag N522 N2130S	struck-off USCR . 25.9.70; H18S N134W (assumed this acft) Ace Air Cargo, struck ank, 7.03am, flight from Detroit; 14.1.85: Ace Air Cargo Express; e AK 12.8.00 retired stored, for sale, rep as Bering Air; e AK 17.4.04, in service; Marathon Oil Co, Findlay OH Florida Development Commission, Tallahassie FL State of Florida, Tallahassie FL Bailey Leasing Corp, Fort Wayne IN Mark H. Thompson, Marietta GA	30.8.12 by jetblast behind 9.63/66 69 70/72 79 6.82/83
3A-644	accident   B747, rol N135W a N135W n N135W n	report 19.1.81: led into snowba accident report noted Anchorag noted Anchorag N522 N2130S	struck-off USCR 25.9.70; H18S N134W (assumed this acft) Ace Air Cargo, struck ank, 7.03am, flight from Detroit; 14.1.85: Ace Air Cargo Express; e AK 12.8.00 retired stored, for sale, rep as Bering Air; e AK 17.4.04, in service; Marathon Oil Co, Findlay OH Florida Development Commission, Tallahassie FL State of Florida, Tallahassie FL Bailey Leasing Corp, Fort Wayne IN Mark H. Thompson, Marietta GA gear collapsed landing, Elgin AFB FL	30.8.12 by jetblast behind 9.63/66 69 70/72 79 6.82/83 5.8.83
3A-644	accident   B747, rol N135W a N135W n N135W n	report 19.1.81: led into snowba accident report noted Anchorag noted Anchorag N522 N2130S	struck-off USCR . 25.9.70; H18S N134W (assumed this acft) Ace Air Cargo, struck ank, 7.03am, flight from Detroit; 14.1.85: Ace Air Cargo Express; e AK 12.8.00 retired stored, for sale, rep as Bering Air; e AK 17.4.04, in service; Marathon Oil Co, Findlay OH Florida Development Commission, Tallahassie FL State of Florida, Tallahassie FL Bailey Leasing Corp, Fort Wayne IN Mark H. Thompson, Marietta GA	30.8.12 by jetblast behind 9.63/66 69 70/72 79 6.82/83
BA-644	accident B747, rol. N135W a N135W n N135W n H18 H18	report 19.1.81: led into snowba accident report noted Anchorag noted Anchorag N522 N2130S N18AW report 5.8.83: g report 12.2.85:	struck-off USCR 25.9.70; H18S N134W (assumed this acft) Ace Air Cargo, struck ank, 7.03am, flight from Detroit; 14.1.85: Ace Air Cargo Express; e AK 12.8.00 retired stored, for sale, rep as Bering Air; e AK 17.4.04, in service; Marathon Oil Co, Findlay OH Florida Development Commission, Tallahassie FL State of Florida, Tallahassie FL Bailey Leasing Corp, Fort Wayne IN Mark H. Thompson, Marietta GA gear collapsed landing, Elgin AFB FL T. Sawyer	30.8.12 by jetblast behind 9.63/66 69 70/72 79 6.82/83 5.8.83 85 12.2.85 on; ng and low cloud,
	accident B747, rol. N135W a N135W n N135W n H18 H18	report 19.1.81: led into snowba accident report noted Anchorag noted Anchorag N522 N2130S N18AW report 5.8.83: g report 12.2.85:	struck-off USCR 25.9.70; H18S N134W (assumed this acft) Ace Air Cargo, struck ank, 7.03am, flight from Detroit; 14.1.85: Ace Air Cargo Express; e AK 12.8.00 retired stored, for sale, rep as Bering Air; e AK 17.4.04, in service; Marathon Oil Co, Findlay OH Florida Development Commission, Tallahassie FL State of Florida, Tallahassie FL Bailey Leasing Corp, Fort Wayne IN Mark H. Thompson, Marietta GA gear collapsed landing, Elgin AFB FL T. Sawyer crashed dest. after takeoff, Cartersville GA ear collapsed landing Elgin AFB, owner Mark H. Thomps crashed immediately after takeoff Cartersville GA snowin	30.8.12 by jetblast behind 9.63/66 69 70/72 79 6.82/83 5.8.83 85 12.2.85 on; ng and low cloud,
3A-644 3A-645	accident i B747, roli N135W a N135W n N135W n H18 H18 accident i cargo flig	report 19.1.81: led into snowba accident report noted Anchorag noted Anchorag N522 N2130S N18AW report 5.8.83: g report 12.2.85: ht, pilot inexper	struck-off USCR 25.9.70; H18S N134W (assumed this acft) Ace Air Cargo, struck ank, 7.03am, flight from Detroit; 14.1.85: Ace Air Cargo Express; e AK 12.8.00 retired stored, for sale, rep as Bering Air; e AK 17.4.04, in service; Marathon Oil Co, Findlay OH Florida Development Commission, Tallahassie FL State of Florida, Tallahassie FL Bailey Leasing Corp, Fort Wayne IN Mark H. Thompson, Marietta GA gear collapsed landing, Elgin AFB FL T. Sawyer crashed dest. after takeoff, Cartersville GA ear collapsed landing Elgin AFB, owner Mark H. Thomps crashed immediately after takeoff Cartersville GA snowing time content of the state of the state of the state of the flight Florida Development Commission, Tallahassie FL State of Florida, Tallahassie FL Bailey Leasing Corp, Fort Wayne IN Mark H. Thompson, Marietta GA gear collapsed landing, Elgin AFB fL T. Sawyer crashed dest. after takeoff, Cartersville GA	30.8.12 by jetblast behind 9.63/66 69 70/72 79 6.82/83 5.8.83 85 12.2.85 on; ng and low cloud, iht for departure;

	Dumod n	nods N148PA	op: Commuter Airlines Speedbird Aircraft Corp, Fort Wayne IN Frederick J. Strauss, Fort Wayne IN Providence Air Charter, Providence RI James A. Dole, Coventry RI Newair Flight Inc, New Haven CT Wilford Blease, Greenville NH ACE Air Cargo Express, Cleveland OH crashed destroyed on takeoff, Louisville KY (dismantled, fuselage dumped Wakeman OH 99)	67/68 69/70 71/72 6.77/79 79 3.85 6.85 10.9.85/86 11.2.86
	N148PA accident	noted Toronto report 11.2.86	yne IN 28.5.76; ONT 11.9.79 Providence Air Charter; op ACE Air Cargo Express; USCR99: ACE Air Cargo Ex two dumped in bushes Wakeman OH 9.8.99;	kpress;
BA-646	H18	N245M	Tulsair Distributors Inc, Tulsa OK Dealers Transport Co, Memphis TN First National Bank of Memphis, Memphis TN Edwards Petroleum, Big Spring TX Wilson C. Edwards, Big Spring TX Jamie Stewart Dawson, Celina TX	4.63 64/70 71/72 79 18.8.83/18 18.10.19/20
	N245M n	oted Big Sprin	g TX 22.10.15 in Connie Edwards' hangar, good conditio	on;
BA-647	H18	N83D (2 N81DA	Youngstown Airways/ Lease Air, Youngstown OH SMB Stage Line Inc, Des Moines IA Kenneth Stoeckmann, Livermore CA Jeff S. Sanders, Portland OR op: Air Fast Freight, Long Beach CA op: North Continent Airlines, Long Beach CA op: Coast Air Freight Inc, Long Beach CA damaged ran off runway landing, Santa Maria CA	4.63/66 69/72 79 6.12.79/91 83 .83/85 85 13.2.85
			ach CA 7.9.83 North Continent Airlines;	
		cciaent report	13.2.85: op Coast Air Freight, no indication extent of dar	nage;
BA-648	H18	N24K (2	built Mahlon C. Kline, Philadelphia PA Niles Machine & Welding Co, Niles OH ran off runway on takeoff, ran into canal, submerged in water, Marco Island FL Aero Craft Leasing, Plymouth MI Burl-Air Freight Inc, Burlington WI crashed, forced landing on road, Covington KY struck-off USCR	nage; .63 64/66 69/72 25.3.72 79 23.3.79/80 19.10.79 30.10.80
BA-648 BA-649	H18 H18	-	built Mahlon C. Kline, Philadelphia PA Niles Machine & Welding Co, Niles OH ran off runway on takeoff, ran into canal, submerged in water, Marco Island FL Aero Craft Leasing, Plymouth MI Burl-Air Freight Inc, Burlington WI crashed, forced landing on road, Covington KY	.63 64/66 69/72 25.3.72 79 23.3.79/80 19.10.79
	H18	N24K (2 N52L (2 N5214 N73FA	built Mahlon C. Kline, Philadelphia PA Niles Machine & Welding Co, Niles OH ran off runway on takeoff, ran into canal, submerged in water, Marco Island FL Aero Craft Leasing, Plymouth MI Burl-Air Freight Inc, Burlington WI crashed, forced landing on road, Covington KY struck-off USCR Transcontinental Gas Pipe Line Corp, Houston TX Transcontinental Gas Pipe Line Corp, Houston TX Fontana Aviation, Iron Mountain MI	.63 64/66 69/72 25.3.72 79 23.3.79/80 19.10.79 30.10.80 6.63/66 69 24.11.69/74 3.7.74

Steven	Oxman, Riva MD	22.3.05/06
		22.3.03/00
N87711 Steven	Oxman, Riva MD	11.4.06/15
ran off	runway landing, stbd gear collapsed, Dayton OH	24.7.09
Planev	iew Aviation Services, Ahoskie NC	23.6.15/20
,	A 1.10.04, tailwheel, in service; 5.05 tailwheel; .06, tailwheel;	

BA-651	H18	N958B	Beech Aircraft Corp, Wichita KS: CofA issued	16.9.63/64
	trigear		(second H18 factory-fitted with Volpar trigear)	
			Missouri Portland Cement Co, St Louis MO	66/70
			Grede Foundries Inc, Milwaukee WI	71/72
			landed with gear locked-up, Saginaw MI	31.1.75
			Strout Aviation, Gahanna OH	79
			op: Air Bama, Muscle Shoals AL	83
			Volpar International Corp, Van Nuys CA	6.83
			Air Siesta Inc, McAllen TX	12.84
			William R. Sandlin, Harlingen TX	4.85/91
			Jim Hankins Air Service, Jackson MS	18.3.92/02
			Mike Hatfield/ Command International Airways/	
			Comat International Airways, Orlando FL	21.8.02/05
			blown on to back by Hurricane Frances, Orlando FL	5.9.04
			struck-off USCR as destroyed	23.9.05

N958B accident report 31.1.75: type Volpar H18, Hamilton spar mod. gear locked up; N958B noted Indianapolis IN 30.5.76 trigear; N958B noted Tucson AZ 11.1.83 "Air Bama" titles; N958B noted Carlsbad CA 13.6.83, 9.83, 2.84 all "Air Bama", trigear, plate BA-651;

N958B noted McAllen TX 10.87 trigear;

N958B noted Jackson-Higgins Field MS 11.8.98, trigear freighter, Hankins Air Service;

N958B noted Panama City FL 13.8.98 trigear freighter Hankins AS;

N958B: Jim Hankins Air Service fleet Status Report 10.8.98: TT 9465 hrs;

Report 11.9.04: blown on back by hurricane recently, wreck trucked out: had been active flying at Orlando prior to this;

BA-652	H18	N422X (1	Beech Aircraft Corp, Wichita KS	.63
	trigear		(first H18 factory-fitted with Volpar trigear)	
		N22X (2	New York Conservation Dept., Albany NY: delivered	11.63/66
			(flown for New York Mayor, Nelson Rockefeller)	
		N722X	State Dept. of Education, Tallahassie FL	69/72
		N22XL	sale rep.	79
			Condor Aviation, Tonawanda NY	12.83
			Sair Aviation, Syracuse NY	9.84/91
			Jim Hankins Air Service, Jackson MS	2.93/95
			El Jeffe Aviation Services, Monroe LA	12.95/99
			Beltway Motel, Baltimore MD	16.9.00/03
			crashed into ravine on takeoff, Westminster MD	23.11.03
	N722X not N22XL not N22XL not N22XL not	ted Frederick ted Reno-Stea ted Camarillo	e FL 3.10.68 trigear, plate BA-652; MD 7.97 Jim Hankins, trigear; ad NV 10.98 trigear, displayed at Air Races with For Sale CA 5.99 "For Sale" signs; 3.11.03: trigear, no injuries, wrecked;	signs;
BA-653	H18	N84D (3 N8451	Youngstown Airways/ Lease Air, Youngstown OH SMB Stage Line Inc, Des Moines IA Royal Airways, Burleson TX Patricia C. Johnson, Edgewater FL Howard Harding, Roosevelt UT	9.63/66 69/81 10.81/84 11.90 9.91

		N408BK	William McGrath/ Island Airlines, Nantucket MA William F. McGrath, Nantucket MA op: Island Airlines, Nantucket MA Woodstone Corp, Stockdale TX	7.4.93/95 1.95/06 16.7.09/17
		N18RW	Richard L.Ward, Griffin GA Richard L.Ward, Griffin GA.	9.4.18/19 10.19
	N8451 no N408BK µ	oted Oklahoma ohoto: tailwhee	ve TX 2.5.73 SMB Stage Line; a City OK 23.12.80 tailwheel, "SMB Stage Line" titles; el, "Island Airlines" titles, in service; eee FL 4.99 flying "Island Airlines" titles, tailwheel;	
BA-654	H18	N347G	built	9.63
			Combs Aircraft, Denver-Stapleton CO SMB Stage Line Inc, Des Moines IA	64/66 69/81
			Universal Aircraft Sales, Detroit MI	6.81
			Jet Services Inc	87
			Blue Ridge Aviation, Morganton NC	5.89/91
			Piedmont Air Cargo, Gastonia NC	8.1.92/95
			crashed during landing, Morganton NC struck-off USCR	25.2.92 10.4.95
BA-655	H18	N1731G	Southern Airways Co, Atlanta GA	10.63/64
		N273MB	Murray Biscuit Čo, Augusta GA	66/72
		C-GWUY	Galaxy Aviation, Drayton Valley ALTA destroyed, hit mountain at 3000 ft, Wrangell AK	8.75 11.8.77
	C-GWUY weather,		rt 11.8.77: flight Ketchikan to Wrangell, VFR flight into po	or
BA-656	H18	N9724Y	Atlantic Aviation Corp, Wilmington DE: CofA issued Maguire Leasing Corp, New York NY	20.11.63/64 66
			Palm Air Aviation, West Palm Beach FL	69/70
			Henry A. Keller, Miami FL	71/72
			FIT Aviation Inc, Melbourne FL	79
			National Bumper Exchange, West Memphis AR crashed Maico, Colombia (during illegal drug run)	19.8.80 26.9.80
	N9724Y r	noted Opa Loc	ka FL 23.8.71;	
	114.0	NO40Y	Page Airways, Rochester NY: CofA issued	3.12.63/64
BA-657	H18	N919X		
BA-657	trigear	N919X	damaged ran off icy runway, landing Worcester MA	11.12.64
BA-657	-	N919X	Simmons Machine Tool Corp, Albany NY	11.12.64 66/69
BA-657	-	N919X	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO	11.12.64 66/69 70
BA-657	-	N919X	Simmons Machine Tool Corp, Albany NY	11.12.64 66/69
BA-657	-	N919X	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX	11.12.64 66/69 70 71/72 79 22.4.81
BA-657	-	N919X	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA	11.12.64 66/69 70 71/72 79
BA-657	trigear		Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX	11.12.64 66/69 70 71/72 79 22.4.81
	trigear		Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY ady NY 8.69 "Simmons" titles, trigear; Beech Aircraft Corp, Wichita KS	11.12.64 66/69 70 71/72 79 22.4.81
	trigear N919X no	oted Schenect	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY ady NY 8.69 "Simmons" titles, trigear; Beech Aircraft Corp, Wichita KS (company demonstrator 64)	11.12.64 66/69 70 71/72 79 22.4.81 27.9.81
	trigear N919X no	oted Schenect	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY ady NY 8.69 "Simmons" titles, trigear; Beech Aircraft Corp, Wichita KS (company demonstrator 64) Mechling Barge Lines Inc, Wilmington DE	11.12.64 66/69 70 71/72 79 22.4.81 27.9.81
	trigear N919X no	oted Schenect N925N N33JC	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY ady NY 8.69 "Simmons" titles, trigear; Beech Aircraft Corp, Wichita KS (company demonstrator 64) Mechling Barge Lines Inc, Wilmington DE Penn Dixie Leasing Corp, New York NY struck-off USCR: "exported"	11.12.64 66/69 70 71/72 79 22.4.81 27.9.81 12.63/64 69 70
	trigear N919X no	oted Schenect N925N	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY ady NY 8.69 "Simmons" titles, trigear; Beech Aircraft Corp, Wichita KS (company demonstrator 64) Mechling Barge Lines Inc, Wilmington DE Penn Dixie Leasing Corp, New York NY struck-off USCR: "exported" Boca Raton Flying Service, Boca Raton FL	11.12.64 66/69 70 71/72 79 22.4.81 27.9.81 12.63/64 69
	trigear N919X no	oted Schenect N925N N33JC	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY ady NY 8.69 "Simmons" titles, trigear; Beech Aircraft Corp, Wichita KS (company demonstrator 64) Mechling Barge Lines Inc, Wilmington DE Penn Dixie Leasing Corp, New York NY struck-off USCR: "exported"	11.12.64 66/69 70 71/72 79 22.4.81 27.9.81 12.63/64 69 70
	trigear N919X no H18	oted Schenect N925N N33JC N925N	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY ady NY 8.69 "Simmons" titles, trigear; Beech Aircraft Corp, Wichita KS (company demonstrator 64) Mechling Barge Lines Inc, Wilmington DE Penn Dixie Leasing Corp, New York NY struck-off USCR: "exported" Boca Raton Flying Service, Boca Raton FL crashed in forced landing off-airport due dual engine failure on approach to land Fort Lauderdale FL	11.12.64 66/69 70 71/72 79 22.4.81 27.9.81 12.63/64 69 70 4.1.73
BA-657 BA-658	trigear N919X no H18 FAA Inde	oted Schenect N925N N33JC N925N x card confirm	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY ady NY 8.69 "Simmons" titles, trigear; Beech Aircraft Corp, Wichita KS (company demonstrator 64) Mechling Barge Lines Inc, Wilmington DE Penn Dixie Leasing Corp, New York NY struck-off USCR: "exported" Boca Raton Flying Service, Boca Raton FL crashed in forced landing off-airport due dual engine	11.12.64 66/69 70 71/72 79 22.4.81 27.9.81 12.63/64 69 70 4.1.73
	FAA Inde Not on US N33JC wa	oted Schenect N925N N33JC N925N x card confirm SCR under eiti as a KingAir b	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY ady NY 8.69 "Simmons" titles, trigear; Beech Aircraft Corp, Wichita KS (company demonstrator 64) Mechling Barge Lines Inc, Wilmington DE Penn Dixie Leasing Corp, New York NY struck-off USCR: "exported" Boca Raton Flying Service, Boca Raton FL crashed in forced landing off-airport due dual engine failure on approach to land Fort Lauderdale FL s N925N to N33JC, N925N, no details on export; her reg 7.65, 7.66, 1.67; and again 1.72; y 1.73 USCR;	11.12.64 66/69 70 71/72 79 22.4.81 27.9.81 12.63/64 69 70 4.1.73
	FAA Inde Not on US N3JC wa BA-658 a	oted Schenect N925N N33JC N925N x card confirm SCR under eiti as a KingAir b dvertised for s	Simmons Machine Tool Corp, Albany NY Malcolm Jacobs Aviation, Chesterfield MO Topeka Inn Management Inc, Topeka KS Golden Isles Aviation, St Simons Island GA Lease Merchant Inc, Boyd TX crashed forced landing off-airport, Gillette WY ady NY 8.69 "Simmons" titles, trigear; Beech Aircraft Corp, Wichita KS (company demonstrator 64) Mechling Barge Lines Inc, Wilmington DE Penn Dixie Leasing Corp, New York NY struck-off USCR: "exported" Boca Raton Flying Service, Boca Raton FL crashed in forced landing off-airport due dual engine failure on approach to land Fort Lauderdale FL s N925N to N33JC, N925N, no details on export; her reg 7.65, 7.66, 1.67; and again 1.72;	11.12.64 66/69 70 71/72 79 22.4.81 27.9.81 12.63/64 69 70 4.1.73

BA-659	H18	N350T	Tex Sun Beechcraft Inc, San Antonio TX	12.63/64
	trigear		R & B Inc, Beverly Hills CA	66
	-9700	N879T	South Plains Contracting Co, Lubbock TX	69
			Newsome & Work Metalizing Co, Akron OH	70/72
		N13AW	Newsome & Work Metalizing Co, Akron OH	79
			Basler Flight Service Inc, Oshkosh WI	6.82/89
		N811BF	Basler Flight Service Inc, Oshkosh WI	2.89/91
			Basler Turbo Conversions Inc, Oshkosh WI	15.3.94/96
			Welch Aviation, Alpena MI	22.1.96
			River City Aviation, West Memphis AR	1.10.96/99
			op: McNeely Charter Service, West Memphis AR	98/99
			Jim Hankins Air Service, Jackson MS	17.3.00/03
			Air Cargo Inc, Sebastian FL	25.2.04/13
			reg expired 31.12.13, struck-off USCR	29.1.18

N811BF noted Oshkosh WI 27.7.89 Basler ramp, "Basler" titles, trigear, plate BA-659; N811BF noted Oshkosh 1.8.90 "Basler Airlines" titles, trigear; N811BF noted Oshkosh WI 1.8.91 "Basler" titles; N811BF noted Dexter MO 14.10.97; N811BF noted West Memphis AR 4.8.98 trigear, McNeely Charter Service, plate: H18-9700 mods; N811BF noted West Memphis AR 15.8.99 trigear McNeely Charter Service; 8.02 report: N811BF still in service with Hankins; N811BF noted Jackson-Hawkins Field MS 5.8.03 trigear, Jim Hankins AS; N811BF noted Jackson-Hawkins Field MS 5.8.03 trigear, and titles;

N811BF noted St John's, Antigua 22.12.04 trigear, no titles;

BA-660	H18	N330KL	built	.64
	trigear		nosed over landing, Broomfield-Jefferson CO	6.11.64
	-		Eagle Food Centre, Rock Island IL	66
		N336GU	General United Leasing Corp, Des Moines IA	69
	Volpar		Princeton Mining Co, Terre Haute IN	70/72
	Turboliner	N638CZ	Tombigbee Aviation, Savannah TN	79
			op: Circle Rainbow Air Inc, Honolulu HI: delivered	10.80/84
			Circle Rainbow Air Inc, Honolulu HI	12.86
			struck-off USCR	9.3.90
		RP-C1103	Pacific Airways, Manila	-
			open storage, engines removed, Manila	07
		RP-C2984	C. M. Aero Services, Manila	3.12

N638CZ noted Honolulu 9.83 "Circle Rainbow Air"titles, trigear, plate BA-660; RP-C1103 noted Manila Domestic 16.4.07 stored engineless;

BA-661	H18	N800G	built	.64
			Reeves Brothers Inc, Spartanburg SC	66/69
			damaged struck snowbank landing Newport News VA	30.1.66
			Presidential Flight Service Corp, St Louis MO	70
		Williams Patent Crusher, St Louis MO gear collapsed landing, Bonne Terre MO	Williams Patent Crusher, St Louis MO	71/72
			8.11.71	
			crashed destroyed landing, Bloomington IL	21.12.72
BA-662	H18	N558B	Beech Aircraft Corp, Wichita KS: CofA issued	13.2.64
	trigear		Cleveland Pneumatic Industries, Cleveland OH	66
		N5580	rereg	
		N787Q	John Figi, Marshfield WI	71/72
			nose gear collapsed landing, Birmingham AL	29.3.78
			Nathaniel I. Gunn, Nixa MO	79
			General Electric Credit Corp, Sunnyvale CA	15.7.80/81
			op: Western States Express	81
			crashed destroyed during forced landing Newhall CA,	
			off-airport after takeoff from Van Nuys CA	28.1.81

N787Q accident report 28.1.81: Western States Express, cargo flight Van Nuys to Las Vegas NV to Salt Lake City UT, power loss both engines probably due carburetter icing, 12.42am, pilot high alcohol level, pilot & 1 pax k;

BA-663	H18	G-ASNX	Short Brothers & Harland Ltd, Gatwick	1.64
	trigear		Cameron Iron Works Ltd, Leeds	2.64/69

	(British CofA issued 6.2.64, del. via Prestwick 31.3.64)	
9Q-CSP	reg	12.69
F-BVEB	Midi Aviation/ Air Midi, Nice	13.6.74/92
	Association pour la Sauvegarde des Avions Anciens –	
	ASPAA, Marmande	21.9.92/94
	(flew 93 as "US Navy BA663/EB")	
	sold to USA: struck-off Register	3.5.94
N18ET	Gary E. Tillman, Rome GA	4.5.94
	Rivair Flying Service, Tulsa OK	20.12.94/06
	(US CofA 12.5.94, del. Toussus-Glasgow-Reykjavik 17.	5.94)
	Peter H. McMillan, San Francisco CA	5.2.07/08
N663TB	Peter H. McMillan, San Francisco CA	22.2.08
	Beech H-18 Inc, Wilmington DE	20.4.09/12
	(based North Weald, England 10/11)	
	Peter H. McMillan, San Francisco CA	28.9.12/20

G-ASNX del via Prestwick 31.3.64 fitted Volpar trigear, for American owned Cameron Iron Works; G-ASNX first noted Gatwick 31.3.64, reported as delivery;

G-ASNX noted Leeds-Bradford 13.4.64 Cameron Iron Works trigear;

G-ASNX at Biggin Hill airshow 7.5.64 displayed by UK Beech agents Short Bros, trigear;

G-ASNX noted Heathrow 26.5.64 Cameron Iron Works;

G-ASNX noted Gatwick 2.8.64;

G-ASNX noted Staverton 11.8.64;

G-ASNX noted Dublin 5.9.64 Cameron Iron Works, trigear;

G-ASNX noted Northolt 9.10.64 Cameron Iron Works;

G-ASNX noted Goodwood 19.4.65 Cameron Iron Works;

G-ASNX noted Heathrow 6.11.64 Cameron Iron Works;

G-ASNX noted Weathersfield 4.6.65 Cameron Iron Works;

G-ASNX noted Gatwick 19.6.65;

G-ASNX noted London-Heathrow 13.7.65 & 5.8.65 Cameron Iron Works;

G-ASNX visited Yeadon 2.9.65 Cameron Iron Works;

G-ASNX noted Yeadon 20.12.65;

G-ASNX at Biggin Hill Air Fair 3.66;

G-ASNX noted Amsterdam-Schiphol 6.3.66 trigear, "Cameron Iron Works";

G-ASNX noted Biggin Hill 14.5.66 "Cameron Iron Works";

G-ASNX arrived Cambridge 26.7.66 for repsray, departed 1.8.66, Cameron Iron Works;

G-ASNX noted Dusseldorf, West Germany 27.1.67;

G-ASNX noted Yeadon 21.11.68;

9Q-CSP noted Fairoaks UK 2.11.69;

9Q-CSP noted Gatwick 1.1.70 ex G-ASNX;

9Q-CSP noted Geneva Switzerland 19.12.70;

9Q-CSP noted London-Gatwick 20.3.71;

9Q-CSP noted London-Redhill 12.4.73 trigear;

F-BVEB noted Paris-Le Bourget 11.4.74 trigear;

F-BVEB visited Stansted 22.4.84, trigear no titles; Brussels 18.12.84 Midi Aviation;

F-BVEB arrived Newcastle UK 31.10.85 ex Nice, trigear, no titles, rep owned by Air Midi;

F-BVEB noted Toussus le Noble 28.7.91 for sale, no titles;

F-BVEB noted Bergerac 6.93 "USN BA-663/EB";

N18ET delivered to USA via Glasgow 5.94 as "USN BA-663/EB";

N18ET noted Tulsa-Jones Field OK 27.8.98 "USN BA-663/EB", freight door being installed at Rivair;

N18ET noted Tulsa-Jones Field 7.11.99 on overhaul "USN EB" trigear;

N18ET noted Tulsa-Jones OK 11.8.00 "USN BA663 EB VC-10", trigear;

N18ET noted Tulsa-Jones OK 3.02 "USN BA663 EB VC-10";

N663TB at airshow Little Gransden, England 29.8.10, trigear, grey white & blue, flying N663TB noted North Weald 8.10, trigear;

BA-664	H18	N8934M	built, CofA issued	31.1.64
	trigear		E. L. Bruce Co, Memphs TN	66
			Auchter Company, Jacksonville FL	69/72
			Rourke Aircraft Sales, Bartlesville OK	79
			Oklahoma Aircraft Corp, Yukon OK	8.82
			Jimmy L. Fun, Rock Springs WY	5.88
			Mike Vermeulen & Norman A. Knapp/ M & N Aviation,	

G-ASNX noted Bournemouth 5.4.64;

Rock Springs WY	6.90/98
David Oreck/ Park 7 Aviation, New Orleans LA	.98/06
Hat Aviation of Statesboro, Statesboro GA	3.10.07/11
Biff Thompson, Statesboro GA	27.5.11/17
Sale rep., Macon GA	18

N8934M noted Reno NV 13.9.75 trigear; N8934M noted Van Nuys CA 8.11.79; N8934M at fly-in Oshkosh 1.8.98 trigear owned by Norm Knapp & Mike Vermeulen of M & N Aviation, Rock Springs WY, plate: BA-664; N8934M at Beech fly-in Tullahoma TN 16.10.98 David Oreck, New Orleans LA; N8934M at Beech fly-in Tullahoma TN 10.10.99 David Oreck LA; N8934M at Beech fly-in Tullahoma TN 18.10.00; N8934M at Beech fly-in Tullahoma TN 16.10.3;

BA-665	H18	N933T	built	.64
	trigear		Textron Inc, Providence RI	66/69
			Boca Raton Flying Service, Boca Raton FL	70/72
			James A. Tripp, Punta Gorda FL	79
			Waring Aviation, Charlottesville VA	9.82/83
			Regency Enterprises, Rayville LA	7.83
			Sair Aviation, Syracuse NY	2.84/91
			Jim Hankins Air Service, Jackson MS	11.91/99
			Freight Runners Express Inc, Milwaukee WI	4.2.00/05
			Kamaka Air, Honolulu HI	12.8.05/17
			(del. to Honolulu ex Oakland CA 17.10.05)	
			University of Hawaii, Honolulu	17.1.18
			struck-off USCR	17.12.18

N933T noted Oklahoma City OK 30.10.80 trigear, no titles; N933T noted Jackson MS 18.7.97 trigear; N933T noted Jackson-Higgins Field MS 11.8.98, trigear freighter, Hankins Air Service; N933T: Jim Hankins Air Service fleet Status Report 10.8.98: TT 11,770 hrs; N933T noted Milwaukee WI 3.5.01 op Freight Runners Express since 2000; N933T noted Milwaukee WI 8.01, N933T noted Milwaukee 22.7.02 trigear; N933Tflew Junta Muni CA to North Las Vegas 8.9.05;

N933T noted Honolulu 26.10.05 just arrived ex Wisconsin on delivery to Kamaka Air, trigear;

BA-666	H18	N8984M	built	.64
	trigear		(delivered to London-Gatwick 12.12.64,	
			repainted 9L-LAH at Gatwick 12.64)	
		9L-LAH	Diamond Corp of Sierra Leone, Freetown	12.64/71
			(9L-LAH del. to USA via Prestwick-Reykjavik 26.11.71)	
		N170LG	Florida Airmotive Inc, Lantana-Palm Beach FL	72/86
			(US CofA renewed 10.2.72)	
			Aero Sun Inc, Lake Worth FL	10.90/91
			Westwind Trading Inc, Lake Worth FL	8.93
			Michael P. Bainton, Deerfield Beach FL	28.3.94/95
			Hopetown Investments Inc, Miami FL	5.7.95/96
			Tom E. Demint, Pine Bluff AR	9.5.96/02
			Excaliber 800 Inc, Wilmington DE	29.10.04/12
			Hentry E. Midura, Winder GA, later Athens GA	24.1.13/20
	N8984M	del Gatwick 12	2.12.64, trigear, panoramic windows, plate BA-666;	
	9L-LAH fi	irst noted Gatv	vick as 9L-LAH 26.12.64 owner DTWA;	
			ill 28.12.64, 6.1.65 trigear, reportedly ex N8984M;	
	9L-LAH n	oted Gatwick	20.8.66 Diamond Corp of SL;	
	9L-LAH n	oted Colombie	er Switzerland 29.7.68;	
	9L-LAH n	oted Berne, S	witzerland 8.11.68, to Gatwick same day; Turnhouse Scoti	and 10.11.68;
	Geneva 1	11.11.68;		
	9L-LAH n	oted Southam	pton UK 24.7.70;	
	91 - I A H n	oted Abidian 🤇	1 71 trigear DCWA	

9L-LAH noted Abidjan 9.1.71 trigear DCWA; 9L-LAH noted Fairoaks UK 2.5.71 9L-LAH displayed by Dismore Aviation at Cranfield Business and Light Aircraft Show 5.9.71 N170LG noted Palm Beach FL 8.10.73; N170LG noted Lantana FL 16.3.81 trigear; N170LG noted Miami FL 14.9.83 Florida Airmotive, (with N169LG A-592, both being op for Air Florida); N170LG noted Palm Beach FL 31.8.93 trigear; N170LG noted Pine Bluff AR 5.8.98 trigear, owned Ted Demint; N170LG at Beech fly-in Tullahoma TN 16.10.98 trigear, Tom & Linda Demint, Pine Bluff AR;

N170LG noted Cincinatti-Lunken OH 5.8.99 trigear, good condition;

N170LG at Beech fly-in Tullahoma TN 10.10.99 Tom Demint AR;

N170LG at Beech fly-in, Tullahoma TN 18.10.00;

N170LG noted Fond Du Lac WI 24.7.02. parking for Oshkosh, plate BA-666 trigear; N170LG at Beech fly-in Tullahoma TN 16.10.03;

BA-667	H18	N906T	Beech Aircraft Corp: demonstrator	.64
	Trigear		(demo tour of Latin & South America 3.64-4.64,	
			tour of SE Asia 10.64)	
			Continental Air Services Inc, Reno NV & Laos	.65/77
			(evacuated to Bangkok-Don Muang .75, stored)	
			Bo Larsson, Vasteras, Sweden, later Reno NV	23.3.77
			(purchased N18843 & N906T at Bangkok	.77
			sold locally .77, not delivered to Sweden)	
			sold to Thailand, struck-off USCR	24.3.77
		HS-CHP	Sununt & Co, Bangkok	3.6.77
			op: Sky of Siam Ltd, Bangkok "Sununt 9"	3.6.77/84
			damaged, props struck ground on takeoff,	
			Phetchabun Province, Thailand	5.11.77
			(wfu open storage Bangkok-Don Muang 84)	
			Boonyong Thiraworawong: purchased at auction	3.86
			Thai Yon Tractor Ltd: displayed at a yard near	
			Don Muang, in Sky of Siam paint scheme	86/88

N906T noted Don Muang Bangkok 9.75 in storage on a taxiway in centre of field with other Beech 18s and Porters evacuated from Vietnam;

BA-667 & advertised for sale 76 by Continental Air Services Pte Ltd, Singapore, both located at Don Muang Airport, Bangkok: also advertised were 7 Porters, 2 DC3s, 2 CV440s; N906T noted Don Muang 10.3.76 trigear, parked with 3 CASI Turbo Porters; N906T & N18843 purchased at Bangkok .77 by Bo Larsson from Aros Parachutingclub, Vasteras, Sweden: N18843 delivered to Sweden .77 but he sold N906T locally prior to leaving Bangkok; HS-CHP noted Bangkok 2.5.84, stored, "Sky of Siam" titles, "Sununt 9" on nose; HS-CHP noted Don Muang 21.8.86 trigear; HS-CHP displayed at garage near Don Muang 86, trigear;

BA-667 noted gate guard few miles north Bangkok Airport 10.87, no reg.;

noted 87/88 on Highway 31 near Don Muang stored in yard at garage, blue/white;

noted 9.8.88 Thai Yon Tractor Ltd yard, north of Don Muang "Thai Yon Tractor Ltd" titles:

further details South American tour 64: see Beech 18 by Robert Parmerter p.307;

BA-668	H18	N952 (2	Colorado Interstate Gas Co, Colorado Springs CO: CofA damaged engine fire while taxying after landing,	20.2.64/67
			Colorado Springs CO	29.3.67
			International Air Service Co, Burlingame CA	69/70
			Malcolm Jacobs Aviation, Chesterfield MO	71/72
			sold to Canada, struck-off USCR	7.10.74
	trigear	C-GPCD	Pacific Coastal Airlines Ltd, Nanaimo BC	11.74/79
	•		Airwest Airlines, Vancouver BC	80
		N8495A	Ridder Air Enterprises Inc, Whitman MA	26.9.80/82
			Plymouth Air Services Ltd, Plymouth MA	4.82
			Ridder Air Enterprises Inc, Whitman MA	2.83
			Coopair Ltd, Weston MA	6.83/96
			Jim Hankins Air Service, Jackson MS	30.1.96
			Alexander Aircraft Inc, Zellwood FL	4.98
			John E. Schnepf, Roche Harbour WA	19.5.98/99
			Blue Yonder Inc, Sand Springs OK	3.3.00/07
			DIVI Co, Wilmington DE	28.4.07
			(departed Tulsa OK 21.7.07 on ferry to Europe,	

	ו C-GPCD C-GPCD	noted Vancou noted Cassidy	via Reykjavik 27.7.07, Wick-Rotterdam 28.7, arrived Basle-Mulhouse 29.7.07, still based there 15) Aircraft Guarantee Corp, Onalaska TX: trustee sale rep., Liestal, Switzerland struck-off USCR E3932 Inc, Gloucestershire Airport, England ver 9.76, "Pacific Coastal Airlines Ltd, Nanaimo BC" titles, ver BC 9.8.79; Nanaimo BC 19.9.79; v, Vancouver Island BC 26.6.80 "Pacific Coastal Airline", tr	-
	N8495A n		ones OK 11.8.00, plate BA-668; am 29.7.07 on ferry, trigear, factory H18 type scheme;	
BA-669	H18 trigear	N1964A	Beech Aircraft Corp, Wichita KS: CofA issued Albamarle Paper Manufacturing, Richmond VA Leggetts Inc, Danville VA	24.2.64 69 70/72
		N333DM	Warrender Flying Service landed right gear locked-up, Omaha NE rereg	74 22.1.74 11.76
			Airbama Inc, Muscle Shoals AL Coastal Construction Co, San Louis Obispo CA op: Circle Rainbow Air Inc, Honolulu HI Circle Rainbow Air Inc, Honolulu HI sold to Philippines: struck-off USCR	79 79 .80/84 12.86/90 9.3.90
	N333DM I N333DM I N333DM 1 RP-C984	noted Van Nu noted Van Nu finally SOR 3. noted Manila	Charles R. Miller/ CM Aero Services, Manila t 22.1.74: Volpar H18, Warrender Flying -, 7 unhurt; ys CA 28.8.79 at Volpar hangar, ex Airbamba, trigear; ys CA 29.11.79 at Volpar hangar, ex Airbamba, trigear; 02 as "destroyed or scrapped"; 1.94 trigear, white & red, no titles; 4.2.98 trigear red/white in service, on CM Air ramp;	.89/98
BA-670	H18 trigear	N954 (2	Colorado Interstate Gas Co, Colorado Springs CO: Cof International Air Service Co, Burlingame CA Malcolm Jacobs Aviation, Chesterfield MO Shenandoah Oil Four Sons Flying Service, Wichita KS Mid-America Sprayers Inc, Johnson KS Pundzak Advertising, Des Moines IA Air SRV Inc/ Lone Star Flight Museum, Galveston TX	A 10.3.64/66 69/70 71/72 78 79 6.86 16.8.89/20
	N954 note Four Sons City-Wichi N954 note N954 adve N954 at a N954 at a which atte N954 note N954 note	ed Houston-He Flying Servic ta-Topeka; ed Lone Star F ertised for sal paint scheme irshow Oklaho irshow Offutt J ended the airs ed Galveston	oma City OK 20.6.98, exec scheme, trigear; AFB NE 29.8.98 exec scheme, LSFM support aircraft for how; TX 29.9.98 trigear; reston TX 9.8.03 trigear, plate BA-670;	rigear,
BA-671	H18 trigear	N1050U N711D PK-BIH	built National Financing Inc, Wilmington DE Sperry Rand Corp, White Plains NY & Phoenix AZ Associated Products of America, New York NY Floair Inc, Wichita KS sold to Indonesia, struck-off USCR (del. to Indonesia as N711D, via Singapore 11.80) Indonesian Aviation Corp/ Indoavia, Jakarta	.64 66 69/72 79 17.9.80 24.11.80 82/90

struck-off Register

20.7.18

N711D noted Van Nuys CA 10.8.72 trigear, plate BA-671; N711D noted Singapore-Seletar 11.80;

	114.0	NIGOGENA	L 314	0.4
BA-672	H18	N8825M N105PE	built Wolman Construction Co, Silver Spring MD	.64 66
		NIUSFE		69
			IDA Leasing Corp, New York NY	
			Loving Insurance Agency, Silver Spring MD	70
			Royal Brand Inc, Massillon OH	71/79
			Cannavo Aviation/ Aero Taxi, Claymont DE	19.3.81/83
			crashed destroyed landing, Allentown PA	25.11.83
	N105PE r	noted Ft Laude	erdale FL 13.6.71;	
BA-673	H18		FA Brasileira as TC-45T FAB 2885	.64/78
	trigear		(FAB designation changed .70 from TC-45T to U-45T)	
	- 0	PT-KXH	Jose A. Simioni	1.78
			Atlanta Taxi Aereo Ltda, Salvador	2.78/84
	FAB type	designations:	see Beech 18 by Robert Parmerter p 310,311	
	114.0			04/77
BA-674	H18		FA Brasileira as TC-45T FAB 2886	.64/77
	trigear		(FAB designation changed .70 from TC-45T to U-45T)	77
		PT-KVY	Jose A. Simioni	.77
	PT-KVY n	oted Lencois	Paulista, Brazil 12.80 reported as derelict;	
			ka FL 18.7.81;	
BA-675	H18		FA Brasileira as TC-45T FAB 2887	.64/77
	trigear		(FAB designation changed .70 from TC-45T to U-45T)	
	-	PT-KXQ	reg	.78
			Devilate Drazil 26 42 20	
	PI-KXQ1	noted Lencois	Paulista, Brazil 26.12.80	
BA-676		noted Lencois		.64/77
BA-676	H18	noted Lencois	FA Brasileira as TC-45T FAB 2889	.64/77
BA-676			FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T)	
BA-676	H18	PT-KXG	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver	10.3.78
BA-676	H18		FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T)	10.3.78
BA-676	H18 trigear	PT-KXG	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA -	10.3.78
	H18 trigear <i>PT-KXG r</i>	PT-KXG	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem 2.81 trigear, in service, TABA;	10.3.78 8.79/83
	H18 trigear <i>PT-KXG r</i> H18	PT-KXG	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>2.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890	10.3.78
	H18 trigear <i>PT-KXG r</i>	PT-KXG	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>7.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64)	10.3.78 8.79/83
	H18 trigear <i>PT-KXG r</i> H18	PT-KXG noted Belem 7	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>2.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T)	10.3.78 8.79/83 .64/77
	H18 trigear <i>PT-KXG r</i> H18	PT-KXG	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>2.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro	10.3.78 8.79/83
	H18 trigear <i>PT-KXG r</i> H18	PT-KXG noted Belem 7	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>2.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM,	10.3.78 8.79/83 .64/77 4.78
	H18 trigear <i>PT-KXG r</i> H18	PT-KXG noted Belem 7	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas	10.3.78 8.79/83 .64/77
	H18 trigear <i>PT-KXG r</i> H18	PT-KXG noted Belem 7 PT-KXK	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>2.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas Jose A. Simioni	10.3.78 8.79/83 .64/77 4.78 79/80
	H18 trigear <i>PT-KXG r</i> H18	PT-KXG noted Belem 7	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>2.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas Jose A. Simioni J & M Aircraft Inc, Opa Locka FL	10.3.78 8.79/83 .64/77 4.78
	H18 trigear <i>PT-KXG r</i> H18	PT-KXG noted Belem 7 PT-KXK	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>7.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas Jose A. Simioni J & M Aircraft Inc, Opa Locka FL (US CofA issued 18.3.82)	10.3.78 8.79/83 .64/77 4.78 79/80 25.2.82
BA-676 BA-677	H18 trigear <i>PT-KXG r</i> H18	PT-KXG noted Belem 7 PT-KXK	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>2.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas Jose A. Simioni J & M Aircraft Inc, Opa Locka FL	10.3.78 8.79/83 .64/77 4.78 79/80
	H18 trigear <i>PT-KXG r</i> H18 trigear	PT-KXG noted Belem 7 PT-KXK N2656X 890 noted Mia	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>7.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas Jose A. Simioni J & M Aircraft Inc, Opa Locka FL (US CofA issued 18.3.82)	10.3.78 8.79/83 .64/77 4.78 79/80 25.2.82
	H18 trigear <i>PT-KXG r</i> H18 trigear <i>TC-45T 2</i> N2656X r	PT-KXG noted Belem 7 PT-KXK N2656X 890 noted Mia	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>7.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas Jose A. Simioni J & M Aircraft Inc, Opa Locka FL (US CofA issued 18.3.82) American Professional Air Service, Miami FL ami FL 21.5.64 trigear, on delivery; ka FL 4.82 trigear;	10.3.78 8.79/83 .64/77 4.78 79/80 25.2.82 11.9.82/91
BA-677	H18 trigear <i>PT-KXG r</i> H18 trigear <i>TC-45T 2</i> <i>N2656X r</i>	PT-KXG noted Belem 7 PT-KXK N2656X 890 noted Mia	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>7.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas Jose A. Simioni J & M Aircraft Inc, Opa Locka FL (US CofA issued 18.3.82) American Professional Air Service, Miami FL ami FL 21.5.64 trigear, on delivery; ka FL 4.82 trigear; FA Brasileira as TC-45T FAB 2891	10.3.78 8.79/83 .64/77 4.78 79/80 25.2.82
BA-677	H18 trigear <i>PT-KXG r</i> H18 trigear <i>TC-45T 2</i> N2656X r	PT-KXG noted Belem 7 PT-KXK N2656X 890 noted Mia	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>7.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas Jose A. Simioni J & M Aircraft Inc, Opa Locka FL (US CofA issued 18.3.82) American Professional Air Service, Miami FL ami FL 21.5.64 trigear, on delivery; ka FL 4.82 trigear;	10.3.78 8.79/83 .64/77 4.78 79/80 25.2.82 11.9.82/91
3A-677	H18 trigear <i>PT-KXG r</i> H18 trigear <i>TC-45T 2</i> <i>N2656X r</i> H18 trigear	PT-KXG noted Belem 7 PT-KXK N2656X 890 noted Mia noted Opa Loc	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>7.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas Jose A. Simioni J & M Aircraft Inc, Opa Locka FL (US CofA issued 18.3.82) American Professional Air Service, Miami FL ami FL 21.5.64 trigear, on delivery; ka FL 4.82 trigear; FA Brasileira as TC-45T FAB 2891 (FAB designation changed .70 from TC-45T to U-45T)	10.3.78 8.79/83 .64/77 4.78 79/80 25.2.82 11.9.82/91 .64/74
BA-677 BA-678	H18 trigear <i>PT-KXG r</i> H18 trigear <i>TC-45T 2</i> <i>N2656X r</i> H18 trigear <i>photo Mia</i>	PT-KXG noted Belem 7 PT-KXK N2656X 890 noted Mia noted Opa Loc	FA Brasileira as TC-45T FAB 2889         (FAB designation changed .70 from TC-45T to U-45T)         M. Yurtserver         Transportes Aereos Regionais da Bacia Amazonica SA -         TABA, Culaba/Belem         7.81 trigear, in service, TABA;         FA Brasileira as TC-45T FAB 2890         (delivered to Brazil via Miami FL 21.5.64)         (FAB designation changed .70 from TC-45T to U-45T)         Rolim A. Amaro         Transportes Aereos Regionais SA - TAM,         Sao Paulo-Congonhas         Jose A. Simioni         J & M Aircraft Inc, Opa Locka FL         (US CofA issued 18.3.82)         American Professional Air Service, Miami FL         ami FL 21.5.64 trigear, on delivery;         tka FL 4.82 trigear;         FA Brasileira as TC-45T FAB 2891         (FAB designation changed .70 from TC-45T to U-45T)         crashed destroyed Salvador, Bahia, Brazil	10.3.78 8.79/83 .64/77 4.78 79/80 25.2.82 11.9.82/91 .64/74 20.8.74
3A-677	H18 trigear <i>PT-KXG r</i> H18 trigear <i>TC-45T 2</i> <i>N2656X r</i> H18 trigear	PT-KXG noted Belem 7 PT-KXK N2656X 890 noted Mia noted Opa Loc	FA Brasileira as TC-45T FAB 2889 (FAB designation changed .70 from TC-45T to U-45T) M. Yurtserver Transportes Aereos Regionais da Bacia Amazonica SA - TABA, Culaba/Belem <i>7.81 trigear, in service, TABA;</i> FA Brasileira as TC-45T FAB 2890 (delivered to Brazil via Miami FL 21.5.64) (FAB designation changed .70 from TC-45T to U-45T) Rolim A. Amaro Transportes Aereos Regionais SA - TAM, Sao Paulo-Congonhas Jose A. Simioni J & M Aircraft Inc, Opa Locka FL (US CofA issued 18.3.82) American Professional Air Service, Miami FL ami FL 21.5.64 trigear, on delivery; tka FL 4.82 trigear; FA Brasileira as TC-45T FAB 2891 (FAB designation changed .70 from TC-45T to U-45T) crashed destroyed Salvador, Bahia, Brazil	10.3.78 8.79/83 .64/77 4.78 79/80 25.2.82 11.9.82/91 .64/74

		PT-KVZ	retired by FAB: offered for disposal Jose A. Simioni Rio Taxi Aereo Ltda, Manaus (PT-KVZ wfu Opa Locka FL 83/93, for sale)	10.5.77 .78 1.7.82/93
		N679ZH	Zack B. Hinton, Locust Grove GA Perrone Leather Apparel Inc, Gloversville NY (restored 94/96 for US CofA, ff 7.3.96)	4.8.93 8.94/95
		N26PL	Bill Perrone/ Perrone Leather Apparel Inc/ Townsend Leather, Gloversville NY Michael Landa, Fayetteville AR	4.95/17 7.12.17/20
	PT-KVZ r PT-KVZ r PT-KVZ r PT-KVZ r PT-KVZ r PT-KVZ r PT-KVZ r N26PL vi. N26PL tiy N26PL at N26PL at N26PL at Twin Bee delivery to	noted Lencois noted Opa Loo noted Opa Loo no	ka FL 10.11.91 road side of hangar: plate H18 BA679; ka FL 6.12.91 trigear, on grass in front of hangar; ka FL 16.4.92, 8.5.92; age Opa Locka 86/93 trigear; keland FL 3.96 Bill Perrone; ny style scheme, no titles, fitted Perrone custom leather int Wichita KS 11.10.97 "Townsend Leather" & "Perone Leather cheme; 1.8.98 Townsend Leather, Johnstown NY, plate: BA-679 T	er Aviation FC-45T 2892; cated due original merter p.310;
BA-680	H18 trigear	PT-KXA	FA Brasileira as TC-45T FAB 2893 (FAB designation changed .70 from TC-45T to U-45T) Jose A. Simioni	.64/77
	FAB U45	T 2893 noted	Nilton Pinto Duarte, Americana Rio-Santos Dumont 20.10.72 ex TC-45T;	83
BA-681	H18		FA Brasileira as TC-45T FAB 2894	.64/77
DA-001	trigear	PT-KXB	(FAB designation changed .70 from TC-45T to U-45T) Jose A. Simioni Transportes Aereos Regionais da Bacia Amazonica SA	27.10.77
			TABA, Culaba/Belem	7.79
			Alfredo Sabatini Judnior, Sao Paulo struck-off Register	83 .92
BA-682	H18 trigear		FA Brasileira as TC-45T FAB 2895 (FAB designation changed .70 from TC-45T to U-45T)	.64/77
		PT-KXC	Jose A. Simioni Joaquim Olavio de Costa, Sao Paulo	19.10.77 83
		N4296E	Cornish Corp, Miami FL	11.7.83
			Steven Ferraro, Miami FL Frank Diblase, Lauderdale FL	9.84 9.86
			Manuel A. Farinas, Miami FL Alligator Air Transport Co, Ft Lauderdale FL struck-off USCR by FAA	6.88/91 10.3.92/13 11.6.13
	FAB 2895 PT-KXC I N4296E I N4296E I	5 noted Rio-Sa noted Opa Loo noted Ft Lauda noted Ft Lauda	Rio-Santos Dumont 20.10.72 ex TC45T; antos Dumont 5.7.73; cka FL 24.11.79; erdale FL 20.9.90 trigear; erdale FL 5.5.92 trigear; erdale FL 4.95;	

N4296E noted Ft Lauderdale FL 4.95;

	N4296E no N4296E no	oted Ft Laude oted Ft Laude	erdale FL10.4.97, 9.97; erdale FL 12.1.98 trigear, retired stored; erdale FL 11.8.05 in service; erdale-Executive FL 5.2.09;	
BA-683	H18 trigear	PT-KXL	FA Brasileira as TC-45T FAB 2896 (FAB designation changed .70 from TC-45T to U-45T) Jose A. Simioni	.64/77 26.1.78
			Alberto Ris, Vitorio	83
BA-684	H18 trigear	PT-KXM	FA Brasileira as TC-45T FAB 2897 (FAB designation changed .70 from TC-45T to U-45T) Moacyr Bueno de Moraes, Sao Paulo	.64/77 11.8.78/83
			Museu Aeroespaciale, Campos dos Afonsos AB	98/05
			dos Afonsos AB Rio 11.4.98 in Museu Aerospaciale restor a at Campo dos Afonsos 1.00; not seen at museum by 201	
BA-685	H18	PP-FMR	Ministerio de Fazenda, Rio de Janeiro	.64/65
	trigear		to FA Brasileira as TC-45T FAB 2909 (FAB designation changed .70 from TC-45T to U-45T)	78
		PT-KXJ	Jose Gilberto de Farias, Vera Cruz (note: PP-FMR still registered 83 Min. Fazenda: struck-off egister 28.3.91)	5.78/83
	PT-KXJ no	oted Opa Loci	ka FL 20.6.78, trigear, not titles;	
BA-686	H18 trigear		FA Brasileira as TC-45T FAB 2899 (FAB designation changed .70 from TC-45T to U-45T)	.64/77
	lingeal	PT-KXD	Jose A. Simioni	3.1.78
			Armando Viana Egresa Transportes Aereos Regionais SA - TAM,	79
		N4498M ETL1319	Sao Paulo-Congonhas K & B Enterprises Inc: US reg candidate	12.79 26.10.83
		EILIJI9	(to FA Mexicana as ETL1319) Santa Lucia AB museum, Mexico City (displ. as "FAM ETL1319")	- 18/20
	PT-KXD no	oted Opa Loc	ka FL 4.10.77, civil reg taped on over FAB basic scheme;	
BA-687	H18 trigear		FA Brasileira as TC-45T FAB 2898 (FAB designation changed .70 from TC-45T to U-45T)	.64/77
		PT-KXE	Jose A. Simioni Atlanta Taxi Aereo Ltda, Salvador	27.10.77 79/83
			retired Salvador	03/11
	FAB C45T PT-KXE pl	2898 noted F hoto (no date)	Dumont 7.1.68; Rio-Santos Dumont 20.10.72; ) Salvador: civil scheme very weathered, flat tyres, trigear; <sup>,</sup> retired 10.03, unmoved 12.08;	
BA-688	H18	N5638K	built Mitwasterr Com Das Maises IA	.64
			Midwestern Corp, Des Moines IA Magna Charta Consultants, Denver CO	66 69
		N800WA	Air Travel Service Co, Lincoln NE Winship Air Service/ Troy Air, Anchorage AK (named <i>Alaskan Trader</i> )	70/72 74/79 74/79
	Volpar Turboliner		(conversion to Turboliner II trigear completed 1.75) gear collapsed landing, damaged by fire, Galena AK	20.7.77
	(conv. #01	8)	gear collapsed on takeoff run, Kenai AK Troy Air, Anchorage AK	23.1.81 1.84
		N800TH	Troy Air, Anchorage AK Connie Kalitta Services, Willow Run MI	3.84/90 6.90/91
		N508FS	Kalitta Flying Service, Detroit-Willow Run MI FS Air Service, Anchorage AK	11.92/93 5.93

			Kalitta Flying Service, Detroit-Willow Run MI Kitty Hawk Charters Inc, Morristown TN	6.93/99 16.6.99/00 7.2.02/06
		N30GB	Dixie Aviation Enterprises, Hendersonville TN GB Airlink inc, Fort Launderdale FL Airsquid Aviation, Las Vegas NV	7.2.02/06 9.6.10/18 3.1.20
	thrust, fire N800WA N800WA N800TH r N508FS r N508FS r N508FS r N508FS r	e after impact, noted Van Nu accident repoi noted Anchora noted Anchora noted Anchora noted Willow R noted Willow R	ys 12.11.77 Troy Air t 23.1.81: Troy Air, minor damage, gear mechanical fai ge AK 27.5.90 Turboliner, no titles; ge AK 8.94 op FS Air Services; ge 10.94 "FS Air" titles, Turboliner, blue/white; Run MI 23.7.00 "FS Air" titles, overhaul in Kitty Hawk ha	ilure;
BA-689	H18	N404X (1	built	.64
		N18X (2	Ontario Airways, Auburn NY	66
		N218X	Ontario Airways, Auburn NY	.66
			heavy landing, gear collapsed, Dayton OH	21.7.67
			Automatic Sprinkler Corp, Cleveland OH	69 70
			reg. pending Carolina Leasing Inc, Anderson SC	70
			James H. Bailey, Laurinburg NC	8.81
			Waring Aviation, Charlottesville VA	11.81/83
			Sair Aviation, Syracuse NY	84
			crashed destroyed after takeoff, Plattsburgh NY	19.3.84
BA-690	H18	N1151S	built	.64
	trigear	N1161S	J. P. Stevens & Co, New York NY	66
		N561DL	Southern Airways Beechcraft Inc, Atlanta GA	.66
		N21S	Douglas & Lomaston Co, Columbus NE Gifford Aviation, Anchorage AK	.66/72 79
		N213	Panorama Air Tour, Honolulu HI (fleet #65)	.79/84
			AirTour Acquisition Corp, Honolulu HI	82
			Pacific Air Express Inc, Honolulu HI	3.84
			ditched in sea after takeoff Honolulu HI	17.7.84
	N21S not colour sch N21S Hoi N21S not	ed Honolulu 5. heme, brown 8 nolulu 23.8.81	GA 3.10.68 trigear, plate BA-690; .9.79 "Panorama Air Tour" titles, fleet #65 ,trigear: new & white ; "Panorama AT #65; 1 in Beech 18 tourist formation;	aircraft, not yet in fle
	Panorama accident r unable to	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera	I 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65; Pacific Alr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport;	
BA-691	Panorama accident r unable to H-18	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera N1152S	I 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65; Pacific Alr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport; J. P. Stevens & Co, New York NY: CofA issued	20.6.64
BA-691	Panorama accident r unable to	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera	I 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65; Pacific Alr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport; J. P. Stevens & Co, New York NY: CofA issued Southern Airways Beechcraft, Atlanta GA	20.6.64 66
BA-691	Panorama accident r unable to H-18	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera N1152S	<ul> <li>I 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65;</li> <li>Pacific Alr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport;</li> <li>J. P. Stevens &amp; Co, New York NY: CofA issued Southern Airways Beechcraft, Atlanta GA Dixie Yarns Inc, Chattanooga TN</li> </ul>	20.6.64 66 69
BA-691	Panorama accident r unable to H-18	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera N1152S	I 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65; Pacific Alr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport; J. P. Stevens & Co, New York NY: CofA issued Southern Airways Beechcraft, Atlanta GA	20.6.64 66
BA-691	Panorama accident r unable to H-18	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera N1152S	<ul> <li>I 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65;</li> <li>Pacific Alr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport;</li> <li>J. P. Stevens &amp; Co, New York NY: CofA issued Southern Airways Beechcraft, Atlanta GA Dixie Yarns Inc, Chattanooga TN Executive Flight Service, Portland OR</li> </ul>	20.6.64 66 69 70/72
BA-691	Panorama accident r unable to H-18 trigear N1162S r	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera N1152S N1162S	<ul> <li>I 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65;</li> <li>Pacific Alr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport;</li> <li>J. P. Stevens &amp; Co, New York NY: CofA issued Southern Airways Beechcraft, Atlanta GA Dixie Yarns Inc, Chattanooga TN Executive Flight Service, Portland OR Claude Ross, Rhine GA</li> </ul>	20.6.64 66 69 70/72 78/79
	Panorama accident r unable to H-18 trigear N1162S r	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera N1152S N1162S	<ul> <li>I 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65; Pacific Alr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport;</li> <li>J. P. Stevens &amp; Co, New York NY: CofA issued Southern Airways Beechcraft, Atlanta GA Dixie Yarns Inc, Chattanooga TN Executive Flight Service, Portland OR Claude Ross, Rhine GA sale reported, Miami FL: USCR</li> <li>olis IN 30.5.76 trigear;</li> </ul>	20.6.64 66 69 70/72 78/79
	Panorama accident r unable to H-18 trigear N1162S r N1162S r	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera N1152S N1162S N1162S	<ul> <li>II 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65; Pacific AIr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport;</li> <li>J. P. Stevens &amp; Co, New York NY: CofA issued Southern Airways Beechcraft, Atlanta GA Dixie Yarns Inc, Chattanooga TN Executive Flight Service, Portland OR Claude Ross, Rhine GA sale reported, Miami FL: USCR</li> <li>olis IN 30.5.76 trigear; Fulton County GA 6.78, no titles, trigear;</li> </ul>	20.6.64 66 69 70/72 78/79 91
BA-692	Panorama accident r unable to H-18 trigear N1162S r N1162S r H18 H18	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera N1152S N1162S N1162S	<ul> <li>II 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65; Pacific AIr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport;</li> <li>J. P. Stevens &amp; Co, New York NY: CofA issued Southern Airways Beechcraft, Atlanta GA Dixie Yarns Inc, Chattanooga TN Executive Flight Service, Portland OR Claude Ross, Rhine GA sale reported, Miami FL: USCR</li> <li>olis IN 30.5.76 trigear; Fulton County GA 6.78, no titles, trigear;</li> <li>built Central Oil Co, Laurel MS</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued</li> </ul>	20.6.64 66 69 70/72 78/79 91 .64 66 18.6.64
BA-692	Panorama accident r unable to H-18 trigear N1162S r N1162S r H18	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera N1152S N1162S noted Indianap noted Atlanta-F	<ul> <li>II 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65; Pacific AIr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport;</li> <li>J. P. Stevens &amp; Co, New York NY: CofA issued Southern Airways Beechcraft, Atlanta GA Dixie Yarns Inc, Chattanooga TN Executive Flight Service, Portland OR Claude Ross, Rhine GA sale reported, Miami FL: USCR</li> <li>olis IN 30.5.76 trigear; Fulton County GA 6.78, no titles, trigear;</li> <li>built Central Oil Co, Laurel MS</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Shop Rite Food Stores, Albuquerque NM</li> </ul>	20.6.64 66 69 70/72 78/79 91 .64 66 18.6.64 66
BA-691 BA-692 BA-693	Panorama accident r unable to H-18 trigear N1162S r N1162S r H18 H18	ed Honolulu H a Air fleet list a report 17.7.84: climb, delibera N1152S N1162S noted Indianap noted Atlanta-F	<ul> <li>II 9.83 "Panorama Air" titles, trigear, plate BA-690; as at 15.11.83: BA-690 tt 10,102 hrs, fleet #65; Pacific AIr Express, engine failure on takeoff Honolulu ately ditched into sea next to airport;</li> <li>J. P. Stevens &amp; Co, New York NY: CofA issued Southern Airways Beechcraft, Atlanta GA Dixie Yarns Inc, Chattanooga TN Executive Flight Service, Portland OR Claude Ross, Rhine GA sale reported, Miami FL: USCR</li> <li>olis IN 30.5.76 trigear; Fulton County GA 6.78, no titles, trigear;</li> <li>built Central Oil Co, Laurel MS</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued</li> </ul>	20.6.64 66 69 70/72 78/79 91 .64 66 18.6.64

			Allegheny Aviation, Pittsburgh PA Superior Electrical Contractors, Acworth GA Gene F. Fisher, Bolling Springs PA Carl W. Scholl, Borrego Springs CA & Chino CA DB Aero Inc, Wilmington DE	71/72 79 3.84/91 19.9.94/97 20.5.97/20
	Believed I	DB Aero is Dar	A 3.93,12.93, 2.95, 24.4.95, 20.9.95 all trigear, good condit ryl Bond/Aero Classics, Chino (warbird & racing pilot); n WI fly-in 7.15. 7.16;	ion, green/white;
BA-694	H18 trigear	N8804M (1 N20PA (2	Beech Aircraft Corp, Wichita KS Pennsylvania Aeronautics Commission, Cumberland PA State of Pennsylvania, Cumberland PA Sair Aviation, Syracuse NY damaged forced landing in field, Utica NY struck-off USCR	.64 .64/70 71/83 18.10.84/91 1.6.88 28.1.91
	N20PA no	oted Youngstov	PA 20.7.68 yellow, "The Keystone State" titles, trigear; wn OH 25.2.83 State of PA, trigear; Sair Aviation, forced landing in field, undercarriage collapse	d;
BA-695	H18 trigear	N925H	Beech Aircraft Corp, Wichita KS (company demonstrator 64/65) Calaveras Cement Co, San Andreas CA Bush Hog Division, Selma AL	.64/65 66 69/72
		N55JM N58JM	rereg rereg Astro Airways, Pine Bluff AR crashed destroyed landing, Centreville IL	.75 20.7.77/78 25.3.78
	aircraft; N58JM ac	cident report 2	CA 11.65, trigear, Beech demonstrator and Mrs Olive Beec 25.3.78: flight Pine Bluff AR to East St Louis IL, struck wire zzle 11am, 3k, 3 serious injuries;	-
BA-696	H18 trigear	N7952K	Beech Aircraft Corp, Wichita KS: CofA issued Twin Disc Clutch Co, Racine WI James R. Bussard, Pontiac MI Provo Flying Service Renge Inc, Boynton Beach FL op: Charles Air Service accident Nassau, Bahamas	9.7.64 66/70 79 83/85 27.5.86/90 90 25.3.90
	N7952K n	oted Ft Lauder	e FL 20.11.83 trigear "Provo Flying Service" small titles; rdale-Executive FL 20.3.85 Provo Flying Service; no details, owner Charles Air Service;	
BA-697	H18	N177G N1772	built landed wheels-up, Knoxville-Island TN Southeastern Beechcraft Inc, Knoxville TN Barnett First National Bank, Jacksonville FL Aamtax Corp, St Petersburg FL	.64 21.11.64 66/70 70/72 5.6.73/91
	N1772 no	ted West Palm	Beach FL 19.7.81;	
BA-698	H18 trigear	N7962K N88DB N161SP	Beech Aircraft Corp, Wichita KS: CofA issued Tecumseh Products Inc, Tecumseh MI R & K Construction Inc, Orlando FL rereg AP St Philip Inc, Tampa FL	9.7.64 66/70 71/72 1.77/79
			Providence Air Charter, Providence RI op: Air Pensylvania Perkiomen Airways Ltd, Reading PA aborted takeoff, rolled into 14 feet gully, Hazelton PA	80 80/81 31.3.81 11.3.81
	N161SP r	noted Miami FL	. 3.10.77, trigear, no titles, took off;	

BA-699	H18	N7998K	Beech Aircraft Corp, Wichita KS: CofA issued	29.1.65
	trigear		General Oilfield Supply Co, Evansville IN	66/79
			nose gear collapsed landing, Atlanta-Fulton GA	17.4.81
			Julac Export Corp, Boynton Beach FL	10.81
			Renge Inc, Boynton Beach FL	5.86/91
			Justin K. Houghton, Shelbourne VT	7.7.92/20
	N7998K no	ted Fort Lau	derdale FL 20.11.83 no titles, trigear; derdale-Executive FL 25.10.84, 5.92; on VT 2.1.08 trigear, vista windows, exec paint scheme, i	n service;
3A-700	H18	N828LS	Beech Aircraft Corp, Wichita KS: CofA issued	24.7.64
			struck post taxying after landing, Houston TX	19.4.65
	ATE		Riviana Foods Inc, Abbeville LA	66
	Westwind I		(rebuilt as ATE Westwind I trigear .67)	
	trigear	N995RF	Riviana Foods Inc, Abbeville LA	69/70
		N355C	C. M. Waters, Alexandria LA	71/72
			Metro Air Taxi, College Park MD	79
			op: Active Aero Charter, Willow Run MI	81
			gear retracted on landing roll, Detroit-Metro MI	11.7.81
			Smithair Inc, Sharpsburg GA	85
			Ajax Aircraft Leasing Inc, Dover DE	5.85/93
		N982AA	Ajax Aircraft Leasing Inc, Belleville MI	3.3.93
		N355C	Ajax Aircraft Leasing Inc, Belleville MI	.93/94
			Yip Group, Belleville MI	11.94/95
			Rousch Air Inc, Livonia MI	16.2.95/11
			(support aircraft for Jack Rousch Ford Race Team,	
			national Atlanta Tana Field CA by 2000)	
			retired Atlanta-Tara Field GA by 2009)	
			struck-off USCR	18.7.11
				18.7.11
	N355C note N355C pho N355C acc Detroit MI, p N355C note N355C note	ed Washingt ito 3.81, no t ident report pilot inadver ed Willow Ru ed Willow Ru ed Willow Ru ed Willow Ru ed Willow Ru ed Willow Ru ed Willow Ru	struck-off USCR (noted open storage stripped Tara Field GA 8.17,	Ashville GA to plate BA-700, r;
- <del>7</del> 01	N355C note N355C pho N355C acc Detroit MI, p N355C note N355C note	ed Washingt to 3.81, no t ident report pilot inadver ed Willow Ru ed Tara Field N5733K	struck-off USCR (noted open storage stripped Tara Field GA 8.17, reported fuselage to become a childrens playhouse) : reg quoted as "N828LS": minor damage, no injuries; on-National 9.73, trigear PT-6 turbines; itles: trigear, turbines; 11.7.81: no operator quoted, minor damage, cargo flight / tantly retracted gear 12.15am; in MI 14.7.81 Westwind I, in MI 3.8.89 trigear turbines, in MI 7.91 trigear turbine; DNT 16.2.85 Smithair, Sharpsburg GA; in MI 2.97 as Westwind I; in MI 2.97 rigear; in MI 8.97 Westwind I; in MI 3.8.99 freighter, stored with props removed, trigear, in MI 2.3.7.00 freighter, stored with props removed, trigear, in MI 1.03 trigear; in 11.6.03 intact; d GA 20.8.17 standing outside on trigear, turbine nacelles Beech Aircraft Corp, Wichita KS: CofA issued	Ashville GA to plate BA-700; r;
A-701	N355C note N355C pho N355C acc Detroit MI, p N355C note N355C note	ed Washingt to 3.81, no t ident report pilot inadver ed Willow Ru ed Willow Ru	struck-off USCR (noted open storage stripped Tara Field GA 8.17, reported fuselage to become a childrens playhouse) : reg quoted as "N828LS": minor damage, no injuries; on-National 9.73, trigear PT-6 turbines; ittles: trigear, turbines; 11.7.81: no operator quoted, minor damage, cargo flight / tantly retracted gear 12.15am; in MI 14.7.81 Westwind I, in MI 3.8.89 trigear turbines, in MI 7.91 trigear turbine; DNT 16.2.85 Smithair, Sharpsburg GA; in MI 2.97 as Westwind I; in MI 2.3.97 trigear; in MI 8.97 Westwind I; in MI 3.8.99 freighter, stored with props removed, trigear, in MI 3.8.99 freighter, stored with props removed, trigear, in MI 2.3.7.00 freighter, stored with props removed, trigear in 11.6.03 intact; d GA 20.8.17 standing outside on trigear, turbine nacelles Beech Aircraft Corp, Wichita KS: CofA issued Riegel Paper Corp, New York NY	Ashville GA to plate BA-700, r; s, parts missing
A-701	N355C note N355C pho N355C acc Detroit MI, p N355C note N335C note N355C note	ed Washingt to 3.81, no t ident report pilot inadver ed Willow Ru ed Tara Field N5733K	struck-off USCR (noted open storage stripped Tara Field GA 8.17, reported fuselage to become a childrens playhouse) : reg quoted as "N828LS": minor damage, no injuries; on-National 9.73, trigear PT-6 turbines; itles: trigear, turbines; 11.7.81: no operator quoted, minor damage, cargo flight / tantly retracted gear 12.15am; in MI 14.7.81 Westwind I, in MI 3.8.89 trigear turbines, in MI 7.91 trigear turbine; DNT 16.2.85 Smithair, Sharpsburg GA; in MI 2.97 as Westwind I; in MI 2.97 rigear; in MI 8.97 Westwind I; in MI 3.8.99 freighter, stored with props removed, trigear, in MI 2.3.7.00 freighter, stored with props removed, trigear, in MI 1.03 trigear; in 11.6.03 intact; d GA 20.8.17 standing outside on trigear, turbine nacelles Beech Aircraft Corp, Wichita KS: CofA issued	Ashville GA to plate BA-700, r; s, parts missing 31.7.64
A-701	N355C note N355C pho N355C acc Detroit MI, p N355C note N335C note N355C note	ed Washingt to 3.81, no t ident report pilot inadver ed Willow Ru ed Tara Field N5733K N251R	struck-off USCR (noted open storage stripped Tara Field GA 8.17, reported fuselage to become a childrens playhouse) : reg quoted as "N828LS": minor damage, no injuries; on-National 9.73, trigear PT-6 turbines; itles: trigear, turbines; 11.7.81: no operator quoted, minor damage, cargo flight / tantly retracted gear 12.15am; in MI 14.7.81 Westwind I, in MI 3.8.89 trigear turbines, in MI 7.91 trigear turbine; DNT 16.2.85 Smithair, Sharpsburg GA; in MI 2.97 as Westwind I; in MI 2.97 as Westwind I; in MI 3.8.99 freighter, stored with props removed, trigear, in MI 3.8.99 freighter, stored with props removed, trigear, in MI 2.3.7.00 freighter, stored with props removed, trigear, in MI 1.03 trigear; in 11.6.03 intact; d GA 20.8.17 standing outside on trigear, turbine nacelles Beech Aircraft Corp, Wichita KS: CofA issued Riegel Paper Corp, New York NY International Air Service Co, Burlingame CA Midvale Dynamics Corp, Clayton MO	Ashville GA to plate BA-700 r; s, parts missing 31.7.64 66 69/70 71/72
A-701	N355C note N355C pho N355C acc Detroit MI, p N355C note N335C note N355C note	ed Washingt to 3.81, no t ident report pilot inadver ed Willow Ru ed Tara Field N5733K	struck-off USCR (noted open storage stripped Tara Field GA 8.17, reported fuselage to become a childrens playhouse) : reg quoted as "N828LS": minor damage, no injuries; on-National 9.73, trigear PT-6 turbines; itles: trigear, turbines; 11.7.81: no operator quoted, minor damage, cargo flight / tantly retracted gear 12.15am; in MI 14.7.81 Westwind I, in MI 3.8.89 trigear turbines, in MI 7.91 trigear turbine; DNT 16.2.85 Smithair, Sharpsburg GA; in MI 2.97 as Westwind I; in MI 2.97 rigear; in MI 8.97 Westwind I; in MI 3.8.99 freighter, stored with props removed, trigear, in MI 3.8.99 freighter, stored with props removed, trigear, in MI 2.3.7.00 freighter, stored with props removed, trigear in MI 1.03 trigear; in 11.6.03 intact; d GA 20.8.17 standing outside on trigear, turbine nacelles Beech Aircraft Corp, Wichita KS: CofA issued Riegel Paper Corp, New York NY International Air Service Co, Burlingame CA	Ashville GA to plate BA-700 r; s, parts missing 31.7.64 66 69/70
A-701	N355C note N355C pho N355C acc Detroit MI, p N355C note N335C note N355C note	ed Washingt to 3.81, no t ident report pilot inadver ed Willow Ru ed Tara Field N5733K N251R	struck-off USCR (noted open storage stripped Tara Field GA 8.17, reported fuselage to become a childrens playhouse) : reg quoted as "N828LS": minor damage, no injuries; on-National 9.73, trigear PT-6 turbines; itles: trigear, turbines; 11.7.81: no operator quoted, minor damage, cargo flight / tantly retracted gear 12.15am; in MI 14.7.81 Westwind I, in MI 3.8.89 trigear turbines, in MI 7.91 trigear turbine; DNT 16.2.85 Smithair, Sharpsburg GA; in MI 2.97 as Westwind I; in MI 2.97 as Westwind I; in MI 3.8.99 freighter, stored with props removed, trigear, in MI 3.8.99 freighter, stored with props removed, trigear, in MI 2.3.7.00 freighter, stored with props removed, trigear, in MI 1.03 trigear; in 11.6.03 intact; d GA 20.8.17 standing outside on trigear, turbine nacelles Beech Aircraft Corp, Wichita KS: CofA issued Riegel Paper Corp, New York NY International Air Service Co, Burlingame CA Midvale Dynamics Corp, Clayton MO	Ashville GA to plate BA-700 r; s, parts missing 31.7.64 66 69/70 71/72
3A-701	N355C note N355C pho N355C acc Detroit MI, p N355C note N335C note N355C note	ed Washingt to 3.81, no t ident report pilot inadver ed Willow Ru ed Tara Field N5733K N251R	struck-off USCR (noted open storage stripped Tara Field GA 8.17, reported fuselage to become a childrens playhouse) : reg quoted as "N828LS": minor damage, no injuries; on-National 9.73, trigear PT-6 turbines; ittles: trigear, turbines; 11.7.81: no operator quoted, minor damage, cargo flight / tantly retracted gear 12.15am; in MI 14.7.81 Westwind I, in MI 3.8.89 trigear turbines, in MI 7.91 trigear turbine; DNT 16.2.85 Smithair, Sharpsburg GA; in MI 2.97 as Westwind I; in MI 2.97 as Westwind I; in MI 3.8.99 freighter, stored with props removed, trigear, in MI 3.8.99 freighter, stored with props removed, trigear, in MI 2.7.00 freighter, stored with props removed, trigear, in MI 1.03 trigear; in 11.6.03 intact; d GA 20.8.17 standing outside on trigear, turbine nacelles Beech Aircraft Corp, Wichita KS: CofA issued Riegel Paper Corp, New York NY International Air Service Co, Burlingame CA Midvale Dynamics Corp, Clayton MO On Mark Aviation, Knoxville TN Sair Aviation, Syracuse NY Jim Hankins Air Service, Jackson MS	Ashville GA to plate BA-700 r; s, parts missing 31.7.64 66 69/70 71/72 79 7.84 25.7.90/05
-701	N355C note N355C pho N355C acc Detroit MI, p N355C note N335C note N355C note	ed Washingt to 3.81, no t ident report pilot inadver ed Willow Ru ed Tara Field N5733K N251R	struck-off USCR (noted open storage stripped Tara Field GA 8.17, reported fuselage to become a childrens playhouse) : reg quoted as "N828LS": minor damage, no injuries; on-National 9.73, trigear PT-6 turbines; ittles: trigear, turbines; 11.7.81: no operator quoted, minor damage, cargo flight / tantly retracted gear 12.15am; in MI 14.7.81 Westwind I, in MI 3.8.89 trigear turbines, in MI 7.91 trigear turbine; DNT 16.2.85 Smithair, Sharpsburg GA; in MI 2.97 as Westwind I; in MI 2.97 as Westwind I; in MI 3.8.99 freighter, stored with props removed, trigear, in MI 3.8.99 freighter, stored with props removed, trigear, in MI 2.7.00 freighter, stored with props removed, trigear, in MI 1.03 trigear; in 11.6.03 intact; d GA 20.8.17 standing outside on trigear, turbine nacelles Beech Aircraft Corp, Wichita KS: CofA issued Riegel Paper Corp, New York NY International Air Service Co, Burlingame CA Midvale Dynamics Corp, Clayton MO On Mark Aviation, Knoxville TN Sair Aviation, Syracuse NY	Ashville GA to plate BA-700 r; s, parts missing 31.7.64 66 69/70 71/72 79 7.84

N161SP accident report 11.3.81: Air Pensylvania: pax flight, took off with snow on wings, ran off runway into gully, 2 crew & pax unhurt;

N123MD noted Panama City FL 13.8.98 trigear freighter, Jim Hankins AS; N123MD: Jim Hankins Air Service fleet Status Report 10.8.98: TT 10,752 hrs;

8.02 report: N123MD still in service with Hankins; crash 21.9.07 cargo flight to Bahamas, operated by Monarch Air Group, pilot badly hurt, struck building and crashed on highway, aircraft destroyed;

BA-702	H18	N7969K	Beech Aircraft Corp, Wichita KS: CofA issued	19.8.64
	trigear		Lehigh Portland Cement Co, Allentown PA	66
			Reading Aviation Service/ Suburban Airlines,	00/70
			Reading PA	69/72
			Midstate Airlines, Marshfield WI	77/79 .79/94
			Union Flights, Sacramento CA	.79/94 18.5.94/97
			Polynesian Airways, Honolulu HI	
			crashed on takeoff, destroyed by fire Honolulu HI	22.2.97
			NY 27.8.74, trigear;	
			eld WI 10.78 "Midstate" titles, trigear;	
	N7969K r	iotea Honoiui	u 6.96 trigear;	
BA-703	H18	PT-CEZ	Central Electrica de Furnas SA, Rio	.64/65
	trigear		FA Brasileira as FAB TC-45T 2908	
		PT-KXI	reg.	.78
			Jose R. D. Fortunato	9.6.80
			Carlos Alberto Edo Palma, Sao Paulo	83
			ka FL 13.4.82 trigear,	
	PT-KXI n	oted Opa Loc	ka FL 27.5.82;	
BA-704	H18	N5645K	built	.64
	trigear		Iowa Beef Packers, Denison IA	66/69
			Nickerson & Nickerson Service Co, Eldon MO	70
			Tidwell Industries Inc, Haleyville LA	71/73
			Volpar Inc, Van Nuys CA	75
			Bailey Leasing Corp, Fort Wayne IN	20.2.75
			Helitrans Australia, Cairns QLD	20.5.75/76
			(N5645K departed Oakland CA 7.6.75 on del. to	
			Australia, arrived Cairns 14.6.75)	
		VH-PDI	Helitrans Australia Pty Ltd, Cairns QLD: reg	11.2.76/78
			Sunbird Airlines, Gladstone QLD	1.9.78
			Sunbird Airlines Pty Ltd, Gladstone QLD	19.12.78/80
			Helimuster Pty Ltd, Sydney-Bankstown NSW	14.1.80
			Eagle Airways, Sydney-Bankstown NSW	7.3.80/80
			Noel R. Vinson Trading Pty Ltd, Sydney NSW	5.9.84
			A. S. Collins, Sydney NSW	2.10.84
			Airtransit, Adelaide SA	88/89
		VH-ATX	Airtransit, Adelaide SA	6.12.89/94
			renamed: Air Kangaroo Island, Adelaide SA	90/94
			Russell Mann/ Sunland Aviation,	
			Brisbane-Archerfield QLD: delivered to Archerfield	17.6.94/04
			(restored at Archerfield 94/99, ff 27.4.99)	
			Russell Mann/ Antique Airways, Redcliffe QLD	.99/11
			Anthony Mitchell, Perth WA	15.7.11/14
			Lena Votrubec, Sydney NSW	27.1.15/20
			Helitrans from Volpar in deal through Bailey Leasing Co,	
	TT 4683 I	hrs; ferry pilot	was Peter Jensen of Helitrans who arrived Van Nuys 4.75	
	while airc	raft being pre	pared by Volpar;	
			each CA 20 5 75 for installation of ferry kit	

N5645K noted Long Beach CA 20.5.75 for installation of ferry kit; Jensen was endorsed on type then departed Van Nuys 6.6.75 for Oakland, departed Oakland on evening of 7.6.75 for Hawaii; routed Honolulu, Pago Pago, Port Vila, Cairns: 52 hrs 15min flying time ex Van Nuys; Operated with N number for first 6 months based Cairns, with VH-PDI on wings, flew to Sydney 7.75 to collect a Turbomeca turbine for a chopper; last flight as N5645K was Moresby-Cairns 14.12.75 for inspection for Australian CofA CAA gave type certification 1.76, ff after maintenance Cairns 14.2.76 as VH-PDI; Used for regular flight Cairns to PNG & West Irian; after 1977 Helitrans began withdrawing from rotary sphere (from a total of 26 helicopters), and established Bankair with a weeknight courier by VH-PDI to Brisbane, then founded Sunbird Airlines 9.10.78 on the Helitrans licence with PDI as its first aircraft on inaugural scheduled pax service Rockhampton-Gladstone QLD; Australian Register: 11.2.76 VH-PDI: owner George H.Bailey Co Inc, Ft Wayne IN. CofR Holder: Helitrans Australia Pty Ltd, Cairns Qld 21.6.78 VH-PDI: owner Helitrans PNG Pty Ltd, Lae PNG CofR Holder: Helitrans Australia Pty Ltd, Cairns Qld N5645K arrived Mascot 12.7.75 Helitrans; N5645K noted Mascot NSW 17.7.75, 19.7.75; N5645K still on USCR91: Bailey Leasing Corp; VH-PDI arrived Moorabbin 3.9.76 to collect parts from Jayrow Helicopters, based at Cairns with Helitrans Pty Ltd; VH-PDI noted Bankstown 12.9.76 white & red; VH-PDI noted Cairns 12.11.79 red/white scheme"Sunbird Airlines" titles; report: Sunbird Airlines used VH-PDI on passenger scheduled service Rockhampton-Gladstone; VH-PDI noted Bankstown 28.4.80 operator Eagle AW new blue/white scheme "HM" on tail no titles; VH-PDI visited Perth WA 4.5.80; VH-PDI noted Bankstown 26.5.80 Eagle Airways: VH-PDI visited Essendon 6.80 "Eagle Airways" titles with Big Bird cartoon on nose; VH-PDI noted Bankstown 20.4.81 "Eagle Airways" titles, blue & white; (VH-ATX listed as DoT Reserved Regs list 7.88 as H18 forAir-Transit) VH-ATX noted Adelaide 30.12.89 trigear; VH-ATX noted Adelaide SA 8.11.90 Airtransit; VH-ATX noted Archerfield 12.95 stripped; VH-ATX delivered to Redcliffe QLD 4.5.99 to be based here with Antique Airways who also have Beech 17 Staggerwing VH-UXP & Tiger Moth VH-BJE; VH-ATX at airshow Scone NSW 29.9.01; VH-ATX at airshow Port Macquarie NSW 2.11.02 trigear, flying; VH-ATX at airshow RAAF Amberley QLD 2.10.04 "Antique Airways" titles; VH-ATX at airshow Bundaberg QLD 15.7.05 "Antique Airways" trigear, flying; VH-ATX noted Coolangatta 31.7.08, crew training prior to being based for a year at Derby WA; VH-ATX noted Derby WA 12.8.08; reportedly auctioned at Derby in 2010; VH-ATX noted Wollongong-Albion Park NSW 14.7.16, 14.2.20;

BA-705	H18	N5738K	built	.64
			Arkansas Best Freight System, Fort Smith AR	69/70
		N500JH	Vero Aero Inc, Vero Beach FL	71/76
			Bob Bixler, San Jose CA	1.3.76
			sold to Tahiti, struck-off USCR	1.6.76
		F-ODCT	Jacques Brun, Papeete, Tahiti	27.8.76/80
			CofA expired 31.7.78, retired at Papeete, Tahiti	
			Michael Mousseigne, Villepreux, France: reg	25,8,80
			burnt for fire practice Tahiti: struck-off Register	5.10.89
BA-706	H18	N303X	built	.64
	trigear		Brockway Glass Co, Brockway PA	66
		N3033	Lester Welch, Tampa FL	69/70
			Jack Adams Aircraft Sales, Walls MS	71/72
		N729F	L. L. Hyde, Comstock NE	25.1.78/80
			op: Allen County Air	80
			crashed destroyed landing in snowstorm, Olathe KS	15.2.80

N729F noted Scottsdale AZ 26.5.73 trigear; N729F accident report 15.2.80: Allen County Air, cargo flight Olathe to Iola KS, returned to Olathe-Johnson County Executive, due NDB & ILS u/s at destination, ice on airframe, aircraft radio transmitter failed, 3.28pm, pilot k;

BA-707	H18	N611Y	built	.64
			W. H. Gonyea, Springfield OR	66/70
			Woodmont Stables, Upper Montclair NY	71/72
			3D Enterprises, Shreveport LA	78
			Ben G. O. Neal Inc, Grand Cane LA	27.12.78/82
			struck-off USCR	6.12.82

BA-708	H18	N5765K (2	Beech Aircraft Corp, Wichita KS: CofA issued	23.9.64
	trigear	N22T (2	Fort Worth National Bank, Fort Worth TX	66/70
			Fort Worth National Co of Texas, Fort Worth TX	71/72
		N22TL	rereg	
		N22TB	rereg	70
			John B. McDuff, Houston TX	79 4 82
			G. D. Ward, Stephenville TX sale reported: USCR	4.83 91
			Sale reported. USCR	91
	N22TL note	ed San Anton	io TX 16.5.73 trigear;	
BA-709	H18	N888Q	Beech Aircraft Corp, Wichita KS: CofA issued	2.10.64
	trigear		BLC Corp, Boston MA	66/70
			Linden Flight Service, Linden NJ	71/72
		N21U (2	Louisiana Executive Air, Morgan City LA	79
			(noted impounded, Grand Turk 4.81)	4.00
			Lawrence D. Morris, Manchester KY	4.82
			Haiti Water Supply Inc, Miami FL	12.82
			sale reported, Miami FL: USCR	91
	N21U noted	d Houston-Ho	obby TX 6.5.73 trigear;	
BA-710	H18	N5658K	Beech Aircraft Corp, Wichita KS: CofA issed	18.9.64
		N717Z	Lockheed Aircraft Corp, Marietta GA	66/69
			Pine Branch Coal Sales, Lexington KY	70
			Mercury Aircraft Inc, Lexington KY	71/72
			crashed destroyed landing in fog, Charlottsville VA	29.11.71
			Sunstream Aircraft Inc, Chicago IL	30.5.74/94
			struck-off USCR	4.94
BA-711	H18	N926T	built	.64
			Leon Fill, Huntington Woods MI	66/69
	ATE		Normich Laboratories, Detroit MI	70/72
	Westwind I		(rebuilt as ATE Westwind I trigear with PT-6A-60As,	
	trigear		completed 7.70, CofA issued 13.7.70;	
			ATE kit 600, serial #39: mod. plate states Westwind I-6	
	Hamilton		(later converted to Hamilton Westwind III with convention	onal
	Westwind I	11	tailwheel and PT6A-27s by Hamilton)	
	tailgear		Lawrence C. Maxson/ Maxson Aviation, Kotzebue AK	78/79
			gear collapsed landing on short strip, Omilik AK	10.7.79
			Blackhawk Airways, Janesville WI	80
		Duck Massa	op: Pronto Aviation Services, El Paso TX	c81
		BUCK MAXSO	on, Kotzebue AK	3.83
			Methow Aviation, Wenatchee WA & Everett WA	26.2.86/01
			Cascade Air, Ephrata WA	00
			(retired stored Ephrata WA 00, Methow titles)	10.2.96
			damaged in groundloop on takeoff, Seattle WA Jim West/ Skydive Greene County Inc, Xenia OH	10.3.86 10.12.02/13
		N75GJ	Skydive Greene County Inc, Xenia OH	.13/20
		quotes type H	had PT6A-27 turbines, owned Maxson Aviation; 118/T, PT-6A-60As) w Aviation: groundloop on takeoff Seattle-Tacoma Airpol	t, PT6A-27s;
	10.3.86 acc N926T note N926T note Westwind I N926T note N926T note	ed Everett W, ed Ephrata W -600, c/n 39; ed Ephrata W ed Xenia OH	A 24.5.90 Westwind III "Merthow" titles; /A 22.3.00 dumped, "Methow" titles, no engines; reported /A 22.5.01 ex longtime resident of Paine Field; 1.8.05 in hangar at Jim West's farm near airfield, under r	
	10.3.86 acc N926T note N926T note Westwind I N926T note N926T note	ed Everett W, ed Ephrata W -600, c/n 39; ed Ephrata W ed Xenia OH	A 24.5.90 Westwind III "Merthow" titles; /A 22.3.00 dumped, "Methow" titles, no engines; reported /A 22.5.01 ex longtime resident of Paine Field;	
3A-712	10.3.86 acc N926T note N926T note Westwind I N926T note N926T note	ed Everett W, ed Ephrata W -600, c/n 39; ed Ephrata W ed Xenia OH	A 24.5.90 Westwind III "Merthow" titles; /A 22.3.00 dumped, "Methow" titles, no engines; reported /A 22.5.01 ex longtime resident of Paine Field; 1.8.05 in hangar at Jim West's farm near airfield, under r /n 39 date 20.7.70 Hamilton Aircraft, Tucson AZ; built	ebuild to fly, 23.10.64
BA-712	10.3.86 acc N926T note N926T note Westwind I N926T note N926T note plate: West	ed Everett W, ed Ephrata W -600, c/n 39; ed Ephrata W ed Xenia OH twind I-600, c	A 24.5.90 Westwind III "Merthow" titles; /A 22.3.00 dumped, "Methow" titles, no engines; reported /A 22.5.01 ex longtime resident of Paine Field; 1.8.05 in hangar at Jim West's farm near airfield, under r /n 39 date 20.7.70 Hamilton Aircraft, Tucson AZ;	ebuild to fly,

N611Y noted New York-La Guardia NY 8.9.71, 31.3.72;

	Nihon Technology Corp	80
N8475E	Eugene C. Eversole, Honolulu HI	22.7.80
	(US CofA issued 19.5.81)	
	Adrian I. Dalsey, Honolulu HI	23.7.81/86
	op: DHL Cargo, Honolulu HI	81/83
RP-C709	Commuter Air Philippines, Manila	86/91
	Air Charter Philippines, Manila	90
	crashed	
	wreck stored Bacolod, Philippines	90/94
	struck-off Register	20.9.06

JA5506 noted Osaka 27.4.73 & 24.5.73 both MSA (plate BA-712); JA5506 noted Hiroshima 12.2.74; JA5506 noted Hiroshima 25.7.77; JA5506 noted Hiroshima 30.6.80 retired; N8475E noted Honolulu 23.8.81 in service with DHL in DHL orange & white scheme no titles; RP-C709 noted Manila 10.9.86 tailwheel, "Commuter Air Philippines" titles, ex DHL orange And white paint scheme;

RP-C709 wrecked fuselage noted Bacolod 1.91 & 1.94;

BA-713	H18	N8631Q	built	.64		
		N153GP	Georgia Pacific Corp, Portland OR	66/72		
	ATE Westwind I		(rebuilt as American Turbine Engine Co ATE Westwind I:			
			PT6A turbines, trigear completed 68)			
	trigear		FFC Inc	74		
	•		lsd: Mountain Air Cargo, Denver NC	74		
	Hamilton		(rebuilt as Hamilton Westwind III with tail gear,			
	Westwind I	11	by Hamilton Aviation at Tucson AZ)			
	tailgear		Tobey Inc, Simsbury CT	78		
	0		Check-Air, Milwaukee WI	.77/79		
			op: Mountain Air Cargo, Denver NC	80/84		
			Coastal States Aviation, Denver NC	10.86		
			struck-off USCR	14.9.88		
		RP-C934	Metro Manila Airways International, Manila	.88/90		
			(delivered via Keflavik-Glasgow 25.7.88)			
			Territory Airlines, Goroka PNG/ Metroair	.90		
			retired Manila .90, stripped airframe sold	.92		
			struck-off Register	.92		
			Charles R. Miller/ CM Aero, Manila: for parts	93/97		
	N153GP photo in "Janes" as type Westwind III;					
	N153GP noted Milwaukee WI 11.3.77 Westwind III tailwheel, "Check Air" titles;					
	N153GP noted Indianapolis IN 7.9.84 freighter, callsign "Mountain Air 14";					
			kee WI 1.9.78 Check Air;			
			berdeen-Glasgow 25.7.8 Manila Airways titles;			
			88: Westwind III "Manila Airways" titles, long nose, tailwhe	el <sup>.</sup>		
			vays International purchased by TAL, PNG .90 to acquire cl			

Note: Metro Manila Airways International purchased by TAL, PNG .90 to acquire charter licence and hangar facilities at Manila and renamed Metroair, Westwinds replaced by TAL Twin Otters; Metroair closed down 2.92 by TAL: turbines and propellers of the 2 Westwinds removed and sent to PNG for resale, airframes offered for sale: appears both went to Chuck Miller for parts; RP-C934 noted Manila 2.1.94;

Parmerter quotes Georgia Pacific Chief Pilot Bob Carter as stating that N153GP was rereg N153LP for a period in 1973 with the affiliated company Louisiana Pacific.

BA-714	H18	N7996K	built	.64
	trigear	N571DU	rereg	
		N571DD	Atlantic Aviation Corp, Wilmington DE	66
			E. I. DuPont de Nemours & Co, Wilmington DE	69/70
			Uni-Lease Inc, Allenhurst NJ	71/72
			R. D. Goodner, Duncan OK	75/79
			Cannavo Aviation, Claymont DE	11.83
			Mid-South Aircraft Sales, Memphis TN	7.87
			Cape Central Airways, Cape Girardeau MO	8.3.88/94
			struck-off USCR	17.3.94

BA-715	H18	N5758K N572D	built Atlantic Aviation Corp, Wilmington DE	.64 66		
		110120	E. I. DuPont de Nemours & Co, Wilmington DE	69		
			National Financing Inc, Wilmington DE	70/72		
		N500MM	Misener Marine Construction Inc, St Petersburg FL	24.6.74		
			crashed destroyed by fire, St Augustine FL	31.12.74		
BA-716	H18	N140Q	built	.64		
	trigear		Thomas J. Watson, Stowe VT	66		
			Exel Corp, Elkhart IN	69/72		
		N140QC	rereg			
		N23LT	Niles Machine & Welding Co, Niles OH	79		
			Eighty Five Delta Inc, Nennah WI	4.83		
			Basler Flight Service, Oshkosh WI	1.85/89		
		N911BF	Basler Flight Service, Oshkosh WI	1.89/94		
			Basler Turbo Conversions Inc, Oshkosh WI	15.3.94/96		
			Welch Aviation, Alpena MI	22.1.96		
			DJW Inc, Wooster OH	7.96/97		
		N223JW	DJW Inc, Wooster OH	4.97/99		
			Jerome Airport, Pittsburgh-Allegheny County PA	15.9.99/05		
			Michael E. Rindler, Southwest Harbour ME Richard L. Standage, Moorpark CA	26.6.06/08 12.5.10/11		
			Sold to new owner, Trier, Germany	12.5.10/11 11/15		
			Aircraft Guaranty Corp Trustee: USCR: based Germany	4.6.11/13		
			stbd main gear retracted landing, ran off runway,	<del>-1</del> .0.11/13		
			Trier-Fohren, Germany	21.10.12		
			exported to Germany, struck-off USCR	15.5.13		
	exponed to Germany, struck-on USCR 15.5.15					
	N223JW N223JW N223JW	at fly-in Oshko noted Pittsbur at fly-in Oshko	sh WI 27.7.89 "Basler" trigear, plate BA-716; osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear;	rport,		
DA 747	N223JW N223JW N223JW N223JW	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-ir	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear; n Tullahoma TN 14.10.07 blue & white, trigear;			
BA-717	N223JW N223JW N223JW	at fly-in Oshko noted Pittsbur at fly-in Oshko	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear;	25.11.64 66/69		
BA-717	N223JW N223JW N223JW N223JW	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-ir	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear; o Tullahoma TN 14.10.07 blue & white, trigear; Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg	25.11.64		
BA-717	N223JW N223JW N223JW N223JW	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-ir N7950K CF-YRC	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear; o Tullahoma TN 14.10.07 blue & white, trigear; Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN	25.11.64 66/69 .70 72/85		
BA-717	N223JW N223JW N223JW N223JW	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-ir N7950K	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear; o Tullahoma TN 14.10.07 blue & white, trigear; Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY	25.11.64 66/69 .70 72/85 1.5.85		
BA-717	N223JW N223JW N223JW N223JW	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-ir N7950K CF-YRC	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear; o Tullahoma TN 14.10.07 blue & white, trigear; Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA	25.11.64 66/69 .70 72/85 1.5.85 4.90/96		
BA-717	N223JW N223JW N223JW N223JW	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-ir N7950K CF-YRC	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear; o Tullahoma TN 14.10.07 blue & white, trigear; Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02		
BA-717	N223JW N223JW N223JW N223JW	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-ir N7950K CF-YRC	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear; o Tullahoma TN 14.10.07 blue & white, trigear; Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY William Chase, Waukee IA	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07		
BA-717	N223JW N223JW N223JW N223JW	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-ir N7950K CF-YRC	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear; o Tullahoma TN 14.10.07 blue & white, trigear; Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07		
BA-717	N223JW N223JW N223JW N223JW H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM	<ul> <li>bsh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; bsh 27.7.03 "Latitude Adjustment", trigear;</li> <li>b Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY</li> <li>Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY</li> <li>William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK crashed destroyed landing, Great Bend KS</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07		
BA-717	N223JW N223JW N223JW N223JW H18 H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM N45GM	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear; o Tullahoma TN 14.10.07 blue & white, trigear; Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK crashed destroyed landing, Great Bend KS	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07		
BA-717	N223JW N223JW N223JW N223JW H18 H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM N45GM	osh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; osh 27.7.03 "Latitude Adjustment", trigear; o Tullahoma TN 14.10.07 blue & white, trigear; Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK crashed destroyed landing, Great Bend KS	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07		
BA-717	N223JW N223JW N223JW N223JW H18 N45GM r N45GM r accident	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM N45GM	<ul> <li>bsh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716;</li> <li>bsh 27.7.03 "Latitude Adjustment", trigear;</li> <li>b Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY</li> <li>Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY</li> <li>William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67; A 9.5.03 trigear no titles; op Bygone Aviation LLC, freight flight from Wichita to Great</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07		
	N223JW N223JW N223JW H18 H18 N45GM r accident during ILS H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM noted Gillette W noted Ankeky f report 9.2.07:	Airport, Allegheny County Airport, Allegheny County Airport, Allegheny County Airport, large nose art "Latitude Adjustment" plate BA-716; and 27.7.03 "Latitude Adjustment", trigear; a Tullahoma TN 14.10.07 blue & white, trigear; Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK crashed destroyed landing, Great Bend KS WY 3.8.00 trigear, plate BA-717 built 11.67; A 9.5.03 trigear no titles; op Bygone Aviation LLC, freight flight from Wichita to Great her; Beech Aircraft Corp, Wichita KS: CofA issued	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 # Bend, crashed		
	N223JW N223JW N223JW N223JW H18 H18 N45GM r At5GM r accident during ILS	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-ir N7950K CF-YRC N45GM N45GM noted Ankeky f report 9.2.07: S in poor weat	<ul> <li>bsh 30.7.00 trigear owned Jay Airport, Allegheny County Airgh, large nose art "Latitude Adjustment" plate BA-716;</li> <li>bsh 27.7.03 "Latitude Adjustment", trigear;</li> <li>a Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued</li> <li>Richardson Homes Corp, Elkhart IN</li> <li>reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN</li> <li>Green Management Corp, Gillette WY</li> <li>Beryl J. Jarvis, Brentwood CA</li> <li>Gerald D. Green, Gillette WY</li> <li>William Chase, Waukee IA</li> <li>op: Bygone Aviation LLC, Guymon OK</li> <li>crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67;</li> <li>A 9.5.03 trigear no titles;</li> <li>op Bygone Aviation LLC, freight flight from Wichita to Great her;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued</li> <li>Noble Drilling Corp, Tulsa OK</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 t Bend, crashed		
	N223JW N223JW N223JW H18 H18 N45GM r accident during ILS H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM noted Gillette V noted Ankeky f report 9.2.07: S in poor weat	<ul> <li>bsh 30.7.00 trigear owned Jay Airport, Allegheny County Airgh, large nose art "Latitude Adjustment" plate BA-716;</li> <li>bsh 27.7.03 "Latitude Adjustment", trigear;</li> <li>a Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued</li> <li>Richardson Homes Corp, Elkhart IN</li> <li>reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN</li> <li>Green Management Corp, Gillette WY</li> <li>Beryl J. Jarvis, Brentwood CA</li> <li>Gerald D. Green, Gillette WY</li> <li>William Chase, Waukee IA</li> <li>op: Bygone Aviation LLC, Guymon OK</li> <li>crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67;</li> <li>A 9.5.03 trigear no titles;</li> <li>op Bygone Aviation LLC, freight flight from Wichita to Great her;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued</li> <li>Noble Drilling Corp, Tulsa OK</li> <li>Oklahoma State University, Stillwater OK</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 t Bend, crashed 9.11.64 66/72 79/82		
	N223JW N223JW N223JW H18 H18 N45GM r accident during ILS H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-ir N7950K CF-YRC N45GM N45GM noted Ankeky f report 9.2.07: S in poor weat	<ul> <li>bsh 30.7.00 trigear owned Jay Airport, Allegheny County Airgh, large nose art "Latitude Adjustment" plate BA-716;</li> <li>bsh 27.7.03 "Latitude Adjustment", trigear;</li> <li>a Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued</li> <li>Richardson Homes Corp, Elkhart IN</li> <li>reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN</li> <li>Green Management Corp, Gillette WY</li> <li>Beryl J. Jarvis, Brentwood CA</li> <li>Gerald D. Green, Gillette WY</li> <li>William Chase, Waukee IA</li> <li>op: Bygone Aviation LLC, Guymon OK</li> <li>crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67;</li> <li>A 9.5.03 trigear no titles;</li> <li>op Bygone Aviation LLC, freight flight from Wichita to Great her;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued</li> <li>Noble Drilling Corp, Tulsa OK</li> <li>Oklahoma State University, Stillwater OK</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 t Bend, crashed 9.11.64 66/72 79/82 11.82/91		
	N223JW N223JW N223JW H18 H18 N45GM r accident during ILS H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM noted Gillette V noted Ankeky f report 9.2.07: S in poor weat N8668Q N430SU	<ul> <li>bsh 30.7.00 trigear owned Jay Airport, Allegheny County Airgh, large nose art "Latitude Adjustment" plate BA-716;</li> <li>bsh 27.7.03 "Latitude Adjustment", trigear;</li> <li>a Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY</li> <li>Beryl J. Jarvis, Brentwood CA</li> <li>Gerald D. Green, Gillette WY</li> <li>William Chase, Waukee IA</li> <li>op: Bygone Aviation LLC, Guymon OK</li> <li>crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67;</li> <li>A 9.5.03 trigear no titles;</li> <li>op Bygone Aviation LLC, freight flight from Wichita to Great her;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Noble Drilling Corp, Tulsa OK</li> <li>Oklahoma State University, Stillwater OK</li> <li>Oklahoma State University, Stillwater OK</li> <li>Ted Neal/ California Coast University, Prescott AZ</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 t Bend, crashed 9.11.64 66/72 79/82 11.82/91 21.7.94/94		
	N223JW N223JW N223JW H18 H18 N45GM r accident during ILS H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM noted Gillette V noted Ankeky f report 9.2.07: S in poor weat	<ul> <li>bsh 30.7.00 trigear owned Jay Airport, Allegheny County Airgh, large nose art "Latitude Adjustment" plate BA-716;</li> <li>bsh 27.7.03 "Latitude Adjustment", trigear;</li> <li>a Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY</li> <li>Beryl J. Jarvis, Brentwood CA</li> <li>Gerald D. Green, Gillette WY</li> <li>William Chase, Waukee IA</li> <li>op: Bygone Aviation LLC, Guymon OK</li> <li>crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67;</li> <li>A 9.5.03 trigear no titles;</li> <li>op Bygone Aviation LLC, freight flight from Wichita to Great her;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Noble Drilling Corp, Tulsa OK</li> <li>Oklahoma State University, Stillwater OK</li> <li>Oklahoma State University, Stillwater OK</li> <li>Ted Neal/ California Coast University, Prescott AZ</li> <li>California Coast University, Prescott AZ</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 <i>Bend, crashed</i> 9.11.64 66/72 79/82 11.82/91 21.7.94/94 18.8.94/99		
	N223JW N223JW N223JW H18 H18 N45GM r accident during ILS H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM noted Gillette V noted Ankeky f report 9.2.07: S in poor weat N8668Q N430SU	<ul> <li>bsh 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; bsh 27.7.03 "Latitude Adjustment", trigear; n Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67; A 9.5.03 trigear no titles; op Bygone Aviation LLC, freight flight from Wichita to Great her;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Noble Drilling Corp, Tulsa OK Oklahoma State University, Stillwater OK Ted Neal/ California Coast University, Prescott AZ California Coast University, Prescott AZ Lace Air Inc, Dover DE</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 t Bend, crashed 9.11.64 66/72 79/82 11.82/91 21.7.94/94 18.8.94/99 22.12.99/01		
	N223JW N223JW N223JW H18 H18 N45GM r accident during ILS H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM noted Gillette V noted Ankeky f report 9.2.07: S in poor weat N8668Q N430SU	<ul> <li>bsh 30.7.00 trigear owned Jay Airport, Allegheny County Airgh, large nose art "Latitude Adjustment" plate BA-716;</li> <li>bsh 27.7.03 "Latitude Adjustment", trigear;</li> <li>a Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67; A 9.5.03 trigear no titles; op Bygone Aviation LLC, freight flight from Wichita to Great her;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Noble Drilling Corp, Tulsa OK Oklahoma State University, Stillwater OK Oklahoma State University, Stillwater OK Ted Neal/ California Coast University, Prescott AZ California Coast University, Prescott AZ Lace Air Inc, Dover DE California Coast University, Santa Ana CA</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 t Bend, crashed 9.11.64 66/72 79/82 11.82/91 21.7.94/94 18.8.94/99 22.12.99/01 20.2.01/07		
	N223JW N223JW N223JW H18 H18 N45GM r accident during ILS H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM noted Gillette V noted Ankeky f report 9.2.07: S in poor weat N8668Q N430SU	<ul> <li>bish 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; bish 27.7.03 "Latitude Adjustment", trigear; a Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67; A 9.5.03 trigear no titles; op Bygone Aviation LLC, freight flight from Wichita to Great her;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Noble Drilling Corp, Tulsa OK Oklahoma State University, Stillwater OK Oklahoma State University, Stillwater OK Ted Neal/ California Coast University, Prescott AZ California Coast University, Prescott AZ Lace Air Inc, Dover DE California Coast University, Santa Ana CA Mercy Airlift Inc, Palm Springs CA</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 t Bend, crashed 9.11.64 66/72 79/82 11.82/91 21.7.94/94 18.8.94/99 22.12.99/01 20.2.01/07 16.7.08/12		
	N223JW N223JW N223JW H18 H18 N45GM r accident during ILS H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM noted Gillette V noted Ankeky f report 9.2.07: S in poor weat N8668Q N430SU	<ul> <li>bish 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; bish 27.7.03 "Latitude Adjustment", trigear; or Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67; A 9.5.03 trigear no titles; op Bygone Aviation LLC, freight flight from Wichita to Great her;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Noble Drilling Corp, Tulsa OK Oklahoma State University, Stillwater OK Oklahoma State University, Stillwater OK Ted Neal/ California Coast University, Prescott AZ California Coast University, Santa Ana CA Mercy Airlift Inc, Palm Springs CA B-25 Mitchell Inc, Tulsa OK</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 t Bend, crashed 9.11.64 66/72 79/82 11.82/91 21.7.94/94 18.8.94/99 22.12.99/01 20.2.01/07 16.7.08/12 7.6.12/18		
BA-717 BA-718 •	N223JW N223JW N223JW H18 H18 N45GM r accident during ILS H18	at fly-in Oshko noted Pittsbur at fly-in Oshko at Beech fly-in N7950K CF-YRC N45GM noted Gillette V noted Ankeky f report 9.2.07: S in poor weat N8668Q N430SU	<ul> <li>bish 30.7.00 trigear owned Jay Airport, Allegheny County Air gh, large nose art "Latitude Adjustment" plate BA-716; bish 27.7.03 "Latitude Adjustment", trigear; a Tullahoma TN 14.10.07 blue &amp; white, trigear;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Richardson Homes Corp, Elkhart IN reg</li> <li>Sherritt-Gordon Air Transport Ltd, Lynn Lake MAN Green Management Corp, Gillette WY Beryl J. Jarvis, Brentwood CA Gerald D. Green, Gillette WY William Chase, Waukee IA op: Bygone Aviation LLC, Guymon OK crashed destroyed landing, Great Bend KS</li> <li>WY 3.8.00 trigear, plate BA-717 built 11.67; A 9.5.03 trigear no titles; op Bygone Aviation LLC, freight flight from Wichita to Great her;</li> <li>Beech Aircraft Corp, Wichita KS: CofA issued Noble Drilling Corp, Tulsa OK Oklahoma State University, Stillwater OK Oklahoma State University, Stillwater OK Ted Neal/ California Coast University, Prescott AZ California Coast University, Prescott AZ Lace Air Inc, Dover DE California Coast University, Santa Ana CA Mercy Airlift Inc, Palm Springs CA</li> </ul>	25.11.64 66/69 .70 72/85 1.5.85 4.90/96 3.4.96/02 8.10.03/07 06/07 9.2.07 t Bend, crashed 9.11.64 66/72 79/82 11.82/91 21.7.94/94 18.8.94/99 22.12.99/01 20.2.01/07 16.7.08/12		

N571DC noted Long Beach CA 6.8.71: reg not listed by Parmerter; N571DD noted Harlingen TX 11.75, trigear; N8668Q noted Tulsa OK 30.9.71 trigear; N700TN nored Breighton, Yorkshire 29.6.19, orange & white, trigear;

BA-719	H18	N5666K	Beech Aircraft Corp, Wichita KS: CofA issued	12.11.64			
	trigear	N7377	United Airmotive Distributors Inc, Wichita KS Certified Check & Title Corp, Wilkesboro NC	66 70/72			
		N7377 N7377M	rereg	10/12			
		N105AF	Airlie Foundation, Warrenton VA	79			
			Doak V. Boreing, Hot Springs AR	10.87/95			
			Pro Turbine Inc, Hot Springs AR	8.97			
			C-Tiger Enterprises Ltd, Wilmington DE	18.11.97/07			
			op: GB Airlink, Fort Lauderdale FL	02/05			
			struck-off USCR as scrapped	23.1.07			
			TX 10.87 trigear; erdale FL 12.1.98, 9.12.98 trigear;				
			erdale-Executive FL 28.6.02 "GB Airlink" titles, trigear, in s	ervice:			
			erdale FL 4.4.01;	,			
			erdale FL 5.03 "GB AirLink" titles, trigear in service;				
			erdale FL 12.1.05 "GB Air Link" titles, trigear				
	N105AF r	noted Ft Laude	erdale FL 11.8.05 GB Airlink, in service;				
BA-720	H18	N5850S	Beech Aircraft Corp, Wichita KS: CofA issued	7.1.65			
			Krause Milling Co, Millwaukee WI	66/78			
		()	Clifford A. Marlatt/ Sky Castle Aviation, New Castle IN	78/80			
		(N585SC)	ntu: Sky Castle Aviation	3.79			
		N5850S	David Kent Dill, Indianapolis IN	4.82			
			Kelley Cars Inc, Fort Wayne IN Ronald W. Smith, Fort Lauderdale FL	10.83 12.12.85/87			
			crashed destroyed, Rockford IL	12.12.85/87 22.9.87			
			Gasheu ueshoyeu, Rouniolu IL	22.3.01			
BA-721	H-18	N404X (2	Beech Aircraft Corp, Wichita KS: CofA issued	17.2.65			
	trigear		Brockway Glass Co, Brockway PA	11.65/66			
		N4043	rereg				
		N595AF	Albany Felt Company	ad			
			dam. landing Bromont QUE Canada, slid off snow cover runway into snow drift, nose gear torn off	red 17.12.68			
			Page Airways, Rochester NY	69			
		N5959F	Page Airways, Rochester NY	70			
		1400001	Graham Manufacturing Co, Batavia NY	71/99			
			(business flights to UK & Europe 6.75 & 6.77)	1.100			
			Sterling A. May, Dallas TX	24.5.99/02			
			C. & L. Kelley Inc, Fort Myers FL	29.5.03/16			
			Mid Atlantic Air Museum, Reading PA	16.3.16/20			
	further de	tail European	visits: Parmerter p.310;				
	N5959F noted Staverton UK 19.6.77,						
	N5959F noted Manchester 23.6.77 "Volpar";						
	N5959F departed Hurn for Faroe Isles 14.6.75;						
	N5959F noted Prestwick 24.6.77 Graham Manufacturing Co;						
	N5959F won award at Reading PA airshow 78: Graham Manufacturing Co;						
	N5959F noted Toronto ONT 3.4.82 Graham Manufacturing Co NY (no titles); N5959F at Tullahoma TN Beech fiv-in 10 10 90:						
	N5959F at Tullahoma TN Beech fly-in 10.10.90; N5959F at Tullahoma TN Beech fly-in 16.10.94;						
	N5959F at Tullahoma TN Beech fly-in 16.10.94; N5959F at Tullahoma TN Beech fly-in 13.10.95;						
	N5959F at Vichita KS Beech fly-in 11.10.97;						
	N5959F at Beech fly-in Tullahoma TN 14.10.07;						
			ed Ft Myers FL, TT 9630 hrs;				
BA-722	H18	N909T	built	.65			
	1110	110001	Texize Chemical Inc, Greenville SC	66			
			crashed destroyed by fire, landing Norwich NY	12.1.68			
DA 700	LI10	NEGEOG	built	66			
BA-723	H18	N5860S N46A (2	built rereg	.65 .65			

		N711 (4 N711LC	Margaretta Carpenter, Wilmington DE rereg W. F. Larson Inc, Plainview TX Flite Service Inc, Pine Mountain GA emergency landing due right engine fire, wing extensive fire damage, Sandersville GA struck-off USCR	66/72 9.4.73 79 18.5.85/94 8.10.87 19.7.94
BA-724	H18 trigear	N835K	Kellogg Co, Battle Creek MI: CofA issued Georgia Iron Works, Grovetown GA Mid South Aircraft Sales, Memphis TN Thomas G. Todd, Tavernia FL Steve Hopkins Golf Capital Corp, Miami FL Eureka Operating Company, Odessa TX crashed destroyed, near Tatum NM	19.4.65/66 69/79 7.81 8.81/95 97 27.5.98/99 6.3.99/02 1.7.02
	N835K no Advertised crash repo	ted Tamiami I d for sale 4.97 ort 1.7.02: owi	ad Island SC 3.9.77; FL 1.5.95 trigear; ' Steve Hopkins: factory trigear, only 3 owners since new; ned by private individual, commercial pilot only occupant, o hours later near a farm at Tatum NM, destroyed;	departed Taos NM
BA-725	N38BW n N38BW n Panorama N38BW n N38BW n N38BW n N38BW n N38BW n	oted Kauai HI oted Honolulu a Air fleet list a oted Honolulu oted Kahului H oted Honolulu oted Honolulu oted Ft Laude	Diesel Engine Sales Inc, St. Augustine FL: CofA issued Ring Power Corp, Jacksonville FL Cone Bros Contracting Co, Tampa FL Air North, Burlington VT Chicago & Southern Airlines, Chicago IL Sam Vires/ Mid-South Aircraft Sales, Memphis TN Panorama Air Tour, Honolulu HI (fleet #66) Airtour Acquisition Corp, Honolulu HI Lani Bird Inc, Honolulu HI Waikiki Circle Tour & Travel, Honolulu HI Tomy International Inc, Honolulu HI Matthew R. Barnett, Honolulu HI Raymond Hinely, Greensboro GA Larry Joe Pruden, Louise MS 5.10.80 Panorama AT #66; 27.8.81 "Panorama Air Tour" #66 brown scheme, trigear; 9.83 "Panorama Air fleet #66, trigear; Is at 15.11.83: BA-725 tt 11,798 hrs, fleet #66; 29.10.85 Lani Bird; HI 2.88 "Scenic Air Tours" titles, allover yellow; 7.89 "Scenic Air Tours", fleet #28; trigear, flying; 12.93, 23.11.94: "Scenic Air Tours": fleet #28, green, trige rdale FL 9.12.98, trigear, op Carib Air Cargo; rdale FL 4.4.01 trigear;	19.4.65/66 69 70 71/72 71 79 79/85 82 6.85 7.85 3.91/95 31.8.95/96 24.4.96/06 18.5.09/20
BA-726	N177X no N516CE r N516CE r	noted Rock Co	rereg Henson Aviation, Hagerstown MD DelMar Mullens, Hayward CA Complete Equity Markets Inc, Wheeling IL Complete Equity Markets Inc, Wheeling IL Carrier Executive Motors Inc, Wheeling IL Great Planes Inc, Lawrence KS David B. Fields, Midland TX CA 25.7.81,	

N516CE noted Janesville-Rock County WI 7.8.97, 2.8.98, 26.7.99, based here, trigear; N516CE noted Janesville-Rock County WI 10.9.02 hangared here, departed for Atlanta;

N516CE noted Janesville WI 23.7.03 trigear; N777XJ at Beech fly-in Tullahoma TN 18.10.14;

BA-727 •	H18	N7927K	built	.65
	trigear		Michigan Aeronautics Commission, Lansing MI	66
		N6000M (2	Michigan Aeronautics Commission, Lansing MI (flew Michigan Governor, George Romney)	69/99
			minor damage hit snowbank landing, Grayling MI	12.3.75
		N6000M	Cody Welch/ CF & S Company Inc, Linden MI:	
			restored to USCR	4.8.99/01
			KEL LLC, Ogallala NE	17.1.02/05
			Time Bandits LLC, Henderson NV	18.4.06/13
			Aircraft Guaranty Corp, TX: trustee: USCR (N6000M del via Goose Bay LAB to Narsaruaq 11.5.13 via Reykjavik, Iceland 13.5.13)	29.3.13/20 ,
	N6000M N6000M N6000M	at fly-in Oshko: at fly-in Oshko: at fly-in Oshko:	t 12.3.75: flight Marquette Mi to Grayling, 3.15pm, 6 unhu sh 30.7.00 trigear, plate BA-727, owned Cody Welch/CFo sh 26.6.01 trigear; sh 23.7.02 trigear, plate BA-727 PSI Digital NE; n-Vreden Germany 17.9.14, trigear	
BA-728	H18	JA5133	built	4.65
-	-		sold to USA, struck-off Register	27.9.76
		N92756	reg	9.76
			(US CofA issued 11.5.77)	
			M & M Air Service, Huntsville AL	79/94
			Jim Hankins Air Service, Jackson MS	13.9.94/17
			damaged on ground by windstorm, Columbus GA (under rebuild by Hankins at Jackson MS 8.02)	c01
			Dakota Express LLC, Wilmington DE	14.11.17/20
	N92756: N92756 r Columbus	Jim Hankins Ai noted Jackson i s GA, plate BA	MS 11.8.98, Hankins Air Service; ir Service fleet Status Report 10.8.98: TT 8823 hrs; MS 1.8.02 under rebuild for Hankins A/S after windstorm -728 spar kit 1509 s/n 195 22.4.75; MS 5.8.08 Jim Hankins AS;	damage at
BA-729	H18	N402A	Beech Aircraft Corp, Wichita KS: CofA issued	14.7.65
-	trigear	N402AP	Atlas Plastics Corp, Cape Girardeau MI	.65/69
	-		Computer & Business Management, Cleveland OH	71/72
		N22BR	Two Bar Ranch, Wheatland WY	79
			James E. Swann, Greenwood MO	9.82
			Jerry L. Englund/ Englund Air Inc, Mobile AL	2.88
			James E. Swann, Independence MO	1.89
			Englund Air Inc, St Elmo AL	1.90
			Jim Hankins Air Service, Jackson MS	15.11.90/17
			Dakota Express LLC, Wilmington DE	14.11.17/20
	8.02 repo N22BR n	ort: N22BR still oted Jackson-F	r Service fleet Status Report 10.8.98: TT 9262 hrs; in service with Hankins; Hawkins Field MS 5.8.03 trigear, plate BA-729, JHAS; Hawkins Field MS 16.8.05, 5.8.08 trigear;	
BA-730	H18	N630TL	Time Life Inc, New York NY: CofA issued	2.8.65/70
	trigear	N684HA	Tecumseh Aircraft Leasing, Dover DE	71/72
	-	N97BC	McBride & Shoff, Metamora IL	79
			Richard J. Jones, Detroit MI	2.8.79/91
	10700			
	N97BC n	oted Detroit-Do	owntown MI 9.80 trigear;	

BA-731							
	H18	JA5507	reg Maritime Safety Agency, Sendai	1.9.65 70/81			
		N60004	retired	30.6.81			
		N69094	Fora Sorenson, Pensacola FL op: Circle Rainbow Air Inc, Honolulu HI	11.8.81 83			
			Hutchinson Auto & Air Transport, Honolulu HI	1.84			
			Circle Rainbow Air Inc, Honolulu HI	12.86			
			struck-off USCR	21.10.88			
		RP-C1104		.89/91			
			ditched in river Cagayan de Oro	11.7.92			
			badly damaged during salvage, wreck dumped Cebu by	1.94			
	JA5507 n	oted Chofu, Ja	anan 13 8 72 <sup>.</sup>				
		oted Sendai 2					
		eported in Jap					
			9.83 trigear, "Circle Rainbow Air" "Mieko";				
	RP-C1104	4 wreckage no	oted Cebu-Lahug 1.94;				
BA-732	H18	JA5150	Maritime Safety Agency, Niigata	10.65/82			
	.IA5150 n	oted Chofu 5.8	5.81 no titles:				
			an 25.4.82 Kyoritsu Koku;				
		-	-				
BA-733	H18	N204CS	built	.65			
			Southern Airways, Atlanta GA	66			
		N204CC	Colonial Stores Inc, Jacksonville FL	69 70			
		N204CC	Central Trust Leasing Corp, Cleveland OH Larry Johnson, McAllen TX	16.2.78			
			crashed destroyed after takeoff, Brownsville TX	20.11.78			
			·····, ······				
			t 20.11.78: Larry Johnson, cargo flight Brownsville to Sprin wreck 3 miles from airport, pilot k;	gfield MO, took off			
BA-734	H18	PK-BIA	Indonesian Aviation Corp/Indoavia, Jakarta	2.11.65/66			
	trigear	P.2022	sold to Indonesian Police	21.11.66 11.66/92			
		F.2022	Indonesian Air & Water Police/ Angk.Kepolisian	11.00/92			
			either BA-734 or BA-737, definitely not BA-743;				
			ng 31.3.69 "Polisi";				
			ng 2.70 "Polisi";				
		oted Singapore oted Jakarta-K	emajoran 13.10.73;				
			Cabe, Indonesia (based there) 92 in service "Polisi Udara" t	titles;			
			· · ·				
BA-735	H18 triacon	PK-BIB	Indonesian Aviation Corp/ Indoavia, Jakarta	1.11.65/00			
	trigear		damaged in accident Kaimana (repaired)	7.5.75 c07			
			derelict in hangar with PK-BIE, scrapped struck-off Register	20.7.18			
				_00			
	PK-BIB noted Singapore-Seletar 13.3.72,						
	PK-BIB noted Singapore-Seletar 3.5.72 trigear no titles;						
	PK-BIB noted Jakarta-Halim 11.95, in service "Indoavia" titles ,"Bomberai" on nose, trigear; Photo PK-BIB & BIE both Indoavia paint scheme, derelict in hangar c2005, parts cut off;						
	FIIOLO PK	סום א סום-	ui indoavia panti scherne, derenci in nangar c2005, paπs c	ut OII,			
	H18	PK-BIC	Indonesian Aviation Corp/ Indoavia, Jakarta	11.65/82			
BA-736	trigear	•	crashed Sintang	11.11.79			
BA-736			-				
BA-736	PK-BIC no	oted Singapor	e-Seletar 8.5.72 trigear, no titles;				
BA-736			Indonesian Aviation Corp/ Indoavia, Jakarta	2.12.65			
BA-736 BA-737	H18	PK-BID					
	H18 trigear	PK-BID	(to Indonesian Police as)	21.11.66			
	trigear		(to Indonesian Police as)	21.11.66			
	trigear	Рк-від Polisi P.2022:	(to Indonesian Police as)	21.11.66			
	trigear		(to Indonesian Police as)	21.11.66			

PK-BIE noted Singapore-Seletar 9.5.72; PK-BIE noted Jakarta-Kemajoran 6.74; Photo PK-BIB & BIE both Indoavia paint scheme, derelict in hangar c2005, parts cut off;

BA-739	H18	PP-FMV	built	.66
	trigear	PT-FMV	Sudene-Superit do des do Nordeste, Recife	83
		PT-LPO	Base Aerofotogrametria SA	14.7.88

PT-FMV noted Recife-Encanta Moca 19.7.81 trigear, "Sudene" titles, named "Asa Branca 1";

BA-740	H18	N908T	Beech Aircraft Corp, Wichita KS: CofA issued	30.1.66
	trigear		W. C. Ruffin, Gainesville FL	69/70
	•		probably: Continental Air Services, Laos	75
			(open storage Bangkok-Don Muang 75 with	
			Vietnam evacuee aircraft)	
		N700CC (2	rereg	
		N701CC	rereg	5.78
			Nuggett Oil Inc, Crestview FL	79
			Moonlight Express Corp, Flushing NY	5.3.80
			crashed destroyed near Troxelville PA	18.11.80

N701CC accident report 18.11.80: Moonlight Express, flight New York to Pittsburgh PA, uncontrolled descent, airframe ice, deicing equipment u/s, dest. 1.53am, pilot k;

BA-741	H18	N2095W	Beech Aircraft Corp, Wichita KS: CofA issued	14.2.66	
			Bowman Transport Inc, East Gadsden AL	69	
			Edward P. Mayer, St Louis MO	70	
		N1LH	Malcolm Jacobs Aviation, Chesterfield MO	71/72	
			Gifford Aviation, Anchorage AK	77/79	
			hard landing, gear collapsed, Noatak AK	31.5.77	
			sale reported, Anchorage-Merrill Field AK	4.81/91	

N1LH accident report 31.5.77: Gifford Aviation Inc, cargo flight Anchorage to Noatak, runway slopes upward, 2 crew unhurt;

BA-742 H18 trigea	H18	N5900S	built	.66
	trigear		Granite Construction Co, Watsonville CA	69/70
	·	N1900G	Granite Construction Co, Watsonville CA ditched into Pacific Ocean on delivery flight, Hilo HI to	71/72
			Papeete, Tahiti	11.2.76
		(F-ODBV)	ntu: M. Brun, Papeete, Tahiti	2.76

N1900G noted Watsonville CA 23.4.72 trigear; N1900G accident report 11.2.76: ferry flight, one engine feathered, unable to maintain altitude, not located, 1 crew missing;

BA-743	H18	N5436U	Floair Inc, Wichita Municiple Airport KS	4.67			
	trigear		Indonesian Army/TNI-AD as A-8037	5.67/82			
			Indonesia Timur				
			(del. to Indonesia via Oakland CA 14.5.67)				
	A-8037 del. via Oakland CA 14.5.67 in full Angkatan Darat scheme & titles with N5436U on sticker on fuselagesides;						
	A-8037 noted Port Moresby PNG 9.11.68 "Angkatan Darat", named "Indonesia Timur 1", bringing Army military commander for West Irian;						
	Arriy millary commander for west mail, A-8037 noted Hong Kong-Kai Tak 31.3.69 Angkatan Darat;						
	A-8037 noted Singapore-Seletar 22.9.72 "Angkatan Darat" under maintenance;						
			30.11.75 TNI-AD;				
BA-744	H18	JA5136	Japan Airlines, Tokyo	4.5.67/74			
	trigear		sold abroad, struck-off Japanese Register	17.4.74			

		(VH-CKQ)	ntu: Trans West Air Charter, Perth WA	4.74		
			(purchase cancelled due Australian certification probler			
		N35AP	Harmor Inc, Newport Beach CA	4.74/79		
			(US CofA issued 24.10.74)			
			op: Brandt Air, Honolulu HI (fleet #7)	76/79		
			op: Alii Hawaii Air, Honolulu HI	78		
			groundloop landing, gear collapsed, Molokai HI	19.5.78		
			retired Honolulu, open storage	79		
			struck-off USCR	6.81		
			Robert S. Whittinghill, Honolulu HI: restored to USCR	24.10.84/93		
			op: Lani Bird, Honolulu HI	84		
		RP-C1159	Pacific Airways Corp, Manila retired derelict Cebu-Mactan AB	5.93 06		
				00		
	JA5136 no	oted Tokyo-Ch	nofu 20.5.74 JAL;			
			I 4.12.76 trigear "Brandt" above windows, "B" on tail fins,	•		
	N35AP ac	cident report	19.5.78: Alii Hawaii Air, flight from Honolulu 5pm, 10 unh	urt;		
	N35AP no	oted Honolulu ·	4.9.79 derelict, trigear, Brandt Fleet #7, stored with other	derelict Beech 18s		
			ndt Air hangar;			
			7.89 poor condition, plate BA-744;			
			Mactan AB 6.1.94 in green primer;			
	RP-C1159	9 noted Cebu-l	Mactan AB early 06, trigear, derelict with RP-C1358;			
	1140	14 5407		F F 07		
BA-745	H18 trigoor	JA5137	Japan Air Lines (delivered via Oekland CA 5 67, San Francisco 7 6 67)	5.5.67		
	trigear		(delivered via Oakland CA 5.67. San Francisco 7.6.67) crashed Murayama C5ity, Yamagata	5.10.67		
			crashed murayania Colty, Tanagata	5.10.07		
BA-746	H18	JA5138	Japan Air Lines	25.5.67		
DA-140	trigear	JA0100	(delivered via Oakland CA 31.5.67)	20.0.07		
	ligeal		sold abroad, struck-off Japanese Register	9.4.74		
		(VH-CKS)	ntu: Trans West Air Charter, Perth WA	4.74		
		(11 01(0))	(purchase cancelled due Australian certification probler			
		N34AP	Harmor Inc, Newport Beach CA	4.74/79		
			op: Alii Hawaii Air, Honolulu HI	79		
			op: Brandt Air, Honolulu HI (fleet #9)	79		
			Scenic Air Tour/ Lani Bird, Honolulu HI (#22)	.80/83		
			op: Scenic Air Tours Hawaii, Honolulu HI	85/89		
			crashed in canyon, dest. Waipio Valley HI (11k)	11.6.89		
	145400 8					
			via Oakland CA 5.67, "JAL" emblem on fuse, trigear;			
		oted Tokyo-Ha		ndt Air:		
			2.9.79 trigear "Ali Hawaii Air" titles, in service, op. by Bra	nul All.		
	plate BA-746, manufactured 5.67); N344p noted Lenai HL 2 9 79;					
	N34Ap noted Lenai HI 2.9.79; N34AP flew Honolulu-Molokai-Lanai-Honolulu 5.9.79 op Brandt Air, fresh baked bread run:					
	N34AP flew Honolulu-Molokai-Lanai-Honolulu 5.9.79 op Brandt Air, fresh baked bread run; N34AP noted Honolulu 12.11.79:					
	N34AP noted Honolulu 12.11.79; N34AP noted Honolulu 27.8.81 trigear "Lani Bird", white with red trim;					
	N34AP noted Honolulu 27.8.81 trigear Lani Bird , white with red trim; N34AP noted Kauai HI 27.8.81 engine fire taxying, no damage: "Lani Bird";					
	N34AP no	ted Honolulu	9.83 "Scenic Air Tour/Lani Bird" fleet #22, trigear, plate E	3A-746;		
			"Scenic Air Tours" titles (only), allover red, trigear #22;	,		
			enic Air Tours Flt 21 was a sightseeing flight from Hilo to	o Kahului,struck		
			300 ft in a scenic area near a waterfall, 50 miles north of			
BA-747	H18	JA5139	Japan Air Lines	9.6.67		
	trigear		sold abroad, struck-off Japanese Register	8.8.74		
		(VH-CKR)	ntu: Trans West Air Charter, Perth WA	4.74		
		(VH-CKW)		4.74		
			(purchase cancelled due Australian certification probler			
		PK-BIF	Indonesian Aviation Corp/Indoavia, Jakarta Mega	8.74/90 20 7 18		
			struck-off Register	20.7.18		
	JA5130 R	JA5138 del iv	eredvia Oakland CA .67 (no date), "JAL" emblem on fus	e trigears:		
		oted Chiyoufu		o, angouro,		
			e-Seletar 11.9.75;			
		gap or c	· ······························			

BA-748	H18	JA5140	Japan Air Lines	7.67/74
	trigear		(delivered via San Francisco CA 14.7.67)	
	-		sold to USA, struck-off Japanese Register	18.2.74
		N33AP	Harmor Inc, Newport Beach CA	2.74/81
			(US CofA issued 14.3.74, N33AP dep. Sendai, Japan	
			on 23.2.74 on del. to Honolulu via Midway island)	
			struck-off USCR	6.81
			Robert S. Whittinghill, Honolulu HI: restored USCR	24.10.84/13
			op: Lani Bird, Honolulu HI	84/85
			op: Polynesian Air-Ways Inc, Honolulu HI	.85/92
			dam. landing, Lanai HI	14.2.92
			struck-off USCR	16.4.13

JA5140 photo Oakland CA .67 "JAL" emblem on fuse, trigear; "JA40" noted Tokyo-Haneda 4.69 - probably this acft; N33AP noted Honolulu 1.76 Island Air Tours, trigear; N33AP noted Honolulu 2.89 & 7.89: both "Polynesian Airways" "Darryl O" trigear; N33AP noted Honolulu 6.10.91 in service, metallic, Polynesian Airways titles

BA-749	H18	JA5141	Japan Air Lines	.67/74
BICTIO	trigear	0.10111	(delivered via San Francisco CA 14.7.67)	
	angean		sold abroad, struck-off Japanese Register	5.2.74
			(F-OCUU departed Sendai, Japan 10.2.74 on del. to	0.2
			Tahiti via Hachijo)	
		F-OCUU	Jacques Brunn, Papeete, Tahiti	2.12.74/76
			Rodolphe Klima, Papeete, Tahiti	15.6.76/77
			Air Tahiti, Papeete	2.2.77/80
			op: Tahiti Air Tours Service – TATS	-
			sold to USA, struck-off French Register	27.5.80
		N8476H	Clyde L. Neill, Indian Wells CA	28.7.80
			(US CofA issued 14.11.80)	
			Air Cortez International Inc, Ontario CA	81/86
			Jerry L. Englund/ Englund Air Inc, Mobile AL	9.86/91
			George A. Long, Baker LA	10.92/94
			Jim Hankins Air Service, Jackson MS	17.11.94/02
			Monarch Air Group LLC, Palm City FL	2.2.06/13
			Kevin McCole, Brookline NH	10.1.13/16
			Joanne McCole, Brookline NH	26.8.16/20
	N8476H N8476H N8476H N8476H N8476H:	noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs;	
	N8476H N8476H N8476H N8476H N8476H:	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear,"Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear;	
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs;	25.7.67/74
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A prt: N8476H stil	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins;	25.7.67/74
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A prt: N8476H stil	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67)	25.7.67/74 12.6.74
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A prt: N8476H stil	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines	
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A port: N8476H stil JA5142	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA	12.6.74 1.74
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A port: N8476H stil JA5142	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register	12.6.74 1.74
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems)	12.6.74 1.74 s)
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems Continental Air Services Inc, Los Angeles CA	12.6.74 1.74 s)
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems Continental Air Services Inc, Los Angeles CA (US CofA issued 30.6.74, based Laos,	12.6.74 1.74 s)
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems Continental Air Services Inc, Los Angeles CA (US CofA issued 30.6.74, based Laos, evacuated to Bangkok-Don Muang 4.75, open storage	12.6.74 1.74 s)
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems Continental Air Services Inc, Los Angeles CA (US CofA issued 30.6.74, based Laos, evacuated to Bangkok-Don Muang 4.75, open storage with other Vietnam civil contractor aircraft)	12.6.74 1.74 s)
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems Continental Air Services Inc, Los Angeles CA (US CofA issued 30.6.74, based Laos, evacuated to Bangkok-Don Muang 4.75, open storage with other Vietnam civil contractor aircraft) Bo Larsson/ Parachutingclub Aros, Vasteras, Sweden: who purchased N18843 & N906T at Bangkok (delivered Bangkok to Sweden, via Antwerp 12.4.77)	12.6.74 1.74 s) 5.74/79
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems Continental Air Services Inc, Los Angeles CA (US CofA issued 30.6.74, based Laos, evacuated to Bangkok-Don Muang 4.75, open storage with other Vietnam civil contractor aircraft) Bo Larsson/ Parachutingclub Aros, Vasteras, Sweden: who purchased N18843 & N906T at Bangkok	12.6.74 1.74 s) 5.74/79
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems Continental Air Services Inc, Los Angeles CA (US CofA issued 30.6.74, based Laos, evacuated to Bangkok-Don Muang 4.75, open storage with other Vietnam civil contractor aircraft) Bo Larsson/ Parachutingclub Aros, Vasteras, Sweden: who purchased N18843 & N906T at Bangkok (delivered Bangkok to Sweden, via Antwerp 12.4.77)	12.6.74 1.74 s) 5.74/79
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems Continental Air Services Inc, Los Angeles CA (US CofA issued 30.6.74, based Laos, evacuated to Bangkok-Don Muang 4.75, open storage with other Vietnam civil contractor aircraft) Bo Larsson/ Parachutingclub Aros, Vasteras, Sweden: who purchased N18843 & N906T at Bangkok (delivered Bangkok to Sweden, via Antwerp 12.4.77) op: Parachutingclub Aros, Vasteras-Johannisberg,	12.6.74 1.74 s) 5.74/79 .77
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems Continental Air Services Inc, Los Angeles CA (US CofA issued 30.6.74, based Laos, evacuated to Bangkok-Don Muang 4.75, open storage with other Vietnam civil contractor aircraft) Bo Larsson/ Parachutingclub Aros, Vasteras, Sweden: who purchased N18843 & N906T at Bangkok (delivered Bangkok to Sweden, via Antwerp 12.4.77) op: Parachutingclub Aros, Vasteras-Johannisberg, Sweden (parachuting ops. most of 1977, then retired, stored Vasteras-Johannisberg for 2 years)	12.6.74 1.74 s) 5.74/79 .77
BA-750	N8476H N8476H N8476H N8476H N8476H 8.02 repo	noted Yuma A2 noted Las Vega noted Ontario ( noted Las Vega Jim Hankins A ort: N8476H stil JA5142 (VH-CKN)	Z 2.81 trigear "Air Cortez" titles; as NV 17.8.82 Air Cortez International (10 pax config.); CA 14.2.83 trigear, "Air Cortez International" titles; as NV 4.2.84 "Air Cortez International" titles, trigear; ir Service fleet Status Report 10.8.98: TT 13,900hrs; I in service with Hankins; Japan Air Lines (delivered via San Francisco CA 30.7.67) sold abroad, struck-off Japanese Register ntu: Trans West Air Charter, Perth WA (purchase cancelled due Australian certification problems Continental Air Services Inc, Los Angeles CA (US CofA issued 30.6.74, based Laos, evacuated to Bangkok-Don Muang 4.75, open storage with other Vietnam civil contractor aircraft) Bo Larsson/ Parachutingclub Aros, Vasteras, Sweden: who purchased N18843 & N906T at Bangkok (delivered Bangkok to Sweden, via Antwerp 12.4.77) op: Parachutingclub Aros, Vasteras-Johannisberg, Sweden (parachuting ops. most of 1977, then	12.6.74 1.74 s) 5.74/79 .77

		RP-C1986 RP-C1358	Circle Rainbow Air Inc, Honolulu HI sold to Philippines: struck-off USCR Pacific Airways Corp, Manila Pacific Airways Corp, Manila crashed landing Manila (repaired) Pacific Airways Corp, Manila Commuter Air, Manila CM Aero Service, Manila	12.86/91 9.3.90 .89/93 .93/94 4.94 1.96/97 10 11/12
	N18843 r N62161, N18843 r evacuee BA-667 & Don Mua N18843 r N18843 r N18843 r RP-C198 RP-C198	hoto Vientiano N62156, N621 noted Bangkok Beech 18s and -750 advertis ng Airport, Ban noted Honolulu noted Honolulu 6 noted Manila 6 noted Cebu-	te, Laos 74 trigear; e, Laos 5.75: trigear, parked with lineup Turbo Porters [48 plus two others & United States of America C-47 0-163 (-Don Muang 23.9.75, trigear, stored in centre of field with d Porters; ed for sale 76 by Continental Air Services Pte Ltd, Singapo ngkok: also advertise 7 Porters, 2 DC3s, 2 CV440s; 1 5.9.79 "Circle Rainbow AIr" titles, name "Mieko"; HI 8.82 "Circle Rainbow Air", trigear in service; 1 9.83 "Circle Rainbow Air", trigear, plate BA-750; a 2.1.94 trigear, white with red trim, no titles; Mactan AB early 06, trigear, derelict with RP-C1159; a 3.3.10 Commuter Air, being changed to RP-C9842;	Vietnam
BA-751	H18 trigear	N7025N JA5508	Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired	13.11.67 13.11.67 1.68/81 9.7.81
		oted Chofu 13 oted Chitose	·	
BA-752	H18 trigear	LV-PIB LV-JFH	delivery reg. Firma Arte Grafica Ed Argentina Juan Quevedo Morales Russo SA Jesus Ibarguren Echeverria, Necochea retired, open storage, San Fernando (flying, based Moron, Argentina 06/20)	11.67 29.12.67 4.8.75 31.3.76 9.8.85 96
	LV-JFH n LV-JFH n	oted San Ferr oted at airsho	-Halcon 7.3.86; nando 19.10.96, open storage, plate BA-752; w General-Rodriguez-Ildefonso Durana 9.3.13; w Alvear 18.9.19 polished metal, green trim, trigear;	
BA-753	H18 trigear	JA5143 N2990F	Japan Air Lines, Tokyo (delivered via San Francisco CA 25.3.68) sold to USA, struck-off Japanese Register B & B Enterprises, Honolulu HI op: Panorama Air Tour, Honolulu HI (fleet #60) Airtour Acquisition Corp, Honolulu HI ditched in sea after takeoff, Kailua-Kona HI	3.68/76 14.4.76 15.4.76/82 80/83 16.9.82/83 8.9.83
	N2990F ı N2990F ı	noted Kahului i noted Hilo HI 2	ncisco CA 25.3.68 on delivery "JAL" insignia; HI 27.7.76 Panorama Air Tour; 16.8.81 "Panorama AT #60", in Beech 18 tourist formation; 1 HI 1.83 "Panorama AT" trigear;	
BA-754	H18 trigear	JA5144 N26035	Japan Air Lines, Tokyo (delivered via Oakland CA 4.68) sold to USA, struck-off Japense Register reg (US CofA issued 11.11.76) B & B Enterprises, Honolulu HI Panorama Air Tour, Honolulu HI Airtour Acquisition Corp, Honolulu HI John A. Bombaro, Newport News VA	.68/76 23.8.76 22.8.76 79 80/85 82 11.85

	Atlantic Aero Inc, Greensboro NC	1.87
	Cape Central Airways, Cape Girardeau MO	5.90/91
N583MS	Cape Central Airways, Cape Girardeau MO	7.94/95
N26035	Air Cargo Express, Little Rock AR	28.6.95/99
	Air Classic Cargo Inc, Orlando FL	18.6.99/14
	AOM Aircraft LLC, Newark DE	8.4.14/20

JA5144 noted Oakland CA 4.68 full JAL scheme;

JA5144 noted Nagoya 18.8.72;

N26035 noted Hilo HI 26.8.81 trigear "Panorama AT #61" in Beech 18 tourist formation; N26035 in Panorama fleet list as at 15.11.83: BA-754 tt 16,413hrs, fleet #61; N26035 noted Van Nuys CA 3.8.85 "Panorama Air " titles;

BA-755	H18	JA5145	Japan Air Lines, Tokyo	.68/73
	trigear		(delivered via San Francisco CA 27.5.68)	
			sold to USA, struck-off Japanese Register	25.10.73
		N28358	reg	25.10.73
			(N28358 departed Sendai Japan 7.11.73 on delivery to	
			Honolulu via Midway)	
			Harmor Inc, Newport Beach CA	20.4.74
			op: Island Air	74
			destroyed, struck mountain, Hilo HI (11 k)	11.4.74

San Francisco CA 27.5.68 on delivery, "JAL" insignia; JAS145 noted 3 JA5145 photo 3.71 in Japan, "JAL" emblem, trigear;

JA5145 noted Chofu 26.11.72;

N28358 accident report 11.4.74: Island Air -, flew into mountain slope, dest. 9.41am;

BA-756	H18	N2052A	Sugihara Shigeyoshi, Scarsdale NY	4.6.69
			exported to Japan, struck-off USCR	6.6.69
		JA5164	All Nippon Airways, Tokyo	.69/71
			crashed Nagoya Airport	14.2.71
BA-757	H18	N2069A	Sugihara Shigeyoshi, Scarsdale NY	4.6.69
			exported to Japan, struck-off USCR	6.6.69
		JA5167	All Nippon Airways, Tokyo	6.69/71
			damaged Kochi (repaired)	10.9.69
			Sumikoh Consultant Co	20.10.71
			retired, struck-off Register as scrapped	10.7.78

JA5167 noted Chiyoufa Japan 7.5.72 with JA5139;

JA5167 noted Chofu 13.8.72 with JA5507, JA5508, JA5133, JA5503;

BA-758	H18	JA5147	Japan Air Lines, Tokyo	.69/73
	trigear		SNKS Co	27.7.73
	-		Toa Domestic Airlines, Tokyo	.73/74
			sold to USA, struck-off Japanese Register	26.2.76
		N99799	reg	2.76
			(US CofA issued 23.7.76)	
			Morgan Air Transport, Pensacola FL	79
			Lani Bird Inc/ Scenic Air Tour, Honolulu HI Aloha	79/84
			Tomy International Inc, Honolulu HI	5.91/95
			op: Scenic Air Tour, Honolulu HI (fleet #20)	89
			Matthew R. Barnett, Honolulu HI	31.8.95
			Dove Development Corp, Greenville TX	11.95
			Jim Hankins Air Service, Jackson MS	12.97/99
			James J. Vocell, Atkinson NH	14.8.01/20

N99799 noted Honolulu 7.89 fleet #20, trigear;

N99799 noted Honolulu 2.9.79 & 5.9.79 "Lani Bird" titles name "Aloha" trigear;

N99799 noted Lihue HI 6.10.80 "Lani Bird" fleet #20;

N99799 noted Honolulu 9.83 "Scenic Air Tour/Lani Bird" Fleet #20, trigear, plate BA-758; N99799 noted Honolulu 7.89 Scenic Air Tour Fleet #20, flying;

BA-759	H18	JA5148	Japan Air Lines, Tokyo	.69/73
	trigear		SNKS Co	18.5.73
			Toa Domestic Airlines, Tokyo	.73
		NOOROO	sold to USA, struck-off Japanese Register	26.2.76
		N99800	reg	2.76
			(US CofA issued 2.9.76) International Racing Service, Huntington Harbor CA	79
			Flite Services Inc, Pine Mountain GA	1.84
			Jim Hankins Air Service, Jackson MS	2.90
			Big Red Inc, Jackson MS	3.5.90/06
			Rugged Investment One LLC, Miami FL	15.3.07/20
		oted Sendai 2	,	
			hofu 24.3.74 JAL;	
			see Beech 18 by Robert Parmerter p.241;	
			s CA 23.9.77 trigear, N99800 painted over previous reg;	
	N99800 n	iotea Osnkosr	n WI 27.7.89 trigear, plate BA-759;	
BA-760	H18	JA5149	Japan Air Lines, Tokyo	.69/73
	trigear		SNKS Co	21.9.73
			Toa Domestic Airlines, Tokyo	.73
			sold to USA, struck-off Japanese Register	26.2.76
		N99801	reg	2.76
			Gifford Aviation, Anchorage AK	79
			Panorama Air Tour, Honolulu HI (fleet #64)	.79/84
			AirTour Acquisition Corp, Honolulu HI Sunshine Aero Industries Inc, Crestview FL	82 2.11.84/20
			w FL 14.8.05 plate BA-760, Sunshine Aero Industries: ope th special radar in connection with Predator UAV project;	rated
	By owner	Bob Keller wi	th special radar in connection with Predator UAV project;	
BA-761			th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY	3.9.69
BA-761	By owner	Bob Keller wi	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR	3.9.69 8.9.69
BA-761	By owner	Bob Keller wi	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways	3.9.69 8.9.69 9.69/71
BA-761	By owner	Bob Keller wi	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR	3.9.69 8.9.69
	By owner	Bob Keller wi	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69
	By owner	Bob Keller wi N2072A JA5169 N2079A	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69
	By owner	Bob Keller wi N2072A JA5169	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81
	By owner	Bob Keller wi N2072A JA5169 N2079A	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69
	By owner H18 H18	Bob Keller wi N2072A JA5169 N2079A JA5509	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81
BA-761 BA-762 BA-763	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81
BA-762	By owner H18 H18 JA5509 n	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-Ha	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81
BA-762	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-Ha N2080A	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69,	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81
BA-762	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-Ha N2080A	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International)	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81
BA-762	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-Ha N2080A	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81
BA-762	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-Ha N2080A	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81
BA-762	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-H N2080A JA5172	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki op: Maritime Safety Agency, Naha	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81 .69 1.70/78 74 75
BA-762	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-Ha N2080A	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki op: Maritime Safety Agency, Naha Circle Rainbow Air Inc, Honolulu HI	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81 .69 1.70/78 74 75 4.6.85/92
BA-762	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-H N2080A JA5172 N763C	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki op: Maritime Safety Agency, Naha Circle Rainbow Air Inc, Honolulu HI sold to Philippines, struck-off USCR	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81 .69 1.70/78 74 75 4.6.85/92 27.1.92
BA-762	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-H N2080A JA5172	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki op: Maritime Safety Agency, Naha Circle Rainbow Air Inc, Honolulu HI sold to Philippines, struck-off USCR Charles R. Miller/ CM Aero, Manila	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81 .69 1.70/78 74 75 4.6.85/92 27.1.92 90/98
BA-762	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-H N2080A JA5172 N763C	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki op: Maritime Safety Agency, Naha Circle Rainbow Air Inc, Honolulu HI sold to Philippines, struck-off USCR Charles R. Miller/ CM Aero, Manila J. G. Gomez, Clark Field	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81 .69 1.70/78 74 75 4.6.85/92 27.1.92 90/98 .00/01
BA-762	By owner H18 H18 JA5509 n H18	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-H N2080A JA5172 N763C	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki op: Maritime Safety Agency, Naha Circle Rainbow Air Inc, Honolulu HI sold to Philippines, struck-off USCR Charles R. Miller/ CM Aero, Manila	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81 .69 1.70/78 74 75 4.6.85/92 27.1.92 90/98
3A-762	By owner H18 H18 JA5509 n H18 trigear	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-H N2080A JA5172 N763C RP-C692	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki op: Maritime Safety Agency, Naha Circle Rainbow Air Inc, Honolulu HI sold to Philippines, struck-off USCR Charles R. Miller/ CM Aero, Manila J. G. Gomez, Clark Field crashed Manila, Philippines	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81 .69 1.70/78 74 75 4.6.85/92 27.1.92 90/98 .00/01
BA-762	By owner H18 H18 JA5509 n H18 trigear	Bob Keller wi N2072A JA5169 N2079A JA5509 oted Tokyo-H N2080A JA5172 N763C RP-C692	th special radar in connection with Predator UAV project; Sugihara Shigeyoshi, Scarsdale NY exported to Japan, struck-off USCR All Nippon Airways crashed Omura, Nagasaki Shigyoshi Sugihara, Scarsdale NY exported to Japan, struck-off USCR Maritime Safety Agency, Chitose retired, struck-off Japanese Register aneda 10.5.73 MSA; built Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki op: Maritime Safety Agency, Naha Circle Rainbow Air Inc, Honolulu HI sold to Philippines, struck-off USCR Charles R. Miller/ CM Aero, Manila J. G. Gomez, Clark Field	3.9.69 8.9.69 9.69/71 14.2.71 8.9.69 11.9.69 10.69/81 18.2.81 .69 1.70/78 74 75 4.6.85/92 27.1.92 90/98 .00/01

N99799 noted Jackson-Higgins Field MS 11.8.98, trigear pax seating, Hankins AS; N99799: Jim Hankins Air Service fleet Status Report 10.8.98: TT 21,715 hrs; N99799 noted Boston-Logan MA 7.02 trigear;

JA5172 noted Tokyo-Chofu 1.4.74 operator Koku Daigaku;

JA5172 noted Naha 7.12.75 MSA; RP-C692 noted Manila 2.1.94; RP-C692 noted Manila 4.2.98 on CM Aero ramp, red/white trigear;

	H18	N2088A	built	.69
BA-764	Trigear	JA5173	Japan Civil Aviation Bureau Aeronautical College (departed Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International) op: Japan Civil Aviation Bureau Aeronautical College/	1.70/80
			Koku Daigaku, Miyazuki	74
			op: Maritime Safety Agency, Hiroshima	80
		N26493	Pacific International Traders Inc, Palau	25.12.81
			Robert E. Etchell, Koror, Micronesia	1.82
			Hutchinson Auto & Air Transport, Honolulu HI	3.84
			Circle Rainbow Air, Honolulu HI	.86/92
			struck-off USCR	23.1.92
			Matthew R. Barnett, Honolulu HI: restored to USCR	22.6.94/95
			Charles B. Mobus, New York NY Beach Aero Partners Inc, Westhampton Beach NY	18.7.95/11
			Dakota Express LLC, Lantana FL	10.1.12/15 27.9.17/18
			Mike Spaulding, Cairns QLD Australia	8.18
			(del. via Santa Monica CA-Hilo HI 13.5.19)	0.10
		VH-MBU	Mike Spaulding Pty Ltd, Cairns QLD	2.8.19/20
		ed; vas noted as c	lelivered ex Chofu, Japan 16.4.82: possibly returned for m	aintenance?
	N26493 w N26493 n N26493 n N26493 n	vas noted as c noted Honolulı noted Honolulı noted Teterbor	lelivered ex Chofu, Japan 16.4.82: possibly returned for m ı 8.9.91, 6.10.91, ı 12.93: derelict, trigear ex JA5173 visible; o NJ 16.7.98 trigear; a Qld 20.8.19 in Mike Spaulding's North Queensland Warl	
BA-765	N26493 v N26493 n N26493 n N26493 n VH-MBU	vas noted as c noted Honolulu noted Honolulu noted Teterbor noted Mareeb	ı 8.9.91, 6.10.91, ı 12.93: derelict, trigear ex JA5173 visible; o NJ 16.7.98 trigear; a Qld 20.8.19 in Mike Spaulding's North Queensland Warl	birds hangar;
BA-765	N26493 w N26493 n N26493 n N26493 n	vas noted as c noted Honolulı noted Honolulı noted Teterbor	ı 8.9.91, 6.10.91, ı 12.93: derelict, trigear ex JA5173 visible; o NJ 16.7.98 trigear;	
BA-765	N26493 v N26493 n N26493 n N26493 n VH-MBU H18	vas noted as c noted Honolulu noted Honolulu noted Teterbor noted Mareeb	<ul> <li>8.9.91, 6.10.91,</li> <li>1.12.93: derelict, trigear ex JA5173 visible;</li> <li>o NJ 16.7.98 trigear;</li> <li>a Qld 20.8.19 in Mike Spaulding's North Queensland Wark</li> <li>Shigeyoshi Sugihara, Scarsdale NY</li> <li>(dep. Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International, dep. Oakland CA 1.7</li> </ul>	birds hangar; 11.69/70 0)
BA-765	N26493 v N26493 n N26493 n N26493 n VH-MBU H18	vas noted as c noted Honolulu noted Honolulu noted Teterbor noted Mareeb N2091A	<ul> <li>8.9.91, 6.10.91,</li> <li>1.2.93: derelict, trigear ex JA5173 visible;</li> <li>o NJ 16.7.98 trigear;</li> <li>a Qld 20.8.19 in Mike Spaulding's North Queensland Ward</li> <li>Shigeyoshi Sugihara, Scarsdale NY</li> <li>(dep. Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International, dep. Oakland CA 1.79</li> <li>exported to Japan, struck-off USCR</li> </ul>	birds hangar; 11.69/70
BA-765	N26493 v N26493 n N26493 n N26493 n VH-MBU H18	vas noted as c noted Honolulu noted Honolulu noted Teterbor noted Mareeb	<ul> <li>8.9.91, 6.10.91,</li> <li>12.93: derelict, trigear ex JA5173 visible;</li> <li>NJ 16.7.98 trigear;</li> <li>Qld 20.8.19 in Mike Spaulding's North Queensland Wark</li> <li>Shigeyoshi Sugihara, Scarsdale NY</li> <li>(dep. Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International, dep. Oakland CA 1.70</li> <li>exported to Japan, struck-off USCR</li> <li>Japan Civil Aviation Bureau Aeronautical College/</li> </ul>	birds hangar; 11.69/70 0) 27.1.70
BA-765	N26493 v N26493 n N26493 n N26493 n VH-MBU H18	vas noted as c noted Honolulu noted Honolulu noted Teterbor noted Mareeb N2091A	<ul> <li>8.9.91, 6.10.91,</li> <li>1.12.93: derelict, trigear ex JA5173 visible;</li> <li>o NJ 16.7.98 trigear;</li> <li>a Qld 20.8.19 in Mike Spaulding's North Queensland Wark</li> <li>Shigeyoshi Sugihara, Scarsdale NY</li> <li>(dep. Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International, dep. Oakland CA 1.70</li> <li>exported to Japan, struck-off USCR</li> <li>Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki</li> </ul>	birds hangar; 11.69/70 0) 27.1.70 2.70/78
BA-765	N26493 v N26493 n N26493 n N26493 n VH-MBU H18	vas noted as c noted Honolulu noted Honolulu noted Teterbor noted Mareeb N2091A	<ul> <li>8.9.91, 6.10.91,</li> <li>12.93: derelict, trigear ex JA5173 visible;</li> <li>NJ 16.7.98 trigear;</li> <li>Qld 20.8.19 in Mike Spaulding's North Queensland Wark</li> <li>Shigeyoshi Sugihara, Scarsdale NY</li> <li>(dep. Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International, dep. Oakland CA 1.70</li> <li>exported to Japan, struck-off USCR</li> <li>Japan Civil Aviation Bureau Aeronautical College/</li> </ul>	birds hangar; 11.69/70 0) 27.1.70
BA-765	N26493 v N26493 n N26493 n VH-MBU H18 trigear	vas noted as c loted Honolulu loted Honolulu loted Teterbor noted Mareeb N2091A JA5174 h 18 manufact	<ul> <li>A. 8.9.91, 6.10.91,</li> <li>A. 12.93: derelict, trigear ex JA5173 visible;</li> <li>NJ 16.7.98 trigear;</li> <li>A. Qld 20.8.19 in Mike Spaulding's North Queensland Wark</li> <li>Shigeyoshi Sugihara, Scarsdale NY</li> <li>(dep. Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International, dep. Oakland CA 1.74</li> <li>exported to Japan, struck-off USCR</li> <li>Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki</li> <li>Civil Aviation College Maintenance Division, Miyazaki</li> <li>(static display in hangar, excellent condition)</li> </ul>	birds hangar; 11.69/70 0) 27.1.70 2.70/78
BA-765	N26493 v N26493 n N26493 n VH-MBU H18 trigear	vas noted as c loted Honolulu loted Honolulu noted Teterbor noted Mareeb N2091A JA5174 h 18 manufact etails Japan s	a 8.9.91, 6.10.91, a 12.93: derelict, trigear ex JA5173 visible; o NJ 16.7.98 trigear; a Qld 20.8.19 in Mike Spaulding's North Queensland Ward Shigeyoshi Sugihara, Scarsdale NY (dep. Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International, dep. Oakland CA 1.70 exported to Japan, struck-off USCR Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki Civil Aviation College Maintenance Division, Miyazaki (static display in hangar, excellent condition) tured ale and ferry: Parmerter p.312/313;	birds hangar; 11.69/70 0) 27.1.70 2.70/78
BA-765	N26493 w N26493 n N26493 n VH-MBU H18 trigear H18 trigear	vas noted as c ooted Honolulu ooted Honolulu noted Teterbor noted Mareeb N2091A JA5174 h 18 manufact etails Japan so noted Agusta-J	<ul> <li>A. 8.9.91, 6.10.91,</li> <li>A. 12.93: derelict, trigear ex JA5173 visible;</li> <li>NJ 16.7.98 trigear;</li> <li>A. Qld 20.8.19 in Mike Spaulding's North Queensland Wark</li> <li>Shigeyoshi Sugihara, Scarsdale NY</li> <li>(dep. Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International, dep. Oakland CA 1.74</li> <li>exported to Japan, struck-off USCR</li> <li>Japan Civil Aviation Bureau Aeronautical College/</li> <li>Koku Daigaku, Miyazuki</li> <li>Civil Aviation College Maintenance Division, Miyazaki</li> <li>(static display in hangar, excellent condition)</li> </ul>	birds hangar; 11.69/70 0) 27.1.70 2.70/78
BA-765	N26493 w N26493 n N26493 n N26493 n VH-MBU H18 trigear H18 trigear	vas noted as c loted Honolulu loted Honolulu loted Teterbor noted Mareeb N2091A JA5174 h 18 manufact etails Japan s noted Agusta-l oted Kagoshir	<ul> <li>a. 8.9.91, 6.10.91,</li> <li>a. 12.93: derelict, trigear ex JA5173 visible;</li> <li>b. NJ 16.7.98 trigear;</li> <li>b. Qld 20.8.19 in Mike Spaulding's North Queensland Ward</li> <li>Shigeyoshi Sugihara, Scarsdale NY</li> <li>(dep. Beech factory on delivery to Japan 26.11.69,</li> <li>ferried by Air Capital International, dep. Oakland CA 1.70</li> <li>exported to Japan, struck-off USCR</li> <li>Japan Civil Aviation Bureau Aeronautical College/</li> <li>Koku Daigaku, Miyazuki</li> <li>Civil Aviation College Maintenance Division, Miyazaki</li> <li>(static display in hangar, excellent condition)</li> </ul>	birds hangar; 11.69/70 0) 27.1.70 2.70/78
BA-765	N26493 w N26493 n N26493 n N26493 n VH-MBU H18 trigear H18 trigear JA5174 n JA5174 n	h 18 manufact boted Honolulu boted Honolulu boted Teterbor noted Mareeb N2091A JA5174 h 18 manufact boted Sapan so noted Agusta-l oted Kagoshir oted Chofu 7.	<ul> <li>a. 8.9.91, 6.10.91,</li> <li>a. 12.93: derelict, trigear ex JA5173 visible;</li> <li>b. NJ 16.7.98 trigear;</li> <li>b. Qld 20.8.19 in Mike Spaulding's North Queensland Ward</li> <li>Shigeyoshi Sugihara, Scarsdale NY</li> <li>(dep. Beech factory on delivery to Japan 26.11.69,</li> <li>ferried by Air Capital International, dep. Oakland CA 1.7</li> <li>exported to Japan, struck-off USCR</li> <li>Japan Civil Aviation Bureau Aeronautical College/</li> <li>Koku Daigaku, Miyazuki</li> <li>Civil Aviation College Maintenance Division, Miyazaki</li> <li>(static display in hangar, excellent condition)</li> </ul>	birds hangar; 11.69/70 0) 27.1.70 2.70/78
BA-765	N26493 w N26493 n N26493 n N26493 n VH-MBU H18 trigear H18 trigear H18 trigear JA5174 n JA5174 n JA5174 n	h 18 manufact boted Honolulu boted Honolulu boted Teterbor noted Mareeb N2091A JA5174 h 18 manufact boted Sapan so noted Agusta-l oted Kagoshir oted Chofu 7.	<ul> <li>A. 8.9.91, 6.10.91,</li> <li>A. 12.93: derelict, trigear ex JA5173 visible;</li> <li>NJ 16.7.98 trigear;</li> <li>A. Qld 20.8.19 in Mike Spaulding's North Queensland Wark</li> <li>Shigeyoshi Sugihara, Scarsdale NY</li> <li>(dep. Beech factory on delivery to Japan 26.11.69, ferried by Air Capital International, dep. Oakland CA 1.70</li> <li>exported to Japan, struck-off USCR</li> <li>Japan Civil Aviation Bureau Aeronautical College/ Koku Daigaku, Miyazuki</li> <li>Civil Aviation College Maintenance Division, Miyazaki</li> <li>(static display in hangar, excellent condition)</li> </ul>	birds hangar; 11.69/70 0) 27.1.70 2.70/78