Rules of Thumb for Maintenance and Reliability Engineers

Ricky Smith

R. Keith Mobley



AMSTERDAM • BOSTON • HEIDELBERG • LONDON NEW YORK • OXFORD • PARIS • SAN DIEGO SAN FRANCISCO • SINGAPORE • SYDNEY • TOKYO Butterworth-Heinemann is an imprint of Elsevier



Contents

Introduction—The Recommended First Step to Rules of Thumb in Reliability Engineering xiii

P A R T

THE BASICS OF MAINTENANCE AND RELIABILITY

CHAPTER

1

Understanding Maintenance and Reliability

- 1.1. The Maintenance Function 3
- 1.2. Strategy to Achieve World-Class Production through Reliability 3
 - 1.2.1. Maintenance Approaches 4
 - 1.2.2. Maintenance Management
 - Philosophy 4
 - 1.2.3. The Function and Control System 5
 - 1.2.4. What Is Maintenance? 5
 - 1.2.5. Specification 6
 - 1.2.6. The Maintenance Function 6
- 1.3. What Is Reliability? 8
 - 1.3.1. Companies That Get It 8
 - 1.3.2. Why Move Toward Proactive Work? 9
 - 1.3.3. A New Way to View Failure 10
- 1.4. Maintenance/Reliability Assessment 10

- 1.5. Introduction to Change Management 14
- 1.6. Developing a Business Case for a Reliability Initiative 16
- 1.7. Calculating Return on Investment 19 1.7.1. Leadership of the ROI Team 19 1.7.2. Case Study 19
- 1.8. Planning and Scheduling 21

CHAPTER

The Functional Maintenance Organization and Its People

- 2.1. Functional Maintenance Organizational Structure 27
- 2.2. Maintenance Supervisor 29 2.2.1. Responsibilities 29
 - 2.2.2. Environmental, Health, and Safety Aspects 30
- 2.3. Maintenance Planner/Scheduler 30 2.3.1. Responsibilities 30
- 2.4. Maintenance and Engineering Manager 31
 - 2.4.1. Responsibilities 31
 - 2.4.2. Environmental, Health, and Safety Aspects 32
- 2.5. Area Manager of Warehouse and Inventory Control 32 2.5.1. Responsibilities 32
- 2.6. Reliability Engineer 33
 - 2.6.1. Responsibilities 34
 - 2.6.2. Job Skills 34
 - 2.6.3. Reliability Engineering Dashboard—Key Performance Indicators 35

CHAPTER

3

Preventive Maintenance Program

- 3.1. Reliability-Based Preventive
 - Maintenance 37
 - 3.1.1. Information Collection 38
 - 3.1.2. System Analysis 38
 - 3.1.3. Identification of Systems 38
 - 3.1.4. Identification of System Functions 38
 - 3.1.5. Selection of Systems 38
 - 3.1.6. System Functional Failure and Criticality Rating 40
- 3.2. Identification of Functionally Significant Items 40
- 3.3. Maintenance Task Selection (Decision Logic Tree Analysis) 403.3.1. Levels of Analysis 41
 - 3.3.2. Paralleling and Default Logic 43
- 3.4. Maintenance Tasks 43
- 3.5. Task Frequencies/Intervals 44

СНАРТЕК

4

Predictive Maintenance Program

- 4.1. Setting Up a Preventive/Predictive Maintenance Program 49
- 4.2. Visual Inspection 50
- 4.3. Vibration Analysis 50
- 4.4. Thermography 53
- 4.5. Tribology 54
- 4.6. Ultrasonics 56

CHAPTER

5

Reliability Processes

- 5.1. Reliability Software—Managing the Health of Assets 57
 - 5.1.1. Building an Effective Asset Reliability Program 58
 - 5.1.2. Using Reliability Software to Put the Program into Action 58

- 5.1.3. Using Handheld Devices to Collect and Upload Condition Inspection Data 59
- 5.1.4. Plotting Asset Health Trends 61
- 5.1.5. Capturing the Experts' Knowledge about Asset Condition 61
- 5.1.6. Integration to Enterprise Asset Management and Computerized Maintenance Management Systems 62
- 5.1.7. The Bottom Line 63
- 5.2. Seven Questions Addressed by Reliability Centered Maintenance 63
- 5.3. Failure Mode and Effects Analysis 66
- 5.4. Equipment Criticality Analysis 68
 - 5.4.1. Preparing for an Equipment Criticality Analysis 71
 - 5.4.2. Conducting the Review 72
 - 5.4.3. Analyzing the Assessment Results 75
 - 5.4.4. Using the Output of the Equipment Criticality Assessment 77
 - 5.4.5. Conclusions 78
- 5.5. Root Cause Analysis 79
 - 5.5.1. Plan 79
 - 5.5.2. Do 81
 - 5.5.3. Check 83
 - 5.5.4. Act 86

CHAPTER

6

Key Performance Indicators

- 6.1. Defining and Understanding KPIs 89
 - 6.1.1. The Problem 90
 - 6.1.2. John Day 91
 - 6.1.3. The Solution 93
- 6.2. KPI Dashboards 93
 - 6.2.1. Plant Manager Dashboard 93
 - 6.2.2. Plant Management Team Dashboard 93
 - 6.2.3. Production Manager (Supervisor) Dashboard 94
 - 6.2.4. Production Operator Dashboard 94
 - 6.2.5. Maintenance Manager (Supervisor) Dashboard 94
 - 6.2.6. Maintenance Staff Dashboard 95
 - 6.2.7. Reliability Engineer Dashboard 95
 - 6.2.8. Engineering Manager Dashboard 95
 - 6.2.9. Purchasing Manager Dashboard 95
 - 6.2.10. Maintenance Stores Manager 95
 - 6.2.11. Conclusion 95

- 6.3. Measuring and Managing the
 - Maintenance Function 95
 - 6.3.1. Physical Asset Management 96
 - 6.3.2. The Asset Reliability Process 976.3.3. Performance Metrics for the
 - Maintenance Function 99
 - 6.3.4. Reliability Process Key Performance Indicators—Leading Measures 99
 - 6.3.5. Work Identification 99
 - 6.3.6. Work Planning 100
 - 6.3.7. Work Scheduling 100
 - 6.3.8. Work Execution 101
 - 6.3.9. Follow-Up 101
 - 6.3.10. Performance Analysis 101
 - 6.3.11. Key Performance Indicators of Maintenance Effectiveness (Result Measures) 102
 - 6.3.12. The Importance of the Work Order 103
 - 6.3.13. Reporting and Use of Key Performance Indicators 103
 - 6.3.14. Conclusion 104

CHAPTER

7

Total Productive Maintenance

- 7.1. Introduction to Total Productive Maintenance 107
 - 7.1.1. The TPM Organization 107
 - 7.1.2. TPM Objectives 108
 - 7.1.3. Autonomous Maintenance 108
 - 7.1.4. Equipment Management 108
 - 7.1.5. TPM Integration 108
 - 7.1.6. TPM Is an Investment 108
 - 7.1.7. Calculating Major Losses Is Key to TPM's Success 109
- 7.2. Lean Reliability 111
 - 7.2.1. The Evolution from Lean Manufacturing to Lean Maintenance to Lean Reliability 111
 - 7.2.2. Managing Asset Performance to Meet Customer Needs 112
 - 7.2.3. The Basic Principles of Lean Reliability 114
 - 7.2.4. How Lean Reliability Aligns with TPM, Kaizen, Five S, and Six Sigma 117
 - 7.2.5. Key Elements to Implement and Sustain Lean Reliability 119
 - 7.2.6. Summary 120

PART

Π

EQUIPMENT AND PROCESSES

CHAPTER

8

Chain Drives

- 8.1. Chain Selection 124
 - 8.1.1. Plain or Detachable-Link Chain 124
 - 8.1.2. Roller Chain 124
 - 8.1.3. Sprockets 124
- 8.2. Chain Installation 124
- 8.3. Power Train Formulas 1258.3.1. Shaft Speed 125
- 8.4. Chain Length 126
- 8.5. Multiple Sprockets 126
- 8.6. Chain Speed 127
- 8.7. Preventive Maintenance Procedures 127

СНАРТЕК

9

Hydraulics

- 9.1. Hydraulic Knowledge 129
- 9.2. Hydraulic Troubleshooter 129
- 9.3. General Maintenance Person 129
- 9.4. Best Maintenance Hydraulic
- Repair Practices 130
- 9.5. Root Cause Failure Analysis 130
- 9.6. Preventive Maintenance 130
- 9.7. Measuring Success 132
- 9.8. Recommended Maintenance Modifications 133

CHAPTER

10

Maintenance Welding

- 10.1. Shielded Metal Arc Welding (SMAW), "Stick Welding" 136
- 10.2. Flux-Cored Arc Welding (FCAW) 13710.2.1. FCAW with Gas 13710.2.2. FCAW Self-Shielded 137
- 10.3. Gas-Shielded Metal Arc Welding (GMAW) 141

- 10.3.1. GMAW for Maintenance Welding 141 10.3.2. Gas Selection for GMAW 141 10.4. Gas Tungsten Arc Welding (GTAW) 144 10.4.1. Applicability of GTAW 145 10.4.2. Advantages and Disadvantages of GTAW 145 10.4.3. Principles of Operating GTAW 145 10.4.4. Polarity and GTAW 147 10.4.5. GTAW Shielding Gases and Flow Rates 147 10.4.6. Electrode Material for GTAW 148 10.4.7. GTAW Electrode Size and Tip Shape 148 10.4.8. GTAW Electrode Holders and Gas Nozzles 149 10.4.9. Characteristics of GTAW Power Supplies 149 10.4.10. GTAW Torches 150 10.4.11. Manual GTAW Techniques 151 10.4.12. Establishing Welding Parameters for GTAW 151 10.4.13. Gas Tungsten Arc Starting Methods 151 10.5. Oxyacetylene Cutting 151 10.6. Air-Carbon Arc Cutting and Gouging 152 10.6.1. Applications 153 10.6.2. Power Sources 154 10.7. Plasma Arc Cutting 155 10.8. Welding Procedures 157 10.9. Qualification of Welders 157 10.10. Plasma Arc Welding 157 10.11. Base Metals 157 10.11.1. The Carbon Steels 157 10.11.2. The Alloy Steels 158 10.11.3. The Nonferrous Metals 160 10.12. Control of Distortion 160 10.13. Special Applications 161 10.13.1. Sheet Metal Welding 161 10.13.2. Hard Surfacing 161 10.13.3. Resisting Abrasive Wear 161 10.13.4. Resisting Impact Wear 161 10.13.5. Types of Surfacing Electrodes 163 10.13.6. Choosing Hard-Facing Material 163 10.13.7. Check Welding Procedure 165 10.13.8. Check Before the Part Is Completely Worn 165 10.13.9. Hard Surfacing with SAW 165 10.14. Selection and Maintenance of Equipment 167 10.14.1. Machines 167 10.14.2. Accessory Equipment 169 10.15. Installation of Equipment 169 10.16. Equipment Operation and Maintenance 170 10.16.1. Keep the Machine Clean and Cool 170 10.16.2. Do Not Abuse the Machine 170
- 10.16.3. Do Not Work the Machine Over Its Rated Capacity 170
 10.16.4. Do Not Handle Roughly 170
 10.16.5. Maintain the Machine Regularly 170
- 10.17. Safety 172

СНАРТЕК

11

Bearings

- 11.1. Types of Movement 175
 - 11.1.1. About a Point (Rotational) 175
 - 11.1.2. About a Line (Rotational) 175
 - 11.1.3. Along a Line (Translational) 175
 - 11.1.4. In a Plane (Rotational/ Translational) 178
- 11.2. Commonly Used Bearing Types 178
 - 11.2.1. Plain Bearings 178
 - 11.2.2. Rolling Element or Antifriction 182
 - 11.2.3. Roller 185
- 11.3. Bearing Materials 187
 - 11.3.1. Plain 188
 - 11.3.2. Rolling Element 188
- 11.4. Lubrication 188
 - 11.4.1. Plain Bearings 188
 - 11.4.2. Rolling Element Bearings 189
- 11.5. Installation and General Handling Precautions 190
 - 11.5.1. Plain Bearing Installation 190
 - 11.5.2. Roller Bearing Installation 190
 - 11.5.3. General Roller-Element Bearing Handling Precautions 192
- 11.6. Bearing Failures, Deficiencies, and Their Causes 193
 - 11.6.1. Improper Bearing Selection and/or Installation 193
 - CHAPTER

12

Compressors

12.1. Centrifugal 199

12.1.1. Configuration 199

- 12.2. Performance 201
 - 12.2.1. First Law of Thermodynamics 201
 - 12.2.2. Second Law of Thermodynamics 202
 - 12.2.3. Pressure/Volume/Temperature (PVT) Relationship 202

- 12.2.4. Pressure/Compression 202
- 12.2.5. Other Performance Indicators 202
- 12.3. Positive Displacement 203
- 12.3.1. Rotary 203
- 12.4. Reciprocating 206
 - 12.4.1. Configuration 207
 - 12.4.2. Performance 210
 - 12.4.3. Installation 210
 - 12.4.4. Operating Methods 212
- 12.5. Troubleshooting 212
 - 12.5.1. Centrifugal 212
 - 12.5.2. Rotary-Type, Positive Displacement 212
 - 12.5.3. Reciprocating, Positive Displacement 216

CHAPTER

13

Gears and Gearboxes

- 13.1. Spur Gears 225
- 13.2. Pitch Diameter and Center Distance 226
- 13.3. Circular Pitch 227
- 13.4. Diametrical Pitch and Measurement 227
 - 13.4.1. Method 1 228
 - 13.4.2. Method 2 228
- 13.5. Pitch Calculations 228
- 13.6. Tooth Proportions 229
- 13.7. Backlash 230
- 13.8. Other Gear Types 230
 - 13.8.1. Bevel and Miter 230
 - 13.8.2. Helical 231
 - 13.8.3. Worm 232
 - 13.8.4. Herringbone 233
 - 13.8.5. Gear Dynamics and Failure Modes 233 13.8.6. Common Characteristics 235
 - T5.6.6. Common Characteristics 23
- 13.9. Troubleshooting 236 13.9.1. Normal Wear 237
 - 13.9.2. Abnormal Wear 237

CHAPTER

14

Packing and Seals

- 14.1. Fundamentals 23914.1.1. Shaft Seal Requirements 23914.1.2. Sealing Devices 239
- 14.2. Mechanical Seal Designs 24214.2.1. Single-Coil Spring Seal 24214.2.2. Positive Drive 242

- 14.3. Installation Procedures 24214.3.1. Packed Stuffing Box 24314.3.2. Mechanical Seals 245
- 14.4. Troubleshooting 248
- 14.4.1. Mechanical Seals 248 14.4.2. Packed Boxes 249

CHAPTER

15

Electric Motors

- 15.1. Bearing Frequencies 251
- 15.2. Imbalance 251
- 15.3. Line Frequency 251
- 15.4. Loose Rotor Bars 251
- 15.5. Running Speed 252
- 15.6. Slip Frequency 252
- 15.7. V-Belt Intermediate Drives 252
- 15.8. Electric Motor Analysis 252

PART

III

ADDITIONAL READINGS ON MAINTENANCE AND RELIABILITY

CHAPTER

16

Reliability Articles

- 16.1. Top Five Reasons Why Companies Don't Measure Reliability: It Seems Like Everyone Has an Excuse as to Why They Don't Measure Reliability 255
 - 16.1.1. Reason 1 255
 - 16.1.2. Reason 2 255
 - 16.1.3. Reason 3 255
 - 16.1.4. Reason 4 255
 - 16.1.5. Reason 5 256
- 16.2. Creating a Culture Change in Your Maintenance Department: Is Your Maintenance Crew in a Reactive Mindset? Check Out a List of Qualifiers to Find Out and Then Learn How to Change It 256

- 16.3. Exterminate Lube Problems: Grease and Oil Expertise Can Be a Serious Competitive Edge 257
 - 16.3.1. Big, Bad, and Ugly 257
 - 16.3.2. Make Lube Expertise a Specialty 258
 - 16.3.3. Get the Job Done 260
- 16.4. What It Takes to Make the Climb from Reactive to RCM 260
 - 16.4.1. Waving the Flag 261
 - 16.4.2. Does Management Understand? 269
 - 16.4.3. Who Owns Reliability? 270
 - 16.4.4. Informal versus Formal PM Programs 270
 - 16.4.5. To Measure Is to Manage 270
 - 16.4.6. Depth of Understanding 271
 - 16.4.7. Indicated Actions 272
 - 16.4.8. Lessons Are Simple 273
- 16.5. Put a Plant-wide Focus on Functional Failures 274
- 16.6. Reliability Is Worth a Second Look: Statistical Analysis and Time-Based Preventive Maintenance Don't Really Address the Ability to Perform—It's Time to Get Familiar with the Definition of Reliability 275
- 16.7. When Preventive Maintenance Doesn't Work 276
- 16.8. The Top Four Reasons Why Predictive Maintenance Fails and "What to Do about It" 277 16.8.1. PF Curve 278
 - 16.8.2. Reason 1: The Collection of PdM Data Is Not Viewed as Part of the Total Maintenance Process 278
 - 16.8.3. Reason 2: The Collected PdM Data Arrives Too Late to Prevent Equipment Failures 279
 - 16.8.4. Reason 3: Many Companies Fail to Take Advantage of Data from PLCs and DCSs 279

- 16.8.5. Reason 4: Most PdM Data Is Dispersed in Too Many Non-Integrated Databases 280
- 16.8.6. Some Simple Guidelines Will Help to Get You Moving in the Right Direction 281
- 16.8.7. Summary 282
 - СНАРТЕК

17

MTBF Users Guide

- 17.1. Understanding Definitions 283
- 17.2. The MTBF Process 283
- 17.3. Example 284
 - 17.3.1. MTBF Percentage Change 284
 - 17.3.2. Total Plant MTBF 284
- 17.4. Summary 284

APPENDIX

Α

Workflow for Planning

APPENDIX

B

Checklists and Forms

Glossary 315 Index 319