

University of Nebraska Forest Service is offering the following items available for interdepartmental transfer.

1. John Deere 350 hay rake

Condition: Fair, not recently used

Damage: damaged rim/tire and PTO shaft

Make: John Deere,

model: 350, S/N: 12565

Year: 1965,

Department: Nebraska Forest Service

Contact: Andrew Zahn azahn3@unl.edu, 402-296-6046

Price (negotiable): \$300.00

Cost object: 22-6553-0003

Address: 2106 Horning Road, Plattsmouth, NE, 68048

Pickup instructions: contact Andrew Zahn



2. International tandem pull behind disk

Condition: Fair, not recently used

Damage: couple missing disks

Make: International

Model: Unknown

S/N: Unknown

Year: Unknown

Department: Nebraska Forest Service

Contact: Andrew Zahn, azahn3@unl.edu, 402-296-6046

Price (negotiable): \$500.00

Cost object: 22-6553-0003

Address: 2106 Horning Road, Plattsmouth, NE, 68048

Pickup instructions: contact Andrew Zahn



3. John Deere 709 pull behind rotary mower

Condition: Good, used annually 2016-2018, PTO driven, hydraulic deck lift, both in good condition

Damage: slightly bent blade

Make: John Deere

Model: 709

S/N: AW2291?

Year: Unknown

Department: Nebraska Forest Service

UNL inventory tag number: 250870

Contact: Andrew Zahn, azahn3@unl.edu, 402-296-6046,

Price (negotiable): \$1500.00

Cost object: 22-6553-0003

Address: 2106 Horning Road, Plattsmouth, NE, 68048

Pickup instructions: contact Andrew Zahn



4. Portable steel stairs (2)

Condition: Good , **Use:** not recently used,

Damage: none,

Make: N/A,

Model: N/A,

S/N: N/A,

Year: N/A,

Department: Nebraska Forest Service,

Contact: Andrew Zahn, azahn3@unl.edu, 402-296-6046,

Price: (negotiable): \$50.00 each,

Cost object: 22-6553-0003,

Address: 2106 Horning Road, Plattsmouth, NE, 68048,

Pickup instructions: contact Andrew Zahn



5. 3-point plow-style tree planter

Condition: Fair, Use: not recently used

Damage: damaged tire/rim, missing seat

Make: N/A

Model: N/A

S/N: N/A

Year: N/A

Department: Nebraska Forest Service

Contact: Andrew Zahn, azahn3@unl.edu, 402-296-6046

Price (negotiable)\$: 1,000.00

Cost object: 22-6553-0003

Address: 2106 Horning Road, Plattsmouth, NE, 68048

Pickup instructions: contact Andrew Zahn



6, 7, & 8. Hay racks - \$50 each Three old hay racks in various conditions. One of the three would be a great replacement parts rack (see rack 10). The other two have all four wheels and roll freely.

6. Hay Rack

Condition: Good , not recently used

Damage: flat tire

Make: Electric Wheel Co.

Model: 650

S/N: J-183532

Year: Unknown,

Department: Nebraska Forest Service

Contact: Andrew Zahn, azahn3@unl.edu, 402-296-6046

Price (negotiable): \$50.00

Cost object: 22-6553-0003

Address: 2106 Horning Road, Plattsmouth, NE, 68048

Pickup instructions: contact Andrew Zahn

7. Hay rack

Condition: Fair not recently used

Damage: flat tire, worn deck

make: Electric Wheel Co.

model: 650

S/N: J-281208,

Year: Unknown

Department: Nebraska Forest Service

Contact: Andrew Zahn, azahn3@unl.edu, 402-296-6046

Price (negotiable): \$50.00

Cost object: 22-6553-0003

Address: 2106 Horning Road, Plattsmouth, NE, 68048

Pickup instructions: contact Andrew Zahn

8. Hay rack

Condition: Poor, not recently used

Damage: 2 missing/damaged wheels, damaged missing deck boards

Make: Unknown

model: Unknown

S/N: Unknown

Year: Unknown

Department: Nebraska Forest Service

Contact: Andrew Zahn, azahn3@unl.edu, 402-296-6046

Price: (negotiable): \$50.00

Cost object: 22-6553-0003

Address: 2106 Horning Road, Plattsmouth, NE, 68048

Pickup instructions: contact Andrew Zahn

RACK 6



RACK 7



RACK 8



9. Danuser Digger 3-point auger

Condition: Very Good, used 2011-2015

Damage: none

make: Danuser Digger

model: F-8,

S/N: 080278

Year: Unknown

Department: Nebraska Forest Service,

Contact: Andrew Zahn, azahn3@unl.edu, 402-296-6046,

Price (negotiable): \$1500.00

Cost object: 22-6553-0003,

Address: 2106 Horning Road, Plattsmouth, NE, 68048,

Pickup instructions: contact Andrew Zahn



10. Caldwell Manta Ray 16 HW 67 batwing rotary mower

Condition: Fair, not recently used

Damage: one damaged tire, missing PTO shaft

Make: E.L. Caldwell & Sons, INC.

Model: 16HW67, S/N: 1339

Year: 1967

Department: Nebraska Forest Service

UNL inventory tag number: N/A

Contact: Andrew Zahn azahn3@unl.edu, 402-296-6046

Price (negotiable): \$1500.00

Cost object: 22-6553-0003

Address: 2106 Horning Road, Plattsmouth, NE, 68048

Pickup instructions: contact Andrew Zahn



