Invoice # 4-1-19

WATER SERVICES FOR MARCH, 2019

TO Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|--|---|------|------------------------|------------|
| MAR. 2019 | Management Fee For Water Operations | 1 | \$250.00 | \$250.00 |
| | Bacterial Water Sample (TCEQ) | 1 | \$30.00 | \$30.00 |
| | Number of Customers for operations, billing, mailing, and collecting. | 227 | 15.00/ Per meter | \$3,405.00 |
| | Rescind Boil Water notices/printed and mailed | 227 | \$2.80 | \$635.60 |
| | | | | |
| | | | - 10 10 | |
| hand and a second s | | | ** | |
| | SUBTOTAL | | · · | \$3,685.00 |
| | ADDITIONAL FEES | | | \$635.60 |
| | TOTAL | | | \$4,320.60 |

-

Invoice # 4-1-19

WATER SERVICES FOR MARCH, 2019

то

Las Palomas Water Service Company Receiver Donald Rauschuber

| | DESCRIPTION | l | QTY. | RATE | TOTAL |
|-----------|---|--------------------|------|------------------------|------------|
| MAR. 2019 | Management Fee For Water | Operations | 1 | \$250.00 | \$250.00 |
| | Bacterial Water Sample (TCE | EQ) | 1 | \$30.00 | \$30.00 |
| | Number of Customers for op mailing, and collecting. | erations, billing, | 227 | 15.00/ Per meter | \$3,405.00 |
| | Rescind Boil Water notices/ | printed and mailed | 227 | \$2.80 | \$635.60 |
| | | · | | | |
| | | SUBTOTAL | | <u> </u> | \$3,685.00 |
| 4Y | 9r | ADDITIONAL FEES | | | \$635.60 |
| dan | | TOTAL | | | \$4,320.60 |
| LPW | D Lk Na ZZSB Sc Receiver Project f-5-19 | | | | |

| | 2258 |
|--|---|
| DONALD G. RAUSCHUBER AND ASSOCIATES INC. P.O. BOX 342707 AUSTIN, TX 78734-0046 | -5-1932-61/1110 |
| PAY TO THE ORDER OF DLIL Wat a CO. LLC | \$4,320 <u>60</u> |
| fourthoused threehand furning delling and the | DOLLARS DELLARS DELLARS |
| JPMorgan Chase Bank, N.A. www.Chase.com FOR INDALI-1-19 LPWSL-Teccium | |
| | nan an |

.

•

2111111

.

2

. .

a second s

i

Invoice # 4-1-19B

WATER SERVICES FOR MARCH, 2019

To Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|-----------|--|--------------|--------------------------|----------------------|
| MAR. 2019 | | | | |
| 3/9/2019 | Met with backhoe contractor and located water mains at: - 156 Lakeview Circle - 756 Lake Valley - 705 Sunrise | 7hrs | \$40.00/hr | \$280.00 |
| 3/14/2019 | Replaced meter at 181 Champions Blvd and repaired leak at meter. | | | \$145.00 |
| 3/14/2019 | Fixed leak at 151 Champions Blvd. - Replaced meter washers. Worked with contractor | | | \$75.00 |
| 3/21/2019 | Boring 756 Lake Valley Dr. and installing a meter box. Installed Tap on 6" water main for 705 Sunrise | 10hrs | \$35.00/hr | \$350.00 |
| 3/22/2019 | Purchase of 12" Tap Saddle and 6" Tap saddle for 156 Lakeview Circle. (Parts) - Tapped 6" main at 156 Lakeview Circle and found | | | \$435.00 |
| | that main had no water. Located Neighbor's meter and dug up service line to locate 12" water main. (labor) | 10.5 hrs | \$25.00/hr | \$262.50 |
| 3/24/2019 | Finished tap saddles and locating 12" service lines at 156 Lakeview. All work was hand dug. Labors: - Senior Operator - Helper | 5hrs 5hrs | \$50.00/hr \$25.00/hr | \$250.00 \$125.00 |
| | | | | |
| | SUBTOTAL | | | \$1,922.50 |
| | ADDITIONAL FEES | | | |
| | TOTAL | | | \$1,922.50 |

Invoice # 4-1-19B

WATER SERVICES FOR MARCH, 2019

To Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE MAR. 2019 | DESCRIPTION | QTY. | RATE | TOTAL |
|-------------------|--|--------------|--------------------------|----------------------|
| 3/9/2019 | Met with backhoe contractor and located water mains at: | 7hrs | \$40.00/hr | \$280.00 |
| 3/14/2019 | Replaced meter at 181 Champions Blvd and repaired leak at meter. | | | \$145.00 |
| 3/14/2019 | Fixed leak at 151 Champions Blvd. - Replaced meter washers. Worked with contractor | | | \$75.00 |
| 3/21/2019 | Boring 756 Lake Valley Dr. and installing a meter box. Installed Tap on 6" water main for 705 Sunrise | 10hrs | \$35.00/hr | \$350.00 |
| 3/22/2019 | Purchase of 12" Tap Saddle and 6" Tap saddle for 156 Lakeview Circle. (Parts) - Tapped 6" main at 156 Lakeview Circle and found | 10.5 hrs | \$25.00/hr | \$435.00 \$262.50 |
| | that main had no water. Located Neighbor's meter and dug up service line to locate 12" water main. (labor) | 10.5 ms | \$25.007hr | \$202.50 |
| 3/24/2019 | Finished tap saddles and locating 12" service lines at 156 Lakeview. All work was hand dug. Labors: - Senior Operator - Helper | 5hrs 5hrs | \$50.00/hr \$25.00/hr | \$250.00 \$125.00 |
| L <u>a</u> | SUBTOTAL | | | \$1,922.50 |
| | ADDITIONAL FEES | | | |
| | TOTAL | | | \$1,922.50 |

Invoice # 5-1-19B

WATER SERVICES FOR APRIL, 2019

To: Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|---------|--|-----------------------------|---|---|
| April | Work Order #110 | | | |
| 2019 | Water break on 2" Gate Valve at Sunrise and Lake Valley | | | |
| 4/16/19 | Replace 2" Gate Valve and repair. Had to shut the system off due to not being able to locate shut off valve. Senior Operator Utility Operator Laborer Trash pump for Lake Parts: 2" Gate Valve, 2" Nipple, 2" Comp. Coupling, 2" pipe, 4 bass of connector, 1 Meter box Total: | 6 hr 6 Hr 6 hr 4hr | \$50/ hr \$40/ hr \$20/ hr \$15/hr \$180.00 | \$300.00 \$240.00 \$160.00 \$60.00 \$180.00 \$940.00 |
| 4/16/19 | Work Order# 108 2" Tap on Sunrise Located 2" line for new customer on Sunrise. Dug up and made Tap Senior Operator Utility Operator Tap saddle and parts (box and tubing) | 5hr 5hr | \$50/hr \$25/ hr \$285.00 | \$250.00 \$125.00 \$285.00 \$660.00 |
| 4/17/19 | Work Order #532073 Pulled meter per customer request - 203 Champions Blvd - 184 Lake Valley Cir - 164 Champions Blvd (?) Total: | | \$50.00 \$50.00 \$50.00 | \$50.00 \$50.00 \$50.00 \$150.00 |

PAID: LANGE # 1012

Invoice # 5-1-19B

WATER SERVICES FOR APRIL, 2019

| 4/17/19 | Work Order # 53 2075 Tried to Locate meter for installation. Customer will mark Location. - 128 Lake View | N/C | N/C | N/C |
|---------|--|-------------------|-------------------------------|----------------------------------|
| 4/17/19 | Work Order #532077 Low pressure complaint at 122 Champions Blvd. Notified customer to contact builder as it was a home owner's issue. House pressure: 47psi. Neighbor Pressure: 80 psi - Operator - Laborer Total | 1.5 hr 1.5 hr | \$50/hr \$20/hr | \$ 75.00 \$30.00 \$105.00 |
| 4-17-19 | Work Order #532078 Had dug up water mains at Lake Valley Dr and Lake view Circle looking for gate valve and 12" main. Located the valve near fence and found old abandoned 6" main (All hand dug) - Senior Operator - Utility Operator - Laborer Total | 5hr 5hr 5hr | \$50/hr \$30/hr \$20/hr | \$250.00 \$150.00 \$100.00 |
| | ADDITIONAL FEES | | | \$500.00 \$2355.00 |
| | TOTAL | | | \$2,355.00 |

| | LAS PALOMAS WATER SERVICES COM DONALD RAUSCHUBER, RECEIVER PO BOX 342 707 AUSTIN, TX 78734-0000 | | 1012 30-9/1140 243 CHECK ADMON |
|-----|--|--------------------|---|
| | Frost | iv dellars and the | DOLLARS |
| FOR | Inoue No. 5-1-193 | | |

.

.

. .

•

,

2

Invoice # 5-1-19

WATER SERVICES FOR APRIL, 2019

то

Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|-------------|---|------|------------------------|------------|
| APRIL, 2019 | Management Fee For Water Operations | 1 | \$250.00 | \$250.00 |
| | Bacterial Water Sample (TCEQ) | 1 | \$30.00 | \$30.00 |
| | Number of Customers for operations, billing, mailing, and collecting. | 227 | 15.00/ Per meter | \$3,405.00 |
| | | | | |
| | | | | |
| | | | | |
| | SUBTOTAL | | | \$3,685.00 |
| | ADDITIONAL FEES | | | |
| | TOTAL | | | 3,685.00 |

PARO LAWSC # 100 1011

Invoice # 5-1-19

WATER SERVICES FOR APRIL, 2019

то

Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|-------------|---|------|------------------------|------------|
| APRIL, 2019 | Management Fee For Water Operations | 1 | \$250.00 | \$250.00 |
| | Bacterial Water Sample (TCEQ) | 1 | \$30.00 | \$30.00 |
| | Number of Customers for operations, billing, mailing, and collecting. | 227 | 15.00/ Per meter | \$3,405.00 |
| | | | | |
| | | | | |
| | | | | |
| | SUBTOTAL | | ± | \$3,685.00 |
| | ADDITIONAL FEES | | | |
| | TOTAL | | | 3,685.00 |

| 4 | LAS PALOMAS WATER SERVICES COMPANY DONALD RAUSCHUBER, RECEIVER PO BOX 342 707 AUSTIN, TX 78734-0000 DATE S-20-19 | 1011 30-9/1140 243 |
|-----|---|--------------------------|
| 2 | PAY TO THE OF DLT WATER W. <u>Hare thousand subundant eighty fire delay and too</u> Frost | JOLLARS C BARANDE |
| FOR | www.frostbank.com | |

•

,

•

-

1

.

•

•

.

2

•

Invoice # 6-1-19

WATER SERVICES FOR MAY, 2019

1

то

Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|-----------|--|------|------------------------|------------|
| May, 2019 | Management Fee For Water Operations | 1 | \$250.00 | \$250.00 |
| | Bacterial Water Sample (TCEQ) | 1 | \$30.00 | \$30.00 |
| | Number of Customers for operations, billing, mailing, and collecting. | 227 | 15.00/ Per meter | \$3,405.00 |
| | | | | |
| | | | | |
| | SUBTOTAL | | I | \$3,685.00 |
| | ADDITIÕNAL FEES | | | · |
| | TOTAL | | | 3,685.00 |

Pran the lorg

DLR WATER CO. 301 MAIN

Invoice # 6-2-19

.

WATER SERVICES FOR MAY, 2019

PLAZA BOX #367 NEW BRAUNFELS, TX.78130 watertexasyahoo.com

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|-------------|--|------|------------|----------|
| May 2019 | | | | |
| 5/15/19 | Work Order #205 Install Water at 151 Champions Blvd | | \$100.00 | \$100.00 |
| 5/15/19 | Work Order# 206 Install Water at 149 Champions Blvd | | \$100.00 | \$100.00 |
| 5/15/19 | Work Order #207 Install Water at 218 Champions Blvd | | \$100.00 | \$100.00 |
| ······· | · · · · · · · · · · · · · · · · · · · | | Sub Total | \$300.00 |
| | | | Additional | \$0.00 |
| | | | Total | \$300.00 |

RULD H 1019

| 4 | LAS PALOMAS WATER SERVICES COMPANY DONALD RAUSCHUBER, RECEIVER PO BOX 342 707 AUSTIN, TX 78734-0000 DATE | 1019 30-9/1140 243 CHECK MMB |
|-----|--|---------------------------------------|
| | Threathousenderghte fine dollars 1 100 | BS985 C |
| FOR | Frost www.frostbank.com | |

.

-

.

×

.

;

Invoice # 5-1-19

WATER SERVICES FOR APRIL, 2019

то

Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|-------------|---|------|------------------------|------------|
| APRIL, 2019 | Management Fee For Water Operations | 1 | \$250.00 | \$250.00 |
| | Bacterial Water Sample (TCEQ) | 1 | \$30.00 | \$30.00 |
| | Number of Customers for operations, billing, mailing, and collecting. | 227 | 15.00/ Per meter | \$3,405.00 |
| | | | | |
| | | | | |
| | . SUBTOTAL | | | \$3,685.00 |
| | ADDITIONAL FEES | | | |
| | TOTAL | | | 3,685.00 |

Invoice # 5-1-19B

WATER SERVICES FOR APRIL, 2019

To: Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|---------------|--|-----------------------------|---|---|
| April 2019 | Work Order #110 | | | |
| 4/16/19 | Water break on 2" Gate Valve at Sunrise and Lake Valley Replace 2" Gate Valve and repair. Had to shut the system off due to not being able to locate shut off valve. Senior Operator Utility Operator Laborer Trash pump for Lake Parts: 2" Gate Valve, 2" Nipple, 2" Comp. Coupling, 2" pipe, 4 bass of connector, 1 Meter box | 6 hr 6 Hr 6 hr 4hr | \$50/ hr \$40/ hr \$20/ hr \$15/hr \$180.00 | \$300.00 \$240.00 \$160.00 \$60.00 \$180.00 \$940.00 |
| 4/16/19 | Work Order# 108 2" Tap on Sunrise Located 2" line for new customer on Sunrise. Dug up and made Tap Senior Operator Utility Operator Tap saddle and parts (box and tubing) | 5hr 5hr | \$50/hr \$25/ hr \$285.00 | \$250.00 \$125.00 \$285.00 \$660.00 |
| 4/17/19 | Work Order #532073 Pulled meter per customer request - 203 Champions Blvd - 184 Lake Valley Cir - 164 Champions Blvd (?) Total: | | \$50.00 \$50.00 \$50.00 \$50.00 | \$50.00 \$50.00 \$50.00 \$150.00 |

Invoice # 5-1-19B

WATER SERVICES FOR APRIL, 2019

| 4/17/19 | Work Order # 53 2075 Tried to Locate meter for installation. Customer will mark Location. - 128 Lake View | N/C | N/C | N/C |
|---------|--|-------------------|-------------------------------|----------------------------------|
| 4/17/19 | Work Order #532077 Low pressure complaint at 122 Champions Blvd. Notified customer to contact builder as it was a home owner's issue. House pressure: 47psi. Neighbor Pressure: 80 psi - Operator - Laborer Total | 1.5 hr 1.5 hr | \$50/hr \$20/hr | \$ 75.00 \$30.00 \$105.00 |
| 4-17-19 | Work Order #532078 Had dug up water mains at Lake Valley Dr and Lake view Circle looking for gate valve and 12" main. Located the valve near fence and found old abandoned 6" main (All hand dug) - Senior Operator - Utility Operator - Laborer Total | 5hr 5hr 5hr | \$50/hr \$30/hr \$20/hr | \$250.00 \$150.00 \$100.00 |
| | ADDITIONAL FEES | | | \$500.00 \$2355.00 |
| | TOTAL | | | \$2,355.00 |

| | LAS PALOMAS WATER SERVICES COMP DONALD RAUSCHUBER, RECEIVER PO BOX 342 707 AUSTIN, TX 78734-0000 | DATE 10-01-19 | 1052 30-9/1140 243 €CHECK MMMS |
|---------------------------------------|---|---------------|---|
| | PAY TO THE ORDER OF DLR WASBER Company chethone and four hadre Otwasty nine dall | | HARS DE Photo |
| 4८५ ५८ ^{FOR_} ५७ ५१ | 42.4 170.00 | | <u>}</u> |

.

;

| T8745 involce for services | adams. | carbonless | • 3-part • numbered |
|---------------------------------------|----------------------|---|---------------------|
| LR WATE GO. | | | |
| 501 main 1/20 # 367 | | INAOICI | END. 464214 |
| N. B. 7× 78130 | | | |
| Цто | SERVICE PERFORMED AT | 0 | Invoice |
| Loha Volly Water Los Palomas he | ADDRESS | 9-19-19 | |
| Los Palómas he | > C CITY, STATE, ZIP | | W |
| | | | |
| customer order no. Sold by | TERMS | | DATE |
| | | | |
| 113 Turn & | Jerry Dr. Act 7 | 28 | |
| Tim Bico, | Dermy Dr. Act 7 | | |
| / | | | |
| Alad to Dis | up + Rephee has | ta Pheete | |
| + BOX Due | to Cistone Lomphi | X- | |
| | 11 | | |
| | parts & mater | | 75 01 |
| | MATS & Mount | | .950 |
| · · · · · · · · · · · · · · · · · · · | | | |
| | | | *** *** |
| | | Tests 1 | 1700 |
| Rin actions: NCTE745 | | <u>1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.</u> | 01 |

PAID 1052

.

| 18745 invoice for services | adams [.] | carbonless • 3-part • numbered |
|---|---|--------------------------------|
| La lista 6. 201 mai Phro #367 N.B. TX 78130 | | INVOICE NO. 464215 |
| LT0 ; O · I | SERVICE PERFORMED AT | Invoice |
| Los Palomos lis | C 165 ADDRESS | -4-19 |
| FY, STATE, ZIP | CITY, STATE, ZIP | -4-19 |
| USTOMER ORDER NO. SOLD BY | TERMS | DATE : |
| lack a Sau | rice Value on | |
| na . | | , |
| Dur -un 1" Som | rice Like & Tune f Corb-Stop. VALLE + PUC fikin 165 of Parts | |
| Unter off a | f Corb-Stop. | |
| thep beed 74 | VALLE + PVC Liki | |
| + Bross Nipp | 165 A PAS | Pats - 125 00 |
| | Labor- | |
| | U the c | 2500/14 100 00 |
| | 4 the c y the | 35.au/H 14000 |
| · · · · · · · · · · · · · · · · · · · | | |
| | | ap 365 00 |
| | | |

.....

MALE

-1

1

PARO IUSZ

| DIR hota E | | 🤃 adams | carbonless • | 3-part∙numbere |
|---|-----------------------------------|---|--------------|------------------|
| 301 min ph N. B TX 7813 | | | IMOKE N | . 454216 |
| /////////////////////////////////////// | | | | Invoice |
| Los Palo. | mas Wsi | SERVICE PERFORMED AT | Merica | Lui |
| ADDreas | | ADORESS | G-12-19 | |
| CITY, STATE, ZIP CLISTOMER ORDER NO. | | CITY, STATE, ZP | | DATE |
| CUSTOMEN UNDER MU. | SOLD BY | TERMS | | DAIE |
| Had Acros Debai | Drs 2 X 55 Street. 14 1" Se | Service hire in our Fre-off Ulta on Joes ted Corp-Styr mic Like from parts. X6 Astar X6 Astar X6 Astar | , | " 199 U 560 0 |
| | 25 .0 Hr | V6 lstur | | 500 |

| Zol MAIL N.B. TV | Ja Co. 11 Haza H367 78130 | | NVOICE NO. | 4642 |
|---------------------|---------------------------------|----------------------|---------------|-------|
| (BILL TO) | | SERVICE PERFORMED AT | | Inv |
| ADDRESS DO | lomos lusc | | <u>9-28-A</u> | |
| CITY, STATE, ZIP | | CITY, STATE, ZIP | - Phrt. | ····· |
| CUSTOMER ORDER NO. | SOLD BY | TERMS | DA | TE |
| • • | / | David Tillary | | |

,

-

Scanned with CamScanner

Invoice # 11-1-19

WATER SERVICES FOR OCTOBER, 2019

R

то

Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | , RATE | TOTAL |
|------------|---|------|------------------------|------------|
| Oct., 2019 | Management Fee For Water Operations | 1 | \$250.00 | \$250.00 |
| | Bacterial Water Sample (TCEQ) | 1 | \$30.00 | \$30.00 |
| | Number of Customers for operations, billing, mailing, and collecting. | 227 | 15.00/ Per meter | \$3,405.00 |
| | | | | |
| | | | | |
| | SUBTOTAL | | | \$3,685.00 |
| | ADDITIONAL FEES | | | |
| | TOTAL | | | 3,685.00 |

,

JAND 12 3685 11/2/19

| LAS PALOMAS WATER SERVICES COMPANY | 1063 |
|---|------------------|
| DONALD RAUSCHUBER, RECEIVER PO BOX 342 707 | 30-9/1140 243 |
| AUSTIN, TX 78734-0000 DATE 11-2-5 | CHECK ARMON |
| APAY TO THE ORDER OF DLA WATER SETUCES Company \$ | 3,685 00 |
| threathousand six hundred eights five dillers make the | ULLARS Deposite |
| Frost www.frostbank.com | Dalah en had |
| FOR INDICA No. 11-1-19 | |
| | |

.

.

| De a Weta 301 main Dh Neu Besty | 4367 7K | | INVOICE NO. 464229 |
|---------------------------------------|--------------|--------------------------------|--------------------|
| New ISport | | | Invoice |
| BILL TO LAS Palon | was lusc Ree | | an Scrice Like |
| ADDRESS Don 1 | Roischiben | ADDRESS 140 | Las Palomas |
| CITY, STATE, ZIP | | | 23-19 |
| CUSTOMER ORDER NO. | SOLD BY | TERMS | DATE |
| Dug. | Palomas + b | off lectur on Repaired Lest | |
| Tuo | Mer + Truch | Motoria Is Lobor Cotal | 33100 |
| adams' NCT8745 | | | 01-11 |

| (| | |
|-----|---|--|
| | LAS PALOMAS WATER SERVICES COMPANY DONALD RAUSCHUBER, RECEIVER | 1064 |
| 3 | PO BOX 342 707 AUSTIN, TX 78734-0000 DATE 11-2-19 | 30-9/1140 243 |
| 2 | PAY TO THE DLR WATOR SORUL COMPANY | میں پیرون 2,924 میں |
| | two thousand nince hudged timenty four dallars and Too | DOLLARS |
| FOR | FIOST 444230 980.00 www.frostbank.com | \bigcirc |
| | 464 241 158.00 | nan man di kalan mandala mana kalan di kalan man di kana kalan manan kalan manan manan kalan kalan di kalan ka |

-

.

- --

X~

~

. . . .

| · - / | | | · - | • • | |
|-----------------------|---|-------------------|----------|-------------|---------|
| DLR lista BUI MAIN | - G. phan #367 1-1, 7v 78130 | | | INVOICE NO. | 464230 |
| New pro | , , | | | | Invoice |
| BILL TO AS Paloma | s WSC Recier | SERVICE PERFORMED | Nou l | Ucto 7 | TAD . |
| ADDRESS Der / | la use Lubar | ADDRESS | 169 Los | | Circle |
| CITY, STATE, ZIP | | CITY, STATE, ZIP | 10-1 | 2-2019 | |
| CUSTOMER ORDER NO. | SOLD BY | TERMS | | DATE | |
| Jen | Aste Man Late View My Little. 1" Top 2 T enrice Line, M | | <u>-</u> | | 3300 |
| · · · · | | Lobu | | | 650 0 |
| adams NCT8745 | | Total | | - | 980 0 |

_

ł

•

| DER W. | star Company | | | | | | • |
|----------------------------|---|-------------------------|---------|-----------|---------|-----------|-----|
| 301 ma | in Phzo 367 | | | INVOICE M | 10. 4 | 6423 | 31 |
| New BR | w-Ry TX 78130 | | | | | | |
| BILL TO | | SERVICE PERFORMED AT | 111 | , , / | | Invoi | ce |
| ADDRESS | Valomos USC Recience | ADDRESS | Va lley | | ~ | | e |
| A M. | Don Rauschuber | 819 CITY, STATE, ZIP | Mackly | bird | Is | <u>ve</u> | |
| | | 1 | 0-13-20 | 9/9 | | | |
| CUSTOMER ORDER NO. | SOLD BY | TERMS | | | DATE | | |
| | Busted Mater & Less 819 Mocking bild Lance Acphend Marta & Reg. Ch Service Like Materials | , aired he | shi . | · · · | · · · · | 90 | ØC |
| | 2050 | · · · · · · · | | ~ | | 95 | 0c |
| | | Total | • • | - | | 185 | 01 |
| adams ⁻ NCT8745 | Warmen | | | L | | | 01- |

. ...

| DLA Likte G. 301 min Phra #367 New Brath, 7x 78130 | | INVOI | се NO. Ц | 6423 | 34 |
|--|------------------|---|----------|-------|----|
| BILL TO LAS Palamas Jusc Recievo | SERVICE PERFORME | la lista Tog | ก | Invoi | ce |
| ADDRESS Dur RAuschuber | ADDRESS | 501 Blue Bon | | , | |
| | CITY, STATE, ZIP | 10-9-19 | | | |
| CUSTOMER ORDER NO. SOLD BY | TERMS | | DATE | | |
| Installed Now W et SOI Ble Ba 5-F Contractor 6×1" Tap yith & New meter JBa | | | | | |
| n | noteric ls | ••••••••••••••••••••••••••••••••••••••• | | 330 | 00 |
| 4 | labur | | - | 625 | 00 |
| adams ⁻ NCT8745 | Total | | | 955 | |

. . .

.

÷

;

، ۱

·····

| DAR Lesta Ce 301 mail Pl Neu BRAUK | | | • | INVOICE I | vo. Ц | 6423 | 35 |
|--|---|------------------|----------|-----------|-------|------------------|----------|
| | | SERVICE PERFORME | D ATa | | | Invoi | ice |
| LAS Paloma | , use Decie | ve | pesk on | Sori | n I | Luc | <u> </u> |
| ADDRESS Der | household | ADDRESS | 119 Ch | Ampia | ィ | | |
| CITY, STATE, ZIP | | CITY, STATE, ZIP | 10-2 | | | | |
| CUSTOMER ORDER NO. | SOLD BY | TERMS | K. | | DATE | | |
| n Cest | on Sarice Champilars, tone Comple Samo Like doff US | ant " | <u>.</u> | | | 105 | |
| 3.5140 | + Truch 35 # 25.00 = K 35.00 | 5 Hrs | | ~ | | 87 122 315 | 57 |

. ł

11

| XR Ubta Co. 301 MAN PH2 New Brule | a [~] 367 | | INVOIO | _{ce no.} 4 | 6424 Invoid |
|---|--------------------|----------------------|-------------------------|--|----------------|
| | | SERVICE PERFORMED AT | Λ | | |
| DDRESS Dalomo | as USC Sheeter | ADDRESS 7.90 | Inko 1 | h lli | |
| HTY, STATE, ZIP | | CITY, STATE, ZIP | U-30-19 | <u> </u> | |
| CUSTOMER ORDER NO. | SOLD BY | TERMS | | DATE | |
| | | | | 1 | |
| Replace | e cista metr | · · · · · · · | · · · · · · · · · · · · | | 0.7 |
| Replace Deplace | | · · · · · · · | | - | 83 |
| Replace Replace | | sterial sterial | | - - - - - - - - - - | 83 |
| Replac Deplace | | · · · · · · · | | | |

مردومه

| | LAS PALOMAS WATER SERVICES COMPANY DONALD RAUSCHUBER, RECEIVER PO BOX 342 707 AUSTIN, TX 78734-0000 DATE 11-2-19 | 1064 30-9/1140 243 €CHECK AMMEN |
|-----|--|---|
| FOR | PAY TO THE OF DER WARDER SORIE & COMPANY TURTHURDER OF DER HULF O FENENT, for dallars ut Too HURERA 331.00 HURERA 44.00 HURERA 331.00 HURERA 44.00 HURERA 45.00 HURERA 44.00 HURERA 45.00 HURERA 44.00 HURERA 45.00 HURERA | DOLLARS DE Photo Seie crite Dellars De Photo Seie crite Dellars |

.

.

. · ·

.

Invoice # 2-1-19

WATER SERVICES FOR FEBURARY, 2019

TO Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|-----------|---|-------|------------------------|------------|
| FEB. 2019 | Management Fee For Water Operations | 1 | \$250.00 | \$250.00 |
| | Bacterial Water Sample (TCEQ) | 2 | \$30.00 | \$60.00 |
| | Setting up computer billing data and working on customer accounts. | 25hrs | \$300.00 | \$300.00 |
| | Number of Customers for operations, billing, mailing, and collecting. | 222 | 15.00/ Per meter | \$3330.00 |
| | Outside contractor needed (See attached invoices) | | | \$1000.00 |
| | Changed Locks for gate | | 75.00 | 75.00 |
| | Installed meter | 1 | 135.00 | 135.00 |
| | | | | • |
| | SUBTOTAL | | | \$3640.00 |
| | ADDITIONAL FEES | | | \$1,510.00 |
| | TOTAL | | | \$5150.00 |
| | ADDITIONAL FEES TOTAL | '~ | | |

Invoice



Bill To Las Palamos Water Company P.O. Box 342707 Austin, Tx 78734 Donald Rauschuber

| Dat | e | Invoice No. | P.O. Number | Terms | Project |
|-------|-----|-------------|-------------|----------------|---------|
| 02/04 | /19 | 620 | | Due on receipt | |

| ltem | Description | Quantity | Rate | Amount |
|----------------|--|----------|-----------|----------|
| 03 Excavation | Emergency Leak Repair @ 129 Merion Ln. Break | | | 0.00 |
| | Caused by Gvec Contractor. Had to Shut off Water | | | |
| | & Repair Break. Also Repaired Customer Line | | | |
| Equipment | Equipment Operator | 7 | 60.00 | 420.00 |
| Operator | | | | |
| Laborer | Laborer | 7 | 20.00 | 140.00 |
| Parts | 1" Parts for Service line & Customer line | | 121.00 | 121.00 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | Subtotal | \$681.00 |
| - 10 | gra | | Sales Tax | \$0.00 |
| Paid | # 2248 | | Total | \$681.00 |
| Chee Paid i | 3^{ra} 3^{r | | | |

Invoice

Bill To Las Palamos Water Company P.O. Box 342707 Austin,Tx 78734 Donald Rauschuber

| Date | Invoice No. | P.O. Number | Terms | Project |
|----------|-------------|-------------|----------------|---------|
| 02/05/19 | 621 | | Due on receipt | |

| ltem | Description | Quantity | Rate | Amount |
|---|---|----------|----------------|----------|
| 03 Excavation | Excavated and repaired water service line @ 126 | | | 0.00 |
| | Champions Blvd | | | |
| Equipment | Equipment Operator | 6.5 | 60.00 | 390.00 |
| Operator | | | | |
| Laborer | Laborer | 6.5 | 20.00 | 130.00 |
| Parts | Parts for Service line repair | | 105.00 | 105.00 |
| Parts | Meter | 1 | 85.00 | 85.00 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | Subtotal | \$710.00 |
| Dara Dara | | | Sales Tax | \$0.00 |
| Paid Dgra Check # 2248 Paid in full | | | Total \$710.00 | |

3-8-19

Invoice



Bill To Las Palamos Water Company P.O. Box 342707 Austin, Tx 78734 Donald Rauschuber

| Date | Invoice No. | P.O. Number | Terms | Project |
|----------|-------------|-------------|----------------|---------|
| 02/05/19 | 622 | | Due on receipt | |

| Item | Description | Quantity | Rate | Amount |
|---------------|--|----------|-----------|--|
| 03 Excavation | Excavated and repaired service line leak and | | | 0.00 |
| | replaced valve on service line @ 136 los palamos | | | |
| Equipment | Equipment Operator | 5.5 | 60.00 | 330.00 |
| Operator | | | | |
| Laborer | Laborer | 5.5 | 20.00 | 110.00 |
| Parts | | | 85.00 | 85.00 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | Subtotal | \$525.00 |
| | | | | |
| | | | Sales Tax | \$0.00 |
| | | - | | ······································ |

Total

\$525.00

3-8-19

Invoice



Bill To Las Palamos Water Company P.O. Box 342707 Austin,Tx 78734 Donald Rauschuber

| Date | Invoice No. | P.O. Number | Terms | Project |
|----------|-------------|-------------|----------------|---------|
| 02/06/19 | 623 | | Due on receipt | |

| Item | Description | Quantity | Rate | Amount |
|---------------------|--|----------|--------------|--------------|
| 03 Excavation | Excavated and exposed water line @ 121 | | | 0.00 |
| | champions blvd. Chased line for several days and | | | |
| | uncovered appox 400 ft of water line and were | | | |
| | unable to find leak. 2/6-2/10 | | | |
| Equipment | Equipment Operator | 35 | 60.00 | 2,100.00 |
| Operator | | 05 | 00.00 | 700.00 |
| Laborer | Laborer | 35 | 20.00 | 700.00 |
| 29 Supervision | David Sr Outside Operator | 10 | 0.00 0.00 | 0.00 0.00 |
| Outside Operator | Outside Operator | 6 | 0.00 | 0.00 |
| Operator | | | | |
| | | | | |
| | | | | : |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| <u> </u> | | <u> </u> | Outstatel | <u> </u> |
| | | | Subtotal | \$2,800.00 |
| Paid Da | ra D | | Sales Tax | \$0.00 |
| clack H | ra DZ \$ 2248 3-8-19 full | | Total | \$2,800.00 |
| Charles . | | | | |
| faid in | tull | | | |
| • | | | | |

Invoice

DLR Water Co 301 Main Plz #367 New Braunfels, Tx 78130

> Bill To Las Palamos Water Company P.O. Box 342707 Austin, Tx 78734 Donald Rauschuber

| Date | Invoice No. | P.O. Number | Terms | Project |
|----------|-------------|-------------|----------------|---------|
| 02/18/19 | 624 | | Due on receipt | |

| ltem | Description | Quantity | Rate | Amount |
|------------------------------|---|-----------|-----------|----------------|
| 03 Excavation | Excavated & exposed discharge line from filters @ water plant. Work on gate valves & butterfly valves to stop water leakage. Located Electric Line from main light pole to main well. Work Preformed on 2-18-19 & 2-19-2019 | | | 0.00 |
| Equipment | Equipment Operator | 11.5 | 60.00 | 690.00 |
| Operator | | 44 5 | 00.00 | 000.00 |
| Laborer 29 Supervision | Laborer David Wallace Sr. | 11.5 6 | 20.00 | 230.00 0.00 |
| | | | | |
| | | | Subtotal | \$920.00 |
| Paid in | full | | Sales Tax | \$0.00 |
| Paid in Dgra c Paidinf | herek the Del | | Total | \$920.00 |
| Paid in f | herskitt Del 2048 2-8-19 | | | |

Invoice

DLR Water Co 301 Main Plz #367 New Braunfels, Tx 78130

| Date | Invoice No. | P.O. Number | Terms | Project |
|----------|-------------|-------------|----------------|---------|
| 02/15/19 | 625 | | Due on receipt | |


| ltem | Description | Quantity | Rate | Amount |
|--------------|--|----------|-----------|------------|
| 22 Specialty | Removed & Installed new boster pump & Replaced | | | 0.00 |
| | old gate valves & Replaced check valves. Had to | | | |
| | shut down water system to do repairs. Had to bring | | | |
| | system pressure back to normal operating pressure. | | | |
| | Work preformed on 2-15-19 & 2-16-19 | | | |
| Equipment | Equipment Operator | 13.5 | 50.00 | 675.00 |
| Operator | | | | |
| Laborer | Laborer | 13.5 | 20.00 | 270.00 |
| Parts | Parts bought by D.L.R Water : 2-New check valves | 1 | 125.00 | 125.00 |
| Parts | 2" galv fittings extra | 1 | 99.00 | 99.00 |
| Outside | Outside contractor needed to wire pump & help shut | | | |
| Operator | down water system. See Attached Invoice | | | |
| | Rano dopen #ZZ400 | | | |
| | | | Subtotal | \$1,169.00 |
| <u> </u> | _ | | Sales Tax | \$0.00 |
| | \sum | | Total | \$1,169.00 |



DLR Water Co 301 Main Plz #367 New Braunfels, Tx 78130 Invoice

| Date | Invoice No. | P.O. Number | Terms | Project |
|----------|-------------|-------------|----------------|---------|
| 02/06/19 | 626 | | Due on receipt | |

| ltem | Description | Quantity | Rate | Amount |
|--------------|--|----------|-----------|----------|
| 12 Doors and | Doors and Trim: Replaced Door and Cleaned up | | | 0.00 |
| Trim | Pump house | | | |
| Equipment | Equipment Operator | 4 | 60.00 | 240.00 |
| Operator | | | | |
| Laborer | Laborer | 4 | 20.00 | 80.00 |
| Parts | New door & Larger Hinges & Larger screws bought by Dlr water | 1 | 250.00 | 250.00 |
| | PARO ÖSTE HEZZHAG | | | |
| | | ξ | Subtotal | \$570.00 |
| | | 5 | Sales Tax | \$0.00 |
| | | r | Total | \$570.00 |



Invoice

DLR Water Co 301 Main Plz #367 New Braunfels, Tx 78130

-

| Date | Invoice No. | P.O. Number | Terms | Project |
|----------|-------------|-------------|-------|---------|
| 02/08/19 | 627 | | | |

| ltem | Description | Quantity | Rate | Amount |
|---------------|--|----------|-----------|----------|
| 03 Excavation | ExcavatedClub house Leak. Leak Reported by | | | 0.00 |
| | customer riding house by old club house in | | | |
| | subdivision .Dug and was unable to find leak. Also | | | |
| | determined that there is no water to old club house. | | | |
| | Located 3 tap locations & called in locates | | | |
| Equipment | Equipment Operator | 4 | 50.00 | 200.00 |
| Operator | | | | |
| Laborer | Laborer | 4 | 17.00 | 68.00 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | Porto | | | |
| | Paro DGR-2249 | | | |
| | | | | |
| | | | | |
| | | | Subtotal | \$268.00 |
| | Q | | Sales Tax | \$0.00 |
| | 3-8-19 | | Total | \$268.00 |

Invoice

DLR Water Co 301 Main Plz #367 New Braunfels, Tx 78130

| Date | Invoice No. | P.O. Number | Terms | Project |
|----------|-------------|-------------|-------|---------|
| 02/25/19 | 628 | | | |

| Item | Description | Quantity | Rate | Amount |
|--------------|--|----------|-----------|----------|
| 22 Specialty | Specialties: Water Line going into storage tank had | | | 0.00 |
| | split. Had to turn off well & storage tank. Replaced | | | |
| | 3" fitting on gate valve & Pipe & Repair coupling. | | | |
| | Difficult time finding parts | | | |
| Equipment | Equipment Operator | 8 | 50.00 | 400.00 |
| Operator | | 1 | | |
| Laborer | Laborer | 8 | 20.00 | 160.00 |
| Parts | 3" Fittings | 1 | 125.00 | 125.00 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | Para den # 2240 | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| · | | | Subtotal | \$685.00 |
| | $\bigcap_{\alpha} 1$ | | Sales Tax | \$0.00 |
| | Kon | | Total | \$685.00 |

3-8-19

DLR Water Co 301 Main Plz #367 New Braunfels, Tx 78130 Invoice

Bill To Las Palamos Water Company P.O. Box 342707 Austin,Tx 78734 Donald Rauschuber

| Date | Invoice No. | P.O. Number | Terms | Project |
|----------|-------------|-------------|-------|---------|
| 02/11/19 | 629 | | | |

3-8-69

| ltern | Description | Quantity | Rate | Amount |
|---------------|---|----------|-----------|----------|
| 03 Excavation | Excavation: Fixed bad service line leak . Had to | | | 0.00 |
| | repair both service lines damaged. Had to replace | | | |
| | meter | | | |
| Equipment | Equipment Operator | 6.5 | 50.00 | 325.00 |
| Operator | | | | |
| _aborer | Laborer | 6.5 | 20.00 | 130.00 |
| Parts | Parts for Repair | 1 | 105.00 | 105.00 |
| Parts | new meter | 1 | 85.00 | 85.00 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | Pakt | | | |
| | Provodire # 2248 | | | |
| | | | | |
| | | S | Subtotal | \$645.00 |
| | () | S | Sales Tax | \$0.00 |
| | at | т | otal | \$645.00 |

nvoice for services adams[.] carbonless · 3-part · numbered C. mai- phio # 367 INVOICE NO. 464210 71 78130 Invoice SERVICE PERFORMED AT lames use Recierce Vo llay ADDRESS 8-22-19 Prossburgen 20-19 CITY, STATE, ZIP 4 W.O 5 SOLD BY TERMS DATE provked a Air Problem at Deptheed Air line at Air Compresson Lacoted Lesk Well site, Laber 175 00 Mats. 82 00 Total 257 01 01 LAS PALOMAS WATER SERVICES COMPANY DONALD RAUSCHUBER, RECEIVER AUSTIN, TX 78734-0000 1047 PAY TO THE ORDER OF DLR WALL DATE 9-10-19 30-9/1140 243 Compre CHECK ARMOR \$ 257 00 Lille no rost DOLLARS DE Sale ww.frostbank.com FOR_ 464210

| ; | - | - |
|---------------------|--|--|
| | | |
| | | |
| | LAS PALOMAS WATER SERVICES COMPANY DONALD RAUSCHUBER, RECEIVER PO BOX 342 707 AUSTIN, TX 78734-0000 DATE | 1046 30-9/1140 243 €CHECK ANNOT |
| A | TO THE OF DLR WATER Conpiny ORDER OF DLR WATER Conpiny three thousand four hudre of three dollars and 73 | \$ 3,40373 |
| ₩ FOR 4 (L4 7 | Frost www.frostbank.com 4 203 (842 0 3) 464 208 (450,00) 464 208 (270.00) 01 (1,336, 73) 4642 0 2 (265,00) 464 213 (240.00) | |

.

· · ·

.

-

.

. (

ŧ

ς.

. ,



.

-

| 1 leve | MAin Pl Bankel | 6, 1920 ⁷ 367 71 78130 | | | INVOICE NO. | 464203 |
|------------------|-------------------|---|-----------------------------|---------|-------------|---------|
| BILL TO | | s lesc hec | SERVICE PERFO | RMED AT | 1/1 | Invoice |
| ADDRESS | Don Ra | wich when | ADDRESS CITY, STATE, ZIF | | - 19 | 7 |
| CUSTOMER ORDER N | łO. | SOLD BY | TERMS | И.д. | <u> </u> | ATE |
| 579 | PArts + Mater | New Tog LAZY QA. Top Soddle | non k Z | " Type | Ponts | 342 0 |
| | Labor | - | | | | |
| | | | | | | |
| · · | | | | · · · · | | |

Para 1046

DLA Usta G. 301 MAIN PHZa # 367 INVOICE NO. 464208 N.B. 7x 78130 Invoice BILL TO SERVICE PERFORMED AT Palamos Use Mecim lo Ila ADDRESS ADDRESS Chause they 8-6-19 8-20-19 CITY, STATE, ZIF CITY, STATE, ZIP 151 L.O. CUSTOMER ORDER NO. SOLD BY TERMS DATE Replacing Old Mita Bunkt LAS Pakmus USC 192 Lake View Circle 162 162 716 Looke Vally & 708 Loke Valla 136 Los Dalomos 414 Claa Love 112 & 216 Loke View Cicle 601 Loke Vally Dr. 9 mite e \$ 50,00 9 45000 450 adams NCT8745

Paro 1046

| DLR lesta 301 mit. | G. Alan # 367 | | | 666000 |
|--|---|----------------------|--|-----------------------|
| N.B. TY 7 | 8130 | | INVOIC | END. 464209 |
| | | | ······································ | Invoice |
| BILL TO LAS Balan | is lise the | SERVICE PERFORMED AT | Ke Vally | |
| ADDRESS Dun DAL | Schburg | ADDRESS | -22-19 | 8-23-19 |
| CITY, STATE, ZIP | | | 0 155 | |
| CUSTOMER ORDER NO. | SOLD BY | TERMS | - | DATE |
| 1 | d BRASS at round Well, I that Est | | | 17000 |
| | I make at Bod make. | 190 Champia | ~ | 100 00 |
| | - · · | · · · · | - | |
| alems: NCT8745 | | Total | | 270 00 |
| | | | Para 100 | 01-1 1 |
| NCT8745 invoice for servi | ces | adams [.] | carbonles | s • 3-part • numbered |
| DLR ULE (Boj min phi N.B. TX 78 | 367 120 # 367 | | | 2 ENO. 464210 |
| N. 13. 14 10 | | | | Invoice |
| ADDRESS Den | mis use Ra Rousburgen | SERVICE PERFORMED AT | LAKe Valle - 20-19 | 1 8-22-A |
| CITY, STATE, ZIP | | CITY, STATE, ZIP | W.0 # 15 | 7 |
| CUSTOMER ORDER NO. | SOLD BY | TERMS | | DATE |

adams[.]

DLR Wate G. 301 MAL Abor # 367 New BANK 15 TX 78130 INVOICE NO. 464211 Invoice BILL TO SERVICE PERFORMED AT Palamis Valle ADDRESS ADDRESS 8-30-19 house CITY, STATE, ZIP CITY, STATE, ZIP LAS PA 102 CUSTOMER ORDER NO. SOLD BY TERMS 161 $\mathcal{U}.\partial.$ Install New Tap at 122 Las Dalamus Double Top for 2 Lots. 8" MAIN &XI Top - Workk Top canadia 2-Lots. ports. 686 73 LAbor & Uncound 2" Blow off 650 00 1336 73 Total adams NCT8745 01-1

PAD 1046

| DLR 301 | Weta min P Bash | Q, bu # 367 1, 7x 78130 | | | INVOICE NO. | 464212 | 2 |
|----------------------------|-----------------------|-------------------------------|----------------|-----------------------|------------------------|-------------------------|-------|
| ADDRESS | o Palan Don Ra | sold BY | SERVICE PERFOR | медат 576 Ш. С. | c 1/c/1 14zy 165 | Invoice lef Orstr | e |
| - | | hest on 576 Lazy | 8-29-, | - | | 90 | |
| edams [•] NCT8745 | LASU. | · · · · · | 70421 | | | 2650 | |

Paro 1041

| | NIAI | A C. | - | | | | |
|---|--------------------|---------------------------------------|------------------|------|--------------|-------|--|
| M.B. 78 78/30 SULTO LA. De lamus was Acc.'s SERVICE PERFORMED AT Lake Vally ADDRESS Disc Dr puthubor 165 Townbord OUTY STATE, 21P U.O. 166 OUSTOMER ORDER NO. SOLD BY TERMS DATE 165 Torn Band Bould RY TERMS DATE 165 Torn Band Bould Compliant of about 2001 DATE Brild Compliant of about 2001 DATE DATE 165 Torn Band Brild Compliant of about 2001 DATE 165 Torn Band Brild Compliant of about 2001 DATE 2000 150 000 150 000 150 000 | What h | the ed. | | | _ | | |
| M.B. 78 78 78 30 SULTO LAS De lamus was Acc.'s SERVICE PERFORMED AT Lake Vally ADDRESS De lamus was Acc.'s ADDRESS OUTY STATE, 21P OUTY STATE, 21P OUTY STATE, 21P OUTY STATE, 21P OUTY STATE, 21P OUSTOMER ORDER NO. SOLD BY TERMS ADDRESS JATE JAT | 301 MA | i p/ A20 367 | | IN | VOICE NO. 41 | 5421 | 3 |
| BILL TO ADDRESS De lomus was Nec. 10 SERVICE PERFORMED AT ADDRESS Disn Browhuber ADDRESS 165 Townbord OITY, STATE, 21P W.O. 166 CUSTOMER ORDER NO. SOLD BY TERMS DATE CUSTOMER ORDER NO. SOLD BY TERMS DATE 165 Town Bend Bouild Compliant debout Lessi Brild Compliant debout Lessi Date Brild Compliant debout Lessi Protection Replace prepipe & Fittins: Home Sold; DATS LAbou 15000 15000 | N.B. J | 78 78130 | | | 4 | | |
| ADDRESS Delance use Merie ADDRESS Address Address Address Address Here's Address Hos Turn bord OTY STATE 21P U.O. 166 CUSTOMER ORDER NO. SOLD BY TERMS DATE USTOMER ORDER NO. SOLD BY TERMS DATE 165 Turn Band Brild Comp Min & about Leoli Brild Comp Min & about Leoli Bridd Comp Min & about Leoli Address Sold, Address Sold, DATE 160 000 150 000 150 000 150 000 240 000 | | | | | | Invoi | ce |
| Dity STATE, 21P OUTY, STATE, 21P OUTY, STATE, 21P U.J. 166 SOLD BY TENMS DATE | LAN | Delamic us | S Accure | | la Ils | | |
| OTV, STATE, ZP U.J. 166 CUSTOMER ORDER NO. SOLD BY TERMS | ADDRESS | Paril | ADDRESS | | | 1 | |
| CUSTOMER ORDER NO. SOLD BY TERMS DATE | CITY, STATE, ZIP | n nyonc | CITY, STATE, ZIP | | 111 | / | |
| 165 Turn Benny Build complain & about Look On our side of theta Replace prepipe & Fitths: Home Sold: DANS LAbu 150 00 Total | CUSTOMER ORDER NO. | SOLD BY | TERMS | U.o. | DATE | | . |
| 165 Turn Benny Build complain & about Look On our side of Meta Replace pre pipe & Fitths: Home Sold: DANS LAbu 150 00 Total | <u>}</u> | | | | | | |
| DANS LASU TOXAL 240 00 | ···· · | | 8-28-1 | 9 | | | 1 |
| 2000 2000 15000 701/ 24000 | | · · · · · · · · · · · · · · · · · · · | | | | | |
| DANS LASU TOXAL 240 00 | | 165 Ture | Berry | | | | |
| DANS LASU TOXAL 240 00 | | Build com | had about | Lesi | | | |
| DANS LASU TOXAL 240 00 | | the due si | In al mita | | | | |
| DANS LASU TOXAL 240 00 | | Prestan a. | al J. F. HIL | | | | |
| DANS LASU TOXAL 240 00 | | Home So | In the visit | | | | |
| Total 240 00 | - | Mune OU | | | | | |
| Total 240 00 | | And. | | | | 9.0 | rai |
| Total 240 00 | | 11/2/03 | · · · | - | | 70 | 00 |
| Total 240 00 | | LAL. | | | | | 00 |
| | | Ny so- | | | | 150 | 00 |
| | | | -Falal | | - | | |
| | adams: NCT8745 | | [0 10] | | | 240 | 00 |

Invoice # 9-1-19

WATER SERVICES FOR AUGUST, 2019

TO Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|--------------|---|------|------------------------|------------|
| August, 2019 | Management Fee For Water Operations | 1 | \$250.00 | \$250.00 |
| | Bacterial Water Sample (TCEQ) | 1 | \$30.00 | \$30.00 |
| | Number of Customers for operations, billing, mailing, and collecting. | 227 | 15.00/ Per meter | \$3,405.00 |
| | | | | |
| | | | | |
| | | | | |
| | SUBTOTAL | | | \$3,685.00 |
| | ADDITIONAL FEES | | | |
| | TOTAL | | | 3,685.00 |

PAD 1045

Make all checks payable to DLR WATER CO., 301 Main Plaza #367, New Braunfels, Texas 78130 THANK YOU FOR YOUR BUSINESS!

| A | LAS PALOMAS WATER SERVICES DONALD RAUSCHUBER, REC PO BOX 342 707 AUSTIN, TX 78734-0000 | | 1045 30-9/1140 243 €CHECK ANNOS |
|-----|---|---------------------|--|
| | The thousand sy hundre | Destty Aseablingal" | S3685 00 Not DOLLARS Deposite |
| FOR | Durse NO. 9-1-19 | | |
| | "001045" #11400093# | 592019035# | |

• • .

.

;

•

.

. (

| 2 | LAS PALOMAS WATER SERVICES COMP DONALD RAUSCHUBER, RECEIVER PO BOX 342 707 AUSTIN, TX 78734-0000 | ANY DATE - 22-49 | 1041 30-9/1140 243 |
|-----|---|---------------------|--------------------------|
| | PAY TO THE OF TOLK Upster Company Husthound sover hundred worth | 5 ,7 | |
| FOR | *Frost www.frostbank.com 464 201, 464 202, 464 204, 464 205, 464 206, + 464 207 | | 2 |

•

•

.

-

.

.

;

•

.

٠

NCT8745 invoice for services adams⁻ carbonless • 3-part • numbered DLR Wata Co. 301 mg ~ P /20 # 367 New BRA-1-6 TY 781 INVOICE NO. 464201 TY 78130 Invoice BILL TO SERVICE PERFORMED A Water Serice Co. ADDRESS B,2 d Auschuber 80 CITY, STATE, ZIP CUSTOMER ORDER NO. SOLD BY TERMS DATE Onto 74-19 W.O # 131 810 Macking Bird Ubter Bresk in Middle ch Street Had Dy & Locaded Ucta Mar + 1" Series_ Across 1" Sevice-Dhen had Serie Openston Openation icts + Sypt.e 35.a/4 (7) 245 25/11-0 175 Materia 180.00 Total adams NGT8745 01-11

F

Pars 1041

| NCT8745 invoice for services | a au | lams | carbonless | · 3-part · | numb | ered |
|------------------------------|---|--------------------------------|---------------------------------------|------------|-----------|---------------|
| DLR Wata " 301 min P | | | INVOICE | 10. 461 | 120 | 2 |
| N.13. 74 78 | | | | | nvoi | |
| ADDRESS Dars 12 RAU | usc Recine | ADDRESS 7-9-19 | he Va | 1 cy 6 | 1/1 | |
| CITY, STATE, ZIP | | CITY, STATE, ZIP W.O. # 132 | | | | $\overline{}$ |
| CUSTOMER ORDER NO. | SOLD BY | TERMS | | DATE | | |
| Cistone- | -19-19 Lev. 0 = Calk d about Fond Lesking + Regained | | - | | | |
| | Serie Opera | Jan 35.av H- 25.00 H | 1.5 14 | | 52 32_ | |
| | Clamp 1 | 2001 | · · · · · · · · · · · · · · · · · · · | L | 102 | 00 |
| adams NCT8745 | | Total | - | 1 | 52 | 00 |

- --

·····

Rain 1041

.....

-

NCT8745 invoice for services 🥭 adams carbonless · 3-part · numbered DLR Ucta 6. 301 mil 1/A20 # 367 Neu BASILI, N 20130 INVOICE NO. 464204 Invoice SERVICE PERFORMED AT BILL TO Walsmas Palomos USC thecine .35 132 ADDRESS Of Auschuber 7-12-19 CITY, STATE CITY, STATE, ZIP U 133 TERMS DATE CUSTOMER ORDER NO. SOLD BY Leta hest at 132 Las Palanss Lesk on Cit-off at Sariachine. Hod to Turn lette off an is up Service Line. Strat & E Scrive Operator & 35.00 Hr Operator 25.00 Hr 34 105 00 314 75 parts for Cat-off Repair 4000 - ---Colal adams NCT8745

Pano 1041

NCT8745 invoice for services adams[.] carbonless · 3-part · numbered DLA Ubta G. 301 Main Phro # 367 New Bartol, TV 78130 INVOICE NO. 464205 Invoice SERVICE PERFORMED AT BILL TO Clour An ADDRES ADDRESS 7-20-19 CITY, STATE, ZIP CITY, STATE, ZIP W.O 4 140 CUSTOMER ORDER NO. SOLD BY TERMS DATE she lette Min at 417 Clouchsu 417 Clouchance "pe. Depried & Rep bad + Broka 6 (1) Depted Broka Water Date 5 His 00 5 Hrs ≩≿≶ 00 100 00 4"-90 & Thega-hugs, 4" hay Sleeve & Moga hugs. 442 The defor, 4" Tigg Shot & Corpstop & Concrete. TAP SALVIE 500 00 adams NCT8745 01-11



| NCT8745 invoice for services | adam 🔏 | is c | arbonless • 3-part • numbered |
|------------------------------|---|---------------------------|-------------------------------|
| DLA Weter Go 30, MAIL PH2 |) | | • ••• |
| 301 MAIL 1/42 N.B. 74 281 | 20 5 36 7 30 | | INVOICE NO. 461206 |
| | | | Invoice |
| BILL TO LAS Palano | s USC becieva | NICE PERFORMED AT 616 6A | Le Valley Dr. |
| ADDRESS Deno 12 DAL | sch bar | 7-20-1 | - |
| CITY, STATE, ZIP | CIT | Y, STATE, ZIP W.O. 13 | |
| CUSTOMER ORDER NO. | SOLD BY | MS | DATE |
| Dopherd Der as Hish | Mila et lett toma ReGrest, B; 11 | 6 hale Volley D Due 70 | |
| | - · · · · · · · · · · · · · · · · · · · | | - |
| | | | |
| Adams' NCT8745 | | | 01-11 |

.

Prana 1041

NCT8745 invoice for services 🏽 adams carbonless · 3-part · numbered DLQ Usta 6. 301 Mr. 2 P Hro # 367 N.B. TV 78130 INVOICE NO. 464207 Invoice BILL TO SERVICE PERFORMED AT nos USC Areieva ADDR ADDRESS CITY, STATE, ZI CITY, STATE, ZIP W.O. 140 CUSTOMER ORDER NO. SOLD BY TERMS DATE Deplacing old Mater, Liss Dalanas Daid for Mater 712 Latue Volley, 707 Latue Vallay 132 LAS DelomAS, 129 Pine Vallay. 185 Champions, 177 Champions. 151 Champions, 149 Champions 139 Champions, 204 Champions 10 Stuck mite e \$50.00 psci 10 500 adams^a NCT8745 01-11

Fano 1041

1

| LAS PALOMAS WATER SERVICES COMPANY DONALD RAUSCHUBER, RECEIVER PO BOX 342 707 AUSTIN, TX 78734-0000 DATE | 1041 30-9/1140 243 @CHECK MINO |
|--|--|
| | -,797 ⁵⁰ |
| twothonand sover hundred works seven dollan + ici-Do | DLLARS DE Sate Designation Designation |
| IOSL WWW.frostbank.com FOR Var. 424 206, 4 4207 | 2 |
| | |

.

. . .

.

•

.

.

.

.

.

•

.

,


3


1

.

•

.





DLR WATER CO. 301 MAIN PLAZA BOX #367 NEW BRAUNFELS, TX.78130 watertexasyahoo.com

Invoice # 7-1-19

WATER SERVICES FOR JUNE, 2019

1

то

Las Palomas Water Service Company Receiver Donald Rauschuber

| DATE | DESCRIPTION | QTY. | RATE | TOTAL |
|------------|---|------|------------------------|------------|
| June, 2019 | Management Fee For Water Operations | 1 | \$250.00 | \$250.00 |
| | Bacterial Water Sample (TCEQ) | 1 | \$30.00 | \$30.00 |
| | Number of Customers for operations, billing, mailing, and collecting. | 227 | 15.00/ Per meter | \$3,405.00 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | SUBTOTAL | | | \$3,685.00 |
| | ADDITIONAL FEES | | | |
| | TOTAL | | | 3,685.00 |

PARO 1026

Make all checks payable to DLR WATER CO., 301 Main Plaza #367, New Braunfels, Texas 78130 THANK YOU FOR YOUR BUSINESS!

DLR WATER CO. 301 MAIN PLAZA BOX #367 NEW BRAUNFELS, TX.78130 watertexasyahoo.com

Invoice # 7-2-19

WATER SERVICES FOR JUNE, 2019

| DATE June 2019 | DESCRIPTION | QTY. | RATE | TOTAL |
|----------------------|---|----------|----------------------|----------------------|
| 6/15/19 | Work Order #125 Hand Dug & Located 6"Line break on Colonial Dr./ Parts Labor | | \$227.00 \$450.00 | \$227.00 \$450.00 |
| 6/22/19 | Work Order# 129 Delivered and collected Lead & Copper Samples | | \$100.00 | \$100.00 |
| 6/28/19 | Work Order #126 Water Leak on Colonial Dr. Hand dug up to Water Main & found broken service line. Installed Dual Meter set-up for 2 meters & Installed large meter box. Parts Labor | | \$475.00 \$650.00 | \$475.00 \$650.00 |
| 6/11/19 | CCR and Public Notices This includes stamps, envelopes, paper (and ink), and labor | 227 | \$2.00/Acct | \$454.00 |
| | | <u> </u> | Sub Total | \$1,902.00 |
| | | | Additional | \$ 454.00 |
| | PA 10 1026 | | Total | \$ 2,356.00 |

Make all

checks payable to DLR WATER CO., 301 Main Plaza #367, New Braunfels, Texas 78130 THANK YOU FOR YOUR BUSINESS!

| | LAS PALOMAS WATER SERVICES COMPANY DONALD RAUSCHUBER, RECEIVER PO BOX 342 707 AUSTIN, TX 78734-0000 DATE | 1026 30-9/1140 243 هجبات ک |
|--------|--|-------------------------------------|
| | PAY TO THE ORDER OF DLR whiter Company - Right thousand forty one dollars _ 1 - | Dollars Dollars |
| FOR I. | Frost www.frostbank.com www.frostbank.com www.frostbank.com www.frostbank.com www.frostbank.com www.frostbank.com www.frostbank.com www.frostbank.com www.frostbank.com | |

ς.

.

x

:

1

,