
METH IN INDIAN COUNTRY

Meth Testing and Remediation Procedures Guidelines and Best Practices


Meth In Indian Country


- Day 1: Introduction Meth in Indian Country –
- Meth in Indian Housing Does it exist? Is it a problem? Review current practices & policies.
- Day 2: Train staff on recommended approach to inspection, remediation & record keeping. Review policies regarding unit management, testing & violations. Will include section on safety

Day 1 - April 14 -9:00 a.m. - Training begins: Introduction and discussion with attendees 10:00 -10:15 - Break - Review current practices and existing policies 11:00 - 11:15 Break 12:00 – 1:00 – Lunch Break 1:00 - Continue discussion on current practices and existing policies 2:00 - 2:15 - Break 3:00 - 3:15 - Break 4:00 - End of Day 1 Training Day 2 - April 15 -9:00 a.m. - Training Day 2 begins: Recommended approaches to inspections, safety, remediation and record keeping. 10:00 - Break 10:15 - Continue discussion on inspections, remediations and record keeping. 11:00 - 11:15 Break 12:00 - 1:00 p.m. - Lunch Break 1:00 p.m. - Review policies regarding unit management, testing and violations. 2:00 - 2:15 - Break - Continue discussion regarding unit management, testing and violations 3:00 - 3:15 - Break 4:00 p.m. - End of Day 2 Training










Collateral Damage

- Elders- Multiple families living in "Grandma's" unit
- More than likely not the fault of the elder
- How does TDHE address?
 - Evict elder?
 - Minor children?
 - Place elder in smaller unit under an agreement that does not allow additional occupants




• A 29-year-old San Carlos Apache woman took a walk, holding her young son in one hand..

• Hyped up on methamphetamine, she stabbed the 5 year old boy to death, later telling officials on the Arizona reservation that her son was the "devil" and "possessed."


Meth Awareness and Abatement Training 2009

POLICY, POLICY, POLICY EDUCATE, EDUCATE, EDUCATE COMMUNICATE WITH COMMUNITY & TRIBAL LEADERS


OUTREACH, OUTREACH, OUTREACH











BH Zero Tolerance Drug Policy

Blackfeet Housing, in order to provide secure, safe and decent housing, hereby adopts a zero tolerance policy regarding illegal drug use, on or off Blackfeet Housing premises pursuant to Blackfeet Housing Resolution #2004-20.

Any occupant, family member, guest or person, whom Blackfeet Housing has reasonable cause to believe, whose illegal drug use or pattern of use, or use of, or pattern of use of alcohol, on or off Blackfeet Housing premises, interferes with the health, safety and peaceful enjoyment of individuals in Blackfeet Housing units, will be subject to immediate board up.


The occupant understands, consents to and agrees that they, their family members and guests will maintain the unit in a drug free state, or be subject to immediate board up. If the occupant, any member of the household or a guest engages in any drug related activity, on or off Blackfeet Housing project premises, they will be subject to immediate board up and eviction proceedings will begin. Conviction is not necessary for eviction.

When Do You Test?


1. Unit becomes vacant (Baseline Test) A baseline test ensures the unit is clean prior to a new move in


2. Reasonable suspicion of drug activity Examples: Police Report, Staff Report, Paraphernalia

3. By tenant request




https://www.youtube.com/watch?v=ca_XsczZX2s










- TDHE may elect to test units systematically under the following conditions:
- 1) Anytime a unit becomes vacant
- 2) Anytime a disturbance involving drugs or drug paraphernalia is reported at a unit
- 3) Anytime a Tenant requests a unit transfer
- Anytime a unit becomes vacant for rehab or emergency repairs








PO Box 449 Browning, Montana 59417 (406)-338-5031 www.blackfeethousing org
DATE: July 11, 2017
TO: SANDI RUNNING CRANE, OCCUPANCY SUPERVISOR FROM: MAUREEN SALOIS, SECURITY SUPERVISOR SUBJECT: UNIT #1841 UNIT #1841 IS CLEAR. THIS UNIT IS CLEARED OF ALL ENVIRONMENTAL SUBSTANCES. UNIT IS READY TO BE PUT BACK IN RENOVATION PROCESS.



BLACKFEET HOUSING
MOVE OUT POSITIVE UNIT
DATE: <u>April 25, 2018</u> TIME: <u>8:52 AM</u>
TO: DEPART.: SECURITY/MAINTE ce: Director, Assistant Director, Renovation, Finance, Material & Supply, Waiting List, Occupancy, FILE UNIT #: 1211 M/O DATE: 4/24/2018
DESCRIPTION: M/O due to Termination. Do not assign or process until further notice
ENVIRONMENTAL TEST POSITIVE DATE: <u>11/15/2017</u> EXTERMINATION DATE: ?
EXTERMINATION DATE: ? POSITIVE:NEGATIVE:
TAKEN BY: SRC




Local Law Enforcement Drug Testing




Marquis Reagent: Primary general screening test for the presumptive identification of Opiates (Morphine, Codeine or Heroin), Demerol, Black Tar, Amphetamine-type compounds including Methamphetamine & Methylenedioxymethamphetamine (MDMA or Ecstacy), Amphetamines and as a general screening agent for other drugs.


\$18.00 Add-on options Custom made for you within 45-60 days. Special products may take long

BLACKFEET HOUSING SECURITY INCIDENT REPORT
Case #: BII1802-018
DII SECURITY OFFICER: 473-A. Bull Calf
 DATETIME OF INCITED: 02-15-2018/0253
HOUSING UNIT: 747
OWNER/TENANT: Butterfly, Karen
OFFENENSE: Removal, Property Damage, Drug Incident
ALCOHOL/DRUG RELATED; Yes
SUSPECT (S): Ben Loring, Mark Weather Wax
SUSPECT/PERSON ARRESTED: Ben Loring
REPORTING PARTY: \$14
VICTIM: Housing Department
WITNESS; N/A
RESPONDING OFFICER (S): 814-473-Man On Call
PROPERTY DAMAGE (TVPE): Ves
PHOTOS TAKEN: Yes
NARRATIVE: 814 requested housing security for welfare check on formale. On arrival officer did knock on door which copened, Back door observed in he bicksted in. Officer did request ambulance walk was laving so. bed in back, room and bad blood on side of his head. Mark Wenther Waa was removed from unit. Ber Loring wan detained for warrant, 314 idd take make in HIS for med clearance ambulance was cancelled suspect refused medical assistance. Upon taking pictures meth pipe picture taken in living room, marijaana pipe picture taken in back bedroom. Several vodka and black velvet bottles throughout the unit. Fridge door is damaged. Burn mark on kitchen celling. Over door damaged. Upon valing outside. Collece Mwagener arrived with four others stating she is living here at this unit that Karen is allowing them to stav there. Tenant was not at this unit. Colten stated she is at her mothers. People were not allowed inside unit but did take they. But Sector and the sum that that Karen is allowing them to stav there. Tenant was not at this unit. Colten stated she is at her mothers. People were not allowed inside unit but did its cheir three door swith them. Man on call did board the back Joor we then the four four thes unit area. BH SECURITY OFFICER SIGNAL UNES, 473-A. But Call





































































<section-header><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item>
















Test Results

- Positive results in a wipe sample test that is sent to the ALS Global Lab for more extensive testing.(\$35.00 for a Lab Test)
- Negative is considered a clean unit and is referred back to TDHE'S Occupancy Department.
- Invalid requires a re-test of the invalid area









			Report Da	te: September 14, 2018
			Phone:	
			Fax: E-mail:	
			E mail.	
			Workorde	
			Client Project ID: Purchase Order:	4649
			Project Manager:	Paul Pope
Analytical Results				
Sample ID: S#49-1 Lab ID: 1825160001	0.00	pling Location: 46	49	Collected: 09/05/2018 Received: 09/08/2018
Method: NIOSH 9111	San	Media: Wipe	147 	Instrument: LCMS06
Method. NICon 9111	Sampli	ng Info: Volume No	t Provided	Analyzed: 09/13/2018 (222639)
Analyte	Result (ug/sample)	Result (ug/100cm²)	RL (ug/sample)	
Methamphetamine	16	NA	0.050	
Sample ID: 5#49-2	0			Collected: 09/05/2018
Lab ID: 1825160002	San	npling Location: 4	549	Received: 09/08/2018
Method: NIOSH 9111		Media: Wipe ng Info: Volume No	t Provided	Instrument: LCMS06 Analyzed: 09/13/2018 (222639)
Analyte	Result (ug/sample)	Result (ug/100cm²)	RL (ug/sample)	
Methamphetamine	3.3	NA	0.050	
Sample ID: S#49-3 Lab ID: 1825160003	8	pling Location: 4	240	Collected: 09/05/2018 Received: 09/08/2018
Method: NIOSH 9111	San	Media: Wipe	549	Instrument: LCMS06
Metriod: NICon 9111	Sampli	ng Info: Volume No	t Provided	Analyzed: 09/13/2018 (222639)
	Result (ug/sample)	Result (ug/100cm²)	RL (ug/sample)	
Analyte	(ug/sample) 2,9	(ug/100cm*)		

ALS	AN	ALYTICAL REP	ORT	
			Workorder: Client Project ID: Purchase Order: Project Manager:	NA
Analytical Results				Collected: 09/05/2018
Sample ID: S#49-4 Lab ID: 1825160004	Se	mpling Location: 40	349	Received: 09/05/2018
Method: NIOSH 9111		Media: Wipe ling Info: Volume No		Instrument: LCMS06 Analyzed: 09/13/2018 (222639)
Analyte	Result (ug/sample)	Result (ug/100cm²)	RL (ug/sample)	
Methamphetamine	7.3	NA	0.050	
Sample ID: S#49-5 Lab ID: 1825160005	Sa	mpling Location: 4	549	Collected: 09/05/2018 Received: 09/08/2018
Method: NIOSH 9111	Samp	Media: Wipe ling Info: Volume No	t Provided	Instrument: LCMS06 Analyzed: 09/13/2018 (222639)
Analyte	Result (ug/sample)	Result (ug/100cm²)	RL (ug/sample)	
Methamphetamine	3.6	NA	0.050	
Sample ID: S#49-6 Lab ID: 1825160006 Method: NIOSH 9111		Media: Wipe		Collected: 09/05/2018 Received: 09/08/2018 Instrument: LCMS06 Analyzed: 09/13/2018 (222639)
Analyte	Result (ug/sample)	Result (ug/100cm²)	RL (ug/sample)	
Methamphetamine	0.83	NA	0.050	
Sample ID: S#49-7 Lab ID: 1825160007	Sa	mpling Location: 46	49	Collected: 09/05/2018 Received: 09/08/2018
Method: NIOSH 9111	Samp	Media: Wipe ling Info: Volume No	t Provided	Instrument: LCMS06 Analyzed: 09/13/2018 (222639)
Analyte	Result (ug/sample)	Result (ug/100cm²)	RL (ug/sample)	
Methamphetamine	26	NA	0.050	
Sample ID: S#49-8 Lab ID: 1825160008	Sa	mpling Location: 46	49	Collected: 09/05/2018 Received: 09/08/2018
Method: NIOSH 9111	Samp	Media: Wipe ling Info: Volume No	t Provided	Instrument: LCMS06 Analyzed: 09/13/2018 (222639)
Analyte	Result (ug/sample)	Result (ug/100cm²)	RL (ug/sample)	
Methamphetamine	0.86	NA	0.050	


			Workord Client Project ID Purchase Order Project Manager	NA	
Analytical Results				0-11-11-11-00/05/0	040
Sample ID: S#49-9 Lab ID: 1825160009	Sar	npling Location: 46	649	Collected: 09/05/2 Received: 09/08/2	
Method: NIOSH 9111	Sampli	Media: Wipe ng Info: Volume Not	t Provided	Instrument: LCMS06 Analyzed: 09/13/2018 (22)	2639
Analyte	Result (ug/sample)	Result (ug/100cm²)	RL (ug/sample)		
Methamphetamine	1.7	NA	0.050		
Sample ID: S#49-10				Collected: 09/05/2	018
Lab ID: 1825160010	Sar	npling Location: 46	49	Received: 09/08/2	018
Method: NIOSH 9111	Sampli	Media: Wipe ng Info: Volume Not	t Provided	Instrument: LCMS06 Analyzed: 09/13/2018 (22)	2639
Analyte	Result (ug/sample)	Result (ug/100cm²)	RL (ug/sample)		
Methamphetamine	ND	NA	0.050		
Report Authorization (/S/ is an elec	tronic signature that	complies with 21 CF	R Part 11)		
Method		Analyst	A limber	Peer Review	
NIOSH 9111		/S/ Christopher \ 09/14/2018 12:4		/S/ Stephen Brose 09/14/2018 13:08	
Laboratory Contact Information ALS Environmental 960 W Levoy Drive Salt Lake City, Utah 84123	E	hone: (801) 266-770 Email: alslt.lab@ALS Web: www.alsslc.com	Global.com		

Analyte ug/sample ug/100cm ³ RL (ug/sample) Methamphetamine 0.47 0.47 0.050
Methamphetamine 0.47 0.47 0.050
Sample ID: SC#28-5 Collected; 05/28 Lab ID: 1415141005 Sampling Location: Blackft Received; 05/31
Method: NIOSH 9111 Media: Wipe Analyzed: 06/05/ Sampling Parameter: Area 100 cm ²
Analyte ug/sample ug/100cm* RL (ug/sample)



















3-2-1 Wash Method


- Step 1 Spray cleaning mixture on all surfaces
- Step 2 Vacuum all surfaces (Hepa Filter)
- Step 3 Rinse off all Surfaces
- Step 4 Repeat Steps 1–3 two more times
- Cleaning Solution: Dawn Dish Soap, Vinegar and Water
- Ratio: 1.5 cups of Dawn, 2 cups vinegar, 3 Gallons of water







<section-header><list-item><list-item><list-item>









MOVE OUT POSITIVE UNIT
DATE: April 25, 2018 TIME: 8:52 AM
TO: MAUREEN/LYLE DEPART.: SECURITY/MAINTE.
ce: CHANCY, ANNA O., POLY, OPAL, MARGIE, YVONNE, SANDI, FILE
UNIT #: 1211 M/O DATE: 4/24/2018
DESCRIPTION: M/O due to Termination. Do not assign or process until further notice
ENVIRONMENTAL TEST POSITIVE DATE: 11/15/2017
EXTERMINATION DATE: ? POSITIVE:NEGATIVE:
TAKEN BY: SRC 20







Units				Updated 4/5/18	
	That Tes	ted Posit	ive for Methamphetamine		
U	nit #		Date Tested	Date Cleared	
1	5006		10/12/201	L 4/25/2012	
2	2214		10/11/201	L 6/13/2012	
3	4642		1/13/2012	2 8/14/2012	
4	5008		2/15/2012	2 9/14/2013	
		2nd	4/14/2014	1 8/8/2014	
5	2008		9/16/2012	2 10/9/2012	
6	5037		10/11/201	L 11/5/2013	
7	5720		5/11/2012	2 11/5/2013	
8	112		3/5/2012	11/16/201	
9	1211		2/14/2012	11/16/201	
10	5906		10/11/2012	2 12/7/2013	
11	1433		2/14/2012	2 2/11/201	
12	4636		8/30/2012	2 2/27/201	
13	1221		10/1/2012	3/25/201	
14	2306		12/1/2013	6/11/2013	


Г


15	632		9/23/2012	6/18/2013
16	733		10/4/2012	8/15/2013
17	1403		2/1/2013	10/1/2013
18	4543		1/28/2013	10/1/2013
19	5007		11/15/2012	10/1/2013
20	5915		3/13/2014	4/2/2014
21	625		4/30/2013	7/24/2014
22	642		2/12/2014	7/24/2014
23	623		11/1/2013	7/24/2014
24	110			7/30/2014
25	5010		3/13/2014	8/4/2014
26	633		3/4/2014	8/4/2014
27	5027		6/4/2013	8/13/2014
28	5028		5/28/2014	9/5/2014
29	2026		3/11/2014	10/8/2014
30	635		5/22/2013	10/17/2014
31	636		12/11/2013	10/10/2014
		2nd	5/13/2015	6/16/2015
32	1405		10/30/2013	11/19/2014
		2nd	3/27/2015	4/16/2015
33	646		7/24/2013	11/5/2014
34	1850		6/2/2014	12/9/2014
35	1831		6/19/2013	12/12/2014

		JI LLI LUIU	0/10/201/
91	135	10/25/2016	6/13/2017
92	632	11/15/2016	6/12/2017
93	140	2/28/2017	6/13/2017
94	4617	6/14/2017	10/5/2017
95	643	6/14/2017	10/26/2017
96	725	6/14/2017	9/12/2017
97	5028	6/14/2017	9/6/2017
98	720	6/14/2017	10/11/2017
99	2206	6/14/2017	10/12/2017
100	1811	6/14/2017	10/4/2017
101	4902	6/19/2017	10/5/2017
102	1841	6/21/2017	7/11/2017
103	2204	7/12/2017	10/24/2017
104	1421	8/21/2017	10/24/2017
105	6003	9/18/2017	10/18/2017
106	1831	10/30/2017	
107	1211	11/15/2017	
108	117	11/21/2017	12/11/2017
108	2408	1/16/2018	
109	1808	1/16/2018	
110	735	1/16/2018	4/2/2018
111	743	4/2/2018	
112	4550	3/16/2018	


				Updated4/5/18
	Units That 1	Fested Negative	for Methamphetamine	
	<u>Unit #</u>		Date Tested	
		<u>100 BLOCK</u>		
1	101		6/25/2014	
2		2nd	2/1/2016	
3	102		3/5/2013	
4		2nd	12/8/2015	
5	104		1/25/2013	
6	105		11/14/2012	
7	107		8/28/2012	
8	108		9/24/2014	
9	109		3/21/2012	
10		2nd	9/10/2014	
11	110		7/30/2014	
12	111		8/28/2013	
13	112		9/26/2014	
14	113		2/11/2015	
15		2nd	4/9/2015	
16	114		4/7/2014	
17	116		3/29/2012	
18	117		9/21/2012	
19	118		3/6/2012	


				_
411	5913		7/14/2015	
412	5925		4/5/2013	
		6000 BLOCK		
413	6005		7/20/2015	
414	6007		3/16/2015	
415		2nd	2/17/2016	
416	6008		2/22/2016	
417	6016		11/5/2014	
		7200 BLOCK		
418	7203		10/18/2012	
419	7206		6/14/2011	
420	7211		3/16/2015	
421		2nd	8/4/2016	
422	7213		2/21/2012	
423	7214		9/3/2014	
		MISC. BLOCK		
424 B	Brewster Ra	nch	2/4/2015	
425 T	homas N		9/21/2012	
426		2nd	1/15/2014	
427		3rd	9/18/2014	
428 T	homas S		1/15/2014	
429		2nd	9/9/2014	
430	802		12/13/2016	














Light Bulbs

- Partnerships with local energy suppliers through grants
- Replace standard incandescent light bulbs

Compact Fluorescent Light Bulbs - 23 Watt



SYLVANIA[•]

Last 10 times longer and use 75% less energy than standard bulbs.

•Not dimmable. •Color: warm white. •<u>Recycling Kit</u> available.

