WELCOME TO THE WORKSHOP!

1. Please turn on your camera.



Hello! My name is ...

- 2. Please introduce yourself at arrival in the **Chat** (Alt + H).
- 3. Please mute yourself while others speak.



- 4. Need technical assistance? Reach out to Rebecca Julie
- 5. If you need Spanish translation, please let us know in the chat










Agenda

- Introductions
- Presentation
- Workshop
 - Breakout Sessions
- Closing Conversation
 - Workshop Summaries
 - Next Steps

Introductions

Mosholu Parkway



Background



Past In-House Improvements









- Painted pedestrian space
- Signal infrastructure changes
- Lane adjustment on Mosholu Parkway at Sedgwick Avenue
- Painted pedestrian space
- Concrete island
- Bus boarding island

- Closed redundant street
- Concrete island
- Concrete sidewalk

Recent Outreach

August 2019

 Walkthrough with Councilmember Cohen and Commissioner Trottenberg

March 2020

DOT to attend Friends of Mosholu Pkwy
Walkthrough, but it was cancelled due to pandemic

January 2022


Walkthrough with Councilmember Dinowitz

Safety Data

- 121 total injuries on Mosholu Parkway between 2015 and 2019
- 50% of pedestrian injuries occurred while a vehicle was turning left and a pedestrian was using the walk signal

Mosholu Pkwy, Van Cortlandt Av to Southern Blvd Injury Summary, 2015-2019 (5 years)

	Total Injuries	Severe Injuries	Fatalities	KSI
Pedestrian	23	0	0	0
Bicyclists	3	0	0	0
Motor Vehicle Occupant	95	7	0	0
Total	121	7	0	0



Existing Conditions

- Vehicles
- Pedestrians
- Bikes



Existing Conditions: Vehicles

Existing Bus Movements on Mosholu Parkway



Bx28

BxM4

Bx34

Existing Condition: Vehicles


- Inconsistent number of lanes throughout corridor
- Analysis shows excess capacity for corridor




Existing Condition: Vehicles




- High turn volume at Sedgwick Avenue, but functions with two through lanes and a left turn lane
- Other intersections along the Parkway have lower turn volumes and more road space





Existing Condition: Vehicles



Each intersection will be evaluated for a left turn lane



Existing Condition: Pedestrians









Existing Condition: Pedestrians





Existing Condition: Bikes

Bike Routes that Intersect with Mosholu Parkway




On Street Shared Lane

On Street Bike Lane

Existing Condition: Bikes





Existing Condition: Bikes





In-House Toolkit







Concrete Islands



Signal Timing Changes



Concrete Sidewalk with Bike Stamps



Parking




Street Furniture and Amenities

Breakout Sessions



Breakout Sessions




Workshop Tools



Workshop Tools: Annotate



Workshop Tools: Annotate



Geographic Area A 💢 Issue 🧡 Asset 💡 Project Idea







Chat: Alt + H



Geographic Area B






Asset



Chat: Alt + H





Geographic Area C 💢 Issue 🧡 Asset 🔞 Project Idea





Chat: Alt + H






Closing Conversation



Workshop Summary



Next Steps

February 2022: Virtual Workshop

Late Winter / Early Spring 2022: work on designs based on insights from workshop, present ideas at community board meeting

Summer 2022: Implementation of street improvements